

**TOWN OF CLARKSTOWN
DEPARTMENT OF ENVIRONMENTAL CONTROL
NEW CITY, NEW YORK**

**OPERATION & MAINTENANCE REPORT
CLARKSTOWN SANITARY LANDFILL**

APRIL 2001 – MARCH 2002

JUNE 2002

LAWLER, MATUSKY & SKELLY ENGINEERS LLP
Environmental Science & Engineering Consultants
One Blue Hill Plaza
Pearl River, New York 10965

Project No. 679-004

TABLE OF CONTENTS

| CHAPTER | TITLE | PAGE No. |
|---------|---|----------|
| 1 | Introduction | 1-1 |
| 2 | Landfill Gas System Maintenance/Balancing | 2-1 |
| 3 | Landfill Gas System Flare Control System | 3-1 |
| 4 | Overall Gas Volume | 4-1 |
| 5 | Other Systems | 5-1 |

APPENDICES

| | |
|----|--|
| A- | Inspection Forms FS-3, FS-4, FCS-1, LFGL-1, LFGH-1, LCS-1, LCS-2, AR-1, SMC-1, SMB-1 |
| B- | Raw Data Sheets – Flare Station Maintenance memos |
| C- | Maintenance Memos |
| D- | Landfill Gas Monitoring For Well Balancing, Form LFGW-1 |
| E- | Monthly Description of Deficiency and Problem, Form DP-1 |
| F- | Monthly Extraction Well Reports |

CHAPTER 1

INTRODUCTION

The purpose of this annual report is to summarize operation and maintenance information for the period April 1, 2001 through March 31, 2002 for the Clarkstown Sanitary Landfill in West Nyack, Rockland County, New York. The landfill, which is located approximately 1,000 feet south of Route 59, is bounded on the East Side by New York State Route 303, and on the North, South and West sides by unoccupied land. The landfill property encompasses approximately 100 acres.

The Town of Clarkstown retained the services of Lawler, Matusky & Skelly Engineer LLP (LMS) to assist in the operation and maintenance of the facility. LMS performed routine inspections and maintenance of the facility under the guidance of the Clarkstown Sanitary Landfill Operation & Maintenance Manual. In addition, LMS conducted off-site gas monitoring to investigate possible migration of landfill gas and directed repairs to the gas collection system and flare system electrical conduits. Normal landfill operation was maintained without major deficiencies during this reporting period.

CHAPTER 2

LANDFILL GAS (LFG) SYSTEM MONITORING/BALANCING/MAINTENANCE

This chapter provides a description of the monitoring/maintenance of the landfill gas system including the followings:

1. LFG System Collection Piping
2. LFG Surface Collector Networks
3. LFG Drip Leg Assemblies
4. LFG System Wellheads, Vaults and Valves
5. LFG Enclosed Ground Flare
6. LFG Monitoring For System Control

2.1 LFG SYSTEM COLLECTION PIPING

Routine maintenance was conducted including visual inspection of the valve and valve vaults for damage or improper operation, and visual inspection of the landfill surface above the buried pipe manifold for any signs of differential settlement or other problems. The Site inspection checklists for the LFG Header Network (Form LFGH-1) and the LFG Lateral Network (Form LFGL-1) are attached in Appendix A.

Some unsatisfactory conditions of zone control valves due to damage in sampling ports and hoses were found in April 2001. By January 2002, all deficiencies related to the sampling ports were fixed.

Unsatisfactory suction pressure of some extraction wells located in Zones I and B was noticed in October 2001 and January 2002, respectively. Preliminary investigation conducted on January 25, 2002 revealed sagging of the buried conveyance pipe between GE 37 and GE 38. This provided a low spot for condensate to build up and fill the main, resulting in loss of suction pressure behind the problem point. Repair was done by resloping the gas main (as best as possible) to drain to the drip leg. In addition, a riser was installed at the mid point to serve as a sleeve for the insertion of a suction line so that

the condensate can be pumped directly out of the main line in case it does not all drain to the drip leg.

A similar repair was performed between GE 2 and GE 3, the area directly west of the flare station. In this line, the grade of the area was too shallow to reslope so that the repair consisted only of placing a riser at the low point.

Well measurements taken after the repairs showed normal suction pressures, indicating successful repairs around the problem areas.

2.2 LFG SURFACE COLLECTOR NETWORKS

Routine visual inspection of the collector areas, especially for signs of excessive differential settlement, was conducted. No major deficiencies were reported.

2.3 LFG DRIP LEG ASSEMBLIES

Quarterly inspections for damage, improper operation, or other problems were conducted. Particular attention was paid to settlement of the drip leg vault, surrounding cover, leakage either in or around the drip leg, liquid pooling in the vaults, and clogging of the drip leg piping. The inspections were detailed on Form FS-4, included in Appendix A. No major deficiencies were found.

2.4 SYSTEM WELLHEAD, VAULTS AND VALVES

The 52 LFG extraction wells were inspected during each well balancing. Visual inspection of each well was conducted for leakage, liquid pooling and hazardous conditions in the surrounding area. Deficiencies were reported on Form DP-1. Several extraction wells have experienced vault settlement. This differential settlement between vault box and the wellhead assembly provided low or no head space between the wellhead and the vault cover. Several damaged sampling ports in the well heads were reported due to this problem. The deficiencies, however, did not affect the overall operation of the landfill.

The gas quality at the 52 gas wells for the 9 months, April, June, August, September, October, November 2001 and January, February and March 2002, is summarized on Figure 2-1 and in the following table:

Table 2-1
Summary of Extraction Well Data

| | SCFM | SCFM | (%) | (%) | (%) | (%) | (in. H ₂ O) |
|---------------------|-------------|-----------------|-----------------|-----------------|----------------|----------------|------------------------|
| | Ave. Q/well | Total Est. Flow | CH ₄ | CO ₂ | O ₂ | N ₂ | S. Pre. |
| Apr-01 | 5.7 | 298 | 40 | 29 | 4 | 27 | -0.8 |
| Jun-01 | 5.3 | 278 | 48 | 27 | 5 | 20 | -2 |
| Aug-01 | 3.4 | - | 44 | 28 | 4 | 24 | -3 |
| Sep-01 | 2.6 | 123 | 41 | 25 | 2 | 23 | -2 |
| Oct-01 | 4.7 | 235 | 42 | 25 | 5 | 26 | -3 |
| Nov-01 | 2.5 | 130 | 46 | 26 | 4 | 26 | -4 |
| Jan-02 | 2.1 | 108 | 48 | 25 | 6 | 23 | -4 |
| Feb-02 | 1.8 | 91 | 49 | 26 | 3 | 21 | -2 |
| Mar-02 ¹ | 2.0 | 104 | 50 | 29 | 4 | 19 | -3 |

¹ Due to malfunction of the landfill portable gas analyzer, not all wells were sampled for gas analysis.

Table 2-2
Summary of Flare Measurements

| | CFM | CFM | (%) | (%) | (%) | (%) |
|--------|--------------|-------------------------------|-----------------|-----------------|----------------|----------------|
| | Average Flow | Est. Ave. Q/well ² | CH ₄ | CO ₂ | O ₂ | N ₂ |
| Apr-01 | 344 | 6.6 | 48 | 31 | 3 | 18 |
| Jun-01 | 351 | 6.7 | 58 | 36 | 1 | 7 |
| Sep-01 | 375 | 7.2 | 45 | 29 | 3 | 24 |
| Oct-01 | 357 | 6.9 | 45 | 25 | 5 | 26 |
| Nov-01 | 331 | 6.4 | 46 | 27 | 3 | 25 |
| Jan-02 | 341 | 6.6 | 41 | 23 | 4 | 29 |
| Feb-02 | 345 | 6.6 | 41 | 27 | 3 | 30 |
| Mar-02 | 385 | 7.4 | 40 | 26 | 3 | 32 |

² Based on 24 hr/day and 30 day/month

Several observations should be noted with respect to these extraction well data, as they stand and in conjunction with data collected at the flare system:

- The nitrogen concentration showed consistently between 20% and 30%, and there was general consistency between the measurements at the extraction wells and at the flare station. The usual explanation for the nitrogen content is intrusion of air into the landfill, caused by over extraction by the blower(s); action taken to reduce over-extraction is determined in 2.6, below.
- The system ran at a metered gas flow of 300-400 CFM during this reporting period. The reason for the inconsistency between the sum of the individual gas well readings and the total flow as measured at the flare system is being investigated. The flow transmitter at the flare station was calibrated in 2002 and should transmit reliable readings. The most likely cause is imprecision of flow measurement device through orifice plates in the extraction wells. This discrepancy is not of great importance to the operation of the system.

A recurring or common problem was liquid pooling in the extraction well vaults. Seven extraction wells were pumped out during the routine operation of November and January.

2.5 ENCLOSED GROUND FLARE

The flare is typically operated automatically by the blower and flare control system, though problems with the control system occasionally shut down the system. Detailed inspection/maintenance are reported in Chapter 3 & Form FS-4 in Appendix A.

Maintenance of the flare included the following:

| | |
|----------------|--|
| Monthly: | Inspect flame arrestor |
| Quarterly: | Check igniter gap, igniter wiring, thermocouple voltage, shutdown valve, all components against "set-point" sheet. Test high temperature shutdown, pilot fail shutdown, flame fail shutdown, test low temperature shutdown. |
| Semi-annually: | Inspect, clean thermocouples and spark igniter |


2.6 LFG MONITORING FOR SYSTEM CONTROL

In order to optimize the gas recovery in terms of gas flow rate and gas quality, LFG System balancing was performed by adjusting the vacuum applied to each lateral and each well, and measuring the resulting gas quality and landfill vacuum. Methodology used was that given in the O & M Manual.


- Zone Valves A, K and L are 10 to 15% open as recommended in O&M Manual.
- During the January 2002 well balancing, Zone Valve G experienced excessive suction pressure. Valve G was closed 40% in order to maintain a suction pressure of 3 in. of water.
- Zone valve C was 90% closed during March 02 well balancing. Zone C has only two extraction wells, GE 9 and GE 10.
- GE 9 has been flooded since LMS started O&M. Despite several efforts to drain the water from the vault, it remains flooded due to its location in an area of low grade.
- GE 10, behind GE 9, has been reported having zero or positive suction pressure indicating blockage of the main line. Zone C, therefore, became inoperable. Zone C is located in the innermost area of the landfill; thus closing the zone valve should not post any risk of gas migration outside the landfill property.
- GE valve 36 & 42 were closed 90% due to its zero methane content.
- GE valve 41 and 47 were partially closed due to its low methane content.

All other extraction well valves are fully open, since the current operating flow rate is between 300 and 400 cfm, significantly below the rate for early period of operation. Though the balancing procedure as described in the O&M Manual assumed that the flare operates at about 600 cfm, it is still valid to follow in adjusting vacuum pressures throughout the extraction wells. However, the reduced gas production rate is best matched by opening the extraction well valves and adjusting the blower system valve accordingly.

August 2001




October 2001




November 2001

LFG Analysis, November 2001




January 2002


LFG Analysis, January 2002



February 2002



March 2002**



**Due to malfunction of the landfill portable gas analyzer, not all wells were sampled for gas analysis. The suction pressures, however, were all sampled

CHAPTER 3

LANDFILL GAS(LFG) SYSTEM FLARE CONTROL SYSTEM

This chapter provides a description of the monitoring/maintenance of the landfill gas system.

3.1 LFG GROUND FLARE CONTROL SYSTEM

The Automatic Flare control system provides temperature control by adjusting the amount of combustion air mixed with the gas via the electrically actuated air intake louvers. It also provides safety shutdowns for emergency conditions. The safety shutdowns are:

1. High Lower Explosive limit (each of 4 building combustible detectors & gas analyzer cabinet (GAC))
2. Blower Overload (each of 2 blowers)
3. High oxygen content in LFG
4. Low Methane content in LFG
5. Flame failure
6. Pilot failure
7. High Flame temperature
8. Low Flame temperature
9. Low Landfill Gas flow
10. Shutdown Valve Fail closed
11. Shutdown Valve Fail open
12. High liquid level in Condensate Tank

The control system receives signals from the sensors & detectors to monitor the operation of the enclosed ground flare. Malfunction of the sensing/detecting devices will trigger alarms and shutdowns of the system.

The landfill experienced several instrumentation problems from May 2001 to February 2002; the problems and their resolutions are described.

- A. Malfunction of the electrical power surge protector in the flare control station shut down the entire flare system. Flare operation was suspended from 5/28/01 to 6/8/01 due to this reason.

To solve this problem, the BP 1400 UPS unit was replaced. Flare was re-started in June 8, 2001.

- B. Several flare shutdowns at midnight revealed a minor software problem in the PLC. With the help of Perennial Energy, the PLC program was modified to fix this bug. The flare has not experienced midnight shutdown since 10/31/01.
- C. Two operator input devices, YIC-1 and YIC-2, in the flare control panel, experienced scrolling problems, resulting in the inability to change setpoints. Upon the town's approval, LMS performed replacement services of two OP1333 interfaces on 2/25/2002.
- D. The main incoming power conduit had settled with the surrounding soil, with the result that there was a separation of the conduit in its above grade portion. This problem was fixed in January 2002 by a new pull box installation on the settled conduit. A similar repair was done at the same time for the conduits between the condensate lift station and the flare control platform
- E. The temperature transmitter for the GAC temperature caused low temperature warning. This deficiency is being investigated.
- F. Incorrect gas readings have caused low methane warning. The Methane analyzer inside the GAC reads 0 % methane, whereas the portable gas analyzer read around 45%. The manufacturer is being contacted for further investigation. In the meantime, the flare temperature readings, taken several times per week, would provide an early warning that methane content of the gas to the flare was decreasing.

CHAPTER 4

LANDFILL GAS(LFG) SYSTEM OVERALL GAS VOLUME

This chapter discusses:

1. Quantitative analysis of gas recovery
2. Off-site monitoring of LFG

4.1 QUANTITATIVE ANALYSIS OF GAS RECOVERY

For the period April 1, 2001 to March 31, 2002, LMS kept a log sheet at the flare station to record flows, flare temperatures and blower run-time readings on a more frequent basis. The log sheet data are summarized below. The raw data sheets are attached in Appendix B.

The total LFG recovered during this period was 124.6 million cubic feet. Total estimated methane volume was 52 million cubic feet. Total operating time was 5720 hours, i.e., 65.3% uptime. Total number of shutdowns reported was 40, an average of 3.3 per month.

April 2001

| | Q(cfm) | 10-HR (B301) | 10-HR (B302) | Temp | Comments |
|---------|--------|--------------|--------------|------|----------|
| 3/29/01 | 327 | 1370 | | 1465 | |
| 4/5/01 | 344 | 1393 | | 1423 | |
| 4/6/01 | 311 | 1394 | | 1430 | |
| 4/23/01 | | | | | Down |
| 4/23/01 | 377 | 1424 | | 1475 | |

| | |
|--------------------|------------|
| Average Q (cfm) | 340 |
| Total Op.Hr | 540 |
| % in Operation | 75 |
| Gas Volume (cu.ft) | 11,016,000 |

May 2001

| | Q(cfm) | 10-HR | 10-HR | Temp | Comments |
|---------|--------|-------|-------|------|----------|
| 5/6/01 | 320 | 1440 | | 1442 | |
| 5/10/01 | | 1441 | | | Down |
| 5/10/01 | 373 | 1441 | | | |
| 5/20/01 | | 1451 | | | Down |
| 5/20/01 | 372 | 1451 | | 1455 | |
| 5/29/00 | | 1457 | | | Down |
| | | | | | No power |

| | |
|--------------------|-----------|
| Average Q (cfm) | 355 |
| Total Op.Hr | 330 |
| % in Operation | 46 |
| Gas Volume (cu.ft) | 7,029,000 |

June 2001

| | Q(cfm) | 10-HR | 10-HR | Temp | Comments |
|---------|--------|-------|-------|------|--------------|
| 6/8/01 | | 1457 | | | UPS fixed |
| 6/8/01 | 367 | 1457 | 1277 | 1436 | B302 started |
| 6/15/01 | 347 | | 1281 | 1471 | |
| 6/19/01 | | | 1287 | | Down |
| 6/19/01 | 370 | | 1287 | 1420 | |
| 6/22/01 | | | 1292 | | Down |
| 6/22/01 | 361 | | 1292 | 1460 | |
| 7/2/01 | | | 1296 | | Down |

| | |
|----------------|-----------|
| Average Q | 361 |
| Total Op.Hr | 190 |
| % in Operation | 26 |
| Gas Volume | 4,115,400 |

July 2001

| | Q(cfm) | 10-HR | 10-HR | Temp | Comments |
|---------|--------|-------|-------|------|--------------|
| 7/2/01 | 402 | 1457 | | 1461 | B301 Started |
| 7/6/01 | | 1461 | | | Down |
| | 407 | 1461 | | | |
| 7/13/01 | 391 | 1467 | | 1480 | |
| 7/19/01 | | 1472 | | | Down |
| 7/19/01 | 412 | 1472 | | | |
| 7/20/01 | 387 | 1475 | | | |
| 7/21/01 | | 1476 | | | Down |
| 7/25/01 | 415 | 1476 | | | |
| 8/2/01 | 390 | 1493 | | 1440 | |

| | |
|----------------|-----------|
| Average Q | 400 |
| Total Op.Hr | 360 |
| % in Operation | 50 |
| Gas Volume | 8,640,000 |

August 2001

| | Q(cfm) | 10-HR | 10-HR | Temp | Comments |
|--------|--------|-------|-------|------|----------|
| 8/2/01 | | 1493 | | | Down |
| 8/3/01 | 410 | | | | |
| 8/8/01 | | 1501 | | | Down |
| 8/9/01 | | 1505 | | | Down |
| 9/5/01 | 384 | 1540 | | 1429 | |

| | |
|----------------|------------|
| Average Q | 397 |
| Total Op.Hr | 500 |
| % in Operation | 69 |
| Gas Volume | 11,910,000 |

September 2001

| | Q(cfm) | 10-HR | 10-HR | Temp | Comments |
|---------|--------|-------|-------|------|----------|
| 9/7/01 | | 1540 | | | Down |
| 9/12/01 | | 1543 | | | Down |
| 9/12/01 | 400 | 1543 | | | |
| 9/17/01 | | 1549 | | | Down |
| 9/17/01 | 395 | 1549 | | | |
| 9/19/01 | 367 | 1554 | | 1398 | |
| 9/21/01 | 345 | 1558 | | 1382 | |
| 9/24/01 | | 1563 | | | Down |
| 9/26/01 | 369 | 1567 | | 1420 | |
| 10/8/01 | | 1588 | | | Down |

| | |
|----------------|------------|
| Average Q | 375 |
| Total Op.Hr | 480 |
| % in Operation | 67 |
| Gas Volume | 10,800,000 |

October 2001

| | Q(cfm) | 10-HR | 10-HR | Temp | Comments |
|----------|--------|-------|-------|------|----------|
| 10/8/01 | 403 | 1588 | | | |
| 10/15/01 | 396 | 1597 | | 1441 | |
| 10/17/01 | 368 | 1601 | | 1439 | |
| 10/18/01 | 345 | 1603 | | 1446 | |
| 10/19/01 | | 1605 | | | Down |
| 10/20/01 | 380 | 1608 | | 1400 | |
| 10/22/01 | 350 | 1612 | | 1425 | |
| 10/23/01 | | | | | Down |
| 10/24/01 | 378 | 1617 | | 1427 | |
| 10/25/01 | 364 | 1619 | | 1453 | |
| 10/26/01 | 355 | 1622 | | 1455 | |
| 10/28/01 | 320 | 1627 | | 1452 | |
| 10/29/01 | | 1628 | | | Down |
| 10/30/01 | 350 | 1630 | | 1447 | |
| 10/31/01 | | 1632 | | | Down |

| | |
|----------------|-----------|
| Average Q | 364 |
| Total Op.Hr | 440 |
| % in Operation | 80 |
| Gas Volume | 9,609,600 |

November 2001

| | Q(cfm) | 10-HR | 10-HR | Temp | Comments |
|----------|--------|-------|-------|------|----------|
| 11/1/01 | 386 | 1634 | | 1442 | |
| 11/5/01 | 348 | 1644 | | 1436 | |
| 11/6/01 | 320 | 1646 | | 1439 | |
| 11/7/01 | 313 | 1649 | | 1440 | |
| 11/9/01 | | 1654 | | | Down |
| 11/12/01 | 325 | 1661 | | 1441 | |
| 11/13/01 | | 1663 | | | Down |
| 11/15/01 | 365 | 1667 | | | |
| 11/16/01 | 348 | 1670 | | 1437 | |
| 11/17/01 | 325 | 1672 | | 1444 | |
| 11/19/01 | 320 | 1677 | | 1418 | |
| 11/20/01 | 305 | 1679 | | 1442 | |
| 11/21/01 | 365 | 1681 | | 1455 | |
| 11/26/01 | 318 | 1693 | | 1447 | |
| 11/27/01 | 285 | 1696 | | 1400 | |
| 11/28/01 | 350 | 1698 | | 1450 | |
| 11/29/01 | 340 | 1700 | | 1450 | |
| 11/30/01 | 355 | 1703 | | 1425 | |

| | |
|----------------|------------|
| Average Q | 335 |
| Total Op.Hr | 710 |
| % in Operation | 99 |
| Gas Volume | 14,271,000 |

| | | | | | |
|---------|-----|------|--|------|---------------------------|
| 1/25/02 | 324 | 1806 | | 1450 | |
| 1/28/02 | | 1812 | | | Down |
| 1/30/02 | 355 | 1817 | | 1425 | Turned off For service |


| | |
|----------------|------------|
| Average Q | 351 |
| Total Op.Hr | 620 |
| % in Operation | 86 |
| Gas Volume | 13,062,923 |

February 2002

| | Q(cfm) | 10-HR | 10-HR | Temp | Comments |
|---------|--------|-------|-------|------|--------------------------|
| 2/4/02 | | 1817 | | | Off for service |
| 2/6/02 | | 1817 | | | Restarted |
| 2/7/02 | 395 | 1819 | | 1439 | |
| 2/11/02 | 368 | 1829 | | 1475 | |
| 2/14/02 | 360 | 1836 | | 1433 | |
| 2/19/01 | 320 | 1848 | | 1430 | |
| 2/20/02 | 310 | 1851 | | 1443 | |
| 2/22/02 | | 1855 | | | Off for calibrations |
| 2/22/02 | 380 | 1855 | | 1450 | Restarted |
| 2/25/02 | | 1856 | | | Down, breaker tripped |
| 2/27/02 | | | | | Flame fail |
| 2/27/02 | 380 | | 1296 | 1452 | B302 started |

| | |
|----------------|-----------|
| Average Q | 359 |
| Total Op.Hr | 390 |
| % in Operation | 58 |
| Gas Volume | 8,400,600 |


**Monitoring Well #3
Clarkstown Landfill**



4.2.2 Monitoring Well #4

| Monitoring Well #4 | | | | | |
|--------------------|---------|---------|-------------------------|-----------|-----------|
| Date | CH4 (%) | CO2 (%) | Total LFG (Million ft³) | CH4 (ppm) | CO2 (ppm) |
| 11-23-Apr | | | | | |
| 4-22-Jun | | | | | |
| 11-24-Sep | | | | | |
| 10-26-Oct | 1 | 18 | 2 | 79 | |
| 14-28-Nov | 1 | 19 | 1 | 79 | |
| 13-14-Jan | | | | | |
| 8-20-Feb | 0 | 19 | 1 | 80 | |
| 15-13-Mar | 0 | 19 | 1 | 80 | |


**Monitoring Well #4
Clarkstown Landfill**



4.2.3 Monitoring Well #9

| Monitoring Well #9 Data | | | | | |
|-------------------------|--------|---------|---------|--------------------------------|---------------------|
| Day | Date | CH4 (%) | CO2 (%) | Total LFG Volume (Million ft³) | 10-Hr Operation (%) |
| 11 | 23-Apr | 31 | 6 | 2 | 61 |
| 4 | 22-Jun | 9 | 9 | 9 | 74 |
| 11 | 24-Sep | 6 | 3 | 14 | 78 |
| 10 | 26-Oct | 2 | 20 | 2 | 77 |
| 14 | 28-Nov | 6 | 17 | 3 | 73 |
| 13 | 14-Jan | 2 | 20 | 0 | 78 |
| 8 | 20-Feb | 15 | 13 | 3 | 69 |
| 15 | 13-Mar | 2 | 20 | 1 | 78 |


**Monitoring Well #9
Clarkstown Landfill**



4.2.4 Monitoring Well #10

| Monitoring Well #10 | | | | | |
|---------------------|---------|---------|-------------------------|-----------|-----------|
| Date | CH4 (%) | CO2 (%) | Total LFG (Million ft³) | CH4 (ppm) | CO2 (ppm) |
| 11-23-Apr | 0 | 14 | 4 | 82 | |
| 4-22-Jun | 1 | 3 | 15 | 61.6 | |
| 11-24-Sep | 0 | 2 | 15 | 83 | |
| 10-26-Oct | 1 | 1 | 15 | 83 | |
| 14-28-Nov | 1 | 3 | 13 | 83 | |
| 13-14-Jan | 0 | 15 | 5 | 80 | |
| 8-20-Feb | 0 | 13 | 5 | 83 | |
| 15-13-Mar | 2 | 20 | 1 | 78 | |

**Monitoring Well #10
Clarkstown Landfill**



CHAPTER 5

OTHER LANDFILL GAS (LFG) SYSTEMS

This chapter provides the inspection/maintenance reports for

1. LFG knockout Tank and LFG Condensate Pump Station
2. Aboveground LFG Condensate Storage Tank
3. Landfill Final Cover System

5.1 LFG KNOCKOUT TANK AND LFG CONDENSATE PUMP STATION

During the repairs to the electrical conduits at the flare station in January 2002, it was discovered that the piping between the LFG knockout tank and the blowers had a leak at the knockout tank connection, due to ground settlement. On February 5th, repair work was performed by re-welding the connection at the knockout tank. A detailed service memo is attached in Appendix C. In order to avoid further settling, the area remains partially open with the pipe exposed.

Routine visual inspection of the leachate collection chambers and surrounding area was performed on a monthly base. Not all of the pump stations appeared to be operable. Pump station #2, #4 and #7 did not turn on under "Hand" operation. Visual inspection of the collection chamber, however, indicated that the water level in each was below the inlet inverts. This ensured that there was no ongoing loss of leachate off the site. In addition to the inoperability of the pumps, the signal back to the main service building was reported to be having problems.

Leachate pump station #1 has experienced excess incoming flow throughout the reporting period. Manual pumping with the existing submersible pump failed to drain the collection chamber indicating significant inflow into the chamber. The source and nature of the infiltration is being investigated.

5.2 ABOVEGROUND LFG CONDENSATE STORAGE TANK

Annual routine visual inspection of tank, piping, valves, and other appurtenant items was performed; quarterly testing of the leak detection system and weekly inspection of vents were conducted to assure there is no restriction in flow.

5.3 LANDFILL FINAL COVER SYSTEM

Final cover inspection was performed quarterly according to the inspection procedures for the final cover described on the checklist and form FCS-1 in Appendix A. As noted in the forms, there has been several minor problems related to settling, i.e., the soil settling caused pipe sagging, as discussed in Chapter 2. There is no major deficiency related to the final cover system of the facility.