Yearn # 2

Five-Year Review Report
Ramapo Landfill Superfund Site
Rockland County
Town of Ramapo, New York

# Prepared by:

United States Environmental Protection Agency Region 2 New York, New York

December 2004

# **EXECUTIVE SUMMARY**

A second five-year review for the Ramapo Landfill Superfund site, located in the Town of Ramapo, Rockland County, New York, was completed. Based upon a review of the Record of Decision, Remedial Action Report, operation and maintenance reports, and Explanation of Significant Differences, and an inspection of the site, it has been concluded that the remedy at the site functions as intended by the decision documents and protects human health and the environment.

# Five-Year Review Summary Form

SITE IDENTIFICATION					
Site Name (from WasteLAN): Ramapo Landfill					
EPA ID (from WasteLAN): NYD000511493					
Region: 2 State: NY City/County: Town of Ramapo/Rockland County					
		SITE	STATUS		
NPL Status: ■	Final □ Deleted □	Other (specify	y)		
Remediation Status (choose all that apply): ☐ Under Construction ☐ Operating ■ Complete					
Multiple OUs? ☐ YES ■ NO Construction completion date: September 30, 1997					
Are portions of the site in use or suitable for reuse? ■ YES □ NO □ N/A					
		REVIE	W STATUS		
Lead agency: ☐ EPA ■ State ☐ Tribe ☐ Other Federal Agency					
Author name: G	uthor name: George Jacob				
Author title: Remedial Project Manager Author affiliation: EPA					
Review period:** 12/1999 to 12/2004					
Date(s) of site inspection: 11/23/04					
Type of review:  □ Post-SARA □ Pre-SARA □ NPL-Removal only □ Non-NPL Remedial Action Site □ NPL State/Tribe-lead □ Regional Discretion □ Policy ■ Statutory					
Review number: □ 1 (first) ■ 2 (second) □ 3 (third) □ Other (specify)					
Triggering action  ☐ Actual RA Onsition Coonstruction Coonstruction Coonstruction Coonstruction Coonstruction Coonstruction Coonstruction Coonstruction	te Construction at ompletion	OU#	☐ Actual RA Start at OU#  ■ Previous Five-Year Review Report		
Triggering action	Triggering action date (from WasteLAN): 12/23/1999				
Due date (five years after triggering action date): 12/23/2004					
Does the report include recommendation(s) and follow-up action(s)? ☐ yes ☐ no Is human exposure under control? ☐ yes ☐ no Is migration of contaminated groundwater stabilized? ☐ yes ☐ no ☐ not yet determined Is the remedy protective of the environment? ☐ yes ☐ no ☐ not yet determined Acres in use or available for use: restricted: 50 acres unrestricted:					

# **Five-Year Review Summary Form (continued)**

# Issues, Recommendations, and Follow-Up Actions

The current monitoring well network does not allow for a determination of a groundwater capture zone nor give early warning regarding potential contaminant migration to downgradient drinking water wells. In addition, it is unclear whether antimony detected in these wells is site-related.

Additional groundwater monitoring wells need to be installed. Until it can be determined, based upon the results of sampling from the new monitoring wells, whether or not the antimony detected in the downgradient drinking water wells is site-related, it is recommended that bottled water and/or point-of-use treatment be provided.

If it is determined that the site is the source of the antimony detected in the downgradient drinking water wells, the alternate water supply contingency remedy may need to be implemented. In addition, the Town may need to implement institutional controls to restrict the use of off-site groundwater.

#### Protectiveness Statement

Based upon a review of the ROD, Remedial Action Report, and O&M Reports and an inspection of the site, it has been concluded that the remedy at the site functions as intended by the decision documents and protects the environment. Further investigation is necessary, however, to ascertain whether the remedy is protective of human health.

#### **Other Comments**

Other Comments on Operation, Maintenance, Monitoring, and Institutional Controls

Groundwater contaminant concentrations have increased in several on-site monitoring wells and contaminant concentrations and flow rates for the groundwater extraction wells are needed to adequately assess the effectiveness of the contaminated groundwater/leachate collection system. In addition, in accordance with best management practices of outdoor shooting ranges, berms should be covered by a roof to prevent erosion of the berm and increased lead mobility. One monitoring well has been damaged and one well requires a new locking cap.

New York State now requires annual certifications that institutional controls that are required by RODs are in place and that remedy-related O&M is being performed. To comply with this requirement, on an annual basis, the site will need to be inspected to determine whether any intrusive activities have been performed at the site and the building and property records will need to be reviewed to ascertain whether or not any filings had been made for such activities. The annual O&M report that is currently submitted by the Town should include a summary of the findings of the above-noted activities, along with certification that remedy-related O&M is being performed.

# Technical Assessment Summary

Based upon the results of the five-year review, it has been concluded that the cap and vegetative cover are intact and in good condition, the fence around the cap within the site is intact and in good repair, at least two groundwater monitoring wells require attention, during the review period, antimony has been detected consistently above MCLs in downgradient drinking water wells, inadequate data exists to determine the effectiveness of the groundwater extraction system; and there are no restrictions on the installation of wells downgradient of site (such restrictions may be necessary if the recommended groundwater investigation determines that the site is the source of the antimony detected in downgradient drinking water wells).

#### I. Introduction

This second five-year review for the Ramapo Landfill site, located in the Town of Ramapo, Rockland County, New York, was conducted by United States Environmental Protection Agency (EPA) Remedial Project Manager (RPM) George Jacob. The review was conducted pursuant to Section 121(c) of the Comprehensive Environmental Response, Compensation, and Liability Act, as amended, 42 U.S.C. §9601 *et seq.* and 40 CFR 300.430(f)(4)(ii) and in accordance with the Comprehensive Five-Year Review Guidance, OSWER Directive 9355.7-03B-P (June 2001). The purpose of five-year reviews is to ensure that implemented remedies protect public health and the environment and that they function as intended by the site decision documents. This report will become part of the site file.

A five-year review is required at this site due to the fact that hazardous substances, pollutants, or contaminants remain at the site above levels that allow for unlimited use and unrestricted exposure.

In accordance with Section 1.3.3 of the five-year review guidance, a subsequent statutory five-year review is triggered by the signing date of the previous five-year review report. The first five-year review was signed on December 23, 1999.

This five-year review found that the implemented remedy is functioning as intended and continues to protect human health and the environment.

# II. Site Chronology

Table 1 (attached) summarize the site-related events from discovery to construction completion.

# III. Background

Site Location

The Ramapo Landfill site is located in the Town of Ramapo, Rockland County, New York, about 35 miles northwest of New York City and 1 mile northeast of the Village of Hillburn, New York. The site is situated at the western base of the Ramapo Mountains off Torne Valley Road east of the New York State Thruway, Route 17, and Route 59.

#### Physical Characteristics

The landfill is situated on a 96-acre tract. Approximately 50 acres of the site (the landfill portion) are covered with fill material. The landfill portion of the site is mounded into two major lobes (northern and southern), and slopes steeply toward the west with grades ranging from less than one percent to greater than 30 percent. Both landfill lobes consist of mixed refuse. Substances

reportedly disposed of in the landfill include industrial sludge and other wastes reportedly from a pharmaceutical company, sewage sludge, municipal refuse, asbestos, construction and demolition debris, yard debris, paint sludge (presumably from an automotive plant), and liquid wastes reportedly from a paper company.

Utility corridors lie on three sides of the site, high voltage power transmission lines to the east and west, and a high pressure gas line to the south. A power substation is located just north of the site.

The main surface waters in the vicinity of the site are the Ramapo River, Torne Brook, and Candle Brook. The Ramapo River, located approximately 300 feet from the southwest corner of the site, is a New York State Department of Environmental Conservation (NYSDEC) Class "A" waters, which may be used as a source of water supply for drinking, culinary, or food-processing purposes. Torne Brook, which flows near the western boundary of the site, and Candle Brook, a tributary of Torne Brook, are NYSDEC Class "B" waters, suitable for primary contact recreation and any other use, except as a source of water supply for drinking, culinary, or food-processing purposes.

The United States Geological Survey has identified an area of less than ten acres near the headwaters of Candle Brook as a wetland.

# Site Geology/Hydrogeology

The site is underlain by a sequence of glacially derived unconsolidated sediments that overly bedrock, which is comprised of granitic and biotite gneiss. The bedrock geology is structurally complex with numerous fault systems in the area. A fracture trace analysis identified a number of lineaments in the vicinity of the site, the most obvious one being the Ramapo fault (approximately 1.25 miles southeast of the site), which strikes northeast and dips steeply southeast. Two other lineaments observed within the immediate area of the landfill include one that lies adjacent to the west side of the landfill and trends northeast. This lineament may represent faulting or other subsurface structures controlling deflections in Torne Brook. The second lineament trends east-west and appears to cross the central portion of the landfill.

The shallow aquifer is comprised of permeable sediments consisting of a grey to brown, very loose to loose sand or sandy gravel with some silt with a hydraulic conductivity on the order of 1 x  $10^{-4}$  cm/sec and a medium-dense to very dense silty sand or gravelly sand with abundant bolders and cobbles with hydraulic conductivity values ranging from  $5.1 \times 10^{-5}$  to  $1.4 \times 10^{-4}$  cm/sec. Below these sand units is a thin weathered rock zone ranging in thickness from a few inches to nearly five feet with hydraulic conductivity values ranging from  $4 \times 10^{-5}$  to  $1.5 \times 10^{-3}$  cm/sec. Underlying the weathered rock zone is a granitic and biotite gneiss bedrock aquifer. In some locations, highly fractured zones were found within the bedrock suggesting faulting. Hydraulic conductivity values for the bedrock aquifer ranged from  $8.9 \times 10^{-5}$  to  $1 \times 10^{-2}$  cm/sec.

Past investigations found that shallow groundwater generally flows towards Torne Brook and the Ramapo River with Torne Brook acting as the discharge area for the water table aquifer and that

groundwater in the bedrock aquifer likely flows beneath Torne Brook. Vertical flow measurements indicated that groundwater generally flows downward.

#### Land and Resource Use

Adjacent to the landfill, the Town of Ramapo currently operates a compaction and transfer facility. Trash and debris are weighed at a weigh station/guard house along Torne Valley Road, compacted at a baler facility adjacent to the site and then transferred to another facility.

A pistol range utilized by the Town of Ramapo Police Department is located in the northeastern area of the site.

Groundwater is withdrawn from the area south and west of the site for residential use. Ten water supply wells, operated by the Spring Valley Water Supply Company and serving a population of over 200,000, are located along the Ramapo River both upstream and downstream of the site. Four of these wells are located within 1,500 feet of the landfill. The closest of these wells lies approximately 500 feet west of the site on the west bank of the Ramapo River. Torne Brook Estate, a residential apartment complex of 25 units, has a water well 450 feet from the landfill. A 2-unit apartment building maintains a water well about 1,200 feet from the landfill.

## History of Contamination

Prior to landfill operations in the 1950s and 1960s, portions of the site were excavated as a source of gravel. In 1971, the Rockland County Department of Health granted a permit to the Town of Ramapo for the operation of the sanitary landfill. At that time, the site was owned by the Ramapo Land Company and the contract-operator was the Torne Mountain Sand and Gravel Co., Inc.

In 1976, a contract was awarded to Carmine Franco of Sorgine Construction Services of New York, Inc., for the operation and maintenance of the landfill. The contract was terminated by the Town of Ramapo in 1979, when the Town began operating the landfill directly. Municipal waste was accepted in the landfill until 1984. The Town of Ramapo continued to accept construction and demolition debris at the landfill until 1989.

A leachate collection system was constructed along the downgradient edge of the landfill from 1984 to 1985. The collected leachate was conveyed to a wastewater treatment pond in the site's southwest corner. After aeration and settling in the pond, the water was discharged to the Ramapo River. Beginning in November 1990, the collected leachate was discharged to the Village of Suffern Wastewater Treatment Plant via a 7,900-foot sewer line.

# Initial Response

In September 1983, the Ramapo Landfill site was placed on the Superfund National Priorities List.

From June 1980 through October 1986, NYSDEC and the Town of Ramapo entered into three Orders on Consent related to phasing out the operation of the landfill, determining the extent of

leachate movement and the feasibility of leachate collection, and constructing a surface-water and groundwater-diversion system, leachate-collection system, and a system capable of transporting or treating the collected leachate.

On February 1, 1988, the Town entered into its fourth and current Order on Consent (Index No. W3-0083-8707) with NYSDEC. This Order required that a remedial investigation and feasibility study (RI/FS) be performed for the site and that the design and construction of the remedy that was to be ultimately selected be undertaken. The Town also received a Title 3, Environmental Bond Act grant to assist it in performing the remedial activities called for by the Order.

#### Basis for Taking Action

The results of the RI revealed that volatile organic compounds (VOCs) were detected in three waste sample (landfill material and paint sludge) locations, ranging from 0.002 milligrams per kilogram (mg/kg) to 110 (mg/kg); VOCs were not detected in any of the surface soil samples. Semi-volatile compounds, including polycyclic aromatic hydrocarbons, were detected in waste samples and surface soil samples at concentrations ranging from 0.042 mg/kg to 16 mg/kg. Antimony, barium, beryllium, cadmium, calcium, chromium, copper, lead, selenium, and zinc were detected in surface soil and waste samples at concentrations exceeding background by an order of magnitude. NYSDEC Water Quality Standards and Guidelines and/or EPA Maximum Contaminant Levels (MCLs)¹ were exceeded for arsenic, chromium, iron, lead, magnesium, manganese, mercury, sodium, benzene, chlorobenzene, and di-n-octyl phthalate in on-site groundwater monitoring wells. No federal or state drinking water standards were exceeded in groundwater samples collected from the nearby public or private water supply wells during the RI.

Surface water samples were collected from Torne Brook, the Ramapo River near the confluence of Torne Brook, a drainage swale on an adjacent property, and two leachate seeps emanating from the landfill. At all surface water locations that were sampled, New York State surface water standards were exceeded for one or more of the following contaminants: vinyl chloride, antimony, arsenic, iron, manganese, mercury, nickel, zinc, ammonia, sulfide, copper, and lead. The highest frequency of the detections above the standards occurred near the confluence of Torne Brook and the Ramapo River, where water from the on-site leachate holding pond was being discharged to the Ramapo River. Three semi-volatile compounds were detected in a sediment sample collected in Torne Brook at concentrations below NYSDEC sediment cleanup criteria. Inorganic compounds detected in sediments which exceeded background concentrations by at least an order of magnitude included antimony, calcium, manganese, and thallium.

The MCL is the highest level of contaminant that is allowed in drinking water. MCLs are promulgated standards that apply to public water systems and are intended to protect human health by limiting the levels of contaminants in drinking water.

#### IV. Remedial Actions

# Remedy Selection

Based upon the results of the RI/FS, in March 1992, EPA signed a ROD for the site, calling for, among other things:

- Installation of a cap on the top of the landfill using a multimedia system, including layers of fill material, a gas-venting system and an impermeable membrane. The landfill side slopes would be capped using a multimedia system without an impermeable membrane if confirmatory studies demonstrated that this approach met the remedial action objectives. Should the confirmatory studies indicate that the overall remedy's effectiveness would be significantly reduced by not including an impermeable barrier in the multimedia cap on the sideslopes, then an impermeable barrier was to be included in the cap on some or all of the side slopes of the landfill;
- Installation of a perimeter drain around the sections of the cap containing the impermeable membrane to collect and divert surface water runoff;
- Installation of groundwater extraction wells to contain the groundwater contamination;
- Collection and diversion of leachate seeps to the existing leachate collection system;
- Conveyance of the collected leachate and contaminated groundwater via the sewer system to a local wastewater treatment facility;
- Imposition of property deed restrictions which would include measures to prevent the installation of drinking water wells at the site, and restrict activities which could affect the integrity of the cap;
- Performance of a maintenance and sampling program upon completion of closure activities. The monitoring program will provide data to evaluate the effectiveness of the remedial effort. Additional monitoring points would be established as needed to detect any future movement of site contaminants toward drinking water sources off-site;
- Development of a contingency plan for rapid implementation of additional measures to protect nearby residents and users of groundwater if those measures are determined to be necessary.

#### Remedy Implementation

The Town of Ramapo retained URS Consultants, Inc. of Buffalo, New York to conduct the remedial design (RD), solicit and obtain bids for the landfill closure, and provide construction administration and resident engineering.

As was noted above, the ROD stated that an impermeable barrier would be placed on the landfill's side slopes if confirmatory studies indicated that the remedy's overall effectiveness would be significantly enhanced. The confirmatory studies indicated that the exclusion of an impermeable barrier from the landfill cap on the side slopes would result in increased infiltration of rainfall through the cap. This would cause the generation of greater quantities of contaminated groundwater, which would result in greater operational costs to collect and treat a larger volume of contaminated groundwater and leachate. In addition, it was determined that either a thicker soil cover or an impermeable barrier would be needed on the side slopes to provide adequate control of landfill gases. The impermeable barrier was found to be the less costly of the two options. Therefore, based upon the results of the confirmatory studies, it was concluded that a cap with an impermeable barrier on the landfill's side slopes would be more protective and more cost-effective than a cap without an impermeable barrier on the side slopes. An Explanation of Significant Differences (ESD) was issued in November 26, 1997 to document these findings.

The RD, which was prepared by URS Greiner Inc., was approved by NYSDEC in 1992. The RD not only included the plans and specifications for the construction of the landfill cap and expanding the leachate collection system, but also included a preliminary design (contingency plan) for the connection of nearby residents to the Pothat Water Company water line should groundwater monitoring data indicate that groundwater standards are being contravened.

A construction contract was awarded to Geo-Con Inc. in 1993. Construction of the site remedy began on December 26, 1994 and was substantially completed on May 30, 1997.

The construction effort involved the construction of a landfill cap (a gas venting layer, a textured 40 mil high density polyethylene geomembrane liner, a 12 inch barrier protection layer, and a 6-inch topsoil layer) and the expansion of the existing leachate collection system to enhance its recovery of contaminated groundwater.

### Institutional Controls Implementation

Although the ROD required the implementation of institutional controls to restrict the use of on-site groundwater and to protect the integrity of the cap, since the site property is municipally-owned, NYSDEC did not require the Town to obtain property deed restrictions to prevent the installation of drinking water wells at the site and restrict activities which could affect the integrity of the cap. The Town has, however, prepared the appropriate language for restrictions to be incorporated into the deed in the event that there is any change anticipated in the ownership/operation of the property.

If the recommended groundwater investigation (see Table 7) determines that the site is a source or potential source of contamination to downgradient areas, the Town may need to implement institutional controls to restrict the use of off-site groundwater.

System Operations/Operation and Maintenance

An Operation and Maintenance Manual, covering post-landfill cap construction inspection and maintenance procedures, was submitted and approved by NYSDEC as part of the RD. During the first year following the landfill cap construction, the site was inspected quarterly and following heavy storm events. For the subsequent years, the site has been inspected on a quarterly basis as follows:

- The site is inspected for debris, litter and/or waste.
- The landfill cap is inspected for vegetation loss due to erosion or poor grass growth. Annual ground inspections at the beginning of each summer also note the status of woody plant species on the landfill surface and side slopes.
- The landfill cap is inspected for settlement, ponding, and animal borrows.
- The gas venting pipes are inspected for damage.
- The site access gate and fence are inspected for operational locks and vandalism.
- The culverts, drainage ditches, and level spreaders are inspected for sediment buildup or erosion.
- The groundwater monitoring wells are inspected for operational locks, damage, and vandalism.

The inspections, maintenance, sampling, monitoring, data evaluation and reporting costs are approximately \$135,000 on an annual basis; these costs are broken down in Table 2 (attached).

# V. Progress Since the Last Five-Year Report

The first five-year review for this site was approved on December 23, 1999, pursuant to OSWER Directives 9355.7-02 (1991), 9355.7-02A (1994), and 9355.7-03A (1995).

At the time of the first five-year review, two downchutes had been damaged by storms in the Summer of 1999, and the damage was exacerbated by impacts from Hurricane Floyd in September 1999. Damage to one downchute was minimal, but damage to the other downchute (1,000-foot long and rip-rap-lined, located between the north and south lobes) was more significant. Also, the soil cover had eroded in some locations and geocomposite was exposed and/or severely damaged.

Since only two years of on-site groundwater data has been generated following the construction of the cap, the 1999 five-year review could not draw any conclusions about the effectiveness of the cap or establish whether groundwater contaminant levels were being reduced.

The 1999 five-year review concluded that, while measures needed to be undertaken to remedy the storm damage, the implemented remedy was protective of human health and the environment. NYSDEC and EPA would continue to monitor groundwater data to determine if groundwater contaminant levels decrease as expected, and if any additional measures are needed to protect nearby residents and users of groundwater as specified in the ROD.

The recommendations and follow-up actions identified in the previous five-year review were related to the needed repairs to the cap. Subsequently, the Town redesigned some of the surficial drainage management features to meet 100-year flood criteria, repaired the damaged geocomposite, and replaced the lost soil and vegetative cover.

#### VI. Five-Year Review Process

# Administrative Components

The five-year review team consisted of George Jacob (RPM), Diana Cutt (Hydrogeologist), Julie McPherson (Human Health Risk Assessor), and Chris Stitt (Ecological Risk Assessor, Biological Technical Assistance Group).

# Community Involvement

The EPA Community Involvement Coordinator for the Sidney Landfill site, Cecilia Echols, published a notice in the *Journal Newspaper*, a local newspaper, on December 16, 2004, notifying the community of the initiation of the five-year review process. The notice indicated that EPA would be conducting a five-year review of the site to ensure that the site is protective of public health and the environment and that the implemented components of the remedy are functioning as designed. It was also indicated that once the five-year review is completed, the results will be made available in the local site repository. In addition, the notice included the RPM's address and telephone number for questions related to the five-year review process or the Ramapo Landfill site. A similar notice will be published when the review is completed.

#### Document Review

The documents, data, and information which were reviewed in completing the five-year review are summarized in Table 3 (attached).

#### Data Review

During the previous five-year review, federal or state drinking water standards were sporadically exceeded for ammonia, antimony, iron, lead, manganese, sodium, xylene, and zinc in samples

collected from nearby public (United Water New York) and private drinking water supply wells. The exceedances of lead, sodium, xylene, and zinc in the drinking water wells were not believed to be site-related<sup>2</sup>. Antimony was detected in one United Water New York supply well sample at 17.1 micrograms per liter ( $\mu$ g/l) collected in December 1995 and in samples collected in June 1998 and September 1998 from a private well at 6.7  $\mu$ g/l and 11.3  $\mu$ g/l, respectively. Antimony was not detected in the last three sampling rounds. Ammonia, which is believed to be site-related, was detected above groundwater standards in three drinking water samples collected through 1995. In 1995, ammonia and nitrate were replaced as site indicator parameters with Total Kjeldahl Nitrogen (TKN), a measure of the combined concentration of ammonia and most forms of organic nitrogen. TKN was detected at slightly elevated levels in two drinking water samples in 1997, but has since been detected at lower levels. The standards for iron and manganese are secondary standards since they affect the aesthetic qualities of drinking water (*i.e.*, taste, odor, staining of fixtures), rather than pose a health risk.

Groundwater monitoring of the on-site wells and the downgradient potable wells has been performed three times a year since 1997. At the onset of the monitoring, the parameters included a comprehensive list of compounds for the majority of wells and surface water sampling points at the landfill. As a result of a review of data and discussions with the Town of Ramapo, URS Greiner Woodward Clyde, NYSDEC, the New York State Department of Health, and EPA, the number of sampling points and the monitoring parameters were reduced.

Groundwater monitoring during the review period shows exceedances of federal or state MCLs for aluminum, antimony, arsenic, barium, beryllium, cadmium, chromium, iron, manganese, nickel and thallium in on-site groundwater monitoring wells (see Table 4).

The closest downgradient residential wells and public supply wells are currently being monitored as part of the monitoring program three times a year. During the review period, arsenic, iron, lead, manganese and thallium concentrations sporadically exceeded their respective MCL and/or Preliminary Remediation Goals (PRGs)<sup>3</sup> in a number of these wells (see Table 5). Since lead exceeded the action level once within the last five years in a private well at 81.9 µg/l, which exceeded the maximum detected concentration in the on-site monitoring well (41.1 µg/l), this suggests that the concentration detected at the off-site location is not site-related. Arsenic has exceeded its PRG; however, the maximum detected concentration is within EPA's cancer risk range and has not exceeded its respective MCL. Iron and manganese exceeded their respective MCLs; however, as was noted above, these values are secondary drinking water standards, which are not enforceable guidelines (it should be noted, howver, that the maximum detected concentrations of iron and manganese did not exceed their respective PRGs). Antimony is the only contaminant that was consistently detected above its MCL in a potable supply well during the review period. It is

Xylene and zinc were not detected above groundwater standards in on-site groundwater. Lead was detected above groundwater standards in on-site groundwater, but was detected at higher levels and at a greater frequency in drinking water samples. Sodium has historically been detected at elevated levels in upgradient, as well as, downgradient groundwater samples.

PRGs are a human health risk-based value that is equivalent to a cancer risk (CR) of 1 x 10<sup>-6</sup> or a hazard index (HI) of 1.

unclear, however, whether the concentrations of antimony detected in these wells are site-related, since there is an inadequate network of wells between the site extraction wells and the public supply wells to confirm that site-related contaminants are migrating off-site.

Interviews

No interviews were conducted for this review.

Site Inspection

On November 23, 2004, a 5-year review-related site inspection was conducted by EPA Personnel, George Jacob, Diana Cutt, Julie McPherson, and Christopher Stitt. Also present at the site inspection were Ted Dzurinko and Edward Moran of Town of Ramapo, and Sabian Endra Mahamooth, NYSDEC project manager.

Institutional Controls Verification

Although the ROD required the implementation of institutional controls to restrict the use of on-site groundwater and to protect the integrity of the cap, since the site property is municipally-owned, NYSDEC did not require the Town to obtain property deed restrictions to prevent the installation of drinking water wells at the site and restrict activities which could affect the integrity of the cap. The Town has, however, prepared the appropriate language for restrictions to be incorporated into the deed in the event that there is any change anticipated in the ownership/operation of the property. New York State now requires annual certifications that institutional controls that are required by RODs are in place and that remedy-related O&M is being performed. To comply with this requirement, on an annual basis, the site will need to be inspected to determine whether any intrusive activities have been performed at the site and the building and property records will need to be reviewed to ascertain whether or not any filings had been made for such activities. The annual O&M report that is currently submitted by the Town should include a summary of the findings of the above-noted activities, along with certifications that remedy-related O&M is being performed.

Other Comments on Operation, Maintenance, Monitoring, and Institutional Controls

Table 6 (attached) summarizes several observations and offers suggestions to resolve the issues.

#### VI. Technical Assessment

Question A: Is the remedy functioning as intended by the decision documents?

The ROD, as modified by the ESD, called for, among other things, the installation of a cap with an impermeable barrier and groundwater and leachate collection and treatment. The purpose of the response action was to reduce the risk to human health and the environment due to contaminants leaching from the landfill mound. The capping of the landfill was to minimize the infiltration of rainfall and snowmelt into the landfill, thereby reducing the potential for contaminants leaching from

the landfill and negatively impacting the wetlands habitat and groundwater quality. Capping was to also prevent direct contact exposure to contaminated soils. Pumping and treating the contaminated groundwater was to contain the groundwater contamination within the site boundary to ensure that groundwater beyond the site boundary meets Applicable or Relevant and Appropriate Requirements (ARARs) for groundwater.

The groundwater remedy (extraction and treatment) has not yet resulted in restoration of groundwater to meet ARARs. The success of the groundwater extraction system in containing and remediating the contaminant plume as intended by the decision documents is difficult to determine at this time. Typically, the success of a groundwater remedy is measured by analysis of groundwater elevations demonstrating consistent plume capture over time, decreasing concentrations in groundwater over time, and data from groundwater extraction wells demonstrating that the wells are consistently operational and are extracting contaminated groundwater.

The monitoring well network is comprised of well clusters aligned in a general northeast to southwest direction along the west side of the landfill, generally parallel to the groundwater extraction wells. With the exception of one well cluster (MW-9), there are no wells radiating from the landfill that would aid in the determination of a capture zone.

In the absence of adequate groundwater elevation data, the second line of evidence in demonstrating the success of the groundwater remedy would be decreasing contaminant concentrations in groudwater over time. The groundwater monitoring data for the site shows continuing MCL exceedances for constituents, such as chromium, antimony, arsenic, and cadmium (see Tables 4 and 5) in monitoring wells. The data does not demonstrate decreasing concentrations over time. Rather, concentrations in certain wells (MW-1OS, MW-1R, MW-3OS, MW-3R, MW-7OS) show an increase over time. Chromium concentrations in MW-3OS, for example, show a general increase from 257  $\mu$ g/l in March 2002, to 1400  $\mu$ g/l in October 2002, to 4250  $\mu$ g/l in April 2003. Additionally concentrations in other wells (*i.e.*, 2-OS) are erratic and show no pattern.

Question B: Are the exposure assumptions, toxicity data, cleanup levels, and remedial action objectives used at the time of the remedy still valid?

The majority of the exposure pathways and the receptor populations identified in the 1991 Baseline Human Health Risk Assessment are still valid. Although some exposure assumptions have changed and several exposure pathways were not evaluated, it is not expected to effect the remedy.

The toxicity values for several contaminants of potential concern (COPCs) have changed since the RI. In order to account for changes in toxicity values since the RI, the maximum detected concentrations of COPCs in monitoring wells during the review period were compared to their respective residential groundwater PRGs and MCLs. As can be seen in Table 4, aluminum, antimony, arsenic, barium, beryllium, cadmium, chromium, iron, manganese, nickel and thallium exceeded their respective MCL and/or PRG on-site. Currently, there are no institutional controls on-site to restrict groundwater use, since the site property is currently owned by the town of Ramapo. Since, NYSDEC did not require deed restrictions to be implemented on-site, it is reasonable to assume that wells maybe installed downgradient for potable use.

The closest downgradient residential wells (PW-1 and PW-2) and the public supply wells (SWVC 93-96) are currently being monitored as part of the monitoring program three times a year. During the review period, antimony, arsenic, iron, lead, manganese and thallium concentrations exceeded their respective MCL and/or PRG (CR =  $1 \times 10^{-6}$  or HI = 1) in these potable supply wells (Table 5).

The remedial action objectives established in the ROD are still valid.

Question C: Has any other information come to light that could call into question the protectiveness of the remedy?

A portion of the site is currently being utilized as a shooting range by the Ramapo Police Department. The shooting range was constructed so that the ammunition fired would enter a berm constructed for the purposes of the shooting range. In accordance with best management practices of outdoor shooting ranges, berms should be covered by a roof to prevent erosion of the berm and increased lead mobility. During the five-year review site inspection, it was observed that a roof was not present and expended bullets were present and accumulating on the ground. Potential human exposure to lead exists at the site through various exposure pathways as a result of the lack of management practices conducted at the shooting range. The primary exposure of lead to humans as a result of shooting range activities is through incidental ingestion of lead contaminated soil. An additional exposure pathway that individuals may be exposed to lead from shooting range activities is by lead bullets or lead particles moving via storm water runoff into the downgradient surface water areas (Torne Brook, Ramapo River and the adjacent wetland). The Torne Brook and Ramapo River are used for recreational purposes, which include swimming and fishing. Dissolved lead may also migrate through soils and leach into the groundwater. However, since an impermeable cap is placed on the landfill, it is expected that any lead on the surface of the landfill would not infiltrate the cap, but rather move via storm water runoff into the downgradient surface water areas. Human health as well as ecological risks at the site could potentially increase due to the activities conducted at this shooting range facility. Waterfowl, such as the Canadian geese observed on the landfill during the site visit are highly susceptible to lead ingestion. These animals often ingest shots, mistaken it for This potential contributing source of lead food, which may lead to increased mortality. contamination at the landfill may be attributable to the shooting range activities. It is recommended that the shooting range be properly maintained and best management practices be implemented to ensure that activities conducted at the shooting range do not impact human health and the environment.

In addition, contaminant concentrations in several monitoring wells (MW-1OS, MW-1R, MW-3OS, MW-3R, MW-7OS) show an increase over time. Chromium concentrations in MW-3OS, for example, show a general increase from 257  $\mu$ g/l in March 2002, to 1400  $\mu$ g/l in October 2002, to 4250  $\mu$ g/l in April 2003.

Technical Assessment Summary

Based upon the results of the five-year review, it has been concluded that:

the cap and vegetative cover are intact and in good condition;

- the fence around the cap within the site is intact and in good repair;
- at least two groundwater monitoring wells require attention: 1) MW-7R has been damaged and has not been sampled since March 2002 (it is likely that this well needs to be replaced) and 2) one of the wells in the MW-3 well cluster requires a new locking cap;
- during the review period, antimony has been detected consistently above MCLs in downgradient water supply wells;
- inadequate data exists to determine the effectiveness of the groundwater extraction system; and
- there are no restrictions on the installation of wells downgradient of site (such restrictions may be necessary if the recommended groundwater investigation determines that the site is the source of the antimony detected in downgradient drinking water wells).

# VII. Issues, Recommendations, and Follow-Up Actions

Table 7 (attached) summarizes the recommendations and follow-up actions stemming from this 5-year review.

#### VIII. Protectiveness Statement

Based upon a review of the ROD, Remedial Action Report, and O&M Reports and an inspection of the site, it has been concluded that the remedy at the site functions as intended by the decision documents and protects the environment. Further investigation is necessary, however, to ascertain whether the remedy is protective of human health.

#### IX. Next Review

Since hazardous substances, pollutants or contaminants remain at the Ramapo Landfill site which do not allow for unlimited use or unrestricted exposure, in accordance with 40 CFR 300.430 (f) (4) (ii), the RA for the site shall be reviewed no less often than every five years. EPA will conduct another five-year review on or before December 2009.

#### Approved:

Event		
Commencement of operation of the landfill	1950	
NYSDEC and Town of Ramapo enter into three Orders on Consent related to phasing out the operation of the landfill, determining the extent of leachate movement and the feasibility of leachate collection, and constructing a surfacewater and groundwater-diversion system, leachate-collection system, and a system capable of transporting or treating the collected leachate	1980-1986	
Site placed on National Priorities List	September 1983	
Town enters into fourth Order on Consent under which a remedial investigation and feasibility study is performed	February 1988	
Record of Decision is signed	March 1992	
Remedial Design Work Plan	1992-1994	
Remedial Action completed	9/1997	
Remedial Action Report approved	?	
ESD	11/1997	

Table 2: Annual Monitoring Costs	
Estimated Costs for Contract Performance	Cost per Year
Sampling and analysis (quarterly)/data evaluation and reporting	\$35,000
Site inspection/maintenance	\$100,000
Total estimated cost	\$135,000

Document Title, Author	Submittal Date	
Record of Decision, EPA	1992	
Explanation of Significant Differences, EPA	199′	
Remedial Investigation/Feasibility Study	1993	
O M & M Report	1998	
Annual Operation and Maintenance Monitoring Report		
Five-Year Review Report, EPA	1999	
Design Analysis Report	1994	
Construction Monitoring Report Ramapo Landfill Remediation (URS Greiner, Inc., December 1998)	1998	
Post-Closure Groundwater Quality Monitoring Reports (Sterling Environmental Engineering, P.C.)	2000-2004	
EPA guidance for conducting five-year reviews and other guidance and regulations to determine if any new Applicable or Relevant and Appropriate Requirements relating to the protectiveness of the remedy have been developed since EPA issued the ROD.		

Table 4 - Comparison of Maximum Detected Concentrations of Contaminants Detected in Monitoring Wells to Their Respective Human Health Risk Based Screening Criteria (Preliminary Remediation Goal) and/or Primary Drinking Water Standard (Maximum Contaminant Level)

Contaminant	Maximum Detected Concentration (Monitoring Wells) (μg/l)	Region 9 Preliminary Remediation Goal (µg/l)	Primary Drinking Water Standard - MCL (μg/l)	Location of Maximum Detected Concentration	Date
Aluminum	98800	36000 (nc)	200*	5-OS	3/04
Antimony	155	15 (nc)	6	3-OS/I	10/03
Arsenic	91.3	0.045 (c)	10	1-OS	10/02
Barium	512	2600 (nc)	200	5-OS	3/04
Beryllium	4.9	73 (nc)	4	5-OS	3/04
Cadmium	9.4	18 (nc)	5	9-R	7/00
Chromium	4250	110 (nc)	100	3-OS/I	4/03
Cobalt	143	730 (nc)		7-OS	3/04
Copper	183	1500 (nc)	1300	5-OS	3/04
Iron	150000	11000 (nc)	300*	5-OS	3/04
Lead	41.1		15	2-OS	4/03
Manganese	24800	880 (nc)	50*	3-OS/I	4/03
Nickel	932	730 (nc)		3-OS/I	4/03
Selenium	3.2	180 (nc)	50	8-OS	3/04
Silver	39.5	180 (nc)	100*	3-OS/I	3/04
Thallium	5.4	2.4 (nc)	2	4-OS	3/04
Vanadium	231	36 (nc)		5-OS	3/04
Zinc	222	11000 (nc)	5000*	5-OS	4/03
Chlorobenzene	2.8	110 (nc)	100	8-I	5/00
Benzene	0.6	0.34 (c)	5	8-I	5/00
1,4-Dichlorobenzene	0.6	0.5 (c)	75	8-I	5/00
Vinyl chloride	2	0.02 (c)	2	8-R	10/03
1,1-DCA	1.1	810		1R	10/01
Chloroethane	1.5	4.6		8R	3/02

#### Footnotes:

<sup>(</sup>c): Value is based on a Cancer endpoint

<sup>(</sup>nc): Value is based on a Non-cancer endpoint

<sup>\*:</sup> Values are National Secondary Drinking water regulations, which are non-enforceable guidelines regulating contaminants that may cause cosmetic or aesthetic effects in drinking water.

# Source:

Region 9 Preliminary Remediation Goals (PRGs) are human health risk based screening criteria. This values are equivalent to a cancer risk of 1 x 10-6 or a hazard index of 1. Refer to: <a href="http://www.epa.gov/Region9/waste/sfund/prg/index.htm">http://www.epa.gov/Region9/waste/sfund/prg/index.htm</a>

National Drinking Water Standards (MCLs) are legally enforceable standards that apply to public water systems. Refer to: <a href="http://www.epa.gov/cgi-bin/epaprintonly.cgi">http://www.epa.gov/cgi-bin/epaprintonly.cgi</a>

Table 5 - Comparison of the Maximum Detected Concentrations of Contaminants Detected in the Potable Supply Wells Downgradient from the Site to Their Respective Human Health Risk Based Screening Criteria (Preliminary Remediation Goal) and/or Primary Drinking Water Standard (Maximum Contaminant Level)

Contaminant	Maximum Detected Concentration (Monitoring Wells) (µg/l)	Region 9 Preliminary Remediation Goal (µg/l)	Primary Drinking Water Standard - MCL (µg/l)	Location of Maximum Detected Concentration	Date
Antimony	19.4	15 (nc)	6	PW-2	10/03
Arsenic	5.6	0.045 (c)	10	PW-1	03/04
Barium	17.6	2600 (nc)	2000	SWVC-94	03/04
Beryllium	0.39	73 (nc)	4	SWVC-93	07/00
Cadmium	2.4	18 (nc)	5	SWVC-94	08/02
Chromium	2.2	110 (nc)	100	PW-2	07/03
Copper	131	1500 (nc)	1300	PW-1	10/03
Iron	939	11000 (nc)	300*	SWVC-93	10/02
Lead	81.9		15	PW-1	10/03
Manganese	88	880	50*	SWVC-95	03/04
Nickel	42.7	730	- <b>-</b>	SWVC-93	03/04
Selenium	3.1	180	50	SWVC-93	03/04
Thallium	4.1	2.4	2	PW-1	04/03
Zinc	70	11000	5000*	PW-2	07/00

#### Footnotes:

(c): Value is based on a Cancer endpoint

(nc): Value is based on a Non-cancer endpoint

\*: Values are National Secondary Drinking water regulations, which are non-enforceable guidelines regulating contaminants that may cause cosmetic or aesthetic effects in drinking water.

#### Source:

Region 9 Preliminary Remediation Goals (PRGs) are human health risk based screening criteria. This values are equivalent to a cancer risk of 1 x 10-6 or a hazard index of 1. Refer to: <a href="http://www.epa.gov/Region9/waste/sfund/prg/index.htm">http://www.epa.gov/Region9/waste/sfund/prg/index.htm</a>

National Drinking Water Standards (MCLs) are legally enforceable standards that apply to public water systems. Refer to: <a href="http://www.epa.gov/cgi-bin/epaprintonly.cgi">http://www.epa.gov/cgi-bin/epaprintonly.cgi</a>

Table 6: Other Comments on Operation, N	Table 6: Other Comments on Operation, Maintenance, Monitoring, and Institutional Controls
Comment	Suggestion
Contaminant concentrations and flow rates (including downtime) for the groundwater extraction wells are needed to adequately assess the effectiveness of the contaminated groundwater/leachate collection system.	Contaminant concentrations and flow rates for the groundwater extraction wells should be provided to EPA, if possible (it is unclear if the extraction wells have sampling ports or flow meters where this data could be obtained).
In accordance with best management practices of outdoor shooting ranges, berms should be covered by a roof to prevent erosion of the berm and increased lead mobility. During the five-year review site inspection, it was observed that a roof was not present and expended bullets were present and accumulating on the ground.	The berm should be covered with a roof.
MW-7R has been damaged and has not been sampled since March 2002 (it is likely that this well needs to be replaced) and one of the wells in the MW-3 well cluster requires a new locking cap.	Monitoring well MR-7R needs to be restored to proper working condition and a locking cap needs to be installed for one of the wells in the MW-3 well cluster.
Groundwater contaminant concentrations have increased in several on-site monitoring wells.	An evaluation of potential causes of rises in groundwater contaminant concentrations needs to be performed. It is possible that extraction wells cycling or not properly operating are the cause of the increasing concentrations.
New York State now requires annual certifications that institutional controls that are required by RODs are in place and that remedy-related O&M is being performed.	On an annual basis, the site will need to be inspected to determine whether any intrusive activities have been performed at the site and the building and property records will need to be reviewed to ascertain whether or not any filings had been made for such activities. The annual O&M report that is currently submitted by the Performing Party should include a summary of the findings of the above-noted activities, along with certifications that the institutional controls are in place and that remedy-related O&M is being performed.

		, in				
	Affects iveness (Y/N)	Future	Z	<b>*</b>	Y	
	Affects Protectiveness (Y/N)	Current	Z	Å		
	Milestone	Date	2/05	\$0/8	ТВD	
	Oversight	Agency	NYSDEC	NYSDEC	NYSDEC	
	Party Demonsible	nesponsible	PRP	PRP	PRP	
ow-Up Actions	Recommendations and	FORON-OP ACTORS	Additional monitoring wells need to be installed to meet these needs.	Until it can be determined, based upon the results of sampling from the above-noted new monitoring wells, whether or not the antimony detected in the downgradient water supply wells is site-related, it is recommended that bottled water and/or point-of-use treatment be provided.	The alternate water supply contingency remedy may need to be implemented. In addition, the Town would need to implement institutional controls to restrict the use of off-site groundwater.	
lable /: Kecommendations and Follow-Up Actions	Issue		The current monitoring well network does not allow for a determination of a groundwater capture zone nor give early warning regarding potential contaminant migration to drinking water wells PW-2 or SWVC 93-96.	During the review period, antimony was consistently detected above the MCL in downgradient drinking water wells. It is unclear, however, whether the antimony detected in these wells is site-related.	If it is determined that the site is the source of the antimony detected in the downgradient drinking water wells.	

The same of the sa	
Table 8: Acro	nyms Used in this Document
ARAR	Applicable or Relevant and Appropriate Requirements
CERCLA	Comprehensive Environmental Response, Compensation, and Liability Act
COPC	Contaminants of Potential Concern
EPA	United States Environmental Protection Agency
ESD	<b>Explanation of Significant Differences</b>
MCLs	Maximum Contaminant Levels
Mg/kg	Milligrams per Kilogram
μg/l	Micrograms per Liter
NYSDEC	New York State Department of Environmental Protection
PRGs	Preliminary Remediation Goals
RA	Remedial Action
RD	Remedial Design
RI/FS	Remedial Investigation/Feasibility Study
ROD	Record of Decision
RPM	Remedial Project Manager
TKN	Total Kjeldahl Nitrogen
VOCs	Volatile Organic Compounds