Prepared by: AECOM Latham, NY 60302031 February 2015

Beaver Smelting Site Fallsburg, NY

Three-Year Periodic Review Report

January 1, 2012 to December 31, 2014

NYSDEC Site Number: 3-53-005

Work Assignment Number D007626-30



Contents

Exe	cutive	Summary	1
1.0	Site C	Overview	2
	1.1	Remedial History	2
2.0	Evalu	ate Remedy Performance, Effectiveness, and Protectiveness	5
	2.1	Operation, Maintenance, and Monitoring Plan Compliance Report	5
	2.2	Engineering and Institutional Control Plan Compliance Report	
3.0	Evalu	ate Costs	11
4.0	Conc	lusions and Recommendations	12
	4.1	Conclusions	12
	4.2	Recommendations	12

List o)† I	abi	es
--------	------	-----	----

Table 1	Analytical Results for Unfiltered Groundwater Samples (1992 - 2013)
Table 2	Analytical Results for Filtered Groundwater Samples (2013)
Table 3	Analytical Results for Leachate and Ditch Samples (1981 - 2014)

List of Figures

Figure 1	Site Location Map
Figure 2	Location of Monitoring Wells
Figure 3	Groundwater Metals Results Exceeding Ambient Water Quality Standards in 2013
Figure 4	Cadmium, Lead, and Selenium Results from 2014 Perimeter Ditch Samples

List of Appendices

Appendix A	Site and Monitoring Well Inspection Forms and Photo Log
Appendix BAnalytical Results E.	xceeding Ambient Water Quality Standards or Guidance Values
Appendix C	IC/EC Certification Form and Property Owner Survey

Engineering Certification

I certify that I am currently a NYS registered professional engineer and that this Periodic Review Report covering the period of January 1, 2012 to December 31, 2014 for the Beaver Smelting Site was prepared in accordance with all applicable statutes and regulations and in substantial conformance with the DER Technical Guidance for Site Investigation and Remediation (DER-10) and that all activities were performed in full accordance with the DER-approved scope of work and any DER-approved modifications.

Respectfully submitted, AECOM

Scott A. Under Nil OFESSIONAL Registered Professional Engineer

New York License No. 075332

February 18, 2015

Date

February 2015

Executive Summary

The Beaver Smelting Site (site) is located in the Town of Fallsburg, Sullivan County, New York (Figure 1). The site (Site Number 3-53-005) is approximately 13 acres in size and is a former aluminum recycling facility that operated for 25 years, resulting in several large and small piles of ash at the facility. In response to a complaint filed in 1984 and the results of an extraction procedure (EP) toxicity test for lead on ash from these piles, a field investigation and feasibility studies were completed between 1986 and 1989 by the responsible party that showed lead, cadmium, and selenium at values above New York State Department of Environmental Conservation (NYSDEC) groundwater standards. In response, a 1989 Consent Order (CO) agreement with the Attorney General was issued that mandated remediation of the site that included consolidation and containment of the exposed ash piles. This remediation was completed in 1991.

Site management began in January 1992 as part of the CO, with the last round of sampling to be performed by the responsible party in October 1994. The NYSDEC then assumed responsibility to perform site management activities. In 2005, the NYSDEC retained AECOM to complete groundwater monitoring for select Superfund Sites under their standby contract, one of which was the Beaver Smelting Site. The monitoring wells were sampled twice during 2005 and once each during 2007, 2008, 2010, 2011, and 2013.

A Site Management Plan (SMP) was finalized in 2014 (AECOM) defining the site monitoring requirements of inspections semi-annually and groundwater sampling of 11 wells (i.e., MW-2; MW-3; MW-4; MW-5; MW-6, MW-7; MW-9; MW-10; MW-11; MW-12; MW-13) every five quarters.

Based on AECOM's review of the historical data and information as well as completed semi-annual site inspections, the selected remedy at the site continues to function as intended. Due to the continuing persistence of site contaminants detected at elevated levels in the site groundwater and surface water, AECOM recommends continued long-term monitoring including basic site maintenance and the sampling of groundwater and leachate. Additional samples are recommended to be collected from the drainage pipe, the surface water along the west perimeter of the landfill, and from the unnamed stream in spring 2015 for dissolved metals to further evaluate the potential contribution of metals contamination from a seep identified in this area.

AECOM also recommends that groundwater and land use restrictions to the site be implemented in the form of an Environmental Easement or Environmental Notice in order to satisfy deed restrictions required by the CO. The deed restriction referenced in the CO does not discuss what the restrictions are. AECOM contacted the Sullivan County Office during the preparation of this PRR and was informed no site use restrictions exist in the referenced deed, although other deeds were referenced. AECOM later completed a records search at the Sullivan County Office in January 2015 and found no additional information.

1.0 Site Overview

The Beaver Smelting Site (site), NYSDEC Site No. 3-53-005, is located on Beaver Lane in the Town of Fallsburg, Sullivan County, New York (Figure 1). The site is Class 4, which means that the site has been properly closed but requires continued site management consisting of operation, maintenance, and monitoring. There is a small two acre capped landfill located on the west side of Beaver Lane with two large buildings remaining on the site from the former aluminum smelting activity (Figure 2). The surrounding area is both wooded and open grassy fields. Current zoning includes mixed residential, commercial, and agricultural use. The site and buildings are currently used as an equipment storage yard for a local contractor. Surrounding site use consists of a number of residences located on Beaver Lane with agriculture on adjacent fields. The site drains to an unnamed stream, referred to as Beaver Smelting Stream that flows west about 2,000 feet to the Neversink River. The stream originates in the marshy area north of the landfill.

1.1 Remedial History

Beaver Smelting and Refining was an aluminum recycling facility that operated for twenty five years. There were three large and numerous small piles of ash located on the site. In response to a complaint filed in 1984 and the results of an extraction procedure (EP) toxicity test for lead on ash from these piles (13.63 mg/L and 200.45 mg/L), field investigations and feasibility studies were completed between 1986 and 1989 by Lawler, Matusky & Skelly Engineers (LMS) for the Beaver Smelting Company. These investigations reported metals including lead, cadmium, and selenium at values above NYSDEC groundwater standards and led to a 1989 CO agreement with the Attorney General mandating remediation of the site. Per the CO, the goal of the remediation was to alleviate the threat from the hazardous substances on site as well as to prevent the migration of hazardous substances off-site by the consolidation of the ash piles, the stabilization of the hazardous substances contained therein, and the placement of clean fill material layered with lime.

The field investigation involved the following activities from the fall of 1986 through the fall of 1987:

- Construction of 11 shallow (12 to 20 feet deep) groundwater monitoring wells in the sediment adjacent to the three ash fills;
- Drilling of five additional borings in the ash to depths 2 to 17 feet below grade;
- Collection of 11 water samples from the groundwater monitoring wells, eight from the seeps at the bases of the fills, and five from the stream;
- Collection of three sediment samples from an on-site pond;
- Laboratory analyses of all water and pond sediment samples for heavy metals and some groundwater samples for volatile organic compounds (VOCs);
- Laboratory analyses of soil samples for cation exchange capacity (CEC);
- Resampling of ground and surface waters for heavy metals;

- Aerial photography and photogrametric mapping of the site and surveying of wells;
- Drilling of 10 borings in each of the three fills and the collection of ash samples; and
- Bench scale chemical treatability study.

The field investigations and feasibility studies were approved in March 1989. Results of these investigations showed groundwater standards being exceeded for lead, cadmium, selenium, and pH and revealed that the overburden consisted of 10 to 20 feet of dense glacial till with large amounts of silt, clay, and fragipan. Due to the very high turbidity of the groundwater in those wells caused by suspended silts and clays, both filtered and unfiltered samples were collected with greater emphasis placed on the results of the filtered (dissolved) results, which are more representative of the groundwater chemistry. The July 1989 results indicated that concentrations ranged from 15 to 48 micrograms per liter (μ g/L) for lead and 18 to 120 μ g/L for selenium; however, selenium exceeded the standards in the upgradient wells and was therefore not related to the site. No VOCs were detected in the groundwater samples.

A CO for remediation of the site was signed by the Attorney General in March 1990 and includes the following remedial components:

- Consolidation of nearly 9,000 cubic yards of smelter ash;
- Grading and capping of the consolidated ash;
- Institutional controls and restrictions on the use of the property and future use of groundwater;
 and
- Monitoring of on-site groundwater contamination to monitor the short term and long term effectiveness of the remedy. Per the CO, groundwater monitoring was to consist of analysis of the following parameters:
 - o Aluminum,
 - o Beryllium,
 - o Cadmium,
 - o Iron.
 - o Lead,
 - o Manganese,
 - o Selenium, and
 - Hexavalent chromium

In October 1991, approximately 9,000 cubic yards of smelter ash waste was consolidated, stabilized, and capped to prevent direct contact with the waste material and reduce leaching of the contaminants to groundwater. A lime stabilization process was utilized to minimize the potential for contaminant leaching. A groundwater collection trench was constructed upgradient of the landfilled waste to minimize infiltration. Due to the high clay content of the soil, migration of contaminants into the groundwater was deemed unlikely. Site management began in January 1992 as part of the CO. In accordance with the CO, the last round of sampling performed by the RP was conducted in October 1994. The NYSDEC then assumed responsibility to perform site operation, maintenance and monitoring (OM&M). In 2005, the NYSDEC retained AECOM to do groundwater monitoring for

selected Superfund Sites under their Standby Contract, one of which was the Beaver Smelting Site. A Site Management Plan (SMP) was finalized in 2014 (AECOM) that defined the objectives for site monitoring requirements and outlined site maintenance requirements, which included inspections semi-annually and groundwater sampling of 11 wells (i.e., MW-2; MW-3; MW-4; MW-5; MW-6, MW-7; MW-9; MW-10; MW-11; MW-12; MW-13) every five quarters.

The private drinking water supply wells serving homes near this site were sampled in 1988, 1993, 1995, and 2009. Site-related contaminants were not detected in any of the wells sampled. An on-site drinking water supply well was sampled in the spring of 2001. No site-related contaminants were detected.

2.0 Evaluate Remedy Performance, Effectiveness, and Protectiveness

Since remaining waste, contaminated soil, and contaminated groundwater exist beneath the site, engineering and institutional controls (EC/ICs) are required to protect human health and the environment. EC/ICs at the site currently consist of:

- A soil cover placed over consolidated landfilled material to prevent exposure to and migration of contaminants:
- A monitoring well network to be maintained and utilized to monitor the effectiveness of the remedial program on the groundwater at the site;
- A perimeter ditch installed to minimize infiltration of groundwater into the soil cover and to collect surface runoff;
- · Land use restrictions; and
- Development and implementation of a SMP that defines the scope of required activities to properly maintain the site and ensure remedy effectiveness. This SMP outlines requirements for:
 - Long-term monitoring of negatively impacted environmental media to provide the necessary data to determine the effectiveness of the remedy, and
 - o Semi-annual site inspections to verify condition of the ECs on the site.

The site has been maintained, and monitoring events have been performed (1992 through 2013) following completion of the remedial activities. The site inspections and groundwater monitoring performed at the site during the reporting period covered by this PRR, January 1, 2012 to December 31, 2014, were completed in general accordance with the draft SMP (AECOM 2008) and final SMP (AECOM 2014).

2.1 Operation, Maintenance, and Monitoring Plan Compliance Report

2.1.1 Confirm Compliance with the OM&M Plan

Site inspections are to be conducted semi-annually with a landfill inspection form completed detailing the observations. Specific areas of the inspection include the following at a minimum:

- Cap integrity (e.g., standing water, deep rooting vegetation, stressed vegetation, settling, erosion, leachate outbreaks, burrowing animals);
- Perimeter ditch condition: and
- Monitoring well network condition (e.g., identification, accessibility, physical damage, missing components, security, and infestation).

Site inspections completed in January and June of 2014 verified that the ECs were maintained as designed. AECOM did not complete site inspections during the first year of this reporting period (2012) because no work assignment existed between AECOM and the NYSDEC. Approval for Work Assignment D007623-30, which covers the work discussed herein, was received on June 28, 2013.

No issues were found with the monitoring well network. All wells were found to be in good condition. Site and monitoring well inspection logs are included as Appendix A as well as photo logs from the site inspections.

A previously identified seep was observed to still be active on the west side of the landfill during both the January 2014 and June 2014 site inspections. In January 2014 the seep was frozen. During the June 2014 site inspection, samples were collected from the surface water and drainage pipe at six locations above and below the west seep. Results for these samples are discussed below in Section 2.1.2.

Pursuant to the draft SMP (AECOM, 2008) and Final SMP (AECOM, 2014), groundwater quality at each of the site monitoring wells is to be monitored until concentrations of contaminants are less than the established remedial goals. During this reporting period, groundwater sampling of the site's monitoring well network for total and dissolved metals was completed in October 2013. A Groundwater Monitoring Report evaluating the results of the site monitoring and assessing whether this remedy is performing effectively was submitted in January 2014 for the October 2013 sampling. Results of this monitoring performed to date are discussed in Section 2.1.2, and data are presented in Tables 1, 2 and 3 and Appendix B. Figure 3 shows the 2013 groundwater concentrations for metals where the dissolved fractions exceed the ambient water quality standards.

	Required F	requency	
Activity	Semi-Annual	15 Months	Compliance Dates
Groundwater Sampling		X	October 2013
Soil Cover Inspection*	X		January 2014; June 2014
Perimeter Ditch Inspection*	Х		January 2014; June 2014
Monitoring Well Network Inspection*	X		January 2014; June 2014

^{*}Note: AECOM did not complete groundwater monitoring or site inspections during the first year of this reporting period (2012). Approval for the current work assignment (D007623-30) was received on June 28, 2013.

2.1.2 Comparison with Remedial Objectives

Tables 1 through 3 and Appendix B include data from the monitoring events performed between 1992 and 2013. The figures in Appendix B show the temporal trends for the contaminants that exceeded the New York State Ambient Water Quality Standards (AWQS) or Guidance Values (TOGS 1.1.1) in at least one of the samples collected during the monitoring period. Figure 3 shows the 2013 groundwater concentrations for the metals where the dissolved fraction exceeds the ambient water quality standards.

As noted during the early field investigations completed during the late 1980s and observed during subsequent sampling events, the turbidity in the site groundwater is very high, ranging from about 12 nephelometric turbidity units (NTUs) to levels exceeding the instrument limit (>1,000 NTUs) during the October 2013 sampling event. In order to provide a more comprehensive view of the groundwater quality in the vicinity of the site with respect to metals, both filtered and unfiltered groundwater samples were collected in 2013 and analyzed for each well consistent with Section 2.1 of NYSDEC DER-10 (May 3, 2010). These results are discussed below.

Unfiltered Groundwater Samples

Total concentrations of metals from the 2013 monitoring event were generally consistent with previous sample results (see Table 1). Iron, lead, and manganese are found widely distributed in the monitoring wells at concentrations exceeding the respective New York State Ambient Water Quality Standards (AWQS) (TOGS 1.1.1). Detections of iron ranged from 139 to 92,200 μ g/l. The AWQS of 300 μ g/l was exceeded at all sampled wells with the exception of MW-12 and MW-13, which are both located to the west of the landfill. Detections of lead ranged from 7.4 to 1,010 μ g/l. The AWQS for lead of 25 μ g/l was exceeded in all wells with the exception of MW-3, MW-9, MW-12, and MW-13, which are located upgradient from and to the west of the landfill. Detections of manganese ranged from 235 to 9,040 μ g/l, exceeding the AWQS of 300 μ g/L at all wells except MW-6, which is located to the east of the landfill.

In addition to the more widespread exceedances, exceedances were observed for the following parameters:

- Selenium was detected in site groundwater at concentrations exceeding the AWQS of 10 μg/L at three of the monitoring wells: 132 μg/L at MW-2, 10.3 μg/L at MW-3, and 11.1 μg/L at MW-10. Selenium was below the method detection limit for all other monitoring wells. Despite concentrations being above the AWQS, concentrations at MW-3 and MW-10 appear to be steadily declining.
- Sodium was detected in site groundwater at concentrations exceeding the AWQS of 20,000 μg/L at three monitoring wells: 23,300 μg/L at MW-4, 25,700 μg/L at MW-12, and 32,000 μg/L at MW-13. Sodium concentrations in all wells are consistent with previous sampling events or appear to be declining with the exception of MW-12. During the 2010 and 2011 sampling, sodium was detected in MW-12 at concentrations of 6,200 and 6,640 μg/L, respectively. The results for the 2013 sampling have increased considerably compared to concentrations observed during the 2005 and 2008 monitoring events.
- Thallium was detected in the site groundwater at a concentration of 10 μg/L at MW-4, exceeding the AWQS of 0.5 μg/L. Thallium has been detected in this well during the 2011 and 2013 sampling events only. There were no detections above the reporting or method detection limits of 1.9 μg/L in the other site wells; however, the laboratory limit exceeds the AWQS of 0.5 μg/L.

In addition to the exceedances discussed above, MW-4 continues to be a source of detections above the AWQS for arsenic, barium, cadmium, chromium, and nickel and above the guidance values for antimony and beryllium.

Filtered Groundwater Samples

Due to the elevated turbidity in the groundwater on this site, filtered samples were also collected and analyzed for metals. While the dissolved samples did indicate fewer exceedances of the respective AWQS and guidance values, exceedances were still observed (see Table 2).

Based on the results for the filtered data, exceedances of the AWQS for iron, manganese, and sodium were most widespread across the site. The AWQS for iron (300 μ g/L) was exceeded at MW-4, MW-9, and MW-10 with elevated concentrations ranging from 944 to 5,720 μ g/L. The AWQS for manganese (300 μ g/L) was exceeded at MW-3, MW-4, MW-5, MW-10, MW-12, and MW-13 with elevated concentrations ranging from 218 to 1,780 μ g/L. The AWQS for sodium (20,000 μ g/L) was exceeded at MW-4, MW-12, and MW-13 with elevated concentrations ranging from 22,800 to 32,900 μ g/L.

In addition to the more widespread exceedances, the following exceedances were observed in the dissolved samples:

- The AWQS for selenium (10 μg/L) was exceeded at MW-2 and MW-10 at concentrations of 140 and 10.3 μg/L, respectively.
- The guidance value for antimony (3 μg/L) was exceeded at MW-4 at a concentration of 11.8 μg/L.
- The AWQS for arsenic (25 μg/L) was exceeded at MW-4 at a concentration of 111 μg/L.
- The AWQS for lead (25 μg/L) was exceeded at MW-4 and MW-10 at concentrations of 194 and 26.7 μg/L, respectively.
- Thallium exceeded the AWQS of 0.5 μg/L at MW-4 with a concentration of 2.7 μg/L.

Surface Water

Leachate samples were collected from the site in 1981, 2000, 2002, and 2009. The exact location of where these samples were collected is unknown, but they are believed to be from the vicinity of the LEACHATE sample identified on Figure 2. Analytical results for these samples are summarized in Table 3 and indicate a continuing source of metals, including lead, to the on-site surface water. To further evaluate this source, samples were collected from surface water and the drain pipe adjacent to the main waste mass on the west side of the landfill for metals during the October 2013 sampling event and again in June 2014 to assess the seep present along the west slope of the landfill.

Along the west perimeter of the landfill, there is an intermittent stream that runs along the top of a buried drain pipe that originates near the northwestern edge of the landfill (see Figure 4). The pipe and this stream then discharge to a drainage ditch in the area of the Down Pipe sample shown on Figure 4. During the 2014 sampling, surface water was collected from the following locations:

- Up Pipe Collected at the inflow of the drainage pipe that runs below the intermittent stream: lead was detected at 192 μg/L.
- Down Pipe Collected at the outflow of the drainage pipe that runs below the intermittent stream: lead was detected at 86.1 µg/L.

 Up Ditch – Collected from the surface water adjacent to the landfill, approximately 5 feet upgradient from the West Seep: lead was detected at 4.8 μg/L.

- West Seep Collected from the surface water adjacent to the landfill at the location of the West Seep: lead was detected at 370 μg/L.
- Down Ditch Collected from the surface water adjacent to the landfill, approximately 5 feet downgradient from the West Seep: lead was detected at 47.3 μg/L.
- Ponded Area Collected from the standing water where surface runoff from both the site as well as Beaver Lane pools: lead was detected at 5,800 µg/L.

These Up Pipe and Down Pipe samples suggest a source upgradient of the landfill with dilution at the outlet of the drain pipe. The Up Ditch, West Seep and Down Ditch samples from the surface water adjacent to the landfill suggest the seep does contribute to the metals in the on-site surface water; however, due to the elevated concentration upgradient from the landfill (192 μ g/L), there appears to be an additional source that should be further evaluated. No water flow estimates were made during the time of the sampling; however observations during site inspections indicate intermittent water flow from both the west seep as well as in the drain pipe and ditch. At the time of sample collection in June 2014, there was approximately 3 inches of water in the ditch with minimal flow. Although the seep appeared to be active, there was no measurable flow at the time of the site visit. The Ponded Area sample indicates the accumulation of lead, as this area is a low spot and collected water either infiltrates into the groundwater or evaporates.

To further evaluate the potential contribution of metals contamination from the landfilled material, additional sampling is recommended during spring 2015 to include the dissolved fraction, and an attempt will be made to collect water directly from the seep prior to it entering the drainage ditch. This may be accomplished by digging slightly into the surface of the seep to collect sufficient standing water. Sediment samples from the ponded area and ditch should also be collected and analyzed for metals to further evaluate the extent of the contamination. Surface water and sediment samples should be collected from the unnamed stream, across Beaver Lane, to assess the potential for contaminant migration offsite.

2.2 Engineering and Institutional Control Plan Compliance Report

Determination of compliance with the IC\ECs at the site is made based on the following criteria:

- The IC/ECs applied at the site are in place and as prescribed in the CO and subsequent work plan and SOW. Site conditions are as designed for the certification period from January 1, 2012 through December 31, 2014.
- The deed restriction referenced in the CO does not describe the site restrictions. AECOM
 contacted the Sullivan County Office during the preparation of this PRR and was informed no
 site use restrictions exist in the referenced deed, although other deeds were referenced.
 AECOM later completed a records search at the Sullivan County Office in January 2015 and
 found no additional information.

Nothing has occurred that would impair the ability of such controls to protect the public health
and the environment, or constitute a violation or failure to comply with any element of the
SMP for such controls.

2.2.1 IC / EC Certification Forms

See Appendix C for the Standby Consultant/Contractor Certification Form and the Property Owner Survey.

3.0 Evaluate Costs

Total annual costs for completion of all the required monitoring and reporting is approximately \$15,000. Major cost components are allocated as follows:

Long-term monitoring and reporting \$9,200 (with analytical costs)

Semi-annual inspections and associated reporting \$5,800

4.0 Conclusions and Recommendations

4.1 Conclusions

The PRR process is used for determining if a remedy continues to be properly managed, as set forth in the SMP and continues to be protective of human health and the environment. On the Beaver Smelting Site, metals remain widely distributed across the site in groundwater and surface water surrounding the landfill at concentrations exceeding the applicable standards.

The following remedial elements were included in the 1989 CO:

- Consolidation of approximately 9,000 cubic yards of smelter ash: Completed in 1991.
- Installation of a soil cover and perimeter ditch: Completed in 1991 with the construction of the landfill cover and ditch. Based on site inspections completed during this reporting period, the cap and ditch appear to be intact and maintained. At least one active seep has been identified on the west slope of the landfill. An evaluation as to whether the seep contains leaching site contaminants has begun, as discussed in Section 2.1, with the collection of additional samples being recommended.
- Monitoring well network: Inspections completed semi-annually demonstrating the monitoring well network is intact and well maintained.
- Deed restrictions: No apparent restrictions exist for land use on the site. The deed
 restriction referenced in the CO does not discuss what the restrictions are. AECOM
 contacted the Sullivan County Office during the preparation of this PRR and was informed no
 site use restrictions exist in the referenced deed, although other deeds were referenced. An
 environmental easement or environmental notice is recommended for the site.
- Groundwater Monitoring: Completed pursuant to the SMP during the current reporting period, and levels of metals continue to exceed regulatory limits.

4.2 Recommendations


Based on the PRR, recommendations for the Beaver Smelting Site include the following:

- Continuing semi-annual site inspections including the perimeter ditch, monitoring wells, and cap integrity;
- Continuing groundwater monitoring on a five quarter basis from the current monitoring well network;
- Monitoring sediment and surface water in ponded areas, drainage ditch, and seep on a five quarter basis, through sampling and estimating water flow;


• Completing an elevation survey of the monitoring well network; surface water and seep locations; collecting groundwater/surface water/seep elevations, and developing a groundwater flow map (this is currently planned for spring 2015); and

• Implementing groundwater and land use restrictions to the site in the form of an environmental easement or environmental notice.

Figures








FILE NAME:

APPROXIMATE


IGURE NO.

60302031.2



1. Up Pipe and Down Pipe were collected from the inflow and outflow of a drainage pipe that runs buried beneath the perimeter ditch on the west side of the landfill. The pipe then discharges to the perimeter ditch.

- 2. West Seep was collected from the perimeter ditch just downslope from the seep.
- 3. Up Ditch and Down Ditch were collected just above and below the West Seep
- 4. ND analyte not detected above the laboratory reporting limit.
- 5. Samples from 2014 Perimeter Ditch Sampling



AECOM

FIGURE 4 CADMIUM, LEAD, AND SELENIUM RESULTS BEAVER SMELTING SITE

NYSDEC SITE # 353005

TOWN OF FALLSBURG, NEW YORK

DRN PROJECT NO. FILE NAME: DATE 01/2015 60302031.2

Tables

Table 1 Analytical Results for Unfiltered Groundwater Samples Beaver Smelting Fallsburg, New York Contaminants of Concern April 1992 to October 2013

Ans	lyte	Aluminum	Antimony	Arsenic	Barium	Beryllium	Cadmium	Calcium	Chromium	Cobalt	Copper	Iron	Lead	Magnesium	Manganese	Mercury	Nickel	Potassium	Selenium	Silver	Sodium	Thallium	Vanadium	Zinc
AWQS		NA	-				5	NA	50	NA	200	300	25	35,000	300	0.7	100	NA	10	50	20,000		NA	
AWQS			3 (GV)	25	1000	3 (GV)			30	IVA	200			(GV)		0.7	100	IVA		30	20,000	0.5	IVA	2,000 (GV)
	Apr-92 Jul-92	5100 4300	-	-	-	U	5 6		-	-	-	4500 4200	500 470	-	1000 950	-	-	-	15 190	-	-	-	-	-
	Oct-92	14000	-	-	-	2	10	-	-	-	-	17000	770	-	2000	-	-	-	240	1	-	-	-	-
	Jan-93	16600	-	-	-	3	10	<u> </u>	-	-	-	11800	1400	-	2000	-	-	-	211	-	-	-	-	-
	Apr-93 Jul-93	9300 5700	-	-	-	1	8		-	-	-	7200 6500	1020 516	-	1400 1000	-	-	-	184	-		-	-	-
	Oct-93	4500	-	-	-	Ü	6	-	-	-	-	3100	570	-	800	-	-	-	135	-	-	-	-	-
	Apr-94	17200	-	-	-	U	U	-	-	-	-	25100	313	-	1100	-	-	-	83.5	-	-	-	-	-
MW-2	Oct-94 Nov-98	15800 6640	-	-	-	U	3.8B	-	-	-	-	23500 11400	383 100	-	1100 506	-	-	-	191 341	-	-	-	-	-
	Nov-99	780	-	-	-	1	7	-	-	-	-	550	64	-	170	-	-	-	260		-	-	-	-
	Oct-00	38700 E	U	40.7	382	2.7B	U	12800	68.4	48.8 B	286	54,800	334	43400	2,220	U	82.8	38300 E	180	6.1 B	2810 B	U	30.8 B	321
	Apr-02 Nov-02	3800 3200	U	U	U	U	U	12000 10000	U	U	100 57	4,800 5,000	140 82	45000 37000	530 540	U	U	26000 28000	230	U	3800 B 3500 B	U	U	60 27
	May-05	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		-		-	-	-
	Oct-05 Sep-08	55,700	39.5J	42.9	555	4.5J	U	15,000	92	70.3	417	96,700	542	47,900	3,980	0.27	126	31,500	57.9	5.3J	5,610	U	29.2J	468
	Feb-10	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			-	-	-	-
	Oct-13	2190*E	U	2.2B	116B	U	0.60B	12300E	4.4B	4.6B	65.2	1700*	154*	26000E	563	U	4.9B	16500E	132	U	U	U	1.2B	79.2E
	Apr-92 Oct-92	470 7100	-	-	-	U	10	-	-	-	-	180 8900	39.4	-	2900 7400	-	-	-	32 53	-	-	-	-	-
	Jul-92	940	-	-	-	Ü	8	-	-	-	-	440	5.3	-	5700	-	-	-	70	-	-	-	-	-
	Oct-00	1720 E	U	U	39.6 B	.26 B	U	25900	1.6 B	2.8 B	14.8 B	2070	2.1 B	12400	1670	U	14.3 B	12200 E	38	U	26700	U	1.6 B	68.9
	Apr-02 Nov-02	1400 320	U	U	U	U	U	30000 23000	U	U	30 U	2000 480	U	15000 11000	1100 810	U	U	9100 10000	38 40	U	29000 27000	U	U	77 26
MW-3	May-05	46,800	U	16.2	680	3.96J	U	34,000	62.2	52.9	535	68,300	87.8	30,800	2,710	0.56	115	13,900	29.9	U	22,800	U	42.1J	674
	Oct-05	17,000	U	12.9	252	1.3J	U	30,200	12.2	15.7J	162	30,400	69.2	17,600	1,640	0.15J	42.9	10,300	20.2	2.8J	20,600	5.5J	U	200
	Sep-08 Feb-10	2,130 3,520	U	U	61.5 54.1	U	U	19,900 19,200	2.97J 3.28J	J	17.7 11.9	4,070 4,640	4.55J 5.92J	9,320 9,730	793 804	U 0.07J	11J 12.3J	8,360 7,390	35.8 32.2	U	20,800 18,000	U	U 4.48J	52.9 53
	Nov-11	855	6.95 J	4.55 J	41.5 J	Ü	U	22,800	U	U	13.6	1,980	2.39 J	10,300	894	U	12.4 J	7,990	29.3	2.01 J	21,000	6.33 J	U	46.3
	Oct-13	930*E	U	U	55.2B	0.30B	0.30B	28600E	2.6B	1.8B	16B	1130*	11.4*	12000E	1060 2600	U	8.9B	8720E	10.3	U	17,500	U	0.90B	76.9E
	Apr-92 Jul-92	380 340	-	-	-	U	U	-	-	-	-	460 270	U 6.2	-	4000	-	-	-	37 150	-	-	-	-	-
	Oct-92	5100	-	-	-	1	10	-	-	-	-	6900	U	-	5900	-	-	-	254		-	-	-	-
	Jan-93 Apr-93	11900 5600	-	-	-	3	30	-	-	-	-	8900 3100	61 39	-	12400 16900	-	-	-	231 106	-	-	-	-	-
	Jul-93	2700	-	-	-	2	20		-	-	-	830	18	-	11100	-	-	-	U	-	-	-	-	-
	Oct-93	890	-	-	-	U	20	-	-	-	-	450	3.7	-	13100	-	-	-	12.2	-	-	-	-	-
	Apr-94 Oct-94	4300 2500	-	-	-	U	7 U	-	-	-	-	6400 3600	9.7 19.7	-	9900 9500	-	-	-	U 2.2	-	-	-	-	-
MW-4	Nov-98	9420	-	-	-	1.8B	6.3	-	-	-	-	11800	162	-	934	-	-	-	3.3B	-	-	-	-	-
	Nov-99	2600	-	-	- 440 P	1.1	7	-	-	-	-	2400	310	- 4500 B	680	-	-	-	5	-	-	-	-	-
	Oct-00 Apr-02	17300 6700	U	312 120	140 B U	2.1B U	4.1B U	8900 7600	20.9 U	12.8 B U	174 110	16500 4900	268 250	4580 B 2600 B	963 720	U	31.1 B U	329000 E 260000	U	U	102000 100000	U	50.3 29 B	114 83
	May-05	43,000	Ü	146	420	4.52J	7.4	9,270	108	55.9	465	57,600	584	16,200	2,810	0.45	90.1	221,000	Ü	Ü	68,100	Ü	68.7	397
	Oct-05	44,500	35.4J	270	442	5.7	3.1J	10,500	65.8	63.9	500	67,900	696	16,200	3,130	0.41	91.9	NA 422222	5.7J	5.0J	62,900	U	66	468
	Sep-08 Feb-10	39,700 31,200	U	92.3	343 297	4.16 3.65	8.44 5.39	6,770 6,800	64.1 55	40.5 37	390 288	53,100 49,500	484 387	12,300 11,600	2,390 2,190	0.27 0.1J	69.9 68	132000 97,700	14.2 15.2	U	38,000 27,000	U	63.4 49.9	291 265
	Nov-11	30,700	Ü	113.0	443	5.81	7.65	5,410	54.5	41.9	421	41,200	585	9,080	3,080	0.3 J	64	103,000	5.87 J	U	25,400	5.65 J	48.8	281
	Oct-13 Apr-92	63400*E 340	5.1B	63.5	1,020	20.1 U	12.7 U	17600E	117	98	195	92200 *	1010 *	15900E	9,040 1100	U -	121	115000E	U 44	U	23,300	10	93.7	733E
	Jul-92	390	-	-	-	Ü	Ü	-	-	-	-	280	Ü	-	1700	-	-	-	140	-	-	-	-	-
	Oct-92	6100	-	-	-	1	U	-	-	-	-	8800	17.6	-	2100	-	-	-	119		-	-	-	-
	Jan-93 Apr-93	3700 2800	-	-	-	U	U	-	-	-	-	3600 3100	16.2 11.4	-	2100 2000	-	-	-	46.5 42.9	-	-	-	-	-
	Jul-93	1600	-		-	U	U			-	-	1600	13.1	-	2400	-	-	-	U	-			-	-
	Oct-93	1700 3100	-	-	-	U	U	-	-	-	-	1500 4800	7.9 4.6	-	1400 1600	-	-	-	26.6 14.9	-	-	-	-	-
	Apr-94 Oct-94	1500	-	-	-	U	U	-	-	-	-	2300	4.6	-	2100	-	-	-	39.6	-	-	-	-	-
MW-5	Nov-98	6890	-	-	-	U	3.8B	-	-	-	-	15000	6.5	-	2440	-	-	-	13.7	-	-	-	-	-
	Nov-99 Oct-00	1100 2370 E	- U	- 1.8 B	- 115 B	0.3B	7 U	22800	3.2 B	5.0 B	- 11.5 B	1600 3380	3.8	13900	1000 2090	- U	- 13.8 B	- 17100 E	14 12.2	- U	18500	- U	- 1.9 B	37.9
	Apr-02	350	U	U	U	U.SB	U	16000	U U	U U	U	270	U U	11000	1400	U	U	9200	13	U	16000	U	U	28
	May-05	34,400	U	25.5	577	2.92J	U	27,100	70.6	44.4J	93.1	55,500	55.6	26,600	3,410	0.13J	88.5	12,400	8.5J	U	11,400	U	31.7J	283
	Oct-05 Sep-08	37,500 6,100	28.6J U	25.5 U	631 159	3.4J 0.48J	U	31,100 15,000	69.2 9.58J	47.8J 7.48J	104 19.8	68,900 9,520	78.3 10.5	29,400 10,200	3,600 1,410	U	88.5 15.8J	13,800 12,600	8.4J 11	3.7J U	14,800 8,190	5.5J U	16.1J 5.98J	260 54
	Feb-10	2,700	U	U	111	U	U	14,700	3.37J	U	10	3,630	4.32J	9,420	999	0.12J	7.25J	10,700	6.59J	U	6,740	U	U	31.2
	Nov-11 Oct-13	7,570 4370*E	U	7.19 J 1.5B	279 287	1.47 J 1.1B	U	15,900 18700E	13.2 8.7B	13.8 J 8.6B	35.5 18B	11,300 4520*	27.8 32.2*	9,380 9900E	1,720 1,800	U	21.9 10.6B	10,000 14500E	7.63 J	1.49 J	7,110 5,700	6.46 J	5.68 J 3.6B	92.8 75.7E
	Apr-92	4370°E 1500	-	1.5B -	- 287	1.1B U	7	18700E	8.7B -	8.6B -	18B -	230	32.2 ^	9900E -	1,800	- -	10.6B	14500E -	U	- -	5,700	- -	3.6B -	/5./E
	Jul-92	1700	-	-	-	0.2	8	-	-	-	-	1100	36	-	650	-	-	-	U	-	-	-	-	-
	Oct-92 Jan-93	10000 5500	-	-	-	2	7	-	-	-	-	17000 8900	180 170	-	800 640	-	-	-	6.7 4	-	-	-	-	-
	Apr-93	4100	-	-	-	2	6	-	-	-	-	5700	89.7	-	580	-	-	-	5.5	-	-	-	-	-
	Jul-93	2000	-	-	-	1	8	-	-	-	-	3000	60.4	-	590	-	-	-	U	-	-	-	-	-
	Oct-93 Apr-94	1600 4100	-	-	-	1 U	U	-	-	-	-	2100 5000	36.6 22.3	-	490 410	-	-	-	5.5 2	-	-	-	-	-
MW-6	Oct-94	3900	-	-	-	Ü	Ü	-	-	-	-	5000	38.5	-	410	-	-	-	7.4	-	-	-	-	-
INI WW-D	Nov-98	9760	-	-	-	1.7B	4.3B	-	-	-	-	13800	67	-	469	-	-	-	U	-	-	-	-	-
	Nov-99 Oct-00	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
	Apr-02	2200	U	U	U	U	U	4600 B	U	U	23 B	3800	45	3600 B	410	U	U	U 44.400	U	U	4900 B	U	U	360
	May-05 Oct-05	90,200 61,700	∪ 33.5J	134 74.6	2,520 1,350	12.7 8.6	1.76J U	13,500 11,500	160 117	100 72.5	270 195	183,000 136,000	1,320 827	37,800 26,100	3,510 2,510	0.29 0.16J	175 121	11,100 8,360	11.6	U 8.1J	4,710J 3,770J	∪ 6.9J	120 61	1,190 753
	Sep-08 Feb-10	29,100 19,800	U	13.5 16.9	470 301	3.56 2.44J	1.58J U	3,810 2,460	44.8 30	29.5 18.8	93.4 44.5	53,100 35,100	331 163	11,000 7,510	1,040 665	U 0.09J	55.6 37	6,690 5,300	8.05J 6.57J	U	3,330 2,920	U	33.2 24.2	375 291
	Nov-11	4,770	U	12.2	188	1.33 J	0.47 J	1,860	10.6	8.39 J	31.6	10,000	89.2	2,070	235	U	22.5	1,810	U	2.07 J	3,550	6.09 J	6.5 J	207
	Oct-13	2410*E	2.8B	3.7B	364	2.0B	0.80B	2720BE	9.0B	7.6B	33.5	5920*	156*	1280BE	235	U	9.7B	1790BE	U	U	U	U	4.7B	262E

December 2014

Table 1 **Analytical Results for Unfiltered Groundwater Samples** Beaver Smelting Fallsburg, New York Contaminants of Concern April 1992 to October 2013

Ana	lvte	Aluminum	Antimony	Arsenic	Barium	Beryllium	Cadmium	Calcium	Chromium	Cobalt	Copper	Iron	Lead	Magnesium	Manganese	Mercury	Nickel	Potassium	Selenium	Silver	Sodium	Thallium	Vanadium	Zinc
AWQS		NA	3 (GV)	25	1000	3 (GV)	5	NA	50	NA	200	300	25	35,000	300	0.7	100	NA	10	50	20,000	0.5	NA	2,000 (GV)
AW45			3(07)	20	1000	3(07)		NA .	30	IVA	200			(GV)		0.7	100	N/A	U	30	20,000	0.5	NA.	2,000 (01)
	Apr-92 Jul-92	2400 3200	-	-	-	U	30 20	-	-		-	190 1500	5.8 14	-	980 970	-	-	-	8.3	-	-	-		-
	Oct-92	9400	-	-	-	5	30	-	-	-	-	6,700	72	-	1,600	-	-	-	14	-	-	-	-	-
	- May-05	11,500	- U	- U	249	- 1.27J	U -	4,340J	12.8	- 13.1J	56.7	18,600	35.2	- 4,820J	771	0.09J	31.1J	2,320J	- U	- U	991J	U	- 11.2J	770
MW-7	Oct-05	11,000	U	11.3	351	1.6J	2.0J	5,540	1.2J	12.5J	82.8	19,900	84.2	4,690J	770	U	38.2J	3,250J	U	U	682J	Ü	U	1,020
	Sep-08	4,610	U	U	190	0.95J	3.27	2,950	7.03J	9.46J	60.8	5,980	19.1	2330	374	U	29.5	3,650	U	U	1,330	U	U	887
	Feb-10 Nov-11	13,300 2,480	U	4.34J 6.63 J	215 193	1.24J 0.88 J	1.93J 2.26 J	2,390 2,510	16.4 4.2 J	12J 7.33 J	51.7 43.0	16,900 4,360	29.9 13.8	4,400 1,520	582 326	0.12J U	30 21.3	6,080 2,310	U	U 2.57 J	1,350 2,480	∪ 5.75 J	14.5J U	645 624
	Oct-13	7660*E	Ü	U	499	2.4B	3.0B	4620BE	10.2	12.6B	88.0	4450*	87.6*	1630BE	726	Ü	24.9B	2820BE	Ü	U	U	U	3.0B	816E
	Apr-92	240	-	-	-	U	U	-	-	-	-	290	U	-	120	-	-	-	U	-	-	-	-	-
	Jul-92	630	-	-	-	U	U	-	-	-	-	740	6.6	-	150	-	-	-	U	-	-	-	-	-
	Oct-92 Jan-93	5200 1700	-	-	-	2 U	U	-	-	-	-	5,400 2,300	40.4 18.7	-	800 310	-	-	-	U	-	-	-		-
	Apr-93	1500	-	-	-	Ü	Ü	-	-	-	-	2,200	23.4	-	200	-	-	-	Ü	-	-	-	-	-
	Jul-93	-	-	-	-	-	-	-	-	-	-	-	-	-		-	-	-		-	-	-	-	-
	Oct-93 Apr-94	1000 3300	-	-	-	U	U	-	-	-	-	1,500 4,100	5.1 4.5	-	150 130	-	-	-	3.2 U	-	-	-	-	-
	Oct-94	3600	-	-	-	U	U	-	-	-	-	5,500	7.7	-	570	-	-	-	2.7	-	-	-	-	-
MW-9	Nov-98	8520	-	-	-	1.7B	3.8B	-	-	-	-	16,400	13.6	-	786	-	-	-	U	-	-	-	-	-
	Nov-99	62	-	- 00D	- 70 1 D	1	7	- 2700 B	-	- 40 B	- 70P	2,100	3	- 1200 P	460	-	- 22B	- 000 D	5	-	- 1010 D	-	- 0	- 47.0 D
	Oct-00 Apr-02	1180 E 290	U	8.8 B U	78.1 B U	U	U	2780 B 3200 B	U	4.9 B U	7.2 B U	2,180 540	2.8B U	1290 B 1300 B	1060 300	U	3.3 B U	903 B U	U	U	1910 B 2800 B	U	U	17.3 B 19 B
	May-05	5,840	Ü	Ü	197J	0.43J	Ü	5,960	4.74J	8.19J	65.8	10,200	17	3,830J	700	0.12J	11.9J	Ü	Ü	Ü	2,090J	Ü	7.46J	51.7
	Oct-05	12,700	9.3J	43	353	1.6J	0.77J	7,550	19.5	15.1J	167	31,000	140	6,760	755	0.05J	22.3J	2,890J	U	2.5J	2,210J	U	1.7J	69.9
	Sep-08	4,020	U	U	155 81.2	U	U	3,630 3.040	4.79J U	4.32J U	26.6 6.41J	7,240 4,590	16 3.23J	2,180 1,450	586 410	U 0.13J	7.46J U	1,850 1,060	U	U	2,240 2.310	U	6.95J U	37.1 18J
	Feb-10 Nov-11	1,650 1,040	U	11.6	112.0	U	U	4,270	U	U	16.6	3,680	5.23J 5.19 J	1,730	516	U.133	6.61 J	845 J	U	2.35 J	3,610	7.18 J	U	24.6
	Oct-13	1550*E	Ü	2.4B	120B	0.30B	Ü	3770BE	3.9B	2.2B	5.6B	2180*	20.5*	1470BE	320	Ü	4.1B	1220BE	Ü	U	2060B	U	2.0B	29.8E
	Apr-92	140	-	-	-	U	U	-	-	-	-	180	U	-	30	-	-	-	640	-	-	-	-	
	Jul-92 Oct-92	500 7100	-	-	-	U 2	U 6	-	-	-	-	480 4,800	6.6 37	-	70 420	-	-	-	1,300 976	-	-	-	-	-
	May-05	78,500	U	49.2	862	6.62	6.18	24,700	89.8	95.7	265	122,000	192	49,400	8,720	0.45	158	42,300	30.6	8.42J	2,760J	U	69	514
MW-10 (MW-9A)	Oct-05	154,000	9.4J	100	1,610	13.4	U	39,600	166	193	582	284,000	502	77,600	20,100	0.58	335	56,800	157	14.4	3,210J	10.1	111	1,060
(11111 374)	Sep-08	45,500	U	27.4	458	3.48	4.31	15,100	40.5	57	144	82,600	110	26,100	3,980	U	88.2	34,500	31	U	2,970	U	38.4	282
	Feb-10 Nov-11	13,800 2,000	U	8.44J 9.4 J	151 75.2	0.81J 0.37 J	U	10,200 8,230	10.9 2.77 J	7.89J 5.11 J	27.1 14.5	17,700 4,410	28.8 13.5	14,600 7,690	607 651	0.12J U	16.6J 8.39 J	26,000 23,300	27.9 17.6	2.18 J	2,630 3,490	∪ 5.62 J	14.6J U	69.9 33.4
	Oct-13	8460*E	2.2B	6.3B	478	2.6B	2.4B	10900E	3.5B	5.2B	37.9	3120*	55.4*	8030E	795	Ü	7.0B	25600E	11.1	U	2100B	U	1.8B	72.6E
	Apr-92	1200	-	-	-	U	U	-	-	-	-	1,600	U	-	170	-	-	-	360	-	-	-	-	-
	Jul-92 Oct-92	1100 9400	-	-	-	U 3	U 6	-	-	-	-	1,400 1,100	5.6 33.7	-	200 1,500	-	-	-	390 340		-	-	-	-
	May-05	171,000	U	34.5	2,550	15.8	0.57J	21,900	391	184	270	285,000	207	83,700	10,000	0.68	320	42,100	44.6	U	1,830J	U	142	1,180
MW-11	Oct-05	258,000	6.6J	52.4	3,580	22.9	U	23,700	569	285	436	497,000	442	118,000	19,800	0.83	510	56,400	69	24.2	3,500J	U	190	1,710
	Sep-08 Feb-10	XX	XX	XX XX	XX XX	XX	XX	XX	XX	XX	XX XX	XX	XX	XX	XX XX	XX XX	XX XX	XX XX	XX XX	XX XX	XX XX	XX	XX XX	XX XX
	Nov-11	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX
	Oct-13	XX	xx	XX	XX	XX	XX	XX	xx	XX	XX	xx	xx	xx	xx	xx	xx	XX	XX	XX	xx	xx	XX	xx
	Apr-92 Jul-92	4500 1500	-	-	-	U	U	-	-	-	-	80 170	U	-	1,900 2,500	-	-	-	9.8		-	-	-	-
	Oct-92	3800	-	-	-	1	U	-	-	-	-	1,100	13.5	-	2,600	-	-	-	16.1		-	-	-	-
	Oct-00	1210 E	U	2.6 B	106 B	.33 B	Ü	54,400	1.8 B	9.6 B	8.6 B	1,370	5.6	24,000	2,300	U	24 B	9890 E	6.6	U	42,500	U	U	51.4
NNW 46	Apr-02	3300	U	U	U	U	U	27,000	U	U	U	110	U	14,000	2,700	U	U 40.51	U 5.740	5.6	U	27,000	U	U 0.771	130.0
MW-12	May-05 Oct-05	1,150 521	U	U 5.6J	71.6J 83.0J	0.145J U	U 0.78J	30,900 30,200	2.78J U	8.12J U	9.26J U	1,350 522	3.66J 12.4	13,700 10,400	2,210 1,490	0.12J U	13.5J U	5,740 3.560J	U	U	30,700 22,900	U	2.77J U	35.2 26.5
	Sep-08	14,200	U	U	204	0.71J	0.74J	43,100	15.6	14.7	41.9	16,900	33.2	21,300	1,910	0.2	31.4	6,480	U	U	37,300	U	10.3J	129.0
	Feb-10	602	U	U	68.7	0.31J	0.43J	5,780	U	6.23J	2.64J	965	2.72J	2,780	793	0.14J	5.82J	1,990	U	U	6,200	U	U	46
	Nov-11 Oct-13	330 192B*E	U	15.2 1.3B	111 147B	U	1.01 J 0.40B	5,780 27600E	U 1.1B	9.34 J 3.8B	6.31 J 5.0B	432 177*	3.36 J 7.4*	2,490 12300E	1,030 1,960	U	12.4 J 9.0B	2,690 4190BE	1.9B	2.32 J U	6,640 25,700	4.78 J U	U	53.2 38.9E
	Apr-92	U 1926 E	-	-	-	U	U.40B	- -	-	3.0D -	-	U	U U	-	1,400	-	-	4190DE -	60	-	-	-	-	-
	Jul-92	70	-	-	-	U	U	-	-	-	-	50	U	-	1,500	-	-	-	88		-	-	-	-
	Oct-92	450 1610 F		- 100	- 65.7.0	U	U	- 24700	-	- 400	-	600	5.5	- 0.700	1,400	-	- 12.0 B	- 22500 5	88.3	-	- 4E 400	-	- 100	- 24.2
	Oct-00 Apr-02	1610 E 72 B	U	1.8 B U	65.7 B U	0.2 B U	U	24700 29000	2.2 B U	4.8 B U	9.0 B U	2,240 62 B	3.8 U	9,780 11,000	1,700 1,500	U	13.9 B U	23500 E 17000	? 19	U	45,400 52,000	U	1.9 B U	31.3 19 B
MW-13		3,590	U	U	90.5J	U	U	25,800	5.87J	5.96J	12.9J	5,670	7.75	10,700	1,440	0.08J	15.2J	18,000	5	U	43,400	U	3.48J	40.3
	Oct-05	1,530	U	U	63.0J	0.22J	U	24,900	U	3.5J	8.0J	2,660	3.7J	9,020	1,120	0.08J	3.5J	18,000	U	U	41,400	U	U	U
	Sep-08 Feb-10	208J 318	U	U	48.2 40J	U	U	19,300 17,400	U	U	4.87J 3.45J	451 489	U	6,930 6,610	984 923	U 0.19J	6.14J 6.55J	16,600 12,600	U	U	39,500 32,100	U	U	25 17.6J
	Nov-11	108	5.61 J	U	40J 40.4 J	U	U	17,400	U	U	3.45J 4.23 J	326	U	6,350	923	0.19J U	9.77 J	12,600	U	U 2.89 J	32,100	5.99 J	U	20.3
	Oct-13		U	Ü	54.3B	Ü	Ü	19700E	1.1B	1.6B	4.5B	139*	8.1*	7580E	1,040	Ü	7.0B	14800E	3.0B	U	32,000	U	Ü	46.8E
																								-

- All data are presented in micrograms per liter (μg/L).
 Metals analysis by US EPA Method 6010/7470.
 B Analyte found in associated method blank.
 U Compound not detected at or above the method detection limit (MDL).
 J Estimated concentration above the MDL but less than the reporting limit.
 * Duplicate analysis not in control limits
 E Serial dilution is not within acceptance criteria, or the reported value is estimated because of the presence of interference.
 AWQS New York State Ambient Water Quality Standards (TOGs 1.1.1); GV guidance value.
 NA indicates 1) no standard or guidance value exists for the compound, or 2) sample was not analyzed for indicated compound.
 S Rample was not analyzed for indicated someound.
 S Rample was not analyzed for indicated compound.

- 12. Sample was not analyzed for indicated compound.

Page 2 of 2 December 2014

Table 2 **Analytical Results for Filtered Groundwater Samples** Beaver Smelting Fallsburg, New York **Contaminants of Concern**

October 2013

An	alyte		Aluminum	Antimony	Arsenic	Barium	Beryllium	Cadmium	Calcium	Chromium	Cobalt	Copper	Iron	Lead	Magnesium	Manganese	Mercury	Nickel	Potassium	Selenium	Silver	Sodium	Thallium	Vanadium	Zinc
AWQS	+ GV	Dissolved or Total	NA	3 (GV)	25	1000	3 (GV)	5	NA	50	NA	200	300	25	35,000 (GV)	300	0.7	100	NA	10	50	20,000	0.5	NA	2,000 (GV)
MW-2	Oct-13	D	143B	2.4B	2.8B	55.6B	0.80B	0.70B	11900	1.2B	1.2B	11.5B	120	8.1	26400	183	U	1.4B	16700	140N	U	U	U	0.90B	20.9
IVIVV-Z	OCI-13	T	2190*E	U	2.2B	116B	U	0.60B	12300E	4.4B	4.6B	65.2	1700*	154*	26000E	563	U	4.9B	16500E	132	U	U	U	1.2B	79.2E
MW-3	Oct-13	D	50.2B	U	U	45.0B	U	U	35,000	0.5B	1.1B	8.0B	193	7.9	12,600	1,120	U	5.7B	7,780	5.7N	U	16,800	U	U	47.4
miv-5	001-10	T	930*E	U	U	55.2B	0.30B	0.30B	28600E	2.6B	1.8B	16B	1130*	11.4*	12000E	1060	U	8.9B	8720E	10.3	U	17,500	U	0.90B	76.9E
MW-4	Oct-13	D	4,400	11.8B	111.0	63B	0.90B	1.5B	3780B	8.5B	5.0B	123	5,720	194	682B	576	U	9.1B	90,200	6.5N	U	22,800	2.7B	42.7B	61
11111-4	001-10	Т	63400*E	5.1B	63.5	1,020	20.1	12.7	17600E	117	98	195	92200*	1010*	15900E	9,040	U	121	115000E	U	U	23,300	10	93.7	733E
MW-5	Oct-13	D	84.0B	U	U	112B	U	U	16,800	0.4B	0.50B	5.5B	U	6.1	9,510	1,260	U	5.3B	11,500	3.8BN	U	6,170	U	U	24.8
11111	000 10	T	4370*E	U	1.5B	287	1.1B	U	18700E	8.7B	8.6B	18B	4520*	32.2*	9900E	1,800	U	10.6B	14500E	U	U	5,700	U	3.6B	75.7E
MW-6	Oct-13	D	116B	2.4B	U	80.5B	U	0.30B	1430B	1.1B	2.9B	5.6B	U	13.1	802B	71	U	5.2B	1320B	U	U	U	U	U	162
-			2410*E 282	2.8B 2.1B	3.7B	364 164B	2.0B	0.80B 2.4B	2720BE 2220B	9.0B 1.1B	7.6B 5.6B	33.5 29.1	5920*	156*	1280BE 992B	235 170	U	9.7B 18.3B	1790BE 2210B	2.9BN	U	U	U	4.7B	262E 703
MW-7	Oct-13	- D	7660*E	2.1B U	U	499	2.4B	3.0B	4620BE	10.2	12.6B	88.0	4450*	11.4 87.6 *	1630BE	726		24.9B	2820BE	2.9DIN	- 11	U	U	3.0B	816E
		, D	35.9B	U	2.2B	73.4B	2.40	3.00	2950B	1.0B	1.1B	00.0	944	7	1170B	298	11	4.4B	972B	11	11	2220B	11	3.0B	17.4B
MW-9	Oct-13	T	1550*E	U II	2.4B	120B	0.30B	11	3770BE	3.9B	2.2B	5.6B	2180*	20.5*	1470BE	320		4.4B	1220BE	11		2060B	- 11	2.0B	29.8E
MW-10		D .	3.520	II	4.7B	80.6B	0.30B	II	5.010	3.8B	2.7B	12.5B	4,340	26.7	5.340	218	U U	4.1B	23.000	10.3N	- U	2.170	II	3.5B	42.9
(MW-9A)	Oct-13	T	8460*E	2.2B	6.3B	478	2.6B	2.4B	10900E	3.5B	5.2B	37.9	3120*	55.4*	8030E	795	Ü	7.0B	25600E	11.1	Ü	2100B	Ü	1.8B	72.6E
		D	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX
MW-11	Oct-13	Т	xx	XX	XX	XX	XX	xx	xx	XX	xx	xx	XX	XX	XX	xx	XX	xx	XX	xx	XX	XX	XX	XX	XX
MM 40	0-440	D	76.8B	U	U	141B	U	0.30B	27,900	0.9B	3.6B	4.6B	U	8.6	12,500	1,780	U	8.6B	4280B	U	U	24,400	U	U	41.5
MW-12	Oct-13	Т	192B*E	U	1.3B	147B	U	0.40B	27600E	1.1B	3.8B	5.0B	177*	7.4*	12300E	1,960	U	9.0B	4190BE	1.9B	U	25,700	U	U	38.9E
MM 40	0-440	D	31.0B	U	U	52.8B	U	U	21,500	0.5B	1.8B	2.9B	U	8	8,220	1,130	U	7.0B	15,100	2.0BN	U	32,900	U	U	46.1
IVIVV-13	Oct-13	T	146B*E	U	U	54.3B	U	U	19700E	1.1B	1.6B	4.5B	139*	8.1*	7580E	1,040	U	7.0B	14800E	3.0B	U	32,000	U	U	46.8E

- All data are presented in micrograms per liter (μg/L).
 Metals analysis by US EPA Method 6010/7470.
- 3. B Analyte found in associated method blank.
- 4. U Compound not detected at or above the method detection limit (MDL).
- 5. J Estimated concentration above the MDL but less than the reporting limit.
- 6. * Duplicate analysis not in control limits
- 7. E Serial dilution is not within acceptance criteria, or the reported value is estimated because of the presence of interference.

 8. AWQS New York State Ambient Water Quality Standards (TOGs 1.1.1); GV guidance value.
- 9. NA indicates 1) no standard or guidance value exists for the compound, or 2) sample was not analyzed for indicated compound.
- 10. xx Well could not be located.

 11. **BOLD** font in shaded cell indicates exceedances of AWQS+GV.

Page 1of 1 December 2014

Table 3 Analytical Results for Leachate and Ditch Samples Beaver Smelting Fallsburg, New York Contaminants of Concern

	Leachate #1 10/21/1981	Leachate #1 11/19/1981	Leachate Sample 10/27/2000	Leachate Sample 4/17/2002	Leachate Sample 5/26/2009	Drainage Ditch 10/22/2013	West Seep 6/27/2014	Up Ditch 6/27/2014	Up Pipe 6/27/2014	Down Pipe 6/27/2014	Down Ditch 6/27/2014	Ponded Area 6/27/2014
Analyte				SDG: 107-03								
Aluminum	NA	NA	3820	3100	3490	4080 *E	45200	1320	234	1430	6810	18000
Antimony	NA	NA	36	U	U	12.1 B	18.8 B	U	5.7 B	5.9 B	3.2 B	153
Arsenic	U	40	48	U	U	4.2 B	18.8	U	U	U	3.2 B	14.7
Barium	810	550	225	U	U	112 B	322	196 B	82.4B	118 B	152 B	195 B
Beryllium	NA	NA	U	U	U	6.2	2.7 B	0.6 B	0.2 B	0.5 B	0.8 B	1.1 B
Cadmium	769	38	20	U	15.7	12.4	6.8	3.5 B	1.5 B	3.8 B	2.2 B	19.4
Calcium	NA	NA	17500	58000	9140	6460 E	20900	4230 B	2950 B	8550	4980 B	9250
Chromium	25	36	4.8	U	U	5.7 B	30.2	0.7 B	1.1 B	1.2 B	4.9 B	20.5
Cobalt	NA	NA	20	U	U	5.3 B	31.5 B	0.4 B	3 B	2.8 B	6.7 B	30.2 B
Copper	NA	NA	690	5100	1130	559	1780	134	64.5	154	298	2440
Iron	NA	NA	35900	1300	6130	7520 *	31600	62.8 B	33.9 B	338	4170	12200
Lead	13.63	200.45	168	18	240	503 *	370	4.8	192	86.1	47.3	5800
Magnesium	NA	NA	20900	810 B	5750	7030 E	5410 E	539 E	771 B	2830 E	1180 E	5350 E
Manganese	NA	NA	3210	180	668	1110	2510	435	89.8	1320	965	1560
Mercury	0.9	0.9	0.2	U	U	U	0.14 B	U	U	U	U	0.15 B
Nickel	NA	NA	19.2	U	U	13.5 B	45.3	11.7 B	3.7 B	12 B	13.7 B	46.6
Potassium	NA	NA	19700	84000	80300	65700 E	15300	3950 B	806 B	26900	7500	27400
Selenium	U	U	16	66	U	5.8	31.4	2 B	U	U	5.2	6.3
Silver	U	U	U	U	U	U	4.0 B	U	0.47 B	0.79	0.62 B	3.4 B
Sodium	NA	NA	63100	24000	27400	18800	3300 E	1230 E	1320 E	8600	2200 E	8550 E
Thallium	NA	NA	U	U	U	U	4.9 B	U	U	4.5 B	U	U
Vanadium	NA	NA	8.9	U	U	3.5 B	38.3 B	U	0.6 B	0.22	5.8 B	13.7 B
Zinc	NA	NA	569	16 B	492	397 E	370	156	212	131	129	1290

- 1. B Analyte found in associated method blank.
- 2. U Compound not detected at or above the method detection limit (MDL).
- 3. J Estimated concentration above the MDL but less than the reporting limit.
- 4. * Duplicate analysis not in control limits
- 5. E Serial dilution is not within acceptance criteria, or the reported value is estimated because of the presence of interference.
- 6. All locations are approximate and not from same location each event.
- 7. All units are in micrograms per liter (µg/L).
- 8. See Figure 4 for approximate locations of samples collected in 2014.

Page 1 of 1 January 2015

Appendix A

Site-Wide Semi-Annual Inspection Form

Beaver Smelting Beaver Lane Fallsburg, New York

2011 CON4	1		
Monitoring will	retwork.		1
Monstony well (Engineering Control (s): Gwintercoptor	Inspection Date:	1/28	114
tounch		-7-7	

Engineering Control (s):	er cop	30(ion Date: 1/ 04/11	
Item	Yes	No	N/A	Comments	
Does the Engineering Control continue to perform as designed?	X			Should Sample and evaluate Seepoth	
Does the Engineering Control continue to protect human health and the environment?	χ			Minould Sample and Ivaluate Seepot	
Does the Engineering Control comply with requirements established in the SMP?	X				
Has remedial performance criteria been achieved or maintained?	Х			maintained	
Has sampling and analysis of appropriate media been performed during the monitoring event?	X			October 2013 - groundwater and discinouse ditch Sampled	
Have there been any modifications made to the remedial or monitoring system?		X			
Does the remedial or monitoring system need to be changed or altered at this time?		X			
Has there been any intrusive activity, excavation, or construction occurred at the site?		Χ			
Were the activities mentioned above, performed in accordance with the SMP?			X		
Was there a change in the use of the site or were there new structures constructed on the site?	X		.,	last inspection (1/2012) reported Soil piles and site. This inspection found numerous log piles 1	ound Nachmer
In case a new occupied structure is constructed or the use of the current building changed, was a vapor intrusion evaluation done?			X		
Were new mitigation systems installed based on monitoring results?			X		
Were the groundwater wells in the monitoring network inspected during this site inspection? If so, were the Monitoring Well Field Inspection Logs Completed?	Χ				

Note: Upon completion of the form any non-conforming items warranting corrective action should be identified here within.

Name of Inspector: Kully Luric w/Chns French	Signature of Inspector: Luy Luie
Inspector's Company: AFCOM	Date: 1/28/9/14

* Drawoge dutch on bust side of landfill was sampled in oct. 2013 and found to have high levels of lead and offer metals. Seep likely drawns to this ditch.

	SITE ID.: INSPECTO		35300 (F
MONITORING WELL FIELD INSPECTION LOG	DATE/TIM	E:	1/28/4
- The state of the	WEILID.:		MW-2
		7/20	Ivo
WELL VISIBLE? (If not, provide directions below) WELL COORDINATES? NYTM XNYTM Y PDOP Reading from Trimble Pathfinder: Satelites: GPS Method (circle) Trimble And/Or Magellan	ţ	YES	NO
	1	YES	NO
WELL I.D. VISIBLE?			<u> </u>
WELL LOCATION MATCH SITE MAP? (if not, sketch actual location on back)	4		
WELL I.D. AS IT APPEARS ON PROTECTIVE CASING OR WELL: SURFACE SEAL PRESENT?		YES	NO X
HEADSPACE READING (ppm) AND INSTRUMENT USED TYPE OF PROTECTIVE CASING AND HEIGHT OF STICKUP IN FEET (If applicable) PROTECTIVE CASING MATERIAL TYPE: MEASURE PROTECTIVE CASING INSIDE DIAMETER (Inches):		ri Gy Si za	4
LOCK PRESENT?	1	YES	NO
LOCK FUNCTIONAL?			
DID YOU REPLACE THE LOCK?			17
IS THERE EVIDENCE THAT THE WELL IS DOUBLE CASED? (If yes, describe below)	1		<
WELL MEASURING POINT VISIBLE?			
MEASURE WELL DEPTH FROM MEASURING POINT (Feet): MEASURE DEPTH TO WATER FROM MEASURING POINT (Feet): MEASURE WELL DIAMETER (Inches): WELL CASING MATERIAL; PHYSICAL CONDITION OF VISIBLE WELL CASING; ATTACH ID MARKER (if well ID is confirmed) and IDENTIFY MARKER TYPE PROXIMITY TO UNDERGROUND OR OVERHEAD UTILITIES.	3	PV Go	Scal
DESCRIBE ACCESS TO WELL: (Include accessibility to truck mounted rig, natural obstructions, overhead power lines, proximity to permanent structures, etc.); ADD SKETCH OF LOCATION ON BACK, IF NECE CONTROL TO A form the form of the form	CESSARY.	unel	well
DESCRIBE WELL SETTING (For example, located in a field, in a playground, on pavement, in a garden,	etc.)		
AND ASSESS THE TYPE OF RESTORATION REQUIRED. Notated at the boundary between a field (landfill Soil cap) in tent of large comparted steel building.) and	brish	pile

in tent of large corngaged fleet building.

IDENTIFY ANY NEARBY POTENTIAL SOURCES OF CONTAMINATION, IF PRESENT

(e.g. Gas station, salt pile, etc.):

REMARKS:

SITE NAME: Beaver Smelting	SITE ID.: 3.573.00.5
Des your supplier of the suppl	INSPECTOR: C.F.
MONITORING WELL FIELD INSPECTION LOG	DATE/TIME: 1/25/19
	WEILID.: MU-3
	YES NO
WELL VISIBLE? (If not, provide directions below)	
PDOP Reading from Trimble Pathfinder: Satelites:	
GPS Method (circle) Trimble And/Or Magellan	1,500 100
WELL LD MIGIDLES	YES NO
WELL I.D. VISIBLE? WELL LOCATION MATCH SITE MAP? (if not, sketch actual location on back)	\ \frac{1}{\sigma}
•	
WELL I.D. AS IT APPEARS ON PROTECTIVE CASING OR WELL:	YES NO
SURFACE SEAL PRESENT?	X
SURFACE SEAL COMPETENT? (If cracked, heaved etc., describe below)	X
PROTECTIVE CASING IN GOOD CONDITION? (If damaged, describe below)	
HEADSPACE READING (ppm) AND INSTRUMENT USED	
TYPE OF PROTECTIVE CASING AND HEIGHT OF STICKUP IN FEET (If applicable)	riser 2 ft
PROTECTIVE CASING MATERIAL TYPE:	4 22
MEASURE PROTECTIVE CASING INSIDE DIAMETER (Inches):	
	YES NO
LOCK PRESENT?	X
LOCK FUNCTIONAL?	
DID YOU REPLACE THE LOCK?	
IS THERE EVIDENCE THAT THE WELL IS DOUBLE CASED? (If yes, describe below)	X
WELL MEASURING POINT VISIBLE?	
MEASURE WELL DEPTH FROM MEASURING POINT (Feet):	
MEASURE DEPTH TO WATER FROM MEASURING POINT (Feet):	
MEASURE WELL DIAMETER (Inches):	
WELL CASING MATERIAL:	Steet NC
PHYSICAL CONDITION OF VISIBLE WELL CASING:	cool The
ATTACH ID MARKER (if well ID is confirmed) and IDENTIFY MARKER TYPE	· · · ·
PROXIMITY TO UNDERGROUND OR OVERHEAD UTILITIES	no
DESCRIBE ACCESS TO WELL: (Include accessibility to truck mounted rig, natural obstructions, overhood, and the second response of the seco	cad CESSARV
power lines, proximity to permanent structures, etc.); ADD SKETCH OF LOCATION ON BACK, IF NE	Cessari.
Accessible by truck munited rig, ~ 100 justs to moved	3 pkcfare 110
Symile of obstactions.	
DESCRIBE WELL SETTING (For example, located in a field, in a playground, on pavement, in a garden	etc.)
AND ASSESS THE TYPE OF RESTORATION REQUIRED.	,/
	1129 Class
	WU) (E U
the luna fill	
AS	

IDENTIFY ANY NEARBY POTENTIAL SOURCES OF CONTAMINATION, IF PRESENT (e.g. Gas station, salt pile, etc.): REMARKS:

STEP TO THE TOTAL PROPERTY OF THE PROPERTY OF	SITE ID.:	353005
MONITORING WELL FIELD INSPECTION LOG	INSPECTOR: DATE/TIME: WEILID.:	1/29/14 1 MW-4
	YES	INO]
WELL VISIBLE? (If not, provide directions below)		
PDOP Reading from Trimble Pathfinder: Satelites:		
GPS Method (circle) Trimble And/Or Magellan	YES	NO
WELL I.D. VISIBLE?		
WELL LOCATION MATCH SITE MAP? (if not, sketch actual location on back)		
WELL I.D. AS IT APPEARS ON PROTECTIVE CASING OR WELL:	YES	NO
SURFACE SEAL PRESENT?	X	
SURFACE SEAL COMPETENT? (If cracked, heaved etc., describe below)	×	
PROTECTIVE CASING IN GOOD CONDITION? (If damaged, describe below)	X	
HEADSPACE READING (ppm) AND INSTRUMENT USED TYPE OF PROTECTIVE CASING AND HEIGHT OF STICKUP IN FEET (If applicable)	0.80	2 14
PROTECTIVE CASING MATERIAL TYPE:	Store	
MEASURE PROTECTIVE CASING INSIDE DIAMETER (Inches):	1 100	1 10 1
LOCK PRESENT?	YES	NO
LOCK FUNCTIONAL?		X
DID YOU REPLACE THE LOCK?		X
IS THERE EVIDENCE THAT THE WELL IS DOUBLE CASED? (If yes, describe below)		X
WELL MEASURING POINT VISIBLE?	L	$\perp X$
MEASURE WELL DEPTH FROM MEASURING POINT (Feet):	-	
MEASURE DEPTH TO WATER FROM MEASURING POINT (Feet):	S-	
WELL CASING MATERIAL:	G	and OUC.
PHYSICAL CONDITION OF VISIBLE WELL CASING;	5 1000	Street 10
ATTACH ID MARKER (if well ID is confirmed) and IDENTIFY MARKER TYPE	9	12070
PROXIMITY TO UNDERGROUND OR OVERHEAD UTILITIES	no	
DESCRIBE ACCESS TO WELL: (Include accessibility to truck mounted rig, natural obstructions, overhea	ad	
power lines, proximity to permanent structures, etc.); ADD SKETCH OF LOCATION ON BACK, IF NEC	CESSARY.	
Accessible to truck number vig , ~ 100 gds to nearest St	ructure, no	natural
obstructions or whileties	14.7 - 11.7	
DESCRIBE WELL SETTING (For example, located in a field, in a playground, on pavement, in a garden,	etc.)	
AND ASSESS THE TYPE OF RESTORATION REQUIRED		
Open einen, On Southwest side of land till, in	d. below.	the
THE TOP		
DENTIFY ANY NEARBY POTENTIAL SOURCES OF CONTAMINATION, IF PRESENT		
(e.g. Gas station, salt pile, etc.):		
	34	
REMARKS:		

SITE NAME:	Beaver Smelling	SITE ID.:	353005
- CONTROL N	NO THE PARTY OF TH	INSPECTOR:	1015
MONITORII	NG WELL FIELD INSPECTION LOG	DATE/TIME:	1/24/14 11
		WEII ID.:	MW-S
#		YES	NO
WELL VISIBLE? ((If not, provide directions below)	×	
	ATES? NYTM XNYTM Y		
	eading from Trimble Pathfinder: Satelites: thod (circle) Trimble And/Or Magellan		
Ora Met	mod (circle) (Timble Allwor Wageman	YES	NO
WELL I.D. VISIBL	E? <u>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>	,, X	
WELL LOCATION	N MATCH SITE MAP? (if not, sketch actual location on back)	X	
	M. C		
WELL I.D. AS IT A	APPEARS ON PROTECTIVE CASING OR WELL: $\wedge \vee \cdot \zeta$	YES	NO
SURFACE SEAL P	PRESENT?	X	
	COMPETENT? (If cracked, heaved etc., describe below)	X	
	SING IN GOOD CONDITION? (If damaged, describe below)	- X	
HEADSDACE DEV	ADING (ppm) AND INSTRUMENT USED		
	CTIVE CASING AND HEIGHT OF STICKUP IN FEET (If applicable)	riser	2 A
	SING MATERIAL TYPE:	Sie	
MEASURE PROTE	ECTIVE CASING INSIDE DIAMETER (Inches):		
		YES	NO
	AL?		1
	NCE THAT THE WELL IS DOUBLE CASED? (If yes, describe below)		X
WELL MEASURIN	IG POINT VISIBLE?	X	
NATION DE MONTO	DEDTH PROMENT AND A GLARAGE POLICE POLICE (F)		
	DEPTH FROM MEASURING POINT (Feet):	-	
	DIAMETER (Inches):	1:11	
	ATERIAL:	PVC	
	ITION OF VISIBLE WELL CASING:	good	
	KER (if well ID is confirmed) and IDENTIFY MARKER TYPE	- 1.0	
PROXIMITY TO U	NDERGROUND OR OVERHEAD UTILITIES	_h0	
DESCRIBE ACCES	S TO WELL: (Include accessibility to truck mounted rig, natural obstructions, over	head	
power lines, proximi	ity to permanent structures, etc.); ADD SKETCH OF LOCATION ON BACK, IF N	ECESSARY.	
是 lin	ited to no truck mount on rig accessibility, Su	ronded by	Small & 8
longe	trees, ~ 100 yds to reenes Structure	U	
DESCRIBE WELLS	SETTING (For example, located in a field, in a playground, on pavement, in a garde	en. etc.)	
	TYPE OF RESTORATION REQUIRED.	,	
	ted in a Small Storol of hees on the South.	end of the	Site
	all from beaver lane		
3		U	
DENTIFY ANY NE	EARBY POTENTIAL SOURCES OF CONTAMINATION, IF PRESENT		90
(e.g. Gas station, salt	t pile, etc.):		
REMARKS:			
	- Mark 27 (1911)		

SITE NAME: Beaver Smelling	SITE ID.: INSPECTOR:	353005
MONITORING WELL FIELD INSPECTION LOG	DATE/TIME: WEILID.:	1/24/14 12:15 MV-6
WELL VISIBLE? (If not, provide directions below)	Y	ES NO
GPS Method (circle) Trimble And/Or Magellan WELL I.D. VISIBLE?		ES NO
WELL LOCATION MATCH SITE MAP? (if not, sketch actual location on back)		
SURFACE SEAL PRESENT?		
HEADSPACE READING (ppm) AND INSTRUMENT USED TYPE OF PROTECTIVE CASING AND HEIGHT OF STICKUP IN FEET (If applicable) PROTECTIVE CASING MATERIAL TYPE:		ES NO
LOCK PRESENT? LOCK FUNCTIONAL? DID YOU REPLACE THE LOCK? IS THERE EVIDENCE THAT THE WELL IS DOUBLE CASED? (If yes,describe below) WELL MEASURING POINT VISIBLE?		X
MEASURE WELL DEPTH FROM MEASURING POINT (Feet): MEASURE DEPTH TO WATER FROM MEASURING POINT (Feet): MEASURE WELL DIAMETER (Inches): WELL CASING MATERIAL: PHYSICAL CONDITION OF VISIBLE WELL CASING: ATTACH ID MARKER (if well ID is confirmed) and IDENTIFY MARKER TYPE PROXIMITY TO UNDERGROUND OR OVERHEAD UTILITIES.	3	re no
DESCRIBE ACCESS TO WELL: (Include accessibility to truck mounted rig, natural obstructions, o power lines, proximity to permanent structures, etc.); ADD SKETCH OF LOCATION ON BACK, I Prof to none, Site is within the Louds line, ~ 200 y	F NECESSARY.	Shudure
DESCRIBE WELL SETTING (For example, located in a field, in a playground, on pavement, in a grand AND ASSESS THE TYPE OF RESTORATION REQUIRED. Side if within the Lovelshine off of a Small field.	arden, etc.)	
(e.g. Gas station, salt pile, etc.): Sult pile located ~ 150 yds from well on be other &	ide of a stee	p ditch (~4 14 00
REMARKS:	induite.	

SITE NAME:	Beaver	Smelting.		SITE ID.:	353005
MONITORING			TOG	INSPECTOI DATE/TIMI	
MONTORING	WELL LIED	INSI ECTION	LOG	WEILID.:	MU-7
		20.			TAGE 1
		74		-	YES NO
WELL VISIBLE? (If not WELL COORDINATES					
	g from Trimble Pathfine	NYTM Y	3:		
GPS Method (c		And/Or Magell			
OI & Memor (chole) Timble	Alla Ol Hagoli	all	Г	YES NO
WELLED VISIBLE?					X
			on on back)		X
	·			-	
WELL I.D. AS IT APPE	ARS ON PROTECTIV	E CASING OR WEL	L:	Ē	YES NO
SURFACE SEAL PRESE	ENT?		**********************		X
SURFACE SEAL COMP					×
PROTECTIVE CASING					X
				3-	() () []
TYPE OF PROTECTIVE				-	11/2/2/1
			***************************************	: 	11 21
MEASURE PROTECTIV	E CASING INSIDE I	DIAMETER (Inches):	***************************************	Т	YES NO
OCK PRESENT?		***			X
					25 X
OID YOU REPLACE TH	IE LOCK?	.,;,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
S THERE EVIDENCE T					
VELL MEASURING PC	DINT VISIBLE?	*************************	,.,.,.,	[X
MEASURE WELL DEPT	CIT ED OM ME VELIDIN	IC POINT (Foot)			
MEASURE DEPTH TO V				S-	
			·/· ··································		
					PVC
			**************************************	-	gued
TTACH ID MARKER (-	
					no
			4		
DESCRIBE ACCESS TO	WELL: (Include acces	ssibility to truck moun	ted rig, natural obstructions,	overhead	
	permanent structures, e	etc.); ADD SKETCH	OF LOCATION ON BACK,	IF NECESSARY.	1, 16
love t			ed rig Inthe for	Su Nonge	er by tree
~ 150 yels to	reapest and	me			
ESCRIBE WELL SETT	ING (For example, loc	ated in a field, in a pla	ayground, on pavement, in a	garden, etc.)	
ND ASSESS THE TVD	E OF PESTORATION	TRECHIRED			
D Calker	- Larade livas	in south	of a Small field	(Somo held	as mentioned
MIL ()	e woods the	3000	Of a special recise	(The state of the s
NW-6)					
DENTIFY ANY NEARB	RY POTENTIAL SOU	RCES OF CONTAMI	NATION, IF PRESENT		
e.g. Gas station, salt pile,			,	1023	
	~ 100 yds for	no well aper	ated by love dry	mage ditch	(~ 4 11 Deep)
- Fit his	4		× V , × 7	- 0	7)
EMARKS:					

SITE	NAME:	

Becover	Smelting

MONITORING WELL FIELD INSPECTION LOG

SITE ID.: INSPECTOR:

OR:

DATE/TIME:

CF 1/28/11 13:00

*	WEII ID.:		MU-1
		YES	NO
WELL VISIBLE? (If not, provide directions below)		X	
WELL COORDINATES? NYTM XNYTM Y			
PDOP Reading from Trimble Pathfinder: Satelites:			
GPS Method (circle) Trimble And/Or Magellan			
	1	YES	NO
WELL I.D. VISIBLE?			X
WELL LOCATION MATCH SITE MAP? (if not, sketch actual location on back)		X	
WELL LOCATION MATCH SITE MAY? (II not, sketch actual location on odex)	H		1
WELL I.D. AS IT APPEARS ON PROTECTIVE CASING OR WELL:			
WELL I.D. AS IT ATTEMAS ON TROTECTIVE CASING OR WELL.	ì	YES	T NO
SURFACE SEAL PRESENT?	(
SURFACE SEAL COMPETENT? (If cracked, heaved etc., describe below)	3	X	
PROTECTIVE CASING IN GOOD CONDITION? (If damaged, describe below)		X	1
PROTECTIVE CASING IN GOOD CONDITION? (II damaged, describe below)	7		
HE ADODA OF DEADING () AND INSTRUMENT LISED			
HEADSPACE READING (ppm) AND INSTRUMENT USEDTYPE OF PROTECTIVE CASING AND HEIGHT OF STICKUP IN FEET (If applicable)	1	riser	a.s f4
PROTECTIVE CASING MATERIAL TYPE:		Stee	
		3140	
MEASURE PROTECTIVE CASING INSIDE DIAMETER (Inches):		YES	T NO
LACK PROPERTY		1 LO	X
LOCK PRESENT?			1
LOCK FUNCTIONAL?	**		1->-
DID YOU REPLACE THE LOCK?			1
IS THERE EVIDENCE THAT THE WELL IS DOUBLE CASED? (If yes, describe below)	1		
WELL MEASURING POINT VISIBLE?			1 1
*			
MEASURE WELL DEPTH FROM MEASURING POINT (Feet):			
MEASURE DEPTH TO WATER FROM MEASURING POINT (Feet):) * 		
MEASURE WELL DIAMETER (Inches):		0.17	-
WELL CASING MATERIAL;		PV	<u></u>
PHYSICAL CONDITION OF VISIBLE WELL CASING:		90	00d
ATTACH ID MARKER (if well ID is confirmed) and IDENTIFY MARKER TYPE			
PROXIMITY TO UNDERGROUND OR OVERHEAD UTILITIES	I P	no	
DESCRIBE ACCESS TO WELL: (Include accessibility to truck mounted rig, natural obstructions, overhead	ead		
power lines, proximity to permanent structures, etc.); ADD SKETCH OF LOCATION ON BACK, IF NE	CESSARY.		
Within the words = Poor to no access, Boulders &	trees	in the	Liny
within the word = Poor to no access, Bondons &		****	
784 768			
DESCRIBE WELL SETTING (For example, located in a field, in a playground, on pavement, in a garder	etc.)		_
	-,/		
AND ASSESS THE TYPE OF RESTORATION REQUIRED. In the cooks 20 gds north of clearing and 12 gds	to Day	mat	
In the words, 20 gds north of clearing and 12 gds	1701 01	room.	
N 18 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
IDENTIFY ANY NEARBY POTENTIAL SOURCES OF CONTAMINATION, IF PRESENT			22
(e.g. Gas station, salt pile, etc.):			
(v.g. Oas station, san prio, cic.).			
REMARKS:			

SITENAME: Beaver Smelling	SITE ID.: INSPECTOR:	353005 CE
MONITORING WELL FIELD INSPECTION LOG	DATE/TIME:	1/28/K 13:
	WEILID.:	MU-10
WELL VISIBLE? (If not, provide directions below)	YES	NO
GPS Method (circle) Trimble And/Or Magellan	YES	NO
WELL LOCATION MATCH SITE MAP? (if not, sketch actual location on back)	. X	X
WELL I.D. AS IT APPEARS ON PROTECTIVE CASING OR WELL:	YES	NO
SURFACE SEAL PRESENT?	X	
HEADSPACE READING (ppm) AND INSTRUMENT USED TYPE OF PROTECTIVE CASING AND HEIGHT OF STICKUP IN FEET (If applicable) PROTECTIVE CASING MATERIAL TYPE:	riser Stor	
LOCK PRESENT? LOCK FUNCTIONAL? DID YOU REPLACE THE LOCK? IS THERE EVIDENCE THAT THE WELL IS DOUBLE CASED? (If yes, describe below) WELL MEASURING POINT VISIBLE?	YES X	NO X
MEASURE WELL DEPTH FROM MEASURING POINT (Feet): MEASURE DEPTH TO WATER FROM MEASURING POINT (Feet): MEASURE WELL DIAMETER (Inches): WELL CASING MATERIAL: PHYSICAL CONDITION OF VISIBLE WELL CASING: ATTACH ID MARKER (if well ID is confirmed) and IDENTIFY MARKER TYPE PROXIMITY TO UNDERGROUND OR OVERHEAD UTILITIES.		
DESCRIBE ACCESS TO WELL: (Include accessibility to truck mounted rig, natural obstructions, overhower lines, proximity to permanent structures, etc.); ADD SKETCH OF LOCATION ON BACK, IF NE medium to poor, cather stored of trees however constant ones would give Vehicular access a 21	ting down	2-3 Drid
DESCRIBE WELL SETTING (For example, located in a field, in a playground, on pavement, in a garden AND ASSESS THE TYPE OF RESTORATION REQUIRED. Within a Small charp of frees seperaling the horth & Sour Identities on an number of size of charp 20 yes from Identities.	dh sides d	The little
DENTIFY ANY NEARBY POTENTIAL SOURCES OF CONTAMINATION, IF PRESENT (e.g. Gas station, salt pile, etc.):	9	<u> </u>
REMARKS:		

SITE NAME: Beaver Smelting	SITE ID.:	353005
	INSPECTOR:	CF
MONITORING WELL FIELD INSPECTION LOG	DATE/TIME:	1/25/14 13-2
90	WEILID.:	MU-IL
· · · · · · · · · · · · · · · · · · ·	YE	s NO
WELL VISIBLE? (If not, provide directions below)	. X	
WELL COORDINATES? NYTM X NYTM Y		
PDOP Reading from Trimble Pathfinder: Satelites:		
GPS Method (circle) Trimble And/Or Magellan	[\vec{ve}	0 100
WELL ID VICIDIES	YE	S NO
WELL LOCATION MATCH SITE MAP? (if not, sketch actual location on back)		- X
WIELD LOCATION MATCH STIE MAY? (II NOI, SKEICH actual location on back)		
WELL I.D. AS IT APPEARS ON PROTECTIVE CASING OR WELL:	_ <u> </u>	n I NO I
SURFACE SEAL PRESENT?	N/A YE	S NO
SURFACE SEAL COMPETENT? (If cracked, heaved etc., describe below)	NVA	
PROTECTIVE CASING IN GOOD CONDITION? (If damaged, describe below)	/\'\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	
HEADSPACE READING (ppm) AND INSTRUMENT USED	10(+)	
TYPE OF PROTECTIVE CASING AND HEIGHT OF STICKUP IN FEET (If applicable)	n'se	c 4 ft
PROTECTIVE CASING MATERIAL TYPE:		leel
MEASURE PROTECTIVE CASING INSIDE DIAMETER (Inches):	Lyp	c I vo I
LOCK PRESENT?	YE	S NO
LOCK FUNCTIONAL?	🗘	Conto
DID YOU REPLACE THE LOCK?		X
IS THERE EVIDENCE THAT THE WELL IS DOUBLE CASED? (If yes, describe below)		X
WELL MEASURING POINT VISIBLE?	NA	
MEACURE WELL DEDUCED ON MEACURAIC BODIE (C.)		
MEASURE WELL DEPTH FROM MEASURING POINT (Feet):		
MEASURE WELL DIAMETER (Inches):	-	
WELL CASING MATERIAL:	(D)	VC
PHYSICAL CONDITION OF VISIBLE WELL CASING:		Chaun
ATTACH ID MARKER (if well ID is confirmed) and IDENTIFY MARKER TYPE	_5011.1.	Silver
PROXIMITY TO UNDERGROUND OR OVERHEAD UTILITIES	n	D
DESCRIBE ACCESS TO WELL: (Include accessibility to truck mounted rig, natural obstructions, overhead to the control of the con		
power lines, proximity to permanent structures, etc.); ADD SKETCH OF LOCATION ON BACK, IF NE	LESSAKI.	
Poor, within Stand at Small pine thees & up a small but	F steep	
benk. aso yets from read.		
DESCRIBE WELL SETTING (For example, located in a field, in a playground, on pavement, in a garden,	. etc.)	
AND ASSESS THE TYPE OF RESTORATION REQUIRED.	,	NO. TOWN
within a Stand of trees dividing field into northern &	Southern	helf
	L SCOOL SALV	100
on South side of stand, just into freet ~ 50 yds from rd.		
DENTIFY ANY NEARBY POTENTIAL SOURCES OF CONTAMINATION, IF PRESENT		φ.
(e.g. Gas station, salt pile, etc.):		
org. out station, state prio, etc.).	<u> </u>	Wallett
EMARKS: Well was locked and either was siezed you	and and	o locked
Well was loved and either was siezed Gi	see or or	e range

SITE	NAME:
SILE	TANKEAL IR.

Beaver	Sme	Hinu

SITE ID .:

INSPECTOR:

MONITORING WELL FIELD INSPECTION LOG	WEILID.:	My-12
The state of the s	YES	NO
WELL VISIBLE? (If not, provide directions below)		
WELL COORDINATES? NYTM X NYTM Y		
PDOP Reading from Trimble Pathfinder: Satelites:		
GPS Method (circle) Trimble And/Or Magellan	YES	NO]
WOLLED VIGIDLES	123	110
WELL LOCATION MATCH SITE MAP? (if not, sketch actual location on back)		
WELL LOCATION MATCH SITE MAP? (II not, sketch actual location oil back)		
WELL I.D. AS IT APPEARS ON PROTECTIVE CASING OR WELL:	YES	NO
SURFACE SEAL PRESENT?	X	
SURFACE SEAL COMPETENT? (If cracked, heaved etc., describe below)	X	
PROTECTIVE CASING IN GOOD CONDITION? (If damaged, describe below)	X	
HEADSPACE READING (ppm) AND INSTRUMENT USED		
TYPE OF PROTECTIVE CASING AND HEIGHT OF STICKUP IN FEET (If applicable)	rise	3.5 #
PROTECTIVE CASING MATERIAL TYPE:	Stre	
MEASURE PROTECTIVE CASING INSIDE DIAMETER (Inches):		
	YES	NO
LOCK PRESENT?	X	
LOCK FUNCTIONAL?		
DID YOU REPLACE THE LOCK?	1	
IS THERE EVIDENCE THAT THE WELL IS DOUBLE CASED? (If yes, describe below)	1	- X
WELL MEASURING POINT VISIBLE?	,	
MEASURE WELL DEPTH FROM MEASURING POINT (Feet):	·	
MEASURE DEPTH TO WATER FROM MEASURING POINT (Feet):	2	
MEASURE WELL DIAMETER (Inches):		1115
WELL CASING MATERIAL:	_ tr	FVC
PHYSICAL CONDITION OF VISIBLE WELL CASING; ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	_60	erel
ATTACH ID MARKER (if well ID is confirmed) and IDENTIFY MARKER TYPE	-	1.5
PROXIMITY TO UNDERGROUND OR OVERHEAD UTILITIES		10
DESCRIBE ACCESS TO WELL: (Include accessibility to truck mounted rig, natural obstructions, overhepower lines, proximity to permanent structures, etc.); ADD SKETCH OF LOCATION ON BACK, IF NEC	CESSARY.	- A V.
trum flimited to be truck ry access rough know	a die	Collincon
~ 100 yels to nearest Smothine		
DESCRIBE WELL SETTING (For example, located in a field, in a playground, on pavement, in a garden,	, etc.)	
AND ASSESS THE TYPE OF RESTORATION REQUIRED.	0 1.6	
hubbed in woods obthrebed by many Small - large	Tres	
DENTIFY ANY NEARBY POTENTIAL SOURCES OF CONTAMINATION, IF PRESENT	5	
(e.g. Gas station, salt pile, etc.):		
DDM A DVG.		
REMARKS:		

SI	ſE	NAME:		Be

Berver	Smelling
	1 /

SITE ID.:

INSPECTOR:

MONITORING WELL FIELD INSPECTION LOG

DATE/TIME:

	WEILID.:	4	MU-13
WELL VISIBLE? (If not, provide directions below)		YES N	0
WELL COORDINATES? NYTM XNYTM Y			
PDOP Reading from Trimble Pathfinder: Satelites:			
GPS Method (circle) Trimble And/Or Magellan	-		
Ÿ.	_	YES N	0
WELL I.D. VISIBLE?		X	
WELL LOCATION MATCH SITE MAP? (if not, sketch actual location on back)	L	X	
WELL I.D. AS IT APPEARS ON PROTECTIVE CASING OR WELL:	ĩ	YES T	NO I
SURFACE SEAL PRESENT?			K
SURFACE SEAL COMPETENT? (If cracked, heaved etc., describe below)	L		X
PROTECTIVE CASING IN GOOD CONDITION? (If damaged, describe below)	,L	X	
HEADSPACE READING (ppm) AND INSTRUMENT USED			
TYPE OF PROTECTIVE CASING AND HEIGHT OF STICKUP IN FEET (If applicable)	-	risor	3 4
PROTECTIVE CASING MATERIAL TYPE:	-	Sical	
MEASURE PROTECTIVE CASING INSIDE DIAMETER (Inches):			
	1	YES	NO
LOCK PRESENT?	F	X	X
LOCK FUNCTIONAL?			
DID YOU REPLACE THE LOCK?	1		X.
IS THERE EVIDENCE THAT THE WELL IS DOUBLE CASED? (If yes, describe below)	+		
WELL MEASURING POINT VISIBLE?	(L	$\Delta \perp$	
MEASURE WELL DEPTH FROM MEASURING POINT (Feet):	V.		
MEASURE DEPTH TO WATER FROM MEASURING POINT (Feet):	8=		
MEASURE WELL DIAMETER (Inches):	59		
WELL CASING MATERIAL:	¥-	PVC.	
PHYSICAL CONDITION OF VISIBLE WELL CASING:	-	Good	
ATTACH ID MARKER (if well ID is confirmed) and IDENTIFY MARKER TYPE		J	
PROXIMITY TO UNDERGROUND OR OVERHEAD UTILITIES	1-	no	
DESCRIBE ACCESS TO WELL: (Include accessibility to truck mounted rig, natural obstructions, overhower lines, proximity to permanent structures, etc.); ADD SKETCH OF LOCATION ON BACK, IF NI	ECESSARY.		
to the to we lamited to none, within the woods	over no	wigh tea	opun
(boulders, downed trees). I wo got to rearest structure		0	
DESCRIBE WELL SETTING (For example, located in a field, in a playground, on pavement, in a garde	n, etc.)		
AND ASSESS THE TYPE OF RESTORATION REQUIRED.	0		
In the words, between the wellen boundary of old lan	d fill &	a res	der 10.
the complete and the sound of t	10013		
DENTIFY ANY NEARBY POTENTIAL SOURCES OF CONTAMINATION, IF PRESENT	4(
(e.g. Gas station, salt pile, etc.):			
		8 7	-
REMARKS:			






Photo 1 Facing East. West Side of Landfill



Photo 3 Frozen Seep on West Side of Landfill



Photo 2 MW-4. Well Closest to Down Gradient Seep



Photo 4 Drainage Ditch on West Side of Landfill. Sampled October 2013.



Photo 5 Facing South Numerous Log Piles and Machinery



Photo 7 Cap Snow Covered but Appears Maintained



Photo 6 Above Ground Storage Tanks Next to Main Building



Photo 8 Facing North. Cleared Road and Machinery around Building

Site-Wide Semi-Annual Inspection Form

Beaver Smelting Beaver Lane Fallsburg, New York

Engineering Control (s): Gw introptor Inspection Date:	4	26	114	

Item	Yes	No	N/A	Comments
Does the Engineering Control continue to perform as designed?	X			
Does the Engineering Control continue to protect human health and the environment?	χ		n#	Surface water sampled to evaluate Seep.
Does the Engineering Control comply with requirements established in the SMP?	X			
Has remedial performance criteria been achieved or maintained?	X			maintained
Has sampling and analysis of appropriate media been performed during the monitoring event?			X	no monitoring since last inepectionsurface water sampled during this site inspection.
Have there been any modifications made to the remedial or monitoring system?		X		
Does the remedial or monitoring system need to be changed or altered at this time?		X		Pending results of seep sampling.
Has there been any intrusive activity, excavation, or construction occurred at the site?		X		
Were the activities mentioned above, performed in accordance with the SMP?	X			
Was there a change in the use of the site or were there new structures constructed on the site?		X		
In case a new occupied structure is constructed or the use of the current building changed, was a vapor intrusion evaluation done?			X	Section 1
Were new mitigation systems installed based on monitoring results?			X	
Were the groundwater wells in the monitoring network inspected during this site inspection? If so, were the Monitoring Well Field Inspection Logs Completed?	X			2:

Note: Upon completion of the form any non-conforming items warranting corrective action should be identified here within.

Name of Inspector: Kelly Lune	Signature of Inspector: Kelly June	
Inspector's Company: AECOM	Date: 06/24/14	

SITE NAME: Beaver	Smotting	

SITE ID.;

MONITORING WELL FIELD INSPECTION LOG	INSPECTOR: DATE/TIME: WEILID.:	6/26/14 MW-2
WELL VISIBLE? (If not, provide directions below) WELL COORDINATES? NYTM XNYTM Y	YE	
PDOP Reading from Trimble Pathfinder: Satelites: GPS Method (circle) Trimble And/Or Magellan	[YE	s Ino
WELL I.D. VISIBLE?		X
WELL LOCATION MATCH SITE MAP? (if not, sketch actual location on back)	X	
WELL I.D. AS IT APPEARS ON PROTECTIVE CASING OR WELL:	YE	ES NO
SURFACE SEAL PRESENT?		X
SURFACE SEAL COMPETENT? (If cracked, heaved etc., describe below)		X
PROTECTIVE CASING IN GOOD CONDITION? (If damaged, describe below)	X	
HEADSPACE READING (ppm) AND INSTRUMENT USED		
TYPE OF PROTECTIVE CASING AND HEIGHT OF STICKUP IN FEET (If applicable)	PIS	00 ~ 11
PROTECTIVE CASING MATERIAL TYPE:	54	el
MEASURE PROTECTIVE CASING INSIDE DIAMETER (Inches):	YE	ES NO
LOCK PRESENT?		X
LOCK FUNCTIONAL?		X
DID YOU REPLACE THE LOCK?		X
IS THERE EVIDENCE THAT THE WELL IS DOUBLE CASED? (If yes, describe below)		X
WELL MEASURING POINT VISIBLE?		X
MEASURE WELL DEPTH FROM MEASURING POINT (Feet):		
MEASURE DEPTH TO WATER FROM MEASURING POINT (Feet):	(
MEASURE WELL DIAMETER (Inches):	0-	
WELL CASING MATERIAL:	PV	C .
PHYSICAL CONDITION OF VISIBLE WELL CASING:	Cyd	200
ATTACH ID MARKER (if well ID is confirmed) and IDENTIFY MARKER TYPE	-0	
PROXIMITY TO UNDERGROUND OR OVERHEAD UTILITIES	N	0
DESCRIBE ACCESS TO WELL: (Include accessibility to truck mounted rig, natural obstructions, overhead power lines, proximity to permanent structures, etc.); ADD SKETCH OF LOCATION ON BACK, IF NEC	d ESSARY.	
accessible - but beaux nigelation buginning to go	wint	his area-
beginning to Shield will.		
DESCRIBE WELL SETTING (For example, located in a field, in a playground, on pavement, in a garden,	etc.)	
AND ASSESS THE TYPE OF RESTORATION REQUIRED. Field along boundary of landfill - Will Want to clear nigetation	<u> </u>	
DENTIFY ANY NEARBY POTENTIAL SOURCES OF CONTAMINATION, IF PRESENT (e.g. Gas station, salt pile, etc.):	320	
		Traillilli
EMARKS:		

SITE NAME:	Romer	Smeetine
		0

MONITORING WELL FIELD INSPECTION LOG

SITE ID.: INSPECTOR: DATE/TIME: 353005 |ZAL |U|24|14

¥(WEII ID.:		MW-3
		YES	NO
WELL VISIBLE? (If not, provide directions below)		X	
WELL COORDINATES? NYTM X NYTM Y			
PDOP Reading from Trimble Pathfinder: Satelites: Sateli			
of 5 (reduced (offices)) Ithlinete I magestant		YES	NO
WELL I.D. VISIBLE?	0	Χ	
WELL LOCATION MATCH SITE MAP? (if not, sketch actual location on back)		X	
WELL I.D. AS IT APPEARS ON PROTECTIVE CASING OR WELL:			
WELLID, AS IT AFTERIS ON PROTECTIVE CASING OR WELL,		YES	NO
SURFACE SEAL PRESENT?		X	
SURFACE SEAL COMPETENT? (If cracked, heaved etc., describe below)	_	×	
PROTECTIVE CASING IN GOOD CONDITION? (If damaged, describe below)	1	X	
HEADSPACE READING (ppm) AND INSTRUMENT USED			
TYPE OF PROTECTIVE CASING AND HEIGHT OF STICKUP IN FEET (If applicable)	7	L' N	Ser
PROTECTIVE CASING MATERIAL TYPE:	-4	Steal	
MEASURE PROTECTIVE CASING INSIDE DIAMETER (Inches):	г	VEC	LNO
LOCK BREGENTS	-	YES	NO
LOCK PRESENT? LOCK FUNCTIONAL?			X
DID YOU REPLACE THE LOCK?	"		X
IS THERE EVIDENCE THAT THE WELL IS DOUBLE CASED? (If yes, describe below)			X
WELL MEASURING POINT VISIBLE?		/1154/1111	X
MEASURE WELL DEPTH FROM MEASURING POINT (Feet):			
MEASURE DEPTH TO WATER FROM MEASURING POINT (Feet):	-		
MEASURE WELL DIAMETER (Inches):	1		
WELL CASING MATERIAL:		DVC	
PHYSICAL CONDITION OF VISIBLE WELL CASING:,		pood	
ATTACH ID MARKER (if well ID is confirmed) and IDENTIFY MARKER TYPE	-	10	
PROXIMITY TO UNDERGROUND OR OVERHEAD UTILITIES	<u></u>	NO	
DESCRIBE ACCESS TO WELL: (Include accessibility to truck mounted rig, natural obstructions, overhe	ad		
power lines, proximity to permanent structures, etc.); ADD SKETCH OF LOCATION ON BACK, IF NE			
accessible - tew obstructions			
		115	
DESCRIBE WELL SETTING (For example, located in a field, in a playground, on pavement, in a garden,	. etc.)		
AND ASSESS THE TYPE OF RESTORATION REQUIRED.	, ,		
Below rip rap on west slope of larafill	Ÿ		
TOPE OF TOPE OF TOTAL			
* * * * * * * * * * * * * * * * * * *			
DENTIFY ANY NEARBY POTENTIAL SOURCES OF CONTAMINATION, IF PRESENT	2		
(e.g. Gas station, salt pile, etc.):			
		70	
REMARKS:			

SITE ID.:

MONITORING WELL FIELD INSPECTION LOG	DATE/TIME WELLID.:		6/26/1 MW-L
WELL VISIBLE? (If not, provide directions below) WELL COORDINATES? NYTM XNYTM Y PDOP Reading from Trimble Pathfinder: Satelites:	. [YES	NO
GPS Method (circle) Trimble And/Or Magellan	Г	YES	NO
WELL I.D. VISIBLE?		X	
WELL I.D. AS IT APPEARS ON PROTECTIVE CASING OR WELL:	r	YES	l no l
SURFACE SEAL PRESENT?	-	X	
SURFACE SEAL COMPETENT? (If cracked, heaved etc., describe below)		Y	
PROTECTIVE CASING IN GOOD CONDITION? (If damaged, describe below)		X	
HEADSPACE READING (ppm) AND INSTRUMENT USED			
TYPE OF PROTECTIVE CASING AND HEIGHT OF STICKUP IN FEET (If applicable)	ż	21 0	ser
PROTECTIVE CASING MATERIAL TYPE:		stee	1
MEASURE PROTECTIVE CASING INSIDE DIAMETER (Inches):	-		
	-	YES	NO
LOCK PRESENT?	-		1
LOCK FUNCTIONAL?			14
DID YOU REPLACE THE LOCK?	_		1 X
IS THERE EVIDENCE THAT THE WELL IS DOUBLE CASED? (If yes, describe below)	-		X
WELL MEASURING POINT VISIBLE?	L		1 1
MEASURE WELL DEPTH FROM MEASURING POINT (Feet):	-		
MEASURE DEPTH TO WATER FROM MEASURING POINT (Feet):			
MEASURE WELL DIAMETER (Inches):	-	010	
WELL CASING MATERIAL:	7	PVC	
PHYSICAL CONDITION OF VISIBLE WELL CASING:	-4	jus	
ATTACH ID MARKER (if well ID is confirmed) and IDENTIFY MARKER TYPE	-	. 10	
PROXIMITY TO UNDERGROUND OR OVERHEAD UTILITIES	-	NO	
DESCRIBE ACCESS TO WELL: (Include accessibility to truck mounted rig, natural obstructions, overher power lines, proximity to permanent structures, etc.); ADD SKETCH OF LOCATION ON BACK, IF NEGROUP ACCESSIBLE	ad CESSARY.		
AND ASSESS THE TYPE OF RESTORATION REQUIRED. Below OP (AD ON) LUST SIDE OF LAND AND ASSESS THE TYPE OF RESTORATION REQUIRED.	elc.)		
IDENTIFY ANY NEARBY POTENTIAL SOURCES OF CONTAMINATION, IF PRESENT (e.g. Gas station, salt pile, etc.):			z.
	.1		
REMARKS:			

SI	TE	NAME:	

Beaver	Smelting

SITE ID.: INSPECTOR:

MONITORING WELL FIELD INSPECTION LOG	DATE/TIME: WEILID.:		6/24/14 MW-5
V 11 Springer 11 S			NO
WELL VISIBLE? (If not, provide directions below)		X	
WELL COORDINATES? NYTM XNYTM Y			
PDOP Reading from Trimble Pathfinder: Satelites: Satelites:			
GPS Method (circle) Trimble And/Or Magellan		YES	NO
WELL I.D. VISIBLE?		<u>/</u>	110
WELL LOCATION MATCH SITE MAP? (if not, sketch actual location on back)		7	
	1	- A	
WELL I.D. AS IT APPEARS ON PROTECTIVE CASING OR WELL:		YES	NO
SURFACE SEAL PRESENT?		X	
SURFACE SEAL COMPETENT? (If cracked, heaved etc., describe below)		X	
PROTECTIVE CASING IN GOOD CONDITION? (If damaged, describe below)		X	
HEADSPACE READING (ppm) AND INSTRUMENT USED	-	. 0	
TYPE OF PROTECTIVE CASING AND HEIGHT OF STICKUP IN FEET (If applicable)	.2		sor
PROTECTIVE CASING MATERIAL TYPE:	-5	tee	
MEASURE PROTECTIVE CASING INSIDE DIAMETER (Inches):		YES	NO
LOCK PRESENT?	1	1123	X
LOCK FUNCTIONAL?	-		
DID YOU REPLACE THE LOCK?			\times
IS THERE EVIDENCE THAT THE WELL IS DOUBLE CASED? (If yes, describe below)	_		X
WELL MEASURING POINT VISIBLE?		X	
MEASURE WELL DEPTH FROM MEASURING POINT (Feet):	-		
MEASURE DEPTH TO WATER FROM MEASURING POINT (Feet):			
MEASURE WELL DIAMETER (Inches):	-4	VC	
WELL CASING MATERIAL:	_1	Control	
PHYSICAL CONDITION OF VISIBLE WELL CASING:		LOCK	
ATTACH ID MARKER (if well ID is confirmed) and IDENTIFY MARKER TYPE PROXIMITY TO UNDERGROUND OR OVERHEAD UTILITIES	,	NO	
PROXIMITY TO UNDERGROUND OR OVERHEAD UTILITIES	· ·	100	
DESCRIBE ACCESS TO WELL: (Include accessibility to truck mounted rig, natural obstructions, overhower lines, proximity to permanent structures, etc.); ADD SKETCH OF LOCATION ON BACK, IF NE	ead CESSARY.		
DESCRIBE WELL SETTING (For example, located in a field, in a playground, on pavement, in a garder AND ASSESS THE TYPE OF RESTORATION REQUIRED. Within thus prush - Southwestern and below			
WHITE THESE PLAST SCOTTING FOR WITH LETTER	Cock D TITE		
DENTIFY ANY NEARBY POTENTIAL SOURCES OF CONTAMINATION, IF PRESENT			
(e.g. Gas station, salt pile, etc.):			
(v.g. Oue station, sait priv, oter).			
REMARKS:			

OLI BITIKUIDI	SITE ID.: INSPECTOR:	35300 KAL
	DATE/TIME:	6/24/
	WEILID.:	MW-
	I VE	e Ino
WELL VISIBLE? (If not, provide directions below)	YE	S NO
WELL COORDINATES? NYTM XNYTM Y	J	
PDOP Reading from Trimble Pathfinder: Satelites:		
GPS Method (circle) Trimble And/Or Magellan		Was a second state of the
	YE	S NO
WELL I.D. VISIBLE?		×
WELL LOCATION MATCH SITE MAP? (if not, sketch actual location on back)	L_>	
w (4)	1	
WELL I.D. AS IT APPEARS ON PROTECTIVE CASING OR WELL:	YE	S NO
CURRACE CEAL ARECENTA	×	.3 140
SURFACE SEAL PRESENT?SURFACE SEAL COMPETENT? (If cracked, heaved ctc., describe below)	-	
PROTECTIVE CASING IN GOOD CONDITION? (If damaged, describe below)		
PROTECTIVE CASING IN GOOD CONDITION? (II dainaged, describe below)		
HEADSPACE READING (ppm) AND INSTRUMENT USED		
TYPE OF PROTECTIVE CASING AND HEIGHT OF STICKUP IN FEET (If applicable)	21	Mer
PROTECTIVE CASING MATERIAL TYPE: ,,,,,,,	<-	eel
MEASURE PROTECTIVE CASING INSIDE DIAMETER (Inches):		
	YE	S NO
LOCK PRESENT?		×
LOCK FUNCTIONAL?		×
DID YOU REPLACE THE LOCK?		Y
S THERE EVIDENCE THAT THE WELL IS DOUBLE CASED? (If yes, describe below)		X
WELL MEASURING POINT VISIBLE?	LX	
MEASURE WELL DEPTH FROM MEASURING POINT (Feet):		
MEASURE DEPTH TO WATER FROM MEASURING POINT (Feet):		
MEASURE WELL DIAMETER (Inches):	No.	
WELL CASING MATERIAL:	44	
PHYSICAL CONDITION OF VISIBLE WELL CASING:	gi	200
ATTACH ID MARKER (if well ID is confirmed) and IDENTIFY MARKER TYPE	-	
ROXIMITY TO UNDERGROUND OR OVERHEAD UTILITIES	N	3
DESCRIBE ACCESS TO WELL: (Include accessibility to truck mounted rig, natural obstructions, overhe	ad	
power lines, proximity to permanent structures, etc.); ADD SKETCH OF LOCATION ON BACK, IF NEC	CESSARY.	
very poor - accessible by toot		
DESCRIBE WELL SETTING (For example, located in a field, in a playground, on pavement, in a garden,	etc.)	
AND ASSESS THE TYPE OF RESTORATION REQUIRED,		
Within trues along open trud	X	

IDENTIFY ANY NEARBY POTENTIAL SOURCES OF CONTAMINATION, IF (e.g. Gas station, salt pile, etc.): REMARKS: Sketch

CATCHE BLABASE	R	Smoltine
SITE NAME:	Deary	SI WOLLING
MONITOR	ING WELL F	IELD INSPEC
		*

SITE ID.: INSPECTOR: DATE/TIME: WEILID.:

TION LOG

	THE INC.
	YES NO
WELL VISIBLE? (If not, provide directions below)	~
WELL COORDINATES? NYTM X NYTM Y NYTM Y	
PDOP Reading from Trimble Pathfinder: Satelites:	
GPS Method (circle) Trimble And/Or Magellan	
	YES NO
WELL I.D. VISIBLE?	X
WELL LOCATION MATCH SITE MAP? (if not, sketch actual location on back)	L_X_1
WELL I.D. AS IT APPEARS ON PROTECTIVE CASING OR WELL:	
WELL I.D. AS IT ATTEMAS ON TROTLETTY E CHOICE ON WELL, MINIMARIAN	YES NO
SURFACE SEAL PRESENT?	X
SURFACE SEAL COMPETENT? (If cracked, heaved etc., describe below)	X
PROTECTIVE CASING IN GOOD CONDITION? (If damaged, describe below)	X
· · · · · · · · · · · · · · · · · · ·	
HEADSPACE READING (ppm) AND INSTRUMENT USED	A
TYPE OF PROTECTIVE CASING AND HEIGHT OF STICKUP IN FEET (If applicable)	21 riser
PROTECTIVE CASING MATERIAL TYPE:	Seel
MEASURE PROTECTIVE CASING INSIDE DIAMETER (Inches):	
	YES NO
LOCK PRESENT?	X
LOCK FUNCTIONAL?	
DID YOU REPLACE THE LOCK?	X
IS THERE EVIDENCE THAT THE WELL IS DOUBLE CASED? (If yes, describe below)	- X
WELL MEASURING POINT VISIBLE?	
MEASURE WELL DEPTH FROM MEASURING POINT (Feet):	77
MEASURE DEPTH TO WATER FROM MEASURING POINT (Feet):	
MEASURE WELL DIAMETER (Inches):	
WELL CASING MATERIAL:	
PHYSICAL CONDITION OF VISIBLE WELL CASING;	PVC
ATTACH ID MARKER (if well ID is confirmed) and IDENTIFY MARKER TYPE	Scool
PROXIMITY TO UNDERGROUND OR OVERHEAD UTILITIES	<u> </u>
DESCRIBE ACCESS TO WELL: (Include accessibility to truck mounted rig, natural obstructions, overhea	nd
power lines, proximity to permanent structures, etc.); ADD SKETCH OF LOCATION ON BACK, IF NEC	ESSARY.
mr - accossible - fort -hil of racil	
get accessible by tall but to thisty	
DESCRIBE WELL SETTING (For example, located in a field, in a playground, on pavement, in a garden, or	etc.)
AND ASSESS THE TYPE OF RESTORATION REQUIRED.	
in heavily wood of area	9 V
In new reg wood at a rec	
IDENTIFY ANY NEARBY POTENTIAL SOURCES OF CONTAMINATION, IF PRESENT	34
(e.g. Gas station, salt pile, etc.):	
(c.g. Gas station, san pine, etc.).	
REMARKS:	

SITE NAME:	Beaver	Smothers

SITE ID.: INSPECTOR: 353005 12AL 6/26/14

MONITORING WELL FIELD INSPECTION LOG

DATE/TIME:

	WEILID.:	Mw-9
WELL VISIBLE? (If not, provide directions below)	1	YES NO
WELL COORDINATES? NYTM XNYTM Y		
PDOP Reading from Trimble Pathfinder: Satelites:		
GPS Method (circle) Trimble And/Or Magellan		
		YES NO
WELL I.D. VISIBLE?		X
WELL LOCATION MATCH SITE MAP? (if not, sketch actual location on back)		X
WELL I.D. AS IT APPEARS ON PROTECTIVE CASING OR WELL:		YES NO
SURFACE SEAL PRESENT?		×
SURFACE SEAL COMPETENT? (If cracked, heaved etc., describe below)		V
PROTECTIVE CASING IN GOOD CONDITION? (If damaged, describe below)		<u>x</u>
HEADSPACE READING (ppm) AND INSTRUMENT USED		
TYPE OF PROTECTIVE CASING AND HEIGHT OF STICKUP IN FEET (If applicable)	3	1 CISOC
PROTECTIVE CASING MATERIAL TYPE:	89-	Stee
MEASURE PROTECTIVE CASING INSIDE DIAMETER (Inches):		YES NO
LOCK PRESENT?		X
LOCK FUNCTIONAL?	···	X
DID YOU REPLACE THE LOCK?	_	X
IS THERE EVIDENCE THAT THE WELL IS DOUBLE CASED? (If yes, describe below)		X
WELL MEASURING POINT VISIBLE?	<u> </u>	
MEASURE WELL DEPTH FROM MEASURING POINT (Feet):	_	
MEASURE DEPTH TO WATER FROM MEASURING POINT (Feet):		
MEASURE WELL DIAMETER (Inches):	-	
WELL CASING MATERIAL:	7	7224
PHYSICAL CONDITION OF VISIBLE WELL CASING:		3000
ATTACH ID MARKER (if well ID is confirmed) and IDENTIFY MARKER TYPE	-	TA
PROXIMITY TO UNDERGROUND OR OVERHEAD UTILITIES	-	00
DESCRIBE ACCESS TO WELL: (Include accessibility to truck mounted rig, natural obstructions, overh power lines, proximity to permanent structures, etc.); ADD SKETCH OF LOCATION ON BACK, IF NE	ead ECESSARY.	
Procaccess - by toot but althout		
DESCRIBE WELL SETTING (For example, located in a field, in a playground, on pavement, in a garder	a etc.)	
	1, 010.)	
AND ASSESS THE TYPE OF RESTORATION REQUIRED.		
in heavily wooded area.		
IDENTIFY ANY NEARBY POTENTIAL SOURCES OF CONTAMINATION, IF PRESENT	$\hat{\epsilon}$	
(e.g. Gas station, salt pile, etc.):		
5 (14)		
REMARKS:		

		0	
SITE NAME:	Bearn	Sme	Hirs-
			0

SITE ID.: INSPECTOR:

124/14

MONITORING WELL FIELD INSPECTION LOG

DATE/TIME:

4	WEILID.:	MINTO
	YI	
WELL VISIBLE? (If not, provide directions below)	2	
WELL COORDINATES? NYTM XNYTM Y		9
PDOP Reading from Trimble Pathfinder: Satelites:		
GPS Method (circle) Trimble And/Or Magellan		ES NO
WELL I.D. VISIBLE?		X
WELL LOCATION MATCH SITE MAP? (if not, sketch actual location on back)	******	V
WELL LOCATION MATCH SITE MAY! (II not, sketch actual location on back)		*
WELL I.D. AS IT APPEARS ON PROTECTIVE CASING OR WELL:	-	
		ES NO
SURFACE SEAL PRESENT?	2	
SURFACE SEAL COMPETENT? (If cracked, heaved etc., describe below)	777	<u> </u>
PROTECTIVE CASING IN GOOD CONDITION? (If damaged, describe below)		
HEADSPACE READING (ppm) AND INSTRUMENT USED		
TYPE OF PROTECTIVE CASING AND HEIGHT OF STICKUP IN FEET (If applicable)	2	RISSET
PROTECTIVE CASING MATERIAL TYPE:		Stell
MEASURE PROTECTIVE CASING INSIDE DIAMETER (Inches):		
	Y	ES NO
LOCK PRESENT?		X
LOCK FUNCTIONAL?	ļ	X
DID YOU REPLACE THE LOCK?		X
IS THERE EVIDENCE THAT THE WELL IS DOUBLE CASED? (If yes, describe below)	-	y - ^
WELL MEASURING POINT VISIBLE?	L	
MEASURE WELL DEPTH FROM MEASURING POINT (Feet):		
MEASURE DEPTH TO WATER FROM MEASURING POINT (Fcet):	-	
MEASURE WELL DIAMETER (Inches):	-	_
WELL CASING MATERIAL:	77	(C)
PHYSICAL CONDITION OF VISIBLE WELL CASING:		3000
ATTACH ID MARKER (if well ID is confirmed) and IDENTIFY MARKER TYPE)0
PROXIMITY TO UNDERGROUND OR OVERHEAD UTILITIES		,0
DESCRIBE ACCESS TO WELL: (Include accessibility to truck mounted rig, natural obstructions, overhea	ad	
power lines, proximity to permanent structures, etc.); ADD SKETCH OF LOCATION ON BACK, IF NEC	CESSARY.	
accessible by foot - in small wooded area.		
DESCRIBE WELL SETTING (For example, located in a field, in a playground, on pavement, in a garden,	etc.)	
AND ASSESS THE TYPE OF RESTORATION REQUIRED.	01	
within small stand of trees along small access	1000	101
*4		21
DENTIFY ANY NEARBY POTENTIAL SOURCES OF CONTAMINATION, IF PRESENT		
(e.g. Gas station, salt pile, etc.):		
REMARKS:		
CINIAICO.		

SITE NAME:	Banks	Smaller
SILE IVANIE.	Dienser	STIGHTING

_SITE ID.: INSPECTOR: DATE/TIME:

10 26/14 MW-11

MONITORING WELL FIELD INSPECTION LOG

WEILID.: YES WELL VISIBLE? (If not, provide directions below) NYTM Y WELL COORDINATES? NYTM X_ PDOP Reading from Trimble Pathfinder:____ ___ Satelites:_ Trimble And/Or Magellan GPS Method (circle) YES NO WELL I.D. VISIBLE? WELL LOCATION MATCH SITE MAP? (if not, sketch actual location on back)..... WELL I.D. AS IT APPEARS ON PROTECTIVE CASING OR WELL: YES NO SURFACE SEAL PRESENT? SURFACE SEAL COMPETENT? (If cracked, heaved etc., describe below) PROTECTIVE CASING IN GOOD CONDITION? (If damaged, describe below) HEADSPACE READING (ppm) AND INSTRUMENT USED...... TYPE OF PROTECTIVE CASING AND HEIGHT OF STICKUP IN FEET (If applicable) PROTECTIVE CASING MATERIAL TYPE: MEASURE PROTECTIVE CASING INSIDE DIAMETER (Inches): NO DID YOU REPLACE THE LOCK? AND PLOUSE TWAT SIKE VISIT IS THERE EVIDENCE THAT THE WELL IS DOUBLE CASED? (If yes, describe below) WELL MEASURING POINT VISIBLE? MEASURE WELL DEPTH FROM MEASURING POINT (Feet): MEASURE DEPTH TO WATER FROM MEASURING POINT (Feet): MEASURE WELL DIAMETER (Inches): WELL CASING MATERIAL: PHYSICAL CONDITION OF VISIBLE WELL CASING; ATTACH ID MARKER (if well ID is confirmed) and IDENTIFY MARKER TYPE PROXIMITY TO UNDERGROUND OR OVERHEAD UTILITIES..... DESCRIBE ACCESS TO WELL: (Include accessibility to truck mounted rig, natural obstructions, overhead power lines, proximity to permanent structures, etc,); ADD SKETCH OF LOCATION ON BACK, IF NECESSARY. DOC- accessible DESCRIBE WELL SETTING (For example, located in a field, in a playground, on pavement, in a garden, etc.) AND ASSESS THE TYPE OF RESTORATION REQUIRED. within mooded ama. IDENTIFY ANY NEARBY POTENTIAL SOURCES OF CONTAMINATION, IF PRESENT (e.g. Gas station, salt pile, etc.): REMARKS:

REMARKS:

SITE ID.:

INSPECTOR:

MONITORING WELL FIELD INSPECTION LOG DATE/TIME: WEll ID .: YES WELL VISIBLE? (If not, provide directions below) WELL COORDINATES? NYTM X____NYTM Y__ PDOP Reading from Trimble Pathfinder: Satelites: GPS Method (circle) Trimble And/Or Magellan YES NO WELL I.D. VISIBLE? WELL LOCATION MATCH SITE MAP? (if not, sketch actual location on back)..... WELL I.D. AS IT APPEARS ON PROTECTIVE CASING OR WELL: YES NO SURFACE SEAL PRESENT? SURFACE SEAL COMPETENT? (If cracked, heaved etc., describe below) PROTECTIVE CASING IN GOOD CONDITION? (If damaged, describe below) HEADSPACE READING (ppm) AND INSTRUMENT USED...... TYPE OF PROTECTIVE CASING AND HEIGHT OF STICKUP IN FEET (If applicable) PROTECTIVE CASING MATERIAL TYPE: MEASURE PROTECTIVE CASING INSIDE DIAMETER (Inches): YES NO LOCK PRESENT? LOCK FUNCTIONAL? DID YOU REPLACE THE LOCK? IS THERE EVIDENCE THAT THE WELL IS DOUBLE CASED? (If yes, describe below) WELL MEASURING POINT VISIBLE? MEASURE WELL DEPTH FROM MEASURING POINT (Feet): MEASURE DEPTH TO WATER FROM MEASURING POINT (Feet): MEASURE WELL DIAMETER (Inches): WELL CASING MATERIAL; PHYSICAL CONDITION OF VISIBLE WELL CASING; ATTACH ID MARKER (if well ID is confirmed) and IDENTIFY MARKER TYPE PROXIMITY TO UNDERGROUND OR OVERHEAD UTILITIES..... DESCRIBE ACCESS TO WELL: (Include accessibility to truck mounted rig, natural obstructions, overhead power lines, proximity to permanent structures, etc.); ADD SKETCH OF LOCATION ON BACK, IF NECESSARY. accessible 160t DESCRIBE WELL SETTING (For example, located in a field, in a playground, on pavement, in a garden, etc.) AND ASSESS THE TYPE OF RESTORATION REQUIRED. eavily wooded area IDENTIFY ANY NEARBY POTENTIAL SOURCES OF CONTAMINATION, IF PRESENT (e.g. Gas station, salt pile, etc.):

SITE NAME: Beaver Smilting	SITE ID.: INSPECTO	ND. T	363
MONITORING WELL FIELD INSPECTION LOG	DATE/TIM		10/7/0
MONTORING WEEL FLEXIS MOTECTION LOG	WEILID.:		Mus
WELL VISIBLE? (If not, provide directions below)		YES	NO
WELL COORDINATES? NYTM XNYTM Y		X	-1
PDOP Reading from Trimble Pathfinder: Satelites:			
GPS Method (circle) Trimble And/Or Magellan			
Crop product (victo)	ſ	YES	NO
WELL I.D. VISIBLE?		X	
WELL LOCATION MATCH SITE MAP? (if not, sketch actual location on back)		1	
	174	-1	4
WELL I.D. AS IT APPEARS ON PROTECTIVE CASING OR WELL:	*		
WILD I.D. AS IT ALL DANS ON PROTECTIVE ORDING OR WEDD.	Ì	YES	NO
SURFACE SEAL PRESENT?			X
SURFACE SEAL COMPETENT? (If cracked, heaved etc., describe below)		_	Y
PROTECTIVE CASING IN GOOD CONDITION? (If damaged, describe below)	1		
,	-		*
HEADSPACE READING (ppm) AND INSTRUMENT USED			
TYPE OF PROTECTIVE CASING AND HEIGHT OF STICKUP IN FEET (If applicable)		211	riser
PROTECTIVE CASING MATERIAL TYPE:		Ste	e\
MEASURE PROTECTIVE CASING INSIDE DIAMETER (Inches):			· ·
	[YES	NO
LOCK PRESENT?		X	
LOCK FUNCTIONAL?			X
DID YOU REPLACE THE LOCK?	1		X
IS THERE EVIDENCE THAT THE WELL IS DOUBLE CASED? (If yes, describe below)	1		X
WELL MEASURING POINT VISIBLE?	Ĭ,	X	
MEASURE WELL DEPTH FROM MEASURING POINT (Feet):			
MEASURE DEPTH TO WATER FROM MEASURING POINT (Feet):			
MEASURE WELL DIAMETER (Inches):			
WELL CASING MATERIAL:		PVC	4
PHYSICAL CONDITION OF VISIBLE WELL CASING:		900	1
ATTACH ID MARKER (if well ID is confirmed) and IDENTIFY MARKER TYPE			
PROXIMITY TO UNDERGROUND OR OVERHEAD UTILITIES		NO	
DESCRIBE ACCESS TO WELL: (Include accessibility to truck mounted rig, natural obstructions, overhower lines, proximity to permanent structures, etc.); ADD SKETCH OF LOCATION ON BACK, IF NE	ead CESSARY.		

IDENTIFY ANY NEARBY POTENTIAL SOURCES OF CONTAMINATION, IF PRESENT

(e.g. Gas station, salt pile, etc.):



Photo 1 Facing North. West Side of Landfill Near Seep and Wetland Vegetation Present.



Photo 3 Drainage Ditch West of Landfill. Sampled June 2014.



Photo 2 Facing East. West Side of Landfill Seep.





Photo 4 Confluence of Drainage Ditch and Unnamed Tributary


AECOM Environment


Appendix B


Analytical Results for Metals Exceeding NYS AWQS or Guidance Values in Monitoring Well MW-2 Beaver Smelting Site, Fallsburg, New York
























- Notes:

 1. The New York State Ambient Water Quality Standards (NYS AWQS) and the New York State Guidance Values (NYS GVs) are represented by a red
- 2. NYS AWQSs and NYS GVs are from 6. NYCRR Part 703.5.
- 3. Only metals that exceeded in at least one of the sampling events in this well
- are plotted.


 4. Analytes not detected above the laboratory method detections limits are included in the plots as 0.

Analytical Results for Metals Exceeding NYS AWQS or Guidance Values in Monitoring Well MW-3 Beaver Smelting Site, Fallsburg, New York





- 1. The New York State Ambient Water Quality Standards (NYS AWQS) and the New York State Guidance Values (NYS GVs) are represented by a red dashed
- line.
 2. NYS AWQSs and NYS GVs are from 6. NYCRR Part 703.5.
 3. Only metals that exceeded in at least one of the sampling events in this well
- 4. Analytes not detected above the laboratory method detections limits are included in the plots as 0.


Analytical Results for Metals Exceeding NYS AWQS or Guidance Values in Monitoring Well MW-4 Beaver Smelting Site, Fallsburg, New York





Analytical Results for Metals Exceeding NYS AWQS or Guidance Values in Monitoring Well MW-5 Beaver Smelting Site, Fallsburg, New York




















- 1. The New York State Ambient Water Quality Standards (NYS AWQS) and the New York State Guidance Values (NYS GVs) are represented by a red dashed
- line.
 2. NYS AWQSs and NYS GVs are from 6. NYCRR Part 703.5.
- 3. Only metals that exceeded in at least one of the sampling events in this well are plotted.


 4. Analytes not detected above the laboratory method detections limits are included in the plots as 0.


Analytical Results for Metals Exceeding NYS AWQS or Guidance Values in Monitoring Well MW-6 Beaver Smelting Site, Fallsburg, New York






























- Notes:


 1. The New York State Ambient Water Quality Standards (NYS AWQS) and the New York State Guidance Values (NYS GVs) are represented by a red dashed line.
- 2. NYS AWQSs and NYS GVs are from 6. NYCRR Part 703.5.


 3. Only metals that exceeded in at least one of the sampling events in this well
- 4. Analytes not detected above the laboratory method detections limits are included in the plots as 0.


Analytical Results for Metals Exceeding NYS AWQS or Guidance Values in Monitoring Well MW-7 Beaver Smelting Site, Fallsburg, New York

















Notes:


- 1. The New York State Ambient Water Quality Standards (NYS AWQS) and the New York State Guidance Values (NYS GVs) are represented by a red dashed line.
- 2. NYS AWQSs and NYS GVs are from 6. NYCRR Part 703.5.
- 3. Only metals that exceeded in at least one of the sampling events in this well are plotted.
- 4. Analytes not detected above the laboratory method detections limits are included in the plots as 0.


Analytical Results for Metals Exceeding NYS AWQS or Guidance Values in Monitoring Well MW-9 Beaver Smelting Site, Fallsburg, New York













- 1. The New York State Ambient Water Quality Standards (NYS AWQS) and the New York State Guidance Values (NYS GVs) are represented by a red dashed
- line.
 2. NYS AWQSs and NYS GVs are from 6. NYCRR Part 703.5.
- Only metals that exceeded in at least one of the sampling events in this well are plotted.
 Analytes not detected above the laboratory method detections limits are included in the plots as 0.


Analytical Results for Metals Exceeding NYS AWQS or Guidance Values in Monitoring Well MW-10 Beaver Smelting Site, Fallsburg, New York





Analytical Results for Metals Exceeding NYS AWQS or Guidance Values in Monitoring Well MW-11 Beaver Smelting Site, Fallsburg, New York





Analytical Results for Metals Exceeding NYS AWQS or Guidance Values in Monitoring Well MW-12 Beaver Smelting Site, Fallsburg, New York











- Notes.


 1. The New York State Ambient Water Quality Standards (NYS AWQS) and the New York State Guidance Values (NYS GVs) are represented by a red dashed
- line.


 2. NYS AWQSs and NYS GVs are from 6. NYCRR Part 703.5.


 3. Only metals that exceeded in at least one of the sampling events in this well are plotted.


 4. Analytes not detected above the laboratory method detections limits are installed in the plotte or 0.


Analytical Results for Metals Exceeding NYS AWQS or Guidance Values in Monitoring Well MW-13 Beaver Smelting Site, Fallsburg, New York











Notes:

- The New York State Ambient Water Quality Standards (NYS AWQS) and the New York State Guidance Values (NYS GVs) are represented by a red dashed line.
- 2. NYS AWQSs and NYS GVs are from 6. NYCRR Part 703.5.
- 3. Only metals that exceeded in at least one of the sampling events in this
- well are plotted.

 4. Analytes not detected above the laboratory method detections limits are included in the plots as 0.

AECOM Environment

Appendix C



Enclosure 1 Institutional and Engineering Controls - Property Owner Survey



_	- Algore		Box 1	
	Site	No. 353005	DOX 1	
	Site	Name Beaver Smelting		
	City	Address: Beaver Lane Zip Code: 12788 /Town: Woodbourne inty: Sullivan Acreage: 2.0		
	Rep	porting Period: January 01, 2012 to December 31, 2014		
			YES	NO
	1.	Is the information above correct?	Ø	
		If NO, include handwritten above or on a separate sheet.		
	2.	Has some or all of the site property been sold, subdivided, merged, or undergone a tax map amendment during this Reporting Period?		×
	3.	Has there been any change of use at the site during this Reporting Period (see 6NYCRR 375-1.11(d))?		対
	4.	Have any federal, state, and/or local permits (e.g., building, discharge) been issued for or at the property during this Reporting Period?		×
		If you answered YES to questions 2, 3 or 4, include documentation with this form.		
	5.	Is the site currently undergoing development?		×
			Box 2	
			YES	NO
	6.	Is the current site use consistent with the use(s) listed below? Industrial	×	
	7.	Are all Institutional Controls (ICs) in place and functioning as designed?	M	
		Arthur M. Rosenshein 1 Docember Date	2014	**

SITE NO. 353005			Box 3
Description of Inst	titutional Controls		
Parcel	Owner	Institutional Control	
141-25.7	WOODBOURNE MINING	Monitoring Plan O&M Plan	
Description of Fra	nin agring Controls		Box 4
TANKS N	gineering Controls <u>Engineering Control</u>		
Parcel 141-25.7	Cover System		
"			
			Box 5
Pariodic	Review Report (PRR) Survey Stateme	nts	

Periodic Review Report (PRR) Survey Statements

For each Institutional or Engineering control listed in Boxes 3 and/or 4, by checking "YES" below I believe all of the following statements to be true:

- (a) the Institutional Control(s) and/or Engineering Control(s) employed at this site remain unchanged since the date that the Control was put in-place, or was last approved by the Department;
- (b) nothing has occurred that would impair the ability of such Control, to protect public health and the environment;
- (c) access to the site will continue to be provided to the Department, to evaluate the remedy, including access to evaluate the continued maintenance of this Control; and
- (d) if a Site Management Plan (SMP) exists, nothing has occurred that would constitute a violation or failure to comply with the SMP for this Control.

NO

Signature of Property Owner





Enclosure 1 Englneering Controls - Standby Consultant/Contractor Certification Form



	6:4	Site Details e No. 353005	Box 1	
	Site	e Name Beaver Smelting		
	City	e Address: Beaver Lane Zip Code: 12788 y/Town: Woodbourne unty: Sullivan e Acreage: 2.0	ú	
	Re	porting Period: January 01, 2012 to December 31, 2014		
				E:
		₩	YES	NO
	1.	Is the information above correct?	Ø	
		If NO, include handwritten above or on a separate sheet.		
ů.	2.	To your knowledge has some or all of the site property been sold, subdivided, merged, or undergone a tax map amendment during this Reporting Period?		ø
	3.	To your knowledge has there been any change of use at the site during this Reporting Period (see 6NYCRR 375-1.11(d))?		Ø
	4.	To your knowledge have any federal, state, and/or local permits (e.g., building, discharge) been issued for or at the property during this Reporting Period?		d
÷		If you answered YES to questions 2 thru 4, include documentation or evidence that documentation has been previously submitted with this certification form		
	5.	To your knowledge is the site currently undergoing development?		☐′
			Doy 2	V 1
		20	Box 2	
		(4 1) :=	YES	NO
	6.	Is the current site use consistent with the use(s) listed below?		
	7.	Are all ICs/ECs in place and functioning as designed?		
		THE ANSWER TO EITHER QUESTION 6 OR 7 IS NO, sign and date below and contact C PM regarding the development of a Corrective Measures Work Plan to address the		les.
	×		E	18
	Sig	nature of Standby Consultant/Contractor Date		

SITE NO. 353005 Box 3

Description of Institutional Controls

<u>Parcel</u>

14.-1-25.7

WOODBOURNE MINING

Institutional Control

Monitoring Plan O&M Plan

Box 4

Description of Engineering Controls

Engineering Control

<u>Parcel</u> 14.-1-25.7

Cover System

Periodic Review Report (PRR) Certification Statements

	a) the Period	ic Review I	report and	d all attachn	nents were	prepare	ed under the	e direction	of. a	nd
	reviewed by, to contractors for	he party m	raking the	certification	n, including					
	b) to the best are in accorda engineering p	ance with th	he require	ements of th	ne site rem	edial pro	gram, and	generally		
	engineering p	ractices, a	no me mi	ormation pr	esented is	accurat	e and comp	YE	S	NO
				¥2				abla	'	
or E	s site has an IC ngineering cont wing statements	rol listed in	or equival Boxes 3	ent as requ and/or 4, I o	ired in the certify by c	Decision hecking	n Documen "YES" belo	t), for eac w that all	h Inst	titutional e
le:	(a) the Institu								chanç	ged sinc
							antral to pr	otect pub	lic he:	alth and
	the environme		d that woւ	uld impair th	ne ability of	such C	ontroi, to pi	J. J	110 (110	
		ent; as occurred	d that wou	ıld constitut	e a failure		ii.	Site Mana	geme	ent Plan,
	the environme (c) nothing ha	ent; as occurred	d that wou	ıld constitut	e a failure		ii.		geme	
) (the environme (c) nothing ha	ent; as occurred	d that wou	ıld constitut	e a failure		ii.	Site Mana	geme	ent Plan,
	the environme (c) nothing ha	ent; as occurred o Site Mar QUESTION	d that wou nagement	uld constitut Plan exists sign and da	e a failure	to comp	ly with the s	Site Mana YE ⊠	ngeme	ent Plan, NO □
	the environme (c) nothing ha equivalent if n	ent; as occurred o Site Mar QUESTION	d that wou nagement	uld constitut Plan exists sign and da	e a failure	to comp	ly with the s	Site Mana YE ⊠	ngeme	ent Plan, NO □
DEC P	the environme (c) nothing ha equivalent if n	ent; as occurred o Site Man QUESTION e developm	d that wou nagement 2 IS NO, s nent of a	uld constitut Plan exists sign and da	e a failure	to comp	ly with the s	Site Mana YE ⊠	ngeme	ent Plan, NO □
DEC P	the environment (c) nothing had equivalent if nothing had equivalent if nothing the ANSWER TO Comment of the management of the second of the s	ent; as occurred o Site Man QUESTION e developm	d that wou nagement 2 IS NO, s nent of a	uld constitut Plan exists sign and da	e a failure	to comp	ly with the s act the an to addre	Site Mana YE ⊠	ngeme	ent Plan, NO □
DEC P	the environment (c) nothing had equivalent if nothing had equivalent if nothing the ANSWER TO Comment of the management of the second of the s	ent; as occurred o Site Man QUESTION e developm	d that wou nagement 2 IS NO, s nent of a	uld constitut Plan exists sign and da	e a failure	to comp	ly with the s act the an to addre	Site Mana YE ⊠	ngeme	ent Plan, NO □
DEC P	the environment (c) nothing had equivalent if nothing had equivalent if nothing the ANSWER TO Comment of the management of the second of the s	ent; as occurred o Site Man QUESTION e developm	d that wou nagement 2 IS NO, s nent of a	uld constitut Plan exists sign and da	e a failure	to comp	ly with the s act the an to addre	Site Mana YE ⊠	ngeme	ent Plan, NO □

IC/EC CERTIFICATIONS

Box 6

Qualified Environmental Professional Signature

I certify that all information in Boxes 2 through 5 are true. I understand that a false statement made herein is punishable as a Class "A" misdemeanor, pursuant to Section 210.45 of the Penal Law.

1 Scott A. UNDERHILL print name	at AECOM TECHNICAL SERVICES NORTHEAST, INC
	40 BRITISH AMERICAN BLUD
	(printipuliness address)
am certifying as a Qualified Environme	ntal Professional AND
Signature of Qualified Environmental F	Professional Constant Date
Signature of Qualified Environmental F	POFESSIONAL DATE