## Division of Environmental Remediation

## Inactive Hazardous Waste Site Operations and Maintenance Review Report

Form Date 96.10.01 Number: 5-58-008 Site Name: Kingsbury Landfill Class: 2 X State Superfund □ Federal Superfund □ Municipal □ Responsible Party **O&M** Information: O&M Start: 10/89 Annual Cost: \$ End: ☐ Estimated Interim Remedial Measures/Operable Units in O&M Phase: ☐ Tank Removal □ Drum Removal □ Soil Removal X Cap/Cover X Containment Structure X Fence/Security ☐ Groundwater Recovery/Treatment X Leachate Collection/Treatment □ Vapor Extraction/Treatment ☐ Air Sparging/Stripper System □ Treatment/Filtration Plant/System □ Potable Water X Other: Annual Monitoring Institutional Controls: □ Deed Restriction X Discharge Permit ☐ Department of Health Sampling Other: Leachate Collection and Treatment System last operated in 1991. **O&M Review Information:** Reports: 08/97 Air sampling of landfill off-gas treatment system by Clough, Harbour and Assoc. (CHA) under WA. 10/97 Groundwater Sampling and Elevation Monitoring by CHA Inspection: 08/22/01. Groundwater Elevations now measured using electronic level recorders. Data downloaded monthly. Average Groundwater elevation on 08/22/01 was 202.10'. Sampling: Annual sampling. Last done on 06/13/01 by central office staff. Other: Mowing of site performed by the Town of Kingsbury (per 10/30/85 Agreement & Determination with NYSDEC) Power and telephone turned off to the treatment facility on 07/28/97. Conclusions: Remedy Effective? ☐ Yes X No: It is agreed that the design is flawed. Large differences in water elevations occur across the slurry wall both up gradient and down gradient. OD Compliance? ☐ Yes ☐ No: NA Consent Order Compliance? ☐ Yes ☐ No: NA Other: Repaired: Eroded areas on southeast slope of the landfill (downgradient) by Div. of Operations in Sept. 1997. Recommendations: Action level to de-water the landfill has been exceeded. Develop a Work Assignment to operate existing treatment system to de-water landfill. ROD/Consent Order Modifications? □ No □ Yes (per above) Reclassify the Site X No □ Yes → Class: Comments: Failure to de-water the landfill could result in a failure of both the slurry wall and cap. This failure will result in a significant environmental impact to nearby canal and surrounding groundwater systems. The treatment system was upgraded in 1995 in anticipation future operation. Project Manager: Reviewer: (518) 402-9640 atthew D. Dunham **BHSC** (518) 402-9640 Gerald J. Rider, Jr. **BHSC** Region or Bureau Name Telephone Name Region or Bureau Telephone