

ADDITIONS/CHANGES TO REGISTRY OF  
INACTIVE HAZARDOUS WASTE DISPOSAL SITES  
PLEASE EXPEDITE

Site Name Johnny Cake Road Farm DEC ID Number 622017  
Site Address Johnny Cake Road, Danube County Herkimer

- Add New Site: (Potential hazardous waste site, Site Inspection Summary Report, EPA Preliminary Assessment Form and Registry Form must be completed and attached)
- Modify Registry data (detail below)
- Reclassify from class        to class       . (justify below)
- Delist (justify below)

[Class 2]  
*New Site*  
*1990-91*

Detail/Justification

The site consists of a house and garage located on approximately 2 acres along the south side of Johnny Cake Road in the Towns of Stark, Danube, and Little Falls in Herkimer County. In 1987 the U.S. Marshall's office seized the site due to the illegal cocaine refining laboratory which was operated in the house and garage building. Volatile organic solvents were stored in the garage and spent solvents were dumped in the driveway. Toluene, Trichloroethene, and Tetrachloroethene (in the groundwater and surface water) are in excess of New York State Ambient Water Quality Standards and NYSDOH groundwater/drinking water standards and/or guidance values.

- Confirmation of hazardous waste disposal; witnessed by U.S. Marshall's Office reps.
- Contravention of applicable g.w. standards has been confirmed thru sampling analysis

Prepared by Peter S. Ouderkirk Date: July 1, 1990

Approvals: TM Koch 7-26-90 \*\*\*

Reg. Haz. Waste Eng. Darrell Sweredowski Date: 7-9-90

R. Tramontano NYSDOH [Signature] Date: 9/11/90

R. Dana/DEE Richard H. Dana Date: 8/22/90

W. Demick/J. Swartwout/  
D. Curtis Thomas A. Ramon Date: 8/9/90

R. Marino [Signature] Date: 9/18/90

E. Barcomb [Signature] Date: 9/19/90

\*\*\*  
See attached sheet.



NEW YORK STATE DEPARTMENTS OF ENVIRONMENTAL CONSERVATION AND HEALTH  
INACTIVE HAZARDOUS WASTE DISPOSAL SITE PRIORITY RANKING WORKSHEET

SITE # 622017 SITE NAME Johnny Cake Rd. farm

- ° **Priority I** - Top priority sites; supersede all others. Priority I can be assigned if any of the following criteria is met:
- a) A sole source or primary aquifer, or a public or private water supply is being contaminated or threatened, or
- b) Human exposure to contaminants has been identified which represents a Significant health risk as determined by DOH, or
- c) There is a bioaccumulation of site contaminants in flora or fauna which results in a health advisory, or
- d) Site contaminants are at levels that are acutely toxic to fish or wildlife or have caused documented fish or wildlife mortality, or
- e) An expedient response could measurably reduce the threat to health or the environment, reduce the scope of a corrective action, or reduce potential remedial costs.
- ° **Priority II** - Important sites. Priority II can be assigned if any of the following criteria is met:
- a) A Class AA or a Class A surface water body or a principal aquifer is being contaminated or threatened; however, no existing water supply has been contaminated, or
- b) There is a bioaccumulation of site contaminants in flora or fauna which results in advisory or actionable levels but below levels necessitating a health advisory, or
- c) Site contaminants are at levels chronically toxic to fish/wildlife, or
- d) Endangered, threatened or rare species, significant habitats, designated coastal zone areas or regulated wetlands are being impacted by releases from the site, or
- e) The site is identified by the International Joint Commission (IJC) as a component in a Remedial Action Plan (RAP), or
- f) The site is within a State Economic Development Zone or is targeted for local government supported development and the developer has expressed a willingness to enter into a consent order with DEC to finance investigation and remediation.
- ° **Priority III** - General Site Category. Priority III will be assigned unless one or more of the site prioritization criteria, specified above, apply to a site. When resources become available, after remedial needs for Priority I and II sites have been accommodated, remediation of sites under this category can be considered.

COMMENT Immediate removal of the contaminated septic system would significantly reduce contaminant migration.

Filled out by (Name): Yvonne D. Whitfield Date: 9/26/90



ANALYTICAL DATA AVAILABLE:

Air-X Surface Water-X Groundwater-X Soil-X Sediment-

CONTRAVENTION OF STANDARDS:

Groundwater-X Drinking Water-X Surface Water-X Air-

LEGAL ACTION:

TYPE...: State- Federal-  
STATUS: Negotiation in Progress- Order Signed-

REMEDIAL ACTION:

Proposed-X Under design- In Progress- Completed-  
NATURE OF ACTION: Soil Removal in contaminated areas- IRM

GEOTECHNICAL INFORMATION:

SOIL TYPE: Silt, sand and gravel overlying gray glacial till  
GROUNDWATER DEPTH: Approximately 5-10 feet


ASSESSMENT OF ENVIRONMENTAL PROBLEMS:

Soils, groundwater and surface water have been contaminated with spent solvents at this site.

ASSESSMENT OF HEALTH PROBLEMS:

Neighboring homeowners utilize groundwater sources as their domestic water. Sampling results have not revealed any private water impacts. Continued monitoring well sampling is recommended. The area is sparsely populated, and there is no evidence of trespass.





LEGEND  
 ● TEST BORING  
 □ MONITOR WELL

NOTE:  
 THIS MAP IS INTENDED TO PROVIDE SCHEMATIC INFORMATION ONLY AND DOES NOT REPRESENT AN ACTUAL FIELD SURVEY



## Preliminary Assessment

*Johnny Cake Road farm  
Johnny Cake Rd.  
Town of Danube  
Herkimer County*

*[Site ID No 62201-]*

Not possible - probably 75° W

		POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT PART 1 - SITE INFORMATION AND ASSESSMENT			I. IDENTIFICATION 01 STATE 02 SITE NUMBER XXXXX	
<b>II. SITE NAME AND LOCATION</b> 01 SITE NAME (Legal, Common, or descriptive name of site): Johnny Cake Road Farm						
02 STREET ROUTE NO. OR SPECIFIC LOCATION IDENTIFIER: Johnny Cake Road				03 CITY: Danube		04 STATE: NY
05 ZIP CODE:		06 COUNTY: Herkimer		07 COUNTY CODE: 22	08 CONG DIST: —	
09 COORDINATES: LATITUDE 42° 58' 00"		LONGITUDE 72° 51' 30"		10 DIRECTIONS TO SITE (Starting from nearest public road):		
<b>III. RESPONSIBLE PARTIES</b> 01 OWNER (if known): U. S. Federal Marshall						
02 STREET (Business, mailing, residential): 213 Federal Building				03 CITY: Utica		04 STATE: NY
05 ZIP CODE: 13501		06 TELEPHONE NUMBER: 615 732-2123				
07 OPERATOR (if known and different from owner):						
08 STREET (Business, mailing, residential):				09 CITY:		10 STATE:
11 ZIP CODE:		12 TELEPHONE NUMBER:				
13 TYPE OF OWNERSHIP (Check one): <input type="checkbox"/> A. PRIVATE <input checked="" type="checkbox"/> B. FEDERAL U.S. Federal Marshall <input type="checkbox"/> C. STATE <input type="checkbox"/> D. COUNTY <input type="checkbox"/> E. MUNICIPAL <input type="checkbox"/> F. OTHER _____ <input type="checkbox"/> G. UNKNOWN						
IV. CHARACTERIZATION OF POTENTIAL HAZARD 01 ON SITE INSPECTION BY (Check all that apply): <input checked="" type="checkbox"/> YES DATE 6/6/90 <input type="checkbox"/> A. EPA <input type="checkbox"/> B. EPA CONTRACTOR <input checked="" type="checkbox"/> C. STATE <input type="checkbox"/> D. OTHER CONTRACTOR <input type="checkbox"/> NO <input type="checkbox"/> E. LOCAL HEALTH OFFICIAL <input type="checkbox"/> F. OTHER _____ CONTRACTOR NAME(S): C. T. Male Associates						
02 SITE STATUS (Check one): <input type="checkbox"/> A. ACTIVE <input checked="" type="checkbox"/> B. INACTIVE <input type="checkbox"/> C. UNKNOWN		03 YEARS OF OPERATION BEGINNING YEAR: 1985 ENDING YEAR: 1987 <input type="checkbox"/> UNKNOWN				
04 DESCRIPTION OF SUBSTANCES POSSIBLY PRESENT KNOWN OR ALLEGED: Drums of solvents containing Toluene, Trichloroethene, Tetra-chloroethene, Methylene Chloride, Acetone, Trans 1,2-Dichloroethene, and 1,1-Dichloroethene.						
05 DESCRIPTION OF POTENTIAL HAZARD TO ENVIRONMENT AND OR POPULATION: Toluene, Trichloroethene and Tetrachloroethene are in the site soils and groundwater in excess of NYS groundwater and drinking water standards.						
<b>V. PRIORITY ASSESSMENT</b> 01 PRIORITY FOR INSPECTION (Check one, if high or medium is checked, complete Part 2 - Waste Information and Part 3 - Description of Hazardous Conditions and Incidents): <input type="checkbox"/> A. HIGH (inspection required promptly) <input type="checkbox"/> B. MEDIUM (inspection required) <input type="checkbox"/> C. LOW (inspection on time available basis) <input checked="" type="checkbox"/> D. NONE (no further action needed, complete current disposition form)						
<b>VI. INFORMATION AVAILABLE FROM</b> 01 CONTACT: Kim Baines						
02 OF (Agency/Organization): C.T. Male Associates				03 TELEPHONE NUMBER: 618) 785-0976		
04 PERSON RESPONSIBLE FOR ASSESSMENT: Peter Ouderkirk		05 AGENCY: NYSDEC	06 ORGANIZATION: DHWR	07 TELEPHONE NUMBER: 315, 785-2513	08 DATE: 7, 1, 90 <small>MONTH DAY YEAR</small>	





POTENTIAL HAZARDOUS WASTE SITE  
PRELIMINARY ASSESSMENT  
PART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS

I. IDENTIFICATION	
01 STATE	02 SITE NUMBER
XXXX	

II. HAZARDOUS CONDITIONS AND INCIDENTS

01 <input type="checkbox"/> A GROUNDWATER CONTAMINATION	02 <input type="checkbox"/> OBSERVED DATE <u>4/25/90</u>	<input type="checkbox"/> POTENTIAL	<input type="checkbox"/> ALLEGED
03 POPULATION POTENTIALLY AFFECTED _____	04 NARRATIVE DESCRIPTION		
Groundwater contaminated above NYS groundwater standards for Toluene, Tetrachloroethene, and Trichloroethene.			

01 <input checked="" type="checkbox"/> B SURFACE WATER CONTAMINATION	02 <input type="checkbox"/> OBSERVED DATE <u>5/30/90</u>	<input type="checkbox"/> POTENTIAL	<input type="checkbox"/> ALLEGED
03 POPULATION POTENTIALLY AFFECTED _____	04 NARRATIVE DESCRIPTION		
Surface water on site in drainage streams contaminated above NYS Ambient Water Quality Standards for Toluene, Trichloroethene and Tetrachloroethene.			

01 <input type="checkbox"/> C CONTAMINATION OF AIR	02 <input type="checkbox"/> OBSERVED DATE <u>4/19/90</u>	<input type="checkbox"/> POTENTIAL	<input type="checkbox"/> ALLEGED
03 POPULATION POTENTIALLY AFFECTED _____	04 NARRATIVE DESCRIPTION		
Volatile organic observed during drilling to levels of 300 ppm volatile organics and gaseous compounds in air.			

01 <input type="checkbox"/> D FIRE EXPLOSIVE CONDITIONS	02 <input type="checkbox"/> OBSERVED DATE _____	<input type="checkbox"/> POTENTIAL	<input type="checkbox"/> ALLEGED
03 POPULATION POTENTIALLY AFFECTED _____	04 NARRATIVE DESCRIPTION		

01 <input checked="" type="checkbox"/> E DIRECT CONTACT	02 <input type="checkbox"/> OBSERVED DATE _____	<input type="checkbox"/> POTENTIAL	<input type="checkbox"/> ALLEGED
03 POPULATION POTENTIALLY AFFECTED _____	04 NARRATIVE DESCRIPTION		
Soil heavily saturated with solvents. Septic tank and swimming pool contaminated with volatile organics.			

01 <input checked="" type="checkbox"/> F CONTAMINATION OF SOIL	02 <input type="checkbox"/> OBSERVED DATE <u>4/19/90</u>	<input type="checkbox"/> POTENTIAL	<input type="checkbox"/> ALLEGED
03 AREA POTENTIALLY AFFECTED _____	04 NARRATIVE DESCRIPTION		
Soil contaminated with Toluene, Trichloroethene, Tetrachloroethene, Methylene Chloride and Acetone.			

01 <input type="checkbox"/> G DRINKING WATER CONTAMINATION	02 <input type="checkbox"/> OBSERVED DATE _____	<input checked="" type="checkbox"/> POTENTIAL	<input type="checkbox"/> ALLEGED
03 POPULATION POTENTIALLY AFFECTED _____	04 NARRATIVE DESCRIPTION		

01 <input type="checkbox"/> H WORKER EXPOSURE/INJURY	02 <input type="checkbox"/> OBSERVED DATE _____	<input type="checkbox"/> POTENTIAL	<input type="checkbox"/> ALLEGED
03 WORKERS POTENTIALLY AFFECTED: _____	04 NARRATIVE DESCRIPTION		

01 <input type="checkbox"/> I POPULATION EXPOSURE/INJURY	02 <input type="checkbox"/> OBSERVED DATE _____	<input checked="" type="checkbox"/> POTENTIAL	<input type="checkbox"/> ALLEGED
03 POPULATION POTENTIALLY AFFECTED _____	04 NARRATIVE DESCRIPTION		



POTENTIAL HAZARDOUS WASTE SITE  
PRELIMINARY ASSESSMENT  
PART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS

I. IDENTIFICATION

01 STATE 02 SITE NUMBER  
XXXX

II. HAZARDOUS CONDITIONS AND INCIDENTS

01  J DAMAGE TO FLORA  
04 NARRATIVE DESCRIPTION  
02  OBSERVED (DATE \_\_\_\_\_)  POTENTIAL  ALLEGED

01  K DAMAGE TO FAUNA  
04 NARRATIVE DESCRIPTION (include name(s) of species)  
02  OBSERVED (DATE \_\_\_\_\_)  POTENTIAL  ALLEGED

01  L CONTAMINATION OF FOOD CHAIN  
04 NARRATIVE DESCRIPTION  
02  OBSERVED (DATE \_\_\_\_\_)  POTENTIAL  ALLEGED

01  M UNSTABLE CONTAINMENT OF WASTES  
Soups, runoff, standing liquids, leaking drums  
03 POPULATION POTENTIALLY AFFECTED \_\_\_\_\_ 04 NARRATIVE DESCRIPTION  
02  OBSERVED (DATE \_\_\_\_\_)  POTENTIAL  ALLEGED

01  N DAMAGE TO OFFSITE PROPERTY  
04 NARRATIVE DESCRIPTION  
02  OBSERVED (DATE \_\_\_\_\_)  POTENTIAL  ALLEGED

01  O CONTAMINATION OF SEWERS, STORM DRAINS, WWTPs  
04 NARRATIVE DESCRIPTION  
02  OBSERVED (DATE 4/19/90)  POTENTIAL  ALLEGED

On site septic tank contaminated.

01  P ILLEGAL/UNAUTHORIZED DUMPING  
04 NARRATIVE DESCRIPTION  
02  OBSERVED (DATE \_\_\_\_\_)  POTENTIAL  ALLEGED

Workers were seen dumping liquids in driveway during cocaine manufacturing.

05 DESCRIPTION OF ANY OTHER KNOWN, POTENTIAL OR ALLEGED HAZARDS


III. TOTAL POPULATION POTENTIALLY AFFECTED: \_\_\_\_\_

IV. COMMENTS

V. SOURCES OF INFORMATION (Cite specific references, e.g., State Dept. Sample Analysis Reports)

file

New York State Department of Environmental Conservation  
50 Wolf Road, Albany, New York 12233



Thomas C. Jorling  
Commissioner

TO: Darrell Sweredoski, RHWRE, Region 6  
RE: Cocaine Lab, Town of Stark, Herkimer County  
DATE: \_\_\_\_\_

This is in response to your May 14, 1990 memorandum. You asked whether your office "should pursue this matter in the course of a normal investigation of an inactive hazardous waste site". The answer is yes.

In response to discussion between staff of the BHSC (Mr. Maddineni) and Peter Ouderkirk of Region 6, Mr. Ouderkirk has mailed to the Bureau all available information concerning the site. It is our understanding that pertinent facts regarding the site are as follows:

- o The site was seized by the Federal Marshall's Office in 1987 at which time it was being used as a dairy farm and an illegal cocaine refining laboratory.
- o Organic solvents were reportedly used and/or stored at the site.
- o C.T. Male Associates, P.C. has been hired by the Federal Marshall's Office to perform a subsurface investigation.
- o Mr. Ouderkirk will meet with the Federal Marshall for further information regarding the documentation of hazardous waste and any other pertinent information.
- o The surface soils and the groundwater are contaminated with solvents as follows:

<u>Surface soils</u>	<u>PPM</u>
Toluene	43.2
Tetrachlorethene	215.0

<u>Groundwater</u>	<u>PPM</u>
Toluene	15.2
Tetrachlorethene	16.3

According to the EPA 2070-12 form; toluene is 25.4 & tetrachlor is @ 56.0.

NYS Standard/Guidance Values PPB  
50  
0.70

If the site is a listable candidate upon completion of the investigation, please initiate the appropriate paperwork. Should you have any questions, please call Srikanth Maddineni at (518) 457-0638.

cc: D. Markell  
G. Firth  
TR:d1  
bcc: M. O'Toole (2)  
C. Goddard  
E. Barcomb  
T. Reamon  
file

*Michael J. O'Toole, Jr.*  
Michael J. O'Toole, Jr.  
Director  
Division of Hazardous Waste Remediation

C.T. MALE ASSOCIATES, P.C.


JOHNYCAKE ROAD FARM SITE  
ENVIRONMENTAL SUBSURFACE INVESTIGATION  
TOWN OF DANUBE  
HERKIMER COUNTY, NEW YORK  
FEDERAL SEIZURE NO. 87-CV-980

JUNE 25, 1990

RECEIVED

JUN 29 1990

NYS Dept. Environmental Conservation  
REGION 6  
REGIONAL ENGINEER



Prepared for:

UNITED STATES FEDERAL MARSHAL  
Northern District of New York  
213 Federal Building  
10 Broad Street  
Utica, New York 13501

Prepared by:

C.T. MALE ASSOCIATES, P.C.  
50 Century Hill Drive  
P.O. Box 727  
Latham, New York 12110  
(518) 785-0976  
CTMA Project No.: 90.2851

UNAUTHORIZED ALTERATION OR  
ADDITION TO THIS DOCUMENT IS  
A VIOLATION OF SECTION 7209  
SUBDIVISION 2 OF THE NEW YORK  
STATE EDUCATION LAW.

COPYRIGHT 1990  
C.T. MALE ASSOCIATES, P.C.

JOHNYCAKE ROAD FARM SITE  
ENVIRONMENTAL SUBSURFACE INVESTIGATION  
TOWN OF DANUBE  
HERKIMER COUNTY, NEW YORK

TABLE OF CONTENTS

<u>SECTION</u>	<u>PAGE</u>
1.0 INTRODUCTION AND SITE DESCRIPTION	1
2.0 SOIL INVESTIGATION	2
3.0 GROUNDWATER INVESTIGATION	5
4.0 SITE SEPTIC SYSTEM INVESTIGATION	7
5.0 SITE HOUSE INVESTIGATION	8
6.0 CONCLUSIONS AND RECOMMENDATIONS	8

APPENDICES

- A. FIGURES, DRAWINGS AND MAPS
- B. TEST BORING LOGS AND MONITOR WELL INSTALLATION DIAGRAMS
- C. MICROTIP® FIELD TESTING DATA
- D. LABORATORY TESTING DATA FOR SOIL SAMPLES
- E. LABORATORY TESTING DATA FOR GROUNDWATER SAMPLES
- F. MISCELLANEOUS LABORATORY SAMPLE DATA
- G. PROPOSED MONITOR WELL INSTALLATION INFORMATION

JOHNYCAKE ROAD FARM SITE  
ENVIRONMENTAL SUBSURFACE INVESTIGATION  
TOWN OF DANUBE  
HERKIMER COUNTY, NEW YORK

1.0 INTRODUCTION AND SITE DESCRIPTION

On April 16, 1990, C.T. Male Associates P.C. was retained by the United States Federal Marshal to perform a subsurface investigation at a former dairy farm property in the Town of Danube, Herkimer County New York. Deputy Marshal Robert Money indicated that the property had been seized by the Federal Government in 1987, because an illegal cocaine refining laboratory was in operation in the house and garage buildings at the site.

The site consists of approximately 377 acres of farmland along the north and south sides of Johnycake Road in the Towns of Stark, Danube and Little Falls, Herkimer County, New York. A two story farmhouse, a two bay garage building and a dairy barn are all located on the west side of the property along both sides of Johnycake Road. A drawing which shows the approximate layout of these buildings in relation to Johnycake Road has been prepared for schematic purposes and included in Appendix A of this report. The section of the property where the subject house and garage buildings are located is depicted on a USGS Topographic Quadrangle map, immediately north of the Danube/Stark Town Line in the Town of Danube. This investigation is assumed to have taken place in the Town of Danube. From this point forth in the report, "the site " will refer to this area immediately around the site buildings on the north and south sides of Johnycake road. A section of the Topographic Map showing the subject site has been included in Appendix A as a site location map, Figure 1.

According to the Marshal's office, volatile organic solvents were stored in drums inside the eastern bay of the garage building. These solvents were then used in the house cellar in the cocaine refining process and then may have been disposed of in a variety of ways. In at least one incidence, Federal Agents reportedly observed these liquids being dumped on the site driveway. Other means of disposal may have included dumping on the unpaved garage floor, dumping into the site septic tank through the house drains or sinks and runoff from the house basement floor to the driveway surface. An additional source of contamination may also include leakage or spillage of the drummed materials in the garage drum storage area. All of these source areas were identified to C.T. Male by the U.S. Marshals office.

The site slopes moderately downward from the potable water supply well just south of the two bay garage, to the north, across Johnycake Road and further downward to a tributary stream of the Ohisa Creek. This stream is approximately 400 to 500 feet north of the site building (the suspect contaminant source area) and topographically downgradient. The topographic relief in this distance, as it is shown on the USGS quadrangle map, is approximately 60 to 70 feet of elevation. The area in general around the subject site is very hilly, rolling topography with a well defined drainage valley north of the site and a steep upwardly sloping hill to the south of the site. Farms and residential dwellings are scattered sparsely through the surrounding area. A single farmhouse is located immediately east of the subject site on the south side of Johnycake Road.

## 2.0 SOIL INVESTIGATION

On April 19 and 20, 1989, C.T. Male Associates performed an investigation of the quality of soils, both surficial and subsurface, in areas suspected of being contaminated. The soil sampling program was divided into two different operations. Samples were collected with hand sampling tools in the soil floor of the garage building where drums of solvents had reportedly been stored, and samples were collected at vertical depth intervals in six test borings advanced with a drilling rig throughout the site property.

### 2.1 Garage Floor Investigation

On April 19, 1989, six soil samples were collected in the dirt floor of the garage, in the east garage bay. The west garage bay has a concrete floor and reportedly was not used to store the drummed chemicals. The samples were collected at 0-1 foot in depth with a hand shovel. At the one foot depth, impassable consolidated materials were encountered in all of the sample locations. The impassable surfaces encountered appeared to be large rocks and in some sample holes may have been buried concrete. This condition limited sampling to the 1 foot depth. Water infiltrated all of the sample holes from the surface down in the back (southern) section of the garage at 6 inches or less in the holes near the front (northern) section of the garage. In all cases, the soil samples were wet or damp.

Soil samples were collected in duplicate and one sample was screened with field instrumentation as they were collected. The samples were placed in clean glass jars and headspace analysis testing was performed in each sample jar. The headspace analysis measurement was performed with a Photovac Microtip® model photoionization detection meter, which reads total ionizable volatile organic compounds with an ionization potential of 10.6 ev. or less, in parts per million (ppm). This instrument was used throughout the investigation as an indicator of gross volatile organic contamination. No contamination was detected in any of the garage floor samples screened during the field sampling: Positive readings on this instrument identify areas of immediate concern, but often will not identify low levels of contamination.

All samples collected from the garage floor were refrigerated at the site for transport and were subsequently submitted to CTM Analytical Laboratories Ltd. of Latham, New York, for analysis.

All samples were analyzed in the testing laboratory by EPA Method 8240 for Priority Pollutant Volatile Organic Compounds. Copies of the laboratory sample results have been included as Appendix E of this report. According to the laboratory data, trace concentrations of volatile organic solvent contamination were detected in samples S-1 and S-3. The contaminants detected were methylene chloride in sample S-1, and trichloroethene, and tetrachloroethene in sample S-3. No contaminants included in the EPA 8240 Priority Pollutant Scan were detected in any of the other four samples. Based on readings obtained with the field instrumentation during the sampling, and the confirmatory laboratory results, it appears that very little contamination is present in the first foot of soil, in the garage bay floor. Because the sampling was limited to the 0-1 foot level due to the presence of impassable rocks and possibly buried concrete, any additional exploration in this area would have to be performed with a backhoe or some other type of powered equipment.

## 2.2 Soil Boring Investigation

On April 19 and 20, 1990, soil borings were advanced into the groundwater table in six locations surrounding the site buildings. A site plan map showing the test boring locations has been included in appendix A. The borings were advanced by Empire Soils Investigations, Inc., Latham, New York with the use of a truck mounted "auger-type" drilling rig using 4-1/4 inch hollow stemmed augers. Samples were collected with 2 inch diameter stainless steel split spoon samplers, through the augers, continuously to the bottom of each boring. Samples were transferred into clean glass jars and

## C.T. MALE ASSOCIATES, P.C.

refrigerated for shipment to the testing laboratory. Replicate samples were used for field screening. The borings were located in areas which appeared to be either topographically or hydraulically downgradient of the suspected contaminant source areas or directly in the areas.

Samples were collected in duplicate and each was screened with a Photovac Microtip® volatile organic vapor meter for the presence of volatile organic contaminants. The duplicate samples were refrigerated for transport to the testing laboratory. Test boring logs and logs of the Microtip® field testing results have been attached in Appendices B and C respectively. As noted in these logs, indications of contamination were detected in all of the test borings at widely varying concentrations. Test borings B-1, B-2 and B-3 exhibited the highest levels of contamination.

In general, the soils observed in all of the test borings appeared to be non-sorted sand, silt and gravel over glacial till, which increased in density as the boring was advanced in depth. A weathered bedrock surface may have been encountered at the bottom of boring B-2, between 13 and 14 feet below grade.

The duplicate sample exhibiting the highest volatile compound contamination by head space analysis (i.e. field screening) and the sample from the bottom of each boring were submitted to the testing laboratory for analysis. Samples were selected to represent the highest potential concentration of volatile organic compounds in each boring and the quality of the soil at the bottom of each boring. These selections were based on field Microtip® readings. Laboratory results for the test boring samples have been included in Appendix D. According to the laboratory results, volatile organic solvent contamination was present in all of the submitted soil samples. The contaminants identified include; Trichloroethene, Tetrachloroethene, Toluene, Acetone, and Methylene Chloride. The levels of the contaminants ranged widely throughout the site and appeared to vary according to both boring location and sample depth. The soil boring sample results have been summarized below in Table 1.

TABLE 1  
SUMMARY OF LABORATORY ANALYSIS RESULTS  
FOR  
TEST BORING SOIL SAMPLES  
COLLECTED APRIL 19 AND 20, 1990

<u>SAMPLE ID</u>	<u>DEPTH</u>	<u>TOL</u>	<u>TCE</u>	<u>PCE</u>	<u>MC</u>	<u>ACT</u>
B-1	2-4	ND	ND	3750	5440	ND
B-1	6-8	ND	ND	ND	ND	13
B-2	6-8	25	8	71	ND	17
B-2	12-14	ND	ND	41	ND	ND
B-3	4-6	ND	ND	294	ND	ND
B-3	12-14	ND	ND	ND	9	19
B-4	2-4	ND	ND	44	ND	ND
B-4	12-14	ND	ND	ND	9	ND
B-5	8-10	183	ND	174	8	74
B-6	4-6	ND	24	166	13	ND

SAMPLE ID IS NOTED AS B-1 = TEST BORING NUMBER 1  
 DEPTH = FEET BELOW THE EXISTING GRADE  
 TOL = TOLUENE CONCENTRATION IN MCG/KG OR PARTS PER BILLION (PPB)  
 TCE = TRICHLOROETHENE CONC. IN PPB  
 PCE = TETRACHLOROETHENE (PERCHLOROETHENE) CONC. IN PPB  
 MC = METHYLENE CHLORIDE CONC. IN PPB  
 ACT = ACETONE IN PPB

### 3.0 GROUNDWATER INVESTIGATION

On April 19 and 20, 1990, five of the six test borings performed at the subject site (described previously in section 2.2 of this report) were converted to groundwater monitor wells. Monitor wells are identified by converting the test boring number to the same monitor well number (ie. test boring B-1 = monitor well MW-1). No well was installed in boring B-5. The wells were constructed by installing 2 inch diameter Schedule 40 PVC slotted well screen and solid riser material through the hollow stemmed drilling augers. Ten feet of 0.010 inch slotted screen was set in the bottom of each well so that the top of each screened interval was approximately 1-2 feet above the observed groundwater table. The annular space of each well boring was packed to above the screened interval with clean silica sand, and then sealed with a two foot vertical bentonite seal to prevent surface

## C.T. MALE ASSOCIATES, P.C.

water infiltration. The wells were finished at the surface with locking steel enclosures which were cemented in place to protect the well installation. Installation diagrams for each of the wells have been included in Appendix B.

A map showing the locations of these wells in relation to the site buildings and Johnycake Road has been included as Figure 2 in Appendix A. The horizontal locations of the wells shown are approximate as they were located in the field with a tape measure. A formal topographic survey was not performed as a function of this phase of the investigation. The vertical well elevations were surveyed relative to a common benchmark, which was assumed to be 100.00 feet. This survey was performed only to determine the groundwater flow direction and establish a groundwater contour map representing conditions on the sampling date. The groundwater contour map is included as Figure 3 in Appendix A and indicates that the general groundwater flow is to the north in this area of the site.

The wells were sampled on April 25, 1990, by CTM Analytical Laboratories LTD. Each well was developed prior to sampling. Discrete samples were collected, refrigerated and delivered to the testing laboratory for analysis. A water sample of the site potable supply well/spring was collected at the same time by sampling the overflow at the wellhead. This well consists of a shallow hole dug in the side of the hill topographically upgradient (to the south) of the site buildings. All samples were submitted to the CTM Analytical Laboratories, LTD in Latham, New York, for analysis.

The samples were analyzed by EPA Method 624 for Priority Pollutant Volatile Organic Compounds. Laboratory results have been included in Appendix E of this report. No contaminants included in the testing parameters were detected in the sample for the potable water supply well. All of the monitor well samples were contaminated with volatile organic solvents. Contaminants detected in these wells were Toluene, Tetrachloroethene, Trichloroethene, Methylene Chloride, and Acetone. Trace concentrations of Trans 1,2-dichloroethene and 1,1-dichloroethene were detected only in monitor well MW-4. Table 2 below summarizes the laboratory sample data for the groundwater samples.

The concentrations of Toluene, Trichloroethene, and Tetrachloroethene reported all exceed the New York State, Department of Environmental Conservation "Ambient Water Quality Standards And Guidance Values" (6 NYCRR Part 203.5, TOGS1.1.1) and NYSDOH (10 NYCRR Part 5 or Part 170) groundwater/drinking water standards and/or guidance values. These values are: Toluene = 10 Micrograms/Liter (ppb) (Standard); Trichloroethene = 10 PPB (Standard); Tetrachloroethene = 0.7 PPB (Guidance Value) 5 PPB (DOH Standard).

TABLE 2  
LABORATORY ANALYSIS DATA  
FOR  
GROUNDWATER SAMPLES  
COLLECTED APRIL 25, 1990

<u>SAMPLE ID</u>	<u>TOL.</u>	<u>TCE</u>	<u>PCE</u>	<u>T12</u>	<u>11D</u>
HOUSE WELL	ND	ND	ND	ND	ND
MW-1	1120	91	971	ND	ND
MW-2	25400	ND	56000	ND	ND
MW-3	1730	ND	4350	ND	ND
MW-4	ND	1280	835	51	25
MW-6	15200	ND	16300	ND	ND

SAMPLE ID IS NOTED AS MW-1 = MONITOR WELL NUMBER 1  
TOL = TOLUENE CONCENTRATION IN MCG/KG OR PARTS PER BILLION (PPB)  
TCE = TRICHLOROETHENE CONC. IN PPB  
PCE = TETRACHLOROETHENE (PERCHLOROETHENE) CONC. IN PPB  
T12 = TRANS 1,2-DICHLOROETHENE CONC. IN PPB  
11D = 1,1-DICHLOROETHENE CONC. IN PPB

#### 4.0 SITE SEPTIC SYSTEM INVESTIGATION

On April 19, 1990, C.T. Male located the house septic tank, approximately 10 feet off the southeast corner of the house. The tank appears to be a 750 - 1000 gallon steel tank and was located with a metal detector. The top of the tank was encountered at approximately two feet below ground level. The steel cover was badly rusted and was easily punctured with a hand shovel.

On April 25, 1990, a field technician from the CTM Analytical Lab LTD sampled liquids from inside the septic tank by inserting a sampling device through the opening in the top of the tank. The sample was refrigerated and transported to the testing laboratory for analysis. The sample was analyzed by EPA Method 624 for Priority Pollutant Volatile Organic Compounds. A copy of the laboratory results for this sample has been included in Appendix F. The laboratory data indicates that high concentrations of Toluene and Tetrachloroethene were found in this sample. Approximately

## C.T. MALE ASSOCIATES, P.C.

one foot of water and 0.5 feet of sludge were present in the tank at the time of sampling.

### 5.0 SITE HOUSE INVESTIGATION

On April 19, 1990, the air quality in the house was screened for total volatile organic vapors with a Photovac Microtip® volatile organic vapor meter. The instrument has a detection limit of 0.5 parts per million and would therefore only detect solvent concentrations of 500 parts per billion or greater. No solvent contamination was detected in the air in any living spaces in the house or in the house cellar with this instrument.

As a second phase of C.T. Male's house investigation, a sample of charcoal-like residue was removed from the concrete basement floor and was submitted to the testing laboratory for analysis (EPA Method 624). The laboratory analysis results for this sample have been included in Appendix F of this report. The laboratory results indicate that the charcoal residue contained high concentrations of Toluene and Tetrachloroethene (Toluene = 43,200 ppb, Tetrachloroethene = 215,000 ppb). This charcoal substance was only observed in the basement of the house.

### 6.0 CONCLUSIONS AND RECOMMENDATIONS

The first phase of investigation has been completed at this site. As noted in the introduction of this report, the purpose of this investigation was to identify a potential for organic solvent contamination which may have been introduced to the subject site as a result of chemicals used at an illegal cocaine refining laboratory, which previously operated on-site. Key potential source areas of contamination were investigated to determine if contaminants had been released. As a result of this investigation it has been determined that significant levels of organic solvent contaminants including hazardous wastes have been released to site soils and have subsequently contaminated groundwater in the area of investigations.

#### CONCLUSIONS

Based on field observations and laboratory analysis results from samples collected at the subject site, C.T. Male can offer the following information and assumptions about site conditions:

C.T. MALE ASSOCIATES, P.C.

1. Widespread areas of organic solvent contaminated soil are present on the subject site. These areas appear to coincide with areas where solvents are believed to have been stored, used or disposed of. The soil contamination appears to be more concentrated in the shallow soil, but was also detected in soils from the deepest sampling depths (as deep or deeper than 12-14 feet below grade). Most of the contaminants identified in site soils are "listed hazardous wastes" as defined in Section 40 Part 261 of the Code of Federal Regulations, and 6 NYCRR Part 371.
2. Groundwater in the area of investigation is contaminated with volatile organic solvents. The solvent contamination was not observed in the house potable water supply well. Because this well is located hydraulically upgradient of the suspect contaminant source areas, contamination was not anticipated. The levels of Trichloroethene, Tetrachloroethene, and Toluene contamination observed in all of the monitor wells exceed the State of New York DEC "Ambient Water Quality Standards And Guidance Values" (6 NYCRR Part 203.5, TOGS1.1.1) and NYSDOH (10 NYCRR Part 5 or Part 170) groundwater/drinking water standards and/or guidance values. The contaminant levels observed in many cases are orders of magnitude greater than the standards and guidance values.
3. Solvent contaminated wastes were observed in sediments on the concrete floor of the house basement, and in liquids in the septic tank for the house. The solvent levels observed in the septic tank liquid are significantly high and pose a threat to surrounding soils and groundwater if they are released. Contaminated sediments in the basement floor pose a similar threat.
4. Two of six samples collected from the garage floor showed very low levels of solvent contamination. Although these samples were not grossly contaminated, they represent only the 0-1 foot depth and therefore may be an indicator of deeper, more significant contamination.
5. A downgradient monitor well north of Johnycake Road is contaminated with solvents similar to those found in the house and garage areas. This may suggest that either the solvent contamination plume has travelled across the road, or an additional unidentified contaminant source or source area may be present north of the road.

RECOMMENDATIONS

It is evident that site groundwater and soils have been contravened by hazardous waste solvent contamination as a result of previous site use. Based on the findings to date, C.T. Male has the following recommendations for continued site investigation and remediation.

1. In order to establish the potential threat to public and/or livestock safety, samples should be collected at water supply wells neighboring the contaminated site area, and in surface water bodies adjacent to and topographically downgradient of the contaminated subject site area. The samples should be submitted to a New York State Department of Environmental Conservation and Department of Health certified testing laboratory, and analyzed for EPA Method 624 parameters (priority pollutant volatile organics).
2. The septic tank for the house is contaminated with high levels of waste toluene and waste tetrachloroethene solvents. This tank may be an active source of solvent leachate contamination and must be emptied as soon as possible. The tank contains both liquid and sludge waste. The tank contents should be transferred into a vacuum truck or drummed, and then transferred under manifest by a 6 NYCRR Part 364 permitted/certified hazardous waste hauler, to an approved/permitted hazardous waste treatment and disposal facility. The tank should be properly decontaminated and removed from the ground. Wastewater from the cleaning should be contained and tested for contamination. If the cleaning wastewater is contaminated, it should be handled and disposed of as a hazardous waste. All site work for this operation must be performed by contractors with updated OSHA approved hazardous waste site safety training required by 29 CFR Part 1910.120. The Excavation should then be backfilled with soil from the adjacent contaminated area to avoid additional soil contamination. The septic system should not be replaced until site soil and groundwater remediation has been completed.
3. All sediments on the concrete floor in the cellar of the house should be removed and drummed. The concrete floor should then be steam cleaned to remove any additional contamination. All cleaning water should be contained, sampled, and tested to determine if it is contaminated with solvent waste. All wastes determined to be hazardous as defined by 6 NYCRR Part 371 and 40 CFR Part 261, must be removed and transported under manifest by a

## C.T. MALE ASSOCIATES, P.C.

6 NYCRR Part 364 permitted/certified hazardous waste hauler, to an approved hazardous waste treatment and disposal facility.

4. Deeper test borings or test pits and a shallow groundwater monitor well should be installed in the dirt floor garage bay area to further investigate the magnitude of contamination in this area.
5. Four monitor wells should be installed in the uppermost bedrock aquifer, in the four most contaminated areas. These locations are identified on Figure 4, the proposed monitor well installation diagram in Appendix G. These wells should be installed to determine if the solvents have contravened the underlying bedrock aquifer. The wells must be installed in such a way that water from the overburden (shallow water) aquifer is not allowed to infiltrate into the bedrock aquifer either during the drilling, or after the well installation.

The method of installation suggested would be to grout an oversized boring into the competent bedrock using a rotary drilling system, and then core through the grout seal using conventional casing and NX coring rods or roller cone bits. Air rotary coring would be preferred over water, so that waste water would not have to be collected for later disposal. The well should be screened in the bedrock starting below the competent rock. A sand pack should be placed around the annular space of the screened interval, and an additional bentonite seal should be installed above the sand pack. A diagram of this proposed installation is included in Appendix G. All future well installation work must be performed by drillers with the necessary OSHA hazardous waste site safety training, as it has been to date.

The ambient air quality must be monitored with a photoionization detector (PID) volatile organic vapor meter (or equivalent) during drilling to ensure that solvent concentrations do not exceed threshold safety limits. Adequate respiratory protection and clothing, as defined by a site Health and Safety plan, must be used by the drillers.

Six additional shallow (overburden) monitor wells should be installed in areas expected to be downgradient and "crossgradient" of the identified contaminated area. These wells will be necessary to define the horizontal limits of contamination and to quantify data for future remediation purposes.

Proposed well locations are shown on Figure 4 in Appendix G. Additional wells installed on adjacent properties to the east of the site would be helpful.

C.T. MALE ASSOCIATES, P.C.

Locations of such wells would be subject to approval by the adjacent property owners.


6. Upon completion of all necessary additional investigations, C.T. Male will recommend a method or methods of site groundwater and soil remediation. These methods will be dependant upon the outcome of the investigation, but may consist of some soil excavation in highly contaminated areas, and treatment and/or disposal of the contaminated soils, and on-site groundwater pumping and treatment.
7. As a result of the findings in this investigation, C.T. Male recommends that all future work at this site be performed in conjunction with and subject to the approval of the New York State Department of Environmental Protection. A formal Health and Safety program should be prepared for the site, and all future work should be performed within the guidelines of such a program, by contractors and/or persons with suitable O.S.H.A. "Hazardous Waste Site Safety Training" (40 hours minimum with 8 hour yearly updated training sessions).

The information presented in this report is limited to the investigations conducted and described, and is not necessarily all inclusive of conditions present at the subject site.

If you have any questions regarding this report, please contact this office at (518) 785-0976.


Respectfully submitted,

C.T. MALE ASSOCIATES, P.C.



Kim L. Baines  
Environmental Scientist

Report reviewed and approved by:



David W. Roecker, P.E.

Department Head, Environmental Engineering

KLB/DWR/cmc