

Inactive Hazardous Waste Site Operations and Maintenance Review Report

Form Date 96.10.01

Site Name: Primoshield Plating		Class: 4	Number: 633027
O&M Funding Source: <input checked="" type="checkbox"/> State Superfund <input type="checkbox"/> Federal Superfund <input type="checkbox"/> Municipal <input type="checkbox"/> Responsible Party			
O&M Information: O&M Start: 12/98 End: Annual Cost: \$ <input type="checkbox"/> Estimated			
Interim Remedial Measures/Operable Units in O&M Phase: <div style="display: flex; flex-wrap: wrap;"> <div style="width: 33%;"><input type="checkbox"/> Drum Removal</div> <div style="width: 33%;"><input checked="" type="checkbox"/> Soil Removal</div> <div style="width: 33%;"><input type="checkbox"/> Tank Removal</div> <div style="width: 33%;"><input type="checkbox"/> Cap/Cover</div> <div style="width: 33%;"><input type="checkbox"/> Containment Structure</div> <div style="width: 33%;"><input checked="" type="checkbox"/> Fence/Security</div> <div style="width: 33%;"><input checked="" type="checkbox"/> Groundwater Recovery/Treatment</div> <div style="width: 33%;"><input type="checkbox"/> Leachate Collection/Treatment</div> <div style="width: 33%;"><input type="checkbox"/> Vapor Extraction/Treatment</div> <div style="width: 33%;"><input type="checkbox"/> Air Sparging/Stripper System</div> <div style="width: 33%;"><input type="checkbox"/> Treatment/Filtration Plant/System</div> <div style="width: 33%;"><input type="checkbox"/> Potable Water Supply/System</div> <div style="width: 33%;"><input checked="" type="checkbox"/> Other: Hazardous Material Removal</div> </div>			
Institutional Controls: <input type="checkbox"/> Deed Restriction <input type="checkbox"/> Discharge Permit <input type="checkbox"/> Department of Health Sampling <input type="checkbox"/> Other:			
O&M Review Information: Reports: <u>Semi-annual Groundwater Permit Reports: 5/31/99, 11/30/99, and 5/31/00 (11/30/00 not done, pump down.)</u> <u>Quarterly Groundwater Monitoring Reports: quarters ending 4/30/99, 7/30/99, 10/30/99, 2/7/00 and 11/30/00</u> Inspection: <u>4/13/99, 7/27/99, 10/28/99, 2/7/00 and 11/30/00</u> Sampling: <u>4/13/99, 7/27/99, 10/28/99, 2/7/00 and 11/30/00</u> Other:			
Conclusions: Remedy Effective? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No: _____ ROD Compliance? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No: _____ Consent Order Compliance? <input type="checkbox"/> Yes <input type="checkbox"/> No: <u>there is no consent order</u> Other:			
Recommendations: <u>The groundwater sampling regimen should be reviewed and possibly changed to 5/4 sampling.</u>			
ROD/Consent Order Modifications? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes (per above) Reclassify the Site? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes → Class:			
Comments: <u>The sump pump will be replaced Spring 2001. At that time, the carbon drums will be disconnected with the ability to reconnect them in the future if possible. Then the POTW sampling can resume. There is also a note in the files that says that once the drums are removed that we should consider disconnecting the phone because the drums failing is the biggest cause of high level alarms, but does the sump pump failure also cause high level alarms? When we consider shutting down the pump, we will need to consider possible impacts that the pumping has had on lowering gw levels, i.e., will basements get flooded when pump is off.</u> <u>Problem severe since system is down</u>			
Project Manager: <u>Susan M. Lasdin</u> Signature		Reviewer: <u>Gerald J. Rider, Jr.</u> Signature	
Susan M. Lasdin, P.E. BHSC 518-457-0927 Name Region or Bureau Telephone		Gerald J. Rider, Jr., P.E., BHSC 518-457-0927 Name Region or Bureau Telephone	