



## MEMORANDUM

**TO:** Andrew English, Acting Director, Bureau of Technical Support  
**FROM:** James Quinn, Chief, Section B *JQ*  
**THRU:** P. David Smith, Director, Remedial Bureau B  
**SUBJECT:** Proposed Reclassification of Site No. 7-04-008, Endicott Village,  
Well Field & Landfill, Broome County  
**DATE:**

A Remedial Action (RA) consistent with the September 1992 Record of Decision (ROD) and implemented at the Endicott Landfill site by the municipality (Village of Endicott) was completed in October 1996. This RA has been completed in accordance with the approved plans and specifications, therefore, we recommend the site to be reclassified from a Class 2 to a Class 4. The 1992 ROD called for:

- Capping the majority of the surface of Landfill No. 1 with a low permeability soil barrier cap, with a minimum of 12 inches of protective barrier fill with a permeability of  $10^{-5}$  cm/sec or less in a ridge and swale configuration, with ridges having slopes of 4 percent and synthetic liner in the swales;
- Capping with bituminous (asphalt) caps the 6-acre parcel of Landfill No. 1 where the Village of Endicott has a permitted yard waste composting facility and the 8-acre Controlled Activity Area (CAA) of the Tri-Cities Airport regulated by the Federal Aviation Administration;
- Performance of an explosive gas investigation and installation of a gas venting system, (as necessary); and
- Collecting, treating, and disposing the leachate seep into a publicly owned treatment works if installation of the cap didn't reduce leachate generation to the extent that the seep no longer exists.

- Recommending that institutional controls be established in the form of deed restrictions on future uses of landfill #1;
- Fencing or other acceptable access restrictions to ensure protection of the Landfill #1 cap;
- Performing long term operation and maintenance of the Landfill #1 cap, gas venting, and leachate systems (if necessary) to provide for inspections and repairs;
- Performing long term air and water quality monitoring;
- Evaluating Site conditions at least once every five years to determine if a modification to the selected remedy is necessary.

In accordance with the ROD, the following remedial work was performed at the site:

- The majority of the surface of Landfill No. 1 was capped with a low permeability of soil barrier cap, with a minimum of 12 inches of protective barrier fill with a permeability of 10-5 cm/sec or less in a ridge and swale configuration, with ridges having slopes of 4 percent and synthetic liner in the swales;
- capping with bituminous (asphalt) the 6-acre parcel of Landfill No. 1 where the Village of Endicott has a permitted yard waste composting facility and the 8-acre Controlled Activity Area (CAA) of the Tri-Cities Airport regulated by the Federal Aviation Administration;
- An explosive gas investigation was performed and a passive system with one vent per acre was installed;
- Ongoing collection, treatment, and disposal of the leachate from the on site seep into a publicly owned treatment works is not required because, after capping of the landfill, the seep stopped flowing.
- Fencing to restrict access was installed to protect the landfill cap.
- Long- term operation and maintenance of the landfill cap and gas venting to provide for inspections and repairs.
- Groundwater monitoring data, attached, supports the reclassification.

The approved O&M Plan, which includes monitoring of the air and water quality, is being implemented by the Town of Endicott. Annual Reports are sent to Ms. Sally Dewes for Department review. EPA provides 5-year evaluations.

Supporting documentation including the Remedial Action Report prepared by the consultant, a copy of the September 1992 Record of Decision and Site Investigation Information form are attached as justification for the reclassification.

If you have any questions, please call Jim Drumm at 402-9768.

Attachment

cc: J. Burke, Region 7  
N. Walz, NYSDOH


bcc: P. D. Smith  
J. Quinn  
J. Drumm  
Dayfile

C:\MyFiles\English.Endic22405.wpd(lm)

**SITE INVESTIGATION INFORMATION**

1. SITE NAME Endicott Village Well field & Landfill		2. SITE NUMBER 7-04-008	3. TOWN/CITY/VILLAGE Endicott	4. COUNTY Broome
5. REGION 7		6. PROGRAM TYPE BCP <input type="checkbox"/> ERP <input type="checkbox"/> SPILL <input type="checkbox"/> SUPERFUND <input checked="" type="checkbox"/> If Superfund: Current <u>2</u> Proposed <u>4</u> Modification <u>X</u>		
7. LOCATION OF SITE (Attach U.S.G.S. Topographic Map showing site location)				
a. Quadrangle Endicott		b. Site Latitude <u>42° 5' 2"</u> Site Longitude <u>78° 5' 29"</u>		
c. Tax Map Number(s) 2-N2-02		d. Site Street Address Airport Road		
8. BRIEFLY DESCRIBE THE SITE (Attach site map showing disposal/sampling locations)				
<p>The Endicott Well Field Superfund Site (the "Site") is located on South Grippen Street at the western end of the Village of Endicott, New York. The Site consists of the ranney well, which is a municipal drinking water supply well, and its zone of influence on area ground water. The boundaries of this area have been generally delineated by Main Street to the north, the eastern boundary of the En-Joie Golf Course to the east, the Susquehanna River to the south, and the Tri-Cities Airport and Airport Road to the west. The Site is composed primarily of flat to gently rolling open land associated with the En-Joie Golf Course, facilities of the Village of Endicott Sewage Treatment Plant ("STP"), and the Endicott Landfill ("Landfill #1"). A portion of Landfill #1 adjacent to the Tri-Cities Airport extends into an approximately 8-acre area designated by the Federal Aviation Administration ("FAA") as the Controlled Activity Area ("CAA"), which includes the Runway Object Free Area ("ROFA"). A 6-acre parcel on Landfill #1 near the entrance to the STP is currently permitted for use by the Village of Endicott to compost yard waste; approximately 2 acres of the composting area are paved. There are two inactive landfills (Landfill #2 and Landfill #3) and a few industrial tracts north of the Site. Private homes are not located within the Site.</p> <p>The Susquehanna River flows to the west along the southern boundary of the Site. The southerly flowing Nanticoke Creek is a tributary to the Susquehanna River and generally bisects the site. Dead Creek, an intermittent stream, originally flowed across Landfill #1 into the Susquehanna River. In the early 1970's, Dead Creek was rerouted by the Village of Endicott to flow into Nanticoke Creek and the abandoned portion of the creek bed was filled in. Several man-made ponds on the En-Joie Golf Course are kept filled by water treated and discharged from the existing purge well, golf course irrigation, and precipitation. Excess water is ultimately discharged into Nanticoke Creek under a New York State Pollutant Discharge Elimination System ("SPDES") permit, which requires monthly sampling and analysis of water from the existing purge well, the pond discharge, and three monitoring wells.</p>				
a. Area <u>70</u> acres      b. Completed: ( ) Env. Property Assessment ( ) Site Characterization ( ) SI ( ) ESI ( ) IRM ( ) RI (x) Construction ( ) OM&M ( ) Spill Response      ( ) Other <u>EPA ID number NYD980780746</u>				
9. CONTAMINANTS DISPOSED (Hazardous Waste, Petroleum, Other. Includes EPA Hazardous Waste Numbers)				
Vinyl Chloride		Chloroethane		Trans-1,2 Dichloroethylene
1,1 Dichloroethane		Xylene		Trichloroethylene
				Chlorobenzene
				Heavy Metal Sludge
10. ANALYTICAL DATA AVAILABLE				
a. ( ) Air (X) Groundwater ( ) Surface Water ( ) Sediment ( ) Soil ( ) Waste ( ) Leachate ( ) EPTox ( ) TCLP				
b. Contravention of Standards or Guidance Values				
chloroethane 2.9 ppm      1,2 dichloroethene 2.7 ppm      Vinyl chloride 130 ppb				
11. CONCLUSION				
This is operable unit ("OU") is OU #2, the third and final OU planned for the Site. EPA issued RODs for OU #1 and OU#3 in September 1987 and March 1991, respectively. The ROD for OU#1 addressed ground water contamination at the ranney well public water supply system, which was the immediate threat to human health posed by the Site, by requiring the installation of an air stripper on the ranney well and continued extraction and treatment of contaminated ground water using the existing purge well on the En-Joie Golf Course. The Rod for OU#3 provided additional ground water control and treatment by requiring the use of a supplemental purge well. This OU#2 ROD addresses the source of ground water contamination, identified as the Endicott Landfill ("Landfill #1" or the "Landfill"), through landfill capping, gas venting, and control and treatment of the leachate seep. Long term management by the town is maintaining these systems.				
The major components of the constructed remedy include the following: - capping the majority of the surface of Landfill #1 with a low permeability soil barrier cap, with a variance of 6NYCRR Part 360 requirements, to allow for a minimum of 12 inches of protective barrier fill with a permeability of 10 <sup>-9</sup> cm/sec or less; in a ridge and swale configuration, with ridges having slopes of 4 percent and synthetic liner in the swales; - capping with bituminous (asphalt) caps the 6-acre parcel of landfill #1 where the Village of Endicott has a permitted yard waste composting facility and the 8-acre Controlled Activity area (CAA) of the Tri-Cities Airport regulated by the Federal Aviation Administration; - a passive gas vent system with one vent per acre; - fencing to ensure protection of the Landfill #1 cap; - long-term operation and maintenance of the Landfill #1 cap, gas venting, and leachate systems to provide for inspections and repairs; - long-term air and water quality monitoring; and - evaluating site conditions at least once every five years to determine if a modification to the selected remedy is necessary.				
a. Institutional Controls (IC) Required? ( ) Y (x) N      b. If yes, identify      c. Are these ICs in place and verified? ( ) Y ( ) N				
12. SITE IMPACT DATA				
a. Nearest Surface Water: Distance <u>0</u> ft.		Direction <u>East</u>		Class <u>A</u>
b. Groundwater: Depth <u>10</u> ft.		Flow Direction <u>East</u>		( ) Sole Source ( ) Primary (x) Other High-Yield Aquifer
c. Water Supply: Distance <u>200</u> ft.		Direction <u>NW</u>		Active (X) Yes ( ) No
d. Nearest Building: Distance <u>100</u> ft.		Direction <u>NE</u>		Use <u>sewage treatment plant</u>
e. Documented fish or wildlife mortality?		( ) Y (X) N		h. Exposed hazardous waste? ( ) Y (X) N
f. Impact on special status fish or wildlife resource?		( ) Y (x) N		i. Site Priority Ranking Sheet ----- Impact Score _____
g. Controlled Site Access?		( ) Y (x) N		j. Significant Threat? ( ) Y (X) N
		k. EPA ID# _____		HRS Score _____
13. SITE OWNER'S NAME Village of Endicott		14. ADDRESS Village of Endicott, Municipal Building, Endicott, NY 13760		15. TELEPHONE NUMBER (607) 757-2423
16. PREPARER Jim Drumm, Environmental Engineer 1		17. APPROVED P. David Smith, Director, Remedial Bureau B		
Signature _____ Date <u>4/6/05</u>		Signature _____ Date _____		
Name, Title, Organization		Name, Title, Organization		

**SITE INVESTIGATION INFORMATION**

1. SITE NAME Endicott Village Well field & Landfill		2. SITE NUMBER 7-04-008		3. TOWN/CITY/VILLAGE Endicott		4. COUNTY Broome	
5. REGION 7		6. PROGRAM TYPE BCP <input type="checkbox"/> ERP <input type="checkbox"/> SPILL <input type="checkbox"/> SUPERFUND <input checked="" type="checkbox"/> If Superfund: Current <u>2</u> Proposed <u>4</u> Modification <u>X</u>					
7. LOCATION OF SITE (Attach U.S.G.S. Topographic Map showing site location)							
a. Quadrangle Endicott		b. Site Latitude <u>42° 5' 2"</u>		Site Longitude <u>78° 5' 28"</u>			
c. Tax Map Number(s) 2-N2-02		d. Site Street Address Airport Road					
8. BRIEFLY DESCRIBE THE SITE (Attach site map showing disposal/sampling locations)							
<p>The Endicott Well Field Superfund Site (the "Site") is located on South Grippen Street at the western end of the Village of Endicott, New York. The Site consists of the ranney well, which is a municipal drinking water supply well, and its zone of influence on area ground water. The boundaries of this area have been generally delineated by Main Street to the north, the eastern boundary of the En-Joie Golf Course to the east, the Susquehanna River to the south, and the Tri-Cities Airport and Airport Road to the west. The Site is composed primarily of flat to gently rolling open land associated with the En-Joie Golf Course, facilities of the Village of Endicott Sewage Treatment Plant ("STP"), and the Endicott Landfill ("Landfill #1"). A portion of Landfill #1 adjacent to the Tri-Cities Airport extends into an approximately 8-acre area designated by the Federal Aviation Administration ("FAA") as the Controlled Activity Area ("CAA"), which includes the Runway Object Free Area ("ROFA"). A 6-acre parcel on Landfill #1 near the entrance to the STP is currently permitted for use by the Village of Endicott to compost yard waste; approximately 2 acres of the composting area are paved. There are two inactive landfills (Landfill #2 and Landfill #3) and a few industrial tracts north of the Site. Private homes are not located within the Site.</p> <p>The Susquehanna River flows to the west along the southern boundary of the Site. The southerly flowing Nanticoke Creek is a tributary to the Susquehanna River and generally bisects the site. Dead Creek, an intermittent stream, originally flowed across Landfill #1 into the Susquehanna River. In the early 1970's, Dead Creek was rerouted by the Village of Endicott to flow into Nanticoke Creek and the abandoned portion of the creek bed was filled in. Several man-made ponds on the En-Joie Golf Course are kept filled by water treated and discharged from the existing purge well, golf course irrigation, and precipitation. Excess water is ultimately discharged into Nanticoke Creek under a New York State Pollutant Discharge Elimination System ("SPDES") permit, which requires monthly sampling and analysis of water from the existing purge well, the pond discharge, and three monitoring wells.</p>							
a. Area <u>70</u> acres		b. Completed: ( ) Env. Property Assessment ( ) Site Characterization ( ) SI ( ) ESI ( ) IRM ( ) RI (x) Construction ( ) OM&M ( ) Spill Response ( ) Other <u>EPA ID number NYD980780746</u>					
9. CONTAMINANTS DISPOSED (Hazardous Waste, Petroleum, Other. Includes EPA Hazardous Waste Numbers)							
Vinyl Chloride		Chloroethane		Trans-1,2 Dichloroethylene		Chlorobenzene	
1,1 Dichloroethane		Xylene		Trichloroethylene		Heavy Metal Sludge	
10. ANALYTICAL DATA AVAILABLE							
a. ( ) Air (X) Groundwater ( ) Surface Water ( ) Sediment ( ) Soil ( ) Waste ( ) Leachate ( ) EPTox ( ) TCLP							
b. Contravention of Standards or Guidance Values							
chloroethane 2.9 ppm		1,2 dichloroethene 2.7 ppm		Vinyl chloride 130 ppb			
11. CONCLUSION							
<p>This is operable unit ("OU") is OU #2, the third and final OU planned for the Site. EPA issued RODs for OU #1 and OU#3 in September 1987 and March 1991, respectively. The ROD for OU#1 addressed ground water contamination at the ranney well public water supply system, which was the immediate threat to human health posed by the Site, by requiring the installation of an air stripper on the ranney well and continued extraction and treatment of contaminated ground water using the existing purge well on the En-Joie Golf Course. The Rod for OU#3 provided additional ground water control and treatment by requiring the use of a supplemental purge well. This OU#2 ROD addresses the source of ground water contamination, identified as the Endicott Landfill ("Landfill #1" or the "Landfill"), through landfill capping, gas venting, and control and treatment of the leachate seep. Long term management by the town is maintaining these systems.</p> <p>The major components of the constructed remedy include the following:</p> <ul style="list-style-type: none"> <li>- capping the majority of the surface of Landfill #1 with a low permeability soil barrier cap, with a variance of 6NYCRR Part 360 requirements, to allow for a minimum of 12 inches of protective barrier fill with a permeability of 10<sup>-9</sup> cm/sec or less; in a ridge and swale configuration, with ridges having slopes of 4 percent and synthetic liner in the swales;</li> <li>- capping with bituminous (asphalt) caps the 6-acre parcel of landfill #1 where the Village of Endicott has a permitted yard waste composting facility and the 8-acre Controlled Activity area (CAA) of the Tri-Cities Airport regulated by the Federal Aviation Administration;</li> <li>- a passive gas vent system with one vent per acre;</li> <li>- fencing to ensure protection of the Landfill #1 cap;</li> <li>- long-term operation and maintenance of the Landfill #1 cap, gas venting, and leachate systems to provide for inspections and repairs;</li> <li>- long-term air and water quality monitoring; and</li> <li>- evaluating site conditions at least once every five years to determine if a modification to the selected remedy is necessary.</li> </ul>							
a. Institutional Controls (IC) Required? ( ) Y (x) N		b. If yes, identify		c. Are these ICs in place and verified? ( ) Y ( ) N			
12. SITE IMPACT DATA							
a. Nearest Surface Water: Distance <u>0</u> ft.		Direction <u>East</u>		Class <u>A</u>			
b. Groundwater: Depth <u>10</u> ft.		Flow Direction <u>East</u>		( ) Sole Source ( ) Primary (x) Other High-Yield Aquifer			
c. Water Supply: Distance <u>200</u> ft.		Direction <u>NW</u>		Active (X) Yes ( ) No			
d. Nearest Building: Distance <u>100</u> ft.		Direction <u>NE</u>		Use <u>sewage treatment plant</u>			
e. Documented fish or wildlife mortality?		( ) Y (x) N		h. Exposed hazardous waste?		( ) Y (x) N	
f. Impact on special status fish or wildlife resource?		( ) Y (x) N		i. Site Priority Ranking Sheet -----Impact Score		-----	
g. Controlled Site Access?		( ) Y (x) N		j. Significant Threat?		( ) Y (x) N	
				k. EPA ID#		HRS Score	
13. SITE OWNER'S NAME Village of Endicott		14. ADDRESS Village of Endicott, Municipal Building, Endicott, NY 13760			15. TELEPHONE NUMBER (607) 757-2423		
16. PREPARER Jim Drumm, Environmental Engineer 1				17. APPROVED			
Signature 		Date 7/16/05		Signature		Date	
Name, Title, Organization				Name, Title, Organization			

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
Division of Environmental Remediation

Inactive Hazardous Waste Disposal Report

April 1, 2003

<b>Site Name:</b> Endicott Village Landfill and Wellfield	<b>Site Code:</b> 704008
<b>Class Code:</b> 2 <b>Region:</b> 7 <b>County:</b> Broome	<b>EPA Id:</b> NYD980780746
<b>Address:</b> Airport Road / Endicott, NY 13760	
<b>Latitude:</b> 42° 5' 2" <b>Longitude:</b> 76° 5' 27"	<b>Site is on the EPA - National Priorities List.</b>
<b>Site Type:</b> Structure Landfill	<b>Estimated Size:</b> 70 Acres

**Site Owner / Operator Information:**

**Current Owner(s) Name:** Village of Endicott  
**Current Owner(s) Address:** 1009 East Main Street / Endicott, NY 13760  
**Owner(s) during disposal:** Village of Endicott  
**Operator(s) during disposal:** Village of Endicott  
**Stated Operator(s) Address:** 1009 East Main Street / Endicott, NY 13760  
**Hazardous Waste Disposal Period:** From: unknown To: 1977

**Site Description:**

This is a former Village landfill that operated up until 1977. It is subject to flooding by the Susquehanna River. Leachate discharges have been noted. The site received many tons of wastewater treatment plant sludge from IBM-Endicott. It had also reportedly received industrial wastes from the Endicott Johnson Co. and solvents from unknown sources. The groundwater table tends to be high in this area and on occasion waste was dumped below groundwater level. Most of the waste disposed was municipal refuse. Analysis of the leachate revealed the presence of various contaminants. Adjacent to the landfill is the Ranney Well, a very large municipally operated drinking water well which serves area residents. The well was contaminated with vinyl chloride and trace levels of other volatile organic compounds. An upgradient purge well reduces the amount of contaminated groundwater entering the well. A Remedial Investigation/Feasibility Study (RI/FS) done in 1984 established that contaminants in the groundwater originated in the area of the Endicott Village Landfill. A Record of Decision (ROD) in 1987 called for the construction of a 3,200 gallon/minute air stripper which was completed on August 21, 1991. The cost of the air stripper was funded by an EQBA Title-3 grant. The IBM Corp. also submitted a supplemental draft RI for this site in the fall of 1990. The finalized supplemental RI/FS was completed in September of 1992, and it identified the landfill as the contaminant source. Subsequent to the report, the EPA issued a ROD calling for the installation of another purge well. A CO for constructing the well was signed by the USEPA, the municipalities and two industrial PRPs. The third & final ROD was signed on September 30, 1992, and calls for capping of the landfill. The cap construction has been completed, and was partially funded by the EQBA Title-3 program and by a potentially responsible party (PRP). Operation and maintenance (O&M) activities are currently underway here. An inspection report is submitted quarterly by the Village of Endicott.

**Confirmed Hazardous Waste Disposal:**

	<b>Quantity:</b>
Vinyl Chloride	unknown
Trans-1,2 Dichlorethylene	unknown
1,1-Dichloroethane	unknown
Trichloroethylene (TCE)	unknown
Chloroethane	unknown
Chlorobenzene	unknown
Xylene	unknown
Heavy Metal Sludge	unknown

<b>Analytical Data Available for:</b> Groundwater
<b>Applicable Standards Exceeded in:</b> Groundwater Drinking Water
<b>Geotechnical Information:</b> Depth to Groundwater:
<b>Soil/Rock Type:</b>

<b>Legal Action: Type:</b> State Consent Order	<b>Status:</b> Order Signed
<b>Remedial Action:</b> Complete	<b>Nature of action:</b> RI/FS + IRM.

**Assessment of Environmental Problems:**


Contamination of surface water and groundwater from industrial waste disposal. The Ranney Well has been sampled and groundwater contamination has been confirmed. A 3,200 gallon/minute air stripper was completed on August 21, 1991. This air stripper will help to minimize the impact of contamination to the drinking water.

**Assessment of Health Problems:**

Due to contamination by low levels of volatile organic compounds in the Ranney municipal water supply well an air stripper was installed in 1991. Additionally, a purge well was installed upgradient of the Ranney Well to divert contaminated groundwater. While approval was given by the USEPA in 1997 to turn off the air stripper, the Village of Endicott continues to operate the stripper as well as the purge well. Approval was granted because recent monitoring of water quality at the Ranney well and within the distribution system shows that volatile organic levels are now below public drinking water standards.



PRELIMINARY



EN-JOIE GOLF COURSE

RAINNEY WELL

SUSQUEHANNA RIVER






AIRPORT ROAD

ANSON RD.

JINTY CREEK

TRI-CITIES AIRPORT

LEGEND

-  PRESUMED LIMITS OF ENDICOTT LANDFILL
-  PRESUMED LIMITS OF REPUTED TOWN OF UNION LANDFILL
-  GROUND PENETRATING RADAR SURVEY
-  SEISMIC REFRACTION SURVEY
-  ELECTROMAGNETIC INDUCTION SURVEY

NOTE  
BASE MAP ADAPTED FROM ENLARGED PHOTOCOPY  
OF USGS ENDICOTT, NEW YORK QUADRANGLE  
MAP.

SCALE 1" = 1000'

FILE NO. R87-6014.2 © 1987 GOLDBERG-ZIMMO & ASSOCIATES, INC.




ENDICOTT LANDFILL SITE  
PROPOSED REMEDIAL  
INVESTIGATION

PROPOSED GEOPHYSICAL  
SURVEY LOCATIONS

APRIL 1987

FIGURE 3.1





**PROJECT  
LOCATION**

SCALE IN FEET



**MALCOLM  
PIRNIE**

VILLAGE OF ENDICOTT  
ENDICOTT, NEW YORK

**SITE LOCATION MAP**

COPYRIGHT © 1995  
MALCOLM PIRNIE, INC.

**FIGURE 1-1**

**MALCOLM  
PIRNIE**

# **REMEDIAL ACTION REPORT**

**Village of Endicott  
Endicott Wellfield Site,  
Operable Unit 2**

Prepared by:

**Malcolm Pirnie, Inc.  
Four Corporate Plaza  
Washington Avenue Extension  
Albany, New York 12203**

**February 1997  
1396013**

## 4.0 DECLARATIONS

### 4.1 GENERAL

---

Malcolm Pirnie personnel have monitored the construction of the Village of Endicott Landfill Closure from the construction of the subgrade through and including the placement of the topsoil layer according to the generally accepted practices at the time of construction. Based on field observations made by Malcolm Pirnie and the field and laboratory test data taken by Malcolm Pirnie or the contractor and subcontractors, the construction observed at the site compiled with the construction contract documents approved by the EPA and NYSDEC, excluding the deviations discussed in this document. The limitations to this report are contained in Section 4.2.

### 4.2 LIMITATIONS

---

This construction certification report was prepared by Malcolm Pirnie for the exclusive use of the Village of Endicott. This report applies specifically to the construction of the landfill cap for the Village of Endicott Landfill Closure, in accordance with generally accepted engineering practices.

The construction observation and monitoring were conducted under the conditions stated. Conclusions made in this report were based on observations and data obtained from field and laboratory tests conducted on widely spaced samples. Variations in properties between test locations may occur.

The topographic measurements were made by the contractor. Malcolm Pirnie did not independently verify the accuracy of this data. As-built drawings are available through the Village of Endicott.

The geosynthetic production quality control testing was completed by Poly Flex, Inc. or other companies acting on their behalf. Malcolm Pirnie did not independently verify the accuracy of this data.

The bituminous asphalt core samples were collected by Fahs-Rolston, Inc. and the laboratory analyses were performed by Atlantic Testing, Inc. Malcolm Pirnie did not independently verify the results of this testing.

TCLP testing of the soil materials used to construct the landfill cap was conducted by Life Science Laboratories, Inc. Malcolm Pirnie did not independently verify the results of this testing.



152

# RECORD OF DECISION

Endicott Well Field

Village of Endicott, Broome County, New York

United States Environmental Protection Agency  
Region II  
New York, New York  
September 1992

# DECLARATION FOR THE RECORD OF DECISION

## *SITE NAME AND LOCATION*

Endicott Well Field Site

Village of Endicott, Broome County, New York.

## *STATEMENT OF BASIS AND PURPOSE*

This decision document presents the selected remedial action for the Endicott Well Field Site (the "Site"), which was chosen in accordance with the requirements of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980, as amended ("CERCLA"), and the National Oil and Hazardous Substances Pollution Contingency Plan ("NCP"). This decision document explains the factual and legal basis for selecting the remedy for this Site.

The New York State Department of Environmental Conservation ("NYSDEC") concurs with the selected remedy. A letter of concurrence from NYSDEC is attached to this document (Appendix IV).

The information supporting this remedial action decision is contained in the Administrative Record file for this Site. The index to the Administrative Record file is attached (Appendix III).

## *ASSESSMENT OF THE SITE*

Actual or threatened releases of hazardous substances from this Site, if not addressed by implementing the response action selected by this Record of Decision ("ROD"), may present an imminent and substantial endangerment to public health, welfare, or the environment.

## *DESCRIPTION OF THE SELECTED REMEDY*

This operable unit ("OU") is OU #2, the third and final OU planned for the Site. EPA issued RODs for OU #1 and OU #3 in September 1987 and March 1991, respectively. The ROD for OU #1 addressed ground water contamination at the ranney well public water supply system, which was the immediate threat to human health posed by the Site, by requiring the installation of an air stripper on the ranney well and continued extraction and treatment of contaminated ground water using the existing purge well on the En-Joie Golf Course. The ROD for OU #3 provided additional ground water control and treatment by requiring the use of a supplemental purge well. This OU #2 ROD addresses the source of ground water contamination, identified as the Endicott Landfill ("Landfill #1" or the "Landfill"),

through landfill capping, gas venting, and control and treatment of the leachate seep. Long term management will be required to maintain these systems.

The major components of the selected remedy include the following:


- \* Capping the majority of the surface of Landfill #1 with a low permeability soil barrier cap, with a variance of 6NYCRR Part 360 requirements, to allow for a minimum of 12 inches of protective barrier fill with a permeability of  $10^{-5}$  cm/sec or less; in a ridge and swale configuration, with ridges having slopes of 4 percent and synthetic liner in the swales;
- \* Capping with bituminous (asphalt) caps the 6-acre parcel of Landfill #1 where the Village of Endicott has a permitted yard waste composting facility and the 8-acre Controlled Activity Area (CAA) of the Tri-Cities Airport regulated by the Federal Aviation Administration;
- \* Performing an explosive gas investigation and installing a gas venting system, as necessary, based on the results of a landfill gas investigation. A passive system with one vent per acre is envisioned, but this will be further evaluated during the remedial design phase;
- \* Collecting, treating, and disposing the leachate seep into the Susquehanna River or to a publicly owned treatment works. If installation of the cap reduces leachate generation to the extent that the seep no longer exists, this may not be warranted. The specific treatment and disposal option will be further evaluated during the remedial design phase, based on implementability;
- \* Recommending that institutional controls be established in the form of deed restrictions on future uses of Landfill #1;
- \* Fencing or other acceptable access restrictions to ensure protection of the Landfill #1 cap;
- \* Performing long term operation and maintenance of the Landfill #1 cap, gas venting, and leachate systems to provide for inspections and repairs;
- \* Performing long term air and water quality monitoring;
- \* Evaluating Site conditions at least once every five years to determine if a modification to the selected remedy is necessary.

Remediation of ground water is expected to be achieved by continued operation and maintenance of the ground water collection and treatment remedial measures already selected for the Site, which are the air stripper at the ranney well, the existing purge well, and the supplemental purge well.

**DECLARATION OF STATUTORY DETERMINATIONS**


The selected remedy is protective of human health and the environment, complies with Federal and State requirements that are legally applicable or relevant and appropriate to the remedial action and is cost effective. The selected remedy utilizes permanent solutions and alternative treatment (or resource recovery) technologies to the maximum extent practicable. Due to the large size of Landfill #1 and the absence of hot spots representing major sources of contamination, Landfill #1 could not practicably be excavated and treated. Therefore, the selected remedy does not satisfy the statutory preference for treatment as a principal element of the remedy with respect to source control.

Because the selected remedy will result in hazardous substances remaining on-site above health-based levels, a review will be conducted within five years after commencement of the remedial action to ensure that the remedy continues to provide adequate protection of human health and the environment.

  
Constantine Sidamon-Eristoff  
Regional Administrator

9/30/92  
Date





### Adjacent Property Summary

Add Adjacent Property

[Close Window](#)

Site Information			
ID:	704008	Program:	State Superfund Program
Name:	Endicott Village Landfill and Wellfield	Address:	Airport Road

4 results found

Property Information						
	Address:	City:	ZIP:	Owner:	Dist. from Site	
1.	<u>720 W MAIN ST</u>	Endicott	13760	VILLAGE OF ENDICOTT	0	<input type="button" value="Add Control"/>
2.	<u>W MAIN STREET</u>	Endicott	13760	VILLAGE OF ENDICOTT	1	<input type="button" value="Add Control"/>
3.	<u>W MAIN ST LAND</u>	Endicott	13760	VILLAGE OF ENDICOTT	1	<input type="button" value="Add Control"/>
4.	<u>W MAIN ST LAND</u>	Endicott	13760	VILLAGE OF ENDICOTT	1	<input type="button" value="Add Control"/>



32 ITHACA STREET  
TELEPHONE (607) 565-3500

WAVERLY, NY 14892-1532  
FAX (607) 565-4083

Date: 21-JAN-2004

Lab Sample ID: L114934-1

Endicott Waste Water Treatment Facility  
Steve Cerny

c/o 1009 E. Main Street  
Endicott, NY 13760

Sample Source: VILLAGE OF ENDICOTT WWTP  
Origin: SPW-010204-G  
Description: GRAB  
Sampled On: 02-JAN-04 00:00 by CLIENT  
Date Received: 02-JAN-04 11:45  
P.O. No: N/A

Analysis Performed	Result	Units	Detection Limit	Date Analyzed	Method	Notebook Reference
EPA 8021						
Dichlorodifluoromethane	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Chloromethane	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Vinyl chloride	22	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Bromomethane	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Chloroethane	10	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Trichlorofluoromethane	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
1,1-Dichloroethene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Methylene chloride	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
trans-1,2-Dichloroethene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
1,1-Dichloroethane	3	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
2,2-Dichloropropane	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
cis-1,2-Dichloroethene	24	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Bromochloromethane	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Chloroform	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
1,1,1-Trichloroethane	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Carbon tetrachloride	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
1,1-Dichloropropene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Benzene	0.8	ug/l	0.7	16-JAN-04 07:04	EPA 8021	03-120-10344
1,2-Dichloroethane	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Trichloroethene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
1,2-Dichloropropane	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Dibromomethane	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Bromodichloromethane	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
2-Chloroethylvinylether	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
cis-1,3-Dichloropropene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Toluene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
trans-1,3-Dichloropropene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
1,1,2-Trichloroethane	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Tetrachloroethene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
1,3-Dichloropropane	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Dibromochloromethane	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
1,2-Dibromoethane (EDB)	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Chlorobenzene	2	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
1,1,1,2-Tetrachloroethane	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Ethylbenzene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
p-Xylene/m-Xylene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
o-Xylene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Styrene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344

Approved by:  
Lab Director

Page 1 of 2  
NY 10252 NJ 73168 PA 68180 EPA NY 00033

*Miranda L. ISVSO*  
QC

KEY: ND or U = None Detected < = less than ug/L = micrograms per liter (equivalent to parts per billion)  
mg/L = milligram per liter (equivalent to parts per million) mg/kg = milligrams per kilogram (equivalent to parts per million)  
B = analyte was detected in the method or trip blank E = estimated value

The information in this report is accurate to the best of our knowledge and ability. In no event shall our liability exceed the cost for these services. Your samples will be discarded after 14 days unless we are advised otherwise.



**FRIEND  
LABORATORY  
I. N. C.**

32 ITHACA STREET  
TELEPHONE (607) 565-3500

WATERLOO NY 14892-1532  
FAX (607) 565-4083

Date: 21-JAN-2004

Lab Sample ID: L114934-1

Endicott Waste Water Treatment Facility  
Steve Cerny

1009 E. Main Street  
Endicott, NY 13760

Sample Source: VILLAGE OF ENDICOTT WWTP  
Origin: SPW-010204-G  
Description: GRAB  
Sampled On: 02-JAN-04 00:00 by CLIENT  
Date Received: 02-JAN-04 11:45  
P.O. No: N/A

Analysis Performed	Result	Units	Detection Limit	Date Analyzed	Method	Notebook Reference
Form	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Propylbenzene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Benzene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
1,2-Tetrachloroethane	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Trichloropropane	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Tolylbenzene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Protoluene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Protoluene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
1-Trimethylbenzene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Butylbenzene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
1-Trimethylbenzene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Tolylbenzene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Dichlorobenzene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Dichlorobenzene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Propyltoluene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Dichlorobenzene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Tolylbenzene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Dibromo-3-chloropropane	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
1-Trichlorobenzene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Chlorobutadiene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
Thalene	U	ug/l	1	16-JAN-04 07:04	EPA 8021	03-120-10344
3-Trichlorobenzene	U	ug/l	5	16-JAN-04 07:04	EPA 8021	03-120-10344
1,1-Dimethyl-tert-butyl-ether (MTBE)	U	ug/l				
Spigate Recovery:						03-120-10344
- Bromofluorobenzene	136	%				03-120-10344
- Bromofluorobenzene	116	%				

Approved by:

Page 2 of 2  
NY 10252 NJ 73168 PA 68180 EPA-NY 00033

QC

ND or U = None Detected < = less than ug/L = micrograms per liter (equivalent to parts per billion)  
mg/L = milligram per liter (equivalent to parts per million) mg/kg = milligrams per kilogram (equivalent to parts per million)  
B = analyte was detected in the method or trip blank E = estimated value

Information in this report is accurate to the best of our knowledge and ability. In no event shall our liability exceed the cost of these services. Your samples will be discarded after 14 days unless we are advised otherwise.

File on eDOCs  Yes \_\_\_\_\_ No

Site Name Endicott

Site No. 704008

County Breome

Town Endicott

Foilable  Yes \_\_\_\_\_ No

File Name 2004-01-01 - Proposed Class Change Package

Scanned & eDOC \_\_\_\_\_