

Justin Starr, P.G.  
New York State Department of Environmental Conservation  
Division of Environmental Remediation, Bureau C  
625 Broadway, 11<sup>th</sup> Floor  
Albany, NY 12233

Arcadis of New York, Inc.  
One Lincoln Center  
110 West Fayette Street  
Suite 300  
Syracuse  
New York 13202  
Phone: 315 446 9120  
Fax: 315 449 0017

[www.arcadis.com](http://www.arcadis.com)

Date: July 10, 2023  
Our Ref: 30169483  
Subject: 2023 Qualitative Site Inspection  
NYSEG Cortland-Homer Former MGP Site  
Site No. 7-12-005

Dear Mr. Starr,

On behalf of the New York State Electric & Gas Corporation (NYSEG), this Site Inspection Letter has been prepared for the Cortland-Homer Former Manufactured Gas Plant (MGP) site, Operable Unit No. 2 (OU-2) located in Homer, New York (the site). This letter presents the results of the 2023 qualitative monitoring event including, adaptive management and corrective action recommendations to support meeting the Year 1 performance criteria and has been prepared in accordance with the Preliminary Monitoring and Maintenance plan included as Appendix G to the April 2020 Remedial Design Report (Remedial Design).

The following sections of this letter report include:

- An introduction summarizing the performance criteria applicable to Year 1 and the monitoring objectives and observations to support potential adaptive management and corrective actions for the restoration.
- Inspection methods used to complete the qualitative monitoring event.
- Summary of observations made in comparison to “as-built” conditions and Year 1 performance criteria including photographs and site locations to reference on site figures.
- Proposed adaptive management and corrective actions to be performed to support meeting the performance criteria.

## Introduction

The spring qualitative monitoring and inspection was performed to evaluate the restoration success and to provide an initial assessment for determining if any of the performance criteria may not be met. Qualitative monitoring is focused on identifying:

- Tree and shrub survival/mortality;
- Herbaceous cover quality;
- Presence of non-native invasive and nuisance species; and
- Erosion control issues associated with the restored channel and banks.

If qualitative monitoring identifies any significant issues affecting the restoration, then corrective actions and/or adaptive management measures may be implemented to ensure that performance criteria are met.

Corrective actions may include use of proactive invasive species management, reseeding herbaceous vegetation areas as necessary, or replanting trees that did not survive. Adaptive management measures may include:

- Adjusting to current climate conditions;
- Implementing a more rigorous watering plan to combat prolonged drought conditions; and
- Reviewing if a restored area or specific species is showing signs of stress or more significant mortality than other species.

The Year 1 performance criteria for plantings includes:

- Trees – 100% survival;
- Shrubs – 80% survival;
- Herbaceous ground cover – at least 85% average cover;
- Vegetation below the mean high-water line (MHWL)
  - Shrubs – 80% total cover by Year 5
  - Emergent wetland vegetation – 80% total cover by Year 5
- Invasive plant species ground cover – 0% of prohibited species, less than 5% regulated species.

The inspection results and recommended corrective actions are outlined in the following sections.

## Site Inspection Methods

During the spring qualitative monitoring event, meander surveys were performed within each of the restored areas (i.e., Area 1, Area 2). The meander survey is used to visually assess and evaluate any significant stability or erosion issues within the banks and associated floodplain or habitat areas, plantings and herbaceous ground cover conditions, herbivore damage, or human usage, and assess the presence of any invasive plant species within or adjacent to the restored habitats.

The eastern shoreline and floodplain areas at Area 1 are located on private property and were not accessible to the meander survey. Instead, a drone survey was used to assess this area and consisted of two separate orthomosaic grid flights at heights of 150 feet (ft) and 120 ft above ground level. Both collections were performed at nadir using a DJI Phantom 4 V2, with 80% endlap and 70% sidelap (403 and 613 photos respectively). The imagery was orthorectified and processed into mosaics with ground sample distance of 0.48 and 0.38" respectively (see Figure 1). A Visible Atmospherically Resistant Index (VARI) was calculated for each orthomosaic to assess the relative vegetative health of different areas in Area 1.

Photographs to assess the restored areas for both Area 1 and 2 were established at fixed assessment points with predetermined cardinal directions at 12 of the targeted 20 locations for Area 1 and all 17 targeted locations for Area 2 (Figures 1 and 2, respectively), fixed assessment point photos are provided as Attachment 1A. Within the eastern shoreline and floodplain area for Area 1, the current drone aerial imagery has been georeferenced to detail current conditions and is shown on Figure 1. During the quantitative monitoring event later this year, the remaining eight fixed assessment point photographs at Area 1 will be taken to document current conditions. Additional photographs were collected at any identified problem areas (e.g., presence of nuisance or invasive plant species, bank sloughing, etc.) (Attachment 1B) and locations for potential corrective action needs were noted and mapped on Figures 4 and 5.

## Site Inspection Observations – Area 1

Restoration activities for Area 1 were substantially completed in November 2021. Year 1 qualitative monitoring was performed by Arcadis staff on May 25, 2023.

### Trees, Shrubs and Live Stakes

As-built conditions for Area 1 included 244 trees, 2,201 shrubs, and 453 live stakes. Trees and shrubs along the western shoreline generally appeared to be in good health with little mortality observed. Herbivore damage was evident along the western and eastern shoreline and floodplain (Attachment 1B, Photos 3 and 11, respectively). Analysis of drone images identified approximately 32 dead tree plantings on the eastern shoreline of restoration Area 1 (Figure 3). Despite the observed mortality within the eastern shoreline, one example of natural recruitment was observed, as a maple sapling was present and healthy. A formal tree and shrub mortality census will be performed as part of the quantitative monitoring effort planned for August/September 2023.

In general, live stakes appeared to be successful along the western shoreline lower bank areas with evident budding and leafing and limited mortality observed. Approximate survival of the black willow, red-osier dogwood, and silky dogwood stakes is estimated to be 40 to 50% across both shorelines. A large portion of live stakes installed on the western shoreline were either not budded out or damaged from high flows and herbivore activity. One example of poor live stake success along the eastern shoreline is shown in Photo 12 (Attachment 1B).

Observations during this Year 1 qualitative inspection indicate that the performance criteria for tree and shrub survival may not be achieved. Further discussion is provided below with respect to potential corrective action needs.

### Herbaceous Cover and Emergent Vegetation

As-built conditions for Area 1 included the seeding of herbaceous cover. Habitat-specific seed mixes were sowed to re-establish vegetative species within the wet meadow, floodplain, bank, and maintained grass planting areas. Approximately 1,400 emergent plugs were installed, comprised of two species, Arrow arum (*Peltandra virginica*) and American bur-reed (*Sparganium americanum*), to restore this emergent vegetative community found in the near-shore inundated planting areas. Overall herbaceous cover appeared in good condition with wildflowers beginning to bloom on the upper banks and into the floodplain along most of the western shoreline. Two areas lacking vegetative cover were identified, one on the western bank and one along the eastern shoreline (Attachment 1B, Photos 5 and 10, respectively). Some bare spots were noted within the restored areas of the western shoreline.

Aerial analysis of the eastern shoreline indicated that none of the planting areas can be reliably estimated at over 85% vegetative cover. Cover was estimated using a VARI index (Figure 6), which classes relative vegetative vigor by using the ratio of intensities of different discrete bands of visible imagery (Green - Red) / (Green + Red - Blue). The ratio emphasizes green reflectance while accounting for objects which may reflect highly across the whole visible spectrum (i.e. bare rock or concrete). Inspection of the imagery confirmed that areas with a VARI score greater than zero appeared to indicate vegetation, while those with VARI scores of zero or less indicated rock, bare dirt, water, or pavement. The VARI image was accordingly classified as vegetation versus non-vegetation, and each planting area was assessed for percentage of vegetative cover. Estimated percent cover ranged from 11% in the West Bank area to 80% in the Floodplain Planting area. True percentages may vary from the

estimates (in particular, the low percentage in the West Bank area may be due to slight spatial shifts in the area boundary or orthoimage), but none of the planting areas can be assumed to be over 85% cover.

Within portions of the emergent vegetation planting zones and along other portions of the shallow and depositional shoreline edges of the river natural recruitment of watercress (*Nasturtium spp.*) was observed (Attachment 1B, Photo 2). Both the Arrow arum and American bur-reed plantings were not observed in most of the targeted emergent planting zones for Area 1. High flow conditions may have disturbed the emergent planting areas in this area. Additional monitoring during the quantitative visit will further determine whether any planted species survived.

The observations during this Year 1 qualitative inspection indicate that the herbaceous cover and emergent vegetation appear to be on track to meet the performance criteria for the western shoreline and potential corrective action measures may be required along the eastern shoreline to improve performance.

## Bank Stability

General soil stability was observed to be in good condition with rip-rap cover along portions of the lower bank, sheet flow drainages, and coir logs installed on bank slopes. Coir logs appeared intact and were in their installed locations. Some minor erosion was observed on banks, near soil-choked rip-rap materials, in lower drainage swale, and in floodplain swale (Attachment 1B, Photos 4, 5, 6, 7, and 9). These locations will be further monitored during the quantitative event to determine whether any require further action.

## Invasive Species

The primary invasive species identified in Area 1 are garlic mustard (*Alliaria petiolata*) (Attachment 1B, Photo 8) and a species of non-native honeysuckle (*Lonicera spp.*), which was sparsely observed within the area. A significant stand of garlic mustard was observed along the western bank below the downstream bridge. Potential nuisance species, yellow rocket (*Barbarea vulgaris*), was observed along portions of the western shoreline (Attachment 1B, Photo 1).

## Signs of Stress

Herbivory was the only evident sign of stress observed in Area 1. The northeast portion of the bank and floodplain planting areas along the eastern bank showed signs of heavy herbivore damage to shrubs that may have been from deer browse based on the abundant tracks found in this area (Attachment 1B, Photo 11) and poor live stake survival (Attachment 1B, Photo 12). One example of herbivore damage was documented on the western shore (Attachment 1B, Photo 3), showing a beaver chew on a willow shrub.

## Site Inspection Observations – Area 2

Restoration activities for Area 2 were completed in November 2022. Year 1 qualitative monitoring was performed by Arcadis staff on May 25, 2023.



## Trees, Shrubs, and Live Stakes

As-built conditions for Area 2 included 257 trees, 2,100 shrubs, and 251 live stakes. In general, the tree plantings appeared in good health with evident budding and leafing on a majority of the individuals observed. Some specimens indicated stress due to recent hard frost and drought conditions indicated by wilted leaves and only some basal leaf growth. Shrub mortalities were observed in the floodplain and upper bank areas and appeared to primarily impact two species, serviceberry (*Amelanchier arborea*) and red-osier dogwood (*Cornus sericea*), with the predominant shrub mortality observed for serviceberry throughout Area 2 (Attachment 1B, Photo 16). A census of serviceberry and red-osier dogwood mortality determined that approximately 60 individual plantings were dead (45 in the upper bank planting area, 15 in the floodplain planting area). Despite these mortalities, the remaining shrubs were relatively healthy and the overall performance criteria 80% survival within the first two growing seasons is being met. Shrubs in the upper bank and floodplain planting area will be reassessed during the quantitative monitoring visit later in the year.

Live stakes planted on the eastern shore within the lower bank area below the MHWL were not observed. Live stake mortality will be reassessed during the quantitative monitoring visit with recommendations provided to meet performance criteria.

## Herbaceous Cover and Emergent Vegetation

Overall herbaceous cover appeared in poor condition with large portions of the restoration area showing limited ground cover. In the upland laydown area, herbaceous cover has not been successfully established (Attachment 1B, Photo 13). Avian species known to nest in barren, rocky areas (Killdeer) were observed nesting in the upland restoration area. The floodplain tree and shrub planting area were also observed to have sparse herbaceous cover (Attachment 1B, Photo 14). Herbaceous cover between top of bank and transitional areas was estimated between 35 to 50%. Areas where herbaceous seed mixes were applied appeared to lack sufficient moisture for plant survival with dry, exposed soil prevalent. Herbaceous cover was improved on the northern banks of Area 2, suggesting there is greater water availability or protection from prolonged, intense sun exposure. Observations of emergent plantings had some arrow arum (*Peltandra virginica*) developing on the east bank (Attachment 1B, Photo 17).

## Bank Stability

General soil stability was observed to be in good condition with rip-rap cover along portions of the lower bank and coir logs installed on bank slopes. Coir logs appeared intact and were in their installed locations. Some instances of minor erosion were documented on banks, including sloughing in the transitional/lower bank below installed coir log (Attachment 1B, Photos 15 and 19).

## Invasive Species

One invasive species was identified in Area 2 during the inspection, as garlic mustard (*Alliaria petiolata*) (Attachment 1B, Photo 18).

## Signs of Stress

The primary indicator of stress was the lack of herbaceous cover and significant shrub mortality. Site inspectors observed dry soil conditions in the upland, laydown area and the upper bank area. These observations suggest this site has not had sufficient water to facilitate plant establishment and survival.

## Corrective Actions

Field observations for Restoration Area 1 and 2 determined that site conditions may not meet performance criteria for Year 1. Recommended corrective actions to improve tree and shrub survivability, expand herbaceous cover, improve emergent plantings, protect woody plants from herbivory, and remove invasive species, include:

### Area 1

- Trees – Limited tree replacement will be required. Tree replacement quantity required to meet 100% survival within the first two growing seasons will be determined during the quantitative inspection. Replacements will be installed either within the fall planting window or the following spring.
- Shrubs – The total shrub survival performance standard (80%) is currently being met. If conditions during the quantitative inspection differ and the performance criteria is not met, then replacement shrubs that have shown higher survival and resistance to herbivores will be proposed.
- Herbaceous cover – Herbaceous planting areas will likely not meet the performance criteria (85% cover). Fall reseeded of these areas is recommended.
- Emergent vegetation and live stakes – Observations indicate the need to monitor their establishment, as loss was evident during this inspection. Recommendations will be determined following the quantitative inspection.
- Invasive Species – Invasive plant species garlic mustard (*Alliaria petiolata*), non-native honeysuckle (*Lonicera spp.*), and nuisance species yellow rocket (*Barbarea vulgaris*) were observed in the restored areas. Proactive invasive plant species management will be implemented in September 2023 to prevent further establishment within the restored planting areas.

### Area 2

- Trees – Due to observed frost damage and drought conditions, tree mortality will be reassessed during the quantitative inspection. Tree replacement, if necessary, will be completed within the fall planting window or the following spring.
- Shrubs – Shrub mortalities were observed in the floodplain and upper bank areas. The quantitative inspection will determine if shrub survival criteria (80%) is being met. If not, replacement shrubs that are more tolerant of low moisture conditions and high sun exposure will be recommended for replanting.
- Herbaceous cover – Upland and bank planting areas indicate low herbaceous ground cover and pending the quantitative monitoring results, most likely will require fall re-seeding and implementation of a watering plan.
- Emergent vegetation and live stakes – Observations indicate the need to monitor their establishment, as loss was evident during this inspection. Recommendations will be determined following the quantitative inspection.
- Invasive Species – Garlic mustard (*Alliaria petiolata*) was observed in the restored areas. Proactive invasive plant species management will be implemented in September 2023 to prevent further establishment within the restored planting areas.

Justin Starr, P.G.  
New York State Department of Environmental Conservation  
July 10, 2023

## Corrective Action Implementation

To date no corrective actions or adaptive management actions have been implemented since restoration activities were completed. A summer inspection is planned for August/September of 2023 to collect quantitative data. Following the summer inspection, NYSEG will develop a plan for implementing recommended corrective actions within the calendar year or prior to next year's monitoring events. This may include fall planting of trees, shrubs, and emergent vegetation, reseeding activities, and implementation of a watering plan, as necessary to facilitate plant establishment and survival.

Please contact Mark Castro at 203-233-1245 or [mark\\_castro@avangrid.com](mailto:mark_castro@avangrid.com) or Levia Terrell at 607-423-1652 or [lterrell@nyseg.com](mailto:lterrell@nyseg.com) or me with questions or comments.

Sincerely,  
Arcadis of New York, Inc.



Joe Bistrovich

Email: [joe.bistrovich@arcadis.com](mailto:joe.bistrovich@arcadis.com)  
Direct Line: 315.671.9697  
Mobile: 315.427.4585

CC. Mark Castro, NYSEG  
Levia Terrell, NYSEG  
Tracy Blazicek, CHMM, NYSEG  
Mark Gravelding, Arcadis  
Jason Vogel, Arcadis

Enclosures:

Figures  
Attachment 1A – Fixed Assessment Photograph Log  
Attachment 1B – Inspection Photograph Log  
Attachment 2 – Monitoring Inspection Checklists

# Figures



Path: T:\env\yseg\Cortland-Homer-VegetationMonitoring\_2023\aprx\Figure 1\Fixed Reference Locations Last Saved By: ldrum 6/9/2023




#### LEGEND

- PHOTO LOCATION WITH DIRECTION
- EMERGENT PLANTING AREA
- FLOODPLAIN PLANTING AREA
- WET MEADOW PLANTING AREA
- INUNDATED PLANTING AREA
- WEST BANK PLANTING AREA

#### NOTES:

1. PROJECTION: NAD 1983 STATEPLANE NEW YORK CENTRAL FIPS 3102 FEET
2. BASEMAP SOURCE: DRONE IMAGERY FLOW BY ARCADIS 05/25/2023; OVERLAID ON ESRI WORLD IMAGERY ACCESSED 6/9/2023



NYSEG - CORTLAND-HOMER FORMER MGP SITE  
HOMER, NEW YORK  
OPERABLE UNIT 2, SITE INSPECTION REPORT

AREA 1 FIXED PHOTO POINT LOCATIONS



FIGURE  
1



Path: T:\ENV\NYSEG\Cortland-Homer\VegetationMonitoring\_2023\april\Figure 2 Area 2 Fixed Reference Locations Last Saved By: ACarlone 6/14/2023




**LEGEND**

- PHOTO LOCATION WITH DIRECTION
- FLOODPLAIN PLANTING AREA
- INUNDATED PLANTING AREA
- UPLAND PLANTING AREA

**NOTES:**

1. PROJECTION: NAD 1983 STATEPLANE NEW YORK CENTRAL FIPS 3102 FEET
2. BASEMAP SOURCE: NYS ITS GIS PROGRAM DATED 2022  
ACCESSED 6/14/2023



NYSEG - CORTLAND-HOMER FORMER MGP SITE HOMER, NEW YORK OPERABLE UNIT 2, SITE INSPECTION REPORT	
AREA 2 FIXED PHOTO POINT LOCATIONS	
	FIGURE <b>2</b>




Path: T:\env\nyseg\Cortland-Homer-VegetationMonitoring\_2023\vegMonitoring\_2023.aprx\Figure 3 Area 1 Eastern Shoreline Aerial Analysis Last Saved By: ldrum 6/13/2023



- LEGEND**
- TREE PLANTING**
- ▲ ALIVE
  - ▲ DEAD
  - EMERGENT PLANTING AREA
  - FLOODPLAIN PLANTING AREA
  - WET MEADOW PLANTING AREA
  - INUNDATED PLANTING AREA
  - WEST BANK PLANTING AREA

- NOTES:**
1. PROJECTION: NAD 1983 STATEPLANE NEW YORK CENTRAL FIPS 3102 FEET
  2. BASEMAP SOURCE: DRONE IMAGERY FLOW BY ARCADIS 05/25/2023; OVERLAID ON ESRI WORLD IMAGERY ACCESSED 6/13/2023



NYSEG - CORTLAND-HOMER FORMER MGP SITE  
HOMER, NEW YORK  
OPERABLE UNIT 2, SITE INSPECTION REPORT

AREA 1 EASTERN SHORELINE  
AERIAL ANALYSIS




Path: T:\env\Nyseg\Cortland-Homer-VegetationMonitoring\_2023\aprx\Figure 4 Area 1 Corrective Action Locations Last Saved By: ldrum 6/9/2023



- LEGEND**
- PHOTO LOCATION WITH DIRECTION
  - EMERGENT PLANTING AREA
  - FLOODPLAIN PLANTING AREA
  - WET MEADOW PLANTING AREA
  - INUNDATED PLANTING AREA
  - WEST BANK PLANTING AREA


- NOTES:**
- 1. PROJECTION: NAD 1983 STATEPLANE NEW YORK CENTRAL FIPS 3102 FEET
  - 2. BASEMAP SOURCE: DRONE IMAGERY FLOW BY ARCADIS 05/25/2023; OVERLAID ON ESRI WORLD IMAGERY ACCESSED 6/9/2023







NYSEG - CORTLAND-HOMER FORMER MGP SITE HOMER, NEW YORK OPERABLE UNIT 2, SITE INSPECTION REPORT	
AREA 1 POTENTIAL CORRECTIVE ACTION LOCATIONS	
ARCADIS	FIGURE 4




Path: T:\ENV\NYSEG\Cortland-Homer\VegetationMonitoring\2023\april\Figure 5 Area 2 Corrective Action Locations Last Saved By: ACarlone 7/6/2023



- LEGEND**
-  PHOTO LOCATION WITH DIRECTION
  -  FLOODPLAIN PLANTING AREA
  -  INUNDATED PLANTING AREA
  -  UPLAND PLANTING AREA

- NOTES:**
1. PROJECTION: NAD 1983 STATEPLANE NEW YORK CENTRAL  
FIPS 3102 FEET
  2. BASEMAP SOURCE: NYS ITS GIS PROGRAM DATED 2022  
ACCESSED 7/6/2023



NYSEG - CORTLAND-HOMER FORMER MGP SITE  
HOMER, NEW YORK  
OPERABLE UNIT 2, SITE INSPECTION REPORT



**AREA 2 POTENTIAL CORRECTIVE  
ACTION LOCATIONS**




FIGURE  
**5**



Path: T:\env\nyseg\Cortland-Homer\VegetationMonitoring\2023\aprx\Figure 6 VARI Index Last Saved By: Idium 6/13/2023



- NOTES:**
1. PROJECTION: NAD 1983 STATEPLANE NEW YORK CENTRAL FIPS 3102 FEET
  2. BASEMAP SOURCE: DRONE IMAGERY FLOW BY ARCADIS 05/25/2023



NYSEG - CORTLAND-HOMER FORMER MGP SITE  
HOMER, NEW YORK  
OPERABLE UNIT 2, SITE INSPECTION REPORT

**GROUND COVER  
VARI INDEX**



FIGURE  
**6**

# **Attachment 1A**

**Fixed Assessment Photograph Log**



## PHOTOGRAPH LOG

Fixed Assessment Photos  
NYSEG – Cortland-Homer Former MGP Site  
OU-2, Area 1 & Area 2  
Homer, New York



**Photo: P1**

**Location:**  
Area 1 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P1.

**Coordinates:**  
42.622328  
-76.183639

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing Northeast.



**Photo: P2**

**Location:**  
Area 1 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P2.

**Coordinates:**  
42.622357  
-76.183528

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing Southeast.



## PHOTOGRAPH LOG

Fixed Assessment Photos  
NYSEG – Cortland-Homer Former MGP Site  
OU-2, Area 1 & Area 2  
Homer, New York



**Photo: P3**

**Location:**  
Area 1 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P3.

**Coordinates:**  
42.621557  
-76.183739

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing South.



**Photo: P4**

**Location:**  
Area 1 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P4.

**Coordinates:**  
42.620648  
-76.183818

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing Northeast.



## PHOTOGRAPH LOG

Fixed Assessment Photos  
NYSEG – Cortland-Homer Former MGP Site  
OU-2, Area 1 & Area 2  
Homer, New York



**Photo: P5**

**Location:**  
Area 1 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P5.

**Coordinates:**  
42.621196  
-76.183360

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing Southeast.



**Photo: P6**

**Location:**  
Area 1 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P6.

**Coordinates:**  
42.620679  
-76.183094

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing South.



## PHOTOGRAPH LOG

Fixed Assessment Photos  
NYSEG – Cortland-Homer Former MGP Site  
OU-2, Area 1 & Area 2  
Homer, New York



**Photo: P7**

**Location:**  
Area 1 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P7.

**Coordinates:**  
42.620039  
-76.182952

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing North.



**Photo: P8**

**Location:**  
Area 1 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P8.

**Coordinates:**  
42.619899  
-76.182847

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing Southeast.



## PHOTOGRAPH LOG

Fixed Assessment Photos  
NYSEG – Cortland-Homer Former MGP Site  
OU-2, Area 1 & Area 2  
Homer, New York



**Photo: P9**

**Location:**  
Area 1 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P9.

**Coordinates:**  
42.619150  
-76.182337

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing Northwest.



**Photo: P10**

**Location:**  
Area 1 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P10.

**Coordinates:**  
42.618981  
-76.182331

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing Southeast.



## PHOTOGRAPH LOG

Fixed Assessment Photos  
NYSEG – Cortland-Homer Former MGP Site  
OU-2, Area 1 & Area 2  
Homer, New York



**Photo: P11**

**Location:**  
Area 1 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P11.

**Coordinates:**  
42.618670  
-76.182358

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing North.



**Photo: P12**

**Location:**  
Area 1 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P12.

**Coordinates:**  
42.618476  
-76.181989

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing North.



## PHOTOGRAPH LOG

Fixed Assessment Photos  
NYSEG – Cortland-Homer Former MGP Site  
OU-2, Area 1 & Area 2  
Homer, New York



**Photo: P21**

**Location:**  
Area 2 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P21.

**Coordinates:**  
42.611597  
-76.183211

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing Northeast.



**Photo: P22**

**Location:**  
Area 2 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P22.

**Coordinates:**  
42.611581  
-76.183231

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing Southwest.



## PHOTOGRAPH LOG

Fixed Assessment Photos  
NYSEG – Cortland-Homer Former MGP Site  
OU-2, Area 1 & Area 2  
Homer, New York



**Photo: P23**

**Location:**  
Area 2 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P23.

**Coordinates:**  
42.611424  
-76.183469

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing Southeast



**Photo: P24**

**Location:**  
Area 2 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P24.

**Coordinates:**  
42.610815  
-76.183410

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing Southeast.



## PHOTOGRAPH LOG

Fixed Assessment Photos  
NYSEG – Cortland-Homer Former MGP Site  
OU-2, Area 1 & Area 2  
Homer, New York



**Photo: P25**

**Location:**  
Area 2 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P25.

**Coordinates:**  
42.610308  
-76.181011

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing Northwest.



**Photo: P26**

**Location:**  
Area 2 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P26.

**Coordinates:**  
42.610139  
-76.181170

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing Northwest.



## PHOTOGRAPH LOG

Fixed Assessment Photos  
NYSEG – Cortland-Homer Former MGP Site  
OU-2, Area 1 & Area 2  
Homer, New York



**Photo: P27**

**Location:**  
Area 2 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P27.

**Coordinates:**  
42.610467  
-76.181748

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing Southwest.



**Photo: P28**

**Location:**  
Area 2 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P28.

**Coordinates:**  
42.610661  
-76.182411

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing Northwest.



## PHOTOGRAPH LOG

Fixed Assessment Photos  
NYSEG – Cortland-Homer Former MGP Site  
OU-2, Area 1 & Area 2  
Homer, New York



**Photo: P29**

**Location:**  
Area 2 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P29.

**Coordinates:**  
42.610751  
-76.182382

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing Northwest.



**Photo: P30**

**Location:**  
Area 2 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P30.

**Coordinates:**  
42.610841  
-76.182750

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing Northwest.



## PHOTOGRAPH LOG

Fixed Assessment Photos  
NYSEG – Cortland-Homer Former MGP Site  
OU-2, Area 1 & Area 2  
Homer, New York



**Photo: P31**

**Location:**  
Area 2 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P31.

**Coordinates:**  
42.611036  
-76.183092

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing South.



**Photo: P32**

**Location:**  
Area 2 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P32.

**Coordinates:**  
42.611201  
-76.182995

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing Northeast.



## PHOTOGRAPH LOG

Fixed Assessment Photos  
NYSEG – Cortland-Homer Former MGP Site  
OU-2, Area 1 & Area 2  
Homer, New York



**Photo: P33**

**Location:**  
Area 2 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P33.

**Coordinates:**  
42.611451  
-76.183020

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing Southwest.



**Photo: P34**

**Location:**  
Area 2 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P34.

**Coordinates:**  
42.611617  
-76.182749

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing Southeast.



## PHOTOGRAPH LOG

Fixed Assessment Photos  
NYSEG – Cortland-Homer Former MGP Site  
OU-2, Area 1 & Area 2  
Homer, New York



**Photo: P35**

**Location:**  
Area 2 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P35.

**Coordinates:**  
42.611898  
-76.182795

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing Southwest.



**Photo: P36**

**Location:**  
Area 2 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P36.

**Coordinates:**  
42.611778  
-76.182308

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing Northwest.

## PHOTOGRAPH LOG

Fixed Assessment Photos  
NYSEG – Cortland-Homer Former MGP Site  
OU-2, Area 1 & Area 2  
Homer, New York



**Photo:** P37

**Location:**  
Area 2 – Fixed Point  
Photo Locations

**Description:**  
Fixed-Point Photo  
Location P37.

**Coordinates:**  
42.612462  
-76.182751

**Date:** 05/25/2023

**Taken By:**  
Nick Firman

**Notes:**  
Facing Southwest.

# **Attachment 1B**

## **Inspection Photograph Log**



## PHOTOGRAPH LOG

Inspection Photos  
NYSEG – Cortland-Homer Former MGP Site  
OU-2, Area 1 & Area 2  
Homer, New York



**Photo: 1**

**Location:**  
Area 1 – Corrective  
Action Photo Locations

**Description:**  
Potential nuisance  
species on west  
shoreline (Yellow  
rocket).

**Coordinates:**  
42.622178  
-76.183542

**Date:** 05/25/2023

**Taken By:**  
Jason Vogel

**Notes:**  
Facing West.



**Photo: 2**

**Location:**  
Area 1– Corrective  
Action Photo Locations

**Description:**  
Natural recruitment of  
watercress in western  
emergent area.

**Coordinates:**  
42.621885  
-76.183556

**Date:** 05/25/2023

**Taken By:**  
Jason Vogel

**Notes:**  
Facing Southeast.



## PHOTOGRAPH LOG

Inspection Photos  
NYSEG – Cortland-Homer Former MGP Site  
OU-2, Area 1 & Area 2  
Homer, New York



**Photo: 3**

**Location:**  
Area 1– Corrective  
Action Photo Locations

**Description:**  
Woody stems of willow  
with signs of beaver  
damage, western  
inundated area.

**Coordinates:**  
42.621834  
-76.183580

**Date:** 05/25/2023

**Taken By:**  
Jason Vogel

**Notes:**  
Facing West.



**Photo: 4**

**Location:**  
Area 1– Corrective  
Action Photo Locations

**Description:**  
Minor bank erosion on  
western shoreline.

**Coordinates:**  
42.620940  
-76.183255

**Date:** 05/25/2023

**Taken By:**  
Jason Vogel

**Notes:**  
Facing West.



## PHOTOGRAPH LOG

Inspection Photos  
NYSEG – Cortland-Homer Former MGP Site  
OU-2, Area 1 & Area 2  
Homer, New York



**Photo: 5**

**Location:**  
Area 1– Corrective  
Action Photo Locations

**Description:**  
Western bank with low  
vegetative cover with  
erosion potential.

**Coordinates:**  
42.620666  
-76.183161

**Date:** 05/25/2023

**Taken By:**  
Jason Vogel

**Notes:**  
Facing South.



**Photo: 6**

**Location:**  
Area 1– Corrective  
Action Photo Locations

**Description:**  
Minor bank erosion in  
soil choked area on  
western shoreline.

**Coordinates:**  
42.619766  
-76.182609

**Date:** 05/25/2023

**Taken By:**  
Jason Vogel

**Notes:**  
Facing Southwest.



## PHOTOGRAPH LOG

Inspection Photos  
NYSEG – Cortland-Homer Former MGP Site  
OU-2, Area 1 & Area 2  
Homer, New York



**Photo: 7**

**Location:**  
Area 1– Corrective  
Action Photo Locations

**Description:**  
Erosion in drainage  
swale on western  
shoreline.

**Coordinates:**  
42.619032  
-76.182144

**Date:** 05/25/2023

**Taken By:**  
Jason Vogel

**Notes:**  
Facing Southwest.



**Photo: 8**

**Location:**  
Area 1– Corrective  
Action Photo Locations

**Description:**  
Stand of invasive garlic  
mustard downstream  
of bridge on western  
lower bank.

**Coordinates:**  
42.618789  
-76.182183

**Date:** 05/25/2023

**Taken By:**  
Jason Vogel

**Notes:**  
Facing East.



## PHOTOGRAPH LOG

Inspection Photos  
NYSEG – Cortland-Homer Former MGP Site  
OU-2, Area 1 & Area 2  
Homer, New York



**Photo: 9**

**Location:**  
Area 1– Corrective  
Action Photo Locations

**Description:**  
Minor erosion and bare  
herbaceous cover in  
floodplain swale on  
eastern shoreline.

**Coordinates:**  
42.619527  
-76.182047

**Date:** 05/25/2023

**Taken By:**  
Jason Vogel

**Notes:**  
Facing East.



**Photo: 10**

**Location:**  
Area 1– Corrective  
Action Photo Locations

**Description:**  
Transitional bank area  
on eastern shoreline  
with low herbaceous  
ground cover.

**Coordinates:**  
42.620804  
-76.182913

**Date:** 05/25/2023

**Taken By:**  
Jason Vogel

**Notes:**  
Facing East.



## PHOTOGRAPH LOG

Inspection Photos  
NYSEG – Cortland-Homer Former MGP Site  
OU-2, Area 1 & Area 2  
Homer, New York



**Photo: 11**

**Location:**  
Area 1– Corrective  
Action Photo Locations

**Description:**  
Area of heavy shrub  
herbivore damage on  
eastern shoreline.

**Coordinates:**  
42.621168  
-76.182988

**Date:** 05/25/2023

**Taken By:**  
Jason Vogel

**Notes:**  
Facing Southeast.



**Photo: 12**

**Location:**  
Area 1– Corrective  
Action Photo Locations

**Description:**  
Representative photo  
of low live stake  
survival on eastern  
shoreline.

**Coordinates:**  
42.621524  
-76.183228

**Date:** 05/25/2023

**Taken By:**  
Jason Vogel

**Notes:**  
Facing Southeast.



## PHOTOGRAPH LOG

Inspection Photos  
NYSEG – Cortland-Homer Former MGP Site  
OU-2, Area 1 & Area 2  
Homer, New York



**Photo: 13**

**Location:**  
Area 2 - Corrective  
Action Photo Locations

**Description:**  
Lay down area with  
sparse vegetative  
cover.

**Coordinates:**  
42.610155  
-76.180923

**Date:** 05/25/2023

**Taken By:**  
Jason Vogel

**Notes:**  
Facing Northwest.



**Photo: 14**

**Location:**  
Area 2 - Corrective  
Action Photo Locations

**Description:**  
Shrub and tree  
planting area with no  
herbaceous cover.

**Coordinates:**  
42.610225  
-76.181359

**Date:** 05/25/2023

**Taken By:**  
Jason Vogel

**Notes:**  
Facing Northwest.



## PHOTOGRAPH LOG

Inspection Photos  
NYSEG – Cortland-Homer Former MGP Site  
OU-2, Area 1 & Area 2  
Homer, New York



**Photo: 15**

**Location:**  
Area 2 - Corrective  
Action Photo Locations

**Description:**  
Lower bank erosion  
area under coir log.

**Coordinates:**  
42.610461  
-76.182001

**Date:** 05/25/2023

**Taken By:**  
Jason Vogel

**Notes:**  
Facing Northeast.



**Photo: 16**

**Location:**  
Area 2 - Corrective  
Action Photo Locations

**Description:**  
Representative photo  
of shrub mortality to  
serviceberry.

**Coordinates:**  
42.610564  
-76.182147

**Date:** 05/25/2023

**Taken By:**  
Jason Vogel

**Notes:**  
Facing North.



## PHOTOGRAPH LOG

Inspection Photos  
NYSEG – Cortland-Homer Former MGP Site  
OU-2, Area 1 & Area 2  
Homer, New York



**Photo: 17**

**Location:**  
Area 2 - Corrective  
Action Photo Locations

**Description:**  
Emergent planting  
area for arrow arum.

**Coordinates:**  
42.611051  
-76.183189

**Date:** 05/25/2023

**Taken By:**  
Jason Vogel

**Notes:**  
Facing North.



**Photo: 18**

**Location:**  
Area 2 - Corrective  
Action Photo Locations

**Description:**  
Invasive garlic mustard  
on bank.

**Coordinates:**  
42.611345  
-76.183098

**Date:** 05/25/2023

**Taken By:**  
Jason Vogel

**Notes:**  
Facing Northeast.



## PHOTOGRAPH LOG

Inspection Photos  
NYSEG – Cortland-Homer Former MGP Site  
OU-2, Area 1 & Area 2  
Homer, New York



**Photo: 19**

**Location:**  
Area 2 - Corrective  
Action Photo Locations

**Description:**  
Lower bank erosion.

**Coordinates:**  
42.611735  
-76.182869

**Date:** 05/25/2023

**Taken By:**  
Jason Vogel

**Notes:**  
Facing Northeast.



# **Attachment 2**

## **Monitoring Inspection Checklists**



Bi-Annual Monitoring Inspection Checklist Cortland-Homer Former MGP Site	
<b>I. GENERAL INFORMATION</b>	
Inspection Date:	May 25, 2023 - Area 1
Conducted By:	Jason Vogel, Nick Firman, Don Reed, Anna Butler
Weather Conditions:	High 40s to mid-50s F, Sunny, Light-Medium winds 10-20mph
<b>II. INSPECTION SUMMARY</b>	
<b>1. Vegetation</b>	
<b>A. Woody Vegetation</b> (Note evidence of damage from trespassing or herbivory, note physical changes since last inspection. If a quantitative assessment is performed, complete the attached field form for each planting area.)	
Live stakes budding and leafing, dogwood live stakes leafed out with pretty good survival along western shoreline, not many observed dead. Natural recruitment - maple sapling.	
Signs of herbivore damage (beaver chew) to willow shrub. Approximately 30 to 50% survival on dogwood stakes within Area 1. No tree collar protection on any tree plantings. Area of heavy shrub herbivore damage along eastern shoreline - Photo 11. Poor live stake survival along eastern shoreline - Photo 12.	
<b>B. Herbaceous Vegetation</b> (Note evidence of areas of bare/sparse vegetation; note any damage from trespassing or herbivory; note any physical changes since last inspection. If a quantitative assessment is performed, complete the attached field form for each planting area.)	
Upper bank cover looks good along western bank - wildflowers coming in. Nesting field sparrow in ground cover in upland planting area. Transitional bank area with low ground cover - Photo 10. Eastern bank indicates areas of lower herbaceous ground cover within the floodplain portion of the restored area from review of aerial imagery.	
<b>C. Presence of Invasive Species</b> (Note the invasive species present. If a quantitative assessment is performed, complete the attached field form for each planting area. If "prohibited" invasive species are observed, record the species, location, and size of the population observed.)	
Lonicera spp. - bush honeysuckle present in a few western top of bank areas. Stand of garlic mustard below downstream bridge. Several potential nuisance species observed, including yellow rocket and spatter dock.	
<b>D. Vegetation below MHWL</b> (Note evidence of damage from trespassing or herbivory, note physical changes since last inspection. If a quantitative assessment is performed, complete the attached field form for each planting area.)	
No emergent plugs observed. Natural recruitment of watercress in emergent area.	
<b>2. Riverbank Stability</b> (Note any physical changes since last inspection; note evidence of significant erosion [e.g., slope failure, ruts, gullies, washouts, or sloughing]; note other conditions that could jeopardize the performance of the completed remediation actions. If a quantitative assessment is performed, complete the attached field form for each transect.)	
Coir logs in place - remain where staked. Along western shoreline: minor bank erosion - Photo 4; area of minor erosion and lack of vegetative cover in bank area - Photo 5; minor bank sloughing in soil-choke/rip-rap area - Photo 6; erosion in drainage swale - Photo 7; and minor erosion in floodplain swale - Photo 9. Eastern shoreline banks were stable, some portions of the inundated shoreline indicated washout, but sediment deposition was present.	
<b>3. Other Observations</b> (Confirm that repair/maintenance activities identified during prior inspection, if any, have been performed; note any other general observations.)	
<b>III. FOLLOW-UP MAINTENANCE AND REPAIR ACTIVITIES</b>	
Recommend some minor repairs to erosion damage observed along western shoreline. Invasive species removal/treatment. Tree replacement with herbivore protection. Use quantitative monitoring event to determine potential need for shrub replacements if survival is less than performance criteria.	

ATTACH ADDITIONAL INFORMATION AS APPROPRIATE



Bi-Annual Monitoring Inspection Checklist Cortland-Homer Former MGP Site	
<b>I. GENERAL INFORMATION</b>	
Inspection Date:	May 25, 2023 - Area 2
Conducted By:	Jason Vogel, Nick Firman, Anna Butler
Weather Conditions:	High 40s to mid-50s F, Sunny, Light-Medium winds 10-20mph
<b>II. INSPECTION SUMMARY</b>	
<b>1. Vegetation</b>	
<b>A. Woody Vegetation</b> (Note evidence of damage from trespassing or herbivory, note physical changes since last inspection. If a quantitative assessment is performed, complete the attached field form for each planting area.)	
Trees are alive with some minor stress from recent frost. Serviceberry and red-osier dogwood appear to show highest shrub mortality. Photo 4 - dead shrub example. Meander survey count of dead shrubs in Area 2: Bank planting area = 45, upland planting area = 15. Still above performance criteria, but stress from prolonged dry conditions may inhibit survival through summer.	
<b>B. Herbaceous Vegetation</b> (Note evidence of areas of bare/sparse vegetation; note any damage from trespassing or herbivory; note any physical changes since last inspection. If a quantitative assessment is performed, complete the attached field form for each planting area.)	
Laydown area - sparse herbaceous cover, needs re-seeding - Photo 1. Upland area - limited to no herbaceous ground cover present.	
Tree and shrub planting area - limited herbaceous cover - Photo 2. Top of bank to transitional area, seeded herbaceous cover approximately 35 to 50%. Northern portion of Area 2 has more herbaceous vegetation, presumably from less sun exposure.	
<b>C. Presence of Invasive Species</b> (Note the invasive species present. If a quantitative assessment is performed, complete the attached field form for each planting area. If "prohibited" invasive species are observed, record the species, location, and size of the population observed.)	
Garlic mustard on upper bank - Photo 6.	
<b>D. Vegetation below MHWL</b> (Note evidence of damage from trespassing or herbivory, note physical changes since last inspection. If a quantitative assessment is performed, complete the attached field form for each planting area.)	
Arrow arum plugs are alive and emerging - Photo 5.	
<b>2. Riverbank Stability</b> (Note any physical changes since last inspection; note evidence of significant erosion [e.g., slope failure, ruts, gullies, washouts, or sloughing]; note other conditions that could jeopardize the performance of the completed remediation actions. If a quantitative assessment is performed, complete the attached field form for each transect.)	
Coir logs stable on bank slopes. Bank soil stable. Minor bank sloughing in transitional/lower bank, erosion below coir log - Photo 3. Erosion on lower bank below coir log - Photo 7.	
<b>3. Other Observations</b> (Confirm that repair/maintenance activities identified during prior inspection, if any, have been performed; note any other general observations.)	
Killdeer nesting in bare and rocky portion of lay down area.	
<b>III. FOLLOW-UP MAINTENANCE AND REPAIR ACTIVITIES</b>	
Recommend re-seeding laydown area including the floodplain and bank area. Implement a watering plan during seed germination period and assess for implementation this summer to protect tree and shrub plantings. Minor invasive species removal/treatment. Some minor erosion repairs to lower bank area present.	
Replacement of dead shrubs with species more tolerant of dry, full sun conditions, if overall shrub survival is not meeting performance criteria.	

ATTACH ADDITIONAL INFORMATION AS APPROPRIATE