



Inactive Hazardous Waste Site Operations and Maintenance Review Report

Form Date 96.10.01

Site Name: Lehigh Industrial Park		Class: 4	Number: 915145
O&M Funding Source: <input checked="" type="checkbox"/> State Superfund <input type="checkbox"/> Federal Superfund <input type="checkbox"/> Municipal <input type="checkbox"/> Responsible Party			
O&M Information: O&M Start: 1998 End: Annual Cost: \$3500.00 <input checked="" type="checkbox"/> Estimated			
Interim Remedial Measures/Operable Units in O&M Phase:			
<input type="checkbox"/> Drum Removal <input checked="" type="checkbox"/> Soil Removal <input type="checkbox"/> Tank Removal <input checked="" type="checkbox"/> Cap/Cover <input type="checkbox"/> Containment Structure <input checked="" type="checkbox"/> Fence/Security <input type="checkbox"/> Groundwater Recovery/Treatment <input type="checkbox"/> Leachate Collection/Treatment <input type="checkbox"/> Vapor Extraction/Treatment <input type="checkbox"/> Air Sparging/Stripper System <input type="checkbox"/> Treatment/Filtration Plant/System <input type="checkbox"/> Potable Water			
Supply/System <input checked="" type="checkbox"/> Other: Infiltration Basin			
Institutional Controls: <input type="checkbox"/> Deed Restriction <input type="checkbox"/> Discharge Permit <input type="checkbox"/> Department of Health Sampling <input type="checkbox"/> Other: None			
O&M Review Information: Reports: Remediation Summary report, O&M Manual, Baseline Sampling Report, 1999 & 2000 Annual Sampling report Inspection: 4/3/2002 Sampling: 4/3/2002: Other:			
Conclusions: Remedy Effective? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No: ROD Compliance? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No: Consent Order Compliance? <input type="checkbox"/> Yes <input type="checkbox"/> No: Other:			
Recommendations: <u>Continued monitoring and maintenance. Infiltration Basin holding water as designed. There is small woody vegetation growing in the riprap at the entrance of the infiltration basin. Snow buildup has pushed the fence over on the western edge of the basin. These require straightening and the top tension wire on fence needs to be tightened. The vehicle gate chain was broken(replaced the lock).</u>			
ROD/Consent Order Modifications? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes (per above) Reclassify the Site? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes → Class:			
Comments: * <u>Trees seem to be in fine shape and all the guy wires have been removed from the trunks. Vegetation at the site still seems to have been an excellent choice. Providing a dense, low cover, the grass is thick with no evidence of erosion at slopes. The trefoil matting is thick and prevented burning and was very drought resistant. In addition the grass never attains a height over 18 inches. It is a very good, low maintenance, cover choice.</u>			
Project Manager:  Signature Date Maurice F. Moore Reg. 9 (716)851-7220		Reviewer:  Signature Date Martin L. Doster, P.E. Reg. 9 (716)851-7220	
Name Region or Bureau Telephone		Name Region or Bureau Telephone	