

CORPORATE OFFICES 232 Delaware Avenue, Suite 33 Buffalo, New York 14202

> PO BOX 406 Buffalo, New York 14205

> TEL: 800.474.6802 716.845.6145 FAX: 716.845.6164 www.lenderconsulting.com

OFFICES

BUFFALO New York

ROCHESTER New York

SYRACUSE New York

Albany New York

New York City New York

VALLEY COTTAGE New York

HARRISBURG PENNSYLVANIA

PITTSBURGH PENNSYLVANIA

Allentown Pennsylvania

Baltimore *Maryland*

Salisbury Maryland

Cleveland *Ohio*

BROWNFIELD CLEANUP PROGRAM FINAL ENGINEERING REPORT For 432 NORTH FRANKLIN STREET SYRACUSE, NEW YORK

BCP AGREEMENT NO: B7-0615-02-06 SITE NO. C734089

Prepared for:

Franklin Properties, LLC and 432 North Franklin Properties, LLC 221 West Division Street. Syracuse, New York 13204

Prepared by:

Lender Consulting Services, Inc. PO Box 406 Buffalo, New York 14205

> April 2006 Revised December 2006

FINAL ENGINEERING REPORT

432 NORTH FRANKLIN STREET, SYRACUSE, NEW YORK

Table of Contents

1.0	INTRODUCTION	
1.1	Background	
1.2	Purpose and Scope	4
2.0	REMEDIAL ACTION	4
2.1	General	
	1.1 Objectives	
2.	1.2 Summary of Work Completed	4
3.0	SITE PREPARATION	4
3.1	Utility Clearance	
3.2	Mobilization	
3.3	Clearing/Grubbing	4
4.0	REMEDIAL ACTIONS IMPLEMENTED	~
4.0 4.1	Soil Excavation SEAOC	
4.1	Sub-Concrete Slab Depressurization System and Vapor Barrier	
		-
5.0	SAMPLE HANDLING	
5.1	Sample, Bottles, Preservation and Holding Time	
	1.1 Sample Bottles1.2 Sample Preservation	
	1.3 Holding Times	
5.2	Chain-of-Custody and Shipping	
5.3	Quality Assurance Objectives	
5.4	Data Usability	
5.5	Laboratory Quality Assurance	8
6.0	DATA VALIDATION	9
6.1	Sample Results	
7.0	SITE CAPPING	
7.1	Barrier Layer Construction	
	1.2 Topsoil Placement	
	1.3 Seeding and Planting	
7.	1.4 Barrier Layer Construction – Asphalt and Concrete 1	2
• •	STORMWATER RUNOFF CONTROL	•
8.0	STORMWATER RUNOFF CONTROL	3
9.0	DISPOSAL 1	3
10.0	GROUNDWATER MONITORING1	3
11.0	COMMUNITY AIR MONITORING 1	3
12.0	OPERATION, MAINTENANCE AND MONITORING PLAN1	3
CERT	IFICATION STATEMENT1	4

FINAL ENGINEERING REPORT 432 NORTH FRANKLIN STREET, SYRACUSE, NEW YORK

Table of Contents

FIGURES

Figure 1	Site Location Map
----------	-------------------

- Figure 2 Areas of Concern
- Figure 3 Barrier Cap Locations
- Figure 4 Sub Slab Vacuum Monitoring Points

APPENDICES

- Appendix A Remedial Action Plan Approval Letter
- Appendix B ERM's Summary of Oversight Activities Report
- Appendix C Vacuum Monitoring Point Construction Detail
- Appendix D Blower Specifications
- Appendix E Data Usability Summary Report and Laboratory Response
- Appendix F STL Laboratory Report Confirmatory Soil Sample Results
- Appendix G Laboratory QC Material Testing Results, Clay Barrier Material
- Appendix H Soil Disposal Characterization Laboratory Report
- Appendix I Soil Disposal Documentation
- Appendix J Groundwater Monitoring Well Construction Details
- Appendix K Community Air Monitoring Data
- Appendix L Maximum Contaminant Concentrations Detected On-Site
- Appendix M Annual Groundwater Monitoring Report

1.0 INTRODUCTION

1.1 Background

The 432 North Franklin Street property (subject property Site) is located within Franklin Square in the City of Syracuse (see Figure 1). The property is more specifically described as:

ALL THAT TRACT OR PARCEL OF LAND situate in the City of Syracuse, County of Onondaga and State of New York and being part of Marsh Lot No. 40 in said city, bounded and described as follows: Beginning at a point in the easterly line of Franklin Street, said point being 206 feet north of Laurel Street, thence north 31° 9' 00" west a distance of 18.42 feet to an angle point, thence continuing north 28° 9' 10" west a distance of 361.22 feet to a point, thence north 61° 50' 50" east a distance of 146.82 feet to a point, thence south 28° 9' 10" east, a distance of 3 feet to a point, thence north 61° 50' 50" east a distance of 128 feet to a point, thence south 28° 9' 10" east, a distance of 73.67 feet to a point, thence southerly along the westerly line of lands owned by the People of the State of New York (formerly New York Central and Hudson River Railroad Company) a distance of 321.30 feet to a point, thence south 59° 25' 40" west, a distance of 151.10 feet to the point and place of beginning.

The subject property was formerly used as an industrial and manufacturing facility. Prior environmental investigations completed by Environmental Resources Management (ERM) identified areas of environmental impairment at the subject property.

Franklin Properties, LLC and 432 Franklin Properties, LLC (Volunteers) entered into a Brownfield Cleanup Agreement with the New York State Department of Environmental Conservation (NYSDEC) in 2004, to perform specific remedial action at the subject property as part of the Brownfield's Cleanup Program (BCP Agreement No. B7-0615-02-06).

Prior studies completed by ERM pursuant to the regulatory agreements identified four areas of concern (AOCs) as summarized below:

- Northeast Corner Area of Concern (NEAOC) This is an area impacted by volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) associated with two closed-inplace 12,000 gallon underground storage tanks (USTs) and a former metal plating operation.
- Central East Area of Concern (CEAOC) This is an area impacted by VOCs and SVOCs associated with an abandoned 550-gallon waste oil UST.
- Southeast Area of Concern (SEAOC) This is an area of VOC, SVOC and lead impacted soil proximate to the historic foundry and a previously removed 2,000 gallon gasoline UST.
- Site Groundwater Impacted groundwater has been identified localized to the specific AOCs at the Site.

AOCs are identified on Figure 2.

ERM was retained to prepare a Remedial Action Plan (RAP). That plan, dated August 2003, was subsequently approved by the NYSDEC following some modification. (The final RAP was dated October 2003.) The NYSDEC formally accepted the RAP in a letter dated October 28, 2003. A copy of that letter is located in Appendix A. ERM implemented certain aspects of the RAP prior to LCS' involvement (LCS was retained on May 20, 2004, by Volunteers to monitor completion). Paragon Environmental Construction, Inc. (Paragon) completed the actual construction portion of the RAP under direct contract to Franklin Properties and 432 Franklin Properties, LLC.

Construction activities related to these components began in the spring of 2004 and were substantially completed by fall of 2004.

1.2 Purpose and Scope

The purpose of this report is to document the implementation of the approved remedy pursuant to the BCA and to document activities warranting the issuance of the Certificate of Completion for the subject property.

2.0 **REMEDIAL ACTION**

2.1 General

The basis for the remedial approach and design are presented in detail in the August 2003 RAP prepared by ERM which was accepted by NYSDEC. This section briefly describes the objectives and remedial measures implemented at the Site:

2.1.1 Objectives

- Eliminate the potential for direct human contact with the VOC-, SVOC- and lead-contaminated soil.
- Prevent the downward and off-Site migration of existing contamination.
- To control soil vapor, if any, from entering the on-Site structure through the building slab.

2.1.2 Summary of Work Completed

In an effort to prevent the potential for human contact with Site contaminants, approved soil excavation was completed prior to installation of clay, asphalt or concrete capping at the Site. As an added measure, a sub-slab depressurization system was installed beneath a permanent vapor barrier constructed of polyethylene and concrete on the interior portion of the structure, for future use if warranted.

3.0 SITE PREPARATION

Prior to initiation of remedial action, various tasks were completed. These tasks are summarized below.

3.1 Utility Clearance

Prior to commencement of field activities, publicly and privately owned utilities at the subject property were marked and identified. Utility clearance was performed by Paragon.

3.2 Mobilization

Heavy equipment and materials, as required for soil removal and grading activities were transported to the Site by Paragon.

3.3 Clearing/Grubbing

Prior to performing remedial work at the exterior AOCs, the subject property was cleared of vegetation (i.e., trees, brush, etc.) that would interfere will the installation process and compromise the integrity of the designed and approved cap systems.

4.0 **REMEDIAL ACTIONS IMPLEMENTED**

The following remedial work was completed at the subject property.

4.1 Soil Excavation SEAOC

In an effort to remove previously identified VOC-, SVOC- and lead-impacted soils within the historical UST area (SEAOC/See Figure 2), limited soil excavation was completed by Paragon with oversight by LCS on May 27, 2004.

A track-mounted excavator was used to excavate an area measuring approximately 15 feet by 12 feet by 8 feet in depth. Soil was excavated and staged on-Site and covered with polyethylene sheeting prior to characterization, loading and off-Site disposal by Paragon.

During excavation, the physical characteristics of all soil/fill samples were classified using the Unified Soil Classification System (USCS) (Visual-Manual Method). To determine when the excavation was complete, soils/fill material from the excavation was placed into sealable PVC bags and allowed to equilibrate to approximate ambient temperature. The container was opened slightly and the photoionization detector (PID) sample inlet probe was placed within the headspace of the container to allow for a reading of the VOCs within the headspace. The PID measurements were recorded in the project field book.

Visual and olfactory observations, combined with PID measurements, were used to monitor the excavated soils for impact. Generally, the excavation was continued vertically until groundwater was encountered and horizontally until either PID measurements were less than 5 parts per million (ppm) or until further excavation was no longer practical [due to structure integrity (West Wall)]. A total of 78.39 tons of soil was excavated. The extent of the excavation is represented on Figure 2.

The following summarizes the final PID measurements and observations within the excavation at the completion of excavation.

Sample Location	PID Measurement (ppm)	Observations
West Wall	363	Moderate gasoline-type odor. Excavation limited by structure.
East Wall	0.0	No suspect odors.
South Wall	0.0	No suspect odors.
North Wall	3.7	Slight unidentified petroleum-type odor.
Bottom	0.0	No suspect odors

ppm = parts per million

Once the excavation was deemed complete, samples of the soil/fill from each of the sidewalls and bottom were sampled using the excavator bucket. Soil samples collected for analysis, with the exception of those for VOCs, were homogenized. The homogenization was completed by removing the soil from the middle of the excavator bucket and transferring it to a stainless steel bowl and mixed to provide a more homogeneous sample to the laboratory. The soil was scraped from the sides, corners, and bottom of the clean surface, rolled to the middle, and thoroughly mixed until the material appeared homogenous. An aliquot of this mound was then transferred to the required sample containers, slightly tamped-down, filled to near the top of the container and sealed with the appropriate cap. Soil/fill on the threads of the container, if any, was removed using a clean paper towel prior to placing the cap on the sample container. Samples for VOCs were collected and transferred to sample containers immediately after collection. VOC soil samples were not mixed, but were placed directly from the excavator bucket and placed into the sample containers in a manner limiting headspace by compacting the soil into the container. Samples for VOC analysis were placed into the appropriate container prior to sample homogenization for the remaining analyses.

Following labeling of the laboratory-supplied sample containers, samples from each of the sidewalls and bottom of the excavation were placed on ice. The samples were then submitted, under standard chain-of-custody, to Severn Trent Laboratories, a New York State Department of Health (NYSDOH) approved laboratory, for analysis in accordance with United States Environmental Protection Agency (USEAP) SW-846 methods 8260, 8270 and 6010 VOCs, SVOCs and lead, respectively, in accordance with the RAP.

See Section 9.0 regarding disposal of impacted soils.

4.2 Sub-Concrete Slab Depressurization System and Vapor Barrier

To prevent any upward migration of soil vapors into the building space, a sub-slab depressurization system was installed above the existing concrete slab by ERM. The sub-slab depressurization system was constructed of a polyvinyl chloride (PVC) header system set within a gravel layer, covered with a 9 mil thick polyethylene sheeting installed below a new nominal four inch thick concrete slab. Concrete perforations were sealed using an elasto-meric material.

The Volunteers installed an electric powered blower to facilitate the removal of soil vapors, as a precautionary measure. Volunteers also installed permanent vacuum monitoring points throughout the on-Site structure to confirm that a negative pressure was being applied by the sub-slab depressurization system.

On June 29, 2004, LCS installed six vacuum monitoring points within the on-Site structure as feasible as a result of the presence of radiant heating coils within a portion of the new concrete slab. The approximate locations of the monitoring points were approved by the NYSDEC during a Site meeting on May 27, 2004. The locations of these monitoring points are identified on Figure 4.

Between June 2004 and May 2005, the installation of three additional blowers resulted in negative pressure measurements at the vacuum monitoring points satisfactory to regulatory authorities. Below is a summary of the negative pressure measurements obtained by LCS on May 12, 2005.

Monitoring Point	Pressure Measurement* (Pascals)
MP-1	-1
MP-2	-9
MP-3	-21
MP-4	-31
MP-5	-39
MP-6	-28
MP-7	-39
MP-8	-18
MP-9	-46

* Minneapolis Pressure and Fan Flow gauge – Model DC-3, calibrated April 10, 2003

Construction details of the sub-slab depressurization and vapor barrier system is located within ERM's Summary of Oversight Activities Report, dated December 2, 2004, located in Appendix B. Construction details for the monitoring points are located in Appendix C. Blower specifications are listed in Appendix D. Please refer to the attached ERM "Summary of Oversight Activities" report dated December 2, 2004, for additional construction details. Please note that subsequent to the issuance of ERM's summary report, three additional electric blowers were added to the sub-slab depressurization system.

The sub-slab depressurization system will be operated continually and periodically monitored by to insure proper operation. Refer to the OM&M plan for specific monitoring details.

5.0 SAMPLE HANDLING

QC field duplicate samples were submitted blind to the laboratory; a fictitious sample ID was created. The sample identifications (of the original sample and its field duplicate) were marked in the field book and on the copy of the chain-of-custody kept by the sampler and copied to the project manager. To the extent possible, sample containers were labeled in the field prior to the collection of samples. Affixed to each sampling container was a non-removable label on which the following information was recorded with permanent waterproof ink.

- Site name, location, and job number;
- Sample identification code;
- Date and time;
- Sampler's name;
- Preservative;
- Type of sample (e.g., soil); and,
- Requested analyses.

5.1 Sample, Bottles, Preservation and Holding Time

5.1.1 Sample Bottles

The selection of sample containers used to collect samples was based on the criteria of sample matrix, analytical method, potential contaminants of concern, reactivity of container material with the sample, QA/QC requirements and regulatory protocol requirements. All sample containers were certified clean as provided by the analytical laboratory.

5.1.2 Sample Preservation

Samples were preserved as detailed below.

Soil Samples

Analytical (all analyses) - cooled to 4 °C with ice; no chemical preservatives added.

5.1.3 Holding Times

Holding times were judged from the verified time of sample receipt (VTSR) by the laboratory; samples were hand delivered from the field to the lab no later than 24 hours from the time of sample collection. Holding time requirements were those specified in the NYSDEC Analytical Services Protocol (ASP) (June 2000); it should be noted that for some analyses, these holding times were more stringent than the holding time for the corresponding analytical method.

Although trip blanks were prepared in the analytical laboratory and shipped to the Site prior to the collection of environmental samples, for the purposes of determining holding time conformance, trip blanks were considered to have been generated on the same day as the environmental samples with which they are shipped and delivered. Procurement of bottles and blanks was scheduled to prevent trip blanks from being stored for excessive periods prior to their return to the laboratory.

5.2 Chain-of-Custody and Shipping

Once the sample containers were filled, they were immediately placed in the cooler with ice (in sealable plastic bags to prevent leaking) to maintain the samples at approximately 4°C. The chain of custody forms were signed and placed in a sealed plastic sealable bag in the cooler. The completed shipping container was closed for transport with shipping tape, and a paper seal was affixed to the lid. When the laboratory received the coolers, the custody seals were checked and lab personnel signed the chain-of-custody form and provided one copy to the Project Manager to verify receipt.

5.3 Quality Assurance Objectives

Data quality objectives (DQOs) for measurement data in terms of sensitivity and the PARCC parameters (precision, accuracy, representativeness, comparability, and completeness) were established so that the data collected would be sufficient and of adequate quality for their intended uses. Data collected and analyzed in conformance with the DQO process described in this document were used in assessing the uncertainty associated with decisions related to this Site.

5.4 Data Usability

A data usability summary was prepared by an independent validator. The DUSR report and comments by the testing laboratory in response to the DUSR are located in Appendix E.

5.5 Laboratory Quality Assurance

5.5.1 Method Blanks

Method blanks were analyzed by the laboratory to determine if laboratory contaminants had biased the sample results.

5.5.2 Laboratory Duplicates

Laboratory duplicates were performed on spiked samples as a Matrix Spike and a Matrix Spike Duplicate (MS/MSD) for volatile and semi-volatile organics, and as a matrix spike and matrix duplicate for inorganics.

5.5.3 Spiked Samples

Two types of spiked samples were prepared and analyzed as quality controls. Matrix Spikes and Matrix Spike Duplicates (MS/MSD) were analyzed to evaluate instrument and method performance and performance on samples of similar matrix. MS/MSD were analyzed for VOCs and SVOCs. In addition, matrix spike blanks (MSBs) were analyzed by the lab as part of the NYSDEC ASP.

6.0 DATA VALIDATION

Data was validated by Waste Stream Technologies, Inc. (WST), a NYSDEC-approved environmental laboratory. Data validation was performed by following guidelines established in the USEPA Region 2 SOP No. HW-6, "CLP Organics Data Review" (Revision No. 8, January 1992); and SOP No. HW-2, "Evaluation of Metals Data for the Contract Laboratory Program (CLP)" (based on SOW 3/90; January 1992). These documents are checklists that are designed to formally and rigorously assess the quality and completeness of CLP data packages. The use of these USEPA SOPs was adapted to conform to the specific requirements of the NYSDEC ASP (e.g., NYSDEC/ASP holding times, matrix spike blank requirements, etc.). Where necessary and appropriate, supplemental validation criteria were derived from the EPA Functional Guidelines (<u>USEPA Contract Laboratory Program National Functional Guidelines for Organic Data Review</u>, Publication 9240.1-05, EPA-540/R-94/012, February, 1993; and <u>USEPA Contract Laboratory Program National Functional Guidelines for Inorganic Data Review</u>, Publication 9240.1-05, February, 1994).

The validation report consists of text results of the review. Validation consisted of target and nontarget compounds with corresponding method blank data, spike and surrogate recoveries, sample data, and a final note of validation decision or qualification, along with any pertinent footnote references. Qualifiers applied to the data are documented in the report text.

6.1 Sample Results

Excavation confirmatory soil and quality assurance/quality control (QA/QC) sample results are located below. Only analytes detected are shown. Cleanup goals consisted of Recommended Soil Cleanup Objectives as set forth with the Technical and Administrative Guidance Memorandum (TAGM) 4046-94, where impacted soils were readily accessible proximate to the SEAOC.

Following receipt of the test results they were provided to the NYSDEC for review. Based on their review, no further work was required as the area was to be capped with asphalt and concrete. The entire analytical report is located in Appendix F. Maximum concentration of VOCs, SVOCs and metals detected on-site during ERM's studies are included within Appendix L.

Compound	Base	East Wall	North Wall	North Wall	South Wall	West Wall	West Wall	Duplicate	Duplicate	Regulatory
	Ry/Rrl	6v/6rd	6v/6rd	µg/kg	6v/6rl	Ry/Rrl	µg/kg	µg/kg	дс µg/kg	ug/kg
vinyl chloride	11>	<11	f 4	<57	<12	<110	<1,600	44	12 DJ	200
chloroethane	<11	<11	<12	<57	16	150	<1,600	16	<62	1,900
methylene chloride	22 B	19B	23 B	160 BD	<16	160 B	<1,600	19 B	99 BD	100
acetone	21 B	3BJ	20 B	26 BDJ	<12	<110	<1,600	9 BJ	15 BDJ	200
1,1-dichloroethene	<11	<11	<12	<57	<12	<110	<1,600	2J	<62	400
1,1-dichloroethane	<11	<11	18	6 DJ	<12	520	<1,600	72	52 DJ	NA
2-butanone	4 J	<11	270 E	250 D	<12	<110	<1,600	24	33 DJ	300
1,1,1-trichloroethane	<11	۶ ا	20	<57	5 J	5,200 E	770 DJ	87	56 DJ	800
trichloroethene	<11	15	120	77 D	5 J	620	1,000 DJ	180	230 D	200
1,1,2-trichloroethane	<11	<11	<12	<57	<12	<110	<1,600	2 J	<62	NA
tetrachloroethene	<11	<11	<12	<57	<12	26 J	<1,600	<11	<62	1,400
toluene	<11	<11	<12	<57	<12	22 J	<1,600	<11	<62	1,500
ethylbenzene	<11	<11	<12	<57	<12	83 J	<1,600	<11	<62	5,500
xylenes	<11	<11	<12	<57	<12	2,900	<1,600	<11	<62	1,200
cis-1,2-dichloroethene	<11	ل 1	130	81 D	<12	440	<1,600	380 E	400 D	NA
trans-1,2-dichloroethene	<11	<11	2 J	<57	<12	<110	<1,600	6 J	<62	300
methylcyclohexane	11>	<11	٢٤	<i>L</i> 3>	<12	<110	180 DJ	<11	<62	NA
isopropylbenzene	11>	<11	<12	<i>L</i> 3>	<12	۲94 ک	<1,600	<11	<62	NA
TICs	26 BJN	10 BJN	290 J	0	17 BJN	22,210 J	35,000 J	10 BJN	50 BJN	10,000*

VOC Analysis by SW-846 Method 8260

ug/kg = micrograms per kilogram

J = Indicates an estimated value

B = This analyte was also detected within the laboratory's method blank and may be the result of laboratory contamination.

E = Identifies compounds whose concentrations exceed the calibration range of the instrument for that specific analysis.

< = Analyte was not detected at or above the method detection limit listed

= Analyte detected above Regulatory Criteria


* = Total VOCs must be less than or equal to 10,000 ug/kg


D = Analysis performed at a dilution

N = Indicates presumptive evidence of a compound.

{H0579010.1}

10





SVOC Analysis by SW-846 Method 8270							
Compound	Base μg/kg	East Wall µg/kg	North Wall μg/kg	South Wall µg/kg	West Wall μg/kg	Duplicate 1 μg/kg	Regulatory Criteria ug/kg
4-methyl phenol	<360	<1,900	<3,900	<380	<4,300	57 J	100 or MDL
naphthalene	28 J	76 J	<3,900	15 J	140 J	55 J	13,000
2-methylnaphthalene	12 J	<1,900	<3,900	<380	130 J	<2,000	36,400
acenaphthylene	31 J	58 J	<3,900	<380	<4,300	<2,000	50,000*
acenaphthene	19 J	87 J	<3,900	30 J	130 J	110 J	50,000*
dibenzofuran	28 J	74 J	<3,900	15 J	<4,300	73 J	6,200
fluorene	43 J	82 J	<3,900	22 J	150 J	140 J	50,000*
phenanthrene	340 J	1,400 J	400 J	320 J	1,500 J	1,800 J	50,000*
anthracene	95 J	330 J	<3,900	92 J	320 J	460 J	50,000*
carbazole	15 J	72 J	<3,900	33 J	160 J	63 J	NA
fluoranthene	490	2,400	600 J	570	1,800 J	<2,600	50,000*
pyrene	460	2,300	530 J	490	1,500 J	<2,000	50,000*
butyl benzyl phthalate	<360	1,900	<3,900	12 J	<4,300	<2,000	50,000*
benzo(a)anthracene	310 J	1,500 J	360 J	510	1,100 J	1,400 J	224 or MDL
chrysene	290 J	1,500 J	350 J	460	1,000 J	1,300 J	400
bis(2-ethylhexyl)phthalate	<360	<1,900	110 J	14 J	<4,300	200 J	50,000*
benzo(b)fluoranthene	220 J	1,300 J	320 J	620	1,100 J	1,200 J	220 or MDL
benzo(k)fluoranthene	200 J	1,200 J	330 J	440	790 J	1,200 J	220 or MDL
benzo(a)pyrene	280 J	1,800 J	410 J	740	1,100 J	1,300 J	61 or MDL
indeno(1,2,3-cd)pyrene	170 J	1,100 J	250 J	380	530 J	480 J	3,200
dibenzo(a,h)anthracene	80 J	470 J	<3,900	180 J	230 J	210 J	14 or MDL
benzo(ghi)perylene	170 J	1,200 J	260 J	360 J	500 J	460 J	50,000*
TICs	1,499 JN	1,850 J	13,500 J	1,323 J	970 J	1,421 JN	500,000**

SVOC Analysis by SW-846 Method 8270

ug/kg = micrograms per kilogram

J = Indicates an estimated value

N = Indicates presumptive evidence of a compound.

< = Analyte was not detected at or above the method detection limit listed

* = Individual SVOCs must be less than 50,000 ug/kg

** = Total SVOCs must be list than 500,000 ug/kg

= Analyte detected above Regulatory Criteria

LEAD Analysis by SW-846 Method 6010

Compound	Base mg/kg	East Wall mg/kg	North Wall mg/kg	South Wall mg/kg	West Wall mg/kg	Duplicate 1 mg/kg	Regulatory Criteria ug/kg
Lead	27.5	420	124	28.2	156	122	500*

mg/kg = micrograms per kilogram

* = Average concentrations in metropolitan or suburban areas or near highways typically range up to 500 ppm

7.0 SITE CAPPING

To eliminate the potential for direct human contact with the VOC-, SVOC- and lead-contaminated soil and to prevent the downward and off-Site migration of existing contaminants into the currently uncontaminated soils, a clay, concrete or asphalt cap was installed on-Site consistent with approved remedy. This work was initiated in late June 2004 and substantially completed in July 2004.

7.1 Barrier Layer Construction

Barrier material was brought on-Site by dump truck and/or cement truck. The clay cap material was obtained from Jack Brown and Sons, a NYSDEC acceptable barrier soil source located in West Monroe, New York.

Material testing was performed ahead of the construction to verify the suitability of the borrow pit soils for barrier layer construction. The testing indicated that the clay cap material had an average hydraulic conductivity of 1.1×10^{-8} cm/sec. The laboratory report is located in Appendix G.

The barrier soil material was either stockpiled for later use or spread as it was brought on-Site. Barrier material was placed in approximately 8-inch lifts. Following placement, the material was compacted. The final cap thickness measured at least 6 inches in thickness. No compaction testing was required by the RAP or completed.

7.1.1 Warning Barrier

Orange construction fencing was installed on top of the clay barrier as a warning indicator prior to application of topsoil as discussed below. This would prevent future accidental excavation into the clay cap.

7.1.2 Topsoil Placement

Topsoil was brought on-Site by dump truck and spread over the orange warning barrier and clay cap. Topsoil used for this project originated from an off-Site source.

7.1.3 Seeding and Planting

Seeding was initiated following placing of the topsoil. Seed was spread on all areas of the subject property where topsoil was placed, as well as perimeter areas disturbed by remedial construction activities.

Refer to Figure 3 for identification of clay-capped areas.

7.1.4 Barrier Layer Construction – Asphalt and Concrete

Asphalt and concrete were applied to all exterior areas not caped with clay. Approximately 12 inches of imported gravel fill material was placed and compacted on the areas to be paved with asphalt. Following compaction of the gravel base a 3 inch thick layer of New York State Department of Transportation (NYSDOT) Type 3 Asphalt Binder Coarse was installed. A NYSDOT Type 1 Asphalt Top Coarse was installed above the Binder Coarse.

In areas not covered by asphalt or clay capping, a concrete cap was installed. Generally, the cap consisted of a minimum four inch thick layer of concrete with a tensile strength of 4,000 pound per square inch (PSI) concrete.

Refer to Figure 3 for identification of asphalt and concrete capped areas.

8.0 STORMWATER RUNOFF CONTROL

New storm water interceptors were installed within the parking lot areas in 2004. It is LCS' understanding that the storm water is collected and discharged directly to the City of Syracuse storm water sewer system. Refer to Figure 3 for locations of the storm water interceptors.

9.0 **DISPOSAL**

Trees, brush and other general debris cleared from the subject property were disposed of by Paragon as general debris. Soils generated (78.39 tons) from the SEAOC were characterized in accordance with the requirements of the City of Auburn landfill, a Part 360, Subtitle D Solid Waste Landfill. The soil was disposed of at the City of Auburn landfill. Waste Characterization analytical testing is located in Appendix H. Disposal documentation is included within Appendix I.

10.0 GROUNDWATER MONITORING

Two monitoring wells were installed on the down-gradient side of the subject property on September 12, 2005, as requested by the NYSDEC. These wells replaced wells destroyed during Site redevelopment. These wells were installed by Parrat-Wolf, Inc. Refer to Figure 3 for monitoring well locations. Both monitoring wells were constructed using two inch-diameter Schedule 40 PVC screen and riser. Screens measuring 10 feet were installed at both locations. The well screen and attached riser were placed approximately 6 inches above the bottom of the borehole (between 14 and 15.5 ft. bgs) and backfilled with No. 1 silica sand. A bentonite chip seal approximately 1.5 feet thick was placed at the surface and hydrated at each monitoring well. Each monitoring well was then fitted with a lockable j-plug and an 8 inch diameter steel man way installed in a concrete pad to complete installation. Well construction diagrams are located in Appendix J.

The initial groundwater monitoring report is located in Appendix M.

11.0 COMMUNITY AIR MONITORING

Air monitoring was required under the RAP during excavation activities. LCS personnel performed community air monitoring of airborne particulates, and organic vapors daily with the use of two MIE Personal DataRAM MiniRae 2000 instruments, respectively. No exceedances of action levels were observed during construction activities. In addition, no visible dust was observed leaving the working area during the excavation work. LCS is not aware of any complaints from neighboring residents during construction activities. Community air monitoring results are presented in Appendix K.

12.0 OPERATION, MAINTENANCE AND MONITORING PLAN

The Operation, Maintenance and Monitoring Plan is being submitted simultaneously under separate cover.

CERTIFICATION STATEMENT

I certify that the Remedial Work Plan was implemented and that all construction activities were completed in substantial conformance with the Department-approved Remedial Work Plan.

Dated: 12/7/06



Jobs al

Report Preparer

hel, PE Peter McKee, P.E.

New York State Professional Engineer

FIGURES







Figure 1- Site Location Map 432 Franklin Street Syracuse, New York



APPENDIX A

New York State Department of Environmental Conservation Division of Environmental Remediation, Region 7

615 Erie Boulevard West, Syracuse, New York 13204-2400 Phone: (315) 426-7519 • FAX: (315) 426-7499 Website: www.dec.state.ny.us



October 28, 2003

Mr. Douglas Sutherland Franklin Properties, LLC 221 West Division Street Syracuse, New York 13204

Re: Remedial Action Work Plan 432 North Franklin Street, Syracuse, NY VCP #V005887

Dear Mr. Sutherland:

The New York State Department of Environmental Conservation and the New York State Department of Health have reviewed the 2003 Remedial Action Work Plan and addendums of October 6, 9, 15, & 28 as well as the revised HASP dated September 2003 and received by the Department October 20, 2003 and the subsequent revision dated October 24, 2003. Upon our review we find the proposed work plan to be protective of human health and the environment and approve of its implementation.

Please contact me at your convenience to schedule Department observation of the field work. It has been a pleasure to work with you and I am looking forward to the successful completion of this project.

Sincerely,

Carh

Carl S. Cuipylo – Engineering Geologist

cc: Gary Litwin Mary Jane Peachy David Smith Maura Desmond Doreen Simmons Ed Hinchey APPENDIX B

Environmental Resources Management

5788 Widewaters Parkway Dewitt, NY 13214 (315) 445-2554 (315) 445-2543 (fax)

2 December 2004

Mr. Doug Sutherland Vice President Franklin Properties, Inc. 221 West Division Street Syracuse, NY 13204

RE: Summary of Oversight Activities Franklin Properties, Inc. 432 North Franklin Street VCP Agreement: B7-0615-02-06 ERM Project No. 0001298

Dear Mr. Sutherland:

As requested, Environmental Resources Management (ERM) has prepared a summary of oversight activities at the Franklin Square property during construction activities in March and April 2004. The property is located at 432 North Franklin Street (Attachment A; Figure 1) in the Franklin Square section of the city of Syracuse, New York. This report contains a chronological summary of ERM's oversight activity and onsite inspection services.

Beginning in February 2004, ERM worked closely with Franklin Properties as they developed construction schedules and began building demolition and site work. During this time ERM met with Franklin Properties project mangers regularly to discuss construction schedules, waste management issues, provide information regarding known site conditions, and to assist with the final development of remedial construction material specifications. ERM also visited the site to monitor activities.

In April 2004, ERM provided oversight and inspection of the installation of the sub-slab ventilation system in the main building at the property. A chronological summary of ERM's activity is presented in Table 1 below. Field notes from each site visit are located in Attachment B of this letter.



Mr. Doug Sutherland ERM Project No.: 0001298 2 December 2004 Page - 2

· |

Table 1Summary of ERM Site Activity

Date	Activity	Problems Encountered
12 April 2004	Met with Franklin onsite managers and inspected ongoing sub-slab ventilation system installation activities. Activities included, grading, vent-pipe trench excavation and pipe installation.	None
13 April 2004	Met with Franklin onsite managers and inspected ongoing sub-slab ventilation system installation. Ongoing activities included completion of vent-pipe installation and compaction of sub-base.	None
15 April 2004	Met with Franklin onsite managers and inspected ongoing sub-slab ventilation system installation activities. Activities included, emplacement and sealing of the vapor barrier and the pouring of the concrete floor in the southern section of the main Building.	None
19 April 2004	Met with Franklin onsite managers to setup air-monitoring program and calibrated equipment.	None
20 April 2004	Met with Franklin onsite managers and discussed staging, sampling and disposal of soil from the Southeast Area of Concern (SEOC); discussed location and installation methodology of sub-slab sampling points; collected background air monitoring data and inspected the excavation of pipes along the north wall of the East Wing.	None

ERM conducted onsite inspection of the sub-slab depressurization system installation. It is ERM's technical opinion that the sub-slab system in the Main Building was installed according to design specifications. Photographic documentation of the installation of the sub-slab venting system and the emplacement of the 9-mil vapor barrier are attached to this report (Attachment C). Franklin onsite managers agreed to collect "as built" measurements and "mark-up" a site drawing for ERM to use in its Mr. Doug Sutherland ERM Project No.: 0001298 2 December 2004 Page - 3

Environmental Resources Management

final report. While onsite, ERM confirmed the appropriate distribution of the sub-slab venting system as shown in Figure 2 (Attachment A).

ERM also conducted the background air-monitoring program on 20 April 2004 prior to the beginning of soil excavation activities at the SEAOC. Mr. Dave Myers calibrated the equipment on 19 April 2004 and visited the site and installed digital data loggers at upgradient and downgradient locations. The data from the background air-monitoring sampling event are located in Attachment D of this report.

Please call me if you have any questions or comments.

Sincerely,

Edward Hinchey, P.G. Partner In Charge

C: Dave Myers – ERM


ATTACHMENTS


J

J

G:\doc\cli\Franklin\corresp\D_Sutherland 18 Feb 2003.doc

ATTACHMENT A (Site Figures)





ATTACHEMNT B (Field Notes)

Daily Project Activity Form

			1			
Client:	Franklin Associates		4-12-04			
Project Name:	The Foundry	ERM Project Number:	00012 9 8			
ATTACHED TO THE Chain of Custo Shipping Mani	dy Field Sampling Re fest Equipment Charg	e 🗌 Injury Report	ERM			
Significant Work Accomplished Today						
→ Inspected Pipe inst Fittings; → MEASURED Within Assured Cimension -> We disco TO DEAD H Rich age	Ch Nupierkowshi Crushed Stone Fill, AULATION; CHECKED F PRESENCE OF FILTER Approximate Location 10' of As specifier ENU that Frankli IS AND PROVIDE MAR SSED ADDING A SEC EAD in A WALL For red to PLACE IN WA	VENT PIPE TRENCGING DR PEN-GRAVEL, TIGU WRAP DE MAN, FOLD AND LA D IN BRAWING; RI NO WILL CONECT "P MED UP DRAWING MD G. INCH VENTICLE Potential Exture Syste II @ North End.	And VENT TNESS OF ALL tennes: ALL ch AN Ron 15 built " = Through Floor			
-v practug ruge	Upcoming Activity		Expected Completion Date			
-D Site Me	reting to kickoff a	SOIL EXCANAtion	4-13-04			

F F F F F F F F F F F F F F F F F F F	
-D SHART SILL EXCAULTION	4-14-04

Personnel	Description of Activity	Hours
E. Hinchey	Site inspection - work GONDINAtion	2.0
	1	

Client:	Franklin Associates	Activity Date:	
Project Name:	The Foundry	ERM Project Number:	0001248

Problems Encountered	Description of Solution	
Nome		

Additional Comments EH determines that Concerte SubFLOOP WAS NOT PRESERE -> WASHED AS RECOMMENDED by ERM -D THE FINAL FLOOR PLAN HAS been determined; the boiler ROOM AND OLD SCALE FOOM, AS WELL AS EAST WING WILL REMAIN IN PLACE AND UNDER ROOF; ERM to Discuss NEED For the Sub-SLAB collection System below FINISHED GRADE ERM to VERIFY HOW WE WANT THE Rich Askens -P VAPOR BARFIER SEALED - EA to Check w) EngiNEER NOTED TWO AREAS WHERE VENT Pipe WORLD NOT - D LAY DOWN FLAT because TRENCHING DID NOT L'INÉ UP N/ VENT PIPE AND FITTINGS; Rich to MAKE SURE CORRECTED AND PEA GRAVEL is PLACED UNDER VENT PIPE where UNDER GRAVER is UNEVEN.

Attach additional pages as necessary and fax to Mr. Doug Sutherland (315) 471-8028 copy to file.

incheta on North Side at Blog. to USE £ Mer surent 4 - 32°5 WELED W the Part #1 Provide PARMER itis week Designer 126 al ic Dimensions of ALL 12 The Event we can pour 878 EVIDENT RX RX 20:173 6-inch DELIDE Rich Ano Ron will P Pipe the Sistem is L L ナるの J. - EH TOOK Same 602 No No Inspected Acc WAn73 South Due I aza Pipe - Vent pipe 55 <u>р</u> TightNESS CLOSHER Server -Soft Dischang Receive BR Buict Lent SiDE 10 Nov Kon ξ キース 71: 35 ١ 1 1 ١ 1 Þ 2 ĉ t 10 . 7 ٦ 1

1: a / m - win start site work @ Am or thous Dan-works to meet to discoss Excertation @ Fruner Casaline this APEAN AS Builds" of the Venting Sy Stem - RicH AND Rol agreed to provide Same to ME. Rear Son EAST SIDE HAVE REEN SAVED AND WILL DE Re-USED; ELW A REC. Sub-SLAB VENTICATIMIN م م A Site Meethos on tues A: let at at giron × 17- × Ŧ fur - son - 73 PUAGE the Access - lüch whitz <u>.</u> Vert , do ; ; しって l 1 pumbing PONETIMI in NUCTIPLE VIO RHH FROST but s. ろに SIDE All MEASUREMENTS to BRICK 22 0 102 ", 4" Ø Q D Ē A ROOK W うち D Ò Û Ó 40-04 1 * t

10 90 ろう NoT N 3 -the - orcost - do'F ERM to Do er. @ eite nan - Kaz - ano r Z t 24 l m/6 ł Ş g 212 ł ١ ì) -0051 l At 0 wing. Sale Phase -ERT 2-inch Pilles (?) 1 3-5664 N,

Daily Project Activity Form

,

Client:	Franklin Associates	Activity Date:	4-13-04
Project Name:	The Foundry	ERM Project Number:	
ATTACHED TO THI Chain of Custo Shipping Mani Site Photograp	dy 📄 Field Sampling Re fest 🕅 Equipment Charg	e 🗌 Injury Repor	t ERM
		Accomplished Today	
-> met w	Rich, RON (MCK/FRA STANDISH to SET-UP D FINISHED Compace GRAVEL BACKFILL	nklin) And PARAG	n Representative
CRAig	STANDISH to SET-UK	O Soil ExCAUATION	ProgRAM
-> inspecte	D FINISHED Compac	teo subbase and	VENT TRENchES
w Pea	GRAVEL BACKFILL	IN-PLACE	
			им и тип, у лагинан - чаланын алардаган сэрэгийн төрө илтон болоон байсан болоон алар
			E (10 14
	Upcoming Activity		Expected Completion Date
Inspection a	OF VADOR BARNier 11	U PLACE AND	I
SEALED	prior to Emplaren	nent of Concrete	4-15-04
· ERM to Cr	nout ALL SOIL EXCL	watin pre-	
Construction	OF VAPOR BARRier , A prior to Emplacen nouct ALL Soil EXCH AND SOIL MANAGEN	NENT Activity 4	1.14 -₽ 4-20
	1	1	
·····			

Personnel	Description of Activity	Hours
E. Hinchey	MEETings a PEC; VENT Inspection	2.0
1		

Client:	Franklin Associates	Activity Date:	4-13-04
Project Name:	The Foundry	ERM Project Number:	0001298

Problems Encountered	Description of Solution
Nove	

Additional Comments
-> PEC HAD NOT REVIEWED THE WORKPLAN, DID NOT PREPARE
A HEALTH AND SAFETY PLAN AND HAD MADE NO ARRANGEMENT
FOR EQUIPMENT NEEDS, Soil MANAGEMENT AND DisposAL
OR GrouND WATER MANAGEMENT, iF ENCOUNTERED
- ERM INFORMED PEC that They ARE REsponsible For
THEIR OWN HES; ERM PREPARED A HASP IN THE
WORKPLAN which they CAN GET FROM FRANKLIN; Rich
SAID HE WOULD PROVIDE it.
- RICH AND PEC REQUESTED THAT ERM MARK the
AREA to be EXCAUATED; DIRECT EXCAVATION; CONECT
ConFIRMATION SAMPLES; CONDUCT PERIMETER DUST
Monitoring AS WELL AS WORK JONE VAPOR Monitoring;
Arrange FOR WASTE testing, MANAgeMENT AND Disposal;
Collect ChAracterization SAMPLES; REVIEW RELEVANT DATA
AND GET DISPOSAL Approvals.
IOCATION: <u>Squacuse</u> Foundry ACTIVITY: <u>Site Meeting inpetim</u> FILED BY: <u>FD HINCHEY</u> SIGNATURE: Show A H
LOCATION: Saturde Foundary ACTIVITY: SITE TO REATING TREETING
FILED BY: <u>FU HANCHEA</u> SIGNATURE: March Han

10 90 かって 3 Fen 15 7.90F 4 8 7 1400 er. @ att nach Ner R K 22 - orleast ERM 3 ١ (۱ í 1 1 2 б cl. ١ i) ι 「「「「「いい」をきまたいいい」 Ant তা SCALE Room 5 -Bhaz-ERT 2-inch Pilles (?) 1 1 3-540 0

Э Ž 3 uti-- Cellert Characterization F ۲ ۱ $\widetilde{\ll}$ 5.4 , K j ٤ رب ت ١ Ì ١ 1 N ĩ 1435 530. -ntdel/ Compassion Prom 0 Scale 1 . . wing RAT 30

A ROOM

Client:	Franklin Associates	Activity Date:	15 APRIL 2004
Project Name:	The Foundry	ERM Project Number:	0001298
TTACHED TO TH Chain of Custo Shipping Mani	ody 🔄 Field Sampling Re		
Site Photograp	hs Inspection Report	Site Drawing	s
	Significant Work	Accomplished Today	
-D INSDER	TED VADOR BAT	IER AT MAINE	Buiching
South	tED VAPOR BAR h SiDE; ALL J AS Specified APPED AND AN PORIMETER EXAN	Dints were Fo	WED AND
PAPED	As specified	: ALL PENETRAT	ions were
OVERO	ADDED AND AN	OVERLAD EXTEND.	ED BEHIND
the	Perimeter EXAN	sion Joint.	มะ และ การเป็น สามารถ สามาร์ ก็ได้ของสามารถมายี่สุดที่สุด รู้และ รัฐมายายางสามารถการสามารถมายสามารถมาย สามารถมาย
		na formanna a na ann an t-Carn Thuncos an ann a' Marranna, a a na haonn ann an Anna ann ann ann ann ann ann a	
			· · · · · · · · · · · · · · · · · · ·
	Upcoming Activity		Expected Completion Date
EXCAVAtio	MIN SEAOC - QUENTED to man	ELM HAS	
been Re	QUESTED to MAN	MAGE Soil	
AND Di	RECT EXCAUAtion	contrate top -	

A WAifing Authonization From Franklin 4-20-04

Personnel **Description of Activity** Hours E. Hinchey VAPIK BARKIER Inspection 0.5


1

Client:	Franklin Associates	Activity Date:	4-15-04
Project Name:	The Foundry	ERM Project Number:	0001298

Problems Encountered	Description of Solution
ERM LEANED THAT THERE WILL BE HEAT LOOPS IN NORTHEAD OF BUILDING: This	Points Duking construction
North END OF Building: this will interer w/ system monitoring	
	•

	Additional Comments						
ELM	OB SERVED	that	the Ra)m 5	on the	e Ast	
5:DE	Will	BE F	ENISHED	AS	interio	R JOACE	ē j
These	Foons	w:11	NEED to	be e	evaluatED	FOR	
Vapor	L INTRU 3	im.					
	99 () 109 (ar) which the set of t			
	ny Manangan a ang di Malangan Lapangan ya a parta sa ang di kata tang Tanana nang di Ma						
					1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -		

		n Jähning mendelen einer oppetigen men einders beide fra Jahnen op som eindersamt.	994 - 1949 - 1949 - 1949 - 1949 - 1970 - 1970 - 1970 - 1970 - 1970 - 197	51 - 46 5 - 14 4 60 - 16 4 6 6 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 			
		e form of the constants for the means of permitting or constants performed by the set					
1991 V 197 Mid Markel V D Faar and an one of a sign of the statement in a		*****					
and takes all a land on the pile of a pile of a state of							
LOCATION:	Forendrum /	/ Sylacose	- ACTIVITY:_	Site	insportion		
FILED BY: Z	E. Hinch	EY	SIGNATUR	E: <u>SO</u>		·	



of a little decay

Client:	Franklin Associates	Activity Date:	19 April 2004	
Project Name:	The Foundry	ERM Project Number:	0 001298 00/6749	
ATTACHED TO THI Chain of Custo Shipping Mani Site Photograpi	dy 📄 Field Sampling Re fest 🗌 Equipment Charg	e 🗌 Injury Report	ERM	
	Significant Work A	Accomplished Today		
o btain	(Calibrated, set up on toring instruments - ed pertinent data from useage.	PDR 2450 PDR 2450 2652 2648 2646 Deta Base Report fo	d) air r field	
	Upcoming Activity		Expected Completion	

1999 - Marine M. M. Handalahan and an analysis and paramy gaptimeters (see a) for a descent and an advantiability (data and		
Personnel	Description of Activity	Hou

David W. Myers	As noted above	2.5

Client:	Franklin Associates	Activity Date:	19 April 2004
Project Name:	The Foundry	ERM Project Number:	

Problems Encountered	Description of Solution
~ /A	

Additional Comments
Preparation for 20 April 2004 Site Usit to perform background sampling.
DEATION: <u>Syracuse office</u> ACTIVITY: <u>Engineering Compliance - Franklin BCA</u> LED BY: <u>David W. Myers</u> SIGNATURE: <u>David W. Myers</u>

Activity Date: Franklin Associates 20 Client: 2004 Project Name: ERM Project Number: 0001298 The Foundry 0016749 ATTACHED TO THIS REPORT: Chain of Custody Field Sampling Reports Subcontractor Invoice Equipment Charge Shipping Manifest Injury Report FR Site Photographs Inspection Report Site Drawings Significant Work Accomplished Today background air monitoring for Commun Performed with_ His Monitoring Program associated Franklin BCP. SE AOC . 2) area "lead" affect soil Discussed staging sempling + disposed of 31 SEAOC with Row. Discussed installing of sub-slab monitoring points with Ron. eckground into - two log/graphs attached. PDR 5 ation of pipes along NE conver of East win 6 **Expected Completion Upcoming Activity** Date SEAOC by Perigon 13 April 2004 Excavation of


Personnel	Description of Activity	Hours
David W. Myers	1, 2, 3, 4 and 5 above	5.5
David W. Myers Ed Hinchey	3,4, and 6 above	2.0

Page	-	2
------	---	---

Client:	Franklin Associates	Activity Date:	20 April 2004
Project Name:	The Foundry	ERM Project Number:	0001298- 00 16 749

Problems Encountered	Description of Solution
N/A	

Additional Comments
EH submitted map to Rich N. of NE drainage feature.
Field work by Paragon to be scheduled by Rich N. who will provide proper notice to Dave myers
LOCATION: <u>Site</u> ACTIVITY: <u>Engineering Compliquee - Franklin</u> BCP FILED BY: <u>David W. Myers</u> SIGNATURE: <u>Wand W. Myer</u>



ad hot a DDR 2650 1 2648 function properly Dully Reports their Law wade 2695 Dum contacts Pine End and 2052 shids off 12652 2646 reverses schedude 400 2652+ 3646 did wet Yew to the 0) \$0/ET/\$ Kutz off PDR PDR wachives and a Dum @ office and Puts off 10R schedules rentral on Lats APOR 22 0 よう KNOW CHASN Keparts completed 4/19 + 4/20/04 DWN 100 Higher Van Cr Kust Ne.Schedelled ~ Dwm demolog PDK MONNALS Thursday. - 4 (hursday Durn Deven Duck 1,4,4,4 Dewonn ADR 1530 240 1500 1.253 1350 1400 440 1410 1420 1420 Dwm redured to site and photographs on windows it 1 25' Not wark area. INE for The places Durn callenter PDR 2653 and places along fence the @ NE partien of request for use backhoe to (Excasetion contraction) ERM will Sample for Waste Classification and Dum uses orange marking paint and parties 12' × 12' area of provide + have on-site for targon NE CORNEC all PDR monitors at their lengthours 30 yd rolloff with Row. Row will excavated sail in a clouble lived abourdened facility. Dum calibrates PDR 2646 and accounte tac proper dispessel excavethon in the SE paci Dwm + EH discuss staging connected to adjacent hydrawd EH + DWM dende site (Ew)investigate pipe along Excavetion detail that of the East Wing (15 工 1045 0940 09.50 1030 0/2/ 1315 1000

ATTACHMNET C (Site Photographs)

Project Name:	432 Franklin Square	Client Name:	Franklin Properties
Project No.:	HU401.00	Site Name:	The Foundry
Prepared By:	ЕЛН	Date:	12 April 2004



NOTES View looking North where main section enters the Three Story Building



NOTES

View looking west along of two laterals at south end of the Main Building

C:\std.frm\ins\dig_photo PAGE - 1 of _____

Project Name:	432 Franklin Square
Project No .:	HU401.00
Prepared By:	ЕЈН

Client Name:	Franklin Properties
Site Name:	The Foundry
Date:	12 April 2004



view 0.	t pea-gra	vel bene	ath vent	




Typical joint	 	
I ypical joint		

C:\std.frm\ins\dig_photo PAGE - 2 of _____

Project Name:	432 Franklin Square
Project No.:	HU401.00
Prepared By:	ЕЛН

Franklin Properties
The Foundry
12 April 2004



NOTES

View looking north along the axis of h Main Building; Main section and	e
laterals in view	




Close	up of joint	 	*********
	up of joint		

Project Name:	432 Franklin Square	Client Name:	Franklin Properties	
Project No.:	HU401.00	Site Name:	The Foundry	
Prepared By:	ЕЛН	Date:	13 April 2004	



NOTES

View looking west at south end of Main Building. Photo shows that the backfilling with pea-gravel is complete.




C:\std.frm\ins\dig_photo PAGE - 1 of _____

Project Name:	432 Franklin Square	Client Name:	Franklin Properties
Project No.:	HU401.00	Site Name:	The Foundry
Prepared By:	ЕЈН	Date:	13 April 2004



NOTES

View looking north along long axis of Main Building showing the backfill with pea-gravel.



NOTES Typical floor penetration prior to emplacement of vapor barrier

C:\std.frm\ins\dig_photo PAGE - 2 of _____

Project Name:	432 Franklin Square
Project No.:	HU401.00
Prepared By:	EJH

Client Name:	Franklin Properties	
--------------	---------------------	--


Site Name: The Foundry

Date: 15 April 2004



NOTES

View looking southwest; vapor barrier complete with adequate overlap at penetrations




NOTES

Vapor barrier complete and ready for installation of concrete; plywood decking was placed on top of vapor barrier to protect it from traffic during work.

> C:\std.frm\ins\dig_photo PAGE - 1 of _____


Project Name:	432 Franklin Square
Project No.:	HU401.00
Prepared By:	ЕЈН

Franklin Properties
The Foundry
15 April 2004



NOTES

Close-up of typical overlap and vapor barrier seam. All seams were triple folded and sealed with tape.



NOTES
Close-up of overlap at structural penetrations

ATTACHMENT D (Air-monitoring Data)

1

.

