PHASE I ENVIRONMENTAL SITE ASSESSMENT

The Kirstein Building 242 Andrews Street & 37 Bittner Street Rochester, New York 14604

PREPARED FOR:

H.V.C., LLC

&

CHAMBERLAIN D'AMANDA OPPENHEIMER AND GREENFIELD

Se

KNAUF SHAW LLP



PREPARED BY: PASSERO ASSOCIATES 100 LIBERTY POLE WAY ROCHESTER, NY 14604

March 14, 2005

P.N. 25030.02

TABLE OF CONTENTS

1.0 EXECUTIVE SUMMARY

- 1.1 Report Findings
- 1.2 Conclusions
- 1.3 Recommendations
- 2.0 PURPOSE
- 3.0 SCOPE OF WORK

4.0 USER PROVIDED INFORMATION

- 4.1 Owner Interview
- 4.2 Environmental Liens/Valuation Reductions
- 4.3 Reason for Performing Phase I Investigation
- 4.4 Day Environmental Phase II Work
- 4.5 Atlantic Testing "Asbestos Management Plan"

5.0 SUBJECT PROPERTY/VICINITY DESCRIPTION

- 5.1 Site Reconnaissance
- 5.2 Adjacent Parcels
- 5.3 Subject Site Photographs

6.0 HISTORY AND USE

- 6.1 City Records
- 6.2 Historic Aerial Photographs
- 6.3 Historical Maps
- 6.4 Polk Directories

7.0 REGULATORY INFORMATION

- 8.0 RADON
- 9.0 RECOMMENDATIONS/CONCLUSIONS
- **10.0 DISCLAIMER**
- **11.0 LIMITATION OF LIABILITY**

TABLE OF CONTENTS (Cont'd)

12.0 APPENDIX

- 12.1 Tax Map
- 12.2 Environmental Questionnaire
- 12.3 ETC January 2000 Phase I Update
- 12.4 Atlantic Testing Laboratories, Asbestos Management Plan
- 12.5 Day Environmental Phase II Reports
- 12.6 1950 Sanborn Fire Insurance Maps
- 12.7 EDR Radius Map Report
- 12.8 Radon
- 12.9 Personnel Qualifications

1.0 EXECUTIVE SUMMARY

Passero Associates performed this Phase I Environmental Site Assessment in conformance with ASTM E 1527-00 for the benefit of H.V.C., LLC; Chamberlain D-Amanda Oppenheimer and Greenfield; and Knauf Shaw LLP. Assignment of this document can be made only with the written permission of Passero Associates.

SUBJECT PROPERTY:

The Kirstein Building 242 Andrews Street / 37 Bittner Street Rochester, New York 14604

1.1 REPORT FINDINGS

The subject site is comprised of 2 contiguous parcels totaling approximately 0.7acre in size, located on the northwest corner of Andrews Street and Bittner Street (formerly Franklin St.) in the City of Rochester, New York (the "Site"). The Site is improved with one approximately 37,298-square-foot six-story masonry building referred to as the Kirstein Building, reportedly built in 1900. The building includes a basement and a sub-basement beneath the Bittner Street sidewalk that houses the boiler room and two large water storage tanks for the heating system. The sub-basement was filled with water at the time of this site inspection.

The Kirstein Building was originally used by the Shuron Optical Company, Inc. to manufacture optical lenses. A number of other industrial tenants later occupied the buildings. It was renovated for use as office space in the 1960s and renovated again in the 1980s, but has been vacant for the last seven years based on the serious decline in downtown commercial office market.

The 37 Bittner Street parcel is currently used as a parking lot; prior to the City reconfiguring streets in the subject area in circa 1980, Bittner Street was the northern extension of Franklin Street. The historic Sanborn Fire Insurance maps and Polk City directories indicate that this parcel was historically comprised of two parcels listed as 191 and 201 Franklin Street. The northern parcel (201 Franklin Street) was utilized as a public gas station from at least 1930 through 1960; it was listed as Franklin Street parking lot and gas station, Monroe Union Oil Co., Inc. gas station, and John J. DeCamilla gas station.

In November and December 2004, Day Environmental, Inc. (Day) performed 2 rounds of Phase II soil and groundwater sampling on site (Appendix 12.5). Day identified residual soil and groundwater contamination on the north side of the Bittner Street parcel relative to the former gas station. In addition, there is <u>no</u> documentation that underground storage tanks (UST) were removed from the gas station. Day also identified the buried remains of a hydraulic lift system.

Day stated that the area of gasoline-impacted soils is approximately 65 feet long parallel to Bittner Street, and approximately 50 feet wide. A review of Day's boring logs indicates that soils are clean down to an approximate depth of 8 feet beneath ground surface (BGS); the contaminated zone is present from approximate depths of 8 feet BGS to 13 or 14 feet BGS. Day indicates that bedrock or dense glacial till at the 13- to 14-feet depth denotes the bottom of the contamination.

The other area of concern identified by Day was the presence of perchloroethylene (PCE) and benzene in indoor air samples, and also in one subslab air sample collected for analysis from beneath the basement floor of the Kirstein Building. PCE is most commonly used as a dry-cleaning solvent. Day attributed the PCE detected in the Kirstein Building to contaminant migration from the dry cleaner on the south side of Andrews Street due south of the subject site.

In January 2000, Environmental Strategies Corporation (ESC) performed a Phase I update for 242 Andrews Street (Appendix 12.3) in which they relied on:

- Sampling and Analysis of Suspected Asbestos-Containing Material Survey, Kirstein Building, Rochester, New York, prepared by Atlantic Testing Laboratories, Limited (November 27, 1996).
- Lead-Based Paint Bulk Sampling, Kirstein Building, Rochester, New York, prepared by Atlantic Testing Laboratories, Limited (November 27, 1996).
- Phase I Environmental Site Assessment of the Kirstein Building at 242 Andrews Street in Rochester, New York, prepared by Environmental Strategies Corporation (December 2, 1996).
- Asbestos Clean-up and Encapsulation Kirstein Building, Rochester, New York, prepared by Environmental Strategies Corporation (January 14, 1997).

These documents were not available for review when this Phase I Environmental Site Assessment was completed. However, since the 1996 Phase I was not performed in accordance with ASTM 1527-00, this report is not relevant for purposes of this application. ESC recommended that in accordance with the recommendation provided in their December 2, 1996 report, asbestos-containing materials and lead-based paints should be identified and removed before any additional renovations are conducted.

CB Richard Ellis provided a copy of the Atlantic Testing Laboratories, Inc. September 30, 1997 "Asbestos Management Plan" (Appendix 12.4). Asbestoscontaining materials (ACM) identified were pipe and pipe elbow insulation; roof compounds; window caulking; electrical housing; stucco; joint compounds; and 9-inch and 12-inch floor tiles and mastics. Appendix 12.4 contains the Atlantic Testing report, including location maps depicting location of the ACM by floor of the Kirstein Building.

1.2 CONCLUSIONS

We have performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of ASTM practice E 1527-00 for the subject parcel referred to as the Kirstein Building, located at 242 Andrews Street / 37 Bittner Street in the City of Rochester, New York. This assessment has revealed <u>no</u> evidence of recognized environmental conditions in connection with the subject site except for the following:

- 1. The northern portion of the 37 Bittner Street parcel, historically listed as 201 Franklin Street, was a public gas station from at least 1930 through 1960. Day identified an approximate area of soil contamination 65-feet long by 50-feet wide of gasoline-impacted soils. Two groundwater samples collected by Day also revealed petroleum contamination greater than the NYSDEC Groundwater standard (Appendix 12.5).
- 2. It is unknown whether underground gasoline tanks remain on site.
- 3. Day detected PCE and benzene, as well as a number of solvent TICs, in one sub-slab soil gas sample and five ambient air samples collected from the basement of the subject building.
- 4. ASTM E 1527-00 states that asbestos-containing materials (ACM) are "non-scope considerations that persons may want to assess in connection with commercial real estate". ACM have been documented in the subject building (Appendix 12.4).
- 5. ASTM E 1527-00 states that lead-based paints are "non-scope considerations that persons may want to assess in connection with commercial real estate". Based on the age of the subject building lead-based paints are assumed to be present.

1.3 **RECOMMENDATIONS**

- 1. To determine if any UST are present on site, we recommend conducting an electromagnetic survey by EM-61, which is a method of identifying buried metal objects. If electromagnetic anomalies are recorded, a subsequent test pit excavation should be conducted to investigate these areas. If any UST are located, they should be properly purged of vapors, cleaned, and removed in compliance with Part 6 NYCRR Part 613.9 of the NYSDEC Petroleum Bulk Storage regulations.
- 2. We recommend conducting a subsurface investigation by Geoprobe to more precisely delineate the contamination on the Bittner Street parcel, and determine the approximate volume of contamination to be addressed. Based on these results, we will determine the most cost-effective way to perform the cleanup, and prepare remedial budget estimates. During the Geoprobe investigation, we will collect one soil sample for laboratory characterization for landfill approval purposes.
- 3. We recommend conducting a sub-slab soil and groundwater sampling program in the basement along the south wall of the subject building to confirm that the PCE is originating at the off-site dry cleaner to the south and there is no on-site independent source of solvent contamination from historic on-site past industrial operations.
- 4. We recommend that a sub-slab venting system be installed to ensure that no volatile organic compounds (VOC) can enter the building in the future.
- 5. Prior to renovation, we recommend soliciting competitive bids to perform asbestos abatement in the building.
- 6. Renovation should be carried out with "lead safe" methodologies in conformance with OSHA regulations. Paints on the floors that have not been renovated since the lead-based paint regulations were promulgated in 1977 should either be sampled or presumed to be lead-based paints. Information that was provided to Atlantic Testing indicate that the first and fourth floors, and the northern approximately half of the second and third floors have been renovated. Lead-based paints are of concern in the remainder of the building.

2.0 PURPOSE

This Phase I Environmental Assessment report has been prepared in accordance with ASTM Standard E 1527-00, *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process.* The purpose of this practice is to identify recognized environmental conditions on the subject property, if any. Recognized environmental conditions are defined as the presence or likely presence of hazardous substances or petroleum products under conditions indicating a past, current, or the threat of a future release of those substances on the property.

In addition, the purpose of this report is to evaluate "business environmental risk" regarding any environmental conditions which can materially impact the property.

3.0 SCOPE OF WORK

The scope of this Phase I Environmental Assessment has been limited to a review of the following sources of information.

- A) Recorded chain of title documents regarding the subject property, including all deeds, easements, leases, restrictions and covenants for a period of 50 years, if provided.
- B) Historical maps and aerial photographs which may reflect prior uses of the subject property and which are reasonably obtainable through state or local government agencies.
- C) Reasonably obtainable federal, state and local government records of: listed hazardous/solid waste sites, spill reports, underground and bulk storage tank facilities, hazardous waste treatment, storage and disposal (TSD) handler and generator records and recorded environmental complaints as provided by the Environmental Data Resources (EDR) Summary Report.
- D) A visual site inspection (reconnaissance) of the subject property and all facilities and improvements on the subject property.
- E) Environmental Strategies Corporation January 19, 2000 Phase I Update including reference to previous asbestos sampling performed in 1996 (Appendix 12.3).
- F) Day Environmental, Inc. November and December 2004 Phase II investigation reports (Appendix 12.5).

To augment that information, a Freedom of Information Law (FOIL) request was sent to the NYSDEC for information concerning the subject site; as of March 14, 2005, a reply has <u>not</u> been received from the NYSDEC. Passero Associates reserves the right to revise this report based upon any pertinent information concerning the subject property that may be forthcoming from this department. To the best of Passero Associates' knowledge, the information contained in this report is true and accurate. Passero Associates' personnel have exercised due diligence in the compilation of the information contained herein appropriate to environmental professionals engaged in investigations of this sort.

4.0 USER PROVIDED INFORMATION

4.1 Owner Interview

Mr. Joseph Rowley of CB Richard Ellis completed the Environmental Questionnaire (Appendix 12.2) and provided information to Peter Morton during the site visit on February 21, 2005. Mr. Rowley also provided copies of the Day Phase II reports discussed below.

The Site is improved with one approximately 37,298-square-foot six-story masonry building referred to as the Kirstein Building, reportedly built in 1900. Originally used to manufacture optical lenses, it was subsequently converted for use as office space. The building includes a basement and a sub-basement beneath the Bittner Street sidewalk that houses the boiler room and two large water storage tanks for the heating system; the boilers were gas-powered, and there are no fuel oil tanks on site. The sub-basement was filled with water at the time of this site inspection on February 21, 2005. Mr. Rowley stated that the subbasement has filled with water since the power was shut off and the sump pumps stopped functioning when the building was vacated approximately seven years ago.

4.2 Environmental Liens/Valuation Reductions

The November and December 2004 Day Phase II reports document environmental liabilities associated with the subject site (Appendix 12.5).

4.3 Reason for Performing Phase I

This Phase I Environmental Site Assessment was performed relative to the purchase of the subject property by H.V.C., Inc. for renovation as commercial and residential space.

4.4 Day Environmental Phase II Reports

In November and December, 2004 Day identified residual soil and groundwater contamination on the north side of the Bittner Street parcel relative to the historic gas station present from at least 1930 to 1960.

The most contaminated soil sample collected by Day was from the depth of 8 feet to 12 feet in their Borehole 12 (see Appendix 12.5). The analytical results are presented in the following table with comparisons to the NYSDEC TAGM 4046 Recommended Soil Cleanup Objectives:

Soil Samples Results STARS-List VOCs IN MICROGRAMS PER KILOGRAM (µg/Kg), PARTS PER BILLION

(ppb)

Volatile Organic Compounds	TB-12 (8' – 12')	NYSDEC TAGM 4046 Recommended Soil Cleanup Objective (PPB) ⁽¹⁾
STARS VOCs		
Benzene	ND	60
n-Butylbenzene	ND	10,000
sec-Butylbenzene	ND	10,000
tert-Butylbenzene	ND	10,000
Ethylbenzene	3,480	5,500
n-Propylbenzene	6,180	3,700
Isopropylbenzene	2,700	2,300
p-Iopropyltolunen	1,460	10,000
Toluene	194	1,500
1,2,4 - Trimethylbenzene	23,500 E	10,000
1,3,5 – Trimethylbenzene	12,800	3,300
Xylenes (total)	16,500	1,200
Total STARS VOCs	66,814	N/A
Total VOC TICs	146,310	N/A
Total TCL/STARS VOCs & TICs	213,124	10,000

Two of Day's groundwater samples from the Bittner Street parcel exhibited petroleum contamination at orders of magnitude greater than the NYSDEC TOGS 1.1.1 Groundwater Standard as tabulated below:

	Sample	Location	NYSDEC TOGS		
Compound Detected	d MW-2 M µg/L I		1.1.1 Groundwater Standard or Guidance Value µg/L (PPB)(1)		
Volatile Organic Compounds			1		
Benzene	ND	51.3	. 1		
Ethylbenzene	934	1,400	5		
n-Propylbenzene	214	210	5		
Isopropylbenzene	115	115	5		
Toluene	ND	34	5		
1,2,4 - Trimethylbenzene	1,900	970	5		
1,3,5 – Trimethylbenzene	657	592	5		
Xylenes	1,080	421	5		

In addition, there is <u>no</u> documentation that underground storage tanks were ever removed from the gas station. Day also identified the buried remains of a hydraulic lift system. Day stated that the area of gasoline-impacted soils is approximately 65 feet long parallel to Bittner Street, and approximately 50 feet wide.

The other area of concern identified by Day was the presence of perchloroethylene (PCE) and benzene in indoor air samples, and in one sub-slab air sample collected for analysis. PCE is most commonly used as a dry-cleaning solvent. Day attributes the PCE detected in the Kirstein Building to the dry cleaner on the south side of Andrews Street due south of the subject site. However, due to the industrial history of the Kristein Building, an investigation in the basement under the building needs to be conducted to confirm that there are no on-site VOC sources. A summary of the five indoor air samples collected by Day with Summa Canisters in the basement of the subject building is tabulated below with a comparison to the USEPA Target Indoor Air Concentration (presented in $\mu g/m^3$):

Detected Volatile Organic Compounds	AIR-1 (µg/m3)	AIR-2 (µg/m3)	AIR-3 (µg/m3)	AIR-4 (µg/m3)	AIR-5 (µg/m3)	USEPA TARGET INDOOR AIR CONCENTRATION (µg/m3) ⁽¹⁾
Benzene	ND	ND	1.4	1.6	ND	0.31
Trichloroethene	1.7	ND	ND	ND	ND	0.022
Toluene	9.3	3.6	4.2	4.5	2.8	400
Tetrachloroethene	4.2	1.6	1.8	1.3	1.8	0.81

4.5 Atlantic Testing "Asbestos Management Plan"

CB Richard Ellis provided a copy of the Atlantic Testing Laboratories, Inc. September 30, 1997 "Asbestos Management Plan" (Appendix 12.4). Asbestoscontaining materials (ACM) identified were pipe and pipe elbow insulation; roof compounds; window caulking; electrical housing; stucco; joint compounds; and 9-inch and 12-inch floor tiles and mastics. Appendix 12.4 contains the Atlantic Testing report, including location maps depicting location of the ACM by floor of the Kirstein Building.

5.0 SUBJECT PROPERTY/VICINITY DESCRIPTION

5.1 SITE RECONNAISSANCE

Joseph Rowley, Jr. accompanied Peter S. Morton, C.P.G. of Passero Associates during the site visit on February 21, 2005:

5.1.1 Site Description -

The subject property consists of two contiguous parcels totaling approximately 0.7 acre, located on the northwest corner of Andrews Street and Bittner Street (formerly Franklin Street) in the City of Rochester, New York. The subject Kirstein Building has an assigned address of 242 Andrews Street, while the tax records have it listed at 234 Andrews Street. The 37 Bittner Street parcel to the north of the subject building is used as a parking lot.

5.1.2 Subject Building -

The currently vacant Kirstein Building is of brick and wood frame construction: it was reportedly built in 1900 and utilized for manufacturing optical lenses. The building was remodeled into office space in the 1960s, again underwent substantial rehabilitation on the exterior and interior in the 1980s. It was heated with two gas-fired boiler located in the basement. The boiler room pit, below the basement level, was filled with water on February 21, 2005. Joseph Rowley said that the water infiltration began when the power supply to the sump pump was terminated when the building was vacated approximately seven years ago.

5.1.3 Evidence of Tanks -

The subject building is heated with natural gas, and <u>no</u> evidence of tanks was noted on site during Passero Associates' site visit. The City of Rochester has <u>no</u> records of tanks on site. There are <u>no</u> NYSDECregistered tanks on the subject site.

The 1950 Sanborn Fire Insurance Map indicates that s "filling station" was located on the subject Bittner Street parcel (Franklin St/ in 1950). It is unknown if gas tanks remain on site beneath the Parking lot on the subject Bittner Street parcel.

5.1.4 Storage Practices -

The subject site was historically used to manufacture optical lenses, and according to the abstract of title, a number of manufacturing interests owned the building, and may have caused the solvent contamination, which appears to be present throughout the site. According to the air sample data, solvent "TICs", or tentatively identified compounds, were more prevalent than the petroleum solvent compounds. MEK and acetone (not typically used in dry cleaning establishments) is also present in some of the air sample data.

5.1.5 Evidence of Spills/Releases -

The Day Phase II data indicated a "reportable spill condition" on the subject Bittner Street parcel (Appendix 12.5).

5.2 ADJACENT PARCELS

A dry cleaner is presently, and has historically been located on the adjacent property on the south side of Andrews Street to the south of the subject site (see photos). This adjacent property is suspected of being the possible source of or contributing to the PCE detected in vapors beneath and inside of the subject building.

5.3 SUBJECT SITE PHOTOGRAPHS

Representative photographs of the subject site are presented in the following page:

The Kirstein Building



Looking west at subject Kirstein Building



Looking south at adjacent dry cleaner, subject building on right



Looking north across 37 Bittner Street parcel historically used as a gas station

6.0 HISTORY AND USE

6.1 RECORDS

<u>The City of Rochester Records Access Officer</u> Contact: Sylvia Rosello (585-428-6066)

Because of the rapid closure of this real estate deal, we have not received the City's F.O.I.L. response. However, Day's work in 2004 indicates that the City records do not adequately address tank issues relative to the historic presence of a gas station on Bittner Street (former Andrews Street) for at least 30 years.

6.2 HISTORIC AERIAL PHOTOGRAPHS

Monroe County Department of Health Aerial photographs from 1930-1999 were reviewed.

The subject Kirstein Building was present throughout the period of these historic photos. The filling station present on the subject site to the north of the building, discussed in Sections 6.3 and 6.4 below, is indistinguishable at the scale of these photos.

6.3 HISTORICAL MAPS

Historical Sanborn Fire Insurance Maps are available from 1892, 1911, 1950 and 1971.

- 1892 The subject parcels were improved with residential houses.
- 1911 The Kirstein Building was present at this time; the present day Bittner Street was referred to as Franklin Street at that time.
- 1950 The subject Bittner Street parcel was utilized as a parking lot with a "filling station"; two gas tanks were indicated on the north and south sides of the filling station building (Appendix 12.6).
- 1971 By 1971 the filling station was gone; the Bittner Street parcel was utilized for parking.

6.4 **POLK DIRECTORIES**

Polk City Directories were reviewed in the City of Rochester Rundel Library relative to historic site usage:

 242 Andrews Street – from the early 1900s until the 1960s, the subject address was listed as "Shuron Optical Co., Inc. plant". In the 1970s, the first floor was "vacant", and floors 3-5 were listed as "Erdman Anthony Associates" (engineering firm). In the 1990s, the Girl Scouts of Genesee Valley, Monroe County Housing Council, and a social services organization utilized the subject building.

37 Bittner Street (formerly 191, 201 Franklin Street) – There has been no listing of the 37 Bittner Street address. Based on the Polk indication of "Andrews Street intersects" and reference to the Sanborn Fire Insurance Map, prior to 1980 the parcel was listed as 191 and 201 Franklin Street. In 1960, 201 Franklin Street was listed as "parking lot and service station"; in 1940, it was listed as "John J. DeCamilla gas station"; in 1930, it was listed as "Monroe Union Oil Co., Inc. gas station".

REGULATORY INFORMATION 7.0

Passero Associates acquired the Environmental Data Resources (EDR) Summary Report relative to the subject site and ASTM-specified search distances (Appendix 12.6).

National Priorities List (NPL)

There are no NPL sites identified within one-mile of the subject parcel.

Comprehensive Environmental Response, Compensation, and Liability Information System (CERCLIS)

There are no CERCLIS sites identified within a 0.5-mile of the subject parcel.

Resource Conservation and Recovery Act (RCRA)

There are no RCRA-listed facilities on the subject site, or on any of the adjacent parcels.

There are no RCRA-listed Treatment, Storage, Disposal Facilities (TSDF) with Corrective Actions (CORRACTS) identified within the ASTM-specified 1.0 mile search distance relative the Site.

Emergency Response Notification System

The EDR database does not indicate any ERNS reports relative to the subject site.

State Priority List (SPL)

There are <u>2</u> NYSDEC-listed Inactive Hazardous Waste Sites located within 1.0 mile of the subject site. The former "Rochester Metal Etching" and Raeco Products" sites are both located approximately 0.9 mile northwest of the subject site, on the opposite side of the Genesee River. The river acts as a hydraulic barrier preventing groundwater migration to the other side; the regional groundwater flow direction is northwards towards Lake Ontario. These NYSDEC-listed Inactive Hazardous Waste sites are hydraulically down gradient, and not of environmental concern relative to the subject site.

Underground Storage Tank Listing (USTs)

There are no registered tanks on the subject site or on any of the adjacent parcels. The former filling station known to be present on the subject site pre-dated the NYSDEC Petroleum Bulk Storage Regulations.

Leaking Storage Tanks (LST)

EDR notes <u>26</u> reported LST incidents within 0.5 mile of the subject site. The respective tank owners are liable for cleanup costs, and the area is serviced by public water. These reported LST incidents do <u>not</u> appear to be of environmental concern relative to the subject site.

Solid Waste/Landfills (SWLF)

There is <u>one</u> SWLF site identified within 0.5 mile of the subject site; Rochester Gas & Electric at 89 East Ave., approximately 0.3 mile southeast of the subject site was reported to have dumped construction/demolition debris (c/d). This site is listed "closed" and no petroleum or hazardous wastes are recorded to have been dumped at this landfill. It is not of environmental concern relative to the subject site.

IMPACT OF IDENTIFIED SITES ON THE SUBJECT PROPERTY

As discussed above, the sites identified within the ASTM-specified search distances do <u>not</u> appear to be environmental concern relative to the subject site.

8.0 RADON

Radon, a naturally occurring, odorless, colorless, radioactive gas, is found throughout the country. Prolonged exposure to elevated indoor radon levels has been associated with increased risks of lung cancer.

In 1994, NYSDOH conducted a basement radon survey across New York State. A mean level of 1.7 picocuries per liter of radon (pCi/l) was measured in the City of Rochester (Appendix 12.5). USEPA has determined an annual average exposure of 4.0 pCi/l as a guidance level for corrective action. **Based on the above, radon does <u>not</u> appear to be of concern in the site area.**

The actual indoor radon level can only be determined through sampling and analysis, <u>not</u> included in the scope of this Phase I Site Assessment.

9.0 **CONCLUSIONS**

We have performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of ASTM Practice E 1527-00 for the subject parcel referred to as the Kirstein Building, located at 242 Andrews Street / 37 Bittner Street, in the City of Rochester, New York. This assessment has revealed <u>no</u> evidence of recognized environmental conditions in connection with the subject site except for the following:

- 1. As discussed, residual gasoline contamination has been identified relative to the historic presence of a gas station on the 37 Bittner Street parcel.
- 2. It is unknown whether underground gasoline tanks and hydraulic lifts remain on site.
- 3. Day detected PCE and benzene, as well as a number of solvent TICs in one sub-slab soil gas sample and five ambient air samples collected from the basement of the subject building.
- 4. Asbestos-containing pipe and pipe elbow insulation; roof compounds; window caulking; electrical housing; stucco; joint compounds; and 9-inch and 12-inch floor tiles and mastics are documented to be present in the subject building.
- 5. Based on the age of the subject building lead-based paints are assumed to be present.

9.1 **RECOMMENDATIONS**

- 1. We recommend that an electromagnetic EM-61 survey be conducted to investigate for UST on the 37 Bittner Street parcel. If any UST are located, they should be properly purged of vapors, cleaned, and removed in compliance with Part 6 NYCRR Part 613.9 of the NYSDEC Petroleum Bulk Storage regulations.
- 2. We recommend conducting a subsurface investigation by Geoprobe to more precisely delineate the contamination on the Bittner Street parcel, and determine the approximate volume of contamination to be addressed.
- 3. We recommend conducting a sub-slab soil and groundwater sampling program in the basement of the subject building to confirm that the PCE is originating at the off-site dry cleaner to the south.
- 4. We recommend that a sub-slab venting system be installed to ensure that no volatile organic compounds (VOC) can enter the building in the future.
- 5. Prior to renovation, we recommend soliciting competitive bids to perform asbestos abatement in the building.
- 6. Renovation should be carried out with "lead safe" methodologies in conformance with OSHA regulations.

10.0 DISCLAIMER

Passero Associates represents only that it provides services in accordance with generally accepted practices in the environmental audit field. No other representation, expressed or implied, is included or intended as part of its services, proposals, contracts or reports.

Passero Associates cannot provide guarantees, certifications or warranties that the property is or is not free of environmental impairment without a Phase II Site Assessment involving collection and laboratory analysis of environmental samples. Even with such a program, the data and samples from any given soil boring or monitoring will indicate conditions that apply only at that particular location, and such conditions may not necessarily apply to the general site as a whole.

11.0 LIMITATION OF LIABILITY

H.V.C., LLC, Chamberlain D'Amanda Oppenheimer and Greefield, Knauf Shaw LLP and Passero Associates have discussed the risks, rewards and benefits of the project and Passero Associates' total fee for services. The risks have been allocated such that H.V.C., LLC, Chamberlain D'Amanda Oppenheimer and Greefield, and Knauf Shaw LLP agree that to the fullest extent permitted by law, Passero Associates' total liability or claims expenses arising out of this agreement from any cause or causes shall <u>not</u> exceed \$100,000.

In addition, H.V.C., LLC, Chamberlain D'Amanda Oppenheimer and Greefield, and Knauf Shaw LLP agree that the due diligence as described in ASTM Practice E1527-00 is acceptable to them, and that to the fullest extent permitted by law, Passero Associates shall not be liable for limiting its site assessment to the due diligence effort described.

Respectfully Submitted,

peto Mak

Peter S. Morton, C.P.G. Certified Professional Geologist

que l'assar

Gary W. Passero, R.E.M. President

APPENDIX 12.1 Tax Map

1

I

1



17-17 2022

24 15 15

antan Citta

LANDATA www.ny-propdata.com - Map Name: maps/ROCH/106_79.tif

APPENDIX 12.2 Environmental Questionnaire

1

1

I

c

SITE SUMMARY

•	
Address: The Kirsten Build na	n
242 Andrews St. & 37 Bittner St.	
Rochester NY 14604	
Why is this Phase I being performed? (purchase/sale/refinance)	· · · ·
Are there any Environmental Liens or Deed Restrictions on the Subject Property?	Yes X No
Has the Value of the Property been reduced due to Environmental Conditions?	Yes X No
Building (if applicable) Year Built: 1906 Use?: Office - Vacated in 1997 Last Renovated?: 1984	
Construction Materials (Wood Frame, Block,): Wood Beam Frame Brick Ex	terior .
How is the Building Heated (Natural Gas/Electric/Fuel Oil): Gas - out of	service since 199
Any Asbestos-Containing Materials?: Yes	
Lead-Based Paint?	
Tanks?No	
Public Water?: Yes - out of service since 1997	
Sanitary Sewer? Yes - out of service since 1997	
Floor Drains? Yes	
Any Historic Drywell/Leachfield Discharge? <u>No</u>	
Site Usage? Former office building with adjoining 36 car parking lot.	
Vame: Joseph F. Rowley, Jr.	
Title: Listing Agent for Owner	
)ate:March 14, 2005	

The Kirsten Building Address: <u>242 Andrews Sf. & 37 Bitther St.</u> City, State, Zip: <u>Rochester NY 14604</u> County: <u>Monroe</u> <u>Tax Account No.: 106.79-01-24</u>

106-79-01-22

	Question		Owner/Occupant	
la	Is the property currently used for an industrial use?	Yes	No	Unknowa
16	Is any adjoining property currently used for an industrial use?	Yes	No	Unknown
2a	Did you observe evidence or do you have any prior knowledge that the property has been used for an industrial use in the past?	Yes	No	Unknown
25	Did you observe evidence or do you have any prior knowledge that any adjoining property has been used for an industrial use in the past?	Yes	No	Unknown
За	Is the <i>property</i> currently used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility (if applicable, identify which)?	Ycs	No	Unknown
35	Is any adjoining property currently used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility (if applicable, identify which)?	Yes	No	Unknown
4a	Did you observe evidence or do you have any prior knowledge that the <i>property</i> has been used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo devoloping laboratory junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility (if applicable, identify which)?	Yes	No	Unknown
45	Did you observe evidence or do you have any prior knowledge that any adjoining property has been used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility (if applicable, identify which)?	YES	No	Unknown

	Question	Owner/Occupant				
10a	Are there currently any registered or unregistered storage tanks (above or underground) located on the <i>property</i> ?	Yes	No	Unknown		
10Ъ.	Did you observe evidence or do you have any prior knowledge that there have been previously, any registered or unregistered storage tanks (above or underground) located on the <i>property</i> ?	Yes	No	Unknown		
114	Are there currently any vent pipes, fill pipes, or access ways indicating a fill pipe protruding from the ground on the <i>property</i> or adjacent to any structure located on the <i>property</i> ?	Yes	No	Unknown		
16	Did you observe evidence or do you have any prior knowledge that there have been previously, any vent pipes, fill pipes, or access ways indicating a fill pipe protruding from the ground on the property or adjacent to any structure located on the property?	Yes	No	İnknown		
12a	Are there currently any flooring, drains, or walls located within the facility that are stained by substances other than water or are emitting foul odors?	Yes	Ňo	Unknown		
125	Did you observe evidence or do you have any prior knowledge that there have been previously, any flooring, drains, or walls located within the facility that are stained by substances other than wafer or are emitting foul odors?	Ύes	Ño	Unknown		
13a	If the <i>property</i> is served by a private well or non-public water system, is there evidence or do you have prior knowledge that contaminants have been identified in the well or system that exceed guidelines applicable to the water system?	Yes	No	Unknown NA		
13b	If the <i>property</i> is served by a private well or non-public water system, is there evidence or do you have prior knowledge that the well been designated as contaminated by any government environmental/health agency?	Yes	No	Unknown NA		
14	Does the owner of occupant of the property have knowledge of environmental liens or governmental notification relating to past or recurrent violations of environmental laws with respect to the property or any facility located on the property?	Yes	No	Unknown		

· · · · · ·					
	Question		Owner/Occup		
Sa	Are there currently any damaged or discarded automotive or industrial batteries, pesticides, paints, or other chemicals in individual containers of >5 gal (19 L) in volume or 50 gal (190 L) in the aggregate, stored on or used at the <i>property</i> or at the facility?	Yes	No	Unknown	
Sb	Did you observe evidence or do you have any prior knowledge that there have been previously any damaged or discarded automotive or industrial batteries, pesticides, paints, or other chemicals in individual containers of >5 gal (19 L) in volume or 50 gal (190 L) in the aggregate, stored on or used at the <i>property</i> or at the facility?	Ycs	No	Unknown	
6 a	Are there currently any industrial <i>drums</i> (typically 55 gal (208 L) or sacks of chemicals located on the property or at the facility?	Yes	No	υπκυόλια	
6Ъ	Did you observe evidence or do you have any prior knowledge that there have been previously any industrial <i>drums</i> (typically 55 gal (208 L) or sacks of chemicals located on the property or at the facility?	Yes	(No)	Unknown	
7a	Did you observe evidence or do you have any prior knowledge that <i>fill</i> dirt has been brought onto the property that originated from a contaminated site?	Yes	€A)	Uaknown	
7Ъ	Did you observe evidence or do you have any prior knowledge that fill dire has been brought onto the property that is of an unknown origin?	Yes	NO	Unknown	
81	Are there currently any pits, ponds, or lagoons located on the property in connection with waste treatment or waste disposal?	Yes	(No)	Unknown	
8Ъ	Did you observe evidence or do you have any prior knowledge that there have been previously, any pils, ponds, or lagoons located on the property in connection with waste treatment or waste disposal?	Yes	No	Unknown	
9 a	Is there currently any stained soil or evidence of spiils on the <i>property</i> ?	Yes	No	Unknown	
9Ъ	Did you observe evidence or do you have any prior knowledge that there has been previously, any stained soil or spills on the <i>property</i> ?	Yes	No	Unknown	

ASTM E 1528-96 TRANSACTION SCREEN QUESTIONNAIRE

		1			
	Question	Owner/Occupant			
15a	Has the owner or occupant of the property been informed of the past existence of hazardous substances or petroleum products with respect to the property or any facility located on the property?	Ye) No	Unknown	
156	Has the owner or occupant of the property been informed of the current existence of <i>hazardous substances</i> or <i>petroleum products</i> with respect to the property or any facility located on the property?	Yes	5 (No) Unknöwn	
15c	Has the owner or occupant of the property been informed of the past existence of environmental violations with respect to the property or any facility located on the property?	Yes	No No) Unknown	
15đ	Has the owner or occupant of the property been informed of the current existence of environmental violations with respect to the property or any facility located on the property?	Yes	No	Unknown	
16a	Does the owner or occupant of the property have knowledge of any environmental site assessment of the property or facility that indicated the presence of hazardous substances or petroleum products on, or contamination of, the property or recommended further assessment of the property?	Yes) No	Unknown	
16 b	Does the owner or occupant of the property have knowledge of any previous testing, monitoring wells, soil and/or groundwater sampling performed on the property?	Yes) No	Unknown	
17	Does the owner or occupant of the property have knowledge of any past, threatened, or pending lawsuits or administrative proceedings concerning a release or threatened release of any hazardous substance or petroleum produces involving the property by any owner or occupant of the property?	Yes	No	Unknowa	
18a	Does the property discharge waste water on or adjacent to the property, other than storm water, into a storm water sewer system?	Yes	Nu	Unknown	
185	Does the property discharge waste water on or adjacent to the property, other than storm water, into a sanitary sewer system?	Yes	Nə	Unknown	
9	To the best of your knowledge, have any hazardous substances or petroleum products, unidentified waste materials, tires, automotive or industrial batteries or any other waste materials been dumped above grade, buried and/or burned on the property?	Yes	No	Unknown	

	Question		Owner/Occupant		
20	Is there a transformer, espacitor, or any hydraulic equipment for which there are any records indicating the presence of PCBs?	Yes	No	Unknown	
21	Does the owner or occupant know of any lead-based paint in the building(s)?	Yes	No	Unknown	
22	To the best of your knowledge, was all paint stripped and removed prior to applying latex paint in the building(s)?	Yes	No	Uuknown	
23a	Does the owner or occupant know of any asbestos-containing materials (ACM) are present in the building(s)?	Yes	No	Unknown	
236	If ACM is present, is an O&M program in place?	Yes	No	Unknown	
24	Does the <i>owner</i> or <i>occupant</i> know of any radon testing performed in the building?	Yes	No	Unknown	

This Questionnaire was completed by:

Name: Joseph F. Rowley

Title: Agent for Owner

Phone Number: 585-240-8080 x 230

Date: March 14, 2005

NOTE Although this questionnaire is taken from ASTM E1528-96 Transaction Screen Process, Passero Associates also uses this information to supplement our Phase I Environmental Site Assessment.

APPENDIX 12.3 ETC January 2000 Phase I Update



ENVIRONMENTAL STRATEGIES CORPORATION

9 Albany Street • Cazenovia, NY 13035 • (315) 655-3900 • Fax (315) 655-3907

January 19, 2000

Mr. Robert Cheney RBC Consulting, LLC P.O. Box 1072 Layton, UT 84041

Re: <u>Phase I Update – 242 Andrews Street</u>, Rochester, New York

Dear Mr. Cheney:

In accordance with our proposal, dated January 14, 2000, Environmental Strategies Corporation (ESC) has updated the Phase I Environmental Assessment, dated December 2, 1996, for the property at 242 Andrews Street in Rochester, New York. The Phase I update is based on a site visit on January 18, 2000, an environmental database search of the site and surrounding properties, and a review of the following documents:

Sampling and Analysis of Suspected Asbestos-Containing Material Survey, Kirstein Building, Rochester, New York, prepared by Atlantic Testing Laboratories, Limited (November 27, 1996).

Lead-Based Paint Bulk Sampling, Kirstein Building, Rochester, New York, prepared by Atlantic Testing Laboratories, Limited (November 27, 1996).

Phase I Environmental Site Assessment of the Kirstein Building at 242 Andrews Street in Rochester, New York, prepared by Environmental Strategies Corporation (December 2, 1996).

Asbestos Clean-up and Encapsulation – Kirstein Building, Rochester, New York, prepared by Environmental Strategies Corporation (January 14, 1997).

The results of the Phase I environmental assessment update is presented below.

Background Information

The existing building, known as the Kirstein Building, is a 6-story office building at the northwest corner of Andrews Street and Bittner Street in Rochester, New York. It is situated on approximately 0.2 acre and is completely covered by the building and an asphalt parking area. There are no landscaped areas, grass, or wooded areas on the property. The building includes a basement and a sub-basement beneath the Bittner Street sidewalk that houses the boiler room and two large water storage tanks for the heating system. The building is constructed of brick with wooden framing, rafters, and trusses, and a tar and asphalt roof. The subject property and surrounding area was reportedly developed in the late 1800s.

Environmental Assessment

On January 18, 2000, ESC performed a site reconnaissance of the building interior and outdoor areas of the property. Due to recent snowfall, portions of the property could not be thoroughly inspected. In addition, the building is no longer supplied with electricity and, thus, the basement and sub-basement areas were inspected with a flashlight. ESC was assisted on the site visit by Steve Savoca of the SB Ashley Corporation.

The Kirstein Building is currently vacant. According to information provided by Mr. Savoca, no additional tenants rented building space after ESC's December 1996 site visit and the building has been vacant since November 1997. Based on the results of the site visit, ESC did not observe any significant changes in the condition of the building or property and no additional areas of potential environmental concern were identified. In December 1997, asbestos-containing stucco was encapsulated in several areas on the sixth floor. These areas were observed to be in good condition during the follow-up site visit. According to Mr. Savoca, no additional removal or encapsulation of these materials has been performed. Minor differences in the condition of the basement were noted. A portion of the basement has been subdivided with walls constructed of metal framing and gypsum board and free-standing walls constructed of architectural glass blocks. According to Mr. Savoca, the basement had been partially renovated for use as a restaurant. Numerous bathroom fixtures such as toilets, sinks, and showers were also observed in the basement.

No solid waste or sanitary waste water is generated onsite and there are no air emissions. No materials are used or stored onsite, with the exception of various building materials (e.g., conduit, plumbing fixtures, lumber) and small quantities of cleaning supplies in the maintenance area of the basement. No polychlorinated biphenyl-containing transformers or hydraulic equipment were observed onsite and no evidence of former or existing underground or aboveground storage tanks (excluding water storage tanks) were observed. In addition, Mr. Savoca reported that no spills have occurred onsite.

ESC reviewed federal and state regulatory databases to determine if any environmental issues have been reported for the subject property or surrounding properties. A copy of

the environmental database report is included in Enclosure A. The subject property was not included on any of the databases reviewed. There were no National Priority List sites or State equivalent priority list sites within one mile of the subject property, and no Resource Conservation and Recovery Act (RCRA) permitted treatment, storage, or disposal facilities or solid waste landfills within 0.5 mile of the subject property. In addition, there are no sites within 0.25 mile of the subject property with RCRA violations or enforcement actions and no sites are on the toxic release inventory database. No sites within 0.125 mile of the subject property are on the Emergency Release Notification System database for spills.

Thirty-one sites within 0.5 mile of the subject property are on the leaking underground storage tank database. According to the database information, 27 of the sites have been closed. Three of the remaining sites are located side-gradient from the subject property (the groundwater flow direction is presumed to be west toward the Genessee River) and, therefore, do not pose a potential environmental concern. The National Ambulance Oxygen Service facility, located approximately 0.5 mile east of the subject property, had a release of diesel fuel to groundwater in 1992. However, due to its distance from the subject property, it is unlikely that this release poses a potential environmental concern. A release from a heating oil aboveground storage tank occurred in the basement of a building at 130 North Clinton Ave, which is less than 0.125 mile east of the subject property. However, because the tank was located in the basement of the building, it is unlikely that this release would adversely affect the subject property.

Eight sites within 0.125 mile of the subject property are on the state spills database; however, each of the spill cases has been closed. Based on the location of these sites, and the fact that the spill cases have been closed, it is unlikely that the subject property would be adversely affected by these releases. Three sites within 0.5 mile of the subject property are on the state-equivalent Comprehensive Environmental Response, Compensation, and Liability Act Information System (CERCLIS) database. These sites appear to be located hydraulically downgradient from the subject property and, thus, are unlikely to pose a potential environmental concern. No other sites identified by the database search appear to pose a potential environmental concern to the subject property.

Recommendations

Based on the results of the follow-up site visit, no additional recommendations are required. In accordance with the recommendations provided in the December 2, 1996, report, asbestos-containing materials and lead-based paint should be identified and removed before any additional renovations are conducted. Asbestos-containing materials present in the building should be managed in accordance with the asbestos management plan for the site. In addition, fluorescent light tubes should be recycled.

ESC appreciates the opportunity to provide environmental services to RBC Consulting, LLC. Please contact me at (315) 655-3900 or Willy Accame of ESC at (303) 850-9200 with any questions or comments regarding the update to the Phase I environmental assessment.

Sincerely yours,

Brian E. Silfer Project Director

Enclosure

cc: Willy Accame, Environmental Strategies Corporation

APPENDIX 12.4 Atlantic Testing Laboratories, Asbestos Management Plan

DRAFT

ASBESTOS MANAGEMENT PLAN

The Kirstein Building

242 Andrews Street

Rochester, New York

PREPARED FOR:

The Union Labor Life Insurance Company Washington, DC

PREPARED BY:

Atlantic Testing Laboratories, Limited 5866 State Route 31 Cicero, New York 13039

ATL REPORT NO. ST5042-2-9-97

September 30, 1997

1. INTRODUCTION

In accordance with our proposal (ATL File No. ST5042-7-97, dated July 24, 1997), Atlantic Testing Laboratories, Limited (ATL) has prepared the following Asbestos Management Plan for The Kirstein Building, located at 242 Andrews Street, Rochester, New York

The Kirstein Building is a six-story structure located in downtown Rochester, New York. The building is partially occupied, and renovation activities have occurred throughout the history of the buildings. This Asbestos Management Plan, also know as an Operations and Management Plan (O&M Plan), is based on ATL's visual examination of exposed building materials within the referenced building on October 17, 1996, and August 1, 1997. During the course of the site visits, bulk samples of the materials suspected to contain asbestos were collected for laboratory analysis. The visual examination and sample collection activities were performed by the undersigned New York State Department of Labor certified Building Inspector and Management Planner.

2. SUSPECTED ASBESTOS-CONTAINING MATERIALS SURVEY

The intent of the survey was to identify asbestos-containing building materials that are present on exposed surfaces (i.e., wall, floor, and ceiling covering; exposed heating system components; fireproofing materials; window caulking materials; and wire insulation) within the structure, and may have a significant impact on future use and/or renovation of the facility. Materials concealed within walls and miscellaneous debris, such as scrap material from facility maintenance and renovation activities (including sweepings, wood, steel, and cement products), are generally not assessed in the course of the visual examination and sampling and analysis program.

Historical information indicated that the fourth floor, and the northern approximately one-half of the second and third floors, have been completely renovated by the previous owners within the past five to six years. Visual examination of these areas at the time of sampling revealed that the existing finish construction appears to be in sound condition, and of relatively recent vintage. The first floor was also renovated before the current owners acquired the building. The remaining areas of the building have not been renovated recently.

2.1 REGULATORY DEFINITIONS AND CONCEPTS

The following definitions and concepts are presented to outline the regulatory concerns in performing an Asbestos Survey and subsequent Asbestos Management Plan.

As defined in Part 56 of the Official Compilation of Codes, Rules, and Regulations of the State of New York (cited as 12 NYCRR, Part 56), Sections 1.4N and 1.4J, asbestos-containing material (ACM) is "any material containing more than one percent by weight of asbestos" and asbestos is "any naturally occurring hydrated mineral silicate separable into commercially usable fibers, including chrysotile (serpentine), amosite (cumingtonite-grunerite), crocidolite (riebeckite), tremolite, anthophyllite, and actinolite." Under Environmental Protection Agency (cited as 40 CFR 763.86) guidelines, if one or more samples from a homogeneous area contain more than one percent asbestiform minerals, then the homogeneous area is considered an ACM. The characteristics of a homogenous area, such as color, friability, texture, application, and appearance, are used in defining the extent and location of each type of material.
The Kirstein Building		September 30, 1997
ATL Report No. ST5042-2-9-97	<u>.</u>	Page 2

Materials considered to be suspected ACM include materials observed during the survey that are identified in Appendix A, entitled "Asbestos-Containing Materials Found in Buildings", of the United States Environmental Protection Agency's "Guidance for Controlling Asbestos-Containing Materials in Buildings", dated June 1985.

By 12 NYCRR 56 definitions, ACM is considered *friable* when it displays the condition of being crumbled, pulverized, powdered, crushed, or exposed asbestos, which is capable of being released into the air, upon application of hand pressure.

The relative potential for disturbance is defined as the likelihood that the material could be disturbed in the future (or shows evidence of past disturbance), the frequency with which occupants are in the vicinity of the material, and its location with respect to vibrations. These factors are evaluated differently depending on whether occupants are likely to contact the material.

The number of samples collected from each homogeneous area was determined based on guidelines presented in 40 CFR Part 763.86 (AHERA Regulations), as applicable. Materials identified to be nonorganically bound (NOB) in nature, and which were determined by polarized light microscopy (PLM) analysis to contain less than one percent asbestos (by weight), were also subjected to TEM analysis to confirm the PLM results. The results of the analyses were interpreted to determine whether the homogeneous areas identified are regulated asbestos-containing materials.

2.2 SAMPLING METHODOLOGIES

The individual homogeneous areas of suspected ACM identified during the visual examination included a total of 4 surfacing materials, 6 thermal system insulation (TSI) materials, and 14 miscellaneous materials, from which 44 bulk samples were obtained and submitted to a New York State Department of Health (NYSDOH) approved laboratory for analysis by PLM methodologies. The laboratory reports and sample custody documentation are contained in Appendix 1.

The following table summarizes the homogeneous areas identified as ACM, the material friability and relative condition, and the potential for disturbance.

Homogeneous Area	Friable	Relative Condition	Potential for Disturbance
Aircell Pipe Insulation	Yes	Generally good, isolated damaged areas	Low
Elbow Insulation	Yes	Generally good, isolated damaged areas	Law
Elbow Insulation with Mineral Wool	Yes	Generally good, isolated damaged areas	Low
Patching Compound-Roof	Yes	Generally good	L.ow
Exterior Knee-wall-Roof	Y⊏s	Generally Good	Low
Protrusion Flashing-Roof	Yes	Generally Good	Low
Window Caulking	No	Generally good, isolated damaged areas	Moderate
Electrical Housing	No	Generally good	Low
Joint Compound	Na	Generally good	Low
Stucco	Na	Generally good, isolated damaged areas	Low
12" Tile White and Gray	No	Generally good	Low
9" Tile Brown	No	Generally Good	Low
9" Tile Mastic	No	Generally Good	Low
9" Tile Gray and White	No	Generally good	Low
9" Tile Green	No	Generally Good	Low
12"Tile Mestic	Na	Generally Good	Low

585 240 8088

The Kirstein Building
ATL Report No. ST5042-2-9-97

September 30, 1997 Page 3

The following table summarizes the general location of the homogenous areas determined to be non-ACM.

Homogeneous Area	- General Location
Fireproofing	Basement
Ceiling Insulation	Basement
Shectrock	Basement, Second Floor, Fifth Floor, Sixth Floor
Old Wire Insulation	Second Floor
Built-up Roofing	Roof
Plaster	First Floor
Sheet Vinyl	Third Floor
Window Caulk	Third Floor
Drop Ceiling Tile	Second Floor, Fifth Floor
Fiberglass Wrap	Fith Floor

Site drawings of the ACM are contained in Appendix II, and depict the general locations on a floor-byfloor basis. Appendix III contains a graphical representation of the hazard assessment for the subject facility. A hazard assessment facilitates the decision process, when formulating the appropriate response action. The rankings of potential hazards range from "low potential for disturbance and in good condition" to "high potential for disturbance and significantly damaged". All ACM at the subject facility was determined to be in good condition, with a moderate to low potential for damage.

3. MANAGEMENT PLAN CONCEPTS

3.1. REGULATORY COMPLIANCE

Both Federal and New York State laws address asbestos handling, disturbance, and health risks of exposure to asbestos. Regulations that could be relevant to the subject facility are outlined below:

FEDERAL

- Occupational Safety and Health Administration (OSHA) 29 CFR Parts 1910.1001, and 1926.1101
- The Clean Air Act (CAA) 40 CFR 61.140-157
- National Emissions Standard for Hazardous Air Pollutants (NESHAP) 40 CFR Part 61
- Toxic Substance Control Act (TSCA) 40 CFR 763
- The Clean Water Act (CWA) 40 CFR 427

<u>STATE</u>

- New York State Labor Law 12 NYCRR 56
- Transportation and disposal of asbestos waste is governed by the New York State Department of Environmental Conservation (NYSDEC) and the New York State Department of Transportation (NYSDOT).

In general, the required asbestos management provisions must conform to the most stringent of the above, where overlapping coverage occurs. A major concern for an asbestos project, or management plan, is compliance with Federal and State regulations promulgated in order to protect health and safety of employees and the general public. Federal and state regulations govern the following:

Health and safety of workers exposed to airborne asbestos fibers;

The Kirstein Building	September 30, 1997
ATL Report No. 575042-2-9-97	Page 4

- Communication of the presence of presumed ACM (PACM) and ACM to employees;
- Notification of building occupants, users, and regulatory agencies, in advance of an asbestos project;
- Work practices to isolate the project area and protect the public from exposure to asbestos fibers;
- Work practices to prevent the spread of airborne asbestos to the breathing air of the public;
- Transportation and disposal of asbestos waste;
- Certification of personnel performing all aspects of an asbestos project;
- Monitoring of airborne asbestos fiber concentrations during all phases of the asbestos project; and
- Record keeping requirements.

3.2. WORKER HEALTH AND SAFETY

Adherence to the above Federal and State regulations will cover regulated aspects of asbestos-related health and safety.

3.3. COMMUNICATION OF HAZARDS

OSHA requires that employers (tenants) and building and facility owners shall notify persons of the presence, location, and quantity of ACM at the facility. Notification is required for the following: prospective contractors applying or bidding work on the premises, and whose employees reasonably can be expected to work adjacent to areas containing ACM; employees of the owner who will work in or adjacent to areas containing ACM; and on multi-employer worksites (all employees or employees who will be performing work within or adjacent to areas containing ACM). Notification can be either in writing or a personal communication to the person to whom notification must be given, or his/her authorized representative.

A regulated area is an area established by the employer to demarcate areas where airborne concentrations of asbestos exceed, or there is a reasonable possibility these may exceed, the permissible exposure limit (PEL) The PEL is an exposure of airborne asbestos concentration of asbestos fibers greater than 0.1 fibers per cubic centimeter (f/cc) of air, as an 8-hour time weighted average (TWA). OSHA requires that warning labels shall be provided and displayed at each regulated area. No regulated areas were identified at the subject building.

OSHA also requires that warning labels shall be affixed to all raw materials, mixtures, scrap waste, debris, and other products containing asbestos fibers, or to the respective containers. The purpose of labeling ACM is also to reduce accidental damage from carelessness, and to visually communicate hazard information to employees, occupants, and sub-contractors at the facility. OSHA states that the provision for labeling does not apply if asbestos fibers have been modified by a bonding agent or coating, and that during any foreseeable use, handling, storage, disposal, processing, or transportation, no airborne concentrations of asbestos fibers in excess of the TWA PEL will be released.

Consequently, only labeling of the abandoned-in-place pipe insulation required. Pipe insulation is the generic name applied to all TSI homogenous areas (i.e., aircell, elbow insulations) associated with the former heat and hot water distribution system. Labels were placed in sufficient quantities to reasonably provide a visual indication of the presence of friable ACM. Typically labels were applied above the drop ceiling, an area which workers may occupy to maintain the mechanical and communication systems.

OSHA guidelines also require employers to communicate the hazard of occupational exposure to airborne concentrations of asbestos fibers to all employees who may perform housekeeping, custodial,

The Kirstein Building ATL Report No. ST5042-2-9-97 September 30, 1997 Page 5

and maintenance activities (Class Four Employees). The communication is met by providing training, posting of warning labels, and administrating recordkeeping requirements Training for Class Four Employees, known as "Asbestos Awareness Training", should consist of the following general components:

- The health effects associated with asbestos exposure;
- The relationship between smoking and exposure to asbestos producing lung cancer;
- The estimated locations and quantity of asbestos-containing material;
- Recognition of material damage and deterioration;
- Requirements in 29 CFR 1910 relating to general housekeeping methodologies; and
- A copy of 29 CFR 1910, for employee reference

3.4. MATERIAL FRIABILITY AND FIBER REALEASE CONTROL

Four general methods are available to manage ACMs as follow: removal, enclosure, encapsulation, and repair and maintenance. The latter three methods are utilized when ACM will not be removed. Before deciding on a recommendation to manage the asbestos in place, it must be determined if it is possible to leave the material in place without endangering the health and safety of employees and occupants. Throughout the evaluation/selection process, there are two fundamental points to consider. First, State and Federal government regulations require the control of asbestos. Second, asbestos fibers typically pose a health and safety hazard when exposure to airborne concentrations above the PEL occur. Therefore, the prime reason for selecting one control method over another is that the method selected will better prevent fiber release into the offices, storage areas, and surrounding air.

4. MANAGEMENT PLAN RECOMMENDATIONS

The recommendations contained herein to manage the ACM at the subject building are presented subsequent to review of the characteristics of each homogenous area. These characteristics include material friability, condition, relative potential for disturbance, and quantity. The homogenous areas and appropriate recommendations are described below

It is noted that all disturbance, repairs, or removal activities should be performed by firms licensed and individuals certified by the NYSDOL

4.1 ROOFING SYSTEMS

The roofing system (patching compound, protrusion flashing, and knee wall flashing) and floor tiles/mastics are organically bound materials with a hazard classification of least hazardous.

The roofing system is comprised of a built-up roof surrounded by an exterior knee wall. The knee wall also is found across the center of the roof, separating the roof into east and west sections. In addition to the knee wall, many protrusions, such as roof vents, plumbing vents, etc., break-up the composition of the built-up roofing. Since there is no discernible difference from the layers of the built-up roofing and the knee wall or protrusion flashing material, it is assumed that the ACM overlaps the built-up roof by at least 2 feet. The general condition of the roof suggests that repair activities are frequent, and the possibility of a complete re-roof within the next 5 to 10 years is likely. Consequently, it is recommended that, if a complete re-roof project is scheduled, the complete roof be considered ACM, due to the complexity of managing an ACM and non-ACM roof project concurrently. However, if isolated

The Kirstein Building	September 30, 1997
ATL Report No. 575042-2-9-97	Page 6

patching activities are scheduled, then non-ACM projects should be limited to the built-up roofing, and at least 2 feet away from any knee wall or protrusion.

4.2 FLOOR TILE AND MASTICS

The original floor finish, with the exception of 60% of the sixth floor, is 9 inch by 9 inch floor tile. During the course of remodeling, the 9" floor tile was either removed, covered by 12 inch by 12 inch tile, or carpeted. In general, the tile was removed at most locations; however, an investigation of the first floor 12" tile revealed a 9" tile underlying the 12" tile and/or the black floor tile mastic has been encapsulated by the tile and carpet.

Damaged floor tile is limited to unoccupied areas, and therefore, the potential for exposure is low. Prior to maintenance or remodeling in these areas, the loose or damaged floor tiles should be removed and disposed of by properly certified individuals. ATL representatives noted that the quantity of loose or damaged tiles is minimal, as the tiles are generally in good condition or are missing

It is recommended that the following care and maintenance criteria for floor tiles, and floor tile mastic, be implemented:

- 1. Sanding of these materials is prohibited.
- 2. Stripping of finishes shall be conducted using low abrasion pads at speeds lower than 300 rpm, and wet methods shall be employed.
- 3. Burnishing or dry buffing may be performed only on flooring that has sufficient finish, so that the pad cannot contact the flooring material.

4.3 WINDOW CAULKING

Five floors of the 6-story structure have original windows. These windows are located along the parking lot side of the building (west face). The windows have a glazing compound that secures the glass to the window frame. The glazing is generally in good condition, and currently non-friable. It is assumed that maintenance activities are minimal, and recommended that the window caulking be managed in place. If the condition of the material deteriorates or renovation activities are planned, then spot or complete abatement is required. Isolated damage has occurred, but debris was not observed.

The window caulking has a moderate potential for disturbance

4.4 PIPE INSULATION

The original heating system was presumed to be a forced steam-system. The piping is insulated with "air-cell" type ACM. Air-cell is a corrugated pipe insulation (white or gray) with a cardboard appearance. The system has been abandoned-in-place, as new, efficient, HVAC systems were installed. Much of the piping system has been removed, and the remaining insulation is in good condition above the drop ceiling, generally inaccessible from the building occupants. In some areas, the pipes run vertically in chaseways and behind built-out walls. On August 1, 1997, labels were applied to the pipes to warn maintenance and mechanical workers of the presence of ACM pipe insulation. Since the pipes are no longer operational, the potential for disturbance is generally limited to installing wires and cables,

The Kirstein Building ATL Report No. ST5042-2-9-97 September 30, 1997 Page 7

and unintentional disturbance. The following recommendations are presented for managing the pipe insulation:

- The insulation is not disturbed.
- Wires, cables, or new mechanical system installations are not allowed to touch, rub, or rest on the insulation.
- Cleaning and dusting the insulation is prohibited.

The insulation is in good condition, with a low potential for disturbance. If additional space is occupied and renovation occurs, the potential for disturbance should be re-evaluated.

4.5 STUCCO

Stucco surfacing material can be found on the fourth, fifth, and sixth floors. The material is trowelled onto the brick surface, present along the exterior wall of the building and the three brick support columns. The stucco is currently non-friable, with no visible damage on the fourth and fifth floors. Two sections of stucco on the sixth floor are water damaged, with loose or fallen stucco. The source of the water damage was presumed to be a leaking roof. The amount of damage observed has not increased between site visits conducted in October 1996 and August 1997. Since the sixth floor is not presently occupied, and the sections that are damaged are not presently used for storage or any other daily activity, the following management options are recommended:

- 1. The damaged areas can be physically blocked off and access prohibited until the area is needed for occupancy.
- 2. The debris can be cleaned from the floor and the damaged areas encapsulated.
- 3. Abate the debris and remaining stucco.

Item 2 is recommended. An asbestos abatement contractor can be retained to clean the debris from the floor and the damaged areas can be sealed with an encapsulant. The resultant area will be suitable for occupation or renovations. A "clean and seal" budget would range from \$1000 to \$3000.

Enclosing the stucco behind new walls is an acceptable management technique. Renovations on the fifth and fourth floor demonstrate that new walls and windows can be installed with little apparent disturbance and abatement of the stucco. It is noted that some abatement may be required, depending on the scope of the renovations, if any.

4.6 Joint Compound

The first floor has been extensively remodeled with new floor, wall, and ceiling coverings. The joints and edges of the sheetrock walls are finished with a trowelled 'joint compound' material. This nonfriable material is in good condition, with no evidence of damage at the time of the site visit.

5. MANAGEMENT PLAN UPDATE/MODIFICATION

It is recommended that the Asbestos Management Plan be updated on an semi-annual schedule. The update will include a facility wide walk-through, addressing the condition, use, and disturbance of all ACM identified. The update will also include interviews with The Kirstein Building operations management, as to the current and future facility activities that may potentially influence the financial impact of managing the ACM. 585 240 8088

The Kirstein Building ATL Report No. ST5042-2-9-97 September 15, 1997 Page 8

Please feel free to contact our office should you have any questions, or require further assistance.

Respectfully submitted, ATLANTIC TESTING LABORATORIES, Limited

DPAFT

Kevin W. Samolis Asst. Project Manager KWSMBR/kws ŗ

Appendix II

Site Sketches Depicting the Locations of ACM













SCALE PROJECT NO. DATE The Kirstein Building 8-25-97 \$15042-2-8-97 none Operations and Management Plan ATLANTIC TESTING LABORATORIES ENDICOTT, NY CAN ON NY CICERO, NY Rochester, New York MANCHESTER. NH UTCA, Nº BUR NOICN, V





Appendix III

Hazard Assessment Organizational Chart



2. Floor Tiles and mastics.

APPENDIX 12.5 Day Environmental Phase II Reports



ENVIRONMENTAL CONSULTANTS AN AFFILIATE OF DAY ENGINEERING, P.C.

DEC 2 0 2004

114

December 17, 2004

Kristina Rogers Winn Development 120 Corporate Woods, Suite 230 Rochester, New York 14623

Re: Status Report: Supplemental Phase II Environmental Assessment 242 Andrews Street/37 Bittner Street Rochester, New York

Dear Ms. Rogers:

This letter summarizes preliminary findings of the supplemental Phase II Environmental Assessment (Phase II ESA) completed by Day Environmental, Inc. (DAY) at the above-referenced property (Site). This work was done in accordance with an addendum proposal dated November 22, 2004 (revised December 2, 2004) submitted by DAY to Winn Development (Winn).

The purpose of the supplemental Phase II ESA was to complete additional studies to augment the findings of previous studies completed by DAY as described in a report titled *Phase II Environmental Site Assessment, 242 Andrews Street, Rochester, New York* dated November 2004 (DAY File 3567S-04). Specifically, the intent of the studies recently completed by DAY was to: 1. evaluate the source and extent of gasoline impact identified on the 37 Bittner Street parcel, and 2. further evaluate various volatile organic compounds (VOCs) identified in a sample of sub-slab soil gas collected from beneath the basement of the Kirstein Building located at 242 Andrews Street.

Supplemental Phase II ESA Studies

The following work was done as part of the supplemental Phase II ESA:

- submittal of a freedom of information law (FOIL) request to the City of Rochester for the 37 Bittner Street parcel and a review of the response;
- excavation of six test pits (designated TP-1 through TP-6) on the 37 Bittner Street parcel in the area of the gasoline tanks identified on a 1951 Sanborn fire insurance map and in proximity to magnetic anomalies identified during previous studies;
- advancement of five test borings (designated TB-14 through TB-18) and the conversion of three of these test borings into groundwater monitoring wells (designated MW-1 through MW-3) on the 37 Bittner Street parcel to further delineate the extent of soil impacted by gasoline-related compounds and to evaluate groundwater quality;

www.dayenvironmental.com

Ms. Kristina Rogers December 17, 2004 Page 2

- collection of air samples (designated AIR-2 through AIR-5) from various locations within the Kirstein Building located on 242 Andrews Street; and
- testing of three soil samples from the test pits/test borings for NYSDEC STARS-list volatile organic compounds (i.e., gasoline-related compounds), three groundwater samples for STARS-list volatile organic compounds (VOCs), and two groundwater samples for lead (i.e., to evaluate the potential presence of leaded gasoline).

[Note: The groundwater sample collected from monitoring well MW-1 (i.e., located approximately 55 feet north of the 242 Andrews Street property) was also tested for Target Compound List (TCL) VOCs. As such, this sample was evaluated for an expanded list including VOCs that are not part of the STARS-list. This analysis was beyond the scope-of-work identified in the addendum proposal dated November 22, 2004.]

A Site Plan showing the location of test borings/monitoring wells, test pits and air sampling locations completed to date is attached to this letter.

Findings

The FOIL response for the 37 Bittner Street parcel included a listing for a building permit issued on 10/03/56. This permit was for the installation a one 2,000-gallon gasoline tank and one "pum" (i.e., presumably a pump associated with the gasoline tank). The FOIL response was incomplete as additional information from the City of Rochester fire department is pending. It is possible that this additional information could include documentation regarding the removal of tanks.

The test pits advanced during this study did not encounter an underground storage tank (UST); however piping that appeared to be associated with USTs was encountered in several of the test pits (e.g., TP-1 and TP-4). The apparent remains of a hydraulic lift system were also encountered in test pit TP-2. While some stained soil was observed adjacent to this equipment, no unusual odors or elevated photoionization detector (PID) readings were detected emanating from this soil.

Tables summarizing the analytical laboratory results for the various samples of soil, groundwater and air collected to date are attached to this letter. The additional testing of the soil samples from test boring TB-17 and test boring TB-18 assisted in defining the lateral extent of soil contamination in the eastern and western portion of the 37 Bittner Street parcel, respectively. The sample from TP-1 was collected adjacent to a pipe encountered in the test pit that exhibited a petroleum-type odor. As shown on Table 2, the soil sample from test pit TP-1 did not contain concentrations above recommended soil cleanup objectives (RSCOs) established by the New York State Department of Environmental Conservation (NYSDEC).

The groundwater samples from monitoring wells MW-2 and MW-3 contain concentrations of various VOCs that exceed groundwater standards or guidance values established by the NYSDEC (refer to Table 3). The concentrations measured in monitoring well MW-1 were generally reported as "not detected", with the exception of a 1,2,4-trimethylbenzene concentration that exceeded the NYSDEC guidance value. [Note: The TCL compounds tested for in the sample from monitoring well MW-1 were also reported as "not detected".]

Ms. Kristina Rogers December 17, 2004 Page 3

> During the recent study, groundwater was measured in monitoring well MW-2 at a depth of about 9.4 feet below the ground surface and at a depth of about 9.1 feet below the ground surface in monitoring well MW-3. However, groundwater was encountered in monitoring well MW-1 at a depth of about 12.1 feet below the ground surface. Although a survey has not yet been completed to determine the elevation of the monitoring wells so that groundwater elevations can be calculated, the depth to water measurements suggest a southerly groundwater flow direction. This direction varies from the regional pattern, which is to the north-northwest. The test results for the groundwater samples collected from monitoring wells MW-2 and MW-3 (i.e., positioned on the northern portion of the 37 Bittner Street property) appear to indicate that these wells are located hydraulically downgradient of the contaminant source area (i.e., the former filling station), which supports a north-northwest groundwater flow pattern. It is possible that monitoring well MW-1 may be installed in a different water-bearing zone than monitoring wells MW-2 and MW-3. [Note: During the drilling of monitoring well MW-1, the soil cuttings were typically damp to moist until the test boring was advanced to a depth of about 30 feet below the ground surface. In addition, standing water was not encountered in the augers until that depth was reached. When the monitoring well was installed and developed, the water level in MW-1 stabilized at a depth of about 12.1 feet below the ground surface.]

> As shown on Table 1, similar VOCs were detected at comparable concentrations in the air samples recently tested (i.e., AIR-2 through AIR-5). For example, tetrachloroethene (PCE) was measured in each sample tested at approximately the same concentration (i.e., including a sample collected from below the basement slab and air samples collected from the basement, the first floor and the sixth floor, near an open window). The concentration of PCE measured in each sample, and the concentration of benzene in air samples from the basement and first floor, exceeded target values for indoor air established by the United States Environmental Protection Agency (USEPA).

Conclusions and Recommendations

The following are preliminary conclusions and recommendations based upon the work completed to date.

- The test pits advanced during this study did not encounter USTs, but the remnants of an apparent hydraulic lift system and piping that may have been associated with the former filling station (i.e. potentially associated with USTs) were encountered. It is recommended that the hydraulic lift system be removed, cleaned and disposed of in accordance with applicable regulations. At the time of removal, the surrounding soil should be tested to evaluate possible leakage from this system. If necessary, impacted soil should also be removed and disposed of in accordance with applicable regulations. During this study, evidence that the piping encountered in the test pits has impacted the subsurface was not identified. As such, it does not appear that the piping has to be removed, but an environmental concerns that may be encountered during future construction activities. These concerns could include piping that may act as a contaminant source area, USTs that were not encountered in the test pits advanced to date, fill materials or other currently unanticipated potential environmental impacts.
- It does not appear that a residual petroleum source is present within the soil at the Site. This is based upon the test borings and test pits advanced to date, and the absence of petroleum impact (i.e., staining, petroleum odors, PID readings, etc.) until depths of about 8.5 feet to 9.5 feet below the ground surface (i.e., comparable to the top of the groundwater table).

Ms. Kristina Rogers December 17, 2004 Page 4

- The groundwater on the 37 Bittner Street parcel is impacted with gasoline-related compounds and the concentrations measured suggest that additional study and/or remediation may be required. It is recommended that the owner of the Site consult a qualified attorney to determine if there is an obligation to report the groundwater impact to the NYSDEC. Assuming that the spill is reported to the NYSDEC, it is recommended that a data package be prepared summarizing the work completed to date. In addition, a meeting should be scheduled with the NYSDEC to review the data, present plans for additional studies deemed necessary to characterize conditions at the Site, and to discuss possible remedial options. Based upon the available data, it appears that groundwater remediation may be warranted to reduce dissolved VOC concentrations. However, based upon the apparent absence of an ongoing source of contamination (including the absence of free product), and pending NYSDEC approval, it may be possible to pursue closure via a risk-based approach.
- The results of the air testing suggest a ubiquitous distribution of PCE within the Kirstein Building located at 242 Andrews Street, and some apparent impact from benzene. Although the specific source of these compounds is not known, the PCE could be attributable to discharges from the drycleaners located adjacent to the Site. Also, the benzene concentrations detected could be related to vehicle exhaust. Based on historic operations at the Site, it is also possible that the PCE and benzene (and the other VOCs detected in the sub-slab and indoor air samples) could be attributable to past sources of contaminants that were generated at the Site. To address the sub-slab and indoor air quality, additional testing could be warranted. In addition, the air discharge reports for the adjacent drycleaners should also be reviewed. It is possible that a sub-slab ventilation system may be needed for the building, and that any air handling equipment at the Site will need to be of sufficient capacity to ensure that indoor air contaminants are below regulatory criteria.

Please contact DAY if there are any questions regarding this letter.

Very truly yours, Day Environmental, Inc. Inora

Raymond L. Kampff Associate

Attachments

-Site Plan -Table 1: Air Sample Results -Table 2: Soil Sample Results -Table 3: Groundwater Sample Results

RLK3913

DRAFT

TABLE 1

242 ANDREWS STREET ROCHESTER, NEW YORK

AIR SAMPLE RESULTS SUMMARY OF DETECTED VOCS IN MICROGRAMS PER CUBIC METER (µg/m³)

Detected Volatile Organic Compounds	AIR-1 (µg/m³)	AIR-2 (µg/m³)	АІ R-3 (µg/m ³)	AIR-4 (μg/m³)	AIR-5 (µg/m³)	USEPA TARGET INDOOR AIR CONCENTRATION (µg/m ³) ⁽¹⁾	USEPA TARGET SHALLOW GAS CONCENTRATION (µg/m ³) ⁽²⁾
A aptence	16	8.9	17	24	9.9	350	3,500
Acelone	17	ND	1.3	1.3	1.4	700	7,000
Tricnioronuoromethane	12	ND	1.0	14	1.7	1,000	10,000
2-Butanone (MEK)	13	ND	1.4	16	ND	0.31	3.1
Benzene	ND		1.4	1.0		0.01	0.22
Trichloroethene	1.7	ND	ND	ND _	ND _	0.022	0.22
Teluene	93	3.6	4.2	4.5	2.8	400	4,000
Toluene	4.0	1.6	1.8	13	18	0.81	8.1
Tetrachloroethene	4.2	1,0	1.0	0.7	1.0	7.000*	70.000*
m,p-Xylenes	2.3	1.7	2.3	Z.1	1.0	/,000	10,000

Samples analyzed by United States Environmental Protection Agency (USEPA) Method TO-15

= Target Indoor Air Concentration from Table 2C (Risk = 1 X 10⁴) as referenced in the USEPA Draft Guidance for Evaluating the Vapor Intrusion to Indoor Air Pathway from Groundwater (1) and Soil (Subsurface Vapor Intrusion Guidance) dated November 20, 2002.

= Target Shallow Gas Concentration from Table 2C (Risk = 1 X 10⁻⁶) as referenced in the USEPA Draft Guidance for Evaluating the Vapor Intrusion to Indoor Air Pathway from (2) Groundwater and Soil (Subsurface Vapor Intrusion Guidence) dated November20, 2002.

= The USEPA Target Concentrations for m-Xylene and p-Xylene are listed separately and each are 7,000 µg/m³ (Indoor Air) and 70,000 µg/m³ (Shallow Gas).

= Bold denotes a concentration that exceeds the Target Shallow Soil Gas Concentration 1.7

= Shading denotes a concentration that exceeds the Target Indoor Air Concentration

AIR-1: Sub-slab air sample collected November 10, 2004

*

AJR-2: Sub-slab air sample collected December 7, 2004

AIR-3: air sample collected from basement on December 7, 2004

AIR-4: air sample collected from first floor on December 7, 2004

AIR-5: air sample collected from sixth floor on December 7, 2004

DRAFT

TABLE 2

242 ANDREWS STREET ROCHESTER, NEW YORK

SOIL SAMPLE RESULTS STARS-List VOCs and Naphtalene IN MICROGRAMS PER KILOGRAM (µg/Kg), PARTS PER BILLION (ppb)

		Sample and Location						NYSDEC TAGM 4046	
	01	02	03	04	05	06	07	RECOMMENDED	
Volatile Organic Compounds	TB-1	TB-4	TB-11	TB-12	TP-1	TB-18	TB-17	SOIL CLEANUP	
	(8'-12')	(10'-12')	(10'-11')	(8'-12')	(3')	(10'-12')	(8'-10')	OBJECTIVE (PPB)(")	
STARS VOCs									
Benzene	ND	ND	ND	ND	ND	ND	ND	60	
n-Butylbenzene	ND	ND	ND	ND	ND	ND	ND	10,000	
sec-Butylbenzene	179	87.4	75.2	ND	ND	ND	22	10,000	
tert-Butvlbenzene	ND	ND	ND	ND	ND	ND	ND	10,000	
Ethylbenzene	327	ND	ND	3,480	ND	ND	ND	5,500	
n-Propylbenzene	898	374	149	6,180	ND	ND	ND	3,700	
Isopropylbenzene	368	80.3	20.8	2,700	ND	ND	ND	2,300	
p-isopropyltoluene	312	132	39.7	1,460	ND	ND	42	10,000	
Toluene	ND	ND	ND	194	ND	ND	ND	1,500	
1.2.4-Trimethylbenzene	3,330	324.0	ND	23,500 E	ND	ND	ND	10,000	
1 3.5-Trimethylbenzene	2,650	147	ND	12,800	ND	ND	ND	3,300	
Xylenes (total)	322	ND	ND	16,500	ND	ND	ND	1,200	
Total STARS VOCs	8,386	1,144.7	285	66,814	ND	ND	64	NA	
Total VOC TICs	23,957	8,393	11,980	146,310	200.1	ND	5,435	N/A	
TOTAL TCL/STARS VOCs & TICs	32,343	9537.7	12,265	213,124	200.1	ND	5,499	10,000	
Naphthalene	437	ND	ND	7,980	ND	ND	ND	13,000	

voc = Volatile Organic Compound

= Tentatively Identified Compounds TiCs

STARS = Spill Technology and Remedation Series

 \thickapprox Not detected at concentration above the reported analytical laboratory detection limit ND

= Not applicable N/A

= Recommended soil cleanup objectives (RSCOs) as referenced in January 24, 1994, NYSDEC Technical and Administrative Guidance Memorandum: Determination of Soil (1) Cleanup Objectives and Cleanup Levels (TAGM 4046) and addendum tables dated August 2001.

= Concentration detected exceeds RSCO 2,700

= Estimated Concentration Е

TABLE 3

242 ANDREWS STREET ROCHESTER, NEW YORK

GROUNDWATER SAMPLES (Collected December 10, 2004) SUMMARY OF STARS-List VOCS, NAPHTHALENE AND LEAD IN MICROGRAMS PER LITER (μg/L), PARTS PER BILLION (ppb)

	Sa	mple Locati	NYSDEC TOGS 1.1.1	
				GROUNDWATER
Detected Constitutent		MW-2	NANA/ O	STANDARD OR
	MW-1*		IVIVY-3	GUIDANCE VALUE
				(PPB) ⁽¹⁾
Volatile Organic Compounds				
Benzene	ND	ND	51.3	1
Ethylbenzene	ND	934	1,400	5
n-Propylbenzene	ND	214	210	5
Isopropylbenzene	ND	115	115	5
Toluene	ND	ND	34	5
1,2,4-Trimethylbenzene	5.03	1,900	970	5
1,3,5-Trimethylbenzene	ND	657	592	5
Xylenes	ND	1,080	421	5
Naphthalene	ND	599	684	10
Metals				
Lead	NT	49	24	25

VOC = Volatile Organic Compound

STARS = Spill Technology and Remediation Series

ND = Not detected at concentration above the reported analytical laboratory detection limit

N/A = Not applicable

NT = Not Tested

= MW-1 was analyzed for USEPA Target Compound List (TCL) and STARS-List VOCs. MW-2 and MW-3 were analyzed for STARS-List VOCs.

 (1) = New York State Department of Environmental Conservation (NYSDEC) Technical and Operational Guidance Series 1.1.1 Ambient Water QualityStandards and Guidance Values and Groundwater Effluent Limitations (TOGS 1.1.1) dated June 1998

1,800 = Concentration detected exceeds groundwater standard or guidance value

DRAFT



.

PHASE II ENVIRONMENTAL SITE ASSESSMENT 242 ANDREWS STREET ROCHESTER, NEW YORK

Prepared by:	Day Environmental, Inc. 40 Commercial Street Rochester, New York 14614
Prepared for:	Winn Development 120 Corporate Woods, Suite 230 Rochester, New York 14623
Project Number:	3567S-04
Date:	November 2004

TABLE OF CONTENTS

1.0	INTE	RODUCTION		1
	1	.1 Background	1	1
	1	.2 Purpose and	l Scope of Work	.1
2.0	PHAS	SE II ENVIRO	ONMENTAL STUDIES	3
	2	.1 FOIL Requ	est	.3
	2	.2 Sub-Slab A	ir Sample	.3
	2	.3 Field Obser	vations	3
	2	.4 Test Boring	JS	.4
	2	.5 Analytical I	Laboratory Testing	.4
3.0	FIND	INGS		.6
	3	.1 FOIL Respo	onse	.6
	3	.2 Subsurface	Conditions	.6
	3	.3 Analytical I	Laboratory Test Results	.7
	3	.4 Extent of Pe	stroleum-Impacted Soil/Fill	.7
4.0	CON	CLUSIONS A	ND RECOMMENDATIONS	.9
Appen	dices:			
Figure	S			
		Figure 1	Locus Plan	
		Figure 2	Site Plan	
Tables				
Tables		Table 1	Summary of VOCs in the Sub-Slab Air Sample	
Tables		Table 1 Table 2	Summary of VOCs in the Sub-Slab Air Sample Summary of STARS VOCs and Naphthalene in Soil Samples	
<u>Tables</u> Appen	dix A	Table 1 Table 2 FOIL respons	Summary of VOCs in the Sub-Slab Air Sample Summary of STARS VOCs and Naphthalene in Soil Samples se	
<u>Tables</u>	dix A	Table 1 Table 2 FOIL respons	Summary of VOCs in the Sub-Slab Air Sample Summary of STARS VOCs and Naphthalene in Soil Samples se	
<u>Tables</u> Appen Appen	dix A dix B	Table 1 Table 2 FOIL respons Test Boring I	Summary of VOCs in the Sub-Slab Air Sample Summary of STARS VOCs and Naphthalene in Soil Samples se	

Appendix C Analytical Laboratory Report and Chain-of-Custody Documentation

1.0 INTRODUCTION

DAY Environmental, Inc. (DAY) was retained by Winn Development (Winn) to conduct a Phase II Environmental Site Assessment (Phase II ESA) at 242 Andrews Street, Rochester, New York (Site). A Project Locus is included as Figure 1 and a Site Plan is included as Figure 2.

1.1 Background

The approximate 0.65-acre Site is currently improved with an approximate 56,000 square foot, sixstory building with a basement and sub-basement. The balance of the Site is paved and used for parking. The building has been vacant since at least 1997; however, the parking lots are being used. As shown on Figure 2, the Site consists of two parcels comprised of the footprint of the building addressed 234 Andrews Street (SBL# 106.790-01-024, referred to as "Parcel 1") and 37 Bittner Street (SBL# 106.790-01-022, referred to as "Parcel 2"). The Site is currently bound to the north by Kovalsky-Carr Electric Supply; to the south by Andrews Street, with Silver Cleaners and Epstein Dry Cleaning and Shirt Service beyond; to the east by Bittner Street with the YWCA beyond and to the west by a parking lot for Kovalsky-Carr with the Andrews Building (office building) beyond.

DAY completed an Environmental Transaction Screen Assessment (DAY File #3394E-04) for the Site. The Environmental Transaction Screen Assessment report dated February 12, 2004 identified a filling station formerly located on a portion of the Site as a recognized environmental condition (REC). Specifically, review of a 1951 Sanborn fire insurance map indicated that a filling station with two gasoline tanks in proximity was formerly located in the northern portion of Parcel 2 (i.e., an area that is currently covered with an asphalt paved parking lot). The status of the tanks and subsurface conditions in this portion of the Site could not be determined based upon work completed in conjunction with the Environmental Transaction Screen Assessment.

In addition to the REC, a dry cleaning facility identified as a RCRA Generator is located south of the Site. The impact of this dry cleaning facility on the Site (if any) was not evaluated as part of the Environmental Transaction Screen Assessment.

1.2 Purpose and Scope of Work

The purpose of DAY's work was to conduct limited studies to evaluate the REC associated with the former filling station reportedly located on the Site and to evaluate the potential impact of the adjacent dry cleaning facility on the building at the Site.

To achieve the stated purpose, the following scope of work was implemented:

- A review of various public records pertaining to 234 250 Andrews Street obtained through the Freedom of Information Law (FOIL).
- The collection and chemical analysis of a sub-slab air sample from the basement of the building at the Site.

- The completion of a site visit and magnetic locator survey.
- The retention of a subcontractor to advance test borings to evaluate subsurface conditions in the reported area of the filling station formerly located on the Site.
- The submittal of selected soil samples from the test borings for analytical laboratory testing.
 - The review and evaluation of the data collected during the above activities to prepare this report of findings.

2.0 PHASE II ENVIRONMENTAL STUDIES

This section describes the regulatory record research, fieldwork and analytical laboratory testing completed as part of this study.

2.1 FOIL Request

On October 15, 2004, a FOIL request was sent to the City of Rochester building and fire departments, Monroe County Department of Health (MCDOH) and the New York State Department of Environmental Conservation (NYSDEC) requesting information pertaining to the Site. Copies of the FOIL responses obtained to date and other relevant documentation are included in Appendix A.

2.2 Sub-Slab Air Sample

On November 9, 2004, DAY drilled a ¹/₂-inch hole through the concrete slab (approximately 9 inches thick) and into granular material beneath the slab in the basement of the building at the Site. This hole was positioned approximately 30 feet from the southeast corner of the building and directly across the street from the dry cleaning facility located south of the Site (refer to Figure 2). Following drilling, flexible tubing was inserted through the hole extending into the sub-grade. The remaining annulus was grouted using anchoring cement. The tubing was then connected to a regulator attached to a Summa canister. The cement was allowed to cure overnight.

On November 10, 2004, DAY opened the valve on the Summa canister to collect a sample. [Note: Prior to delivery to the Site, the analytical laboratory lab calibrated the regulator on the canister such that it would continually draw air at a consistent rate into the canister over a 6-hour period.] Approximately six hours after the canister was opened, DAY closed the valve, removed the tubing from the slab and filled the hole in the floor with anchoring cement. The Summa canister was then delivered to the analytical laboratory for testing (refer to Section 2.5).

2.3 Field Observations

On November 9, 2004, DAY used a Shoenstadt Model GA-52A magnetic locating device in an attempt to identify magnetic anomalies in the northern portion of the Site (i.e., within a current parking lot that was reported to be the location of a former filling station and generally within the northern limits of Parcel 2). Several areas of magnetic anomaly were identified using the magnetic locating device, however the specific source of these anomalies (e.g., buried underground storage tanks (USTs), metal fragments within the fill, etc.) could not be determined. During the magnetic locator survey, two depressions measuring approximately 3 feet by 5 feet were observed in the asphalt pavement of the parking lot (i.e., in proximity of test boring location TB-2 and TB-8; refer to Figure 2). The cause of these approximate 4-inch deep depressions is not known (e.g., associated with current or former USTs or some other source).

2.4 Test Borings

DAY retained SLC Environmental Services, Inc. (SLC) to advance test borings at the Site using direct-push drilling techniques. On November 9, 2004, SLC advanced thirteen (13) test borings using a truck-mounted Simco Earthprobe 2000 direct-push drill rig. The approximate locations of these test borings are presented on Figure 2 and these locations are further described below:

- Test Borings TB-1, TB-3, TB-10, TB-11 were advanced in the reported location of the former filling station and in areas where magnetic anomalies were identified.
 - Test Borings TB-2 and TB-8 were advanced where depressions in the asphalt were observed.
 - Test borings TB-4, TB-5, TB-6, TB-7, TB-9, TB-10, TB-11, TB-12 and TB-13 were advanced to evaluate subsurface conditions throughout the Site and to assist in delineating the extent of apparent petroleum-impact identified in test borings advanced in the reported location of the former filling station.

In each of the test borings advanced during this study, soil samples were collected in consecutive intervals extending from the ground surface to depths ranging from 6.0 feet below land surface (BLS) to 14.0 feet BLS where equipment refusal was encountered. These direct-push samples were collected using a 4-foot long sampling device equipped with disposable inner plastic sleeves.

A DAY representative observed the soil and fill samples collected in order to develop a stratigraphic description of the subsurface conditions and to evaluate the recovered samples for evidence of contamination (i.e., odors, staining, etc.). The ambient air space above portions of the soil/fill samples was screened using a MiniRae 2000 photoionization detector (PID). Prior to use, the PID was calibrated using an isobutylene gas standard. The DAY representative recorded pertinent information for each test boring including PID measurements and subsequently prepared test boring logs describing subsurface conditions and observations. Copies of the test boring logs prepared are included in Appendix B.

Upon completion, the test borings were filled with drill cuttings and capped with an asphalt patch. However, test borings TB-4, TB-5, TB-6 and TB-13 were left open until the end of the day prior to backfilling. A bailer was lowered down the borehole in an attempt to measure the static groundwater level. Three of the four borings collapsed and a groundwater measurement could not be obtained, but groundwater was observed at a depth of about 10.5 feet BLS in test boring TB-5.

2.5 Analytical Laboratory Testing

The sub-slab air and soil/fill samples collected during this study were submitted to Paradigm Environmental Services, Inc. (Paradigm) under chain-of-custody control for analytical laboratory testing. The following analytical laboratory testing program was implemented as part of this study:

DAY ENVIRONMENTAL, INC.

- One sub-slab air sample (designated AIR-1) was submitted for volatile organic compounds (VOCs) using United States Environmental Protection Agency (USEPA) Method TO-15 [Note: The TO-15 analysis was completed by Colombia Analytical Services, Simi Valley, California (i.e., a subcontractor to Paradigm)];
- Four soil/fill samples were submitted for NYSDEC Spill Technology and Remediation Series (STARS)-list VOCs including the top twenty tentatively identified compounds (TICs) using USEPA Method 8260;
- One soil/fill sample was submitted for STARS-list semi-volatile organic compounds (SVOCs) using USEPA Method 8270; and
- One soil/fill sample was submitted for total lead using USEPA Method 6010.

Copies of the analytical laboratory reports submitted by Paradigm and executed chain-of-custody documentation are included in Appendix C.

3.0 FINDINGS

This section presents the findings of this Phase II ESA.

3.1 FOIL Response

The City of Rochester FOIL response did not indicate the existence or closure of tanks at the Site. As shown in Appendix C, the information obtained from the City of Rochester is primarily related to code violations. The MCDOH did not have documents pertaining to the Site and as of the date of this report the NYSDEC has not responded to the FOIL request. [Note: NYSDEC spills and petroleum bulk storage (PBS) record checks were included in the Environmental Transaction Screen Assessment report. Although information was not available for the Site, these records described conditions on nearby properties.] It is not anticipated that the NYSDEC has additional records pertaining to the Site.

3.2 Subsurface Conditions

Fill material was encountered in each test boring advanced during this study. This fill extended from the ground surface and it generally consisted of asphalt, sand and gravel. In test borings TB-1, TB-2, TB-7, TB-8, TB-10, TB-11, TB-12 and TB-13 brick fragments were intermixed in the fill material. A piece of a tar-like substance was observed within the fill in test boring TB-3; ash and cinders were observed in the fill within test boring TB-5 and TB-7 and glass and roots were observed in the fill collected from test boring TB-13. The fill ranged in thickness from about one foot in test borings TB-12 and TB-13 to about eight feet in test boring TB-1. Based on the observation of the samples collected from the test borings advanced during this study, the average thickness of fill material at the Site is approximately four feet.

Evidence of UST systems (e.g., metal fragments, piping, etc.) was not identified in the samples collected from the test borings advanced during this study (i.e., including test borings TB-2 and TB-8 advanced adjacent to the depressions observed in the asphalt pavement).

Indigenous soil beneath the fill material generally consisted of sand with lesser components of silt and gravel. The indigenous soil extended beneath the fill (i.e., ranging in thickness from about one to eight feet with an average thickness of about four feet) to depths of about six to fourteen feet BLS, where equipment refusal was encountered. The source of this refusal is not known, but it could be representative of bedrock or a dense soil deposit (e.g., glacial till) that could not be penetrated by the direct-push sampling equipment. Groundwater was measured in the open borehole of test boring TB-5 at a depth of about 10.5 feet BLS. However, based upon observations of the soil samples it is suspected that stabilized groundwater may occur at depths of about 9 to 10 feet BLS.

PID readings above background (i.e., 0.0 ppm) were measured in seven of thirteen test borings advanced during this study. The peak PID readings measured during this study ranged from 20.5 ppm in test boring TB-11 at a depth of about 9.5 feet BLS and 1,318 ppm in test boring TB-1 at a
depth of about 9.0 feet BLS. Petroleum-type odors and staining were observed in 7 of 13 test borings (i.e., the same test borings containing samples with PID readings above background). Specifically, evidence of apparent petroleum-impact was detected in test borings TB-1, TB-2, TB-3, TB-4, TB-5, TB-11 and TB-12 (refer to Figure 2).

3.3 Analytical Laboratory Test Results

The results of the analytical laboratory testing conducted as part of this Phase II ESA are presented in this section.

Sub-Slab Air Sample Results

VOCs were detected above the detection limits utilized by the analytical laboratory in the one sub-slab air sample tested during this study. As shown on Table 1, the VOCs acetone; trichlorofluoromethane; 2-butanone (MEK); trichloroethene; toluene; tetrachloroethene; and m, p-xylenes were detected in the sample. A concentration of 1.7 μ g/m³ of trichloroethene was measured and this value exceeds both the target shallow soil gas concentration and the target indoor air concentration of 0.22 μ g/m³ and 0.022 μ g/m³, respectively. A concentration of 4.2 μ g/m³ of tetrachloroethene exceeds the target indoor air concentration of 0.81 μ g/m³ as referenced in the USEPA *Draft Guidance for Evaluating the Vapor Intrusion to Indoor Air Pathway from Groundwater and Soil (Subsurface Vapor Intrusion Guidance)* dated November 20, 2002.

Soil/Fill Sample Results

SVOCs were not detected above the detection limits utilized by the analytical laboratory in the one sample tested during this study. The sample tested for total lead had a concentration of 3.79 ppm. This concentration is below the to Recommended Soil Cleanup Objective (RSCO) of 500 ppm referenced in the NYSDEC document titled: "Division of Technical and Administrative guidance Memorandum: *Determination of Soil Cleanup Objectives and Cleanup Levels*" (TAGM 4046).

STARS list VOCs and VOC TICs were detected in each of the four samples tested during this study. Naphthalene was detected in 2 of 4 soil samples analyzed. As shown on Table 2, the VOCs sec-Butylbenzene; Ethylbenzene; n-Propylbenzene; Isopropylbenzene; p-Isopropyltoluene; Toluene; 1,2,4-Trimethylbenzene; 1,3,5-Trimethylbenzene; and Xylene were detected at concentrations exceeding RSCOs established in TAGM 4046. The total concentration of specific STARS-list VOCs ranged between 285 parts per billion (ppb) (sample 03/TB-11) and 66,184 ppb (sample 04/TB-12). The total VOCs (including TICs) ranged between 9,537.7 ppb (sample 02/TB-4) and 213,124 ppb (sample 04/TB-12). With the exception of sample 02/TB-4 the total VOC concentration (including TICs) exceeds the RSCO of 10,000 ppb established in TAGM 4046.

3.4 Extent of Petroleum-Impacted Soil/Fill

In the test borings exhibiting petroleum-impact, the initial evidence of impact appears to occur at depths of about 8.5 feet to 9.5 feet BLS. Available information suggests that groundwater may occur at depths of about 9 to 10 feet BLS, but groundwater monitoring wells are required to confirm this assumption. The petroleum-impacted soil appears to extend to the bottom of the test borings (i.e., where equipment refusal was encountered). However, in some of the test borings the PID readings appeared to decrease with depth. The source of the petroleum-impacted soil was not specifically defined during this study (i.e., leaking USTs were not identified during the work completed), but the former filling station is a likely source. [Note: Based upon the analytical laboratory test results, the VOCs detected appear to be typical of "older" gasoline (e.g., MTBE, a relatively recent gasoline additive, was not detected).]

Based upon the test borings advanced during this study, the analytical laboratory test results and observations/PID readings, it appears that an area on the Site measuring about 65 feet in a direction generally parallel to Bittner Street and about 50 feet in a general east to west direction contains soil/fill material with VOC concentrations exceeding RSCOs. However, no test borings were advanced on the adjacent property to the north or within the Bittner Street right-of-way to the east to evaluate petroleum-impact in these areas.

The area containing soil/fill material with VOC concentrations exceeding RSCOs appears to be predominately located within the northern portion of Parcel 2 of the Site. The soil samples collected during this study from test borings TB-6, TB-7 and TB-8 did not exhibit evidence of petroleum-impact. These test borings are positioned between the Kirsten Building and the area of petroleum-impacted soil defined above.

4.0 CONCLUSIONS AND RECOMMENDATIONS

Based upon the work completed during this Phase II ESA, the following items can be concluded.

- The sub-slab air sample collected from the basement of the building at the Site exhibited evidence of trichloroethene and tetrachloroethene above the draft guidance values in the subsurface soils that appears to be attributable to the dry cleaning facility to the south of the Site. Since the concentration of trichloroethene is above the target shallow soil gas concentration, the potential exists that trichloroethene may be present in the ambient air in the building.
- The City of Rochester FOIL response received to date did not indicate the existence or closure of tanks at the Site. It does not appear that the MCDOH or the NYSDEC have additional documents pertaining to environmental conditions at the Site.
- Thirteen test borings were advanced to depths up to 14 feet BLS to evaluate subsurface conditions at the Site.
- Fill material extending from the ground surface to depths of about one foot to about eight feet
 was encountered in each test boring advanced during this study. The average thickness of fill
 material encountered in the test borings advanced during this study is approximately four
 feet. The fill generally consists of sand and gravel with intermixed asphalt and lesser
 amounts of brick fragments, ash, cinders and glass in some locations.
- Indigenous soil beneath the fill material generally consists of sand with lesser components of silt and gravel. The indigenous soil extended beneath the fill to depths of about six to fourteen feet BLS, where equipment refusal was encountered. The source of equipment refusal could not be determined as part of this study, but it may be attributable to bedrock or a dense indigenous soil deposit (e.g., glacial till).
- Groundwater monitoring wells were not installed during this study, but a water level measurement of 10.5 feet BLS was measured within a borehole left open following drilling. Also, based upon observations of the soil samples, it is suspected that stabilized groundwater may occur at depths of about 9 to 10 feet BLS.
- Evidence of petroleum-impact (i.e., odors, staining, elevated PID readings, etc.) was detected in seven of the thirteen test borings advanced during this study. STARS list VOCs and VOC TICs were detected in each of the four soil samples tested during this study. The concentrations measured in three of these samples exceed the RSCOs established by the NYSDEC.
- In the test borings exhibiting petroleum-impact, the initial evidence of impact appears to occur at depths of about 8.5 feet to 9.5 feet BLS. The petroleum-impacted soil appears to extend to the bottom of the test borings (i.e., where equipment refusal was encountered).

However, in some of the test borings the PID readings appeared to decrease with depth.

- The source of the petroleum-impacted soil was not specifically determined during this study (i.e., leaking USTs were not encountered during the work completed), but the filling station that was formerly located at the Site is a likely source.
- It appears that at a minimum an area on the Site measuring about 65 feet in a direction generally parallel to Bittner Street (i.e., generally north to south) and about 50 feet in a general east to west direction contains soil/fill material with VOC concentrations exceeding RSCOs established by the NYSDEC. This area appears to be predominately located within the northern portion of Parcel 2 of the Site.
- Soil samples collected from test borings positioned between the Kirstein Building and the area of petroleum-impacted soil predominately located in the northern portion of Parcel 2 did not exhibit evidence of petroleum-impact.

Based upon the findings of this Phase II ESA, it is recommended that additional studies be performed to assess the need for and type of remediation (if any) required to address the apparent petroleum-impact identified at the Site as well as the presence of chlorinated solvents in the indoor air quality in the building. This work should include additional studies to confirm that no USTs, or other potential on-going sources of petroleum-impact, remain at the Site.

Additional studies should also include monitoring additional sub-slab locations at the Site to define the extent of trichloroethene and tetrachloroethene. Air samples should be collected in the ambient air in the basement to correlate the data collected below the slab to ambient air in the building. Finally, a background sample should be collected at the Site away from basement.

Additional studies consisting of test borings and groundwater monitoring wells and appropriate analytical laboratory testing should be done to better characterize subsurface conditions and delineate the extent of petroleum-impact. Depending on the results of these studies, remediation may be required to address petroleum-impact (i.e., source removal).

Based upon the intended use of the portion of the Site where petroleum-impact has been detected as a paved parking lot and the depth/extent of petroleum-impact, it is also possible that only limited remediation (or monitoring) will be required for the Site. This would require acceptance by the NYSDEC and completion of a risk-based assessment to document that the petroleumimpacted material at the Site does not pose an unacceptable risk.

FIGURES





·

.

TABLES

TABLE 1

242 ANDREWS STREET ROCHESTER, NEW YORK

SUMMARY OF VOCS IN MICROGRAMS PER CUBIC METER (µg/m³)

SUB-SLAB AIR SAMPLE (Collected November 10, 2004)

Detected Volatile Organic Compounds	AIR-1 (μg/m ³)	USEPA TARGET INDOOR AIR CONCENTRATION (µg/m ³) ⁽¹⁾	USEPA TARGET SHALLOW GAS CONCENTRATION (µg/m ³) ⁽²⁾
Acetone	16	350	3,500
Trichlorofluoromethane	1.7	700	7,000
2-Butanone (MEK)	13	1,000	10,000
Trichloroethene	. 1.7	0.022	0.22
Toluene	9.3	400	4,000
Tetrachloroethene	4.2	0.81	8.1
m,p-Xylenes	2.3	7,000*	70,000*

Samples analyzed by United States Environmental Protection Agency (USEPA) Method TO-15

(1) = Target Indoor Air Concentration from Table 2C (Risk = 1 X 10⁻⁶) as referenced in the USEPA Draft Guidance for Evaluating the Vapor Intrusion to Indoor Air Pathway from Groundwater and Soil (Subsurface Vapor Intrusion Guidance) dated November 20, 2002.

(2) = Target Shallow Gas Concentration from Table 2C (Risk = 1 X 10⁻⁶) as referenced in the USEPA *Draft Guidance for Evaluating the Vapor Intrusion to Indoor Air Pathway from Groundwater and Soil (Subsurface Vapor Intrusion Guidance)* dated November20, 2002.
 The USEPA Target Concentrations for m-Xylene and p-Xylene are listed separately and each are 7,000 w/m³ (Indeor

= The USEPA Target Concentrations for m-Xylene and p-Xylene are listed separately and each are 7,000 μ g/m³ (Indoor Air) and 70,000 μ g/m³ (Shallow Gas).

1.7 = Bold denotes a concentration that exceeds the Target Shallow Soil Gas Concentration

= Shading denotes a concentration that exceeds the Target Indoor Air Concentration

TABLE 2

242 ANDREWS STREET ROCHESTER, NEW YORK

SUMMARY OF STARS VOCS AND NAPHTHALENE IN MICROGRAMS PER KILOGRAM (µg/Kg), PARTS PER BILLION (ppb)

		Sample an		NYSDEC TAGM 4046	
Volatile Organic Compounds	01 TB-1 (8'-12')	02 TB-4 (10'-12')	03 TB-11 (10'-11')	04 TB-12 (8'-12')	RECOMMENDED SOIL CLEANUP OBJECTIVE (PPB) ⁽¹⁾
STARS VOCs					
Benzene	ND	ND	ND	ND	60
n-Butylbenzene	ND	ND	ND	ND	10,000
sec-Butylbenzene	179	87.4	75.2	ND	10,000
tert-Butylbenzene	ND	ND	ND	ND	10,000
Ethylbenzene	327	ND	ND	3,480	5,500
n-Propylbenzene	898	374	149	6,180	3,700
lsopropylbenzene	368	80.3	20.8	2,700	2,300
p-Isopropyltoluene	312	132	39.7	1,460	10,000
Toluene	ND	ND	ND	194	1,500
1,2,4-Trimethylbenzene	3,330	324.0	ND	23,500 E	10,000
1,3,5-Trimethylbenzene	2,650	147	ND	12,800	3,300
Xylenes (total)	322	ND	ND	16,500	1,200
Total STARS VOCs	8,386	1,144.7	285	66,814	NA
Total VOC TICs	23,957	8,393	11,980	146,310	N/A
TOTAL TCL/STARS VOCs & TICs	32,343	9537.7	12,265	213,124	10,000
Naphthalene	437	ND	ND	7,980	13,000

SOIL SAMPLES (Collected November 9, 2004)

VOC = Volatile Organic Compound

TICs = Tentatively Identified Compounds

STARS = Spill Technology and Remedation Series

ND = Not detected at concentration above the reported analytical laboratory detection limit

N/A = Not applicable

(1) = Recommended soil cleanup objectives (RSCOs) as referenced in January 24, 1994, NYSDEC Technical and Administrative Guidance Memorandum: Determination of Soil Cleanup Objectives and Cleanup Levels (TAGM 4046) and addendum tables dated August 2001.

2,700 = Concentration detected exceeds RSCO

E = Estimated Concentration

APPENDIX A

.

FOIL RESPONSE



AN AF:

October 15, 2004

Ms. Kim Shutts NYS DEC 6274 East Avon-Lima Road Avon, New York 14414

RE: FOIL REQUEST JOB NUMBER 2890AUD

Dear Ms. Shutts:

This letter is a Freedom of Information Law request for the following location:

OWNER

PROPERTY

"

I.F.F. Lisbon Asset Advisory Services, LLC

Kirsten Building 242-250 Andrews Street Rochester, NY

Kirsten Optical Manufacturing

We would appreciate being informed of any environmental records on the above site.

If you have any questions concerning this matter, please do not hesitate to call. Thank you for your cooperation.

Very truly yours,

M. Meller

Sandi M. Miller

SMM/s

*Map Attached

FR4945

www.dayenvironmental.com

60 EAST 42[™] STREET, SUITE 1641 NEW YORK, NEW YORK 10165-1617 (212) 986-8645 FAX (212) 986-8657 0

MONROE Applicatio M COUNTY Monroe Cou	on for Access to Records laintained at the unty Department of Health
Return To: FOI Officer, Room 976 Monroe County Department of 111 Westfall Road P.O. Box 92832 Rochester, New York 14692-893	Fax: (505) 274 - 6098 Health 32
I hearby apply to: [X] inspect	[$1/2$] obtain a copy of the following record(s) *:
Balenter, Ny	MCDOH RECORD
Please print name	Jandi M. Neller Signature
Representing (if applicable)	$\frac{10-15-04}{1000}$
Mailing address Richester NY 14614 City, State, Zip code	Telephone number 454-0825 Fax number
FOR AGENCY USE ONLY:	
 Approved Denied Denied For the reason(s) checked below: Confidential Disclosure Part of investigatory files Unwarranted invasion of personal privacy Record is not maintained by this agency Records for which this agency is legal custodian cannot be found Exempted by statute other than Freedom of Information Act Other: 	FOI Number:

*A Record Duplication charge of \$.25 per (8.5 x 11") page is payable to Monroe County Department of Health.

NCTICE: You have the right to appeal denial of this application.

earby request an appeal__

Signature

Department of Public Health

Monroe County, New York



Maggie Brooks County Executive

Andrew S. Doniger, M.D., M.P.H. Director

November 3, 2004

Day Environmental, Inc. 40 Commercial Street Rochester, New York 14614 Attn: Sandi M. Miller

35675-04

RE: Freedom of Information Request HD04-270 242-250 Andrews Street, Rochester (C)

Dear Ms. Miller:

This is in follow-up to your Freedom of Information Request for documents maintained in Monroe County Department of Health files, received at the Department of Health on October 15, 2004.

Staff at the Monroe County Department of Health searched the files and were unable to locate information regarding the above-referenced request. We contacted you on October 25, 2004 to discuss your request. An additional response was made on November 3, 2004 in response to your telephone request.

We now consider this request closed.

If you have future needs, please feel free to contact my office at 585-274-6067.

Sincerely

Richard S. Elliott, P.E. FOI Officer

RSE: ey c: file

APPENDIX B TEST BORING LOGS

.

BORING NUMBER: TB-1

Project: 242 Andrews Street, Rochester, NY DAY Representative: J. Scherer Drilling Contractor: SLC Environmental Services

Drilling Rig: Simco Earthprobe 200

Sampling Method: Direct Push

Project No: 3567S-04 Boring Location: See Site Plan

Ground Surface Elevation: NA

Start Date: 11/09/04

Borehole Diameter: 2.0"

Water Level: -----

Т

Datum: NA Completion Date: 11/09/04 Borehole Depth: 14.0'

Completion Method: Backfilled with cuttings, asphalt patch

Depth (feet)	Blows per 0.5'	Number	Depth (feet)	% Recovery	N-Value or RQD %	Peak PID Reading (ppm)	Well Installation Log	Sample Description
- - 1-				-		0.0		Asphalt, Brick, Sand, some Gravel (FILL)
2	NA	S-1	0-4	75	NA			Brown medium to coarse Sand some Gravel (FILL)
3-						0.0		some Silt
4 								
5						0.0 -		trace Brick
6 	NA	S-2	4-8	100	NA	0.0		
7						0.0		
8						67.1		Gray fine to medium SAND, some Silt, little Gravel, petroleum-type odor, moist
9 				-		1318		
10	NA	S-3	8-12	100	NA	1182		
11						164		
12		S 4	12.14	100	NA	72.2		Tan fine SAND, some Silt, petroleum-type odor
	NA	3-4	12-14	100		402		
15								Refusal at 14.0'
16	-							
17								
18								
19								
20-								

File: 3567b1.log

BORING NUMBER: TB-2

Project: 242 Andrews Street, Rochester, NY DAY Representative: J. Scherer Drilling Contractor: SLC Environmental Services Drilling Rig: Simco Earthprobe 200 Sampling Method: Direct Push Project No: 3567S-04 Boring Location: See Site Plan Ground Surface Elevation: NA Start Date: 11/09/04 Borehole Diameter: 2.0"

Datum: NA Completion Date: 11/09/04 Borehole Depth: 13.0'

Completion Method: Backfilled with cuttings, asphalt patch Water Level: ----

Depth (feet)	Blows per 0.5'	Number	Depth (feet)	% Recovery	N-Value or RQD %	Peak PID Reading (ppm)	Well Installation Log	Sample Description
						0.0		Asphalt, black medium to coarse Sand, Brick (FILL)
,						0.0		
27	NA	5-1	0-4	60	NA			
3						0.0		
4						· · ·		Tan, fine SAND, some Silt, damp
5 -						0.0 🔗		
6	NA	S-2	4-8	100	NA	0.0		
7						0.0		
8								petroleum-type odor, black staining Gray fine SAND
9-						52.6		
10	NA	S-3	8-11	100	NA	74.6		
 - - 11-+						383		
	NA	S 4	11 12	100	ΝΔ	232		some Gravel
12	NA	3-4	11-13	100	NA	402		
13								Refusal at 13.0'
14								
15								
16								
17								
18-1								
19								
20-								

File: 3567b2.log

BORING NUMBER: TB-3

Project: 242 And	rews Street, Roche	ester, NY		Project No Boring Lo	Project No: 3567S-04 Boring Location: See Site Plan						
Drilling Contrac	tor: SLC Environn	nental Services		Ground Surface Elevation: NA Datum: NA							
Drilling Rig: Sim	ico Earthprobe 200)		Start Date: 11/09/04 Completion Date: 11/09/04							
Sampling Metho	od: Direct Push			Borehole Diameter: 2.0" Borehole Depth: 14.0'							
Completion Met	thod: Backfilled wi	ith cuttings, aspha	it patch	Water Level:							
			T								

Depth (feet)	Blows per 0.5'	Number	Depth (feet)	% Recovery	N-Value or RQD %	Peak PID Reading (ppm)	Welf Installation Log	Sample Description
111						0.0		Asphalt, Gravel, black Sand, damp (FILL)
1						2.8		niece of tar-like substance
2	NA	S-1	0-4	90	NA	0.0		
3						0.0		
4								Brown medium to coarse SAND, some Silt, trace Gravel, damp
5						0.0		
6	NA	S-2	4-8	100	NA	·		
7-						0.0		
8								
9-1-						40.9		petroleum-type odor, staining, moist
- - 10	NA	S-3	8-12	100	NA	399		
11						816		
12						189		
			10.44	100		165		transition to tan
	NA	5-4	12-14	100	NA	41.9		
14-+ - -								Refusal at 14.0'
15								
16								
17-								
18					4			
19-1								
20								
20								

File: 3567b3.log

BORING NUMBER: TB-4

Project: 242 Andrews Street, Rochester, NY	Project No: 3567S-04						
DAY Representative: J. Scherer	Boring Location: See Site Plan						
Drilling Contractor: SLC Environmental Services	Ground Surface Elevation: NA	Datum: NA					
Drilling Rig: Simco Earthprobe 200	Start Date: 11/09/04 Completion Date: 11/09/04						
Sampling Method: Direct Push	Borehole Diameter: 2.0" Borehole Depth: 13.0'						
Completion Method: Backfilled with cuttings, asphalt patch	Water Level:						

Depth (feet)	Blows per 0.5'	Number	Depth (feet)	% Recovery	N-Value or RQD %	Peak PID Reading (ppm)	Weil Installation Log	Sample Description
						0.6		Asphalt, black medium to coarse Sand, trace Gravel (FiLL)
2	NA	S-1	0-4	60	NA	0.0		
3						0.0		Dark brown SILT, some Clay, damp
4								
5-						- 0.0 · ·		Brown fine to medium SAND, trace Silt, trace Gravel, damp
6 	NA	S-2	4-8	90	NA	0.0		
7-						0.0		
8						400		
9-						100		transition to tan, petroleum-type odor, moist
10-	NA	S-3	8-12	100	NA	72.7		
1						169		
11-1						383		staining with petroleum odor
12-	NA	S-4	12-13	100	NA	165		wet sheen on water in sample liner
13-								Refusal at 13.0'
14-								
15								
19								
16								
17-								
18								
19								
20						1		

E

ľ

BORING NUMBER: TB-5

DAY Representative: J. Scherer	Boring Location: See Site Plan						
	Boring Location: See Site Plan						
Drilling Contractor: SLC Environmental Services	Ground Surface Elevation: NA	Datum: NA					
Drilling Rig: Simco Earthprobe 200	Start Date: 11/09/04 Completion Date:						
Sampling Method: Direct Push	Borehole Diameter: 2.0" Borehole Depth: 14.0'						
Completion Method: Backfilled with cuttings	Water Level: 10.5' (within borehole 11/09)						

Depth (feet)	Błows per 0.5'	Number	Depth (feet)	% Recovery	N-Value or RQD %	Peak PID Reading (ppm)	Well Installation Log	Sample Description
1						3.4		Asphalt, black coarse Sand, Cinders, Ash (FILL)
2 1 1 1 1	NA	S-1	0-4	55	NA	0.1		
~ - - - -						0.0		
3								Tan fine to medium to fine SAND, little Silt, damp
4						0.0		some Clay, moist
, 1111	NA	S-2	4-8	50	NA	2.2		
				00		:		
						0.0		
8 7						286		petroleum-type odor
9111						586		
10	NA	S-3	8-12	90	NA	796		
11 						1020		wat
12						33.1		Wel
13-	NA	S-4	12-14	100	NA	299		
14								Refusal at 14.0'
15								
16								
17								
18-								
19-								
20-								

BORING NUMBER: TB-6

Project: 242 Andrews Street, Rochester, NY	Project No: 3567S-04						
DAY Representative: J. Scherer	Boring Location: See Site Plan						
Drilling Contractor: SLC Environmental Services	Ground Surface Elevation: NA Datum: NA						
Drilling Rig: Simco Earthprobe 200	Start Date: 11/09/04 Completion Date: 11/09/04						
Sampling Method: Direct Push	Borehole Diameter: 2.0" Borehole Depth: 11.5'						
Completion Method: Backfilled with cuttings, asphalt patch	Water Level:						

					1		·	
Depth (feet)	Blows per 0.5'	Number	Depth (feet)	% Recovery	N-Value or RQD %	Peak PID Reading (ppm)	Well Installation Log	Sample Description
								Asphalt, black coarse Sand and Gravel (FILL)
1						0.0		
2	NA	S-1	0-4	80	NA	0.0		Brown medium Sano, moist (FILL)
3						0.0		
1 1						0.0 -		Brown fine to medium SAND, some Silt, trace Gravel, moist
5						0.0		
6 1	NA	S-2	4-8	95	NA	0.0		
7-1						0.0 .		
8-						0.0		
						0.0		
3	NA	S-3	8-11.5	100	NA	0.0	:	wet
10						0.0		
11-1						0.0		
12								Refusal at 11.5'
13-								
14 1 1								
15								
16								
18-								
ישי רוד רוד								
20								

File: 3567b6.log

BORING NUMBER: TB-7

Project: 242 Andrews Street, Rochester, NY	Project No: 3567S-04 Boring Location: See Site Plan						
DAY Representative: J. Scherer							
Drilling Contractor: SLC Environmental Services	Ground Surface Elevation: NA	Datum: NA					
Drilling Rig: Simco Earthprobe 200	Start Date: 11/09/04	Completion Date: 11/09/04					
Sampling Method: Direct Push	Borehole Diameter: 2.0"	Borehole Depth: 11.0'					
Completion Method: Backfilled with cuttings, asphalt patch	Water Level:						
·							

Depth (feet)	Blows per 0.5'	Number	Depth (feet)	% Recovery	N-Value or RQD %	Peak PID Reading (ppm)	Well Installation Log	Sample Description
1						0.0		Asphalt, Brick coarse Sand, some Gravel, Cinders (FILL)
2	NA	S-1	0-4	55	NA	0.0		Brown fine to medium Sand, trace Gravel, trace Brick (FILL)
3						0.0		
4								Brown fine to medium SAND, trace Gravel, moist
5						0.0		
6 1 1	NA	S-2	4-8	80	NA	0.0		
7						0.0		
8	<u> </u>							
9				100		0.0		
10-	NA	S-3	8-11	100	NA	0.0		
11								Refusal at 11.0'
12-								
13-								
14								
15								
16								
17-								
18-								
19-								
20-								

File: 3567b7.log

BORING NUMBER: TB-8

٦

Project: 242 Andrews Street, Rochester, NY	Project No: 3567S-04					
DAY Representative: J. Scherer	Boring Location: See Site Plan					
Drilling Contractor: SLC Environmental Services	Ground Surface Elevation: NA	Datum: NA				
Drilling Rig: Simco Earthprobe 200	Start Date: 11/09/04	Completion Date: 11/09/04				
Sampling Method: Direct Push	Borehole Diameter: 2.0"	Borehole Depth: 12.0'				
Completion Method: Backfilled with cuttings, asphalt patch	Water Level:					
· · · · · · · · · · · · · · · · · · ·						

Depth (feet)	Blows per 0.5'	Number	Depth (feet)	% Recovery	N-Value or RQD %	Peak PID Reading (ppm)	Well Installation Log	Sample Description
						0.0		Asphalt, black coarse Sand, Brick, Gravel (FILL)
		6.1	0.4	00	NA	0.0		
27	NA	5-1	0-4	90		0.0		Brown silty SAND, trace Clay, trace Gravel, damp
3 1 1						0.0		
4								Brown fine to medium SAND, trace Gravel, damp
5-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1						0.0		
6 1	NA	S-2	4-8	100	NA	0.0		
7-1						0.0		
8 1								moist
9 1						0.0		
10	NA	S-3	8-12	100	NA	0.0		
11						0.0		
12								Refusal at 12.0'
13								
14								
15								
16								
17-								
13								
19								
20								

BORING NUMBER: TB-9

Project: 242 Andrews Street, Rochester, NY	Project No: 3567S-04						
DAY Representative: J. Scherer	Boring Location: See Site Plan						
Drilling Contractor: SLC Environmental Services	Ground Surface Elevation: NA	Datum: NA					
Drilling Rig: Simco Earthprobe 200	Start Date: 11/09/04	Completion Date: 11/09/04					
Sampling Method: Direct Push	Borehole Diameter: 2.0"	Borehole Depth: 12.0'					
Completion Method: Backfilled with cuttings, asphalt patch	Water Level:						

Depth (feet)	Blows per 0.5'	Number	Depth (feet)	% Recovery	N-Value or RQD %	Peak PID Reading (ppm)	Well Installation Log	Sample Description
						0.0		Asphalt, Black Sand, and Gravel (FILL)
2	NA	S-1	0-4	90	NA	0.0		Dark brown silty SAND, trace Gravel, damp
3-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1						0.0		Brown fine to medium SAND, some Silt, trace Gravel, damp
4 1 1 5	i					- 0.0		
6	NA	S-2	4-8	60	NA	0.0		
7-1			- - - - -			0.0		moist
8 9						0.0		
10	NA	S-3	8-12	100	NA	0.0		
11						0.0		some Gravel
12								Refusal at 12.0'
13								
14					-	:		
15								
16								
17-								
18-								
19								
20-								

BORING NUMBER: TB-10

Project: 242 Andrews Street, Rochester, NY	Project No: 3567S-04	
DAY Representative: J. Scherer	Boring Location: See Site Plan	
Drilling Contractor: SLC Environmental Services	Ground Surface Elevation: NA	Datum: NA
Drilling Rig: Simco Earthprobe 200	Start Date: 11/09/04	Completion Date: 11/09/04
Sampling Method: Direct Push	Borehole Diameter: 2.0"	Borehole Depth: 6.0'
Completion Method: Backfilled with cuttings, asphalt patch	Water Level:	

Depth (feet)	Blows per 0.5'	Number	Depth (feet)	% Recovery	N-Value or RQD %	Peak PID Reading (ppm)	Well Installation Log	Sample Description
						0.0		Asphalt, black Sand, Gravel, Brick (FILL)
			0.4	20	NIA	0.0		
2 1	NA	5-1	0-4	00	NA	0.0		Black Silty SAND, wet
3 - 1						0.0		
4								
5-	NA	S-2	4-6	5	NA	0.0		
6						:		Refusal at 6.0'
7								
8-								
9-								
10								
11-								
- 								
13								
	4 4 4							
15-								
16-								
17-								
18 -								
19-								
20-								

BORING NUMBER: TB-11

Project: 242 Andrews Street, Rochester, NY	Project No: 3567S-04						
DAY Representative: J. Scherer	Boring Location: See Site Plan						
Drilling Contractor: SLC Environmental Services	Ground Surface Elevation: NA	Datum: NA					
Drilling Rig: Simco Earthprobe 200	Start Date: 11/09/04	Completion Date: 11/09/04					
Sampling Method: Direct Push	Borehole Diameter: 2.0"	Borehole Depth: 11.0'					
Completion Method: Backfilled with cuttings, asphalt patch	Water Level:						

Depth (feet)	Blows per 0.5'	Number	Depth (feet)	% Recovery	N-Value or RQD %	Peak PID Reading (ppm)	Well Installation Log	Sample Description
						0.0		Asphalt, black medium to coarse Sand, Gravel (FILL)
						0.0		
2	NA	S-1	0-4	90	NA	0.0		Brown Sand, some Silt, some Gravel, Brick (FILL)
3						0.0		
4								Brown Silty SAND, trace Gravel, moist
5-						0.0		
6 1	NA	S-2	4-8	75	NA	0.0		
7						0.0		
8-								
9						0.0		
- 10	NA	S-3	8-11	80	NA	20.5		
11_						23.2		petroleum-type odor
								Refusal at 11.0'
12								
13— -								
14								
15								
16								
17-								
18- 18-								
19-								
20-								

BORING NUMBER: TB-12

Proj DA`i	ect: 242 And Represent	lrews St ative: J	reet, Roche . Scherer	ster, NY			Project No: 3567S-04 Boring Location: See Site Plan				
Drill Dril San Con	Project: 242 Andrews Street, Rochester, NY PAY Representative: J. Scherer Prilling Contractor: SLC Environmental Services Prilling Rig: Simco Earthprobe 200 Sampling Method: Direct Push Completion Method: Backfilled with cuttings, asphalt principal services						Ground Su Start Date Borehole I Water Lev	urface Elevation: NA : 11/09/04 Diameter: 2.0" el:	Datum: NA Completion Date: 11/09/04 Borehole Depth: 13.0'		
aet)	5		aet)	very	o	iding	on Log		Sample Description		

Depth (feet)	Blows per 0.5'	Number	Depth (feet)	% Recovery	N-Value or RQD %	Peak PID Readin (ppm)	Well Installation	Sample Description
1 1 2 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	NA	S-1	0-4	80	NA	0.0 0.0 0.0		Asphalt, black Sand, Gravel, Brick (FILL) Brown Silty SAND, trace Gravel, moist
5 5 6 7 7	NA	S-2	4-8	100	NA	0.0 0.0		
8	NA	S-3	8-12	100	NA	30.6 612 659 173		SAND and SILT petroleum-type odor
12	NA	S-4	12-13	70	NA	282 81.3		wet Refusal at 13.0'
14								
15-								
10								
18								
19								
20-	1							

I

I

BORING NUMBER: TB-13

Project: 242 Andrews Street, Rochester, NY	Project No: 3567S-04			
DAY Representative: J. Scherer Boring Location: See Site Plan				
Drilling Contractor: SLC Environmental Services	Ground Surface Elevation: NA	Datum: NA		
Drilling Rig: Simco Earthprobe 200	Start Date: 11/09/04 Completion Date: 11/09/04			
Sampling Method: Direct Push	Borehole Diameter: 2.0" Borehole Depth: 11.0'			
Completion Method: Backfilled with cuttings, asphalt patch	Water Level:			

Depth (feet)	Blows per 0.5'	Number	Depth (feet)	% Recovery	N-Value or RQD %	Peak PID Reading (ppm)	Well Installation Log	Sample Description
1 1 2 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	NA	S-1	0-4	60	NA	0.0 0.0 0.0		Asphalt, Black Sand, Brick, Roots, Glass (FILL)
4 5 5 7 7 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	NA	S-2	4-8	100	NA	0.0		Brown fine to medium to fine SAND, moist
9 	NA	S-3	8-11	100	NA	0.0		Rock fragments
12 13 14 15 16 17 18 19 19								Refusal at 11.0'

I

APPENDIX C

ANALYTICAL LABORATORY REPORT AND CHAIN-OF-CUSTODY DOCUMENTATION

•

E



179 Lake Avenue, Rochester NY 14608 (585) 647-2530 FAX (585) 647-3311

Day Environmental, loc.	Lab Project No.:	04-3361
242 Andrews	Sample Type:	Soil
35675-04	Method:	SW846 6010
	Date(s) Sampled:	11/09/2004
	Date Received:	11/10/2004
	Date Analyzed:	11/11/2004
	Day Environmental. Inc. 242 Andrews 35675-04	Day Environmental. Inc.Lab Project No.:242 AndrewsSample Type: Method:35675-04Date(s) Sampled: Date Received: Date Analyzed:

Laboratory Report for Solid Analysis

Lab Sample No.	Field ID No.	Field Location	Lead Result (mg/kg)
11289	N/A	01/TB-1 (8-12)	3.79

ELAP ID No.: 10958

Comments:

roved By; Bruce Hoogesteger, Technical Director

This report is part of a multipage document and should only be evaluated in its entirety. Chain of Custody provides additional File ID:043361.xls

ENVITIONMENTAL SEBUICES, INC.

LL SERVICES, INC. 179 Lake Avenue Rochester, New York 14608 (585) 647 - 2530 FAX (585) 647 - 3311

Semi-Volatile STARS Analysis Report for Soils/Solids/Sludges

Client: Day Environmental

Client Job Site:	242 Andrews St	Lab Project Number:	04-3361
Client Job Number: Field Location:	3567S-04	Lab Sample Number:	11289
Field ID Number:	N/A	Pate Sampled: Pate Received:	11/09/2004
Sample Type:	Soil	Date Analyzed:	11/12/2004

Base / Neutrals	Results in ug / Kg
Acenaphthene	ND< 309
Acenaphthylene	ND< 309
Anthracene	ND< 309
Benzo (a) anthracene	ND< 309
Benzo (a) pyrene	ND< 309
Benzo (b) fluoranthene	ND< 309
Benzo (g,h,i) perylene	ND< 309
Benzo (k) fluoranthene	ND< 309
Chrysene	ND< 309
Dibenz (a,h) anthracene	ND< 309
Fluoranthene	ND< 309
Fluorene	ND< 309
indeno (1,2,3-cd) pyrene	ND< 309
Naphthalene	ND< 309
Phenanthrene	ND< 309
Pyrene	ND< 309

ELAP Number 10958

Method; EPA 82700

Data File: 22357,D

Comments: ND donotes Non Detect ug / Kg = microgram per Kilogram

Signature;

Bruce Horgesteger, Technical Director



179 Lake Avenue Rochester, New York 14608 (585) 647 - 2530 FAX (585) 647 - 3311

Volatile STARS Analysis Report for Soils/Solids/Sludges

Client: Day Environmental

Client Job Site:	242 Andrews	Lab Project Number:	04-3361 11289
Client Job Number:	35678-04		11200
Field Location:	01/TB-1 (8-12)	Date Sampled:	11/09/2004
Fleid ID Number:	N/A	Date Received:	11/10/2004
Sample Type:	Soil	раte Analyzed:	11/11/2004
		5	

Aromatics	Results in ug / Kg
Benzene	ND< 43.2
n-Butylbenzone	ND< 43.2
sec-Butylbenzene	179
tert-Butylbenzene	ND< 43.2
Ethylbenzene	327
n-Propylbenzene	898
lsopropylbenzene	368
p-lsopropyltoluene	312
Naphthalene	437
Toluene	ND< 43.2
1,2,4-Trintethylbenzene	3,330
1,3,5-Trimethylbenzene	2,650
m,p-Xylene	322
o-Xylene	ND< 43.2
Miscellaneous	
Methyl tert-bulyl Ether	ND< 43.2

ELAP Number 10958

Method: EPA 82608

Data File: 25838.D

Comments: ND denotes Non Detect ug / Kg = mlcrogram per Kilogram

Signature:

Bruce Hoogesteger; Technical Director This report is part of a multipage document and should only be evaluated in its entirety. Chain of Custody provides additional information, including compliance with sample condition requirements upon receipt.

11/09/2004

11/10/2004

11/11/2004

PARADIGM

ERVIRONMENTAL SERVICES, INC.

179 Lake Avenue Rochester, New York 14608 (585) 647 - 2530 FAX (585) 647 - 3311

Date Analyzed:

Volatile Analysis Report for Solids/Sludges

Client: Day Environmental

Sample Type:

 Client Job Site: 	242 Andrews	Lab Project Number: Lab Sample Number:	04-3361 11289
Client Job Number:	35675-04		
Field Location:	01/TB-1 (8-12)	pate Sampled:	11/09/20
Field ID Number:	N/A	Date Received:	11/10/20

Soll

Tentatively Identified Compounds	CAS Number	Retention Time	Results in ug / Kg	Percent Fit
Octane	000111-65-9	7.12	1,390	83
Ethyl cyclohexane	001678-91-7	7.87	907	90
Unk. Alkane	N/A	7.93	1,270	N/A
Unk. Alkane	N/A	8.30	1,350	N/A
Unk. Alkane	N/A	9.06	1,200	N/A
Unk. Alkane	N/A	9.26	1,170	N/A
Unknown ,	N/A	9.58	1,120	N/A
Unk. ALkyl Benzene	N/A	10.10	827	N/A
Unk. ALkyl Benzene	N/A	10.40	1,610	N/A
Unk. ALkyl Benzene	N/A	11.30	1,030	N/A
Unk. ALkyl Benzene	N/A	11.39	2,460	N/A
Unk. Alkane	N/A	11,53	1,050	N/A
Unk. Alkyl Benzono	N/A	11.61	821	N/A
Unk, Alkyl Benzene	N/A	11.74	1,060	N/A
Unk. Alkyl Banzene	N/A	11.82	1,200	N/A
Unk. Alkyl Benzene	NA	1,95	1,330	N/A
tetramethyl benzene	N/A	12.32	900	N/A
Unk. Alkyl Benzene	N/A	2.43	855	N/A
Unk. Alkyl Benzene	N/A	2.60	927	N/A
Unk. Alkyl Benzene	N/A	2.77	1,480	N/A
ELAP Number 10958	Method: E	PA 8260B		Data Files 25220 D

Method: EPA 82608

Data File: 25836.D

Commants: ND denotes Non Detect ug / Kg = mlcrogram per Kilogram

Signature:

Bruca Hoogesteyer: Technical Director

This report is part of a multipage document and should only be evaluated in its entirely. Chain of Cuatody provides additional information, including compliance with sample condition requiremente upon recelpi. A43261T1,XLS



ENVIRONMENTAL SERVICES. ING. 179 Lake Avenue Rochester, New York 14608 585) 647 - 2530 FAX (585) 647 - 3311

Volatile STARS Analysis Report fdr Soils/Solids/Sludges

Client: Day Environmental

Client Job Site:	242 Andrews	ab Project Number: ab Sample Number:	0 4-3361 11290
Client Job Number:	35678-04		
Field Location:	02/TB-4 (10-12)	ate Sampled:	11/09/2004
Field ID Number:	N/A I	ate Received:	11/10/2004
Sample Type:	Soil	ate Analyzed:	11/11/2004

Aromatics		Results in ug / Ko	1
Benzene		ND< 12.9	
n-Butylbenzene		ND< 12.9	
sec-Butylbenzene	÷	87.4	
tert-Butylbenzene		ND< 12.9	
Ethylbenzene		ND< 12.9	
n-Propylbenzene		374	
isopropylbenzene		80.3	
p-Isopropyltoluen	e	132	
Naphthalene		ND< 32.3	
Toluene		ND< 12.9	
1,2,4-Trimethylbe	nzene	324	
1,3,5-Trimethylbe	nzene	147	
m,p-Xylene		ND< 12.9	
o-Xylene		ND< 12.9	
Miscellaneous			
Methyl tert-butyl E	ther	ND< 12.9	
ELAP Number 10958	Method: EPA 82606	Data F	lle: 25837.D

Method: EPA 82608

Comments: ND denotes Non Detect ug / Kg = microgram per Kilogram

Signature:

Bruca Hocgesleger. Technical Diraclor

This report is part of a multipage document and should only be evaluated in its entirely. Chain of Custody pipyldes additional information, including compliance with sample condition 043361V2.XLS requirements upon repeint

PARADIGM

ENVIRIDAMENTAL SERVICES. INC. 179 Lake Avenue Rochester, New York 14608 (585) 647 - 2530 FAX (585) 647 - 3311

Volatile Analysis Report for Solis/Solids/Sludges

Client: Day Environmental

~	1:		Ich	Site
し	11ei	nτ.	JOD	Site;

242 Andrews

Client Job Number:3567S-04Field Location:02/TB-4 (10-12)Field ID Number:N/ASample Type:Soil

Lab Project Number:04-3361ab Sample Number:11290Date Sampled:11/09/2004Date Received:11/10/2004Date Analyzed:11/11/2004

Tentatively Identified Compounds	CAS Number	Retention Time	Results in ug 7 Kg	Percent Fit
Octane	000111-65-9	7.12	498	83
Ethyl cyclohexane	001678-91-7	7.87	361	90
Unk. Alkane	N/A	7.93	556	N/A
Unk, Alkane	N/A	8.30	427	N/A
Unk. Alkane	N/A	9.06	485	N/A
Unk, Alkane	N/A	9.26	479	N/A
Unknown	N/A	9.32	343	N/A
Unk. ALkyl Benzene	N/A	9.39	815	N/A
Unk. ALkyl Benzene	N/A	9.58	427	N/A
Unk, ALkyl Benzene	N/A	10.11	362	N/A
Unknown Alkane	N/A	10.86	369	N/A
Unknown Alkyl Banzene	N/A	11.39	543	N/A
Unk, Alkyl Benzene	N/A	11.82	388	N/A
Unk. Alkyl Benzene	N/A	11.97	420	N/A
Unk, Alkyl Benzene	N/A	12.40	440	N/A
Unknown	NA	12.58	401	N/A
Unknown alkyl benzene	N/A	12.71	323	N/A
Unk, Alkyl Benzene	N/A	12.78	433	N/A
Unk. Alkyl Benzone	N/A	12.87	349	N/A
Ипкломп	N/A	13.15	401	<u>N/A</u>
ELAP Number 10958	Method: 8	PA 8260B		Data File: 25837.D

Comments: ND denotes Non Detect ug / Kg = microgram per Kildgram

Bruce Hoogesteger: / echnical Director

Signature:

This report is part of a multipage document and should only be evaluated in its entirely. Chain of Custody provides additional information, including compliance with sample condition requirements upon receipt.

PARADIGM

179 Lake Avenue Rochaster, New York 14608 (585) 647 - 2530 FAX (585) 647 - 3311 ENVIRONMENTAL SERVICES, INC.

Volatile STARS Analysis Report for Soils/Solids/Sludges

Client: Day Environmental

Client Job Site:	242 Andrews	Lab Project Number: Lab Sample Number:	04-3361 11291
Client Job Number: Field Location: Field ID Number: Sample Type:	3567S-04 03/TB-11 (10-11) N/A Soil	Date Sampled: Date Received: Date Analyzed:	11/09/2004 11/10/2004 11/11/2004

Aromatics	Results in ug / Kg
Benzene n-Butylbenzene sec-Butylbenzene tart-Butylbenzene Ethylbenzene n-Propylbenzene Isopropylbenzene p-Isopropyltoluene Naphthalene Toluene 1,2,4-Trimethylbenzene 1,3,5-Trimethylbenzene m,p-Xylene o-Xylene	ND< 11.9 ND< 11.9 75.2 ND< 11.9 ND< 11.9 149 20.8 39.7 ND< 29.6 ND< 29.6 ND< 11.9 ND< 11.9 ND< 11.9 ND< 11.9 ND< 11.9
Miscellaneous Methyl tert-butyl Ether	ND< 11.9

ELAP Number 10958

Method: EPA 82508

Data File: 25838.D

Comments: ND denotes Non Detect ug / Kg = microgram per Kilogram

Signature:

PAGE

08/12


179 Lake Avenue Rochester, New York 14608 (585) 647 - 2530 FAX (585) 647 - 3311 ENVIRONMENTAL SERVICES. INC.

Volatile Analysis Report for Soils/Solids/Sludges

Client: Day Environmental

Client Job Site:	242 Andrews	Lab Project Number: Lab Sample Number:	04-3361 11291
Client Job Number: Field Location: Field ID Number: Sample Type:	3567S-04 03/TB-11 (10-11) N/A Soil	Date Sampled: Date Received: Date Analyzed:	11/09/2004 11/10/2004 11/11/2004

In the still and Compounds	CAS Number	Retention Time	Results in ug / Kg	Percent Fit
Lentauvely identified Compounds	N/A	5.02	367	. N/A
Unk. Alkane	N/A	5.26	1,920	N/A
Unk, Alkane	1N/25 N/25	6.02	415	N/A
Unk. Alkane	N//N	6.37	1,640	N/A
Unk, Alkane	IN/A	6.49	2,390	N/A
Unk. Alkane	N/A	6.50	267	N/A
Unk. Alkane	NA	6.86	687	N/A
Unk. Alkane	N/A	7 73	213	N/A
Unk. Alkane	N/A	7 93	192	N/A
Unk ALkane	N/A	8 20	207	N/A
Unk. Alkane	N/A	10.86	225	N/A
Unknown Alkane	N/A	10.00	166	N/A
Unk. Alkane	N/A	11.79	314	N/A
Unk. Alkyl Benzene	N/A	11.20	486	N/A
Unk, Alkyl Benzene	N/A	11.50	287	N/A
Unk. Alkyl Benzene	N/A	11.01	308	N/A
Unk. Alkyl Benzene	N/A	11.70	818	N/A
Unknown alkyl benzene	N/A	11.04	189	N/A
Unk, Alkyl Benzene	N/A	11,90	504	N/A
Unk. Alkyl Benzene	N/A	12.20	385	N/A
Unk, Alkyl benzene	<u>N/A</u>	12.//		Data File: 25838.D
ELAP Number 10958	Method:	EPA 8260B		

Comments: ND denotes Non Delect ug / Kg = micragram per Kilogram

Bruce Hoogestagaf: Technical Director

Signature:



179 Lake Avenue Rochester, New York 14608 (585) 647 - 2530 FAX (585) 647 - 3311

Volatile STARS Analysis Report for Soils/Solids/Sludges

Client: Day Environmental

Client Job Site:	242 Andrews	Lab Project Number: Lab Sample Number:	04-3361 11292
Client Job Number: Field Location: Field ID Number: Sample Type:	3567S-04 04/TB-12 (8-12) N/A Soil	Date Sampled: Date Received: Date Analyzed:	11/09/2004 11/10/2004 11/11/2004

Aromatics	Results in ug / Kg
Benzene	ND< 91.4
n-Butylbenzene	ND< 91.4
sec-Butylbenzene	ND< 91,4
tert-Butylbenzene	ND< 91.4
Fthylbenzene	3,480
n-Propylhenzene	6,180
Isonroovibenzene	2,700
n-isopropyltoluene	1,460
Nanbthalene	7,980
Toluene	194
1 2 4-Trimethylbenzene	E 23,500
1 3 5-Trimethylbenzene	12,800
m p-Xylene	16,500
o-Xylene	ND< 91.4
Miscellaneous	
Methyl tert-butyl Ether	ND< 91.4
	D. L. DIL. OFOCC D

ELAP Number 10958

Method: EPA 8260B

Data File: 25866.D

Comments: ND denotes Non Detect

Signature:

ug / Kg = mlcrogram per Kilogram

E= Estimated concentration. Exceeds calibration range.

للرتيكم Bruce Hoogesteger: Tegenical Director

This report is part of a multipage document and mould only be evaluated in its entirely. Chain of Custody provides additional information, including compliance with sample condition 043361V4.XLS

PARADIGM

179 Lake Avenue Rochester, New York 14608 (585) 647 - 2530 FAX (585) 647 - 3311 ENVIRONMENTAL SERVICES, INC.

Volatile Analysis Report for Soils/Solids/Sludges

Client: Day Environmental

Client Job Site:	242 Andrews	Lab Project Number: Lab Sample Number:	04-3361 11292
Client Job Number: Field Location: Field ID Number: Sample Type:	3567S-04 04/TB-12 (8-12) N/A Soil	Date Sampled: Date Received: Date Analyzed:	11/09/2004 11/10/2004 11/11/2004

Tentatively Identified Compounds	CAS Number	Retention Time	Results in ug / Kg	Percent Fit
	000111-65-9	7.13	24,200	90
Unk Alkane	N/A	7.28	5,300	N/A
Unk Alkane	N/A	7.73	5,250	N/A
	N/A	7,8D	4,480	N/A
Link Alkane	N/A	7.88	7,450	N/A
Unk Alkane	N/A	7,93	9,090	N/A
Link, Alkane	N/A	8.09	5,300	N/A
Unk. Alkane	N/A	8.18	15,700	N/A
	N/A	8.30	9,910	N/A
Hink Alkane	N/A	8.77	3,930	N/A
Unknown Alkane	N/A	9.06	6,620	N/A
Unk Alkana	N/A	9.26	5,940	N/A
llink. Alkane	N/A	9,32	4,190	N/A
	N/A	9,40	10,100	N/A
Unk. Alkane	N/A	9.59	5,620	N/A
Unk. Alkyl Benzene	N/A	10.10	10,800	N/A
Linknown alkyl benzene	N/A	10.11	4,520	N/A
Unk. Alkyl Benzene	N/A	10.40	5,620	N/A
Unk. Alkyl Benzene	N/A	11.07	5,030	N/A
Unk Alkyl benzene	N/A	11.40	7,260	N/A
	Melhad- F	PA 8260B		Data File: 25866.D

ELAP Number 10958

Method: EPA 82608

Comments: ND denotes Non Detect ug / Kg = microgram per Kllogram

Bruce Hoogesteller: Technical Director

Signature:

This report is part of a multipage documant and should only be evaluated in its entirety. Chain of Custody provides additional information, including compliance with sample condition 043251T4.XLS regultements upon receipt.

	NMENT	AL			Beabran				1.11.2.2	i n			54 540880	in de la composition						
SERVICE	ES, INC	х Г.	COMPAN	^{IV:} N. K. K.				COMPA	¥7:			INVO	<u>CE</u> TO	- 24 - 24			LAB PADJECT #	CLIE		
179 Lake Avenu	с,с	-	ADDRES	Jay Enviro	MMMENTAL, 100	<u> </u>		ADDRES		<u>s /4</u>	Mr	<u> </u>			<u></u>		14 22/1	350	,75-0	Ϋ́
Rochester, NY 1 (585) 647-2530	4608 (800) 724-1	[997	CITY:	200 heater	STATE:	NC IU	,	CITY:				·····	STAJ	E:	ZiP:			ב: (WORKIN)	G DAYS)	
FAX: (595) 647-8	3311		PHONE:	454020		///// C		PHONE:		·			AX:				By NOON	,	270	OTHER
PROJECT NAME/SIT	E NAME:		ATTN:	Rev Kamp	4370 <i>0L</i>	<u>د</u>	· · · · · · · · · · · · · · · · · · ·	ATTN:										Ť ، آ		
242 Andre	ws St		COMMEN		<u> </u>			I										³ [19	
											Test	1 678	MAIN							
		C C	S metal (Se					C	L					9119:22					<u> 남</u> 쪽을 가 썼	are the second states of the s
		O M	G				NS A	N N U T	20	·										
DATE	TIME	o S	R	SAMPL	E LOCATION/FIELD ID		T	M A B I	PEC	S.R.C.							REMARKS		FARADI	
		I T	В				i X	E N R E	50	10	0									
		E			h			A S	826	ŝ	2									3
I WG/04	0855		X	01/TB-1	(8-12)		Soil	1	X	X	X								1116	289
2 W/9/64	1100		X	02/TB-4	(10-12)		501	1	X								· · · · · · · · · · · · · · · · · · ·		112	290
31/9/01	1345		\times	03/TB-1	1 (10-11)		Sail	}	X								<u>,</u>		1112	291
4 11/4/01	1406		X	04/TB-12	(8-12)		Soil	1	X								······································		1 1 2	292
5																				
6																				
7											+									
8							·					$\left \right $								
9																				
10			· · · · · · · · · · · · · · · · · · ·		······································			·				┼╌┼╴	╶╂╾┾							
*LAB USE	ONLY BE	LOW	CHIS	INE#1				- 										ning af a sig		
Sample Conditio	n: Per NEL/	AC/ELAP	210/24	1/242/243/244	n den de la			<u>9</u>	1	決.ia.		T King	<u> </u>		<u>112-2-45</u>	비즈북구철			<u>(1999)</u> [1999]	<u>37:14 (1994</u>
Reci	eipt Parame	ter Tump:		NELAC Comp	llance		11. ~	7						.1.1	. 1.					
Comments:				×Д	N		VI BV.	<u></u>						1/9/0	1/160)		Г		

ーイ・ファ

5

T 1 + +

))))

• • • •

.

Cอสาเกษกไร:	Container Typa:	Y 🔀	N	Marte	11/9/01/1600		
	Preservation:		N. []	Sampled by	Date/Time	Total Cost:	
Comments:	Labela - T	'	IN	Relinquished By	Date/Time		
Солителіз:	ruxaing time;	Y 💢	N	Bacalvad By	119104 11:07 Am		[]
Caturients:	(Te)nperature:	Y 💢	N	Ally and all Beceived @Tab By	11/10/04/1127	P.I.F.	

COLUMBIA ANALYTICAL SERVICES, INC.

RESULTS OF ANALYSIS

Page 1 of 2

lient: lient Sample ID:	Paradigm Environmental Services, Inc. 04-3368-11302	CAS Project ID: P2402452 CAS Sample ID: P2402452-001
		Deta Callested: 11/10/04

Date Collected: 11/10/04 EPA TO-15 Date Received: 11/12/04 Tekmar AUTOCAN/HP5972/HP5890 II+/MS2 Date(s) Analyzed: 11/15/04 Aristotle Bragasin 1.00 Liter(s) Volume(s) Analyzed: Summa Canister

Pf 1 = 3.5

AC00426

Test Code:

nalyst:

Test Notes:

ontainer ID:

Instrument ID:

Sampling Media:

-1.7 Pi 1 =

D.F. = 1.40

CAS#	Compound	Result µg/m³	MRL µg/m³	Result ppbV	MRL ppbV	Data Qualifier
71 87 3	Chloromethane	ND	1.4	ND	0.68	
75-01-4	Vinyl Chloride	ND	1.4	ND	0.55	<u> </u>
74-83-9	Bromemethane	ND	1.4	ND	0.36	
74-00-3	Chloroethane	ND	1.4	ND	0.53	-
67 64-1	Acetone	16	7.0	6.8	2.9	-
75-69-4	Trichlorofluoromethane	1.7	1.4	0.31	0.25	_
75-05-4	1 1-Dichloroethene	ND	1.4	ND	0.35	-
75-55-4	Methylene chloride	ND	1.4	ND	0.40	-
75-03-2	Trichlorotrifluoroethane	ND	1.4	ND	0.18	_
76-15-1	Carbon Disulfide	ND	1.4	ND	0.45	
156.60.5	mang_1 2-Dichloroethene	ND	1.4	ND	0.35	
75 34 3	1 1-Dichloroethane	ND	1.4	ND	0.35	
15-34-3	Mathyl tert-Butyl Ether	ND	1.4	ND	0.39	
1634-04-4	View A cetate	ND	1.4	ND	0.40	_
108-05-4	2 Butanone (MFK)	13	1.4	4.4	0.47	
/8-93-3	z-Butal(vice (1011))	ND	1.4	ND	0.35	
156-59-2	Chloreform	ND	1.4	ND	0.29	
67-66-3			1.4	ND	0.35	
107-06-2	1,2-Dichioroculane		1.4	ND	0.26	
71-55-6	1,1,1-Irichioroemanc		1.4	ND	0.44	
71-43-2	Benzenc		1.4	ND	0.22	
56-23-5	Carbon Tetrachloride		14	ND	0.30	
58-87-5	1.2-Dichloropropane					

ND = Compound was analyzed for, but not detected above the laboratory reporting limit.

MRL = Method Reporting Limit - The minimum quantity of a target analyte that can be confidently determined by the referenced metho-

Secondary Store Counter

Verified By:_____

Date:

Page No.1

COLUMBIA ANALYTICAL SERVICES, INC.

RESULTS OF ANALYSIS Page 2 of 2

Client:Paradigm EnClient Sample ID:04-3368-11302

Paradigm Environmental Services, Inc. 04-3368-11302

CAS Project ID: P2402452 CAS Sample ID: P2402452-001

Test Code: Istrument ID: Analyst: Sampling Media: est Notes: Container ID: EPA TO-15 Tekmar AUTOCAN/HP5972/HP5890 II+/MS2 Aristotle Bragasin Summa Canister AC00426 Date Collected: 11/10/04 Date Received: 11/12/04 Date(s) Analyzed: 11/15/04 Volume(s) Analyzed: 1.00 Liter(s)

Pf 1 = 3.5

D.F. = 1.40

CAS #	Compound	Result µg/m³	MRL µg/m³	Result ppbV	MRL ppbV	Data Qualifier
75-27-4	Bromodichloromethane	ND	1.4	ND	0.21	
79-01-6	Trichloroethene	1.7	1.4	0.31	0.26	
10061-01-5	cis-1,3-Dichloropropene	ND	1.4	ND	0.31	
108-10-1	4-Methyl-2-pentanone	ND	1.4	ND	0.34	_
10061-02-6	trans-1,3-Dichloropropene	ND	1.4	ND	0.31	~
79-00-5	1,1,2-Trichloroethane	ND	1.4	ND	0.26	
108-88-3	Tolucne	9.3	1.4	2.5	0.37	
591-78-6	2-Hexanone	ND	1.4	ND	0.34	
124-48-1	Dibromochloromethane	ND	1.4	ND	0.16	
106-93-4	1.2-Dibromoethane	ND	1.4	ND	0.18	_
127-18-4	Tetrachloroethene	4.2	1.4	0.62	0.21	
108-90-7	Chlorobenzene	ND	1.4	ND	0.30	
100-41-4	Ethylbenzene	ND	1.4	ND	0.32	
136777-61-2	m.p-Xylenes	2.3	1.4	0.53	0.32	_
75-25-2	Bromoform	ND	1.4	ND	0.14	
100-42-5	Styrene	ND	1.4	ND	0.33	_
95-47-6	o-Xylenc	ND	1.4	ND	0.32	
79-34-5	1.1.2.2-Tetrachloroethane	ND	1.4	ND	0.20	
541-73-1	1.3-Dichlorobenzene	ND	1.4	. ND	0.23	_
106-46-7	1.4-Dichlarobenzene	ND	1.4	ND	0.23	
95_50-1	1.2-Dichlorobenzene	ND	1.4	ND	0.23	

Pi1 = 1

-1.7

ND = Compound was analyzed for, but not detected above the laboratory reporting limit.

NRL = Method Reporting Limit - The minimum quantity of a target analyte that can be confidently determined by the referenced method

Verified By:____

Date:

APPENDIX 12.6 1950 Sanborn Fire Insurance Map

.



APPENDIX 12.7 EDR Radius Map Report

· · · ·

The EDR Radius MapTM Report

The Kirstein Building 242 Andrews St. Rochester, NY 14604

Inquiry Number: 01376628.1r

March 10, 2005

The Standard in Environmental Risk Management Information

EDR[™] Environmental

Data Resources Inc

440 Wheelers Farms Road Milford, Connecticut 06460

Nationwide Customer Service

 Telephone:
 1-800-352-0050

 Fax:
 1-800-231-6802

 Internet:
 www.edrnet.com

TABLE OF CONTENTS

SECTION

PAGE

Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	6
Orphan Summary	120
EPA Waste Codes	EPA-1
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

GeoCheck - Not Requested

Thank you for your business. Please contact EDR at 1-800-352-0050 with any questions or comments.

Disclaimer - Copyright and Trademark Notice

Disclaimer - Copyright and Trademark Notice This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2005 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

A search of available environmental records was conducted by Environmental Data Resources, Inc. (EDR). The report meets the government records search requirements of ASTM Standard Practice for Environmental Site Assessments, E 1527-00. Search distances are per ASTM standard or custom distances requested by the user.

EXECUTIVE SUMMARY

TARGET PROPERTY INFORMATION

ADDRESS

242 ANDREWS ST. ROCHESTER, NY 14604

COORDINATES

Latitude (North):	43.160200 - 43° 9' 36.7"
Longitude (West):	77.608800 - 77° 36' 31.7"
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	287903.4
UTM Y (Meters):	4781694.0
Elevation:	519 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property: Source:

43077-B5 ROCHESTER EAST, NY USGS 7.5 min quad index

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the ASTM E 1527-00 search radius around the target property for the following databases:

FEDERAL ASTM STANDARD

NPL	National Priority List
Proposed NPL	Proposed National Priority List Sites
CERCLIS	Comprehensive Environmental Response, Compensation, and Liability Information
	System
CERC-NFRAP	CERCLIS No Further Remedial Action Planned
CORRACTS	Corrective Action Report
RCRA-TSDF	Resource Conservation and Recovery Act Information
ERNS	Emergency Response Notification System

STATE ASTM STANDARD

CBS UST..... Chemical Bulk Storage Database

MOSF UST	Major Oil Storage Facilities Database
SWTIRE	Registered Waste Tire Storage & Facility List
SWRCY	Registered Recycling Facility List

FEDERAL ASTM SUPPLEMENTAL

CONSENT	_ Superfund (CERCLA) Consent Decrees
ROD	_ Records Of Decision
Delisted NPL	National Priority List Deletions
FINDS	Facility Index System/Facility Identification Initiative Program Summary Report
HMIRS	Hazardous Materials Information Reporting System
MLTS	. Material Licensing Tracking System
MINES.	Mines Master Index File
NPL Liens	_ Federal Superfund Liens
PADS	. PCB Activity Database System
INDIAN RESERV	Indian Reservations
UMTRA	_ Uranium Mill Tailings Sites
ODI	_ Open Dump Inventory
DOD	_ Department of Defense Sites
RAATS	RCRA Administrative Action Tracking System
TRIS	. Toxic Chemical Release Inventory System
TSCA	. Toxic Substances Control Act
SSTS	_ Section 7 Tracking Systems
FTTS INSP	. FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, &
	Rodenticide Act)/TSCA (Toxic Substances Control Act)

STATE OR LOCAL ASTM SUPPLEMENTAL

HSWDS	Hazardous Substance Waste Disposal Site Inventory
AST	Petroleum Bulk Storage
CBS AST	Chemical Bulk Storage Database
MOSF AST	Major Oil Storage Facilities Database
DEL SHWS	Delisted Registry Sites
AIRS	Air Emissions Data
SPDES	State Pollutant Discharge Elimination System

EDR PROPRIETARY HISTORICAL DATABASES

Coal Gas_____ Former Manufactured Gas (Coal Gas) Sites

BROWNFIELDS DATABASES

US BROWNFIELDS...... A Listing of Brownfields Sites Brownfields...... Brownfields Site List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property. Page numbers and map identification numbers refer to the EDR Radius Map report where detailed

data on individual sites can be reviewed.

Sites listed in *bold italics* are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

FEDERAL ASTM STANDARD

RCRAInfo: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRAInfo replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System(RCRIS). The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month. Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month Large quantity generators generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month. Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste.

A review of the RCRA-LQG list, as provided by EDR, and dated 11/23/2004 has revealed that there are 2 RCRA-LQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
ROCHESTER CITY OF FORMER PRINT	304-308 ANDREWS ST	0 - 1/8 E	C11	16
CITY OF ROCHESTER MICHAELS STE	87 N CLINTON AVE	1/8 - 1/4 SE	E20	25

RCRAInfo: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRAInfo replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System(RCRIS). The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month. Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month Large quantity generators generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month. Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

A review of the RCRA-SQG list, as provided by EDR, and dated 11/23/2004 has revealed that there are 17 RCRA-SQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
SILVER DRY CLEANING CO INC	245 ANDREWS ST	0-1/8 ESE	A3	7
YWCA - PER CON ELEC	175 N CLINTON AVE	0 - 1/8 ENE	4	8
ROCHESTER EDUCATION OPPOR CENT	305 ANDREWS ST	0-1/8 E	C12	16
JOYCE FAMILY PROPERTIES	172-180 PLEASANT ST	1/8 - 1/4 ESE	23	26
ST VINCENT PRESS	250 CUMBERLAND ST	1/8 - 1/4 ENE	24	26
BARIS TAILORING	48 ST PAUL ST	1/8 - 1/4 S	25	27
ROCHESTER CITY OF ROCHESTER BU	414 ANDREWS ST	1/8 - 1/4 E	F26	27
FLEET BANK	159 E MAIN ST	1/8 - 1/4 S	31	43
HYATT REGENCY ROCHESTER	125 E MAIN ST	1/8 - 1/4 S	H32	43
ROCHESTER RIVERSIDE CEONVENTIO	123 E MAIN ST	1/8 - 1/4 S	H33	44
CASE-HOYT CENTRAL AVENUE	439 CENTRAL AVE	1/8 - 1/4NE	134	44
LAMINATING ARTS & FINISHES INC	439 CENTRAL AVE	1/8 - 1/4 NE	/36	50
Lower Elevation	Address	Dist / Dir	Map ID	Page
RUMRILL-HOYT INC	180 ST PAUL ST	0-1/8 W	B5	8

TC01376628.1r EXECUTIVE SUMMARY 3

Lower Elevation	Address	Dist / Dir	Map ID	Page
NYSDOT BIN 1048750 & 104875A	CLINTON AVE OVER I-490	0-1/8 N	D14	18
H & A OF NEW YORK	189 N WATER ST	1/8 - 1/4 W	21	25
ROCHESTER CITY OF OLD GREYHOUN	120 ANDREWS ST	1/8 - 1/4 WSW	22	26
ROCHESTER GAS & ELECTRIC CORPO	84 ANDREWS STREET	1/8 - 1/4 WSW	' G38	52

STATE ASTM STANDARD

SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the SHWS list, as provided by EDR, has revealed that there are 2 SHWS sites within approximately 1 mile of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
FORMER RAECO PRODUCTS	24 SPENCER STREET	1/2 - 1 WNW	/ 63	117
FORMER ROCHESTER METAL ETCHING	100 LAKE AVENUE	1/2 - 1 WNW	/ 64	118

SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the list.

A review of the SWF/LF list, as provided by EDR, has revealed that there is 1 SWF/LF site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
RUSSELL GAS & ELECTRIC	89 EAST AVE.	1/4 - 1/2SE	J43	59

LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the LTANKS list, as provided by EDR, and dated 02/10/2005 has revealed that there are 26 LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
NUSBAUM CLEANER DISTRIB.	304-308 ANDREW ST.	0 - 1/8 E	C7	10
CULLARI (JAMES) APARTMENT	130 NORTH CLINTON AVENU	0 - 1/8 ESE	C8	11
WALLACH (ERWIN)	430 ANDREWS STREET	1/8 - 1/4 E	F2 7	28
JOHNSON & LUND	167 LIBERTY POLE WAY	1/8 - 1/4 E	29	34
PAL OIL	EAST MAIN STREET	1/4 - 1/2ESE	42	58
YMCA (OLD)	26 GIBBS STREET	1/4 - 1/2ESE	44	60
CONSTRUCTION SITE	CLINTON / BROAD STREE	1/4 - 1/2SSE	45	61
HALLMAN CHEVROLET (FORMER)	200 EAST AVENUE	1/4 - 1/2SE	J47	63
JOMOR ENTERPRISES	246 EAST AVENUE	1/4 - 1/2ESE	50	85
FORMER DMV PARKING LOT	SOUTH AVENUE @COURT STR	1/4 - 1/2SSE	52	91
Lower Elevation	Address	Dist / Dir	Map ID	Page
RAE OIL COMPANY	195 ST PAUL BOULEVARD	0 - 1/8 W	B6	9

Dist / Dir

Map ID

Page

Lower Elevation

Address

ROCHESTER GAS & ELECTRIC CORP	84 ANDREWS STREET	1/8 - 1/4WSW G30	36
ROCHESTER GAS & ELECTRIC	FRONT / ANDREWS STREE	1/8 - 1/4WSW G37	50
ST. SIMONS TERRACE	360 ST PAUL STREET	1/4 - 1/2NNW 39	54
FIGHT VILLAGE APARTMENTS	WARD / NORTH CLINTON	1/4 - 1/2N 40	55
GERMANOW-SIMON INC	408 ST PAUL STREET	1/4 - 1/2NW 41	56
PEPSI COLA FACILITY	425 ORMOND STREET	1/4 - 1/2NNE K48	79
PEPSI COLA BOTTLING COMPANY	425 ORMOND STREET	1/4 - 1/2NNE K49	82
HIGH FALLS BREWING COMPANY	445 ST PAUL STREET	1/4 - 1/2NW 51	87
ROCHESTER (CITY OF)	MILL ST-HOLLEY PUMP STA	1/4 - 1/2W 53	92
SIBLEYS DISTRIBUTION CTR	62 NASSAU STREET	1/4 - 1/2NNE L54	94
L C D NASSAU	68 NASSAU STREET	1/4 - 1/2NNE L55	95
WILLOW INDUSTRIES	68 NASSAU ROAD	1/4 - 1/2 NNE L56	97
UNITED PARCEL SERVICE	75 NASSAU ST	1/4-1/2NNE L57	98
ROCHESTER GAS&ELECTRIC BE	296 MILL STREET/BEEBEE	1/4 - 1/2WNW M58	109
ROCHESTER GAS & ELECTRIC CORP	254 MILL ST	1/4 - 1/2 WNW M59	111

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the UST list, as provided by EDR, and dated 01/01/2002 has revealed that there are 5 UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
AERO AUTOCARE, INC.	430 ANDREWS STREET	1/8 - 1/4 E	F28	29
MAGUIRE FAMILY PROPERTIES	439 CENTRAL AVENUE	1/8 - 1/4 NE	135	45
Lower Elevation	Address	Dist / Dir	Map ID	Page
UNITED STATES POSTAL SERVICE	DOWNTOWN STATION	0 - 1/8 NNE	17	21
CROSSROADS APARTMENTS	GENESEE CROSSROADS PARC	0 - 1/8 SW	19	24

NY VCP: Voluntary Cleanup Agreements. The voluntary remedial program uses private monies to get contaminated sites remediated to levels allowing for the sites' productive use. The program covers virtually any kind of site and contamination.

A review of the VCP list, as provided by EDR, and dated 12/17/2004 has revealed that there are 3 VCP sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
FORMER HALLMAN'S CHEVROLET	196-212 EAST AVENUE	1/4 - 1/2SE	J46	63
Lower Elevation	<u>Address</u>	Dist / Dir	Map ID	Page
RG&E - BEEBEE STATION RG&E - WEST STATION MGP SITE	254 MILL STREET 254 MILL STREET	1/4 - 1/2 WNI 1/4 - 1/2 WNV	V M60 V M61	115 116

MAP FINDINGS

Map ID Direction Distance Distance (ft.) Elevation Site

EDR ID Number EPA ID Number

Database(s)

S102679031 PAL OIL (Continued) UST Involvement: False Spill Record Last Update: 02/21/92 Is Updated: False Corrective Action Plan Submitted: 11 02/20/92 Date Spill Entered In Computer Data File: Date Region Sent Summary to Central Office: / / Tank Test: PBS Number: Not reported Tank Number: Not reported Test Method: Not reported Capacity of Failed Tank: Not reported Not reported Leak Rate Failed Tank: Gross Leak Rate: Not reported Material: Material Class Type: 1 Quantity Spilled: 8 Gallons Units: Unknown Qty Spilled: 8 Quantity Recovered: 0 Unknown Qty Recovered: False Material: GASOLINE Class Type: Petroleum GASOLINE Chem Abstract Service Number: 09/29/1994 Last Date: Num Times Material Entry In File: 21329 02/17/92: ROCHESTER FIRE DEPT CLEANED UP WITH SPEEDY DRI. DEC Remarks: PAL OIL OVERFILLED A BULK STORAGE TANK. CONTACT PERSON: KEVIN KYLE Spill Cause: S101650498 SWF/LF J43 **RUSSELL GAS & ELECTRIC** 89 EAST AVE. N/A SE 1/4-1/2 ROCHESTER, NY 0 1990 ft. Site 1 of 3 in cluster J Relative: LF: Higher Secondary Addr : Not reported Region Code : **ROCHESTER GAS & ELECTRIC** Phone Number: Not reported Owner Name : Actual: 535 ft. Owner Type : Private Owner Address: 89 EAST AVE. Not reported ROCHESTER, NY 14649 Owner Phone : Owner Email : Not reported Not reported Contact Name : Not reported Contact Address : Not reported Not reported Not reported Contact Email : Not reported Contact Phone : Not reported Landfill - construction and demolition debris Activity Desc : Activity Number: 28D13 Accuracy Code : Active Not reported No North Coordinate :Not reported East Coordinate : Not reported Regulatory Status None Waste Type : Not reported Authorization Date :Not reported Authorization # : None Expiration Date : Not reported INACTIVE Flag :

The EDR Radius Map[™] Report

The Kirstein Building 242 Andrews St. Rochester, NY 14604

Inquiry Number: 01376628.1r

March 10, 2005

EDR[™] Environmental Data Resources Inc

The Standard in Environmental Risk Management Information

440 Wheelers Farms Road Milford, Connecticut 06460

Nationwide Customer Service

 Telephone:
 1-800-352-0050

 Fax:
 1-800-231-6802

 Internet:
 www.edrnet.com

FORM-ERK

TABLE OF CONTENTS

SECTION

PAGE

Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	6
Orphan Summary	120
EPA Waste Codes	EPA-1
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

GeoCheck - Not Requested

Thank you for your business. Please contact EDR at 1-800-352-0050 with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADDE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2005 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

A search of available environmental records was conducted by Environmental Data Resources, Inc. (EDR). The report meets the government records search requirements of ASTM Standard Practice for Environmental Site Assessments, E 1527-00. Search distances are per ASTM standard or custom distances requested by the user.

TARGET PROPERTY INFORMATION

ADDRESS

242 ANDREWS ST. ROCHESTER, NY 14604

COORDINATES

 Latitude (North):
 43.160200 - 43° 9' 36.7"

 Longitude (West):
 77.608800 - 77° 36' 31.7"

 Universal Tranverse Mercator:
 Zone 18

 UTM X (Meters):
 287903.4

 UTM Y (Meters):
 4781694.0

 Elevation:
 519 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property: Source:

43077-B5 ROCHESTER EAST, NY USGS 7.5 min quad index

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable") government records either on the target property or within the ASTM E 1527-00 search radius around the target property for the following databases:

FEDERAL ASTM STANDARD

NPL	National Priority List
Proposed NPL	Proposed National Priority List Sites
CERCLIS	Comprehensive Environmental Response, Compensation, and Liability Information
	System
CERC-NFRAP	CERCLIS No Further Remedial Action Planned
CORRACTS	Corrective Action Report
RCRA-TSDF	Resource Conservation and Recovery Act Information
ERNS	Emergency Response Notification System

STATE ASTM STANDARD

CBS UST..... Chemical Bulk Storage Database

1000

MOSF UST	Major Oil Storage Facilities Database
SWTIRE	Registered Waste Tire Storage & Facility List
SWRCY	Registered Recycling Facility List

FEDERAL ASTM SUPPLEMENTAL

CONSENT	Superfund (CERCLA) Consent Decrees
ROD	Records Of Decision
Delisted NPL	National Priority List Deletions
FINDS	Facility Index System/Facility Identification Initiative Program Summary Report
HMIRS	Hazardous Materials Information Reporting System
MLTS	Material Licensing Tracking System
MINES	Mines Master Index File
NPL Liens	Federal Superfund Liens
PADS	PCB Activity Database System
INDIAN RESERV	Indian Reservations
UMTRA	Uranium Mill Tailings Sites
OD1	Open Dump Inventory
DOD	Department of Defense Sites
RAATS	RCRA Administrative Action Tracking System
TRIS	Toxic Chemical Release Inventory System
TSCA	Toxic Substances Control Act
SSTS	Section 7 Tracking Systems
FTTS INSP	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, &
	Rodenticide Act)/TSCA (Toxic Substances Control Act)

STATE OR LOCAL ASTM SUPPLEMENTAL

HSWDS	Hazardous Substance Waste Disposal Site Inventory
AST	Petroleum Bulk Storage
CBS AST	Chemical Bulk Storage Database
MOSF AST	Major Oil Storage Facilities Database
DEL SHWS	Delisted Registry Sites
AIRS	Air Emissions Data
SPDES	State Pollutant Discharge Elimination System
AIRSSPDES	Air Emissions Data State Pollutant Discharge Elimination System

EDR PROPRIETARY HISTORICAL DATABASES

Coal Gas_____ Former Manufactured Gas (Coal Gas) Sites

BROWNFIELDS DATABASES

US BROWNFIELDS...... A Listing of Brownfields Sites Brownfields...... Brownfields Site List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property. Page numbers and map identification numbers refer to the EDR Radius Map report where detailed

data on individual sites can be reviewed.

Sites listed in **bold italics** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

FEDERAL ASTM STANDARD

RCRAInfo: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRAInfo replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System(RCRIS). The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month. Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste, or over 1 kg of acutely hazardous waste per month. Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste.

EXECUTIVE SUMMARY

A review of the RCRA-LQG list, as provided by EDR, and dated 11/23/2004 has revealed that there are 2 RCRA-LQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
ROCHESTER CITY OF FORMER PRINT	304-308 ANDREWS ST	0 - 1/8 E	C11	16
CITY OF ROCHESTER MICHAELS STE	87 N CLINTON AVE	1/8 - 1/4SE	E20	25

RCRAInfo: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRAInfo replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System(RCRIS). The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month. Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month Large quantity generators generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month. Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

A review of the RCRA-SQG list, as provided by EDR, and dated 11/23/2004 has revealed that there are 17 RCRA-SQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
SILVER DRY CLEANING CO INC	245 ANDREWS ST	0-1/8 ESE	A3	7
YWCA - PER CON ELEC	175 N CLINTON AVE	0-1/8 ENE	4	8
ROCHESTER EDUCATION OPPOR CENT	305 ANDREWS ST	0-1/8 E	C12	16
JOYCE FAMILY PROPERTIES	172-180 PLEASANT ST	1/8 - 1/4ESE	23	26
ST VINCENT PRESS	250 CUMBERLAND ST	1/8 - 1/4 ENE	24	26
BARIS TAILORING	48 ST PAUL ST	1/8 - 1/4 S	25	27
ROCHESTER CITY OF ROCHESTER BU	414 ANDREWS ST	1/8 - 1/4 <i>E</i>	F26	27
FLEET BANK	159 E MAIN ST	1/8 - 1/4 S	31	43
HYATT REGENCY ROCHESTER	125 E MAIN ST	1/8 - 1/4 S	H32	43
ROCHESTER RIVERSIDE CEONVENT/O	123 E MAIN ST	1/8 - 1/4 S	H33	44
CASE-HOYT CENTRAL AVENUE	439 CENTRAL AVE	1/8 - 1/4 NE	134	44
LAMINATING ARTS & FINISHES INC	439 CENTRAL AVE	1/8 - 1/4NE	136	50
Lower Elevation	Address	Dist / Dir	Map ID	Page
RUMRILL-HOYT INC	180 ST PAUL ST	0-1/8 W	B5	8

Lower Elevation	Address	Dist / Dir	Map ID	Page
 NYSDOT BIN 1048750 & 104875A	CLINTON AVE OVER I-490	0-1/8 N	D14	18
H & A OF NEW YORK	189 N WATER ST	1/8 - 1/4 W	21	25
ROCHESTER CITY OF OLD GREYHOUN	120 ANDREWS ST	1/8 - 1/4 WSW	/ 22	26
ROCHESTER GAS & ELECTRIC CORPO	84 ANDREWS STREET	1/8 - 1/4 WSW	G38	52

STATE ASTM STANDARD

SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the SHWS list, as provided by EDR, has revealed that there are 2 SHWS sites within approximately 1 mile of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
FORMER RAECO PRODUCTS	24 SPENCER STREET	1/2 - 1 WNW	/ 63	117
FORMER ROCHESTER METAL ETCHING	100 LAKE AVENUE	1/2 - 1 WNW	/ 64	118

SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the list.

A review of the SWF/LF list, as provided by EDR, has revealed that there is 1 SWF/LF site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
RUSSELL GAS & ELECTRIC	89 EAST AVE.	1/4 - 1/2SE	J43	59

LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the LTANKS list, as provided by EDR, and dated 02/10/2005 has revealed that there are 26 LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Higher Elevation Address		Map ID	Page
NUSBAUM CLEANER DISTRIB.	304-308 ANDREW ST.	0-1/8 E	C7	10
CULLARI (JAMES) APARTMENT	130 NORTH CLINTON AVENU	0 - 1/8 ESE	C8	11
WALLACH (ERWIŃ)	430 ANDREWS STREET	1/8 - 1 /4 E	F27	28
JOHNSON & LUND	167 LIBERTY POLE WAY	1/8 - 1/4 E	29	34
PALOIL	EAST MAIN STREET	1/4 - 1/2ESE	42	58
YMCA (OLD)	26 GIBBS STREET	1/4 - 1/2ESE	44	60
CONSTRUCTION SITE	CLINTON / BROAD STREE	1/4 - 1/2SSE	45	61
HALLMAN CHEVROLET (FORMER)	200 EAST AVENUE	1/4 - 1/2 SE	J47	63
JOMOR ENTERPRISES	246 EAST AVENUE	1/4 - 1/2ESE	50	85
FORMER DMV PARKING LOT	SOUTH AVENUE @COURT STR	1/4 - 1/2 SSE	52	91
Lower Elevation	Address	Dist / Dir	Map ID	Page
RAE OIL COMPANY	195 ST PAUL BOULEVARD	0 - 1/8 W	B6	9

TC01376628.1r EXECUTIVE SUMMARY 4

Lower Elevation

Lower Elevation	Address	Dist / Dir	Map ID	Page
ROCHESTER GAS & ELECTRIC CORP	84 ANDREWS STREET	1/8 - 1/4 WSW	G30	36
ROCHESTER GAS & ELECTRIC	FRONT / ANDREWS STREE	1/8 - 1/4WSW	G37	50
ST. SIMONS TERRACE	360-ST PAUL STREET	1/4 - 1/2NNW	39	54
FIGHT VILLAGE APARTMENTS	WARD / NORTH CLINTON	1/4 - 1/2N	40	55
GERMANOW-SIMON INC	408 ST PAUL STREET	1/4 - 1/2NW	41	56
PEPSI COLA FACILITY	425 ORMOND STREET	1/4 - 1/2NNE	K48	79
PEPSI COLA BOTTLING COMPANY	425 ORMOND STREET	1/4 - 1/2NNE	K49	82
HIGH FALLS BREWING COMPANY	445 ST PAUL STREET	1/4 - 1/2 NW	51	87
ROCHESTER (CITY OF)	MILL ST-HOLLEY PUMP STA	1/4 - 1/2W	53	92
SIBLEYS DISTRIBUTION CTR	62 NASSAU STREET	1/4 - 1/2NNE	L54	94
	68 NASSAU STREET	1/4 - 1/2NNE	L55	95
WILLOW INDUSTRIES	68 NASSAU ROAD	1/4 - 1/2NNE	L56	97
UNITED PARCEL SERVICE	75 NASSAU ST	1/4 - 1/2 NNE	L57	98
ROCHESTER GAS&ELECTRIC BE	296 MILL STREET/BEEBEE	1/4 - 1/2 WNW	M58	109
ROCHESTER GAS & ELECTRIC CORP	254 MILL ST	1/4 - 1/2WNW	M59	111

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the UST list, as provided by EDR, and dated 01/01/2002 has revealed that there are 5 UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page	
AERO AUTOCARE, INC.	430 ANDREWS STREET	1/8 - 1/4 E	F28	29	
MAGUIRE FAMILY PROPERTIES	439 CENTRAL AVENUE	1/8 - 1/4 NE	135	45	
Lower Elevation	Address	Dist / Dir	Map ID	Page	
UNITED STATES POSTAL SERVICE	DOWNTOWN STATION	0 - 1/8 NNE	17	21	
CROSSROADS APARTMENTS	GENESEE CROSSROADS PARC	0 - 1/8 SW	19	24	
ROCHESTER GAS & ELECTRIC CORP	84 ANDREWS STREET	1/8 - 1/4WSW	7 G30	36	

NY VCP: Voluntary Cleanup Agreements. The voluntary remedial program uses private monies to get contaminated sites remediated to levels allowing for the sites' productive use. The program covers virtually any kind of site and contamination.

A review of the VCP list, as provided by EDR, and dated 12/17/2004 has revealed that there are 3 VCP sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page	
FORMER HALLMAN'S CHEVROLET	196-212 EAST AVENUE	1/4 - 1/2 SE	J46	63	
Lower Elevation	Address	Dist / Dir	Map ID	Page	
RG&E - BEEBEE STATION	254 MILL STREET	1/4 - 1/2 WN	N M60	115	
RG&E - WEST STATION MGP SITE	254 MILL STREET	1/4 - 1/2 WNV	V M61	116	

FEDERAL ASTM SUPPLEMENTAL

FUDS: The Listing includes locations of Formerly Used Defense Sites Properties where the US Army Corps Of Engineers is actively working or will take necessary cleanup actions.

A review of the FUDS list, as provided by EDR, and dated 12/31/2003 has revealed that there is 1 FUDS site within approximately 1 mile of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
NAVY & MARINE CNTR #3		1/2 - 1 NE	62	116

STATE OR LOCAL ASTM SUPPLEMENTAL

SPILLS: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 02/10/2005 has revealed that there are 7 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
HENNING ELECTRIC FORMER AMOCO NUSBAUM (A) CO	55 BITTNER STREET 128 NORTH CLINTON 304-308 ANDREWS STREET	0 - 1/8 NE 0 - 1/8 ESE 0 - 1/8 E	1 9 C10 518	6 13 14 23
Lower Elevation	Address	Dist / Dir	Map ID	Page
AGRICULTURAL TRANSPORT MV CUSTOM TIRE GENESSEE BREWERY	ROUTE 490 E/ CLINTON AV 209 NORTH CLINTON AVENU 245 ST PAUL BLVD	0 - 1/8 N 0 - 1/8 NNE 0 - 1/8 NW	D13 15 16	17 19 20

DRYCLEANERS: A listing of all registered drycleaning facilities.

A review of the DRYCLEANERS list, as provided by EDR, and dated 06/15/2004 has revealed that there is 1 DRYCLEANERS site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page	
SILVER DRY CLEANERS	245 ANDREWS STREET	0 - 1/8 ESE	A2	7	

BROWNFIELDS DATABASES

NY VCP: Voluntary Cleanup Agreements. The voluntary remedial program uses private monies to get contaminated sites remediated to levels allowing for the sites' productive use. The program covers virtually any kind of site and contamination.

A review of the VCP list, as provided by EDR, and dated 12/17/2004 has revealed that there are 3 VCP

sites within approximately 0.5 miles of the target property.

.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page	
FORMER HALLMAN'S CHEVROLET	196-212 EAST AVENUE	1/4 - 1/2 SE	J46	63	
Lower Elevation	Address	Dist / Dir	Map ID	Page	
RG&E - BEEBEE STATION RG&E - WEST STATION MGP SITE	254 MILL STREET 254 MILL STREET	1/4 - 1/2 WNV 1/4 - 1/2 WNV	V M60 V M61	115 116	

TC01376628.1r EXECUTIVE SUMMARY 7

Due to poor or inadequate address information, the following sites were not mapped:

22.2

Site Name	Database(s)
RT 490 AT INNER LOOP MVA	NY Spills
NYS BARGE CANAL	NY Spills
ROUTE 490 @CLINTON BRIDGE	NY Spills
WASTE MANAGEMENT	NY Spills
ROUTE 490 & ROUTE 390	NY Spills
RT 490 MVA	NY Spills
MVA	NY Spills
BAYLOR (HOMER) MVA	NY Spills
RT 490 AT GOODMAN ST MVA	NY Spills
FLORIAN, MICHAEL	NY Spills
AMERICAN FREIGHT SYSTEM	NY Spills
TRADCO MVA	NY Spills
GOTTRY CORP MVA	NY Spills
RT 490 MVA	NY Spills
GOODMAN EXIT	NY Spills
CROP CAIR	NY Spills
BARGE CANAL AT ROUTE 490	NY Spills
BARGE CANAL @ROUTE 490	NY Spills
RYDER DEDICATED LOGISTICS	NY Spills
AMES & CHILD ACCIDENT	NY Spills
ROCHESTER MACHINERY TRUCK	NY Spills
ROUTE 490 EASTBOUND	NY Spills
ROUTE 490 AT ROUTE 590	NY Spills
ROUTE 490 EAST TO 590 N	NY Spills
ROUTE 490	NY Spills
ROUTE 490	NY Spills
GREYHOUND BUS LINES	NY Spills
RT 490 MVA	NY Spills
AMERICAN MOLD	NY Spills
CLINTON STREET SOUTH	NY Spills
SOUTH CLINTON AVENUE	NY Spills
KODAK PARK BUILDING 218	NY Spills
5TH ST	NY Spills
EMPIRE BOULEVARD & RT 590	NY Spills
IN FRONT OF 65 LYCEUM ST	NY Spills



TARGET PROPERTY:The KirADDRESS:242 AnCITY/STATE/ZIP:RochesLAT/LONG:43.160

The Kirstein Building 242 Andrews St. Rochester NY 14604 43.1602 / 77.6088 CUSTOMER: Passero Associates CONTACT: Pete Morton INQUIRY #: 01376628.1r DATE: March 10, 2005 5:30 pm

Copyright © 2005 EDR, Inc. © 2003 GDT, Inc. Rel. 07/2003. All Rights Reserved.



Copyright @ 2005 EDR, Inc. @ 2003 GDT, Inc. Rel. 07/2003. All Rights Reserved.

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	<u>1/2 - 1</u>	> 1	Total Plotted
FEDERAL ASTM STANDARD	<u>)</u>							
NPL Proposed NPL CERCLIS CERC-NFRAP CORRACTS RCRA TSD RCRA Lg. Quan. Gen. RCRA Sm. Quan. Gen. ERNS		1.000 1.000 0.500 0.250 1.000 0.500 0.250 0.250 TP	0 0 0 0 1 5 NR	0 0 0 0 1 12 NR	0 0 0 N R 0 0 N R N R	0 NR NR 0 NR NR NR	NR NR NR NR NR NR NR NR	0 0 0 0 2 17 0
STATE ASTM STANDARD								
State Haz. Waste State Landfill LTANKS UST CBS UST MOSF UST VCP SWTIRE SWRCY		1.000 0.500 0.250 0.250 0.500 0.500 0.500 0.500	0 0 3 2 0 0 0 0 0 0	0 4 3 0 0 0 0	0 1 19 NR 0 3 0 0	2 NR NR NR NR NR NR	NR NR NR NR NR NR NR	2 1 26 5 0 3 0 0
FEDERAL ASTM SUPPLEME	NTAL							
CONSENT ROD Delisted NPL FINDS HMIRS MLTS MINES NPL Liens PADS INDIAN RESERV FUDS UMTRA ODI DOD RAATS TRIS TSCA SSTS FTTS		1.000 1.000 TP TP TP 0.250 TP TP 1.000 1.000 0.500 0.500 1.000 TP TP TP TP	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 0 RR R 0 RR 0 0 0 0 0 RR RR R N N 0 N N 0 0 0 0 0 0 R R R R R N N N N N N N N N N N N N N N	0 0 0 RR RR RR 0 0 0 0 0 RR RR RR RR RR	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	R R R R R R R R R R R R R R R R R R R	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
STATE OR LOCAL ASTM SU	PPLEMENTA	<u>L</u>						
HSWDS		0.500	0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

93. **1**88

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
AST		TP	NR	NR	NR	NR	NR	0
CBS AST		0.250	0	0	NR	NR	NR	Ō
MOSF AST		0.500	0	0	0	NR	NR	0
NY Spills		0.125	7	NR	NR	NR	NR	7
DEL SHWS		1.000	0	0	0	0	NR	0
DRYCLEANERS		0.250	1	0	NR	NR	NR	1
AIRS		TP	NR	NR	NR	NR	NR	0
SPDES		TP	NR	NR	NR	NR	NR	0
EDR PROPRIETARY HIS	TORICAL DATAB	ASES						
Coal Gas		1.000	0	0	0	0	NR	0
BROWNFIELDS DATABA	ASES							
US BROWNFIELDS		0.500	0	0	0	NR	NR	0
Brownfields		0.500	0	0	0	NR	NR	0
VCP		0.500	0	0	3	NR	NR	3

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

TC01376628.1r Page 5

MAP FINDINGS

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

Coal Gas Site Search: No site was found in a search of Real Property Scan's ENVIROHAZ database.

1 NE < 1/8 78 ft.	HENNING ELECTRIC 55 BITTNER STREET ROCHESTER, NY				NY Spills	S104652801 N/A
Relative: Higher	SPILLS: Spill Number:	0070107		Region of Spill:	8	
Actual: 520 ft.	ID: Date Call Receive Region Close Da	ed: te :	628 7 2 05/15/00 05/15/00		11	
	Material Spilled: Water Affected: Spill Cause: Tank Number:	GASOLIN COMBINE Other Not report	E D SEWERS ed	Amount Spilled: Spill Source: Resource Affected Tank Size :	30 Gal. COMMERCIAL VEHICL : Surface Water Not reported	.E
	lest Method:	Not report	ed	Leak Rate:	Not reported	
	Spill Number: Spill Date: ID: Date Call Receive Region Close Dat	0070107 05/13/200	0 12:00 Not reported Not reported	Region of Spill: Reported to D e pt:	8 05/15/00 14:02	
	Material Spilled: Water Affected: Spill Cause:	Not report COMBINE Other	D SEWERS	Amount Spilled: Spill Source: Resource Affected	Not reported Commercial Vehicle : Surface Water	
	Water Affected: Facility Contact: Investigator:	COMBINE Not reporte DT	D SEWERS ed	Spill Source: Facility Tele: SWIS:	Commercial Vehicle (716) 473-3392 26	
	Caller Name: Caller Phone: Notifier Name: Notifier Phone:	Not report Not report Not report	ed ed ed	Caller Agency: Caller Extension: Notifier Agency:	Not reported Not reported Not reported	
	PBS:	Not report	ed	Notifier Extension:	Not reported	
	Spiller Contact: Spiller: Spiller Address:	Not reporte HENNING MONROE	ed ELECTRIC AVENUE	Spiller Phone:	Not reported	
ROCHESTER, NY DEC Remarks : Not reported Remark: A TRUCK HIT A PIECE OF METAL THAT RIPPED TH GASOLINE TO ASPHALT. MOST OF THE MATERIAL AND GREEN STUFF. APPROXIMATELY 5 GALLONS NOTIFIED AND SEWER WAS FLUSHED. ONE DRUM OF WASTE WAS GENERATED. CITY OF RO				T RIPPED THE GAS IE MATERIAL WAS Y 5 GALLONS WENT D. ONE CITY OF ROCHEST 130 HRS	S TANK OPEN, SPILLING CLEANED UP WITH SPE T TO COMBINED SEWEF ER HIRED EP S TO DISI	i EEDI DRI RS. MCPW POSE OF.
	Spill Class:	Known rele	ase with minimal potential for	fire or hazard. DEC F	Response.	
	Tank Test: PBS Number: Tank Number: Test Method: Capacity of Fail Leak Rate Faile Gross Leak Rat Material:	Willing Res ed Tank: d Tank: e:	ponsible Party. Corrective act Not reported Not reported Not reported Not reported Not reported Not reported	ion taken.		
	Material Class	ype:	1			

Map ID Direction Distance Distance (ft Elevation	.) Site			MAP FINDING	S		EDR ID Number		
					·				
	HENNING ELECTR	IC (Continue	d)				S104652801		
	Quantity Sn	illed:	30						
	Units:	incu.	Gallons						
	Unknown Q	ty Spilled:	30						
	Quantity Re	covered:	25						
	Unknown Q	ty Recovered:	False						
	Material:		GASOLINE						
	Class Type:		Petroleum	0.000					
	Chem Abstr	act Service NL	imber:	GASOLINE					
	Num Times	Material Entry	In File:	09/29/1994					
	Spill Closed Df	1. 05/15/00	in rue.	21329					
	Spill Notifier:	Health De	partment		PBS Number:	Not reported			
	Cleanup Cease	ed: 05/15/00							
	Last Inspection	n: //			Cleanup Meets Sto	i:False			
	Recommended	d Penalty:	Penalty Not Re	ecommended					
	Spiller Cleanup	Dt//			Enforcement Date:	11			
	Invstgn Comple	ete://	05/10/00		UST Involvement:	False			
	Is Lindsted	ast opdate:	05/16/00 Falso						
	Corrective Acti	on Plan Subm	itted.	11					
	Date Spill Entered In Computer Data File: 05/15/00 14:09								
	Date Region Sent Summary to Central Office: / /								
	This is the most recent NY SPILLS record for this site.								
		~							
	Click this hyperlink while viewing on your computer to access								
		v.e.v.a							
A 2	SILVER DRY CLEAR	NERS				DRYCLEANERS	S106437422		
ESE	245 ANDREWS STREET ROCHESTER, NY 14604						N/A		
< 1/8									
248 ft.		- •							
Relative:	Site 1 of 2 in cluste	ГA							
ligher	Drycleaners:								
	Facility ID :		8-2626-00088	3					
Actual:	Region :		REG 8						
2311.									
13	SILVER DRY CLEAR					PCPA SOC	1000420256		
ESE	245 ANDREWS ST					FINDS	NYD013138110		
< 1/8	ROCHESTER, NY 1	4604							
248 ft.									
Relative: Higher	Site 2 of 2 in cluster A								
	RCRAInfo:								
	Owner:	PAUL MANU	JSE						
Actual:		(212) 555-12	212						
123 IT.	EPA ID:	NYD013138	110						
	Contact:	PAUL MANU	JSE						
		(716) 454-49	50						
	Classification:	Small Quanti	ity Generator						
	TSDF Activities	: Not reported							

MAP FINDINGS

4

ENE

< 1/8

288 ft.

Relative:

Higher

Actual:

524 ft.

B5

West

< 1/8

370 ft.

Lower

Actual:

516 ft.

Relative:

EDR ID Number Database(s) EPA ID Number SILVER DRY CLEANING CO INC (Continued) 1000430356 Violation Status: No violations found NY MANIFEST Click this hyperlink while viewing on your computer to access additional NY MANIFEST detail in the EDR Site Report. FINDS: Other Pertinent Environmental Activity Identified at Site: Aerometric Information Retrieval System/AIRS Facility Subsystem Resource Conservation and Recovery Act Information system YWCA - PER CON ELEC RCRA-SQG 1000871202 175 N CLINTON AVE NY000003863 FINDS ROCHESTER, NY 14604 RCRAInfo: 175 NORTH CLINTON ASSOCIATERS LP Owner: (212) 555-1212 EPA ID: NY000003863 Contact: Not reported Classification: Small Quantity Generator TSDF Activities: Not reported Violation Status: No violations found FINDS: Other Pertinent Environmental Activity Identified at Site: Resource Conservation and Recovery Act Information system RUMRILL-HOYT INC RCRA-SQG 1000361940 180 ST PAUL ST FINDS NYD980763908 ROCHESTER, NY 14604 Site 1 of 2 in cluster B RCRAInfo: RUMRILL HOYT INC Owner: (212) 555-1212

EPA ID: NYD980763908 Contact: Not reported Classification: Small Quantity Generator

TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site: Resource Conservation and Recovery Act Information system

MAP FINDINGS

Map ID Direction Distance Distance Elevation

Distance (ft. Elevation) Site						Database(s)	EDR ID Number EPA ID Number
B6 West < 1/8	RAE OIL COMPANY 195 ST PAUL BOULEVARD ROCHESTER, NY							S102678572 N/A
302 It.	Site 2 of 2 in cluster B							
Relative:								
Lower	Spill Number:	7881018			Region of Spill:	8		
Actual:	Spill Date:	10/18/78			Reported to Dept:	Ĩ		
514 ft.	ID:	94659			Date Call Receive	d:10/18/78	3	
	Material Spilled:	#2 FUEL	OIL		Amount Spilled:	200 Gal	l.	
	Region Close Dt:	10/18/78						
	Water Affected:	SANITAR	Y SEWER		Spill Source:	PRIVAT	E DWELLING	
	Resource Affectd	: In Sewer						
	Spill Cause:	Tank Ove	rfill					
	Tank Number:	Not report	led		Tank Size:	Not repo	rted	
	PBS:	Not report	led		Leak Rate:	Not repo	rted	
	Spill Number:	7881018			Region of Spill:	8		
	Spill Date:	10/18/197	8 11:00		Reported to Dept:	10/18/78		
	iD:	Not report	ed		Date Call Received	d:Not repo	rted	
	Material Spilled:	Not report	ed		Amount Spilled:	Not repo	rted	
	Region Close Dt:	Not report	ed		•	•		
	Water Affected:	SANITARY SEWER			Spill Source:	Private D	Owelling	
	Resource Affectd	In Sewer						
	Spill Cause:	Tank Ove	ank Overfill					
	Facility Contact:	Not report	ed	d Facility Tele: Not re		Not repo	rted	
	Investigator:	BF Not report	eported eported eported eported eported eported		SWIS: Caller Agency: Caller Extension: Notifier Agency: Notifier Extension: Spiller Phone:	26 Not so to to to		
	Caller Name.	Not report				Not repo	rtea	
	Notifier Name:	Not report				Not reported		
	Notifier Phone:	Not report				Not reported	rted	
	PBS:	Not report				Not reported		
	Spiller Contact:	Not report						
	Spiller:	RAE OIL COMPANY				•		
	Spiller Address:	195 ST PA	AUL BOULEVAR TER	D				
	Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken						
	Spill Closed Dt:	10/18/78						
	Spill Notifier:	Local Age	ncy		PBS Number:	Not repor	rted	
	Cleanup Ceased:	10/18/78						
	Last Inspection:	//	-					
	Cleanup Meets St	andard:	I rue					
	Spiller Cleanup Dr	enaity:	Penalty Not Re	commended				
	Enforcement Date	ale.	11					
	Investigation Com	nlete:	10/18/78					
	UST Involvement:	P	False					
	Spill Record Last	Update:	01/09/01					
	Is Updated.		False					
	Corrective Action	Plan Subm	itted:	11				
	Date Spill Entered Date Region Sent Tank Test:	In Comput Summary	ter Data File: to Central Office	01/06/93 : / /				
	PBS Number:		Not reported					
	Tank Number:		Not reported					
	Test Method:		Not reported					



Map ID Direction Distance Distance (ft.) Elevation Site

C7

East < 1/8

394 ft.

Relative:

Higher

Actual:

527 ft.

Spiller: Spiller Address: NUSBAUM CLEANER DIST.

304-308 ANDREW ST. ROCHESTER, NY

Database(s)

EDR ID Number EPA ID Number

RAE OIL COMPANY (Continued)

Capacity of Failed Tank: Not reported Loak Rate Failed Tank: Not reported Gross Leak Rate: Not reported Material: Spiled: 200 Units: Gallons Unknown Dty Spilled: 200 Quantity Spilled: 200 Unknown Dty Spilled: 200 Date Strate Service Number: #2 FUEL OLL Class Type: Petroloum Chem Abstract Service Number: #2 FUEL OLL Last Date: 1207/1994 Num Times Material Entry In File: 24464 DEC Remarks: FIRE DEPARTMENT FLUSHED OLL TO CATCH BASINS IN ALLEY BEHIND BUILDING WHI CHE PRETER SEWER SYSTEM IN CITY, 1/8/01: PAPER FILE REMOVED AS PER RECOR D RETENTION POLICY. Spill Cause: RAE OL CO. OVERFILLED HOME HEATING OLL TANK CAUSING NO. 2 FUEL OIL TO F LUW OUT OF VENT PPE AND INTO COMBINED SEWER TO VAN CARE STP. NUSBAUM CLEANER DISTRIB. Suit 16 sin cluster C LTANKS: Spill Date: 05/22/86 Material Spilled: Not reported Spill Cause: Tank Failure Tank Number: 8601285 Region of Spill: \$ Spill Cause: Tank Failure Tank Number: 801285 Region of Spill: \$ Spill Cause: Tank Failure Tank Number: 801285 Region of Spill: \$ Spill Cause: Tank Failure Tank Number: 801285 Region of Spill: \$ Spill Cause: Tank Failure Tank Number: 8012936 Water Affection Land Spill Cause: Tank Failure Tank Number: 8012955 Region of Spill: \$ Spill Date: 05/22/86 Water Affectid: OL Land Spill Cause: Tank Failure Tank Number: 8012955 Region of Spill: \$ Spill Date: 05/22/86 Not reported Date Call Received Dispited: Not reported Tank Number: 8012955 Region of Spill: \$ Spill Cause: Tank Failure Tank Number: 8012955 Region of Spill: \$ Spill Cause: Tank Failure Tank Number: 801295 Strate Strate Spill Source: Other CommercialIndustrial Resource Affectid: Not reported Material Spilled: Not reported Region Clase Dt: Not reported Region Clase Dt: Not reported Region Clase Tank Failure Facility Tele: Not reported Region Clase Tank Failure Facility Tele: Not reported Region Clase Tank Failure Facility Tele: Not reported Region Clase Dt: Not reported Region Clase Dt: Not reported Re	RAEC	DIL COMPANY (Continued	1)	S102678572					
Leak Rate Failed Tank: Not reported Gross Leak Rate: Not reported Material: Material Class Type: 1 Quantity Spilled: 200 Quantity Recovered: 0 Unknown Qly Spilled: 200 Quantity Recovered: 0 Unknown Qly Recovered: 1 Other Abstract Service Number: #2 FUEL OIL Class Type: Petroleum Chem Abstract Service Number: #2 FUEL OIL TO CATCH BASINS IN ALLEY BEHIND BUILDING WHI CH ENETER SEWER SYSTEM IN CITY, 1/8/01: PAPER FILE REMOVED AS PER RECOR D RETENTION POLICY. Spill Cause: RAE OIL CO. OVERFILLED HOME HEATING OIL TANK CAUSING NO. 2 FUEL OIL TO F LOW OUT OF VENT PIPE AND INTO COMBINED SEWER TO VAN CARE STP. NUSBAUM CLEANER DISTRIB. Site 1 of 5 in cluster C LTANKS: Spill Number: 8601285 Region of Spill: 8 Spill Number: 8601285 Region of Spill: 8 Spill Number: 8601285 Region of Spill: 8 Spill Cause: Tank FABRIC SOFTENER Amount Spilled: 0 Ibs. Region Class Dt: 05/23/66 Water Affectid: Not reported Tank Number: 8601285 Region of Spill: 8 Spill Cause: Tank Failure Tank Number: 8601285 Region of Spill: 8 Spill Cause: Tank Failure Tank Number: 8601285 Region of Spill: 8 Spill Cause: Tank Failure Tank Number: 8601285 State Regoted Leak Rate: Not reported Meterial Spill Cause: Tank Failure Spill Cause: Tank Failure Spill Cause: Tank Failure Spill Cause: Tank Failure Facility Tole: Not reported Meter Affected: Not reported Meterial Spill Cause: Tank Failure Facility Tole: Not reported Caller Marne: Not reported Caller Marne: Not reported Notifier Flexen: Not reported		Capacity of Failed Tank: Not reported								
Gross Leak Rate: Not reported Material: Material Class Type: 1 Quantity Spilled: 200 Quantity Recovered: 0 Units: Gallons Unknown Qly Spilled: 200 Quantity Recovered: 1 Unknown Qly Recovered: False Material: #2 FUEL OIL Class Type: Petroleum Chern Abstract Service Number: #2 FUEL OIL Class Type: Petroleum Chern Abstract Service Number: #2 FUEL OIL Class Type: Petroleum Chern Abstract Service Number: #2 FUEL OIL Class Tate: 1207/1994 Num Times Material Entry In File: 24464 DEC Remarks: FIRE DEPARTMENT FLUSHED OIL TO CATCH BASINS IN ALLEY BEHIND BUILDING WHI CH ENETER SEWER SYSTEM IN CITY. 1/8/01: PAPER FILE REMOVED AS PER RECOR D RETERVITON POLICY. Spill Cause: RAE OIL CO. OVERFILLED HOME HEATING OIL TANK CAUSING NO. 2 FUEL OIL TO F LOW OUT OF VENT PIPE AND INTO COMBINED SEWER TO VAN CARE STP. MUSSAUM CLEANER DISTRIB. Site 1 of 5 in cluster C LTANKS: Spill Number: 8601/285 Spill Number: 8601/285 Spill Number: 8601/285 Region of Spill: 8 Spill Cause: Tank Failure Tank Name: Not reported Spill Cause: Tank Failure Tank Number: 8601/285 Region of Spill: 8 Spill Cause: Tank Failure Tank Number: 8601/285 Region of Spill: 9 Spill Cause: Tank Failure Tank Number: 8601/285 Region of Spill: 8 Spill Cause: Tank Failure Tank Number: 8601/285 Region of Spill: 8 Spill Cause: Tank Failure Tank Number: 8601/285 Region of Spill: 8 Spill Cause: Tank Failure Tank Number: 8601/285 Region of Spill: 8 Spill Cause: Tank Failure Tank Number: 8601/285 Region of Spill: 8 Spill Cause: Tank Failure Tank Number: 8601/285 Region of Spill: 8 Spill Cause: Tank Failure Tank Method: Not reported Material Spilled: Not reported Material Spilled: Not reported Material Spill Cause: Tank Failure Facility Tele: Not reported Material Spilled: Not reported Material Spilled: Not reported Material Spill Cause: Tank Failure Facility Tele: Not reported Material Spilled: No		Leak Rate Faile	ed Tank:	Not reported						
Material: Material: Material: 200 Quantity Spilled: 200 Unknown Oty Spilled: 200 Ouknity Recovered: 0 Unknown Oty Spilled: 200 Unknown Oty Spilled: 200 Unknown Oty Spilled: 200 Unknown Oty Spilled: 200 Unknown Oty Spilled: 220 Unknown Oty Spilled: 220 Chem Abstract Service Number: #2 FUEL OIL Last Date: 120/7/1994 Num Times Material Entry In File: 24464 DEC Remarks: FIRE DEPARTIMENT FLUSHED OIL TO CATCH BASINS IN ALLEY BEHIND BUILDING WHI CH ENETER SEWER SYSTEM IN CITY. 1/8/01: PAPER FILE REMOVED AS PER RECOR D R ETENTION POLICY Spill Cause: RAE OIL CO. OVERFILLED HOME HEATING OIL TANK CAUSING NO. 2 FUEL OIL TO F LOW OUT OF VENT PIPE AND INTO COMBINED SEWER TO VAN CARE STP. N/A NUSBAUM CLEANER DISTRIB. LTANKS S104276552 Spill Date: 05/22/86 Region of Spill: 6 S Spill Number: 8601285 Region of Spille: 0 Ibs. Region Close Dt: 05/22/86 Spill Source:		Gross Leak Rate: Not reported								
Material Class Type: 1 Quantity Spilled: 200 Quantity Recovered: 0 Unknown Qly Spilled: 200 Quantity Recovered: 0 Unknown Qly Recovered: 7 Material: #2 FUEL OIL Class Type: Petroleum Chem Abstract Services Number: #2 FUEL OIL Last Date: 12/07/1994 Num Times Material Entry In File: 2446 DEC Remarks: FIRE DEPARTMENT FLUSHED OIL TO CATCH BASINS IN ALLEY BEHIND BUILDING WHI CH ENETER SEWER SYSTEM IN CITY. 1/8/01: PAPER FILE REMOVED AS PER RECOR D RETENTION POLICY. Spill Cause: RAE OIL CO. OVERFILLED HOME HEATING OIL TANK CAUSING NO. 2 FUEL OIL TO F LOW OUT OF VENT PIEC AND INTO COMBINED SEWER TO VAN CARE STP. NUSBAUM CLEANER DISTRIB. Spill Cause: RAE OIL CO. OVERFILLED HOME HEATING OIL TANK CAUSING NO. 2 FUEL OIL TO F LOW OUT OF VENT PIEC AND INTO COMBINED SEWER TO VAN CARE STP. NUSBAUM CLEANER DISTRIB. Spill Cause: Size Stream	٩	Material:								
Quantity Spilled: 200 Units: Gallons Unknown Qly Spilled: 200 Quantity Recovered: 0 Unknown Qly Secured: 0 Unknown Qly Recovered: False Material: #2 FUEL OLL Class Type: Petroleum Chem Abstract Service Number: #2 FUEL OLL Last Date: 1207/1994 Num Times Material Entry In File: 24464 DEC Remarks: FIRE DEPARTMENT FLUSHED OIL TO CATCH BASINS IN ALLEY BEHIND BUILDING WHI CH ENETER SEWER SYSTEM IN CITY. 1/8/01: PAPER FILE REMOVED AS PER RECOR D RETENTION POLICY. Spill Cause: RAE OLIC.CO. VERTPLIZED HOME HEATING OIL TANK CAUSING NO. 2 FUEL OIL TO F LOW OUT OF VENT PIPE AND INTO COMBINED SEWER TO VAN CARE STP. N/A NUSSAUM CLEANER DISTRIB. LTANKS Spill Number: 8601285 Region of Spill: 8 Spill Date: 05/22/86 Reported to Dept: 1 / ID: 100140 Date Call Recoived/35/22/86 Water Affected: Not reported Spill Source: OTHER COMM/INDUSTRIAL Region of Spille: 8 Spill Source: OTHER COMM/INDUSTRIAL		Material Class	Гуре:	1						
Units: Gallons Unknown Oty Spille: 200 Ouantify Recovered: 0 Unknown Oty Spille: 201 Class Type: Petroleum Chem Abstract Services Number: #2 FUEL OIL Last Date: 12/07/1994 Num Times Material Entry In File: 2446 DEC Remarks: FIRE DEPARTMENT FLUSHED OIL TO CATCH BASINS IN ALLEY BEHIND BUILDING WHI CH ENETTER SEWER SYSTEM IN CITY. 1/8/01: PAPER FILE REMOVED AS PER RECOR D RETENTION POLICY. Spill Cause: RAE OIL CO. OVERFILLED HOME HEATING OIL TANK CAUSING NO. 2 FUEL OIL TO F LOW OUT OF VENT PIEC AND INTO COMBINED SEWER TO VAN CARE STP. NUSBAUM CLEANER DISTRIB. Solil Number: 8601285 Spill Sever Stream St		Quantity Spilled	l:	200						
Unknown Gty Spilled: 200 Quantify Recovered: 7 Unknown Gty Recovered: 7 Waterial: #2 FUEL OIL Class Type: Petroleum Chem Abstract Service Number: #2 FUEL OIL Last Date: 12/07/1994 Num Times Material Entry In File: 24464 DEC Remarks: FIRE DEPARTMENT FLUSHED OIL TO CATCH BASINS IN ALLEY BEHIND BUILDING WHI CH ENETER SEWER SYSTEM IN CITY, 1/8/01: PAPER FILE REMOVED AS PER RECOR D RETENTION POLICY. Spill Cause: RAE OIL CO. OVERFILLED HOME HEATING OIL TANK CAUSING NO. 2 FUEL OIL TO F LOW OUT OF VENT PIPE AND INTO COMBINED SEWER TO VAN CARE STP. TO VAN CLEANER DISTRIB. Spill Number: 8601285 Region of Spill: 8 Spill Number: 8601285 Region of Spill: 8 Spill Date: 05/22/86 Reported to Dept: / / ID: 100140 Date Call Received/05/22/86 Water Affected: Not reported Spill Source: OTHER COM/INDUSTRIAL Resource Affectd: On Land Spill Cause: Tank Failure Tank Number: 8601285 Region of Spill: 8 Spill Number: Not reported Spill Source: OTHER COM/INDUSTRIAL Resource Affectd: On Land Spill Cause: Tank Failure Tank Number: 8601285 Region of Spill: 8 Spill Number: 8601285 Region of Spill: 9 Spill Source: OTHER COM/INDUSTRIAL Resource Affectd: On Land Spill Cause: Tank Failure Tank Number: 8601285 Region of Spill: 8 Spill Date: 05/22/86 Source: OTHER COM/INDUSTRIAL Resource Affectd: On Land Spill Cause: Tank Failure Tank Number: 8601285 Region of Spill: 8 Spill Date: 05/22/86 15.15 Regotted to Dept: 05/22/86 15.35 ID: Not reported Leak Rate: Not reported Material Spilled: Not reported Spill Cause: Tank Failure Tank Size: Other Commercial/Industrial Resource Affectd: On Land Spill Cause: Tank Failure Tank Failure Tank Failure Spill Source: Other Commercial/Industrial Resource Affectd: On Land Spill Cause: Tank Failure Spill Cause: Tank Failure Spil		Units:		Gallons						
Quantity Recovered: 0 Unknown Oty Recovered: #2 FUEL OIL Class Type: Petroleum Chem Abstract Service Number: #2 FUEL OIL Last Date: 12/07/1994 Num Times Material Entry In File: 24464 DEC Romarks: FIRE DEPARTMENT FLUSHED OIL TO CATCH BASINS IN ALLEY BEHIND BUILDING WHI CH ENETER SEWER SYSTEM IN CITY. 1/8/01: PAPER FILE REMOVED AS PER RECOR D R FITENTION POLICY. Spill Cause: RAE OIL CO. OVERFILLED HOME HEATING OIL TANK CAUSING NO. 2 FUEL OIL TO F LOW OUT OF VENT PIPE AND INTO COMBINED SEWER TO VAN CARE STP. N/A NUSBAUM CLEANER DISTRIB. LTANKS \$104276552 Spill Date: 05/22/66 Reported to Dept: 1 / ID: 100140 Date Call Received/05/22/66 Material Spilled: NA FABRIC SOFTENER Amount Spilled: 0 lbs. Region Close Dt: Spill Source: OTHER COMM/INDUSTRIAL Resource Affect: On Land Spill Source: OTHER COMM/INDUSTRIAL Spill Cause: Tank Kaitre Not reported Leak Rate: Not reported Tank Number: 8601285 Region of Spill: 8 Spill Source OTHER COMM/INDUSTRIAL <t< th=""><th></th><th>Unknown Qty S</th><th>pilled:</th><th>200</th><th></th><th></th><th></th><th></th><th></th></t<>		Unknown Qty S	pilled:	200						
Unknown Oty Recovered: False Material: #2 FUEL OIL Class Type: Petroleum Chem Abstract Service Number: #2 FUEL OIL Last Date: 12/07/1994 Num Times Material Entry In File: 24464 DEC Remarks: FIRE DEPARTMENT FLUSHED OIL TO CATCH BASINS IN ALLEY BEHIND BUILDING WHI CH ENETER SEWER SYSTEM IN CITY. 1/8/01: PAPER FILE REMOVED AS PER RECOR D RETENTION POLICY. Spill Cause: RAE OIL CO. OVERFILLED HOME HEATING OIL TANK CAUSING NO. 2 FUEL OIL TO F LOW OUT OF VENT PIPE AND INTO COMBINED SEWER TO VAN CARE STP. NUSBAUM CLEANER DISTRIB. Stat 1 of 5 in cluster C LTANKS: Spill Number: 8601285 Region of Spill: 8 Spill Date: 05/22/86 Reported to Dept: / / ID: 100140 Date Call Received/05/22/86 Material Spilled: RRX FABRIC SOFTENER Region Close D: 05/22/86 Water Affection: Not reported Spill Cause: Tank Failure Tank Number: Not reported Spill Cause: Tank Failure Tank Number: 8601285 Region of Spill: 8 Spill Cause: Tank Failure Tank Number: Not reported Spill Cause: Tank Failure Tank Number: 8601285 Region of Spill: 8 Spill Cause: Tank Failure Tank Number: Not reported Spill Cause: Tank Failure Tank Number: 8601285 Region of Spill: 8 Spill Cause: Tank Failure Tank Number: Not reported Spill Cause: Tank Failure Tank Number: 8601285 Region of Spill: 8 Spill Cause: Tank Failure Tank Number: Not reported Spill Cause: Tank Failure Tank Number: Mol reported Spill Cause: Tank Failure Tank Number: Mol reported Spill Cause: Tank Failure Tank Number: Mol reported Spill Cause: Tank Failure Tank Number: 8601285 Region of Spill: 8 Spill Source: Other Commercial/Industrial Resource Affectd: On Land Spill Cause: Tank Failure Tank Size: Not reported Material Spilled: Not reported Material Spill Cause: Tank Failure Facility Contact: Not reported Notifier Name: Not reported Notifier Name: Not reported Notifier Name: Not reported Notifi		Quantity Recov	ered:	0						
Material: #2 FUEL OIL Class Type: Petroloum Chem Abstract Service Number: #2 FUEL OIL Last Date: 12/07/1994 Num Times Material Entry In File: 24464 DEC Remarks: FIRE DEPARTMENT FLUSHED OIL TO CATCH BASINS IN ALLEY BEHIND BUILDING WHI CH ENETRA SEWER SYSTEM IN CITY. 1/8/01: PAPER FILE REMOVED AS PER RECOR D RETENTION POLICY. Spill Cause: RAE OIL CO. OVERFILLED HOME HEATING OIL TANK CAUSING NO. 2 FUEL OIL TO F LOW OUT OF VENT PIPE AND INTO COMBINED SEWER TO VAN CARE STP. NUSBAUM CLEANER DISTRIB. 304-308 ANDREW ST. ROCHESTER, NY Site 1 of 5 in cluster C LTANKS: Spill Date: 05/22/86 Material Spilled: RXF XABRIC SOFTENER Amount Spilled: 0 fbs: Region Close DI: 05/22/86 Water Affection: Not reported Spill Cause: Tank Failure Tank Number: Not reported Spill Cause: Tank Failure Tank Number: Not reported Spill Cause: Tank Failure Tank Number: 8601285 Spill Cause: Tank Failure Tank Number: 8601285 Spill Cause: Tank Failure Tank Number: Not reported Spill Cause: Tank Failure Tank Number: Not reported Material Spilled: Not reported Material Spill Cause: Tank Failure Tank Number: Not reported Spill Cause: Tank Failure Tank Number: Not reported Spill Source: Other Commercial/Industrial Resource Affect: On Land Spill Source: Other Commercial/Industrial Resource Affect: Not reported Material Spill Cause: Tank Failure Tank Number: Not reported Material Spill Cause: Tank Failure Facility Contact: Not reported Material Spill Cause: Tank Failure Facility Contact: Not reported Notifier Phone: Not report		Unknown Qty F	Recovered:	False	False					
Class Type: Petroleum Chem Abstract Service Number: #2 FUEL OIL Last Date: 12/07/1994 Num Times Material Entry In File: 24464 DEC Remarks: FIRE DEPARTMENT FLUSHED OIL TO CATCH BASINS IN ALLEY BEHIND BUILDING WHI CH ENETER SEWER SYSTEM IN CITY. 1/8/01: PAPER FILE REMOVED AS PER RECOR D RETENTION POLICY. Spill Cause: RAE OIL CO. OVERFILLED HOME HEATING OIL TANK CAUSING NO. 2 FUEL OIL TO F LOW OUT OF VENT PIPE AND INTO COMBINED SEWER TO VAN CARE NUSBAUM CLEANER DISTRIB. SUSBAUM CLEANER DISTRIB. Stel 1 of 5 in cluster C LTANKS Spill Number: 8601285 Region of Spill: 8 Spill Date: 05/22/86 Reported to Dept: / / ID: 100140 Date Call Received:05/22/86 Material Spilled: RRX FABRIC SOFTENER Amount Spilled: 0 lbs. Region Close DL: 05/23/86 Water Affected: Not reported Spill Cause: Tank Failure Tank Number: 8601285 Region of Spill: 8 Spill Cause: Tank Failure Tank Number: Not reported Spill Number: 8601285 Region of Spill: 8 Spill Cause: Tank Failure Tank Number: Not reported Spill Cause: Tank Failure Tank Number: 8601285 Region of Spill: 8 Spill Cause: Tank Failure Tank Number: Not reported Spill Cause: Tank Failure Tank Number: Not reported Material Spilled: RC reported Spill Number: 8601285 Region of Spill: 8 Spill Date: 05/22/986 15:15 Region of Spill: 8 Spill Date: 05/22/986 15:15 Region of Spill: 8 Spill Date: 05/22/986 15:15 Reported to Dept: 05/22/86 15:35 Date Call ReceivedNot reported Material Spilled: Not reported Material Spilled: Not reported Material Spilled: Not reported Material Spill Cause: Tank Failure Facility Contact: Not reported Material Spill Cause: Tank Failure Facility Contact: Not reported Material Spilled:		Material:		#2 FUEL OIL						
Chem Abstract Service Number: #2 FUEL OIL Last Date: 12/07/1994 Num Times Material Entry In File: 24464 DEC Remarks: FIRE DEPARTMENT FLUSHED OIL TO CATCH BASINS IN ALLEY BEHIND BUILDING WHI CH ENETER SEWER SYSTEM IN CITY. 18/01: PAPER FILE REMOVED AS PER RECOR D RETENTION POLICY. Spill Cause: RAE OIL CO. OVERFILLED HOME HEATING OIL TANK CAUSING NO. 2 FUEL OIL TO F LOW OUT OF VENT PIPE AND INTO COMBINED SEWER TO VAN CARE STP. NUSBAUM CLEANER DISTRIB. S04-308 ANDREW ST. ROCHESTER, NY Site 1 of 5 in cluster C LTANKS: Spill Date: 05/22/86 Region of Spill: 8 Spill Date: 05/22/86 Reported to Dept: 1 / ID: 100140 Date Call Received 05/22/86 Material Spilled: RRX FABRIC SOFTENER Region Close Dt: 05/23/86 Water Affected: Not reported Spill Cause: Tank Failure Tank Number: Not reported Spill Cause: Tank Failure Tank Number: 8601285 Region of Spill: 8 Spill Date: 05/22/86 Fill Spille: 0 Ibs. Region of Spill: 8 Spill Cause: Tank Failure Tank Number: Not reported Tank Size: Not reported Test Method: Not reported Leak Rate: Not reported Spill Cause: Tank Failure Tank Number: 8601285 Region of Spill: 8 Spill Date: 05/22/96 15:15 Regord of Dopt: 05/22/86 15:35 ID: Not reported Amount Spille: Not reported Material Spilled: Not reported Fill: 8 Spill Date: 05/22/96 15:15 Regord of Dopt: 05/22/86 15:35 ID: Not reported Amount Spill: 8 Spill Cause: Tank Failure Tank Number: 8601285 Region of Spill: 8 Spill Cause: Tank Failure Tank Not reported Amount Spille: Not reported Material Spilled: Not reported Amount Spille: Not reported Material Spilled: Not reported Amount Spille: Not reported Region Close Dt: Not reported Amount Spille: Not reported Material Spilled: Not reported Amount Spille: Not reported Material Spill Cause: Tank Failure Facility Contact: Not reported Amount Spille: Not reported Material Spill Cause: Tank Failure Facility Contact: Not reported Caller Extension: Not reported Notifier Mame: Not reported Caller Extension: Not reported Notifier Mame: Not reported Caller Extension: Not reported Notifier Phone: Not re		Class Type:		Petroleum						
Last Date: 12/07/1994 Num Times Material Entry In File: 24464 DEC Remarks: FIRE DEPARTMENT FLUSHED OIL TO CATCH BASINS IN ALLEY BEHIND BUILDING WHI CH ENETER SEWER SYSTEM IN CITY. 1/8/01: PAPER FILE REMOVED AS PER RECOR D RETENTION POLICY. Spill Cause: RAE OIL CO. OVERFILLED HOME HEATING OIL TANK CAUSING NO. 2 FUEL OIL TO F LOW OUT OF VENT PIPE AND INTO COMBINED SEWER TO VAN CADE STP. NUSBAUM CLEANER DISTRIB. Sylil Number: 8601285 Region of Spill: 8 Spill Date: 05/22/86 Reported to Dept: / / ID: 100140 Date Call Received 05/52/86 Material Spilled: RRX FABRIC SOFTENER Amount Spilled: 0 lbs. Region Close Dt: 05/23/86 Water Affected: Not reported Spill: 8 Spill Number: Not reported Tank Size: Not reported Tank Number: Not reported Tank Size: Not reported Task Method: Not reported Tank Size: Not reported Spill Date: 05/22/1966 15:15 Region of Spill: 8 Spill Date: 05/22/1966 15:15 Region of Spill: 8 Spill Date: 05/22/1966 15:15 Reported to Dept: 05/22/1966 15:35 ID: Not reported Amount Spilled: Not reported Task Method: Not reported Amount Spill Source: OTHER COMM/INDUSTRIAL Region Close Dt: Not reported Tank Size: Not reported Test Method: Not reported Amount Spill Source: Other Commercial/Industrial Spill Cause: Tank Failure Task Number: 8601285 Region of Spill: 8 Spill Date: 05/22/1966 15:15 Reported to Dept: 05/22/1966 15:35 ID: Not reported Amount Spilled: Not reported Material Spilled: Not reported Amount Spilled: Not reported Region Close Dt: Not reported Amount Spill Source: Other Commercial/Industrial Resource Affected: On Land Spill Cause: Tank Failure Facility Contact: Not reported Amount Spilled: Not reported Region Close Dt: Not reported Amount Spilled: Not reported Region Close Dt: Not reported Amount Spilled: Not reported Resource Affected: On Land Spill Cause: Tank Failure Facility Contact: Not reported Amount Spilled: Not reported Investigato: CB SWIS: 26 Caller Extension: Not reported Notifier Mame: Not reported Caller Extension: Not reported Notifier Phone:		Chem Abstract	Service Nu	umber:	#2 FUEL OIL					
Num Times Material Entry In File: 24464 DEC Remarks: FIRE DEPARTMENT FLUSHED OIL TO CATCH BASINS IN ALLEY BEHIND BUILDING WHI CH ENETER SEWER SYSTEM IN CITY. 1/8/01: PAPER FILE REMOVED AS PER RECOR D RETENTION POLICY. Spill Cause: RAE OIL CO. OVERFILLED HOME HEATING OIL TANK CAUSING NO. 2 FUEL OIL TO F LOW OUT OF VENT PIPE AND INTO COMBINED SEWER TO VAN CARE STP. MUSBAUM CLEANER DISTRIB. 304-308 ANDREW ST. NUSBAUM CLEANER DISTRIB. 304-308 ANDREW ST. ROCHESTER, NY Site 1 of 5 in cluster C LTANKS: Spill Date: 05/22/66 Regond 5 pill: 8 Spill Date: 05/22/66 Reported to Dept: 1 / ID ID: 100140 Date Call Received:05/22/66 Material Spilled: RRX FABRIC SOFTENER Amount Spilled: 0 Ibs. Region Close Dt: 05/23/86 Water Affected: Not reported Spill Source: OTHER COMM/INDUSTRIAL Resource Affectd: On Land Spill Cause: Tank Failure Tank Number: 8601285 Region of Spill: 8 Spill Date: 05/22/86 15:15 Regonded to Dept: 05/22/86 15:35 ID: Not reported Date Call Received: Not reported Material Spilled: Not reported Amount Spilled: Not reported Material Spilled: Not reported Spill Source: Other Commercial/Industrial Resource Affected: On Land Spill Cause: Tank Failure Facility Centact: Not reported Spill Source: Other Commercial/Industrial Resource Affected: On Land Spill Cause: Tank Failure Facility Centact: Not reported Spill Source: Other Commercial/Industrial Resource Affected: On Land Spill Cause: Tank Failure Facility Centact: Not reported Spill Source: Other Commercial/Industrial Resource Affected: Not reported Spill Source: Not reported Spill Cause: Tank Failure Facility Centact: Not reported Spill Cause: Tank Failu		Last Date:			12/07/1994					
DEC Remarks: FIRE DEPARTMENT FLUSHED OIL TO CATCH BASINS IN ALLEY BEHIND BUILDING WHI CH ENETERS SEWER SYSTEM IN CITY. 1/8/01: PAPER FILE REMOVED AS PER RECOR D RETENTION POLICY. Spill Cause: RAE OIL CO. OVERFILLED HOME HEATING OIL TANK CAUSING NO. 2 FUEL OIL TO F LOW OUT OF VENT PIPE AND INTO COMBINED SEWER TO VAN CARE STP. NUSBAUM CLEANER DISTRIB. LTANKS Site 1 of 5 in cluster C LTANKS: Spill Number: 8601285 Region of Spill: 8 Spill Number: 8601285 Region Close Dt: 05/22/86 Material Spilled: RXF FABRIC SOFTENER Region Close Dt: 05/23/86 Water Affected: Not reported Spill Number: 8601285 Region Close Dt: 05/23/86 Water Affected: Not reported Spill Cause: Tank Failure Tank Number: Not reported Tank Number: 8601285 Spill Cause: Tank Failure Tank Number: 8601285 Spill Date: 05/22/1986 15:15 Reported to Dept: 05/22/86 15:35 Dic Not reported Date: 05/22/1986 15:15 Region of Spill		Num Times Ma	terial Entry	In File:	24464					
CH ENETER SEWER SYSTEM IN CITY. 1/8/01: PAPER FILE REMOVED AS PER RECOR D RETENTION POLICY. Spill Cause: RAE OIL CO. OVERFILLED HOME HEATING OIL TANK CAUSING NO. 2 FUEL OIL TO F LOW OUT OF VENT PIPE AND INTO COMBINED SEWER TO VAN CARE STP. UNUSBAUM CLEANER DISTRIB. 304-308 ANDREW ST. ROCHESTER, NY Site 1 of 5 in cluster C LTANKS: Spill Date: 05/22/86 Reported to Dept: 1 / I ID: 100140 Date Call Received 05/22/86 Material Spilled: RRX FABRIC SOFTENER Amount Spilled: 0 lbs. Region Close Dt: 05/23/86 Water Affected: Not reported Spill Source: OTHER COMM/INDUSTRIAL Resource Affectd: On Land Spill Cause: Tank Failure Tank Number: 8601285 Region of Spill: 8 Spill Date: 05/22/86 15:15 Regoted to Dept: 01/22/86 15:35 ID: Not reported Date Call Received Not reported Material Spilled: Not reported Amount Spilled: Not reported Material Spilled: Not reported Spill Surce: Other Commercial/Industrial Region Close Dt: Not reported Date Call Received Not reported Material Spilled: Not reported Spill Surce: Other Commercial/Industrial Region Close Dt: Not reported Spill Source: Other Commercial/Industrial Resource Affected: Not reported Spill Source: Not reported Region Close Dt: Not reported Spill Source: Not reported Region Close Dt: Not reported Caller Agency: Not reported Region Close Dt: Not reported Caller Agency: Not reported Region Close Dt: Not reported Caller Agency: Not reported Notifier Name: Not reported Notifier Extension: Not reported Notifier Name: Not reported Notifier Ztension: Not reporte	[DEC Remarks:	FIRE DEP	PARTMENT FLUS	HED OIL TO	CATCH BASINS IN	ALLEY BEHI	ND BUILDIN	NG WHI	
Spill Cauşe: D. RETENTION POLICY. Spill Cauşe: CAR COLL CO. OVERFILLED HOME HEATING OIL TANK CAUSING NO. 2 FUEL OIL TO FLOW OUT OF VENT PIPE AND INTO COMBINED SEWER TO VAN CARE STP. NUSBAUM CLEANER DISTRIB. LTANKS \$104276552 S04-308 ANDREW ST. N/A ROCHESTER, NY Site 1 of 5 in cluster C LTANKS: Spill Number: 8601285 Spill Number: 8601285 Region of Spill: 8 Spill Date: 05/22/66 Reported to Dept: 1 / ID: 100140 Date Call Received 05/2/86 Material Spilled: N/A Water Affected: Not reported Spill Source: OTHER COMM/INDUSTRIAL Resource Affectd: On Land Spill Source: OTHER COMM/INDUSTRIAL Resource Affectd: On Land Spill Cause: Tank Failure Tank Number: Not reported Tank Size: Not reported Test Method: Not reported Date Call Received/Not reported PBS: Spill Number: 6601285 Region of Spill: 8 Spill Number: 8601285 Reported to Dept: 05/22/86 Material Spilled: Not reported Amount Spilled:			CH ENETI	ENETER SEWER SYSTEM IN CITY. 1/8/01: PAPER FILE REMOVED AS PER RECOR						
Spill Cause: RAE OIL CO. OVERFILLED HOME HEATING OIL TANK CAUSING NO. 2 FUEL OIL TO FLOW OUT OF VENT PIPE AND INTO COMBINED SEWER TO VAN CARE STP. NUSBAUM CLEANER DISTRIB. LTANKS \$104276552 304-308 ANDREW ST. N/A ROCHESTER, NY Site 1 of 5 in cluster C LTANKS: Spill Number: Spill Date: 05/22/86 Region of Spill: 8 Spill Date: 05/22/86 Material Spilled: RRX FABRIC SOFTENER Region Close Dt: 05/23/86 Water Affected: Not reported Spill Cause: Tank Failure Tank Number: Not reported Spill Number: Not reported Tank Number: Not reported Spill Number: 8601285 Spill Number: 8601285 Spill Number: 8601285 Region of Spill: 8 Spill Number: 8601285 Region Close Dt: 05/22/1986 Not re			D RETENTION POLICY.							
LIAW SOLITOF VENTIFIE AND INTO COMBINED SEVER TO VAR CARE STP. LIAWKS STRUE. NUSBAUM CLEANER DISTRIB. SOLA308 ANDREW ST. ROCHESTER, NY Site 1 of 5 in cluster C LTANKS: Spill Number: 8601285 Spill Date: 05/22/86 Material Spilled: RRX FABRIC SOFTENER Region Close Dt: 05/23/86 Water Affected: Not reported Spill Cause: Tank Failure Tank Number: Not reported Spill Cause: Tank Failure Tank Number: Not reported PBS: Not reported Spill Date: 05/22/86 15:15 Region of Spill: 8 Spill Cause: Tank Failure Tank Number: Not reported Material Spilled: Not reported Material Spilled: Not reported Spill Cause: Tank Failure Facility Contact: Not reported Facility Contact: Not reported Facility Contact: Not reported Facility Contact: Not reported Caller Agency: Not reported Caller Phone: Not reported Notifier Name: Not reported Notifier Name: Not reported Notifier Agency: Not reported Notifier	5	Spill Cause:	RAE OIL (CO. OVERFILLE	D HOME HEAD	TING OIL TANK CA	USING NO. 2		10 F	
NUSBAUM CLEANER DISTRIB. LTANKS \$104276552 S04-308 ANDREW ST. ROCHESTER, NY N/A Site 1 of 5 in cluster C LTANKS Spill Number: 8601285 Region of Spill: 8 Spill Number: 05/22/86 Reported to Dept: / / 10: 10140 Date Call Received/05/22/86 Material Spilled: RX FABRIC SOFTENER Amount Spilled: 0 Ibs. Region Close Dt: 05/23/86 Spill Source: OTHER COMM/INDUSTRIAL Resource Affectd: Not reported Tank Size: Not reported Tank Number: Not reported Tank Size: Not reported Test Method: Not reported Tank Size: Not reported Spill Number: 8601285 Region of Spill: 8 Spill Number: 801285 Region of Spill: 8 Spill Number: 801285 Region of Spill: 8 <t< th=""><th></th><th></th><th>LOW OUT</th><th>OF VENT PIPE</th><th></th><th>JMBINED SEWER I</th><th></th><th>ESIP.</th><th></th></t<>			LOW OUT	OF VENT PIPE		JMBINED SEWER I		ESIP.		
NUSBAUM CLEANER DISTRIB. 304.308 ANDREW ST. ROCHESTER, NY Site 1 of 5 in cluster C LTANKS: Spill Number: 8601285 Spill Number: 8601285 Spill Date: 05/22/86 Material Spilled: RRX FABRIC SOFTENER Amount Spilled: 0 lbs. Region Close Dt: 05/23/86 Water Affected: Not reported Spill Source: 0THER COMM/INDUSTRIAL Resource Affectd: On Land Spill Cause: Tank Failure Tank Number: Not reported Tank Size: Not reported Spill Number: 8601285 Spill Number: 8601285 Spill Number: 8601285 Spill Surce: 0THER COMM/INDUSTRIAL Resource Affectd: On Land Spill Cause: Tank Failure Tank Number: Not reported Spill Cause: 05/22/1986 15:15 Spill Number: 8601285 Spill Number: 8601285 Spill Number: 8601285 Spill Date: 05/22/1986 15:15 Spill Surce: 05/22/1986 15:15 Spill Cause: Tank Failure Tank Not reported Amount Spilled: Not reported Amount Spilled: Not reported Amount Spilled: Not reported Region Close Dt: Not reported Spill Source: 0ther Commercial/Industrial Resource Affectd: On Land Spill Cause: Tank Failure Region Close Dt: Not reported Region: Close								-		
304-308 ANDREW ST. N/A ROCHESTER, NY Site 1 of 5 in cluster C Site 1 of 5 in cluster C E Site 1 of 5 in cluster C Site 1 of 5 in cluster C Spill Number: 8601285 Region of Spill: 8 Spill Date: 05/22/86 Reported to Dept: 1 / . ID: 100140 Date Call Received:05/22/86 0 Material Spilled: RRX FABRIC SOFTENER Amount Spilled: 0 lbs. Region Close Dt: 05/23/86 0 0 Water Affected: Not reported Spill Source: OTHER COMM/INDUSTRIAL Resource Affectd: Not reported Tank Size: Not reported Tank Number: Not reported Tank Size: Not reported PBS: Not reported Leak Rate: Not reported PBS: Not reported Date Call Received:Not reported Spill Couse: Not reported Material Spilled: Not reported Amount Spilled:: Not reported Material Spilled: Not reported Amount Spilled:: Not reported Material Spilled: Not reported Spill Source: <td< th=""><th>NUSB</th><th>AUM CLEANER</th><th>DISTRIB.</th><th></th><th></th><th></th><th></th><th>LTANKS</th><th>S104276552</th></td<>	NUSB	AUM CLEANER	DISTRIB.					LTANKS	S104276552	
ROCHESTER, NY Site 1 of 5 in cluster C LTANKS: Spill Number: 8601285 Region of Spill: 8 Spill Date: 05/22/86 Reported to Dept: / / ID: 10140 Date Call Received/05/22/86 Material Spilled: RRX FABRIC SOFTENER Amount Spilled: 0 lbs. Region Close Dt: 05/23/86	304-3	08 ANDREW ST.							N/A	
Site 1 of 5 in cluster C LTANKS: Spill Number: 8601285 Spill Date: 05/22/86 Material Spilled: RRX FABRIC SOFTENER Amount Spilled: 0 lbs. Region of Spill: 0 lbs. Region Close Dt: 05/23/86 Water Affected: Not reported Spill Source: 0THER COMM/INDUSTRIAL Resource Affectd: 0n Land Spill Cause: Tank Failure Tank Number: 8601285 Spill Number: 8601285 Spill Number: 8601285 Spill Number: 8601285 Spill Source Spill Number: 8601285 Spill Source Spill Source: 05/22/86 l5:35 Spill Source Spill Source: 05/22/86 l5:35 Spill Cause: Tank Failure Tank Number: 05/22/1986 15:15 Region of Spill: 8 Spill Date: 05/22/1986 15:15 Region of Spill: 8 Spill Date: 05/22/1986 15:15 Region of Spill: 8 Spill Source: 05/22/86 15:35 Spill Source: 05/22/86 15:35 Spill Cause: Tank Failure Facility Contact: Not reported Spill Source: 0ther Commercial/Industrial Resource Affectd: 0n Land Spill Cause: Tank Failure Facility Contact: Not reported Caller Agency: Not reported Caller Agency: Not reported Caller Agency: Not reported Caller Phone: Not reported Notifier Phone: Not reported Notifier Phone: Not reported Notifier Phone: Not reported Notifier Agency: Not reported Notifier Stension: Not reported Notifier Stension	ROCH	IESTER, NY								
Site 1 of 5 in cluster C LTANKS: Spill Number: 8601285 Region of Spill: 8 Spill Date: 05/22/86 Reported to Dept: / ID: 100140 Date Call Received:05/22/86 0 Material Spilled: RRX FABRIC SOFTENER Amount Spilled: 0 lbs. Region Close Dt: 05/23/86 0 0 Water Affected: Not reported Spill Source: 0THER COMM/INDUSTRIAL Resource Affectd: On Land 5 Spill Cause: Tank Failure Tank Number: Not reported Tank Size: Not reported Test Method: Not reported Leak Rate: Not reported PBS: Not reported Date Call Received:Not reported 5/22/186 15:15 ID: Not reported Date Call Received:Not reported Material Spilled: Not reported Amount Spilled: Not reported Water Affected: Not reported Amount Spilled: Not reported Region Close Dt: Not reported Spill Source: Other Commercial/Industrial Resource Affected: On Land										
LTANKS:Region of Spill:8Spill Number:8601285Reported to Dept:1ID:100140Date Call Received:05/22/86Material Spilled:RRX FABRIC SOFTENERAmount Spilled:0Material Spilled:Not reportedSpill Source:OTHER COMM/INDUSTRIALResource Affectd:Not reportedSpill Source:OTHER COMM/INDUSTRIALResource Affectd:Not reportedTank Size:Not reportedTank Number:Not reportedTank Size:Not reportedTank Number:Not reportedLeak Rate:Not reportedPBS:Not reportedDate Call Received:Not reportedSpill Cause:Spill Date:05/22/1986 15:15Region of Spill:8Spill Date:05/22/1986 15:15Reported to Dept:05/22/86 15:35ID:Not reportedDate Call Received:Wot reportedMaterial Spilled:Not reportedAmount Spille:Not reportedWater Affected:Not reportedSpill Source:Other Commercial/IndustrialResource Affectd:Not reportedSpill Source: <th>Site 1</th> <th>of 5 in cluster C</th> <th></th> <th></th> <th></th> <th></th> <th></th> <th></th> <th></th>	Site 1	of 5 in cluster C								
Spill Number:8601285Region of Spill:8Spill Date:05/22/86Reported to Dept:1ID:100140Date Call Received:05/22/86Material Spilled:RRX FABRIC SOFTENERAmount Spilled:0 lbs.Region Close Dt:05/23/86Spill Source:OTHER COMM/INDUSTRIALResource Affectd:Not reportedSpill Source:OTHER COMM/INDUSTRIALResource Affectd:On LandSpill Cause:Not reportedTank Number:Not reportedTank Size:Not reportedTask Number:Not reportedLeak Rate:Not reportedPBS:Not reportedDate Call Received: Not reportedSpill Cause:Spill Date:05/22/1986 15:15Region of Spill:8Spill Date:05/22/1986 15:15Reported to Dept:05/22/86 15:35ID:Not reportedDate Call Received: Not reportedMaterial Spilled:Not reportedMaterial Spilled:Not reportedArmount Spille:Not reportedWater Affected:Not reportedSpill Source:Other Commercial/IndustrialRegion Close Dt:Not reportedSpill Source:Other Commercial/IndustrialResource Affectd:On LandSpill Source:Other Commercial/IndustrialSpill Contact:Not reportedSwils:26Caller Agency:Not reportedCaller Agency:Not reportedInvestigator:CBSwils:26Caller Phone:Not reportedCaller Agency:Not reportedNoti	LT/	ANKS:								
Spill Date:05/22/86Reported to Dept:/ /ID:100140Date Call Received:05/22/86Material Spilled:RRX FABRIC SOFTENERAmount Spilled:0 lbs.Region Close Dt:05/23/8601450145Water Affected:Not reportedSpill Source:OTHER COMM/INDUSTRIALResource Affectd: On LandSpill Cause:Tank FailureTank Size:Not reportedTank Number:Not reportedTank Size:Not reportedNot reportedTest Method:Not reportedLeak Rate:Not reportedPBS:Not reportedDate Call Received: Not reportedSpill Number:8601285Region of Spill:8Spill Date:05/22/1986 15:15Reported to Dept:05/22/86 15:35ID:Not reportedDate Call Received: Not reportedMaterial Spilled:Not reportedAmount Spilled:Not reportedMaterial Spilled:Not reportedSpill Source:Other Commercial/IndustrialRegion Close Dt:Not reportedSpill Source:Other Commercial/IndustrialResource Affectd:On LandSpill Source:Other Commercial/IndustrialSpill Cause:Tank FailureFacility Tele:Not reportedHacsingtor:CBSWIS:26Caller Name:Not reportedSWIS:26Caller Phone:Not reportedNotifier Agency:Not reportedNotifier Name:Not reportedNotifier Agency:Not reportedNotifier Name:Not reported <th>5</th> <th>Spill Number:</th> <th>8601285</th> <th></th> <th></th> <th>Region of Spill:</th> <th>8</th> <th></th> <th></th>	5	Spill Number:	8601285			Region of Spill:	8			
ID:100140Date Call Received 05/22/86Material Spilled:RXX FABRIC SOFTENERAmount Spilled:0 lbs.Region Close Dt:05/23/86Spill Source:OTHER COMM/INDUSTRIALWater Affected:Not reportedSpill Source:OTHER COMM/INDUSTRIALResource Affectd: On LandTank Number:Not reportedLeak Rate:Not reportedTank Number:Not reportedTank Size:Not reportedNot reportedTest Method:Not reportedLeak Rate:Not reportedPBS:Not reportedDate Call Received Not reportedSpill Cause:Spill Source:Spill Date:05/22/1986 15:15Region of Spill:8Spill Date:05/22/1986 15:15Reported to Dept:05/22/86 15:35ID:Not reportedDate Call Received Not reportedMaterial Spilled:Not reportedWater Affected:Not reportedSpill Source:Other Commercial/IndustrialRegion Close Dt:Not reportedSpill Source:Other Commercial/IndustrialWater Affected:Not reportedSpill Source:Other Commercial/IndustrialResource Affectd:Not reportedSpill Source:Spill Cause:Tark FailureFacility Tele:Not reportedSpill Cause:Tark FailureSpill Cause:Facility Contact:Not reportedSWIS:26Caller Name:Not reportedCaller Agency:Not reportedInvestigator:CBCaller Agency:Not reportedCaller Phone:Not re	5	Spill Date:	05/22/86			Reported to Dept:	11			
Material Spilled:RRX FABRIC SOFTENER Region Close Dt:Amount Spilled:0 lbs.Region Close Dt:05/23/86Spill Source:OTHER COMM/INDUSTRIALWater Affected:Not reportedSpill Source:OTHER COMM/INDUSTRIALResource Affectd:On LandTank Size:Not reportedSpill Cause:Tank FailureTank Size:Not reportedTank Number:Not reportedLeak Rate:Not reportedTest Method:Not reportedLeak Rate:Not reportedPBS:Not reportedDate Call Received: Not reportedDate Call Received: Not reportedMaterial Spilled:Not reportedAmount Spilled:Not reportedMaterial Spilled:Not reportedSpill Source:Other Commercial/IndustrialRegion Close Dt:Not reportedSpill Source:Other Commercial/IndustrialResource Affectd:On LandSpill Source:Other Commercial/IndustrialSpill Cause:Tank FailureFacility Tele:Not reportedFacility Contact:Not reportedSWIS:26Caller Name:Not reportedCaller Agency:Not reportedInvestigator:CBSWIS:26Caller Name:Not reportedCaller Agency:Not reportedNotifier Name:Not reportedNotifier Agency:Not reportedNotifier Phone:Not reportedNotifier Agency:Not reported	1	iD:	100140			Date Call Received	1:05/22/86			
Region Close Dt:05/23/86Water Affected:Not reportedSpill Source:OTHER COMM/INDUSTRIALResource Affectd:On LandSpill Source:OTHER COMM/INDUSTRIALSpill Cause:Tank FailureTank Size:Not reportedTank Number:Not reportedLeak Rate:Not reportedTest Method:Not reportedLeak Rate:Not reportedPBS:Not reportedSpill Date:05/22/1986 15:15Region of Spill:8Spill Date:05/22/1986 15:15Reported to Dept:05/22/86 15:35ID:Not reportedAmount Spilled:Not reportedMaterial Spilled:Not reportedSpill Source:Other Commercial/IndustrialRegion Close Dt:Not reportedSpill Source:Other Commercial/IndustrialResource Affectd:On LandSpill Source:Other Commercial/IndustrialSpill Cause:Tank FailureFacility Tele:Not reportedFacility Contact:Not reportedSWIS:26Caller Name:Not reportedCaller Agency:Not reportedInvestigator:CBCaller Agency:Not reportedCaller Phone:Not reportedCaller Agency:Not reportedNotifier Name:Not reportedNotifier Agency:Not reportedNotifier Phone:Not reportedNotifier Agency:Not reported	ļ	Material Spilled:	RRX FAB	RIC SOFTENER		Amount Spilled:	0 lbs.			
Water Affected:Not reportedSpill Source:OTHER COMM/INDUSTRIALResource Affectd:On LandSpill Cause:Tank FailureTank Number:Not reportedTank Size:Not reportedTest Method:Not reportedLeak Rate:Not reportedPBS:Not reportedLeak Rate:Not reportedSpill Date:05/22/1986 15:15Region of Spill:8Spill Date:05/22/1986 15:15Reported to Dept:05/22/86 15:35ID:Not reportedDate Call Received-Not reportedMaterial Spilled:Not reportedAmount Spilled:Not reportedWater Affected:On LandSpill Source:Other Commercial/IndustrialSpill Cause:Tank FailureFacility Tele:Not reportedResource Affectd:On LandSWIS:26Caller Name:Not reportedCaller Agency:Not reportedNotifier Phone:Not reportedNotifier Agency:Not reportedNotifier Phone:Not reportedNotifier Agency:Not reported	I	Region Close Dt:	05/23/86							
Resource Affectd: On LandSpill Cause:Tank FailureTank Number:Not reportedTank Number:Not reportedTest Method:Not reportedPBS:Not reportedSpill Number:8601285Spill Date:05/22/1986 15:15ID:Not reportedMaterial Spilled:Not reportedMaterial Spilled:Not reportedWater Affected:Not reportedSpill Cause:Tank FailureFacility Contact:Not reportedSpill Cause:Tank FailureFacility Contact:Not reportedInvestigator:CBCaller Name:Not reportedNot reportedCaller Agency:Not reportedNot reportedCaller Phone:Not reportedNotifier Phone:Not reportedNotifier Phone:Not reportedNotifier Phone:Not reportedNotifier Phone:Not reportedNotifier Phone:Not reportedNotifier Sume:Not reportedNotifier Extension:Not reportedNotifier Extension:Not reportedNotifier Phone:Not reportedNotifier Extension:Not reportedNotifier Extension:Not reportedNotifier Phone:Not reportedNotifier Extension:Not reportedNotifier Phone:Not reportedNotifier Phone:Not reportedNotifier Phone:Not reportedNotifier Phone:Not reportedNotifier Extension:Not	۱.	Water Affected:	Not report	ed		Spill Source:	OTHER CO	MM/INDUST	TRIAL	
Spill Cause:Tank FailureTank Number:Not reportedTank Size:Not reportedTest Method:Not reportedLeak Rate:Not reportedPBS:Not reportedLeak Rate:Not reportedSpill Number:8601285Region of Spill:8Spill Date:05/22/1986 15:15Reported to Dept:05/22/86 15:35ID:Not reportedDate Call Received Not reportedMaterial Spilled:Not reportedAmount Spilled:Not reportedWater Affected:Not reportedSpill Source:Other Commercial/IndustrialResource Affectd:On LandSpill Cause:Tank FailureFacility Contact:Not reportedFacility Tele:Not reportedInvestigator:CBSWIS:26Caller Name:Not reportedCaller Agency:Not reportedNotifier Phone:Not reportedNotifier Agency:Not reportedNotifier Phone:Not reportedNotifier Agency:Not reportedNotifier Phone:Not reportedNotifier Extension:Not reported	I	Resource Affectd:	On Land							
Tank Number:Not reportedTank Size:Not reportedTest Method:Not reportedLeak Rate:Not reportedPBS:Not reportedLeak Rate:Not reportedSpill Number:8601285Region of Spill:8Spill Date:05/22/1986 15:15Reported to Dept:05/22/86 15:35ID:Not reportedDate Call Received:Not reportedMaterial Spilled:Not reportedAmount Spilled:Not reportedMaterial Spilled:Not reportedSpill Source:Other Commercial/IndustrialResource Affectd:On LandSpill Source:Other Commercial/IndustrialSpill Cause:Tank FailureFacility Tele:Not reportedFacility Contact:Not reportedSWIS:26Caller Name:Not reportedCaller Agency:Not reportedNotifier Phone:Not reportedNotifier Agency:Not reportedNotifier Phone:Not reportedNotifier Agency:Not reportedNotifier Phone:Not reportedNotifier Extension:Not reported	5	Spill Cause:	Tank Failu	ıre						
Test Method: PBS:Not reportedLeak Rate:Not reportedSpill Number:8601285Region of Spill:8Spill Date:05/22/1986 15:15Reported to Dept:05/22/86 15:35ID:Not reportedDate Call Received:Not reportedMaterial Spilled:Not reportedAmount Spilled:Not reportedWater Affected:Not reportedSpill Source:Other Commercial/IndustrialResource Affectd:On LandSpill Cause:Tank FailureFacility Contact:Not reportedSWIS:26Caller Name:Not reportedCaller Agency:Not reportedNot reportedCaller Extension:Not reportedNotifier Name:Not reportedNot reportedNotifier Phone:Not reportedNot reportedNotifier Phone:Not reportedNot reported	-	Tank Number:	Not report	ed		Tank Size:	Not reported	1		
PBS:Not reportedSpill Number:8601285Region of Spill:8Spill Date:05/22/1986 15:15Reported to Dept:05/22/86 15:35ID:Not reportedDate Call Received:Not reportedMaterial Spilled:Not reportedAmount Spilled:Not reportedMaterial Spilled:Not reportedAmount Spilled:Not reportedWater Affected:Not reportedSpill Source:Other Commercial/IndustrialResource Affectd: On LandSpill Cause:Tank FailureFacility Contact:Not reportedFacility Tele:Not reportedInvestigator:CBSWIS:26Caller Name:Not reportedCaller Agency:Not reportedNotifier Name:Not reportedNotifier Agency:Not reportedNotifier Phone:Not reportedNotifier Agency:Not reportedNotifier Phone:Not reportedNotifier Extension:Not reportedNotifier Phone:Not reportedNotifier Extension:Not reported	-	Test Method:	Not report	ed		Leak Rate:	Not reported	t		
Spill Number:8601285Region of Spill:8Spill Date:05/22/1986 15:15Reported to Dept:05/22/86 15:35ID:Not reportedDate Call Received:Not reportedMaterial Spilled:Not reportedAmount Spilled:Not reportedMaterial Spilled:Not reportedAmount Spilled:Not reportedWater Affected:Not reportedSpill Source:Other Commercial/IndustrialResource Affectd: On LandSpill Cause:Tank FailureFacility Contact:Not reportedFacility Tele:Not reportedInvestigator:CBSWIS:26Caller Name:Not reportedCaller Agency:Not reportedNotifier Name:Not reportedNot fier Agency:Not reportedNotifier Phone:Not reportedNotifier Agency:Not reportedNotifier Phone:Not reportedNotifier Extension:Not reported	I	PBS:	Not report	ed						
Spill Number:860/1285Region of Spill.oSpill Date:05/22/1986 15:15Reported to Dept:05/22/86 15:35ID:Not reportedDate Call Received:Not reportedMaterial Spilled:Not reportedAmount Spilled:Not reportedRegion Close Dt:Not reportedSpill Source:Other Commercial/IndustrialWater Affected:Not reportedSpill Source:Other Commercial/IndustrialResource Affectd: On LandSpill Cause:Tank FailureFacility Contact:Not reportedFacility Tele:Not reportedInvestigator:CBSWIS:26Caller Name:Not reportedCaller Agency:Not reportedNotifier Name:Not reportedNotifier Agency:Not reportedNotifier Name:Not reportedNotifier Agency:Not reportedNotifier Phone:Not reportedNotifier Extension:Not reportedNotifier Phone:Not reportedNotifier Extension:Not reported			0004005			Deales of Callly	0			
Spill Date:05/22/1986 15:15Reported to Dept.05/22/06 15:35ID:Not reportedDate Call Received:Not reportedMaterial Spilled:Not reportedAmount Spilled:Not reportedRegion Close Dt:Not reportedSpill Source:Other Commercial/IndustrialWater Affected:Not reportedSpill Source:Other Commercial/IndustrialResource Affectd: On LandSpill Cause:Tank FailureFacility Contact:Not reportedFacility Tele:Not reportedInvestigator:CBSWIS:26Caller Name:Not reportedCaller Agency:Not reportedNotifier Name:Not reportedCaller Extension:Not reportedNotifier Name:Not reportedNotifier Agency:Not reportedNotifier Phone:Not reportedNotifier Extension:Not reportedNotifier Phone:Not reportedNotifier Extension:Not reported		Spill Number:	8601285	0 45.45		Region of Spin.	0			
ID:Not reportedDate Call Received Not reportedMaterial Spilled:Not reportedAmount Spilled:Not reportedRegion Close Dt:Not reportedSpill Source:Other Commercial/IndustrialWater Affected:Not reportedSpill Source:Other Commercial/IndustrialResource Affectd: On LandSpill Cause:Tank FailureFacility Contact:Not reportedFacility Tele:Not reportedInvestigator:CBSWIS:26Caller Name:Not reportedCaller Agency:Not reportedCaller Phone:Not reportedCaller Extension:Not reportedNotifier Name:Not reportedNotifier Agency:Not reportedNotifier Phone:Not reportedNotifier Agency:Not reportedNotifier Phone:Not reportedNotifier Extension:Not reported		Spill Date:	05/22/198	C 15:15		Reported to Dept.	US/ZZ/00 To	.35		
Material Splitd:Not reportedAntount Splitd:Not reportedRegion Close Dt:Not reportedSpill Source:Other Commercial/IndustrialWater Affected:Not reportedSpill Source:Other Commercial/IndustrialResource Affectd: On LandSpill Cause:Tank FailureFacility Contact:Not reportedFacility Tele:Not reportedInvestigator:CBSWIS:26Caller Name:Not reportedCaller Agency:Not reportedCaller Phone:Not reportedCaller Extension:Not reportedNotifier Name:Not reportedNotifier Agency:Not reportedNotifier Phone:Not reportedNotifier Extension:Not reported		ID: Mataziat Califadi	Not report	ed		Amount Spillod:	Not reported	1		
Region Close DLNot reportedSpill Source:Other Commercial/IndustrialWater Affected:Not reportedSpill Source:Other Commercial/IndustrialResource Affectd:On LandFacility Contact:Not reportedSpill Cause:Tank FailureFacility Tele:Not reportedFacility Contact:Not reportedSWIS:26Caller Name:Not reportedCaller Agency:Not reportedCaller Phone:Not reportedCaller Extension:Not reportedNotifier Name:Not reportedNotifier Agency:Not reportedNotifier Phone:Not reportedNotifier Extension:Not reported		Material Spilleu:	Not report	eu		Amount Spilleu.	Not reported			
Water Affected.Not reportedSpin Godice.State Contract Contr		Nator Affected:	Not report	eu ed		Spill Source:	Other Comm	hercial/Indus	strial	
NetworkVariableSpill Cause:Tank FailureFacility Contact:Not reportedFacility Contact:Not reportedInvestigator:CBCaller Name:Not reportedCaller Phone:Not reportedNotifier Name:Not reportedNotifier Name:Not reportedNotifier Phone:Not reported		Pacourca Affected.		eu		opin oodree.				
Facility Contact:Not reportedFacility Tele:Not reportedInvestigator:CBSWIS:26Caller Name:Not reportedCaller Agency:Not reportedCaller Phone:Not reportedCaller Extension:Not reportedNotifier Name:Not reportedNotifier Agency:Not reportedNotifier Phone:Not reportedNotifier Extension:Not reported		Spill Cause:	Tank Failu	ire						
Investigator:CBSWIS:26Caller Name:Not reportedCaller Agency:Not reportedCaller Phone:Not reportedCaller Extension:Not reportedNotifier Name:Not reportedNotifier Agency:Not reportedNotifier Phone:Not reportedNotifier Extension:Not reportedNotifier Phone:Not reportedNotifier Extension:Not reported	,	Eacility Contact	Not report	ed		Eacility Tele	Not reported	1		
Caller Name:Not reportedCaller Agency:Not reportedCaller Phone:Not reportedCaller Extension:Not reportedNotifier Name:Not reportedNotifier Agency:Not reportedNotifier Phone:Not reportedNotifier Extension:Not reportedNotifier Phone:Not reportedNotifier Extension:Not reported	· .	Investigator:	CB			SWIS:	26			
Caller Phone:Not reportedCaller Extension:Not reportedNotifier Name:Not reportedNotifier Agency:Not reportedNotifier Phone:Not reportedNotifier Extension:Not reported		Caller Name	Not report	ed		Caller Agency:	Not reported	1		
Valid Notifier Name: Not reported Notifier Agency: Not reported Notifier Phone: Not reported Notifier Extension: Not reported		Caller Phone	Not report	ed		Caller Extension	Not reported	-		
Notifier Phone: Not reported Notifier Extension: Not reported	, I	Notifier Name	Not report	ed		Notifier Agency:	Not reported			
Hound Hoursenand Hound Hound Hound Hound		Notifier Phone	Not report	ed		Notifier Extension:	Not reported	I		
PBS: Not reported		PRS.	Not report	ed		LIGHT EXCHOLOR.		•		
Spiller Contact: Not reported Spiller Phone: Not reported		Spiller Contact:	Not report	ed		Spiller Phone:	Not reported	1		
Map ID	MAP FINDINGS									
--	--------------	-------------	---------------							
Distance										
Distance (ft.)		Detebaso(s)	EDR ID Number							
Elevation Site										
······································										
			S104276552							

NUSBAUM CLEANER DISTRIB. (Continued)

Spill Class:	Known rele Willing Res	ase that creates p ponsible Party. Co	otential for fi	re or hazard. DEC on taken.	Response.
Spill Closed Dt:	05/23/86			DDO Number	Not reported
Spill Notifier:	Health Dep	artment		PBS Number:	Not reported
Cleanup Ceased:	05/23/86				
Last Inspection:	11				
Cleanup Meets S	tandard:	True			
Recommended P	enalty:	Penalty Not Reco	mmended		
Spiller Cleanup D	ate:	11			
Enforcement Date	e:	11			
Investigation Con	nplete:	11			
UST Involvement	:	False			
Spill Record Last	Update:	02/13/01			
is Updated:		Faise			
Corrective Action	Plan Subm	itted:			
Date Spill Entere	d In Comput	er Data File:	06/03/86		
Date Region Sen	t Summary	to Central Office:	//		
Tank Test:					
PBS Number:		Not reported			
Tank Number:		Not reported			
Test Method:		Not reported			
Capacity of Fa	iled Tank:	Not reported			
Leak Rate Fail	ed Tank:	Not reported			
Gross Leak Ra	ate:	Not reported			
Material:					
Material Class	Туре:	3			
Quantity Spille	ed:	0			
Units:		Pounds			
Unknown Qty	Spilled:	No			
Quantity Reco	vered:	0			
Unknown Qty	Recovered:	False			
Material:		RRX FABRIC SC	JEIENER		
Class Type:		Non Pet/Non Ha			
Chem Abstrac	t Service Nu	umber:	RRXFABRI	C SUPTEMER	
Last Date:	_		Not reported		
Num Times M	aterial Entry	In File:			AS DER PAPER RETENTIO
DEC Remarks:	/ / : CAS	E CLOSED. 02/13	WU1: PAPER	FILE REMOVED	ASPERTALERRE
	N POLICY	(. 			ACTUAL QUANTITY SPILLED-1-2PIN
Spill Cause:	C/O ROC	K HAZMAT IEAM	I RESPONDE		
	15				

~~	
C8	CULLARI (JAMES) AFARTMENT
ESE	130 NORTH CLINTON AVENUE
< 1/8	ROCHESTER, NY
395 ft.	

Site 2 of 5 in cluster C

Relative: Higher

Relative: Higher	LTANKS:	
Ingliei	Spill Number:	9404660
Actual:	Spill Date:	07/01/94
527 ft.	1D:	201693
	Material Spilled:	#2 FUEL OIL
	Region Close Dt:	Not closed
	Water Affected:	Not reported
	Resource Affectd	: On Land
	Spill Cause:	Tank Failure
	Tank Number:	Not reported
	Test Method:	Not reported
	PBS:	Not reported

Region of Spill:	8
Reported to Dept:	11
Date Call Received	1:07/01/94
Amount Spilled:	135 Gal.
Spill Source:	PRIVATE DWELLING
Tank Size:	Not reported
Leak Rate:	Not reported

LTANKS S101174706 N/A

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

S101174706

CULLARI (JAMES) APARTMENT (Continued)

Region Close Dt: Not reported

Resource Affectd: On Land

9404660

07/01/1994 10:04

Not reported

Not reported

Not reported

Tank Failure

Not reported

Improbable)

11

JAMES CULLARI

τw

Spill Number:

Material Spilled:

Water Affected:

Facility Contact:

Spill Cause:

Investigator:

Caller Name:

Caller Phone:

Notifier Name:

Notifier Phone:

Spiller Contact:

Spiller Address:

Spill Closed Dt:

Recommended Penalty:

Investigation Complete:

Spill Record Last Update:

Spiller Cleanup Date:

Enforcement Date:

UST involvement:

Spill Notifier: Cleanup Ceased: / / Last Inspection: / / Cleanup Meets Standard:

Spill Class:

PBS:

Spiller:

Spill Date:

ID:

Region of Spill: 8 Reported to Dept: 07/01/94 14:30 Date Call Received:Not reported Not reported Amount Spilled: Private Dwelling Spill Source: (716) 388-7961 Facility Tele: SWIS: 26 Not reported Caller Agency: Caller Extension: Not reported Notifier Agency: Not reported

Notifier Extension: Not reported

Not reported

RICH'S DUGWAY RD ROCHESTER, NY 14625 Known release that creates potential for fire or hazard. (Highly PBS Number: Not reported Fire Department False Penalty Not Recommended 11 11 11 False 03/16/98 False 11 07/06/94

Spiller Phone:

Is Updated: Corrective Action Plan Submitted: Date Spill Entered In Computer Data File: Date Region Sent Summary to Central Office: / / Tank Test: PBS Number: Not reported Not reported Tank Number: Not reported Test Method: Capacity of Failed Tank: Not reported Not reported Leak Rate Failed Tank: Not reported Gross Leak Rate: Material: Material Class Type: 1 135 Quantity Spilled: Gallons Units: 135 Unknown Qty Spilled: Quantity Recovered: n Unknown Qty Recovered: False #2 FUEL OIL Material: Petroleum Class Type: #2 FUEL OIL Chem Abstract Service Number: 12/07/1994 Last Date: 24464 Num Times Material Entry In File:

07/01/94: FIRE DEPT PUMPED UP FREE PRODUCT USED ABSORBENTS ON RESIDUAL. DEC Remarks: BUTCH JONES OF MCHD REPORTED 2 DRUMS OF LIQUID 1 DRUM OF ABSORBENTS. JM



EDR ID Number Database(s) EPA ID Number

CULLARI (JAMES) APARTMENT (Continued)

Spill Cause:

S101174706

SPOKE TO JIM CULLARI ADVISED HIM OF DISPOSAL OPTIONS. HE IS TO ADVISE O FFICE OF ARRANGEMENTS. BASEMENT TO BE VENTILATED. 03/16/98: TRANSFERED BS TO TW. AN ABOVEGROUND 275 GAL FUEL OIL TANK, LOCATED IN BASEMENT OF APARTMENT B LDG RUSTED. ESTIMATED LOSS OF 135 GALS OF 2 FUEL. TANK HAD NOT BEEN IN USE. CONVERTED TO NATURAL GAS. CONTACT: RP

9 ESE < 1/8 405 ft.	FORMER AMOCO 128 NORTH CLINTON ROCHESTER, NY					NY SI	oills	S104880076 N/A
Relative: Higher	SPILLS: Spill Number:	0070455		R	egion of Spill:	8		
	Spill Date:	10/26/00	70.004	R	eported to Dept:	11		
Actual:	ID:		70834					
521 π.	Date Call Receive	ed:	10/26/00					
	Region Close Dat		10/26/00	^	mount Spillod:	Unknown Gal		
	Material Spilled:	GASULINE	≓ l	A	nill Sourco:	GASOLINE STAT		
	Water Affected:	Not reporte	a	3	pill Source.	On Land		
	Spill Cause:		. al	к т	esource Anecieu.	Not reported		
	Tank Number:	Not reporte	90 2	14	alik Size . ook Poto:	Not reported		
	Test Method:	Not reporte	eu -		eak nale.	Not reported		
	Spill Number:	0070455		R	egion of Spill:	8		
	Spill Date:	10/26/2000) 12:00	R	eported to Dept:	10/26/00 14:35		
	ID:		Not reported					
	Date Call Receive	ed:	Not reported					
	Region Close Dat	e :	Not reported					
	Material Spilled:	Not reporte	ed	A	mount Spilled:	Not reported		
	Water Affected:	Not reporte	ed	S	pill Source:	Gas Station		
	Spill Cause:	Unknown		R	esource Affected:	On Land		
	Water Affected:	Not reporte	ed	S	pill Source:	Gas Station		
	Facility Contact:	Not reporte	ed	F	acility Tele:	Not reported		
	Investigator:	DT		S	WIS:	26		
	Caller Name:	Not reporte	ed	С	aller Agency:	Not reported		
	Caller Phone:	Not reporte	ed	С	aller Extension:	Not reported		
	Notifier Name:	Not reporte	ed	N	otifier Agency:	Not reported		
	Notifier Phone:	Not reporte	ed	N	otifier Extension:	Not reported		
	PBS:	Not reporte	ed	_				
	Spiller Contact:	Not reporte	ed	S	piller Phone:	Not reported		
	Spiller:	FORMER	AMOCO					
	Spiller Address:	128 NORT ROCHEST	H CLINTON ER, NY					
	DEC Remarks :	Not reporte	ed					
	Remark:	CALLER S	TATES THAT GASO	LINE UST S	REMAIN ON SIT	E OF THE FORME	R AN	1000
		STATION.	REDFRONT RESTA	URANT CUI	RRENTLY OCCU	PIES THE SITE. PE	3S AN	ID SPILLS
		DATABAS AT 1515 H	E SEARCH REVEAL RS AT 10/26/2000.	ED NO INFO	DRMATION ON TI	HE PROPERTY. FA	AXED	TO MCHD
	Spill Class:	Known rele	ease with minimal pot	tential for fire	e or hazard. DEC f	Response.		
	Tank Test:	Thing i to	ponoible r arty. com					
	PBS Number:		Not reported					
	Tank Number:		Not reported					
	Test Method:		Not reported					
	Capacity of Fai	led Tank:	Not reported					
	Leak Rate Faile	ed Tank:	Not reported					
	Gross Leak Ra	te:	Not reported					
	Material:							

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

S104880076

FORMER AMOCO (Continued)

Material Class Type:	1			
Quantity Spilled:	0			
Units:	Gallons			
Unknown Qty Spilled:	No			
Quantity Recovered:	0			
Unknown Qty Recovered:	True			
Material:	GASOLINE			
Class Type:	Petroleum			
Chem Abstract Service Nu	ımber:	GASOLINE		
Last Date:		09/29/1994		
Num Times Material Entry	In File:	21329		
Spill Closed Dt: 10/26/00				
Spill Notifier: Citizen			PBS Number:	Not reported
Cleanup Ceased: 10/26/00				
Last Inspection: / /			Cleanup Meets Sto	I:False
Recommended Penalty:	Penalty Not Rec	commended		
Spiller Cleanup Dt/ /			Enforcement Date:	11
Invstgn Complete:/ /			UST Involvement:	False
Spill Record Last Update:	01/31/01			
Is Updated:	False			
Corrective Action Plan Submitted:		11		
Date Spill Entered In Computer Data File:		10/26/00 15:	06	
Date Region Sent Summary to Central Office:				
This is the	most recent NY	SPILLS record	i for this site.	

Click this hyperlink while viewing on your computer to access additional NY SPILLS detail in the EDR Site Report.

NY Spills S102169371 C10 NUSBAUM (A) CO N/A 304-308 ANDREWS STREET East < 1/8 ROCHESTER, NY 453 ft. Site 3 of 5 in cluster C **Relative:** SPILLS: Higher Region of Spill: 8 8603560 Spill Number: Reported to Dept: / / Spill Date: 08/29/86 Actual: 102426 529 ft. ID: Date Call Received: 08/28/86 10/01/86 Region Close Date : Material Spilled: PERCHLOROECHYORINE Amount Spilled: 0 Gal. OTHER COMM/INDUSTRIAL Spill Source: Water Affected: Not reported Resource Affected: Groundwater Spill Cause: Deliberate Not reported Tank Size : Tank Number: Not reported Test Method: Leak Rate: Not reported Not reported 8 8603560 Region of Spill: Spill Number: Reported to Dept: 08/28/86 10:30 08/29/1986 10:30 Spill Date: Not reported ID. Not reported Date Call Received: Region Close Date : Not reported Amount Spilled: Not reported Material Spilled: Not reported Other Commercial/Industrial Spill Source: Water Affected: Not reported Resource Affected: Groundwater Spill Cause: Deliberate Other Commercial/Industrial Spill Source: Water Affected: Not reported Facility Tele: (7.16) 454-4757 Facility Contact: Not reported SWIS: 26 Investigator: ΒF Not reported Caller Agency: Caller Name: Not reported Caller Extension: Not reported Not reported Caller Phone:



Database(s)

EDR ID Number EPA ID Number

S102169371

NUSBAUM (A) CO (Continued)

Notifier Name:	Not reported	d		Notifier Agency: Notifier Extension:	Not reported Not reported			
Notifier Phone.	Not reporte	d						
PDO. Spillor Contact:	Not reporte	d		Spiller Phone:	Not reported			
Spiller Contact.	A NUSBAU	M CO (MARSH L	ABS)	•				
Spiller Address	304-308 AN	DREWS STREE	т					
Spiller Address.	ROCHEST	ER. NEW YORK						
DEC Remarks :	/ / : REFE	RRED TO SW FO	OR ACTION -	POSSIBLE CRIMIN	NAL INVESTIGATION.			
DECHOMAN	FOUR 600	GAL TANKS ON	SITE AND VI	ENTED INSIDE OF	BUILDING, HEAVY FUMES			
	PERC). SF	PILLS AND DUM	PING OF PEF	RC, ACIDS, ALKALI	IS AND PHOSPHATE			
	COMPOUN	IDS ON SITE SO	AKING INTO	GROUNDWATER				
	, FACILITY	VERY CLOSE T	O GENESEE	RIVER. SMALL Q	UANTITIES OF HAZ WASTES			
	ALSO THR	OWN INTO DUM	IPSTER. 09	/28/95: This is add	litional information			
	about mate	rial spilled from the	ne translation	of the old spill file:				
	PERCHLO	RETHYLENE.	1/17/01: PAP					
	ILE REMO	VED AS PER PA	PER RETEN					
Remark:	PERCHLO	R., ACIDS, ALKA	LIS BEING A		GALLI DISI COLD OF DI			
	SPILLER			d DEC Posponse	Willing			
Spill Class:	Known rele	ease that creates	a file or naza	IQ. DEC Response.	4 minig			
	Responsib	le Party. Correctiv	ve action take					
lank lest:		Not reported						
PBS Number:		Not reported						
Tank Number:		Not reported						
Connective of Fr	iled Tank	Not reported						
Look Rote Fai	led Tank:	Not reported	Not reported					
Gross Leak R	ate [.]	Not reported	Not reported					
Material:								
Material Class	Type:	3						
Quantity Spille	ed:	0						
Units:		Gallons						
Unknown Qty	Spilled:	No						
Quantity Reco	overed:	0						
Unknown Qty	Recovered:	False						
Material:		PERCHLOROE	CHYORINE					
Class Type:		Non Pet/Non Ha						
Chem Abstrac	ct Service Nu	imber:	PERCHLOR					
Last Date:		la Ella						
Num Times N	aterial Entry	in File:	I I					
Spill Closed Dt:	Fodoral G	overnment		PBS Number:	Not reported			
Cleanup Cease	- 10/01/86	overnment			•			
Last Inspection:				Cleanup Meets S	td:True			
Recommended	Penalty:	Penalty Not Red	commended					
Spiller Cleanup	Dt/ /	•		Enforcement Date	e://			
Invstan Comple	te://			UST Involvement	: Faise			
Spill Record Las	st Update:	04/17/01		×				
Is Updated:		False						
Corrective Actio	n Plan Subn	nitted:	11					
Date Spill Enter	ed In Compu	iter Data File:	09/02/86					
Date Region Se	nt Summary	to Central Office		d for this site				
	This is the	e most recent NY	SHILLS recoi	ra for this site.				

<u>Click this hyperlink</u> while viewing on your computer to access additional NY SPILLS detail in the EDR Site Report.

21. S. LEE A. LONGPOOL				
Charles the design of the second s	그 그렇게 가지 않는 것 없다는 것 같아요. 가지 않는 것이 없는 것이 없다.	1.10.3.0		
	MAP FINDINGS			

Database(s)

EDR ID Number EPA ID Number

C11 East < 1/8	ROCHESTER CITY 304-308 ANDREW ROCHESTER, NY	FINDS RCRA-LQG	1001493664 NYR000075572	
453 π.	Site 4 of 5 in clust	er C		
Relative: Higher	RCRAInfo: Owner:	CITY OF ROCHESTER		
Actual: 529 ft.	EPA ID:	(716) 428-6855 NYR000075572		
	Contact:	ANNE SPAULDING (716) 428-7474		
	Classification TSDF Activiti	: Large Quantity Generator es: Not reported		
	Violation Stat	tus: No violations found		
	NY MANIFES	ST		
		<u>Click this hyperlink</u> while viewing on your computer to access additional NY MANIFEST detail in the EDR Site Report.		
	FINDS: Other Pertine Resource	ent Environmental Activity Identified at Site: Conservation and Recovery Act Information system		
C12 East < 1/8	ROCHESTER ED 305 ANDREWS S ROCHESTER, NY	UCATION OPPOR CENTER T 14604	RCRA-SQG FINDS	1000241140 NYD982736746
453 π.	Site 5 of 5 in clus	ter C		
Relative: Higher	RCRAInfo: Owner:	STATE OF NEW YORK		
Actual: 529 ft.	EPA ID:	(212) 555-1212 NYD982736746		
	Contact:	Not reported		
	Classification	n: Small Quantity Generator lies: Not reported		
	Violation Sta	tus: No violations found		
	NY MANIFE	ST		
		<u>Click this hyperlink</u> while viewing on your computer to access additional NY MANIFEST detail in the EDR Site Report.		

FINDS:

Other Pertinent Environmental Activity Identified at Site: Resource Conservation and Recovery Act Information system

Map ID Direction Distance Distance (ft.) Site Elevation

D13

North

< 1/8 484 ft.

Lower

Actual:

502 ft.

AGRICULTURAL TRANSPORT MV

ROUTE 490 E/ CLINTON AVE

ROCHESTER, NY

EPA ID Number Database(s) S102172994 NY Spills N/A

EDR ID Number

Site 1 of 2 in cluster D Relative: SPILLS: Region of Spill: 8 8402814 Spill Number: Reported to Dept: / / 01/18/85 Spill Date: 97371 ID: 01/22/85 Date Call Received: 06/01/86 Region Close Date : Amount Spilled: 50 Gal. Material Spilled: DIESEL UNKNOWN Spill Source: GROUND Water Affected: Resource Affected: On Land Traffic Accident Spill Cause: Not reported Tank Size : Tank Number: Not reported Leak Rate: Not reported Not reported Test Method: Region of Spill: 8 Spill Number: 8402814 Reported to Dept: 01/22/85 11:30 01/18/1985 11:00 Spill Date: Not reported n. Not reported Date Call Received: Region Close Date : Not reported Not reported Amount Spilled: Material Spilled: Not reported Spill Source: Unknown Water Affected: GROUND Resource Affected: On Land Traffic Accident Spill Cause: Unknown Spill Source: GROUND Water Affected: Not reported Facility Tele: Facility Contact: Not reported SWIS: 26 Not reported Investigator: Not reported Caller Agency: Not reported Caller Name: Caller Extension: Not reported Not reported Caller Phone: Not reported Notifier Agency: Not reported Notifier Name: Notifier Extension: Not reported Notifier Phone: Not reported Not reported PBS: Spiller Phone: Not reported Not reported Spiller Contact: Not reported Spiller: Spiller Address: Not reported / / : CLEANUP ACTION: ABSORBANTS SAND USED TO RECOVER MATERIAL. DEC Remarks : AMERICAN ENVIRONMENTAL REMOVED 10 BARRELS OF ABSORBANTS TO FRONTIER 09/28/95: This is additional information about material DELIVERY. spilled from the translation of the old 02/23/01: PAPER FILE REMOVED PER PAPER spill file: DIESEL FUEL RETENTION POLICY. TRACTOR TRAILER MOTOR VEHICLE ACCIDENT RESULTING IN RUPTURE OF SADDLE TANKS. ART HULL, DRIVER FOR AGRICULTURAL TRANSPORT, 5212 W 30TH ST, Remark: CICERO, IL 60650). FIRE DEPT PUMPED OUT TANKS AND PLACED IN DRUMS. Possible release with minimal potential for fire or hazard or Known Spill Class: release with no damage. DEC Response. Willing Responsible Party. Corrective action taken. Tank Test: Not reported PBS Number: Not reported Tank Number: Not reported Test Method: Not reported Capacity of Failed Tank: Not reported Leak Rate Failed Tank: Not reported Gross Leak Rate: Material: Material Class Type: 1 50 Quantity Spilled:



(212) 555-1212 EPA ID: NYD986911154 Contact: JOSEPH INGALLS (607) 324-7580

> Classification: Small Quantity Generator TSDF Activities: Not reported

Violation Status: No violations found

NY MANIFEST

Click this hyperlink while viewing on your computer to access additional NY MANIFEST detail in the EDR Site Report.

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Resource Conservation and Recovery Act Information system

Map ID Direction Distance Distance (ft.) Elevation Site

EDR ID Number EPA ID Number Database(s)

S102679291 NY Spills N/A

15 NNE < 1/8	CUSTOM TIRE 209 NORTH CLINTON / ROCHESTER, NY	AVENUE				N	T Shiis	N/A
520 ft.								
Relative: Lower	SPILLS: Spill Number: Spill Date:	9406181 08/01/94		Reç Rep	gion of Spill: ported to Dept:	8 / /		
Actual: 506 ft.	ID: Date Call Receive	2 d: 0	03098 8/02/94					
	Region Close Date	e: 0	2/22/95					
	Material Spilled:	WASTE OIL		Am	ount Spilled:	U Gal.		PIAL
	Water Affected:	Not reported		Spi	Source:	On Land		((/ C
	Spill Cause:	Housekeepi	ng	Re	source Affected:	Not reported		
	Tank Number:	Not reported	1	lar	nk Size :	Not reported		
	Test Method:	Not reported	1	Lea	ak Rate:	NotTeported		
				Re	gion of Spill:	8		
	Spill Number:	9406181		Re	ported to Dept.	08/02/94 10:	15	
	Spill Date:	08/01/1994	12:00	Re	ported to Dept.	00.02.01		
	ID:	1	Not reported					
	Date Call Receive	ed: I	Not reported					
	Region Close Dat	te:	Not reported	٨٣	ount Spilled:	Not reported		
	Material Spilled:	Not reported	1	All	ill Source:	Other Comm	ercial/Indu	strial
	Water Affected:	Not reporte	d	Sp Bo	source Affected	On Land		
	Spill Cause:	Housekeep	ing	Re Sn	Source:	Other Comm	ercial/Indu	strial
	Water Affected:	Not reporte	d	54	cility Tele	Not reported		
	Facility Contact:	Not reporte	d	1 a S\		26		
	Investigator:	DT		54 Ca	aller Agency.	Not reported		
	Caller Name:	Not reporte	d	C:	aller Extension	Not reported		
	Caller Phone:	Not reporte	d	0a Na	alier Extension.	Not reported		
	Notifier Name:	Not reporte	d		tifier Extension	Not reported		
	Notifier Phone:	Not reporte	d	INC	Juner Extension.	Hotropone		
	PBS:	Not reporte	d	6.	illor Phone:	Not reported		
	Spiller Contact:	Not reporte	d	5	filler r fiorie.	(lot lope lo-		
	Spiller:	CUSTOM	FIRE					
	Spiller Address:	SAME				PSTER SLOP	PΥ	
	DEC Remarks :	08/02/94: A HOUSEKE 02/22/95: J	ALSO OLD OIL FIL EPING HAS BEE! IM ON SITE; NOT HER ACTION NEE	N ONGOING FO ED NOTHING U DED AT THIS	DR YEARS. DEF JNUSUAL, NO A TIME.	PT TO MAKE I	INSPECTION ONTMAIN/	ON. ATION.
	Remark:	CALLER S TANKS. T/	TATES THAT SLO ANKS SURROUNI D THEN DRAINS	SLOPPY HOUSEKEEPING AROUND ABOVEGROUND WASTE OIL SUNDED BY CINDERBLOCK SAND AROUND BOTTOM. OIL SPILLS ANS AWAY, CONTACT: DAVID COSTA				ASTE OIL)IL SPILLS
	Spill Class:	Known rele Willing Res	ease with minimal sponsible Party. C	potential for fire orrective action	or hazard. DEC taken.	Response.		
	Tank Test:							
	PBS Number:		Not reported					
	Tank Number		Not reported					
	Test Method:		Not reported					
	Capacity of Fa	ailed Tank:	Not reported					
	Leak Rate Fa	iled Tank:	Not reported					
	Gross Leak R	Rate:	Not reported					
	Material:							
	Material Class	s Type:	1					
	Quantity Spill	ed:	0					
	Units:		Gallons					
	Unknown Qty	/ Spilled:	No					
	Quantity Rec	overed:	0					
	Unknown Qty	Recovered:	False					

Map ID Direction Distance Distance (ft.) Elevation Site

EDR ID Number EPA ID Number

S102679291

Database(s)

CUSTOM TIRE (Continued) WASTE OIL Material: Class Type: Petroleum Chem Abstract Service Number: WASTE OIL Last Date: 09/27/1994 9509 Num Times Material Entry In File: 02/22/95 Spill Closed Dt: Spill Notifier: Citizen PBS Number: Not reported Cleanup Ceased: 02/22/95 Last Inspection: / / Cleanup Meets Std:True Recommended Penalty: Penalty Not Recommended Spiller Cleanup Dt/ / Enforcement Date: / / Invstgn Complete:/ / UST Involvement: False Spill Record Last Update: 03/24/95 Is Updated: False Corrective Action Plan Submitted: 11 Date Spill Entered In Computer Data File: 08/05/94 Date Region Sent Summary to Central Office: / /

This is the most recent NY SPILLS record for this site.

Click this hyperlink while viewing on your computer to access additional NY SPILLS detail in the EDR Site Report.

16 **GENESSEE BREWERY** NW 245 ST PAUL BLVD < 1/8

ROCHESTER, NY 543 ft. SPILLS: **Relative:** Spill Number: 9704410 Region of Spill: 8 Lower Spill Date: 07/14/97 Reported to Dept: / / Actual: ID: 250401 499 ft. Date Call Received: 07/14/97 Region Close Date : 07/14/97 Material Spilled: ASH Amount Spilled: Water Affected: Not reported Spill Source: Spill Cause: Unknown Resource Affected: Air Tank Number: Not reported Tank Size : Test Method: Not reported Leak Rate: Spill Number: 9704410 Region of Spill: 8 Spill Date: 07/14/1997 10:15 ID: Not reported Date Call Received: Not reported Region Close Date : Not reported Material Spilled: Not reported Amount Spilled: Water Affected: Not reported Spill Source: Spill Cause: Unknown Resource Affected: Air Water Affected: Not reported Spill Source: Facility Contact: Not reported Facility Tele: Investigator: DT SWIS: 26 Caller Name: Caller Agency: Not reported Caller Phone: Not reported Caller Extension: Notifier Name: Not reported Notifier Agency: Notifier Phone: Not reported Notifier Extension: PBS: Not reported Spiller Contact: Not reported Spiller Phone: Spiller: Not reported Spiller Address: Not reported

NY Spills S102667237

N/A

Unknown Gal. UNKNOWN Not reported Not reported

Reported to Dept: 07/14/97 11:20

Not reported Unknown Unknown Not reported Not reported Not reported Not reported Not reported Not reported

DEC Remarks : 07/14/97 SPILL CLEANED-UP, NO FURTHER ACTION NEEDED BY SPILLS. CLOSED.

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s) E

EDR ID Number EPA ID Number

S102667237 **GENESSEE BREWERY** (Continued) ash ans soot disharge from an unknown area, rochester fd and mchd Remark: enroute. 7/14/97 1344 hours. dt spoke w/ mark les c ynski. ash came from r g e 20 min opacity excursion from a stack located at r g e ash is being cleaned up Possible release with minimal potential for fire or hazard or Known Spill Class: release with no damage. DEC Response. Willing Responsible Party. Corrective action taken. Tank Test: Not reported PBS Number: Not reported Tank Number: Not reported Test Method: Capacity of Failed Tank: Not reported Leak Rate Failed Tank: Not reported Not reported Gross Leak Rate: Material: 3 Material Class Type: 0 Quantity Spilled: Units: Gallons Unknown Qty Spilled: No Quantity Recovered: 0 Unknown Qty Recovered: False Material: ASH Non Pet/Non Haz Class Type: Chem Abstract Service Number: ASH Not reported Last Date: Num Times Material Entry In File: 16 Spill Closed Dt: 07/14/97 PBS Number: Not reported Health Department Spill Notifier: Cleanup Ceased: / / Cleanup Meets Std:False Last Inspection: / / Penalty Not Recommended Recommended Penalty: Enforcement Date: / / Spiller Cleanup Dtf / UST Involvement: False Invstgn Complete:/ / 09/19/97 Spill Record Last Update: False Is Updated: Corrective Action Plan Submitted: 11 Date Spill Entered In Computer Data File: 07/14/97 Date Region Sent Summary to Central Office: / / This is the most recent NY SPILLS record for this site. Click this hyperlink while viewing on your computer to access

additional NY SPILLS detail in the EDR Site Report.

17UNITED STATES POSTAL SERVICENNEDOWNTOWN STATION< 1/8</td>ROCHESTER, NY 14605

553 ft.

PBS UST: **Relative:** CBS Number: Not reported 8-035335 PBS Number: Lower SWIS ID: 2614 Not reported SPDES Number: UNITED STATES POSTAL SERVICE Actual: Operator: (716) 546-6425 511 ft. ANDREW MARTIN **Emergency Contact:** (716) 846-2352 Total Tanks: Ω UNITED STATES POSTAL SERVICE Owner: 1335 JEFFERSON ROAD ROCHESTER, NY 14692

TC01376628.1r Page 21

UST

U001849774

N/A



Database(s)

EDR ID Number EPA ID Number

U001849774

UNITED STATES POSTAL SERVICE (Continued)

(716) 272-5940 Federal Government Owner Type: Owner Mark: First Owner Owner Subtype: Not reported Mailing Address: UNITED STATES POSTAL SERVICE ATTN: ANDREW MARTIN 1200 WILLIAM STREET BUFFALO, NY 14240 (716) 846-2352 Tank Status: Closed - Removed Capacity (gals): 6000 Tank Location: UNDERGROUND Tank Id: 001 Install Date: 06/01/1990 Tank Type: Fiberglass reinforced plastic [FRP] Product Stored: UNLEADED GASOLINE Tank Internal: FIBERGLASS LINER [FRP] Pipe Internal: FIBERGLASS LINER [FRP] Pipe Location: Underground FIBERGLASS [FRP] Pipe Type: Tank External: FIBERGLASS Missing Data for Tank: No Missing Data Pipe External: FIBERGLASS Second Containment: DOUBLED-WALLED TANK Leak Detection: INTERSTITIAL MONITORING/IN-TANK SYSTEM **Overfill Prot:** Catch Basin Dispenser: Suction Date Tested: Not reported Next Test Date: Not reported Date Closed: 07/01/1998 Test Method: Not reported Deleted: False Updated: True Dead Letter: False Owner Screen: No data missing FAMT: Fiscal amount for registration fee is correct Total Capacity: n Renewal Date: Not reported Tank Screen: n Federal ID: Not reported Renew Flag: No data missing Renwal has not been printed Facility Screen: Certification Flag: False Certification Date:09/20/1996 Old PBS Number: Not reported Expiration Date: 10/09/2001 Inspected Date: 10/19/1994 Inspector: WLS Inspection Result: Not reported Lat/long: Not reported Facility Type: OTHER Town or City: ROCHESTER (C) Town or City Code: 14 County Code: 26 Region: 8 PBS Number: 8-035335 CBS Number: Not reported SPDES Number: Not reported SWIS ID: 2614 UNITED STATES POSTAL SERVICE Operator: (716) 546-6425 Emergency Contact: ANDREW MARTIN (716) 846-2352 Total Tanks: 0 Owner: UNITED STATES POSTAL SERVICE 1335 JEFFERSON ROAD ROCHESTER, NY 14692 (716) 272-5940 Owner Type: Federal Government Owner Mark: First Owner Owner Subtype: Not reported UNITED STATES POSTAL SERVICE Mailing Address: ATTN: ANDREW MARTIN

MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

U001849774

UNITED STATES POSTAL SERVICE (Continued)

	1200 WILLIAM STREET		
	BUFFALO, NY 14240		
	(716) 846-2352		
Tank Status:	Closed - Removed		
Capacity (gals):	10000		
Tank Location:	UNDERGROUND		
Tank Id:	001	Install Date:	12/01/1982
Tank Type:	Steel/carbon steel	Product Stored:	UNLEADED GASOLINE
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	Not reported	Pipe Type:	Not reported
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	NONE		
Leak Detection:	NONE		
Overfill Prot:	2	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	06/01/1990	Test Method:	Not reported
Deleted:	False	Updated:	Irue
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is corre	ct	
Total Capacity:	0	Renewal Date:	Not reported
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date	09/20/1996
Old PBS Number:	Not reported	Expiration Date:	10/09/2001
Inspected Date:	10/19/1994	Inspector:	WLS
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	OTHER		
Town or City:	ROCHESTER (C)		
Town or City Code:	14		
County Code:	26		
Region:	8		

XEROX SQUARE 100 NORTH CLINTON ROCHESTER, NY

ROOMEDTER, M

Site 1 of 2 in cluster E

Relative: Higher

E18

SE

< 1/8 588 ft.

Actual: 530 ft.

0270252	
07/26/02	
	35744
ed:	07/26/02
te :	07/26/02
HYDRAUL	IC OIL
Not report	ed
Other	
Not report	ed
Not report	ed
	0270252 07/26/02 ed: te: HYDRAUI Not report Other Not report Not report

NY Spills S106005988 N/A

Region of Spill: 8 Reported to Dept: / /

Amount Spilled:2 Gal.Spill Source:OTHER COMM/INDUSTRIAL.Resource Affected: On LandTank Size :Not reportedLeak Rate:Not reported

Map ID Direction Distance Distance (ft.) Elevation Site

EDR ID Number EPA ID Number

Database(s)

19 SW < 1/8	CROSSROADS APARTMEN GENESEE CROSSROADS F ROCHESTER, NY 14603	ITS PARCEL 2			UST	U003314719 N/A
629 ft.						
Relative: Lower	PBS UST: PBS Number: SPDES Number:	8-182184 Not reported	CBS Number: SWIS ID:	Not reported 2614		
Actual: 514 ft.	Operator:	(716) 325-5232				
	Emergency Contact:	TONY CLINKSCALES (716) 238-6430				
	Total Tanks: Owner:	1 CROSSROADS APARTMENTS - RHAC 1265 SCOTTSVILLE ROAD ROCHESTER, NY 14624 (716) 464-9400				
	Owner Type: Owner Mark: Owner Subtype: Mailing Address:	Corporate/Commercial First Owner Not reported CROSSROADS APARTMENTS - RHAC ATTN: MARK A PURDELL 1265 SCOTTSVILLE ROAD ROCHESTER, NY 14624 (716) 464-9400				
	Tank Status: Capacity (gals): Tank Location: Tank Id:	In Service 5000 UNDERGROUND 001	Install Date:	03/01/1982	R 4 FUI	EL OIL
	Tank Type: Tank Internal: Pipe Location: Tank External: Missing Data for Tank: Pipe External: Second Containment: Lock Detection:	Steel/carbon steel Not reported Underground Not reported Minor Data Missing Not reported NONE	Pipe Internal: Pipe Type:	Not reported STEEL/IRON	4	
	Overfill Prot: Date Tested: Date Closed: Deleted: Dead Letter: FAMT	Product Level Gauge 12/01/1997 Not reported False False Fiscal amount for registration fee is correct	Dispenser: Next Test Date: Test Method: Updated: Owner Screen: ect	Submersible 12/01/2002 TANKOLOG True No data mis	iΥ [VAC sing	CUTECT]
	FAM1: Total Capacity: Tank Screen: Renew Flag: Certification Flag: Old PBS Number: Inspected Date: Inspection Result: Lat/long: Facility Type: Town or City: Town or City Code: County Code:	Fiscal amount for registration rec is cone 5000 Minor data missing Renwal has not been printed False Not reported Not reported Not reported Not reported APARTMENT BUILDING ROCHESTER (C) 14	Renewal Date: Federal ID: Facility Screen: Certification Date Expiration Date: Inspector:	Not reported Not reported No data mis e:09/18/1997 07/10/2002 Not reported	l sing l	

Map ID Direction Distance Distance (ft.) Elevation Site

EDR ID Number Database(s) EPA ID Number

E20 SE 1/8-1/4 669 ft.	CITY OF ROCHESTER MICHAELS STERN BLDG 87 N CLINTON AVE 1/4 ROCHESTER, NY 14604 1ft.					1004762702 NYR000099606	
	Site 2 of 2 in cluster	E					
Relative: Higher	RCRAInfo: Owner:	CITY OF ROCHESTER					
Actual: 531 ft.	EPA ID:	(716) 428-6855 NYR000099606					
	Contact:	ANNE SPAULDING (716) 428-7474					
	Classification: TSDF Activities:	Large Quantity Generator Not reported					
	BIENNIAL REPOR Last Biennial Re	TS: sporting Year: 2001					
	<u>Waste</u> <u>Qu</u> D001 D019 D022	<u>uantity (Lbs)</u> 1953.72 458.72 458.72	<u>Waste</u> D002 D021 D039	Quantity (Lbs) 150.00 550.46 1651.38			
	Violation Status	· No violations found					
	FINDS: Other Pertinent Resource Co	<u>Click this hyperlink</u> while viewing or additional NY MANIFEST detail in t Environmental Activity Identified at Sit Inservation and Recovery Act Information	n your compute he EDR Site R e: lion system	er to access Report.			
21 West 1/8-1/4 736 ft.	H & A OF NEW YOR 189 N WATER ST ROCHESTER, NY 1	K 4604			RCRA-SQG FINDS	1000457587 NYD986928489	
Relative: Lower	RCRAInfo: Owner:	OLDE ROCHESTERVILLE					
Actual:	EPA ID:	NYD986928489					
500 ft.	Contact:	Not reported	Not reported				
	Classification: TSDF Activities						
	Violation Status	s: No violations found					
	NY MANIFEST						
		<u>Click this hyperlink</u> while viewing o additional NY MANIFEST detail in	n your comput the EDR Site F	er to access Report.			

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s) EDR ID Number EPA ID Number 1000457587

H & A OF NEW YORK (Continued)

FINDS:

Other Pertinent Environmental Activity Identified at Site: Resource Conservation and Recovery Act Information system

22 WSW 1/8-1/4 786 ft.	ROCHESTER CITY OF OLD GREYHOUND BUS TERM 120 ANDREWS ST ROCHESTER, NY 14604			1001493538 NYR000074179
Relative: Lower	RCRAInfo: Owner:	CITY OF ROCHESTER		
Actual:	EPA ID:	(716) 428-6855 NYR000074179		
496 ft.	Contact:	ANNE SPAULDING (716) 428-7474		
	Classification: TSDF Activities	Small Quantity Generator :: Not reported		¢
	Violation Status	s: No violations found		
	FINDS: Other Pertinent Resourc e Co	Environmental Activity Identified at Site: onservation and Recovery Act Information system		
23 ESE 1/8-1/4 867 ft.	JOYCE FAMILY PROPERTIES 172-180 PLEASANT ST 4 ROCHESTER, NY 14604		RCRA-SQG FINDS	1000168342 NYD986891430
Relative: Higher	RCRAInfo: Owner:	MARINE MIDLAND BANK		
Actual:	EPA ID:	NYD986891430		
535 ft.	Contact:	Not reported		
	Classification: TSDF Activities	Small Quantity Generator : Not reported		
	Violation Status	: No violations found		
	FINDS: Other Pertinent Resource Co	Environmental Activity Identified at Site: onservation and Recovery Act Information system		
24 ENE 1/8-1/4 874 ft.	ST VINCENT PRESS 250 CUMBERLAND ROCHESTER, NY 1	6 ST 4605	RCRA-SQG FINDS	1000981483 NY0001003466
Relative:				

Relative: Higher

Actual: 524 ft.



Database(s)

EDR ID Number EPA ID Number

.

1000981483

ST VINCENT PRESS (Continued)

			-	
D	$\sim \Box$	י מי	nf	o.

Owner:	BARBARA ANZALONE
EPA ID:	NY0001003466
Contact:	DEBORAH MANCUSO (716) 325-5320
Classification: TSDF Activities:	Small Quantity Generator Not reported

Violation Status: No violations found

NY MANIFEST

<u>Click this hyperlink</u> while viewing on your computer to access additional NY MANIFEST detail in the EDR Site Report.

FINDS:

Other Pertinent Environmental Activity Identified at Site: Resource Conservation and Recovery Act Information system

25 South 1/8-1/4 951 ft.	BARIS TAILORING 48 ST PAUL ST ROCHESTER, NY 14	4604	RCRA-SQG FINDS	1000447166 NYD986907061
Relative: Higher Actual:	RCRAInfo: Owner: EPA ID:	YILMAZ BARIS (212) 555-1212 NYD986907061		
522 ft.	Contact: Classification: TSDF Activities Violation Status NY MANIFEST FINDS: Other Pertinent Resource C	Not reported Small Quantity Generator : Not reported :: No violations found <u>Click this hyperlink</u> while viewing on your computer to access additional NY MANIFEST detail in the EDR Site Report. t Environmental Activity Identified at Site: onservation and Recovery Act Information system		
F26 East 1/8-1/4 1064 ft. Relative: Higher Actual: 529 ft.	ROCHESTER CITY 414 ANDREWS ST ROCHESTER, NY Site 1 of 3 in cluste	OF ROCHESTER BUILDING SVC 14604 r F	RCRA-SQG FINDS	1001090298 NYR000021352

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

1001090298

ROCHESTER CITY OF ROCHESTER BUILDING SVC (Continued)

RCRAInfo:

Owner:	CITY OF ROCHESTER (716) 428-7474
EPA ID:	NYR000021352
Contact:	Not reported
Classification: TSDF Activities:	Small Quantity Generator Not reported

Violation Status: No violations found

NY MANIFEST

Click this hyperlink while viewing on your computer to access additional NY MANIFEST detail in the EDR Site Report.

FINDS:

Other Perlinent Environmental Activity Identified at Site: Resource Conservation and Recovery Act Information system

F27 East 1/8-1/4 1093 #	WALLACH (ERWIN) 430 ANDREWS STREE ROCHESTER, NY	ΞT		LTANKS	S100122477 N/A
1035 11.	Site 2 of 3 in cluster F				
Relative:					
Higher	LTANKS:		Design of Spills	0	
	Spill Number:	8603686	Region of Spill.		
Actual:	Spill Date:	08/29/86	Reported to Dept.	1 1	
529 ft.	ID:	102453	Date Call Received	.00/29/00	
	Material Spilled:	GASOLINE	Amount Spilled:	U IDS.	
	Region Close Dt:	09/22/86	Call Courses		TRIAL
	Water Affected:	Not reported	Spill Source.	UTHER COMMININGUS	
	Resource Affectd:	Groundwater			
	Spill Cause:	lank Failure	Task Cizor	Not reported	
	Tank Number:	Not reported	Tank Size.	Not reported	
	Test Method:	Not reported	Leak Rate:	Notreponed	
	PBS:	Not reported			
	Spill Number:	8603686	Region of Spill:	8	
	Spill Date:	08/29/1986 08:00	Reported to Dept:	08/29/86 09:00	
		Not reported	Date Call Received	Not reported	
	Material Spilled:	Not reported	Amount Spilled:	Not reported	
	Region Close Dt	Not reported			
	Water Affected:	Not reported	Spill Source:	Other Commercial/Indu	strial
	Resource Affected	Groundwater			
	Spill Cause:	Tank Failure			
	Facility Contact:	Not reported	Facility Tele:	(716) 232-1887	
	Investigator:	BF	SWIS:	26	
	Caller Name:	Not reported	Caller Agency:	Not reported	
	Caller Phone:	Not reported	Caller Extension:	Not reported	
	Notifier Name:	Not reported	Notifier Agency:	Not reported	
	Notifier Phone:	Not reported	Notifier Extension:	Not reported	
	PBS:	Not reported			
	Spiller Contact:	Not reported	Spiller Phone:	Not reported	
	Spiller:	ERWIN WALLACH			
	Spiller Address.	ERWIN'S SERVICE STATION			
	-r	430 ANDREWS ST & UNIVERS			

MAP FINDINGS Map ID Direction Distance EDR ID Number Distance (ft.) EPA ID Number Elevation Site Database(s)

WALLACH (ERWIN) (Continued)

F28

East

1/8-1/4

1093 ft.

Polativo

S100122477 Known release that creates potential for fire or hazard. DEC Response. Spill Class: Willing Responsible Party. Corrective action taken. 09/22/86 Spill Closed Dt: PBS Number: Not reported Spill Notifier: **Responsible Party** Cleanup Ceased: 09/22/86 Last Inspection: / / Cleanup Meets Standard: True Recommended Penalty: Penalty Not Recommended Spiller Cleanup Date: 11 Enforcement Date: 11 Investigation Complete: 11 UST Involvement: True Spill Record Last Update: 04/17/01 Is Updated: False Corrective Action Plan Submitted: 11 09/05/86 Date Spill Entered In Computer Data File: Date Region Sent Summary to Central Office: / / Tank Test: PBS Number: Not reported Not reported Tank Number: Test Method: Not reported Capacity of Failed Tank: Not reported Leak Rate Failed Tank: Not reported Gross Leak Rate: Not reported Material: Material Class Type: 1 0 Quantity Spilled: Units: Pounds Unknown Qty Spilled: No Quantity Recovered: 0 Unknown Qty Recovered: False Material: GASOLINE Class Type: Petroleum Chem Abstract Service Number: GASOLINE Last Date: 09/29/1994 Num Times Material Entry In File: 21329 / / : ROCHESTER FIRE DEPT NOTIFIED; MCHD NOTIFIED. / / : TANK REPLAC DEC Remarks: EMENTS ON 9/22; MCHD ON SCENE; ROCH FD ALSO PRESENT. / / : TANK REPLAC EMENTS ON 9/22; MCHD ON SCENE; ROCH FD ALSO PRESENT; NO EVIDENCE OF CONT AMINATION FOUND; NO FURTHER ACTION NECCESSARY. 4/17/01: PAPER FILE REMO VED AS PER PAPER RETENTION POLICY. 2000 AND 4000 GALLON UNLEADED U.G. TANKS; CORE SAMPLES INDICATED VERY SL Spill Cause: IGHT ODOR. OWNER TO REPLACE ALL TANKS U003314784 AERO AUTOCARE, INC. UST N/A 430 ANDREWS STREET ROCHESTER, NY 14604 Site 3 of 3 in cluster F

Higher	PBS UST:				
	PBS Number:	8-144592	CBS Number:	Not reported	
Actual:	SPDES Number:	Not reported	SWIS ID:	2614	
529 ft.	Operator:	ERIK STARK			
		(7 16) 232-1887			
	Emergency Contact:	ERIK STARK			
		(716) 323-2681			
	Total Tanks:	3			
	Owner:	AERO AUTOCARE, INC.			



Database(s)

EDR ID Number EPA ID Number

AERO AUTOCARE, INC. (Continued)			U0033147
Owner Type: Owner Mark: Owner Subtype: Mailing Address:	430 ANDREWS STR ROCHESTER, NY 14 (716) 323-2681 Corporate/Commerci Second Owner Not reported AERO AUTOCARE, I ATTN: ERIK STARK 430 ANDREWS STR ROCHESTER, NY 14 (716) 232-1887	EET 1604 INC. EET 1604		
Tank Status:	In Service			
Capacity (gals):	4000			
Tank Location:	UNDERGROUND			
Tank ld:	001		Install Date:	10/01/1986
Tank Type:	Steel/carbon steel		Product Stored:	UNLEADED GASOLINE
Tank Internal:	Not reported		Pipe Internal:	Not reported
Pipe Location:	Underground		Pipe Type:	GALVANIZED STEEL
Tank External:	SACRIFICIAL ANOD	E		
Missing Data for Tank: Pipe External:	Minor Data Missing WRAPPED [PIPING]			
Second Containment:	NONE			
Leak Detection:	VAPOR WELL/IN-TA	NK SYSIEM	Diananaari	Submorsible
Date Tested:	Not reported	CII Dasili	Next Test Date:	Not reported
Date Closed:	Not reported		Test Method:	Not reported
Deleted:	False		Undated:	True
Dead Letter:	False		Owner Screen:	No data missing
FAMT:	Fiscal amount for reg	istration fee is correc	xt	.5
Total Capacity:	20000		Renewal Date:	Not reported
Tank Screen:	Minor data missing		Federal ID:	Not reported
Renew Flag:	Renwal has not been	printed	Facility Screen:	No data missing
Certification Flag:	False		Certification Date	:02/27/2001
Old PBS Number:	Not reported		Expiration Date:	02/21/2006
Inspected Date:	08/02/1994		Inspector:	RC
Inspection Result:	Not reported			
Lat/long:				
Facility Type.		DALES		
Town of City Code:	14			
County Code:	26			
Region:	8			
PBS OWNHIST				
Emorgency:				
Emergency Tel:	(716) 442-5983		OId PBSNO:	Not reported
Facility Type:	RETAIL GASOLINE S	SALES	olu i bolito.	Heriopoliou
Facility Owner:		ERWINS SERVICE	STATION	
Facility Address:		(ERWINSONS INC, 430 ANDREWS STR ROCHESTER NY 1	DBA) REET	
Inspector:	RC		Inspect Date:	08/02/1994
Insp Result:	Not reported		Federal ID:	16-1407943
Owner:	ERWINSONS INC			
Owner Tel:	(716) 232-1887		Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported			
Mail Address:	ERWINSONS INC			

Map ID Direction Distance Distance (ft.) Elevation Site

	L	<u></u>			
) Site				Database(s)	EDR ID Number EPA ID Number
AERO AUTOCARE, INC.	(Continued)				1003314784
Owner Mark: Certify Date: Total Capacity (Gal): CBS Registration Num SPDES Number: Lat/Long : County Facility: Facility Phone : Num of Active Tanks : Facility Owner: Facility Address:	DBA ERWINS SER 430 ANDREWS ST ROCHESTER, NY DAVID WALLACH (716) 232-1887 First Owner 06/30/2002 20000	VICE STATION REET 14604 Not reported Not reported 2614 (716) 232-1887 3 ERWINSONS INC 430 ANDREWS S ⁻	Expiration:	06/30/2002	000314704
Owner Phone: Facility Status: Certificate Needs Print Renewal Printed : Pre-printed Renewal F Fiscal Amt For Registr Dt Ownership Transfer Facility Record Update	ed : orm Last Printed : ation Fee Pbsrect: Occurr in Computer : d:	ROCHESTER, NY (716) 232-1887 1 False False Not reported True 02/21/2001 True	14604		
PBS Number: SPDES Number: Operator: Emergency Contact: Total Tanks: Owner:	8-144592 Not reported ERIK STARK (716) 232-1887 ERIK STARK (716) 323-2681 3 AERO AUTOCARE, 430 ANDREWS STF ROCHESTER, NY 1 (716) 232 2681	INC. REET 4604	CBS Number: SWIS ID:	Not reported 2614	
Owner Type: Owner Mark: Owner Subtype: Mailing Address:	Corporate/Commerc Second Owner Not reported AERO AUTOCARE, ATTN: ERIK STARK	ial INC.			

Tank Status: In Service Capacity (gals): 6000 Tank Location: UNDERGROUND Tank Id: 002 Tank Type: Steel/carbon steel Tank Internal: Not reported Pipe Location: Underground Tank External: SACRIFICIAL ANODE Missing Data for Tank: Minor Data Missing Pipe External: WRAPPED [PIPING]

Second Containment:

430 ANDREWS STREET ROCHESTER, NY 14604 (716) 232-1887

NONE

Install Date: 10/01/1986 Product Stored: UNLEADED GASOLINE Pipe Internal: Not reported Pipe Type: GALVANIZED STEEL

APPENDIX 12.8 Radon

New York State Department of Health

A BALL

BASEMENT RADON READINGS, BY GAZATEER CODE September 15, 1994

	r		September 15, 1994)
GAZ. CODE	COUNTY	CITY OR VILLAGE	NUMBER OF HOUSES	MEAN pCi/l	STAND. DEV.	GEOM. MEAN pCi/l	GEOM. STAND. DEV.
2560 2561 2563 2564		Nunda Ossian Sparta	4 1 3	4.3 12.3 3.3	1.8	4.0 12.3 2.6	1.6
2565 2566 2601	Madison	Springwater W. Sparta York Opeida C	6 2 3	29.8 2.7 2.1	60.2 2.5 0.5	4.2 2.1 2.1	2.3 7.1 2.9 1 3
2621 2622 2623		Cazenovia V. Deruyster V. Morrisville V.	29 20 3	3.2 3.9 4.7 14.7	4.6 2.3 6.8	2.0 3.3 1.9	2.4 1.9 5.1
2624 2625 2626 2627		Earlville V. Hamilton V. Canastota V. Wampsville V	2 [°] 6 14	9.6 11.9 4.8	11.2 6.9 14.3 4.9	10.1 8.3 7.4 3.3	3.1 2.2 2.8 2.4
2628 2629 2630		Madison V. Chittenango V. Munnsville V.	2 6 20 4	6.7 4.0 7.2 3.0	4.5 2.1 12.8 3 2	5.9 2.9 3.1	2.1 3.1 3.4
2650 2651 2652 2653		Brookfield Cazenovia / Deruyter / Eaton	4 31 2	12.4 4.1 4.7	7.0 3.7 4.2	10.5 3.0 3.7	4.6 2.1 2.2 2.8
2654 2655 2656		Fenner Georgetown Hamilton	7 4 1 15	13.0 2.7 18.3 10.3	10.6 1.7	8.7 2.4 18.3	3.0
2658 2659 2660	-	Lebanon Lenox Lincoln Madison	5 3 2	2.4 1.4 10.1	2.4 0.8 8/.0	6.3 1.7 1.2 8.3	2.2 2.5 2.1 2.5
2661 2662 2663		Nelson Smithfield Stockbridge	3 7 1 1	5.7 7.3 5.0 0.5	4.1 8.1	4.8 5.1 5.0	2.0 2.3
2701 2721 2722	Monroe	Sullivan Rochester C. Honeoye Falls(Village) Spencerport V	39 305 21	4.8 1.7 3.2	8.0 1.7 2.7	2.4 1.2 2.1	3.0 2.3 2.6
2723 2724 2725 2726/		Hilton V. 3. Rochester V. Fairport V.	16 14 39	5.4 2.8 2.1 1.8	8.3 3.0 1.5 1.4	2.8 1.9 1.6 1 3	3.1 2.2 2.1
2727 2728 2729		Churchville V. Brockport V. Webster V.	59 5 5 26	2.1 3.3 1.9	2.3 2.8 1.4	1.6 2.6 1.6	2.0 2.2 2.0
2730 2750 2751 2752		Scottsville V. Brighton Chili Clarkson	14 79 34	20.1 2.0 1.9	0.9 24.9 1.3 2.4	1.2 8.4 1.6 1.2	1.9 4.3 2.0 2.8
2753 2754 2755 2756		Gates Greece Hamlin	8 31 138 16	1.7 2.3 1.6 1.1	1.0 2.4 1.5	1.4 1.6 1.2	1.9 2.3 2.2
2757 2758 2759	,	Henrietta Árondequoit Mendon	46 73 69	1.8 1.8 16.4	1.5 1.5 26.7	1.0 1.4 1.3 4.9	1.8 2.0 2.4 4 4
2760		Parma	14 15	2.8 1.9	1.7 1.4	2.2	2.2

APPENDIX 12.9 Personnel Qualifications