## **REMEDIATION SERVICES**

## ENGINEERING REPORT

## PERFORMED ON THE GREYSTON BAKERY SITE

Located at

104 Ashburton Avenue City of Yonkers Westchester County, New York

> December 2003 (Revised February 2004)

Voluntary Cleanup Index: D3-0002-00-09 ESI File: GY99143.50

Prepared By:

Prepared For:

Ecosystems Strategies, Inc. 24 Davis Avenue Poughkeepsie, New York 12603 Greyston Foundation 21 Park Avenue Yonkers, New York 10703

The undersigned has reviewed this <u>Report</u> and certifies to Greyston Foundation that the information provided in this document is accurate as of the date of issuance by this office. Any and all questions or comments, including requests for additional information, should be submitted to the undersigned.

I certify that the <u>Remedial Action Workplan</u> was implemented and that all activities were completed substantially in accordance with the Department-approved <u>Remedial Action Workplan</u> and were personally witnessed by a person under my direct supervision.

Paul H. Ciminello President

on Akins, P.E. est Engineer

Environmental Services and Solutions

## TABLE OF CONTENTS

1.0	INTRO	DUCTION1
	1.1	Purpose
	1.2	Limitations
	1.3	Site Location and Description
	1.4	Previous Environmental Investigations
2.0	SUMM	1ARY OF REMEDIAL ACTIVITIES
	2.1	Summary of Services
	2.2	Excavation and Disposal of Petroleum-Contaminated Soil
		2.2.1 Approved Task (Summary of <u>Workplan</u> )
		2.2.2 Specific Remedial Actions Completed
		2.2.3 Deviations from Workplan
	2.3	Installation/Operation of DNAPL-LNAPL Removal-Monitoring System
		2.3.1 Approved Task (Summary of <u>Workplan</u> )
		2.3.2 Specific Remedial Actions Completed
		2.3.3 Deviations from Workplan
	2.4	Installation of VES System under the On-Site Structure
		2.4.1 Approved Task (Summary of <u>Workplan</u> )
		2.4.2 Specific Remedial Actions Completed
	0.5	2.4.3 Deviations from <u>Workplan</u>
	2.5	Installation of Geomembrane over Non-Paved Portions of the Site
		2.5.1 Approved Task (Summary of <u>Workplan</u> )
		2.5.2 Specific Remedial Actions Completed 2.5.3 Deviations from Workplan
	26	
	2.6	Completion of Air-Quality Testing 2.6.1 Approved Task (Summary of <u>Workplan</u> )
		2.6.1 Approved Task (Summary of <u>Workplan</u> ) 2.6.2 Specific Remedial Actions Completed
		2.6.3 Deviations from Workplan
		2.0.5 Deviations from <u>workplan</u>
3.0	CONC	CLUSIONS AND RECOMMENDATIONS 16
TABL	ES	
Page	12	Table 1: Discharge Stack Sampling
Page	15	Table 2: Summary of Indoor Air-Quality Data
APPE	NDICES	3
А		and Drawings
B		ographs - Dispessel Manifests

- Waste Disposal Manifests Laboratory Results C D

REMEDIATION SERVICES ENGINEERING REPORT – DRAFT GY99143.50R

Environmental Services and Solutions PAGE 1 OF 17 DECEMBER 2003 (REVISED FEBRUARY 2004)

## 1.0 INTRODUCTION

#### 1.1 Purpose

This <u>Remediation Services Engineering Report</u> (Report) summarizes relevant fieldwork (completed by Ecosystems Strategies, Inc. (ESI) and authorized subcontractors) performed to satisfy the <u>Workplan For Site Remediation Activities</u> (Workplan), revised and approved by the NYSDEC October 2000, on the property known as the Greyston Bakery Site, located at 104 Ashburton Avenue, City of Yonkers, Westchester County, New York. The <u>Workplan</u> is incorporated as part of this <u>Report</u> by reference. The work summarized in this <u>Report</u> was performed to address known environmental contamination identified by ESI during previous investigations of the property, conducted from 1999 to the present.

The specific purpose of this <u>Report</u> is to satisfy the requirements set forth in the New York State Department of Environmental Conservation (NYSDEC) Voluntary Cleanup Program and to document all remedial activities performed on the subject property. Remedial activities (see Section 2.0) were deemed necessary based upon information obtained from prior fieldwork, which revealed the presence of petroleum hydrocarbons in localized on-site soils and groundwater. This <u>Report</u>: 1) describes soil excavation, fieldwork methodology, and soil/groundwater sampling procedures; 2) includes discussions of the resulting analytical data from collected soil samples; and, 3) provides conclusions and recommendations drawn from the fieldwork and analytical data.

## 1.2 Limitations

This written analysis is a summary of fieldwork activities conducted at the Greyston Bakery property and is not relevant to any other property. It is a representation of the property analyzed as of the respective dates of fieldwork. This <u>Report</u> cannot be held accountable for activities or events resulting in contamination after the dates of fieldwork.

Services summarized in this <u>Report</u> were performed in accordance with generally accepted practices and established NYSDEC protocols. Unless specifically noted, the findings and conclusions contained herein must be considered not as scientific certainties but as probabilities based on professional judgment.

## 1.3 Site Location and Description

The subject property is an irregularly-shaped parcel having approximately 195 feet of frontage on the northern side of Ashburton Avenue, approximately 216 feet of frontage on the eastern side of Alexander Street, and extending approximately 295 feet northward from Ashburton Avenue (see the Site Location Map included in Appendix A). The subject property is comprised of a single tax lot (City of Yonkers Tax ID: Section 2, Block 2618, Lot 1).

The northern and western portions of the subject property are comprised of unpaved, fenced-in areas that are overgrown with vegetation. The central eastern portion of the property is a fenced-in, macadam-paved parking lot. A one-story, brick structure, occupied by a Metro-North substation is present near the eastern border of the subject property. A concrete retaining wall separates the subject property from adjoining railroad usages to the east. A Fieldwork Map is included in Appendix A of this Report.

REMEDIATION SERVICES ENGINEERING REPORT – DRAFT GY99143.50R

## 1.4 Previous Environmental Investigations

The subject property was historically used as a manufactured gas plant (MGP). Contamination with petroleum products is often associated with MGP sites as the result of raw material storage and manufacturing procedures. According to available information, several structures and three crude oil tanks were present on the subject property until sometime between 1917 and 1942. Historic Sanborn Fire Insurance maps show that in 1942 only a few small structures remained on the western portion of the subject property, and that by 1951 only one structure (later identified as a motor oil storage shed) remained in the southwest corner of the subject property. Local building department records indicated the presence of on-site structures between 1969 and 1979. However, historical maps do not depict any on-site structures (other than the motor oil storage shed) between the years of 1951 and 1989. The present day Metro-North substation is depicted on the 1989 and later historic maps as having been built circa 1987.

The Site has been the subject of several environmental investigations that have accurately and comprehensively documented on-site environmental conditions. Laboratory data from soil, water, and product samples collected from the Site by ESI are provided in the <u>Workplan</u> (note: maps and data tables referenced below are provided in applicable attachments to the <u>Workplan</u>). A summary of previous investigative work is provided below:

 Soil samples collected from multiple depths during fieldwork activities conducted on September 27th and 28th, 1999 indicated the presence of volatile organic compounds (VOCs) and polycyclic aromatic hydrocarbons (PAHs) at levels exceeding NYSDEC guidance values. Both light and dense non-aqueous phase liquids ("LNAPL" and "DNAPL", respectively) were encountered in the northeast corner of the Site, identified as Area 1 on the Site Features Map (see Appendix A of the <u>Workplan</u>). A sample of LNAPL was identified as #4 or #6 oil. VOC and PAH concentrations, identified by sample location, are presented in Data Table 1 and Data Table 2, respectively (see Appendix E of the <u>Workplan</u>).

Shallow soil samples were collected from a depth of 1-3' below grade during subsequent fieldwork activities conducted on April 26, 2000. These samples were analyzed for RCRA metals (arsenic, barium, cadmium, chromium, mercury, lead, selenium, and silver) and cyanide. Laboratory results indicated that cadmium, cyanide, mercury, and silver were either not detected above laboratory detection limits or were detected at concentrations below their respective action levels.

Subsurface soil samples were also collected on April 26, 2000 to determine the presence or absence of PAHs in the unpaved, overgrown area located in the northwest quadrant of the Site. All PAHs, with the exception of anthracene, benzo (g,h,I) perylene, dibenzo (a,h) anthracene, and indeno (1,2,3-cd) pyrene, were detected at concentrations exceeding NYSDEC guidance levels in these samples.

On April 26, 2000, soil borings were extended in the vicinity of boring B-1 (located in the parking area approximately 80 feet from the northeast property corner) for the purpose of delineating the extent of vertical and lateral contamination. PAHs were detected above NYSDEC guidance levels in samples submitted from boring B-1, with the exception of benzo(g,h,i) perylene and indeno (1,2,3-cd) pyrene. Laboratory analysis of samples obtained from various depths within the boring indicated that the concentration of contaminants increased significantly with sample depth for all PAHs detected. A summary of the data obtained from boring B-1 is presented in Table 3 (see Appendix E of the <u>Workplan</u>).

REMEDIATION SERVICES ENGINEERING REPORT – DRAFT GY99143.50R

Environmental Services and Solutions PAGE 3 OF 17 DECEMBER 2003 (REVISED FEBRUARY 2004)

Based on field observations indicating gross contamination, soil samples obtained from borings B-3A, B-4A, B-5A and B-6A, which were collected for the purpose of delineating lateral contamination, were not submitted for laboratory analysis.

2. Prior to ESI being retained to provide environmental services on the Site, groundwater sampling was conducted by Malcolm Pirnie in 1995 (only incomplete results of the Malcolm Pirnie sampling were made available to ESI). Laboratory results from water sampling conducted by ESI on August 31, 1999 confirmed the presence of VOCs and PAHs in on-site groundwater monitoring wells at levels exceeding NYSDEC guidance values. Comparisons of VOC and PAH concentrations between the two sampling rounds are provided in Table 4 (VOCs) and Table 5 (PAHs); both Tables are provided in Appendix E of the Workplan.

On April 26, 2000, one groundwater monitoring well and one product recovery well were installed on the Site. A product sample was collected from the recovery well.

Five of the existing monitoring wells were purged and sampled to determine the presence or absence of chemical and petroleum contamination. All samples collected were submitted for laboratory analysis of dissolved metals and petroleum hydrocarbons. No metals were detected above established NYSDEC guidance levels. Petroleum hydrocarbon data obtained from this sampling event are provided in Table 6 (see Appendix E of the <u>Workplan</u>). Dissolved hydrocarbons were detected in all on-site monitoring wells (except MW-6) at levels exceeding NYSDEC groundwater protection standards.

On May 17, 2000, a Tidal Influence Study (TIS) was conducted on the Site. Groundwater flow was documented to be in a southwesterly direction, toward the Hudson River, located approximately 480 feet west of the Site. Based on the direction of flow, on-site groundwater travels an estimated distance of 3,000 feet before entering the Hudson River. A Groundwater Contour Map, illustrating on-site groundwater flow, is included in the <u>Workplan</u>. Data documented in the TIS indicate that tidal influence on the Site is relatively minor.

3. During the subsurface investigation conducted in September 1999, free product was encountered in boring B-1. The sample collected from B-1 separated into three distinct layers: an upper LNAPL layer, a middle aqueous layer, and a lower DNAPL layer. Laboratory analysis of the upper layer identified the presence of #4 or #6 fuel oil. Laboratory analysis of the lower DNAPL layer determined this product to be a heavy petroleum-related compound. A second sampling event, conducted on April 26, 2000 from the base of the product recovery well (RW-1, located approximately 6 feet northwest of soil boring B-1), confirmed this analysis.

REMEDIATION SERVICES ENGINEERING REPORT – DRAFT GY99143.50R

## 2.0 Summary of Remedial Activities

## 2.1 Summary of Services

ESI conducted the following remedial services on the Site, in accordance with an approved NYSDEC <u>Remedial Action Workplan</u> under the Voluntary Cleanup Agreement:

- Excavation and disposal of approximately 120 tons and 29.4 tons of petroleumcontaminated soils located in the vicinity of the DNAPL collection system on two distinct dates respectively;
- Installation of a DNAPL/LNAPL monitoring/collection well and hydraulic barrier;
- Installation of a Soil Vapor Extraction (SVE) system under the slab of the on-site structure;
- Installation of a geosynthetic clay liner (GCL) Geocomposite liner over all portions of the Site not covered by the building or impervious surfaces; and,
- Collection and analysis of building interior air-quality samples.

Each task is described below, including relevant field observations, analytical data, disposal manifests, and other supporting documentation. Any variations to the approved <u>Workplan</u> are provided herein with justifications for the modifications and any referenced prior NYSDEC approvals for said modifications.

All samples collected for chemical analysis were submitted to York Analytical Laboratories, Inc. (York), a New York State Department of Health certified laboratory (ELAP Certification Number 10854), in accordance with NYSDEC sample collection protocols.

Relevant photographs of remedial activities are provided in Appendix B.

## 2.2 Excavation and Disposal of Petroleum-Contaminated Soil

#### 2.2.1 Approved Task (Summary of Workplan)

The <u>Workplan</u> proposed that any encountered petroleum-contaminated soil in the vicinity of the proposed building slab and in utility trenches be removed from the Site, or be re-used (as appropriate) as on-site fill to be placed under the proposed barrier layer.

Soils subject to off-site disposition were identified in the northeastern portion of the property where the DNAPL remediation system was proposed to be installed. In addition, it was anticipated that excavation to install the storm drainage system in the portion of the Site would encounter soils warranting off-site disposition.

#### 2.2.2 Specific Remedial Actions Completed

During the course of construction activity at the Bakery site it was necessary to excavate soil material from discreet areas throughout the site. Excavated soil material was field screened with a photo-ionization detector (PID) for the presence of VOCs, and all soils exhibiting positive PID readings were stockpiled on and covered with 6 millimeter polyurethane sheeting (poly sheeting).

REMEDIATION SERVICES ENGINEERING REPORT – DRAFT GY99143.50R

Excavation and stockpiling of soil material occurred during September 2002 during installation of hydraulic barrier and again in July 2003 during installation of DNAPL-LNAPL Removal/Monitoring System.

Two off-site soil disposal events were recorded during the on-site construction activity. Approximately 120 tons of petroleum-contaminated soil was removed from the site on September 17, 2002. This soil material was stockpiled during the installation phase of the Hydraulic barrier. The soil was delivered to Clean Earth of Philadelphia for recycling. Soil disposal manifests are included as Appendix C of this document.

The second off-site soil disposal event occurred on July 25, 2003. Approximately 30 tons of petroleum contaminated soil material was removed from the site and delivered to T.T Materials Corporation. This material was generated during the drilling and installation of the DNAPL/LNAPL Recovery/Monitoring Well. Soil disposal manifests are included as Appendix C.

Soils excavated in the footprint of drainage pipes as well as in the footprint of the sewer lines were inspected by ESI personnel using field-screening instruments (i.e., PID). As soils were excavated, ESI personnel inspected the soils and provided recommendations for re-use. PID readings in the southwestern portion of the Site ranged from 0.5 ppm to 50 ppm, consistent with soils remaining in the ground. No sheens were identified in standing water in the utility trenches, indicating an absence of leachable petroleum contamination. Based on these observations, ESI personnel recommend that soils in these areas be re-used as backfill in the trenches or as soil to be placed under the barrier layer.

#### 2.2.3 Deviations from Workplan

No substantive deviations from the approved Workplan are noted.

## 2.3 Installation/Operation of DNAPL-LNAPL Removal/Monitoring System

#### 2.3.1 Approved Task (Summary of Workplan)

#### System Design and Installation

A product recovery system was proposed to be installed and maintained to remove LNAPL and DNAPL from on-site saturated soils located on the eastern central portion of the site. Monitoring wells and borings in other portions of the site did not contain measurable free product; therefore, it was concluded that free product was restricted to the eastern-central portion of the site.

#### LNAPL

The use of a shallow (2'-10') recovery well (EMW-2R) to recover LNAPL via a preferential product-water separator system, operating on an "as-needed" basis to mechanically remove accumulated free-floating product, was proposed. (This system was not utilized, see Section 2.3.2, below).

REMEDIATION SERVICES ENGINEERING REPORT – DRAFT GY99143.50R

#### DNAPL

A funnel and gate system was proposed to recover the DNAPL in the vicinity of boring B-1. Approximately seventy-five (75) linear feet of tight steel sheeting would be installed immediately west and south of the deep recovery well EMW-3. As proposed, the tight sheeting would be installed in a vertical, open "L" configuration such that a 50-foot section of sheeting running roughly north-south and a 25-foot wing of sheeting running generally east-southeast (the "funnel"), would be aligned in an approximate 150-degree angle with an open gap (the "gate") at the confluence of the walls. The gate would be open to the northeast, facing into the groundwater flow.

The sheeting would be installed to approximately 28 feet below grade surface (bgs), such that it penetrated the organic silty-clay layer by several feet. The top of the installed sheeting would be cut approximately three feet bgs so that the upper regime of the groundwater flow would not be affected. A deep (minimum two-foot), wide-bore recovery well (EMW-3) would be installed approximately three feet east of the gate, thus creating the "funnel and gate" system. The base of the wide-bore well, located approximately 25 feet bgs, would act via gravity flow as a collection chamber.

Accumulated product would be monitored via a product thickness gauge located within the chamber and would be removed by connecting a vacuum truck to an extraction pipe exiting the chamber (accessible through a man-way at the surface). The collected DNAPL (and small volumes of groundwater) would be containerized and removed from the site periodically by a certified waste hauler.

The installation sequence would begin with the downgradient monitoring point then proceed to the sheet pile and end with the deep recovery well (EMW-3). Using this sequence, the location and extent of the DNAPL contamination can be confirmed using the downgradient monitoring point and the sheet piling and deep recovery well can be accurately installed between the monitoring point and boring.

#### 2.3.2 Specific Remedial Actions Completed

#### **LNAPL Recovery Well Installation**

No recoverable volume of LNAPL product was observed during trenching activity related to installation of the hydraulic barrier. LNAPL product observed on trench groundwater was consistently measured at less than ¼ inch. Based on the absence of a recoverable volume of LNAPL product, no LNAPL recovery well was installed and all product recovery activities were limited to the installation and operation of the hydraulic-barrier funnel and gate system at the eastern portion of the site.

REMEDIATION SERVICES ENGINEERING REPORT – DRAFT GY99143.50R

Environmental Services and Solutions PAGE 7 OF 17 DECEMBER 2003 (REVISED FEBRUARY 2004)

#### LNAPL Recovery during hydraulic barrier installation trenching activity

During the trenching activity related to installation of the hydraulic barrier, a vacuum truck was utilized on two occasions to remove surface LNAPL sheens. On April 29 and May 17, 2002, the open trench utilized to install the hydraulic barrier was vacuumed in an attempt to recover LNAPL product. Approximately 1,136 gallons and 1,100 gallons, respectively, of a petroleum/water mix were vacuumed from the trench. Although a visible sheen was observed on the water surface, no significant level of LNAPL was recorded. Product recovery was initiated in an attempt to reduce petroleum odors generated during trenching activity and to record any potential LNAPL recharge for future recovery determination. After pumping, no additional LNAPL sheens were observed on the groundwater surface. Slight sheens were observed wicking from the soils on the trench edges. Liquid disposal manifests are included as Appendix C of this document.

#### **DNAPL Recovery Well Installation**

On April 29, 2002, ESI personnel observed the excavation of a trench (50 feet long, 5 feet wide, and approximately 5 feet deep) east of the piling network at the center of the site. This trench was excavated to facilitate the installation of hydraulic barrier. The location of this trench and subsequent barrier is provided in the DNAPL-LNAPL Removal-Monitoring System Drawing included in Appendix A.

Excavated material encountered from the surface to a depth of approximately 3 feet appeared free of contamination. These soils included a large volume of bricks and granite cobbles. The soils 3 to 4 feet bgs exhibited a petroleum odor and staining, but only minimal PID readings (less than 1.0 ppm). Groundwater was encountered at 4 feet bgs. A slight sheen was observed on standing water observed in the excavation. As permitted in the <u>Workplan</u>, excavated materials were stockpiled separately for on-site reuse.

A brick building footing was encountered at approximately 3.5 feet bgs at a distance 40 feet south of the northern end of the trench. Increased levels of overt contamination (odors and staining) were noted in subsurface material encountered south of the footing at 3 to 5 feet bgs. Contaminated materials from this area were segregated and stockpiled on poly sheeting on the northeast corner of the site. These soils were covered with poly sheeting and were disposed of off-site during September 2002.

Free product was observed on the surface of the groundwater in this portion of the excavation and was removed utilizing a vacuum tuck provided by Luzon Environmental Services. Approximately 1,136 gallons were pumped from the excavation. Pumping was intended to skim off the floating product and to assess the timing of returning product.

Constant air-quality monitoring of the excavation and work zone was conducted utilizing a PID. PID readings were recorded continuously and ranged from 0.2 ppm - 5.5 ppm for the duration of the excavation and stockpiling activity. As PID levels approached 5.0 ppm, actions intended to reduce vapor generation were suggested by ESI and were implemented by the construction manager. Plastic sheeting was used to cover the south end of the excavation at the conclusion of work activities to provide a temporary vapor barrier and potential relief from nuisance odors for the duration of excavation activities. At the conclusion of trenching and barrier installation activity, the features were backfilled and nuisance odors diminished. The funnel-gate (DNAPL Recovery Well) is located beneath the asphalt paved area of the site identified by a steel manhole cover adjacent to the east exterior staircase.

REMEDIATION SERVICES ENGINEERING REPORT – DRAFT GY99143.50R

Environmental Services and Solutions PAGE 8 OF 17 DECEMBER 2003 (REVISED FEBRUARY 2004)

Excavation of the elevator pit was also observed on April 29, 2002 at the site. Excavation activity conducted in the center, west border of the site did not reveal any visibly contaminated soils. Groundwater was encountered at approximately four feet. No visibly stained soils or sheens were encountered on groundwater. Field observations and PID readings confirmed the absence of any measurable odors or VOCs in the work zone and excavation. Material encountered in the excavation consisted of brown fill type soils with rocks to approximately 12 inches in diameter. Soils removed from this area were stockpiled adjacent to the excavation for potential re-use on-site.

On July 21, 2003, representatives from ESI/DE personnel inspected the installation of the DNAPL Recovery Well in accordance with specifications outlined in the <u>Workplan</u>. Precision Drilling, Inc. of Stockton, N.J., installed an 18-inch diameter steel recovery well immediately upgradient from the location of the "gate" confluence gap (unimpeded location of DNAPL Recovery well) of the installed steel sheeting. The Recovery Well consisted of an18-inch diameter stainless steel casing pipe equipped with a ten-foot length of .04-inch screen (from approximately 13 to 23 feet bgs). A five-foot stainless steel sump was installed immediately below the well screen (approximately 23 to 28 bgs) with welded cap. A 4-inch diameter stainless steel recovery pipe was installed to the floor of the sump section to allow recovery of accumulating DNAPL utilizing a vacuum truck on a yet-to-be determined basis. DNAPL-LNAPL Removal-Monitoring System drawing is provided as Appendix A.

#### Initial DNAPL Monitoring/Pumping Event (August 12, 2003)

ESI conducted initial field monitoring and pumping events at the DNAPL recovery well on August 12, 2003 and during the week of September 1, 2003. Peak PID readings of 942 ppm and strong petroleum odors were recorded at the interior recovery collar, and a sheen was noted on the water surface within the well, during fieldwork activities on August 12. A 7-foot thick column of DNAPL and water (from approximately 20' bgs) was observed and approximately 400 gallons of an oil/water mix were pumped from the well during this initial pumping/observation event. The well pumping protocol included drawing the water column within the well down to the well screening (visible at approximately 12' bgs) and awaiting re-charge. After complete re-charge (30 to 60 minutes) the well column was again pumped down to the depth of the screening.

#### Subsequent DNAPL Monitoring/Pumping Event (Week of September 1, 2003)

The DNAPL Recovery well was revisited on September 2, 3, 4, and 5, 2003 for pumping and monitoring activity, and to record observations relevant to planning future recovery operations. Observation protocols were identical to those utilized during the August fieldwork event. No product column was detected during the September screenings, with a product level meter. A visible petroleum sheen and odors were observed atop the water column during all screening events. During these events approximately 200 gallons of oil-water mix was pumped from the recovery well. Product was removed utilizing a vacuum truck provided by Enviro-Waste Inc. of Brewster New York. Pumping was suspended after the September 5, 2003 event to re-assess observations and encountered well conditions.

#### Monitoring/Recovery for DNAPL Well

The current rate for the recharge of measurable and recoverable DNAPL product from EMW-3 is unknown. It is recommended that additional monitoring of the well be accomplished utilizing the product level meter to determine if a recoverable volume of DNAPL is accumulating in the well column.

REMEDIATION SERVICES ENGINEERING REPORT – DRAFT GY99143.50R

#### 2.3.3 Deviations from Workplan

The following deviations from the approved Workplan occurred:

- No active LNAPL recovery was installed because no measurable LNAPL has been documented on the Site. LNAPL was removed from the trench during the installation of the hydraulic barrier and the DNAPL recovery well has been monitored for the presence of LNAPL, with no evidence of measurable product documented from well installation (September 2003 to November 2003). Continued monitoring is proposed (see Section 3.0, below).
- The DNAPL barrier was relocated to accommodate a design change in the building.
- The DNAPL barrier was reconfigured to accommodate a subgrade obstruction. During the DNAPL barrier installation process various subsurface obstacles were encountered. These obstacles included large timbers and massive concrete rubble. Refusal was encountered (approximately 12' bgs) in areas immediately southeast of the proposed DNAPL recovery well point (the barrier was to continue at a 135 degree angle toward the southeast). The DNAPL barrier was instead relocated and installed at a right angle from the proposed DNAPL well. The alteration is shown in full detail on the "as built drawing". The barrier is currently the same linear feet but the collection angle is roughly 90 degrees instead of the more oblique 135 degrees originally proposed.
- Removal of accommodated DNAPL has been suspended until this product is of sufficient volume to warrant removal. Continued monitoring is proposed (see Section 3.0, below).

## 2.4 Installation of Vapor Extraction System under the On-Site Structure

#### 2.4.1 Approved Task (Summary of Workplan)

As a supplemental preventative measure, a vapor barrier underlain by a vapor extraction system (VES) would be installed under the proposed foundation for the building. The purpose of this barrier VES would be to eliminate the migration of petroleum hydrocarbon vapors into the building, consistent with good construction practices.

Generally, the barrier VES would consist of a minimum 10-mil plastic liner, properly sealed at the interior joints, underlain by a highly porous substrate (e.g., gravel) containing 2-inch slotted PVC piping. All penetrations through the plastic liner would be properly sealed. The PVC piping would be connected to vertical pipes extending above the roofline. Vacuum pumps (fans) connected to each vertical pipe would ensure the maintenance of an appropriate air-pressure gradient under the building. Venting discharge points would be properly located above the roofline to minimize the likelihood of air emissions impacting building air-quality via roof-mounted air intakes.

Four vapor extraction points (possibly connected to maximize fan efficiency), and six monitoring points (located throughout the building to confirm effective vacuum in the entire subgrade), were proposed.

System start-up and initial testing would occur after the concrete floor had been poured. Extraction wells would be connected to fans and carbon filtration systems, and would be operated for a minimum of 12 hours prior to data and sample collection activities.

REMEDIATION SERVICES ENGINEERING REPORT – DRAFT GY99143.50R

Environmental Services and Solutions PAGE 10 OF 17 DECEMBER 2003 (REVISED FEBRUARY 2004)

Air samples would be collected at each extraction point (before and after carbon filtration) and be analyzed for PAHs using NIOSH Method 5515. (These data would be used to determine the need for any applicable air-quality permits and the need for continued air discharge treatment). Vacuum data would be collected from the six monitoring points.

The <u>Workplan</u> proposed that the VES would be monitored for fourteen (14) calendar days, with monitoring consisting of vacuum measurement at all monitoring points and air-emission screening with a PID. At the end of the monitoring period, one air sample would be collected from the sampling port prior to any air treatment. System effectiveness would be achieved if: 1) field data documented continued maintenance of specified vacuum levels; and, 2) laboratory data documented air discharge PAH levels consistent with previously collected data.

#### 2.4.2 Specific Remedial Actions Completed

A double layer of 6-mil plastic was laid (12-mil total thickness) over all areas of the building's footprint prior to the pouring of the concrete floor. ESI personnel inspected the vapor barrier and documented proper sealing of all penetrations. Extraction points were constructed of four-inch PVC piping.

On April 16, 2003, ESI personnel inspected the installation of the VES and related components, and oversaw the temporary installation of three of the fan units, which were utilized to begin the initial vapor venting process during the construction activities. No positive PID readings were recorded at discharge points or in ambient air. No significant petroleum odors were detected at the fan exhaust points. Slight vacuum was observed at all air intake points throughout the foundation, although quantitative measurements of vacuum were not conducted at that time.

A vacuum test was conducted at the monitoring points on September 23 utilizing a Magnehelic gauge fitted to attach securely to the vacuum monitor point. Two monitor points located in the southeast and southwest portion of the building were suitable for monitoring. The third vacuum monitoring point previously located in the northwest portion of the structure could not be located and may have been lost during construction activity. Monitoring point S.E.-MP (located in the southeast portion of the structure) exhibited approximately 1.6 FPM of vacuum. Monitoring point S.W.-MP (located in the southwest portion of the structure exhibited 1.7 FPM of vacuum. A slight vacuum was detectable at both monitoring points.

ESI personnel conducted air discharge monitoring for PAH's on May 14, 2003. High and low volume air pumps utilizing appropriate sampling tubes were placed at vapor extraction/stack discharge points on the roof of the on-site structure to provide a profile of sub-slab petroleum vapors. Two, high volume air pumps were placed at discharge stacks one and two (SD-1, north-central portion of the roof, and SD-2, eastern portion of roof). Pump failure prevented sampling of the third stack (SD-3, located to the northwest). One low volume air pump (GIL Air III) was also placed at stack discharge one (SD-1 Duplicate) to provide a low-flow control profile. An additional high volume pump was used to collect an ambient background sample at the rooftop, at a point distant from all other vapor extraction/stack discharge points. The high volume pumps were fitted with intake flow regulators and allowed to collect air samples for a period of 24 hours (flow rate of approximately 20 liters per minute).

REMEDIATION SERVICES ENGINEERING REPORT – DRAFT GY99143.50R

Environmental Services and Solutions PAGE 11 OF 17 DECEMBER 2003 (REVISED FEBRUARY 2004)

On October 23, 2003 four of the five discharge stacks were sampled (grab sampled into 3-litre tedlar bags filled at 4 litres/minute.) for VOCs utilizing a low volume air pump (GIL Air III). The fifth stack was inaccessible at the time of sample collection. A PID was utilized by ESI personnel to screen the air during fieldwork activities. No PID readings above 0.0 ppm were noted at any of the active stacks. Samples of the stack discharge were collected into tedlar bags and sent to York Analytical Laboratories for analysis of VOCs utilizing USEPA method TO-14 (all data are summarized in Table 1, below and complete laboratory data packages are provided in Appendix D). Low levels of VOCs are identified at each stack, confirming the effectiveness of the VES system in removing VOCs from the subslab. Individual VOC concentrations are well below NYSDEC short term guidance concentrations at each sample location. Total VOC concentrations are well below discharge levels that would warrant a permit as a pollution emission point; therefore, no NYSDEC air discharge permit is required for this facility.

REMEDIATION SERVICES ENGINEERING REPORT GY99143.50R <u>Environmental Services and Solutions</u> PAGE 12 OF 17

December 2003 (Revised February 2004)

## Table 1:Discharge Stack Samples

(μg /M³)         (μg /M³)         (lbs/day)         (μg /M³)         (μg /M³) <th>Discharge</th>	Discharge
Benzene         1300         11.37         0.0087728         5.74         0.0044288         3.57         0.0027545         ND           Ethylbenzene         54000         4.85         0.0037421         ND	(lbs/day)
o-xylene 4300 6.61 0.0051001 ND ND ND ND ND	ND
	ND
	ND
p&m-xylene   4300   9.7   0.0074843   ND   ND   ND   ND   ND   ND   ND   N	ND
Tetrachloroethylene 1000 ND ND ND ND ND 12.42 0.0095829 15.18	0.0117125
Toluene 37000 49.75 0.0383858 22.2 0.0171289 16.86 0.0130087 14.95	0.011535
Total VOCs         82.28         0.0634851         27.94         0.0215578         32.85         0.0253462	

REMEDIATION SERVICES ENGINEERING REPORT GY99143.50

#### 2.4.3 Deviations from <u>Workplan</u>

The following deviations are noted:

- The Workplan specified two-inch slotted PVC piping; 4-inch PVC piping was installed.
- The <u>Workplan</u> anticipated the installation of 6 monitoring points; only three 3 monitoring points were installed for measuring vacuum. One of the three monitoring points located in the northwest corner of the structure was lost during construction activity.
- The <u>Workplan</u> anticipated the need for carbon filtration. Air-quality testing documented the absence of VOCs and SVOCs in the air discharge at levels warranting treatment.
- The <u>Workplan</u> specified the use of NIOSH Method 5515 to assess levels of SVOCs inside the building and in the air discharged at the roof. Based on subsequent communications with the NYSDEC, USEPA Method TO-13 was substituted.
- No requirement for testing for VOCs is specified in the <u>Workplan</u>. In subsequent communications with the NYSDEC, the Department requested additional air-quality sampling for these compounds using USEPA Method TO-14.

## 2.5 Installation of the Geomembrane over Non-Paved Portions of the Site

#### 2.5.1 Approved Task (Summary of Workplan)

The <u>Workplan</u> proposed the installation of a geosynthetic clay liner (GCL), across all contaminated areas (with slopes less than 25% in grade) not covered by asphalt or buildings, to prohibit potential contact with subsurface contaminated soils. The GCL would be visually inspected during installation.

#### 2.5.2 Specific Remedial Actions Completed

Representatives from Dewkett Engineering, P.C. reviewed delivery, handling, and installation procedures for geosynthetic clay liner (GCL) with the Contractor prior to product delivery. Periodic inspections were conducted from the initial installation date through completion of GCL installation to verify subgrade preparation, material handling, product installation (e.g. – seam overlap, etc.) and cover soil installation were conducted across portions of the site not covered by either the building or asphalt surfaces.

#### 2.5.3 Deviations from Workplan

Cover soil thickness was varied in select portions of the site (e.g. – "run up" alongside curbed parking) to ensure that positive drainage resulted across all portions of the project. Some portions of the GCL were prematurely hydrated due to sudden weather events and these portions of the GCL were trimmed and replaced prior to final cover soil installation.

REMEDIATION SERVICES ENGINEERING REPORT GY99143.50

## 2.6 Completion of Air-Quality Testing

#### 2.6.1 Approved Task (Summary of Workplan)

Post-construction indoor and outdoor air-quality sampling, performed in accordance with established NYSDOH protocols, would be conducted to document on-site air-quality both within the on-site building(s) and the exterior areas. External air-quality would be determined by collecting and analyzing five air samples (two upwind locations and three downwind locations), with both a sample and a duplicate sample collected at one sample location. Internal air would be determined by collecting and analyzing two air samples at locations inside the bakery. Samples will be analyzed for VOCs using USEPA Method TO-14 and for PAHs using USEPA Method TO-13.

#### 2.6.2 Specific Remedial Actions Completed

On September 24, 2003 ESI conducted an interior air-quality sampling event. Interior operating conditions were achieved by this time and interior conditions were deemed acceptable to conduct air-quality monitoring. Three SUMA canisters were placed at locations throughout the interior of the structure and fitted with 2-hour intake regulators. One canister was placed outside the structure to act as a background sample. Prior to the sampling event a thorough interior survey was conducted including screening for VOCs with a PID. No readings above 0.0 ppm were recorded with the PID. No materials were encountered which would influence the outcome of the sampling. All canisters were sent to York analytical laboratories for analysis of VOCs utilizing USEPA Method TO-14

SUMA canister York 509 was placed in the west center of the building interior within the retail and office space. SUMA canister York 526 was placed on the east wall of the oven room at the oven outlet. SUMA canister York 505 was placed in the building center adjacent to the sugar and flour storage silos. SUMA canister York 518 was placed in the northeast corner of the parking lot to provide a background sample. Concentrations of 1,2,4 trimethylbenzene, 1,3,5 trimethylbenzene, ethylbenzene, p-& m- xylenes, styrene and toluene were detected at various concentrations in the interior ambient air samples. No VOCs above minimum detection limits were detected in the background sample. This is unusual for a sample obtained in an urban environment. All interior air samples exhibited concentrations of at least three VOCs which represent an exceedance of background concentrations (collected from the exterior of the structure). Specific mastics, paint and caulk were being used in the interior finish stages of building construction. There is the potential for vapors from these products to have interfered with the collection of representative interior ambient air samples.

Data documented acceptable concentrations of VOCs within the structure. All concentrations are acceptable when compared with OSHA and NIOSH values (which have not been currently updated). Concentrations of the five detected VOCs are well below OSHA and NIOSH guidance values (see enclosed laboratory data in Appendix D).

REMEDIATION SERVICES ENGINEERING REPORT GY99143.50 Environmental Services and Solutions PAGE 15 OF 17 DECEMBER 2003 (REVISED FEBRUARY 2004)

Laboratory analysis of interior air samples was also compared to New York State Department of Health (NYSDOH) interior air-quality data. NYSDOH has established comparison values for certain VOCs in indoor and outdoor air. Comparison with the NYSDOH data indicates that seven VOCs were detected at various concentrations above the 25<sup>th</sup> percentile (NYSDOH comparison value) in at least one of the samples. Two VOCs were detected at concentrations above the 75<sup>th</sup> percentile (NYSDOH comparison value) in six samples. One VOC was detected at concentrations above the 95<sup>th</sup> percentile (NYSDOH comparison value) in three interior air samples. No VOCs were detected in air sample 518 (Background) collected from the rear exterior parking area as a background sample (see the Summary of Indoor Air-Quality table, below).

#### Table 2: Summary of Indoor Air-Quality Data

(Results in **bold** exceed the NYSDOH 75 percentile concentration. All results measured in ppbv.)

Detected Compounds	Action	Levels	1				
	NYSDOH 25 <sup>th</sup> Percentile	NYSDOH 75 <sup>th</sup> Percentile	NYSDOH 95 <sup>th</sup> Percentile	509	526	505	518 Background
styrene	<0.2	<2.4	<2.4	2.0	ND	ND	ND
1,2,4- trimethylbenzene	0.45	1.4	4.1	1.5	1.7	2.0	ND
1,3,5- trimethylbenzene	<0.2	<2.0	<2.0	1.3	ND	1.5	ND
ethylbenzene	0.39	1.1	1.5	ND	ND	1.0	ND
p&m-xylenes	0.51	2.2	4.8	1.3	1.0	2.0	ND
o-xylene	0.44	1.2	1.8	ND	ND	1.1	ND
toluene	1.7	6.7	13	46	17	7.5	ND
Notes: 1. Source: <u>Back</u> <u>by the NYSDC</u> ND= Not Detected.					of VOC	Cs Sam	ipled

#### 2.6.3 Deviations from Workplan

No substantive deviation occurred.

REMEDIATION SERVICES ENGINEERING REPORT GY99143.50

## 3.0 CONCLUSIONS AND RECOMMENDATIONS

This office has completed the services summarized in Section 2.0 for the Greyston Bakery property, located at 104 Ashburton Avenue, City of Yonkers, Westchester County, New York. All work was completed in coordination with New York State Department of Environmental Conservation (NYSDEC) personnel and consistent with the <u>Workplan for Site Remediation</u> <u>Activities (Revised October 2000)</u> (Workplan) prepared by ESI (approved by the NYSDEC, Voluntary Clean-up Index: D3-0002-00-09). Remedial activities outlined in the <u>Workplan</u> were completed in conjunction with construction of the Bakery, conducted between April 2002 and October 2003.

Based on the services provided and data generated, the following conclusions have been made:

1. Petroleum contaminated soils as identified in the Workplan have been either excavated and disposed of off-site at a licensed repository or re-interred on-site under the approved barrier layer.

#### No further remedial work is warranted.

2. The LNAPL recovery system as proposed was determined to be unnecessary at this time due to the absence of recoverable floating product. Site observations continue to document a slight sheen but no recoverable thickness of LNAPL.

#### Continued monitoring is recommended to document any change in site conditions. Monitoring is recommended on a monthly basis with quarterly reports submitted to the owner and the NYSDEC.

3. The DNAPL recovery system has been installed and the initial product within the collection chambers was removed for proper off-site disposition. Initial short-term monitoring has documented a slower-than-expected rate of DNAPL recharge into the collection chamber.

Additional monitoring of the DNAPL recovery system is recommended to document DNAPL concentrations. Specifically it is recommended that a long term (once monthly for a period of one year or bi-weekly for six months) monitoring plan be implemented to observe and record DNAPL trends. In addition to monitoring the DNAPL recovery system two adjacent monitoring wells (MP-1 and MP1-5) should also be monitored quarterly for the presence of DNAPL. Data obtained from all monitoring shall be provided to the NYSDEC.

4. A Vapor Extraction System (VES) was installed under the building. Testing was conducted for both vacuum levels under the slab and the air-quality of the discharge for the roof-top fans. Data confirm the effectiveness of the VES.

No further remediation activities are warranted. An inspection of the system should be conducted on an annual basis with a statement of its condition provided to both the Client and the NYSDEC.

REMEDIATION SERVICES ENGINEERING REPORT GY99143.50


5. A geomembrane has been installed over all portions of the Site not covered by an impervious surface. Oversight of the installation was conducted by a professional engineer, who has concluded that the installation was in conformance with specifications.


No further remedial action is warranted. An inspection of membrane should be conducted on an annual basis with a statement of its condition provided to both the Client and the NYSDEC.


 Indoor and outdoor air-quality testing was conducted to document ambient levels of VOCs and compare these levels to concentrations detected inside the building. Data from air samples inside the building were below OSHA/NIOSH and NYSDOH exposure levels. Stack emissions were below SGC guidance levels.


No further remedial actions is warranted.

APPENDIX A Maps and Drawings









.

2

1

۳

ø

1

**APPENDIX B** 

Photographs



## **PHOTOGRAPHS**

1. Pre building construction. Backfilling of building footprint.



2. VES module installation.



## PHOTOGRAPHS

3. Installation of DNAPL/LNAPL – Removal Monitoring System collection of auger spoils for off-site dispensation.



4. Installation of DNAPL/LNAPL Removal Monitoring System auger casing installation.



## PHOTOGRAPHS

5. 18" diameter DNAPL/LNAPL Removal Monitoring System detail.



6. 4" diameter DNAPL recovery pipe being inserted into DNAPL/LNAPL Removal Monitoring System.


## PHOTOGRAPHS



7. Collection of tedlar samples for VOC analysis VES roof discharge.

## APPENDIX C

## Waste Disposal Manifests



	Gold - Leave with Generator	Pink - Return to Generator	evilangi <mark>eres</mark> Canady ((angores	noitaniteed - etinW
	eteruose bre ent si gniogerot e	and to the best of my knowledge the	above named aski laitetam beman svoda	I hereby certify that the
		5825		SUDNI 1
	- <b>4</b> 3 <b>4</b> 2 <b>8</b> 0 2	▼ 6 ON 0004d	SEDIVAES JATNEMNOAIVNE	NOZUJ Site Name
	ts beviecer asw (sitetam etc.		(iote) amount or portion in cubic yards, gallons, or tru	tshi vilites of si sint
	te bevieten zeu lohoten ein		de la constance	
	n - 1944 (18) (1994 - 1994), and a straight state of a straight state of a straight state of a straight state of	NOILVN		
		BUIADIS JANIA	ejeŭ initianginte	einieißis iekiig
L	wojeg per		evode be	at the generator site list
	이 가 있는 것 같은 것 같	nan evoda edily (hat the above nan	above named material was picked up	김 씨가 가지 않는 것 같아요. 김 씨가 집에 가지 않는 것 같아요. 이 것 같아요. 이 것 같아요.
		200-AC 0015011160 0150	DCE NA 15286	
		Vericle No. / Ficeuse No	0201 XOB 0	
		Driver Name (Print)	:ONI 'OO 710 NOZ(	
		SPORTER C		
			I The provide the second secon	
	<b>) 160</b> 0 (01	velsem enoplex (U:e nou:e); (e)/e)e	mibernen enederen Iani Yilnes yderen	
			0221 NN	
			COMBUSTIBLE LIQUID	
	C. Carlon D. S. Carlon C. Carlon		Description of Wasia	in the second
	Containers Codes	In the None No.		
				5 7 5 100 00 0
		SSOLDDA .	<u> </u>	178 Yeld sseippy
			PRASE DE-ONY - 4 FT	
		BUVION		
	ISEEINYW ELISM	MASAOQUUVZVIIBI	NOIN	
			and the second	1-800-858-8546 E
	914) 262 (416) XA3 162-432 (416) XA3		20 1	80874864 (419) 80-464 (416) XA7
3	ELMSFORD NY 1052			NO STANDOOM
			215	
1990 - 1990 - 1990 - 1990 - 1990 - 1990 - 1990 - 1990 - 1990 - 1990 - 1990 - 1990 - 1990 - 1990 - 1990 - 1990 -				

68721 YN JODINGOOW 0701 XOB

1

	and a second				
가장에 가장한 것이다. 같은 것은 사람이 가장이 가장에 가장이 있는 것이다. 같은 것은 사람이 가장이 가장 것이다.					
CUEVONIN'S OPPLIE FOL	ACNE		, 172.15		
	1 suppressed		1		
Rene			- <u>1</u>		
ADDRESS					
[26] M. C. M.					
			a Asta	р 1 — Кыйс	J. M.
in <mark>herenegenezettetetetetetetetetetetetetetetetete</mark>			ni e un <del>cru</del> nci. E		
international and a second sec					
in produce productions and the second se				l-lar son Bittariera. Na sin sin sin	ali este an estat. Al
					ante de la
				la prime de la comunicación de la c Esta de la comunicación de la comunic	
1997 - Charles Carlos - Carlos					
					j R
			ان معمد . وفي ريدية		
	and fight agents and the second s Second Second				
CELECHWEIDEN			TOMAN		
	e) vediameta esta 45 avia)				
/ di igenious con	o telenter opti is del	SI DR LODAD	officiel by difficiel	16	
				FIREAT	29/84



Dello or far t, permeticat	
300 (X)	

SHP HOUR	
Said Leferance	
TENDROTE MARC	
CCHUTTER	
Contraction Containty	
Carthy April April 19	

12 6066				
ee tee				
935 A29				
COMBONES (C.C.				
wages are				:
Welghe anno				

MERCHIT THERE I PRESSED BY

6.....

배명 이양법 (아양송).

	TT Materials Corp a Cor
Non-l	Hazardous Waste Manifest TT MATERIALS COR
NYDEC	Solid Waste Facility #14M03 Permit Number # 3-1326-00144/00001-0
Generator	Site
Generator Name GREYSTON BANERY	Site Name GREYSTON BALLENY CONST. SI
Generator Address	Site Address 104 AEEXANDER ST.
Address YOMENS N.T.	Address YONKERS NY.
	EJI) Phone #()
	Waste Description
	sel Fuel D Gasoline D Jet Fuel D
#4 Oil 🙀 #6	Oil d' Mineral Oil D Kerosene D
	ted soils are not a hazardous waste nor does it contain PCB's a
ellned by 40 CFR Part 261 or any applic	
JONATHAN A. WAYLAN ESI AS AS	bent For A formath Alight 7,2510
	Art 10/
	EYI TOM Signature
	E 47 TOM Signature Date
	Transporter
ransporter name Nicco TRUCK	Transporter Driver name Nick Lumo
Transporter name Nicco TRUCK	Driver name     Nick Lumo       NY     Veh. No./Lic # 10796772
Transporter name Nicco TRUCK Address 2 CARA DR Pok Contact CARE	Driver name     Nick Lumo       NY     Veh. No./Lic #       Vehicle cert #     34327
Transporter name Nicco MRUCK Addressiz (ARA) DR Pok Contact CHARIS	Driver name     Nick Lumo       NY     Veh. No./Lic #       Vehicle cert #     3A327
ransporter name <u>Nicco TRUCK</u> Address <u>12. (ARA) DR Pok</u> Contact <u>CHARA</u> DR Pok Contact <u>CHARA</u> Phone ( <u>CHAR</u> )	Driver name     Nick Lumo       NY     Veh. No./Lic #     079678       Vehicle cert #     34327
ransporter name <u>Nicco TRUCK</u> Address <u>12. (ARA) DR Pok</u> Contact <u>CRUCIS</u> Phone ( <u>CRUCIS</u> hereby certify that the above named material	Transporter         Driver name       Nick Lunno         NY       Veh. No./Lic #         Veh. No./Lic #       07947R         Vehicle cert #       34327         I hereby certify that the above named material was delivered without incident to the facility listed below:
ransporter name <u>Nicco TRUCK</u> Address <u>iz (ARA) DR Pok</u> Contact <u>Chicis</u> Phone ( <u>MG) (Chicis</u> hereby certify that the above named material res picked up at the generator site listed above: <u>MAN</u> 7.	Transporter         Driver name       Nick Lunno         NY       Veh. No./Lic #         Veh. No./Lic #       07947R         Vehicle cert #       34327         I hereby certify that the above named material was delivered without incident to the facility listed below:
ransporter name <u>Nicco TRUCK</u> Address <u>12 (ARA) DR Pok</u> Contact <u>CHICLS</u> Phone ( <u>MG)</u> hereby certify that the above named material res picked up at the generator site listed above: <u>MAN</u> 7.	Transporter         Driver name       Nick Luimo         NY       Veh. No./Lic #       1079 UTR         Vehicle cert #       34527         I hereby certify that the above named material was delivered without incident to the facility listed below:         25-03 X       NMM       7/25/03
ransporter name <u>Nicco TRUCK</u> Address <u>12 (ARA) DR Pok</u> Contact <u>CHICLS</u> Phone ( <u>MG)</u> hereby certify that the above named material res picked up at the generator site listed above: <u>MAN</u> 7.	Transporter         Driver name       Nick Lumo         NY       Veh. No./Lic #       079407R         Veh. No./Lic #       079407R       Vehicle cert #         Vehicle cert #       3A527         I hereby certify that the above named material was delivered without incident to the facility listed below:         25-03       X         Driver signature       Delivery date
ransporter name <u>Nicco TRUCK</u> Address <u>iz (ARA) DR Pok</u> Contact <u>Chicis</u> Phone ( <u>MG)</u> <u>Signal</u> hereby certify that the above named material res picked up at the generator site listed above: <u>Madu</u> 7.	Transporter         Driver name       Nick Luimo         NY       Veh. No./Lic #       1079 UTR         Vehicle cert #       34527         I hereby certify that the above named material was delivered without incident to the facility listed below:         25-03 X       NMM       7/25/03
Transporter name Nicco MRUCK Addressiz CARel DR Pok Contact CARel DR Pok Contact CARels Phone (MS) Contact CARels Phone (MS) Contact CARels Phone (MS) Contact Pok Phone I CARels Phone (MS) Contact Pok Phone I CARels Phone I CARels	Transporter         Driver name       N:CK Luston         NY       Veh. No./Lic #       1079 kTR         Vehicle cert #       3.4.5.2.7         I hereby certify that the above named material was delivered without incident to the facility listed below:         25-03       X         Driver signature       Delivery date         Facility
Transporter name Nicco TRUCK Address CARA DR Pok Contact CARA DR Pok CARA	Transporter         Driver name       Nick lumbo         NY       Veh. No./Lic # 1079 kTR         Veh. No./Lic # 1079 kTR       Vehicle cert # 34527         I hereby certify that the above named material was delivered without incident to the facility listed below:         25-33       X         Driver signature       Delivery date         Facility       Delivery date         29,17       Tons of the above described non-hazardous virgin
Transporter name Nicco TRUCK Address CARA DR Pok Contact CARA DR Pok CARA	Driver name       Nick Luston         NY       Veh. No./Lic #       1079 LTR         Vehicle cert #       34327         I hereby certify that the above named material was delivered without incident to the facility listed below:         25-03       X         Driver signature       Delivery date         Facility
Transporter name Nicco MCUCK Addressiz CARel DR Pok Contact CHARE'S Phone (MS) hereby certify that the above named material ras picked up at the generator site listed above: MARE Ship Driver signature Ship	Transporter         Driver name       Nick lumbo         NY       Veh. No./Lic # 1079 kTR         Veh. No./Lic # 1079 kTR       Vehicle cert # 34527         I hereby certify that the above named material was delivered without incident to the facility listed below:         25-33       X         Driver signature       Delivery date         Facility       Delivery date         29,17       Tons of the above described non-hazardous virgin
Transporter name <u>Nicco TRUCK</u> Address <u>12 (Area) DR Pok</u> Contact <u>CANES</u> Phone ( <u>MS</u> ) hereby certify that the above named material vas picked up at the generator site listed above: <u>Made 7</u> Driver signature Ship	Transporter         Driver name       Nick Luims         NY       Veh. No./Lic #       1079terre         Vehicle cert #       34527         I hereby certify that the above named material was delivered without incident to the facility listed below:         25-63       X         Driver signature       Driver signature         Delivery date         Pacility         Tons of the above described non-hazardous virgin ed at TT Materials Corp. Solid Waste Facility in Wingdale, NY.
Transporter name Nicco TRUCK Address CARA DR Pok Contact CARA DR Pok Contact CARA DR Pok Phone (MC) hereby certify that the above named material was picked up at the generator site listed above: MAA 7- Driver signature This Manifest document certifies that contaminated petroleum soils was received hereby certify that the above named material	Transporter         Driver name       Nick Luims         NY       Veh. No./Lic #       1079terre         Vehicle cert #       34527         I hereby certify that the above named material was delivered without incident to the facility listed below:         25-63       X         Driver signature       Driver signature         Delivery date         Pacility         Tons of the above described non-hazardous virgin ed at TT Materials Corp. Solid Waste Facility in Wingdale, NY.



# Facility Weight Ticket

	Customer ID # Date of form generation Job ##	
Site Name Site Address Transporter Name	Lorry Stong Bo Yon Pere Ny	Parts.
Generator Name	Coluston C. Found	Labor
Contr Agent Company Contr Agent Address Contr Agent Contact	- Kontan	SCALE WEIGHT PRINTOUT
Scale ID# Truck ID# LB Gross LB Tare LB Net		
Weight Data Weight time	39.47 SED BY	Date 7-25-0
ſ		

i B

	e Facility #14M03 er # 3-1326-00144/00001-0	
enerator		Site
ESTON BANGERY ANT 452-1658 (EST)	Site Address 104	AREXANDER ST.
Waste [	Description	
<b>XI SE #6</b> Oil (		Jet Fuel 🛛 Kerosene 🗅
art 261 or any applicable state	law.	Dete
Tran	sporter	
DR PCK NY	Veh. No./Lic #0	96TR
11433 bove named material arator size flated above:		re named material Int 10 the facility listed below:
The 7-25-03 Shipment date	X Driver signature	1 71251 Delivery dete
Fa	cility	
nent certifies that 29, 4	Tons of the above desc Iterials Corp. Solid Waste I	ribed non-hazardous virg
	PETSTON BANGATION ANT ASZ-1658 (EST) Waste I Diesel Fuel #6 Oil COAL TAR the above designated soils and art 261 or any applicable state LAN EST AS AGENT FOR GREVITON Tran SIGLO TRUCK DR PCK NY NAMES I Shipment data TRAN Shipment data	$ETSTDU< \frac{POUNDATION}{PAHGATION}$ Site NameGRETSTI         Site NameGRETSTI       Site NameGRETSTI         Site AddressOA         Waste Description         Dill         Waste Description         Diesel FuelGasoline         #6 OilMineral Oil         Waste Description         Diesel FuelGasoline         #6 Oil

Ecosystems Strateg	105, 1110.	Environmental Services and So
	APPENDIX D	
		_
	Laboratory Resu	lts



eș I



# **Technical Report**

prepared for

**Ecosystems Strategies, Inc.** 24 Davis Avenue Poughkeepsie, NY 12603 Attention: Jon Kaplan

Report Date: 5/28/2003 Re: Client Project ID: GY99143.40 York Project No.: 03050516 R

CT License No. PH-0723 New York License No. 10854 Mass License No. M-CT106 Rhode Island License No. 93 NJ License No. CT401



DNE RESEARCH DRIVE STAMFORD, CT 06906 (203) 325-1371 FAX (203) 357-0166

Report Date: 5/28/2003 Client Project ID: GY99143.40 York Project No.: 03050516 R

Ecosystems Strategies, Inc. 24 Davis Avenue

Poughkeepsie, NY 12603 Attention: Jon Kaplan

## Purpose and Results

This report contains the analytical data for the sample(s) identified on the attached chain-of-custody received in our laboratory on 05/19/03. The project was identifed as your project "GY99143.40".

The analyses were conducted utilizing appropriate EPA, Standard Methods, and ASTM methods as detailed in the data summary tables .

All samples were received in proper condition meeting the NELAC acceptance requirements for environmental samples except those indicated under the Notes section of this report.

All the analyses met the method and laboratory standard operating procedure requirements except as indicated under the Notes section of this report, or as indicated by any data flags, the meaning of which is explained in the attachment to this report, if applicable.

The results of the analyses, which are all reported on an as-received basis unless otherwise noted, are summarized in the following table(s).

Client Sample ID			SD-1		SD-1 Duplicate LF	
York Sample ID			03050516-01		03050516-02	
Matrix			AIR		AIR	
Parameter	Method	Units	Results	MDL	Results	MD
Polynuclear Aromatic Hydrocarbon	EPA CompTO13	ug/cu.m.				
Acenaphthene			Not detected	0.35	Not detected	1.74
Anthracene			Not detected	0.35	Not detected	1.74
Benzo[a]anthracene			Not detected	0.35	Not detected	1.7
Benzo[a]pyrene			Not detected	0.35	Not detected	1.74
Benzo[b]fluoranthene	_		Not detected	0.35	Not detected	1.74
Benzo[g,h,i]perylene			Not detected	0.35	Not detected	1.74
Benzo[k]fluoranthene			Not detected	0.35	Not detected	1.74
Chrysene			Not detected	0.35	Not detected	1.74
Dibenz[a,h]anthracene			Not detected	0.35	Not detected	1.74
Fluoranthene			Not detected	0.35	Not detected	1.7
Fluorene			Not detected	0.35	Not detected	1.7
lndeno[1.2,3-cd]pyrene			Not detected	0.35	Not detected	1.7
Naphthalene	-		Not detected	0.35	Not detected	1.7
Phenanthrene			Not detected	0.35	Not detected	1.7
Pyrene			Not detected	0.35	Not detected	1.74

# Analysis Results



Client Sample ID			SD-2		Ambient Background	L
York Sample ID			03050516-03		03050516-04	
Matrix			AIR		AIR	
Parameter	Method	Units	Results	MDL	Results	MD
Polynuclear Aromatic Hydrocarbon	EPA CompTO13	ug/cu.m.				
Acenaphthene			Not detected	0.35	Not detected	0.3
Anthracene			Not detected	0.35	Not detected	0.3
Benzo[a]anthracene			Not detected	0.35	Not detected	0.3
Benzo[a]pyrene		_	Not detected	0.35	Not detected	0.3
Benzo[b]fluoranthene			Not detected	0.35	Not detected	0.1
Benzo[g,h,i]perylene			Not detected	0.35	Not detected	0.3
Benzo[k]fluoranthene			Not detected	0.35	Not detected	0.1
Chrysene			Not detected	0.35	Not detected	0.1
Dibenz[a,h]anthracene			Not detected	0.35	Not detected	0.1
Fluoranthene			Not detected	0.35	Not detected	0.1
Fluorene			Not detected	0.35	Not detected	0.3
Indeno[1,2,3-cd]pyrene			Not detected	0.35	Not detected	0.1
Naphthalene			Not detected	0.35	Not detected	0.
Phenanthrene			Not detected	0.35	Not detected	0.
Pyrene			Not detected	0.35	Not detected	0.3

Units Key:

For Waters/Liquids: mg/L = ppm : ug/L = ppb

For Soils/Solids: mg/kg = ppm : ug/kg = ppb

#### Notes for York Project No. 03050516 R

1. The MDL (Minimum Detectable Limit) reported is adjusted for any dilution necessary due to the levels of target and/or non-target analytes and matrix interference.

- 2. Samples are retained for a period of thirty days after submittal of report, unless other arrangements are made.
- 3. York's liability for the above data is limited to the dollar value paid to York for the referenced project.
- 4. This report shall not be reproduced without the written approval of York Analytical Laboratories, Inc.
- 5. All samples were received in proper condition for analysis with proper documentation.
- 6. All analyses conducted met method or Laboratory SOP requirements.
- 7. It is noted that no analyses reported herein were subcontracted to another laboratory.

Approved By: Robert Q. Bradley Managing Director

Date: 5/28/2003

Bottles Received	in Field by al Instructions	Date/Time	San	ıple Relinqu	ished by			Date/Time	•		Received in LAB by	Dale/Time	C
Bottles Relinquish	ed from Lab by	Date/Time	Sarr	iple Relinqu	ished by		ľ	Date/Tim	a	Samp	Received by	' Oate/Time	- 
				JK			Ş	19 m	*-p	Na		19 1230	2
ain-of-Custor						T.E. I							
1. Piter Str.			The second	Hanniski	The second					-	States - 1. States -		
									÷				_
									·				_
													-
									· · · · ·				
	C. C	- CHURCH-U							· · · · · · · · · · · · · · · · · · ·	<u> </u>			_
	AMBIENT B	ACKEROUND	X				X			<u> </u>		1 <u>x</u>	-
	So -2						┨┦		<i>.</i>	- <u> </u>			-
	1	PLUATE-LF)		<u> </u>							·	/***C #1:0417	-
	SD-1		5/1+-5	15/03			X		TO	-13A		1-FILTER SORT	 !
Sample No.	Locat	ion/ID	Date Sa	mpled	S Water	ample Soil		THER	ANA	LYSES F	EQUESTED	Container Description(s	<u>}</u>
	rategies, Inc.	Jonathan A	. Kapian	Pam(	Quenzie	er	G	1991	43.4	<b>D</b>		n A. Kaplan e (Printed)	
<u>Compan</u>		Report			ice To			FIU	ect ID/N	<u>v.</u>	Samples Colle	cted By (Signalure)	-
12031 325-13	7   FAX (203) 3	57-0166	- <u></u>	1-1-1-		<del></del>		Droi	oot ID/N			~	-
ONE I	1480847081 REDCARCH DRIVE 1080, CT 06900				-iel	<u>a </u>	na	111-	01-6	usioc	l <u>v Recor</u> t	- FI 	-
	'ORK			5	क्राजनी ही	7 🛩	A #	~	<i>.</i>		h. Peeck	Page 1 of _	

YORK


# **Technical Report**

prepared for

Ecosystems Strategies, Inc. 24 Davis Avenue Poughkeepsie, NY 12603 Attention: Jonathan A. Kaplan

Report Date: 9/29/2003 Re: Client Project ID: GY99143.40 York Project No.: 03090736

CT License No. PH-0723 New York License No. 19854 Mass. License No. M-CT106 Rhode Island License No. 93 NJ License No. CT401



ONE RESEARCH DRIVE

STAMFORD, CT 06906 (203) 325-1371

FAX (203) 357-0166

Page 1 of 4

#### Report Date: 9/29/2003 Client Project ID: GY99143.40 York Project No.: 03090736

#### Ecosystems Strategies, Inc.

24 Davis Avenue Poughkeepsie, NY 12603 Attention: Jonathan A. Kaplan

#### Purpose and Results

This report contains the analytical data for the sample(s) identified on the attached chain-of-custody received in our laboratory on 09/25/03. The project was identified as your project "GY99143.40".

The analyses were conducted utilizing appropriate EPA, Standard Methods, and ASTM methods as detailed in the data summary tables .

All samples were received in proper condition meeting the NELAC acceptance requirements for environmental samples except those indicated under the Notes section of this report.

All the analyses met the method and laboratory standard operating procedure requirements except as indicated under the Notes section of this report, or as indicated by any data flags, the meaning of which is explained in the attachment to this report, if applicable.

The results of the analyses, which are all reported on an as-received basis unless otherwise noted, are summarized in the following table(s).

Client Sample ID			509		526	
York Sample ID			03090736-01		03090736-02	
Matrix			AIR		AIR	
Parameter	Method	Units .	Results	MDL	Results	MDL
Volatiles(TO-14 list)	EPA TO14	ppbv				•••
1,1,1-Trichloroethane			Not detected	1.0	Not detected	1.0
1,1,2,2-tetrachloroethane			Not detected	1.0	Not detected	0.1
1,1,2-Trichloroethane			Not detected	1.0	Not detected	1.0
1,1-Dichloroethane			Not detected	1.0	Not detected	1.0
1,1-Dichloroethylene			Not detected	1.0	Not detected	1.0
1,2,4-Trichlorobenzene			Not detected	1.0	Not detected	1.0
1,2,4-Trimethylbenzene			1,5	1.0	1.7	1.0
1,2-Dibromoethane			Not detected	1.0	Not detected	1.0
1,2-Dichlorobenzene			Not detected	1.0	Not detected	1.0
1,2-Dichloroethane		1	Not detected	1.0	Not detected	1.0
1,2-Dichloropropane			Not detected	1.0	Not detected	1.0
1,2-Dichlorotetrafluoroethane			Not detected	1.0	Not detected	1.0
1,3,5-Trimethylbenzene	· · · · · · · · · · · · · · · · · · ·		1.3	1.0	Not detected	1.0
1,3-Dichlorobenzene		1	Not detected	1.0	Not detected	1.0
1,4-Dichlorobenzene		1	Not detected	1.0	Not detected	1.0
3-Chloropropene		+	Not detected	1.0	Not detected	1.0

#### Analysis Results



Client Sample ID			509		526	
York Sample ID			03090736-01		03090736-02	
Metrix			AIR		AIR	
Parameter	Method	Units	Results	MDL	Results	MDL
4-Ethyltoluene	-		Not detected	1.0	Not detected	1.0
Benzene			Not detected	1.0	Not detected	1.0
Benzyl Chloride			Not detected	1.0	Not detected	1.0
Bromomethane			Not detected	1.0	Not detected	1.0
Carbon Tetrachloride			Not detected	1.0	Not detected	1.0
Chlorobenzene			Not detected	1,0	Not detected	1.0
Chloroethane			Not detected	1,0	Not detected	1.0
Chloroform			Not detected	1.0	Not detected	1.0
Chloromethane			Not detected	1.0	Not detected	1.0
cis-1,2-Dichloroethylene	<u> </u>		Not detected	1.0	Not detected	1.0
cis-1,3-Dichloropropylene			Not detected	1.0	Not detected	1.0
Dichlorodifluoromethane			Not detected	1.0	Not detected	1.0
Ethylbenzene			Not detected	1.0	Not detected	1.0
Freon-113			Not detected	1.0	Not detected	1.0
Hexachloro-1,3-Butadiene			Not detected	1.0	Not detected	1.0
Methylene Chloride			Not detected	1.0	Not detected	1.0
o-Xylene			Not detected	1.0	Not detected	1.0
p- & m-Xylenes			1.3	1.0	1.0	1.0
Styrene			2.0	1.0	Not detected	1.0
Tetrachlorocthylene			Not detected	1.0	Not detected	1.0
Toluene			46	1.0	17	1.0
trans-1,3-Dichloropropylene		1	Not detected	1.0	Not detected	1.0
Trichloroethylene			Not detected	1.0	Not detected	1.0
Trichlorofluoromethane			Not detected	1.0	Not detected	1.0
Vinyl Chloride			Not detected	1.0	Not detected	1.0

Client Sample ID			505		518 (Background)	
York Sample 1D			03090736-03		03090736-04	
Matrîx			AIR		AIR	
Parametér	Method	Units	Results	MDL	Results	MDL
Volatiles(TO-14 list)	EPA TO14	ppbv			*= 4	
1,1,1-Trichloroethane			Not detected	1.0	Not detected	1.0
1,1,2,2-totrachloroethane			Not detected	1.0	Not detected	1.0
1,1,2-Trichloroethane			Not detected	1.0	Not detected	1.0
1,1-Dichloroethane			Not detected	1.0	Not detected	1.0
1,1-Dichloroethylene			Not detected	1.0	Not detected	1.0
1,2,4-Trichlorobenzene			Not detected	1.0	Not detected	1.0
1,2,4-Trimethylbenzene	1		2.0	1.0	Not detected	1.0
1,2-Dibromoethane		1	Not detected	1.0	Not detected	1.0
1,2-Dichlorobenzene			Not detected	1.0	Not detected	1.0
1,2-Dichloroethane			Not detected	1.0	Not detected	1.0
1,2-Dichloropropane			Not detected	1.0	Not detected	1.0
1,2-Dichlorotetrafluoroethane			Not detected	1.0	Not detected	1.0
1,3,5-Trimethylbenzene			1.5	1.0	Not detected	1.0
1,3-Dichlorobenzene		+	Not detected	1.0	Not detected	1.0
1,4-Dichlorobenzene	<u>+</u>	<u> </u>	Not detected	1.0	Not detected	1.0
3-Chloropropene		1	Not detected	1.0	Not detected	1.0
4-Ethyltoluene			Not detected	1.0	Not detected	1.0
Benzene		<u>+</u> -	Not detected	1.0	Not detected	1.0

YORK

Client Sample (D			505		518 (Background)	
York Sample ID			03090736-03		03090736-04	·
Matrix			AIR	<u> </u>	AIR	
Parameter	Method	Units	Results	MDL	Results	MDL
Benzyl Chloride			Not detected	1.0	Not detected	1.0
Bromomethane			Not detected	1.0	Not detected	1.0
Carbon Tetrachloride			Not detected	1.0	Not detected	1.0
Chlorobenzene			Not detected	1.0	Not detected	1.0
Chloroethane			Not detected	1.0	Not detected	1.0
Chloroform			Not detected	1.0	Not detected	1.0
Chloromethane			Not detected	1.0	Not detected	1.0
cis-1,2-Dichloroethylene			Not detected	1.0	Not detected	1.0
cis-1,3-Dichloropropylene			Nut detected	1.0	Not detected	1.0
Dichlorodifluoromethane			Not detected	1.0	Not detected	1.0
Ethylbenzene			1.0	1.0	Not detected	1.0
Freon-113		1	Not detected	1.0	Not detected	1.0
Hexachloro-1,3-Butadiene		T	Not detected	1.0	Not detected	1.0
Methylene Chloride		-	Not detected	1.0	Not detected	1.0
o-Xylene			1.1	1.0	Not detected	1.0
p- & m-Xylenes			2.0	1.0	Not detected	1.0
Styrene			Not detected	1.0	Not detected	1.0
Tetrachloroethylene		1	Not detected	1.0	Not detected	1.0
Toluene			7.5	1.0	Not detected	1.0
trans-1,3-Dichloropropylene		1	Not detected	1.0	Not detected	1.0
Trichloroethylene		<u>† –                                    </u>	Not detected	1.0	Not detected	1.0
Trichlorofluoromethane			Not detected	1.0	Not detected	1.0
Vinyl Chloride			Not detected	1.0	Not detected	1.0

Units Key:

For Waters/Liquids: mg/L = ppm ; ug/L = ppb

For Soils/Solids: mg/kg = ppm; ug/kg = ppb

#### Notes for York Project No. 03090736

1. The MDL (Minimum Detectable Limit) reported is adjusted for any dilution necessary due to the levels of target and/or non-target analytes and matrix interference.

2. Samples are retained for a period of thirty days after submittal of report, unless other arrangements are made.

3. York's liability for the above data is limited to the dollar value paid to York for the referenced project.

4. This report shall not be reproduced without the written approval of York Analytical Laboratories, Inc.

5. All samples were received in proper condition for analysis with proper documentation.

6. All analyses conducted met method or Laboratory SOP requirements.

7. It is noted that no analyses reported herein were subcontracted to another laboratory.

Approved By:

Robert Q. Br Managing Dire

Date: 9/29/2003

YC	YORK	tics, Inc.			ield	Ch	ain-(	of-Custo	Field Chain-of-Custody Record	Page 1 of
рыс ясислясы Баме Втамерар, СТ Цөррб (203) 325-1371 FAX (203) 357-0166	оне ясексиен Ваче Втангово, СТ (16906 (5-137) FAX (203) 35	ve D6 357-0166						, ,	063	02090136.
Company Name	Name	Report To	To:	Invoice To:	e To:		Proje	Project ID/No.	Constan A Ket	with A Kit-
Ecosystems Strategies, Inc.	tegies, Inc	Jonathan A. Kaplan	Kapian	Barbara Quinn	Quinn	. U	G 499145.40	2. 2	Jonathan	ampres construct of carpinative) Jonathan A. Kaplan Mare 10-100
Sample No.	Loc	Location/ID	Date Sai	Sampled	Sample Water Soil	Sample Matrix r Soil Air D	ых Отнея	ANALYSE	ANALYSES REQUESTED	Name (* 1990) Container Description(s)
	York	509	52.5	5	   	****		70-1	4	SumA
	YORK	526							4	
4	YORK	505						•		
	YORK	S i & (BAtifetauru)	- × (îm							~~×
		v .				<u> </u>				
								·		
									· · ·	
										E
				   		,   				
							6 3 9 3 9 4 9 4 9 4 9 4 9 4 9 4 9 4 9 4 9 4 9 4			
Clidin-or-UDStody Record	у кесога			¥		- ministration of the second s	10:40 A 7 25/09	1 zslos	atment	3/2 1025
Battles Relinquished from Lab by	rd dert mort b	y Dete/Time	Sau 	Sample Relinquished by	thed by	l	Dale/Time		Coll of the American Street	L June
Bottles Received in Fred by	n Field by	Date/Time	San	Sample Relinquished by	hed by	) 	Datè/Time	 	Sample Reconced in LAB by	DataTine
Comments/Special Instructions	I Instruction	suo							Time	
										RUSH(define)

-

and a second second

(




# **Technical Report**

prepared for

Ecosystems Strategies, Inc. 24 Davis Avenue Poughkeepsie, NY 12603 Attention: Jonathan A. Kaplan

Report Date: 10/28/2003 Re: Client Project ID: GY99143.40 York Project No.: 03100754

CT License No. PH-0723 New York License No. 10854 Mass. License No. M-CT106 Rhode Island License No. 93 NJ License No. CT401





ONE RESEARCH DRIVE

STAMFORD, CT 06906

(203) 325-1371

#### Ecosystems Strategies, Inc.

24 Davis Avenue Poughkeepsie, NY 12603 Attention: Jonathan A. Kaplan

### Purpose and Results

This report contains the analytical data for the sample(s) identified on the attached chain-of-custody received in our laboratory on 10/24/03. The project was identified as your project "GY99143.40".

The analyses were conducted utilizing appropriate EPA, Standard Methods, and ASTM methods as detailed in the data summary tables .

All samples were received in proper condition meeting the NELAC acceptance requirements for environmental samples except those indicated under the Notes section of this report.

All the analyses met the method and laboratory standard operating procedure requirements except as indicated under the Notes section of this report, or as indicated by any data flags, the meaning of which is explained in the attachment to this report, if applicable.

The results of the analyses, which are all reported on an as-received basis unless otherwise noted, are summarized in the following table(s).

Client Sample ID			F-1		F-2	
York Sample ID			03100754-01		03100754-02	
Matrix			AIR		AIR	
Parameter	Method	Units	Results	MDL	Results	MDL
Volatiles(TO-14 list)	EPA TO14	ppbv				
1,1,1-Trichloroethane			Not detected	1.0	Not detected	1.0
1,1,2,2-tetrachloroethane		_	Not detected	1.0	Not detected	1.0
1,1,2-Trichloroethane			Not detected	1.0	Not detected	1.0
1,1-Dichloroethane			Not detected	1.0	Not detected	1.0
1,1-Dichloroethylene			Not detected	1.0	Not detected	1.0
1,2,4-Trichlorobenzene			Not detected	1.0	Not detected	1.0
1,2,4-Trimethylbenzene			Not detected	1.0	Not detected	1.0
1,2-Dibromoethane			Not detected	1.0	Not detected	1.0
1,2-Dichlorobenzene			Not detected	1.0	Not detected	1.0
1,2-Dichloroethane			Not detected	1.0	Not detected	1.0
1,2-Dichloropropane			Not detected	1.0	Not detected	1.0
1,2-Dichlorotetrafluoroethane			Not detected	1.0	Not detected	1.0
1,3,5-Trimethylbenzene			Not detected	1.0	Not detected	1.0
1,3-Dichlorobenzene			Not detected	1.0	Not detected	1.0
1,4-Dichlorobenzene			Not detected	1.0	Not detected	1.0
3-Chloropropene			Not detected	1.0	Not detected	1.0

### Analysis Results



Client Sample ID			F-1		F-2	
York Sample ID			03100754-01		03100754-02	
Matrix			AIR		AIR	
Parameter	Method	Units	Results	MDL	Results	MDL
4-Ethyltoluene			Not detected	1.0	Not detected	1.0
Benzene			3.5	1.0	1.5	1.0
Benzyl Chloride			Not detected	1.0	Not detected	1.0
Bromomethane			Not detected	1.0	Not detected	1.0
Carbon Tetrachloride			Not detected	1.0	Not detected	1.0
Chlorobenzene			Not detected	1.0	Not detected	1.0
Chloroethane			Not detected	1.0	Not detected	1.0
Chloroform			Not detected	1.0	Not detected	1.0
Chloromethane	-		Not detected	1.0	Not detected	1.0
cis-1,2-Dichloroethylene			Not detected	1.0	Not detected	1.0
cis-1,3-Dichloropropylene	-		Not detected	1.0	Not detected	1.0
Dichlorodifluoromethane			Not detected	1.0	Not detected	1.0
Ethylbenzene			1.1	1.0	Not detected	1.0
Freon-113			Not detected	1.0	Not detected	1.0
Hexachloro-1,3-Butadiene			Not detected	1.0	Not detected	1.0
Methylene Chloride			Not detected	1.0	Not detected	1.0
o-Xylene			1.5	1.0	Not detected	1.0
p- & m-Xylenes			2.2	1.0	Not detected	1.0
Styrene			Not detected	1.0	Not detected	1.0
Tetrachloroethylene			Not detected	1.0	Not detected	1.0
Toluene			13	1.0	5.8	1.0
trans-1,3-Dichloropropylene			Not detected	1.0	Not detected	1.0
Trichloroethylene			Not detected	1.0	Not detected	1.0
Trichlorofluoromethane			Not detected	1.0	Not detected	1.0
Vinyl Chloride			Not detected	1.0	Not detected	1.0

Ť

•

لتت

Client Sample ID			F-3		<b>F-4</b>	
York Sample ID		_	03100754-03		03100754-04	
Matrix			AIR		AIR	
Parameter	Method	Units	Results	MDL	Results	MDL
Volatiles(TO-14 list)	EPA TO14	ppbv				
1,1,1-Trichloroethane			Not detected	1.0	Not detected	1.0
1,1,2,2-tetrachloroethane			Not detected	1.0	Not detected	1.0
1,1,2-Trichloroethane			Not detected	1.0	Not detected	1.0
1,1-Dichloroethane			Not detected	1.0	Not detected	1.0
1,1-Dichloroethylene			Not detected	1.0	Not detected	1.0
1,2,4-Trichlorobenzene			Not detected	1.0	Not detected	1.0
1,2,4-Trimethylbenzene			Not detected	1.0	Not detected	1.0
1,2-Dibromoethane			Not detected	1.0	Not detected	1.0
1,2-Dichlorobenzene			Not detected	1.0	Not detected	1.0
1,2-Dichloroethane			Not detected	1.0	Not detected	1.0
1,2-Dichloropropane		_	Not detected	1.0	Not detected	1.0
1,2-Dichlorotetrafluoroethane			Not detected	1.0	Not detected	1.0
1,3,5-Trimethylbenzene			Not detected	1.0	Not detected	1.0
1,3-Dichlorobenzene			Not detected	1.0	Not detected	1.0
1,4-Dichlorobenzene			Not detected	1.0	Not detected	1.0
3-Chloropropene			Not detected	1.0	Not detected	1.0
4-Ethyltoluene			Not detected	1.0	Not detected	1.0
Benzene			1.1	1.0	Not detected	1.0

Client Sample ID			F-3		F-4	
York Sample ID	_		03100754-03		03100754-04	
Matrix			AIR		AIR	
Parameter	Method	Units	Results	MDL	Results	MDL
Benzyl Chloride			Not detected	1.0	Not detected	1.0
Bromomethane			Not detected	1.0	Not detected	1.0
Carbon Tetrachloride			Not detected	1.0	Not detected	1.0
Chlorobenzene			Not detected	1.0	Not detected	1.0
Chloroethane			Not detected	1.0	Not detected	1.0
Chloroform			Not detected	1.0	Not detected	1.0
Chloromethane			Not detected	1.0	Not detected	1.0
cis-1,2-Dichloroethylene			Not detected	1.0	Not detected	1.0
cis-1,3-Dichloropropylene			Not detected	1.0	Not detected	1.0
Dichlorodifluoromethane			Not detected	1.0	Not detected	1.0
Ethylbenzene			Not detected	1.0	Not detected	1.0
Freon-113			Not detected	1.0	Not detected	1.0
Hexachloro-1,3-Butadiene			Not detected	1.0	Not detected	1.0
Methylene Chloride			Not detected	1.0	Not detected	1.0
o-Xylene			Not detected	1.0	Not detected	1.0
p- & m-Xylenes			Not detected	1.0	Not detected	1.0
Styrene			Not detected	1.0	Not detected	1.0
Tetrachloroethylene			1.8	1.0	2.2	1.0
Toluene			4.4	1.0	3.9	1.0
trans-1,3-Dichloropropylene			Not detected	1.0	Not detected	1.0
Trichloroethylene			Not detected	1.0	Not detected	1.0
Trichlorofluoromethane			Not detected	1.0	Not detected	1.0
Vinyl Chloride			Not detected	1.0	Not detected	1.0

Units Key: For W

For Waters/Liquids: mg/L = ppm ; ug/L = ppb

For Soils/Solids: mg/kg = ppm ; ug/kg = ppb

#### Notes for York Project No. 03100754

1. The MDL (Minimum Detectable Limit) reported is adjusted for any dilution necessary due to the levels of target and/or non-target analytes and matrix interference.

- 2. Samples are retained for a period of thirty days after submittal of report, unless other arrangements are made.
- 3. York's liability for the above data is limited to the dollar value paid to York for the referenced project.
- 4. This report shall not be reproduced without the written approval of York Analytical Laboratories, Inc.
- 5. All samples were received in proper condition for analysis with proper documentation.
- 6. All analyses conducted met method or Laboratory SOP requirements.
- 7. It is noted that no analyses reported herein were subcontracted to another laboratory.

Approved By: Robert Q. Bradley Managing Director

Date: 10/28/2003

1	BEARCH DRIVI	6	<b>i i</b>	∎ 		<b>-</b>   Cł	nain-	of-C	ustod	v <b>Record</b>	7 Pas	
Company	Company Name Report To		To:	Invoice To:		Τ	Proj	ect ID/N	0.	Jonathon A Kyl		
		1/ f am								ollected By (Signature)		
Ecosystems Strategies, Inc. Jonathan A.		Kapian	aplan Barbara Quinn			Graai	13.40		Jonathan A. Kaplan			
							·	N		e (Printed)		
Sample No.	Loca	tion/ID	Date Sa	mpled		mple Ma Soil Ai	itrix ir OTHER	ANA	LYSES RE	EQUESTED	Container Description(s)	
	F-)	·	10.23	03		X	-	ΤØ	-14		3. LITRE TEDLAN	
	F-2							· · · · ·		•	1. LITRE TEDLAR	
	F-3											
	F-4		X			X					L X	
										· ·		
								· · · · · · · · · · · · · · · · · · ·				
								:				
								<u>-</u>				
4												
hain-of-Custoc	ly Record		$\Box$	Aidu	· · · · · · · · · · · · · · · · · · ·	i	0/24/03	10.00 m			1024 5	
Bottles Relinquished from Lab by Date/Time		Sa	Sample Relinquished by			Date/Time			Received by	Date/Time, 10-24-03/1700		
Bottles Received in Field by Date/Time		Sa	Sample Relinquished by			Date/Time		Sample R	leceived in LAB by	Date/Yime		
omments/Speci	al Instructio	ns								-Around Time StandardRUS	H(define)	