
Monthly Inspection Photograph Log				
<i>Client:</i> NYSDEC		Project Number:	3616206123	
<i>Site Name:</i> Franklin Cle	aners	Site Location:	Rockville Centre, New York	
<i>Photographer:</i> Mike Bates				
Date: April 14, 2022		SPH SAVE		
Photograph: 1		Dry and Wet Chemical Fixed Temperature Seming General Year Manufactured	1 Data	
<i>Direction:</i> Not applicable		MONTHLY INSPECTM DATE BY DA VI V ND		
Description:			- <u>6</u>	
Fire extinguisher inspection tag. Annual maintenance inspection of fire extinguisher completed by Coastal Fire Systems, LLC.				
<i>Photographer:</i> Mike Bates		-	12	
<i>Date:</i> April 14, 2022				
Photograph: 2				
<i>Direction:</i> North				
Description:	-			
Fire extinguisher location inside treatment building.				

Monthly Inspection Photograph Log					
<i>Client:</i> NYSDEC	Project Number:	3616206123			
<i>Site Name:</i> Franklin Clea	aners Site Location:	Rockville Centre, New York			
<i>Photographer:</i> Mike Bates					
<i>Date:</i> April 14, 2022					
Photograph: 3					
<i>Direction:</i> Northeast					
<i>Description:</i> Interior of treatment building.					
<i>Photographer:</i> Mike Bates					
<i>Date:</i> April 14, 2022					
Photograph: 4					
Direction:					
Northwest					
<i>Description:</i> Interior of treatment building.					

L



	Monthly Inspection Photograph Log					
<i>Client:</i> NYSDEC		Project Number:	3616206123			
<i>Site Name:</i> Franklin Cle	aners	Site Location:	Rockville Centre, New York			
<i>Photographer:</i> Mike Bates						
<i>Date:</i> April 14, 2022			ENDER			
Photograph: 7						
<i>Direction:</i> Northwest						
<i>Description:</i> Lawn surrounding treatment building.						
<i>Photographer:</i> Mike Bates						
<i>Date:</i> April 14, 2022						
Photograph: 8						
<i>Direction:</i> Northwest		X A Yora				
<i>Description:</i> Lawn surrounding treatment building.						