

July 23, 2012

New York State Department of Environmental Conservation Division of Environmental Remediation Bureau of Construction Services 625 Broadway, 12th Floor Albany, New York 12233-7013

Attn: Jeffrey E. Trad, P.E.

Environmental Engineer II

Re:

Sonia Road Landfill Remediation Program

Site Registry No. 152013 Post Closure Program

Dear Mr. Trad:

Transmitted herewith is the First Semi-Annual Sonia Road Post Closure Monitoring Report for 2012.

Sincerely, alan B Sancher

Alan R. Sanchez

Vice President of Operations

ARS:wc

cc:

Eric M. Hofmeister, President

Anthony J. Varrichio, P.E., Chief Engineer

Fazil Rahaman, Acting Ground Waster Treatment Plant Operator

File



#### TOWN OF ISLIP SUFFOLK COUNTY, NEW YORK

#### SONIA ROAD LANDFILL WEST BRENTWOOD, NEW YORK SITE REGISTRY NO. 152013



#### POST CLOSURE MONITORING AND MAINTENANCE REPORT

JANUARY THROUGH JUNE 2012

#### POST-CLOSURE MONITORING AND MAINTENANCE REPORT SONIA ROAD LANDFILL BRENTWOOD, NEW YORK

#### TABLE OF CONTENTS

<u>Title</u>	Page
SITE INSPECTION CHECKLIST	1-14
FIELD PHOTOGRAPHS	Appendix A
GAS MIGRATION MONITORING.	Appendix B
WELL CONDITION REPORT	Appendix C
OMNTEC FIELD TEST RESULTS	Appendix D
CARS STORED ON SITE	Appendix E

SITE INSPECTION CHECKLIST

### POST CLOSURE MONITORING AND MAINTENANCE PLAN SONIA ROAD LANDFILL TOWN OF ISLIP

## VEGETATIVE COVER SITE INSPECTION CHECKLIST DATE: 6/7/2012

Semi-Annual Inspection

 $\boxtimes$ 

Storm Inspection

INSPECTION BY: | Fazil Rahaman

PROBLEM											GRID I.D. F
PROBLEM CODE											PROBLEM CODE
											PRIORITY CODE
PRIORITY CODE	Y   N   #	Y   N   #	Y \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	Y   N   #	Y N H	Y   N   #	Y   N   #	Y   N   #	Y   N   #	Y   N   #	PHOTO TAKEN
E Directions:											COMMENTS

	f
Litter	е
Unauthorized dumpling	d
Undesirable growth	С
Dead areas	9
Bare spots	20
PROBLEM CODE	

3 2 1	Immediate Correct within 1 week Correct within 1 month
2	Correct within 1 week
w	Correct within 1 month
4	Correct within 3 months
S	Correct within 6 months
6	Correct within 1 year

List <u>only</u> items or areas of the site where problems or where repairs or rehabilitation deficiencies

are noted or

are required.

If entire site Vegetative Cover is acceptable, check box and sign below.

 $\boxtimes$ 

Signature: Fail Polamon

## POST CLOSURE MONITORING AND MAINTENANCE PLAN SONIA ROAD LANDFILL

# SITE INSPECTION CHECKLIST

SO	SOIL COVER					DATE	DATE: 6/14/2012	
Sen	Semi-Annual Inspection		Storm Ir	Storm Inspection		INSPI	INSPECTION BY: Fazil Rahaman	
	GRID I.D.	PROBLEM CODE	PRIC	PRIORITY CODE	PHOTO TAKEN		COMMENTS	ENTS
B	B5 & F4	Č	5		Y⊠ N □ # 4		See 1st half report.	
					Y   N   #		A THE PASSED AND THE RESERVE OF THE PASSED AND THE	THE THE PROPERTY OF THE PROPER
				and an order	# N H			
					# N N Y			
					Y   N   #			
					Y   N   #			The second secon
					Y   N   #			The second secon
					Y   N   #			
					Y   N   #			
-					Y   N   #			
		PROBLEM CODE	EM CO	DE			PRIORITY CODE	Directions:
a	Erosion damage	mage	æ	Waste by	Waste breakthrough	1	Immediate	List only items or areas of
6	Slope movement	ement	h	Leachate	Leachate breakthrough	2	Correct within 1 week	the site where problems or
c	Ponding (>10x10")	10x10")	٦.	Exposed	Exposed geosynthethics	w	Correct within 1 month	deficiencies are noted or
d	Holes		٠.	Vandalism	im	4	Correct within 3 months	where repairs or
е	Cracking		~	Vector in	Vector infestation	5	Correct within 6 months	rehabilitation are required.
1	Rutting of soils	soils	-			6	Correct within 1 year	
lf ent	ire site Soil C	If entire site Soil Cover is acceptable, check box and sign below.	le, checl	c box and	sign below.			

Signature:

# TOWN OF ISLIP SONIA ROAD LANDFILL LOSURE MONITORING AND MAINTENANCE P

# POST CLOSURE MONITORING AND MAINTENANCE PLAN SITE INSPECTION CHECKLIST

(KIP KAI			DATE:	6/14/2012	
Storm In	spection [		INSPE	CTION BY: Fazil Rahaman	
PRIO	RITY	PHOTO TAKEN	$\dashv$	COMN	COMMENTS
			-		
	Y	□ z	3	onitoring.	
	Y [	Z   #			
	Υ[	Z   #			
	Y[	□ × □ #			
	У[	N			
	]4	N		And the second s	
	] Y	N			
	] Y	Z			
BLEM CO	DE			RIORITY CODE	Directions
60	Waste break	cthrough	-	Immediate	List only items or areas of
h	Leachate br	eakthrough	2	Correct within 1 week	the site where problems or
. 1-	Exposed ge	osynthethics	သ	Correct within 1 month	deficiencies are noted or
-	Damaged ba	askets	4	Correct within 3 months	where repairs or
	Loose ties		5	Correct within 6 months	rehabilitation are required.
-			6	Correct within 1 year	
	Storm In PRIO CO BLEM CO BLEM CO g h h h		FE Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	PHOTO TAKEN  F  PHOTO TAKEN  #	DATE: 6/14/2012   INSPECTION BY:   Fazil Rate   Fazil R

- Signature:

### POST CLOSURE MONITORING AND MAINTENANCE PLAN SITE INSPECTION CHECKLIST SONIA ROAD LANDFILL TOWN OF ISLIP

### ACCESS ROADS

		PHOTO TAKEN	PRIORITY	BLEM	PROBLEM	GRID I.D.
Fazil Rahaman	INSPECTION BY:		Storm Inspection	$\boxtimes$	spection	Semi-Annual Inspection
	DATE: 6/14/2012				AUS	ACCESS NOADS

	PROI	PROBLEM CODE	ODE
B	Potholes	10	Depressions
-		0	- Presononio
ь	Burrow holes	h	
c	Erosion gullies		
р	Loss of stone cover		
е	Exposed geotextile	× '	
f	Obstructions/debris	_	

	PRIORITY CODE
	Immediate
	Correct within 1 week
pu=0.555	Correct within 1 month
-	Correct within 3 months
	Correct within 6 months
	Correct within 1 year

#### Directions:

rehabilitation are required. where repairs or deficiencies are noted or the site where problems or List only items or areas of

If all Access Roads are acceptable, check box and sign below.

 $\boxtimes$ 

Signature: Fail Bhama

# SONIA ROAD LANDFILL POST CLOSURE MONITORING AND MAINTENANCE PLAN SITE INSPECTION CHECKLIST

# ( 1111 ( ) aces

### COLLECTION SASTEM (1 of 4) SITE INSPECTION CHECKLIST DATE: 6/14/2012

STORMWATER CULLECTION STSTEM (1 01 4)	COLLECTI	ONSTRUCTOR		CALL: Vi I II de V a de
Semi-Annual Inspection		Storm Inspection		INSPECTION BY:   Fazil Rahaman
GRID I.D.	BLEM	PRIORITY	PHOTO TAKEN	COMMENTS
Perimeter Swales	CONT			
111 0 112				Monitoring.
H1& H5			<b>∀</b> □ <b>Z X</b> #	TATOTHOUTHE
			Y   N   #	
			Y \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
			Y   N   #	
Diversion Swales				
			Y   N   #	
			Y N H	
			Y □ N □ #	
			Y   N   #	
	PROBI	PROBLEM CODE		PRIORITY CODE Directions:
a Vandalism		g Erosion	Erosion control fabric 1	
1	ment			C
1	lation	i Expose	Exposed geosynthethics 3	Correct within 1 month
d Ponded water	er	j Wash outs		Correct within 3 months
e Vegetative cover	over	k 5677	SETTLEMENT	Correct within 6 months
f Debris/ clogging	ging	-	0	Correct within I year
If Perimeter Swales	and Diversion	Swales are accep	If Perimeter Swales and Diversion Swales are acceptable, check box and sign below.	

Signature:

## SONIA ROAD LANDFILL TOWN OF ISLIP

## POST CLOSURE MONITORING AND MAINTENANCE PLAN SITE INSPECTION CHECKLIST

OIN O I O I EIN		DATE: 6/14/2012	
torm Inspection		NSPECTION BY: Fazil Rahaman	
PRIORITY	PHOTO TAKEN	COMMENTS	ENTS
	Y   N   #		
	Y   N   #		
	Y   N   #		
	Y N H	And the second s	
		Culvert Outlets	
	Y   N   #		
	Y   N   #		
	Y   N   #		
	Y   N   #		
CODE		PRIORITY CONF	
	n control fabric	1 Immediate	List only items or areas of
		C	the site where problems
i Loss of			deficiencies are noted or
-			where repairs or
_		5 Correct within 6 months	rehabilitation are required
1 Woody		C	
way are accept	able, check box and sign below		,
	Storm Inspection  LEM PRIORITY DE CODE  PROBLEM CODE  g Erosion h Loss of i Loss of i Loss of j Soil ero k Soil ero l Woody	Semi-Annual Inspection Storm Inspection PROBLEM CODE  Inlet Structures    PROBLEM CODE   PHOTO TAKEN CODE   PHOTO TAKEN CODE   PHOTO TAKEN	HOTO TAKEN    Culvert Outlets   Fazil Raction

- Signature: Foil Rehaman

### POST CLOSURE MONITORING AND MAINTENANCE PLAN SONIA ROAD LANDFILL TOWN OF ISLIP

# SITE INSPECTION CHECKLIST

	1	
INSP	ECTION BY: Fazil Rahaman	
PHOTO TAKEN	COMMENTS	ENTS
N		
N		
N		
N   #		
X		
N   #		
Z #		
N   #		
	PRIORITY CORE	
round 1	Immediate	List only items or areas of
2	Correct within 1 week	the site where problems or
	Correct within 1 month	deficiencies are noted or
ets	Correct within 3 months	where repairs or
	Correct within 6 months	rehabilitation are required.
ation 6	Correct within 1 year	
PE  PIE  PIE  PIE  PIE  PIE  PIE  PIE	PHOTO TAKEN    N   #	PRIORITY CODE  1 Immediate 2 Correct within 1 wee 3 Correct within 1 mon 4 Correct within 3 mon 5 Correct within 6 mon 6 Correct within 1 year

Signature: Fall Many

## SONIA ROAD LANDFILL TOWN OF ISLIP

## POST CLOSURE MONITORING AND MAINTENANCE PLAN SITE INSPECTION CHECKLIST

STORWING LER COLLECTION STOLEM (4 of 4)	HONDIDIEN	1 (4 01 4)	DALI	DA1E: 6/14/2012	
Semi-Annual Inspection	Storm Inspection	on _	INSP	INSPECTION BY: Fazil Rahaman	1
GRID I.D. PROBLEM CODE	PRIORITY	PHOTO TAKEN		СОМІ	COMMENTS
Drywells					
C5 K	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Y   N   #		Monitoring (Located on access road).	oad).
		Y □ N □ #			
		Y □ N □ #			
		Y □ N □ #			
Culverts/ Outlets					
		Y   N   #			
		Y   N   #			
		Y   N   #			AND THE LOCAL SECTION OF THE PROPERTY OF THE P
		Y   N   #			
PROB	PROBLEM CODE			PRIORITY CODE	Directions:
Vandalism	g Erosic	Erosion control fabric	1	Immediate	List only items or areas of
b Slope movement		Soil erosion around	2	Correct within 1 week	the site where problems o
_	i Expos	Exposed geosynthetics	ß	Correct within 1 month	deficiencies are noted or
d Ponded water	j Dama	Damage/ instability	4	Correct within 3 months	where repairs or
_	k		5	Correct within 6 months	rehabilitation are required
f Debris/ clogging	1		6	Correct within 1 year	

Signature:

### TUWIN OF ISLIT

# SONIA ROAD LANDFILL

## POST CLOSURE MONITORING AND MAINTENANCE PLAN SITE INSPECTION CHECKLIST

RECHARGE BASINS	BASINS			$D_t$	DA1E: 0/14/2012	
Semi-Annual Inspection	nspection 🖂	Storm Inspection		Z	INSPECTION BY: Fazil Rahaman	
GRID I.D.	PROBLEM CODE	PRIORITY	PHOTO TAKEN	AKEN	COMMENTS	, w
Recharge Basin No. 1	sin No. 1					Control of the Contro
A3	Α	8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	Y □ N ⊠ #		Monitoring.	
			Y   N   #			
			Y □ N □ #			
			# N H		*	
Recharge Basin No. 2	in No. 2					
A5	Α		Y □ N ⊠ #		Monitoring.	
			# N H			
			Y   N   #			
			Y   N   #			
PI	PROBLEM CODE		PRI	PRIORITY CODE	Directions:	
a	Vegetation		1 Im	Immediate	List only it	ns or areas of
ь	Sideslope erosion		2 Co	-		problems
c	Sideslope failures		3 Co	Correct within 1		delicies are noted of
d	Silt accumulation			Correct within 3 months		
e	Overflow conditions	ns		Correct within 6 months	ths	•
f	Debris/ clogging		6 Co	Correct within 1 year	year	

### TOWN OF ISLIF

# SONIA ROAD LANDFILL POST CLOSURE MONITORING AND MAINTENANCE PLAN SITE INSPECTION CHECKLIST

MONITORING WELLS	WELLS			DA	DATE: 6/29/2012
Semi-Annual Inspection		Storm Inspection		INS	INSPECTION BY: FPM/H2M
ITEM I.D.	PROBLEM CODE	PRIORITY	PHOTO TAKEN	AKEN	COMMENTS
Landfill Gas Monitoring Wells	nitoring Wells				See well condition reports prepared by Town consultants.
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		Y   N   #		FPM reports attached (January through June).
			Y   N   #		
			Y   N   #		
			# N N Y		
Groundwater Monitoring Wells	onitoring Wells				See well condition reports prepared by Town consultants.
8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		Y   N   #		H2M report attached, (September 2, 2011)
			Y   N   #		
			Y 🗌 N 🗎 #		
			Y □ N □ #		
Dad	PROBLEM CODE		PR	PRIORITY CODE	Directions:
a Da	Damage		1 In	Immediate	only items or areas of t
b Va	Vandalism		2 C	Correct within 1 week	site where problems
c Se	Settlement		3 C	Correct within 1 month	
d Ve	Vector infestation		4 C	Correct within 3 months	
e			5 C	Correct within 6 months	months are required.
f			6 C	Correct within 1 year	year
If all Monitoring Wells are acceptable, check box and sign below.	Vells are acceptal	ble, check box and	l sign below.		

Signature:

### TO AA TA OT WON'TH

# SONIA ROAD LANDFILL POST CLOSURE MONITORING AND MAINTENANCE PLAN SITE INSPECTION CHECKLIST

Semi-Annual Inspection

 $\boxtimes$ 

Storm Inspection

INSPECTION BY: Fazil Rahaman

			T	-	The same of the sa	-	-	-	-	All Designations
		S	2	LFG Collection			13 & 18	11	LFG Recovery Wells/ Valve Vaults	HEM LD.
(aerosa) (a		D	п	LFG Collection Wells (GC1 - GC 16)			K	H	Wells/ Valve Va	CODE
		Monitoring		C 16)		And the second s	ω		ults	CODE
Y   N   #	Y   N   #	Y □ N ⊠ #	Y □ N ⊠ #		Y   N   #	Y   N   #	Y⊠ N □ # 1	Y N X #		PHOTO TAKEN
		Sand comeing up through sump opening					Remove dirt from within.			COMMENTS

	PRO	PROBLEM CODE	Ιğ
- 1	Odor	gG	Broken valve
4	Damage	h	Broken piping
C	Vandalism	1.	Exposed geosynthetics
d	Settlement	j.	Damage/instability
е	Vector infestation	k	Soil erosion around
Ļ,	No vacuum	_	A

1	PRIORITY CODE
-	Immediate
2	Correct within 1 week
ယ	Correct within 1 month
4	Correct within 3 months
5	Correct within 6 months
6	Correct within 1 year

#### Directions:

List only items or areas of the site where problems or deficiencies are noted or where repairs or rehabilitation are required.

If entire site Landfill Gas Collection System is acceptable, check box and sign below.

Signature:

### IUWIN OF ISLLI

### POST CLOSURE MONITORING AND MAINTENANCE PLAN SITE INSPECTION CHECKLIST SONIA ROAD LANDFILL

# LANI

Semi-Annual Inspection	LANDFILL GAS COMPOUND
Storm Inspection	MPOUND
☐ INSPECTION BY:	DATE: 6/28/2012
Fazil Rahaman	

		Condensate Storage		0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	Flare			A&B	Blower Pad/ B	ITEM I.D.	
		rage						K	Blower Pad/ Blower Nos, 104A and 104B	PROBLEM CODE	
	0 0 0 0 0 0 0 0	Liquid Volume = 707						Monitoring	and 104B	PRIORITY CODE	
# N N Y	Y   N   #	= 707 Gallons	Y   N   #	Y□ N □ #		Y   N   #	Y   N   #	Y □ N ⊠ #		PHOTO TAKEN	
	See print out attached.	Alarms: Y 🗌 N 🔯 Test System: OK 🔯 Not Successful 🔲		USED FOR VENTING ONLY				Minor oil leak between pully and housing.		COMMENTS	

PROBLEM CODE
Broken valve
7 7 1 -

	4 Correct within 3 months	2 Correct within 1 week 3 Correct within 1 month	1 Immediate	PRIORITY CODE
months		week		E

#### Directions:

rehabilitation are required. List only items or areas of the site where problems or where repairs or deficiencies are noted or

If entire site Landfill Gas Compound is acceptable, check box and sign below.

- Signature:

## POST CLOSURE MONITORING AND MAINTENANCE PLAN SONIA ROAD LANDFILL

A ( 1141 ( ) A ADMAA

# SITE INSPECTION CHECKLIST

Signature:

## SONIA ROAD LANDFILL

# POST CLOSURE MONITORING AND MAINTENANCE PLAN SITE INSPECTION CHECKLIST


COMMENTS		DATE: 6/28/2012
Semi-Annual Inspection	Storm Inspection	INSPECTION BY: Fazil Rahaman
	ADDITIONAL COMMENTS AS REQUIRED	ENTS AS REQUIRED
All gas collection wells and gas val	All gas collection wells and gas valve vaults inspected this round of inspection.	
Site inspection has been completed, check box and sign below.	ed, check box and sign below.	

Signature:

#### APPENDIX A FIELD PHOTOGRAPHS(9)

6/14/12 GEID I.D. 65

Chyliz CRIDID F4



6/14/12 GRID I.D. 65





Chylis GRID ID FH







PICE IOF3









PACE FOR 3

DOCK D MES

#### APPENDIX B GAS MIGRATION MONITORING REPORTS (6)



FPM Group, Ltd.
FPM Engineering Group, P.C.
formerly Fanning, Phillips and Molnar

CORPORATE HEADQUARTERS 909 Marconi Avenue Ronkonkoma, NY 11779 631/737-6200 Fax 631/737-2410

February 6, 2012

Mr. Alan R. Sanchez Vice President of Operations Islip Resource Recovery Agency 401 Main Street Islip, New York 11751

Re:

Sonia Road Landfill

January 2012 Landfill Gas Monitoring Results

FPM File No. 631-12-16

Dear Mr. Sanchez:

On January 10, 2012, FPM Group (FPM) performed landfill gas monitoring at the above-referenced site. Monitoring was performed with a Landtec GEM 2000 Gas Analyzer.

Oxygen  $(O_2)$  gas and methane  $(CH_4)$  gas were zeroed according to the manufacturer's specifications. The gas analyzer was calibrated with 15 percent (%)  $CH_4$  and 15% carbon dioxide  $(CO_2)$  with the balance nitrogen  $(N_2)$  gas, and 4%  $O_2$  with the balance  $N_2$  gas according to the manufacturer's recommendation prior to sampling.

The landfill gas monitoring results are provided in Table 1. The next landfill gas monitoring event is tentatively scheduled for February 21, 2012. Jim Jahnke will be notified several days in advance of the sampling event.

Should you have any questions, please do not hesitate to call me at (631) 737-6200, ext. 229.

Sincerely,

Jessica K. Bluth Hydrogeologist

JKB:tac Attachment

CC:

Jim Jahnke (via fax) Fazil Rahaman (via fax)

S \lisip RRA\Reports\Sonia-Ltrs\2012 Letters\January docx

#### TABLE 1 LANDFILL GAS MONITORING RESULTS SONIA ROAD LANDFILL ISLIP, NEW YORK

#### **Gas Monitoring Wells**

Location ID	Well Condition	Time & Date	CH₄	CO2	O <sub>2</sub>	Atmospheric Pressure	Relative Pressure
SONIBLOW	OK	1/10/2012 10:58	0.0	0.0	21.4	29.8	-7.97
GM-01	OK	1/10/2012 11:00	0.0	0.4	21.0	29.8	-0.01
GM-02	OK	1/10/2012 11:06	0.0	0.0	20.9	29.8	0.01
GM-03	OK	1/10/2012 11:10	0.0	0.1	21.0	29.8	0.01
GM-04	OK	1/10/2012 11:56	0.0	0.1	21.3	29.8	-0.01
GM-05	OK	1/10/2012 11:13	0.0	0.1	21.1	29.8	0.00
GM-06	OK	1/10/2012 11:16	0.0	0.2	21.1	29.8	-0.02
GM-07	OK	1/10/2012 11:20	0.0	3.1	17.0	29.8	-0.01
GM-08	OK	1/10/2012 11:23	0.0	1.4	19.4	29.8	0.00
GM-09	OK	1/10/2012 11:27	0.0	1.5	20.0	29.8	-0.01
GM-10	OK	1/10/2012 11:30	0.0	0.5	21.2	29.8	0.00
GM-11	OK	1/10/2012 11:33	0.0	0.0	21.7	29.8	-0.01
GM-12	OK	1/10/2012 11:37	0.0	0.2	21.5	29.8	-0.01
GM-13	OK	1/10/2012 11:41	0.0	1.8	19.1	29.8	0.00
GM-14	OK	1/10/2012 11:43	0.0	2.2	18.4	29.8	-0.01
GM-15	OK	1/10/2012 11:46	0.0	0.5	21.1	29.8	-0.02
GM-16	OK	1/10/2012 11:49	0.0	0.7	20.7	29.8	-0.02
GM-17	OK	1/10/2012 11:51	0.0	0.2	21.4	29.8	0.00

#### Notes:

CH<sub>4</sub>, CO<sub>2</sub>, and O<sub>2</sub> are reported in percent gas.

Relative well head pressure is reported in inches of water.

Atmospheric pressure is reported in inches of mercury.

Recovery System Status - On

Weather - Sunny, 45°F



**FPM** group

Engineering and Environmental Science

FPM Group, Ltd.
FPM Engineering Group, P.C.
formerly Fanning, Phillips and Molnar

CORPORATE HEADQUARTERS 909 Marconi Avenue Ronkonkoma. NY 11779 631/737-6200 Fax 631/737-2410

March 6, 2012

Mr. Alan R. Sanchez Vice President of Operations Islip Resource Recovery Agency 401 Main Street Islip, New York 11751

Re:

Sonia Road Landfill

February 2012 Landfill Gas Monitoring Results

FPM File No. 631-12-16

Dear Mr. Sanchez:

On February 23, 2012, FPM Group (FPM) performed landfill gas monitoring at the above-referenced site. Monitoring was performed with a Landtec GEM 2000 Gas Analyzer.

Oxygen  $(O_2)$  gas and methane  $(CH_4)$  gas were zeroed according to the manufacturer's specifications. The gas analyzer was calibrated with 15 percent (%)  $CH_4$  and 15% carbon dioxide  $(CO_2)$  with the balance nitrogen  $(N_2)$  gas, and 4%  $O_2$  with the balance  $N_2$  gas according to the manufacturer's recommendation prior to sampling.

The landfill gas monitoring results are provided in Table 1. The next andfill gas monitoring event is tentatively scheduled for March 14, 2012. Jim Jahnke will be notified several days in advance of the sampling event.

Should you have any questions, please do not hesitate to call me at (631) 737-6200, ext. 229.

Sincerely,

Jessica K. Bluth Hydrogeologist

JKB:tac Attachment

CC:

Jim Jahnke (via fax) Fazil Rahaman (via fax)

S:Visip RRA/Reports/Sonia-Lira/2012 Letters/Fabruary.docx

#### TABLE 1 LANDFILL GAS MONITORING RESULTS SONIA ROAD LANDFILL ISLIP, NEW YORK

#### **Gas Monitoring Wells**

Location ID	Well Condition	Time & Date	CH₄	CO2	O <sub>2</sub>	Atmospheric Pressure	Relative Pressure
SONIBLOW	OK	2/23/2012 11:10	10.3	15.7	4.2	29.4	-15.94
GM-01	OK	2/23/2012 11:12	0.0	8.0	19.7	29.4	0.02
GM-02	OK	2/23/2012 11:15	0.0	1.5	19.5	29.4	-0.01
GM-03	OK	2/23/2012 11:18	0.0	0.0	20.9	29.4	-0.10
GM-04	OK	2/23/2012 12:04	0.0	0.4	20.3	29.4	0.06
GM-05	OK	2/23/2012 11:23	0.0	0.0	21.0_	29.4	-0.24
GM-06	OK	2/23/2012 11:26	0.0	0.4	20.0	29.3	-0.11
GM-07	OK	2/23/2012 11:28	0.0	6.4	10.4	29.3	-0.14
GM-08	ОК	2/23/2012 11:32	0.0	3.3	15.1	29.3	-0.10
GM-09	OK	2/23/2012 11:35	0.0	1.6	18.7	29.4	-0.09
GM-10	OK	2/23/2012 11:37	0.0	0.7	20.5	29.4	-0.09
GM-11	OK	2/23/2012 11:40	0.0	1.8	19.4	29.4	-0.01
GM-12	ОК	2/23/2012 11:44	0.0	0.5	20.5	29.4	-0.04
GM-13	OK	2/23/2012 11:47	0.0	1.9	18.0	29.3	-0.02
GM-14	OK	2/23/2012 11:50	0.0	0.1	21.2	29.3	-0.05
GM-15	OK	2/23/2012 11:52	0.0	0.8	19.9	29.4	-0.03
GM-16	OK	2/23/2012 11:55	0.0	1.4	18.9	29.3	-0.09
GM-17	ОК	2/23/2012 11:59	0.0	0.5	20.6	29.4	0.19

#### Notes:

CH<sub>4</sub>, CO<sub>2</sub>, and O<sub>2</sub> are reported in percent gas. Relative well head pressure is reported in inches of water. Atmospheric pressure is reported in inches of mercury. Recovery System Status - On Weather - Mostly sunny, 55°F





FPM Group, Ltd.
FPM Engineering Group, P.C.
formerly Fanning, Phillips and Molnar

CORPORATE HEADQUARTERS 909 Marconi Avenue Ronkonkoma, NY 11779 631/737-6200 Fax 631/737-2410

April 13, 2012

Mr. Alan R. Sanchez Vice President of Operations Islip Resource Recovery Agency 401 Main Street Islip, New York 11751

Re

Sonia Road Landfill

March 2012 Landfill Gas Monitoring Results

FPM File No. 631-12-16

Dear Mr. Sanchez:

On March 7, 2012, FPM Group (FPM) performed landfill gas monitoring at the above-referenced site. Monitoring was performed with a Landtec GEM 2000 Gas Analyzer.

Oxygen  $(O_2)$  gas and methane  $(CH_4)$  gas were zeroed according to the manufacturer's specifications. The gas analyzer was calibrated with 15 percent (%)  $CH_4$  and 15% carbon dioxide  $(CO_2)$  with the balance nitrogen  $(N_2)$  gas, and 4%  $O_2$  with the balance  $N_2$  gas according to the manufacturer's recommendation prior to sampling.

The landfill gas monitoring results are provided in Table 1. The next landfill gas monitoring event is tentatively scheduled for April 23, 2012. Jim Jahnke will be notified several days in advance of the sampling event.

Should you have any questions, please do not hesitate to call me at (631) 737-6200, ext. 229.

Singerely.

Jessida K. Bluth

Hydrogeologist

JKB:tac Attachment

CC:

Jim Jahnke (via fax)

Fazil Rahaman (via fax)

S:\ielip RRA\Reporta\Sonle-Lira\2012 Letters\March.docx

#### TABLE 1 LANDFILL GAS MONITORING RESULTS SONIA ROAD LANDFILL ISLIP, NEW YORK

#### Gas Monitoring Wells

Location ID	Well Condition	Time & Date	CH4	CO2	O <sub>2</sub>	Atmospheric Pressure	Relative Pressure
SONIBLOW	OK	3/7/2012 11:11	8.6	13.4	7.0	30.4	-35.47
GM-01	OK	3/7/2012 11:13	0.0	0.7	20.3	30.4	0.00
GM-02	OK	3/7/2012 10:19	0.0	1.4	19.6	30.4	0.00
GM-03	OK	3/7/2012 10:22	0.0	0.2	20.8	30.4	0.00
GM-04	OK	3/7/2012 11:20	0.0	0.2	20.3	30.4	-0.05
GM-05	QK	3/7/2012 10:26	0.0	4.3	12.4	30.4	0.01
GM-06	OK	3/7/2012 10:29	0.0	0.3	20.9	30.4	0.00
GM-07	OK	3/7/2012 10:31	0.0	2.7	16.5	30.4	0.04
GM-08	OK	3/7/2012 10:34	0.0	1.0	20.1	30.4	0.00
GM-09	OK	3/7/2012 10:36	0.0	2.1	19.2	30.4	0.02
GM-10	OK	3/7/2012 10:39	0.0	0.7	21.0	30.4	0.00
GM-11	OK	3/7/2012 10:48	0.0	1.5	20.0	30.4	-0.01
GM-12	OK	3/7/2012 10:51	0.0	0.3	21.1	30.4	-0.02
GM-13	OK	3/7/2012 10:54	0.0	1.4	19.5	30.4	-0.01
GM-14	OK	3/7/2012 10:57	0.0	2.6	17.4	30.4	-0.01
GM-15	OK	3/7/2012 11:00	0.0	0.6	20.7	30.4	0.00
GM-16	OK	3/7/2012 11:02	0.0	1.2	20.0	30.4	-0.07
GM-17	OK	3/7/2012 11:06	0.0	0.5	20.8	30.4	0.05

#### Notes:

 ${\rm CH_4,\ CO_2,\ and\ O_2}$  are reported in percent gas. Relative well head pressure is reported in inches of water. Atmospheric pressure is reported in inches of mercury. Recovery System Status - On Weather - Partly cloudy,  $50^{\circ}{\rm F}$ 



FPM group

Engineering and Environmental Science

FPM Group, Ltd.
FPM Engineering Group, P.C.
formerly Fanning, Phillips and Molnar

CORPORATE HEADQUARTERS 909 Marconi Avenuo Ronkonkoma, NY 11779 631/737-6200 Fax 631/737-2410

May 7, 2012

Mr. Alan R. Sanchez Vice President of Operations Islip Resource Recovery Agency 401 Main Street Islip, New York 11751

Re:

Sonia Road Landfill

April 2012 Landfill Gas Monitoring Results

FPM File No. 631-12-16

Dear Mr. Sanchez:

On April 13, 2012, FPM Group (FPM) performed landfill gas monitoring at the above-referenced site. Monitoring was performed with a Landtec GEM 2000 Gas Analyzer.

Oxygen  $(O_2)$  gas and methane  $(CH_4)$  gas were zeroed according to the manufacturer's specifications. The gas analyzer was calibrated with 15 percent (%)  $CH_4$  and 15% carbon dioxide  $(CO_2)$  with the balance nitrogen  $(N_2)$  gas, and 4%  $O_2$  with the balance  $N_2$  gas according to the manufacturer's recommendation prior to sampling.

The landfill gas monitoring results are provided in Table 1. The next landfill gas monitoring event is tentatively scheduled for May 23, 2012. Jim Jahnke will be notified several days in advance of the sampling event.

Should you have any questions, please do not hesitate to call me at (631) 737-6200, ext. 229.

Sincerely,

Jessida K. Bluth

Hydr#geologist

JKB:tac Attachment

CC:

Jim Jahnke (via fax)

Fazil Rahaman (via fax)

S:\latic RRA\Reporte\Senia-Ltrx\2012 Lotters\April.docx

#### TABLE 1 LANDFILL GAS MONITORING RESULTS SONIA ROAD LANDFILL ISLIP, NEW YORK

#### **Gas Monitoring Wells**

Location ID	Well Condition	Time & Date	CH4	CO2	Oz	Atmospheric Pressure	Relative Pressure
SONIBLOW	OK	4/13/2012 10:01	6.8	12.1	8.0	30.1	-35.37
GM-01	OK	4/13/2012 9:59	0.0	1.1	19.8	30.1	0.00
GM-02	OK	4/13/2012 10:04	0.0	2.4	18.4	30.1	0.00
GM-03	ΟK	4/13/2012 10:07	0.0	0.0	20.6	30.1	-0.04
GM-04	OK	4/13/2012 11:02	0.0	0.1	20.3	30.1	-0.08
GM-05	OK	4/13/2012 10:10	0.0	0.0	20.8	30.1	-0.21
GM-06	OK	4/13/2012 10:12	0.0	0.6	20.2	30.1	-0.08
GM-07	OK	4/13/2012 10:15	0.0	1.7	19.0	30.1	-0.05
GM-08	OK	4/13/2012 10:17	0.0	1.1	19.6	30.1	-0.10
GM-09	OK	4/13/2012 10:20	0.0	3.4	16.8	30.1	-0.09
GM-10	OK	4/13/2012 10:22	0.0	8.0	20.3	30.1	-0.06
GM-11	OK	4/13/2012 10:26	0.0	1.0	20.0	30.1	-0.03
GM-12	OK	4/13/2012 10:29	0.0	0.2	20.9	30.1	-0.12
GM-13	OK	4/13/2012 10:33	0.0	1.0	20.0	30.1	-0.06
GM-14	OK	4/13/2012 10:36	0.0	1.0	19.9	30.1	-0.09
GM-15	OK	4/13/2012 10:38	0.0	0.9	20.0	30.1	-0.08
GM-16	OK	4/13/2012 10:41	0.0	1.1	19.9	30.1	-0.16
GM-17	OK	4/13/2012 10:43	0.0	0.6	20.4	30.1	-0.12

#### Notes:

CH<sub>4</sub>, CO<sub>2</sub>, and O<sub>2</sub> are reported in percent gas.
Relative well head pressure is reported in inches of water.
Atmospheric pressure is reported in inches of mercury.
Recovery System Status - On
Weather - Partly cloudy, 57°F





FPM Group, Ltd.
FPM Engineering Group, P.C.
formerly Fanning, Phillips and Molnar

CORPORATE HEADOUARTERS 90S.Marconi Avenue Flonkonkoma, NY 11779 -631/737-6200 Fax 631/737-2410

June 11, 2012

Mr. Alan R. Sanchez Vice President of Operations Islip Resource Recovery Agency 401 Main Street Islip, New York 11751

Re:

Sonia Road Landfill

May 2012 Landfill Gas Monitoring Results

FPM File No. 631-12-16

Dear Mr. Sanchez:

On May 30, 2012, FPM Group (FPM) performed landfill gas monitoring at the above-referenced site. Monitoring was performed with a Landtec GEM 2000 Gas Analyzer.

Oxygen  $(O_2)$  gas and methane  $(CH_4)$  gas were zeroed according to the manufacturer's specifications. The gas analyzer was calibrated with 15 percent (%)  $CH_4$  and 15% carbon dioxide  $(CO_2)$  with the balance nitrogen  $(N_2)$  gas, and 4%  $O_2$  with the balance  $N_2$  gas according to the manufacturer's recommendation prior to sampling.

The landfill gas monitoring results are provided in Table 1. The next landfill gas monitoring event is tentatively scheduled for June 25, 2012. Jim Jahnke will be motified several days in advance of the sampling event.

Should you have any questions, please do not hesitate to call me at (631) 737-6200, ext. 229.

Sincerely

Jessica K. Bluth Hydrogeologist

12 K/B

JKB:tac Attachment

CC:

Jim Jahnke (via email)

Fazil Rahaman (via email)

S Vislip RRA\Reports\Spria-Ltrs\2012 Letters\May.docx

#### TABLE 1 LANDFILL GAS MONITORING RESULTS SONIA ROAD LANDFILL ISLIP, NEW YORK

#### Gas Monitoring Wells

Location ID	Well Condition	Time & Date	CH₄	CO <sub>2</sub>	O <sub>2</sub>	Atmospheric Pressure	Relative Pressure
SONIBLOW	OK	5/30/2012 11:21	9.8	14.9	6.3	29.6	-34.98
GM-01	OK	5/30/2012 10:26	0.0	1.5	19.0	29.7	-0.01
GM-02	OK	5/30/2012 10:29	0.0	4.5	15.2	29.7	-0.05
GM-03	OK	5/30/2012 10:32	0.0	0.1	20.7	29.7	0.00
GM-04	OK	5/30/2012 11:25	0.0	1.1	18.7	29.7	-0.04
GM-05	OK	5/30/2012 10:45	0.0	0.0	20.7	29.7	-0.17
GM-06	OK	5/30/2012 10:47	0.0	1.1	19.8	29.6	-0.10
GM-07	OK	5/30/2012 10:50	0.0	3.6	16.2	29.6	-0.12
GM-08	OK	5/30/2012 10:54	0.0	2.0	18.3	29.6	-0.11
GM-09	OK	5/30/2012 10:56	0.0	2.0	18.2	29.6	-0.13
GM-10	OK	5/30/2012 10:59	0.0	1.3	19.5	29.6	-0.07
GM-11	OK	5/30/2012 11:02	0.0	2.1	18.5	29.6	0.00
GM-12	OK	5/30/2012 11:04	0.0	0.7	19.9	29.7	→0.05
GM-13	OK	5/30/2012 11:07	0.0	2.2	18.4	29.7	-0.03
GM-14	OK	5/30/2012 11:10	0.0	2.9	17.5	29.6	-0.06
GM-15	OK	5/30/2012 11:12	0.0	1.8	18.9	29.7	-0.05
GM-16	ОК	5/30/2012 11:15	0.0	1.8	18.6	29.6	-0.13
GM-17	OK	5/30/2012 11:17	0.0	1.4	19.4	29.6	-0.09

#### Notes:

 ${\rm CH_4,\ CO_2,\ and\ O_2}$  are reported in percent gas. Relative well head pressure is reported in inches of water. Atmospheric pressure is reported in inches of mercury. Recovery System Status - On Weather - Overcast,  $74\,^{\circ}{\rm F}$ 





FPM Group, Ltd. FPM Engineering Group, P.C. formerly Fanning, Phillips and Molnar

CORPORATE HEADQUARTERS 909 Marconi Avenue Ronkonkoma, NY 11779 631/737-6200 Fax 631/737-2410

July 9, 2012

Mr. Alan R. Sanchez Vice President of Operations Islip Resource Recovery Agency 401 Main Street Islip, New York 11751

Re:

Sonia Road Landfill

June 2012 Landfill Gas Monitoring Results

FPM File No. 631-12-16

Dear Mr. Sanchez:

On June 22, 2012, FPM Group (FPM) performed landfill gas monitoring at the above-referenced site. Monitoring was performed with a Landtec GEM 2000 Gas Analyzer.

Oxygen (O2) gas and methane (CH4) gas were zeroed according to the manufacturer's specifications. The gas analyzer was calibrated with 15 percent (%) CH<sub>4</sub> and 15% carbon dioxide (CO<sub>2</sub>) with the balance nitrogen (N<sub>2</sub>) gas, and 4% O<sub>2</sub> with the balance N<sub>2</sub> gas according to the manufacturer's recommendation prior to sampling.

The landfill gas monitoring results are provided in Table 1. The next landfill gas monitoring event is tentatively scheduled for July 26, 2012. Jim Jahnke will be notified several days in advance of the sampling event.

Should you have any questions, please do not hesitate to call me at (631) \( \pi 37-6200, \text{ ext. 229.} \)

Sincerely.

Jessica K. Bluth

Hydrogeologist

JKB:tac Attachment

CC:

Jim Jahnke (via email)

Fazil Rahaman (via email)

S:\lslp RRA\Reports\Sonia-Ltrs\2012 Letters\June docx

#### TABLE 1 LANDFILL GAS MONITORING RESULTS SONIA ROAD LANDFILL ISLIP, NEW YORK

#### Gas Monitoring Wells

Location ID	Well Condition	Time & Date	CH₄	CO <sub>2</sub>	O <sub>2</sub>	Atmospheric Pressure	Relative
SONIBLOW	OK	6/22/2012 11:30	10.2	15.1	5.4	29.7	-14.42
GM-01	OK	6/22/2012 11:32	0.0	1.8	17.7	29.7	0:01
GM-02	OK	6/22/2012 11:36	0.0	5.4	12.8	29.7	-0.03
GM-03	OK	6/22/2012 11:39	0.0	0.0	19.8	29.7	-0.06
GM-04	OK	6/22/2012 13:03	0.0	1.2	17.3	29.7	-0.01
GM-05	OK	6/22/2012 11:47	0.0	0.0	19.8	29.7	-D.21
GM-06	OK	6/22/2012 11:50	0.0	1.5	18.0	29.7	-0.10
GM-07	OK	6/22/2012 11:53	0.0	5.9	10.9	29.7	→0.12
GM-08	OK	6/22/2012 12:28	0.0	2.6	16.3	29.7	-0.06
GM-09	OK	6/22/2012 12:31	0.0	2.2	16.8	29.7	-0.05
GM-10	OK	6/22/2012 12:34	0.0	1.4	18.6	29.7	-0.02
GM-11	OK	6/22/2012 12:39	0.0	2.3	17.6	29.7	0.00
GM-12	OK	6/22/2012 12:43	0.0	0.9	18.8	29.7	-0.02
GM-13	OK	6/22/2012 12:45	0.0	3.1	16.4	29.7	0.00
GM-14	OK	6/22/2012 12:48	0.0	3.0	16.1	29.7	-0.02
GM-15	OK	6/22/2012 12:51	0.0	2.6	16.8	29.7	-0:02
GM-16	OK	6/22/2012 12:55	0.0	1.8	17.4	29.7	-0:05
GM-17	OK	6/22/2012 12:58	0.0	1.9	17.8	29.7	-0:05

#### Notes:

CH<sub>4</sub>, CO<sub>2</sub>, and O<sub>2</sub> are reported in percent gas.

Relative well head pressure is reported in inches of water.

Atmospheric pressure is reported in inches of mercury.

Recovery System Status - On

Weather - Partly cloudy, 92°F



#### APPENDIX C GROUNDWATER WELL CONDITION REPORT



#### architects + eingineers

175 Pinelawn Road, Stee 308 Melville, NY 11747

tel 631.756.8000 fax 631.393.6322

September 2, 2011

Anthony Varrichio, P.E.,, Chief Engineer Islip Resource Recovery Agency 401 Main Street Islip, New York 11751

Re:

Well Condition Rieport, 2011 Report Sonia Road Landfill H2M No. ISLP10(1)1

Dear Mr. Varrichio:

The purpose of this letter is to provide the 2011 well inspection summary report for the 35 monitoring wells at the Sonia Road Landfill. The completed well inspection checklists are enclosed. The well inspection did not reveal any significant damage, security issues or other concerns related to the sampled monitoring wells that would require corrective action, except at 10 wells. The following concerns were noted during the inspection:

- The rubber gaskeet on the vault for monitoring well MW-06I was damaged.
- The PVC casings; for monitoring wells MW-14I and MW-14D appeared to have been cut, and may need to be resurveyed.
- The manhole cover for monitoring well MW-13S was missing.
- The manhole cower and J-plug were not fitting completely flush on monitoring well MW-1D.
- The locks on wellis MW-03D, MW-11D, MW-11I, MW-11S, and MW-13I are missing.

If you have any questioms or require any additional information, please call me at (631) 756-8000, extension 1484.

Very truly yours,

HOLZMACHER, McLENIDON & MURRELL, P.C.

Christopher J. Flyan Senior Project Manager

**Enclosures** 

X:\ISLP (Town of Islim) - 10560\2010\Sonia Rd 2010\Final Report\2011\2011 Well Condition Report

# Table 1 WELL INSPECTION SUMMARY – 2011 SONIA ROAD LANDFILL

Seal   Covert/Statuspipe   Lock Intact?   Casing Alignment   Survey Point	Yes	Unmarked	Straight	Yes	Intact	Intact	MW-14D
Seal   Coveriousupppe   Lock Intact?   Casing Alignment   Survey Point	Yes	Marked	Straight Hed	Vec	Intact	Intact	MW-141
Seal   Covernstandpipe   Lock Intact?   Casing Alignment   Survey Point	Yes	Marked	Slightly Tilled	Yes	Intact	Intact	MW-14S
Seal   Covernstaupppe   Lock Intact?   Casing Alignment   Survey Point	Yes	Marked	Straight	Yes	Intact	Intact	MW-13D
Seal   Coeff Shaupppe   Lock Intact?   Casing Alignment   Survey Point	Yes	DONIEN	Straight	No	Intact	Intact	MW-131
Seal   Covert/Shaudpipe   Lock Intact?   Casing Alignment   Survey Point	Yes	Marked	Slightly Tilted	Yes	Missing manhole cover	Intact	SCI-MIN
Seal   Cover/Shanupppe   Lock Intact?   Casing Alignment   Survey Point	Yes	Markad	Straight	Yes	Intact	Intact	CIT-MIN
Seal   Cover/Shanupppe   Lock Intact?   Casing Alignment   Survey Point	103	Markad	Straight	Yes	Intact	IIItact	IZI-44 IAI
Seal   Coret/Stanupppe   Lock Intact?   Casing Alignment   Survey Point	Ves	Marked	Straight	Yes	Intact	Intact	MW-121
Seal Covert/Standpipe Lock Intact? Casing Alignment Survey Point Intact Intact Yes Straight Marked	Ves	Marked	Straight	No	Intact	Intact	MW-12S
Seal Cover/Shaudpipe Lock Intact? Casing Alignment Survey Point Intact Intact Intact Yes Straight Marked Intact Yes Straight Marked Intact Yes Straight Marked Intact Yes Straight Marked Intact Yes Straight Marked Yes Straight Marked Intact Intact Yes Straight Marked Marked Intact Intac	Ves	Marked	Straight	No	Intact	Intact	MW-IID
Seal   Cover/Standpipe   Lock Intact?   Casing Alignment   Marked	Vas	Marked	Straight	Z	intact	Intact	MW-III
Seal Cover/Standpipe Lock Intact? Casing Alignment Survey Point Intact Intact Yes Straight Marked Intact Yes Straight Marked Intact Yes Straight Marked Intact Yes Straight Marked Yes Straight Marked Yes Straight Marked Yes Straight Marked Intact Intact Intact Yes Straight Marke	Vec	Marked	Straight	Yes	Intact	Intact	MW-11S
Seal Cover/Shandpipe Lock Intact? Casing Alignment Intact Intact Intact Intact Yes Straight Marked Intact In	Yes	Marked	Straight	Yes	Intact	Intact	MW-10D
Seal Covert/Standpipe Lock Intact? Casing Alignment Survey Point Intact Intact Yes Straight Marked	Yes	Marked	Straight	Yes	THREE	Intact	MW-101
Seal Covert Straight Lock Intact? Casing Alignment Survey Point Intact Intact Yes Straight Marked Intact Yes Straight Marked Intact Intact Intact Yes S	Yes	Marked	Straight	Yes	Intact	Intact	S01-WW
Seal Cover/Standpipe Lock Intact? Casing Alignment Survey Point Intact Intact Yes Straight Marked	Yes	Marked	Straight	Yes	Intact	Intact	MW-07D
Seal COVET/SHAUDPIPE LOCK Intact? Casing Alignment Marked Intact Intact Yes Straight Marked Marked Intact Intact Yes Straight Marked Intact Intact Yes Straight Marked Marked Intact Yes Straight Marked Intact Intact Yes Straight Marked Intact Yes Straight Marked Intact Yes Straight Marked Intact Yes Straight Marked Intact Intact Yes Straight Marked Intact Intact Yes Straight Marked Intact Intact Yes Straight Marked Yes Straigh	Yes	Marked	Straight	Yes	Intact	Intact	MW-071
Seal   Cover/Strangpipe   Lock Intact?   Casing Alignment   Survey Point	Yes	Marked	Straight	Yes	Intact	Intact	MW-078
Seal CoeffStandpipe Lock Intact? Casing Alignment Survey Point Intact Intact Yes Straight Marked Intact Yes Straight Marked Marked Intact Intact Yes Straight Marked Marked Yes Straight Marked Intact Yes Straight Marked Yes Strai	Yes	Marked	nalgnt	108	Intact	Intact	MW-06D
Seal         Cover/Statudpipe         Lock Intact?         Casing Alignment         Survey Point           S         Intact         Intact         Yes         Straight         Marked           Intact         Intact	Yes	Marked	Straight	100	Gasket damaged	Intact	MW-061
Seal Cover/Standpipe Lock Intact? Casing Alignment Survey Point  Intact Intact Yes Straight Marked	Yes	Marked	Jugiane	4 9	Intact	Intact	MW-06S
Intact   Intact   Yes   Straight   Marked	Yes	Marked	naight	Ves	Intact	Intact	MW-05D
Seal   Cover/Standpipe   Lock Intact?   Casing Alignment   Survey Point	Yes	Marked	Ingiano	V	Intact	Intact	MW-051
Seal   Cover/Standpipe   Lock Intact?   Casing Alignment   Survey Point	Yes	Marked	Dualgill	Vac	Intact	Intact	MW-058
Seal   Cover/Standpipe   Lock Intact?   Casing Alignment   Survey Point	Yes	Marked	Straight	Vac	Intact	Intact	MW-04D
Seal   Cover/Standpipe   Lock Intact?   Casing Alignment   Survey Point	Yes	рамия	Straight	Yes	Intact	Intact	MW-041
Seal   Cover/Standpipe   Lock Intact?   Casing Alignment   Survey Point	Yes	Marked	Straight	Yes	Intact	Intact	MW-045
Seal   Cover/Standpipe   Lock Intact?   Casing Alignment   Survey Point	Yes	Marked	Straight	N.	Intact	Intact	JEO-W INI
Seal   Cover/Standpipe   Lock Intact?   Casing Alignment   Survey Point	Yes	Marked	Straight	Yes	Intact	intact	LCO-M TAT
Seal   Cover/Standpipe   Lock Intact?   Casing Alignment   Survey Point	res	Marked	Straight	Yes	Intact	Intact	MW 030
Seal   Cover/Standpipe   Lock Intact?   Casing Alignment   Survey Point	1 08	Marked	Straight	Yes	Intact	THEACT	SEO-WM
Seal   Cover/Standpipe   Lock Intact?   Casing Alignment   Survey Point	T CO	Marked	Straight	Yes	Intact	Intact	MW-02D
Seal   Cover/Standpipe   Lock Intact?   Casing Alignment   Survey Point     Intact   Intact   Yes   Straight   Marked     Intact   Intact   Yes   Straight   Marked     Intact   Intact   Yes   Straight   Marked	169	Marked	Straight	Yes	Intact	Intact	MW-02I
Seal Cover/Standpipe Lock Intact? Casing Alignment Survey Point Intact Intact Yes Straight Marked	V	Marked	Straight	Yes	intact	Interest	MW-01D
Seal Cover/Standpipe Lock Intact? Casing Alignment Survey Point	Vec	Marked	Straight	Yes	Intact	Intact	MW-011
O'VOR'S TO A CONTROL OF THE PARTY OF THE PAR	Well Labeled?	Survey Point	Casing Alignment	Lock Intact?	Cover/Standpipe	Seal	MW-01S

#### APPENDIX D OMNTEC FIELD TEST RESULTS

---OMNTEC Mfg.,Inc. Tel: 1(631)981-2001 Fax: 1(631)981-2007

--SITE INFORMATION: Name:Town Of Islip Addr:SONIA ROAD LANDFILL ID#: EL018627 VER 4.22 PR 030603 JUN 28, 2012 08:02 AM

---OMNTEC PROBE TH 06/28/12 08:02:12 Tank 1

Product Type: Leachate Product Height: 7.48(In) Water: 1.29(In) Gross Volume: 327.23(G) T.C.: 284.23(G) Water: 42.48(G) Ullage: 5501.77(G) TEMP .: 64.00(°F)

STICK MERSUNED CONDENSATE TOOK 21/8=707 GAZ ---OMNTEC Mfg.,Inc. Tel: 1(631)981-2001 Fax: 1(631)981-2007

--SITE INFORMATION: Name:Town Of Islip Addr:SONIA ROAD LANDFILL ID#: EL018627 VER 4.22 PR 030603 JUN 28, 2012 08:02 AM

---Testing PROM
PROM Tests OK

---Testing RAM PANSSED
--Parameter Flash Used 01.79%

---Check Slot

Slot 1 Annunciator Bloard Slot 2 Relay Bloard Slot 3 Relay Bloard

-Testing Level Probes

T# PRODUCT TYPE TEST
T1 Leachate P

-Testing Leak Sensors

S# P/N LABEL ITEST
01 BXPDS T 1,Sump#: 2 P
(S/N: 200113631)
02 BXPDS T 1,Sump#: 1 P
(S/N: 200080154)
03 BXPDWF T 1,Dble\_Wall#: 1 P

(S/N: 210030803) 04 BXUT1 Caution Level P (S/N: 500031027)

S#= SENSOR NUMBER, P/N= PART NUMBER, F#= TANK, S/N= SENSOR SERIAL NUMBER, P=PASS, A=ALARM, F=FAIL, NR=NO FREPLY

#### APPENDIX E CARS STORED ON SITE(6)

1
ü
1
1
7

VALLEY STREAM HYUNDAI	MASSAPEQUA NISSAN	MILLENNIUM HYUNDAI	MILLENNIUM HONDA	LEXUS OF R.V.C	LEXUS OF MASSAPEQUA	HUNTINGTON TOYOTA	HUNTINGTON CHEVY	ATLANTIC VOLKSWAGEN	ATLANTIC TOYOTA	ATLANTIC NISSAN	ATLANTIC HYUNDAI	ATLANTIC HONDA	ATLANTIC CHEVY	ATLANTIC CADDY	ATLANTIC AUDI	ADVANTAGE TOYOTA	WESTBURY NISSAN		DEALERSHIPS
																		ONLO	
0	340	0	85	0	0	121	9	75	269	596	447	332	144	64	31	111	86	ONITS AT LEXUS PDI	
0	0	0	0	110	102	0	0	0	0	0	0	78	118	0	0	0	0		

TOTALS

2710

408

#### 3/1/2012

DFALFRSHIPS	I IIH NO STINI I	LINITS AT LEVI IS BOIL
WESTBURY NISSAN		136
ADVANTAGE TOYOTA		101
ATLANTIC AUDI		25
ATLANTIC CADDY		68
ATLANTIC CHEVY		156
ATLANTIC HONDA		614
ATLANTIC HYUNDAI		602
ATLANTIC NISSAN		607
ATLANTIC TOYOTA		178
ATLANTIC VOLKSWAGEN		63
<b>HUNTINGTON CHEVY</b>		0
<b>HUNTINGTON TOYOTA</b>		145
LEXUS OF MASSAPEQUA		0
LEXUS OF R.V.C		0
MILLENNIUM HONDA		138
MILLENNIUM HYUNDAI		0
MASSAPEQUA NISSAN		352
VALLEY STREAM HYUNDAI		0

TOTALS

#### 4/5/2012

VALLEY STREAM HYUNDAI	MASSAPEQUA NISSAN	MILLENNIUM HYUNDAI	MILLENNIUM HONDA	LEXUS OF R.V.C	LEXUS OF MASSAPEQUA	<b>HUNTINGTON TOYOTA</b>	HUNTINGTON CHEVY	ATLANTIC VOLKSWAGEN	ATLANTIC TOYOTA	ATLANTIC NISSAN	ATLANTIC HYUNDAI	ATLANTIC HONDA	ATLANTIC CHEVY	ATLANTIC CADDY	ATLANTIC AUDI	ADVANTAGE TOYOTA	WESTBURY NISSAN	DEALEROHIPO	DEVIEDS::::::::::::::::::::::::::::::::::::
					18						9							ONITS ON HILL	
0	351	0	209	0	0	162	0	94	261	512	448	612	84	58	40	151	249	UNITS AT LEXUS PDI	
0	0	0	0	137	142	0	0	0	0	0	0	0	0	0	0	0	0		

TOTALS

3231

279

TOTALS	MILLENNIUM HONDA MILLENNIUM HYUNDAI MASSAPEQUA NISSAN VALLEY STREAM HYUNDAI	ATLANTIC TOYOTA  ATLANTIC TOYOTA  ATLANTIC VOLKSWAGEN  HUNTINGTON CHEVY  HUNTINGTON TOYOTA  LEXUS OF MASSAPEQUA	WESTBURY NISSAN ADVANTAGE TOYOTA ATLANTIC AUDI ATLANTIC CADDY ATLANTIC DODGE ATLANTIC HYUNDAI ATLANTIC NISSAN	4/30/2012 DEALERSHIPS
3621	3 1	1 1 4	. 60 >1	UNITS ON HILL
21	0 163 0 374	475 191 139 0 159	168 288 51 47 46 46 0 720	UNITS AT LEXUS PDI
390	192 0 0 0	0 0 0 0 198	000000	

 $x=if=-\epsilon$ 

4	۲
(	ū
1	-
1	-
(	È
ŀ	-
ľ	-

TOTALS	VALLEY STREAM HYUNDAI	MASSAPEQUA NISSAN	MILLENNIUM HYUNDAI	MILLENNIUM HONDA	LEXUS OF R.V.C	LEXUS OF MASSAPEQUA	HUNTINGTON TOYOTA	HUNTINGTON CHEVY	ATLANTIC VOLKSWAGEN	ATLANTIC TOYOTA	ATLANTIC NISSAN	ATLANTIC HYUNDAI	ATLANTIC HONDA	ATLANTIC DODGE	ATLANTIC CHEVY	ATLANTIC CADDY	ATLANTIC AUDI	ADVANTAGE TOYOTA	WESTBURY NISSAN	DEALERSHIPS (	プルーンニー
ώ																				UNITS ON HILL	
3445	7	391	45	139	0	0	118	0	129	202	558	686	536	13	60	34	35	391	101	UNITS AT LEXUS PDI	
254	0	0	0	0	120	134	0	0	0	0	0	0	0	0	0	0	0	0	0		

а А.,

6/28/2012 DEALERSHIPS UNITS ON HILL	UNITS AT LEXUS PDI
WESTBURY NISSAN	63
ADVANTAGE TOYOTA	372
ATLANTIC AUDI	27
ATLANTIC CADDY	48
ATLANTIC CHEVY	120
ATLANTIC DODGE	47
ATLANTIC HONDA	491
ATLANTIC HYUNDAI	610
ATLANTIC NISSAN	627
ATLANTIC TOYOTA	241
ATLANTIC VOLKSWAGEN	125

TOTALS

3505

290

VALLEY STREAM HYUNDAI

MASSAPEQUA NISSAN

MILLENNIUM HYUNDAI

MILLENNIUM HONDA

0 202 0 0 149 5 372

163127

EXUS OF R.V.C

**HUNTINGTON CHEVY** 

**HUNTINGTON TOYOTA** 

LEXUS OF MASSAPEQUA