

TOWN OF HUNTINGTON

FRANK P. PETRONE, Supervisor

ENVIRONMENTAL WASTE MANAGEMENT

Mr. John Strang, P.E. NYS Dept. of Environmental Conservation Division of Environmental Remediation Bureau of Hazardous Site Control, 11th Floor 625 Broadway Albany, New York 12233-7014 April 9, 2007

Re: Huntington/East Northport Landfill; NYSDEC Site #1-52-040

Dear Mr. Strang,

As required by the Record of Decision for the above referenced site, transmitted herewith please find copies of the "Landfill Gas and Control System Monitoring Report" for the East Northport Landfill for the months of January 2007 and February 2007, as well as a copy of the East Northport Landfill Quarterly Site Inspection Report for the first quarter of CY2007.

Please do not hesitate to call me if you have any questions or comments regarding these documents.

Sincerely

Robert Litzke

Environmental Analyst

RL:rl

Enclosed:

- 1.) Landfill Gas and Control System Monitoring Report, January 2007
- 2.) Landfill Gas and Control System Monitoring Report, February 2007
- 3.) East Northport Landfill Quarterly Site Inspection Report, 1st Quarter CY2007.

Cc:

file (w/o encl.'s)

M. Laux, Deputy Director, DEWM, TOH (w/o encl.'s)

P. Del Col, Director, Engineering Services, TOH (w/encl.'s)

M. Gross, Landfill Supervisor, DEWM, TOH (w/encl.'s)

T. Chambers, Covanta (w/encl.'s)

S. H. Rahman, NYSDEC (w/encl.'s)

Town of HuntingtonDepartment of Environmental Waste Management

East Northport Landfill Quarterly Site Inspection Report

| Date Day of the Week Report No. | | | | | | | | |
|---------------------------------|---|---|---|-----|-----|---|---|---------|
| Feb. 21, 2007 | S | M | T | (W) | T - | F | S | 2007-01 |

| Inspection Participants | | | | | | | | |
|-------------------------|---------------|--------------|--|--|--|--|--|--|
| Signature / | Print Name | Organization | | | | | | |
| 1. muhruf | Robert Litzke | TOH DEWM | | | | | | |
| 2. | | | | | | | | |
| 3. | | | | | | | | |

| Equipment/Instrumentation Used | | | | | | | |
|--------------------------------|----|--|--|--|--|--|--|
| 1. N/A | 4. | | | | | | |
| 2. | 5. | | | | | | |
| 3. | 6. | | | | | | |

| Atmospheric Conditions (readings taken @ Islip-MacArthur Airport) | | | | | | | | |
|---|------------|-----------|------------|--------|---------------|--|--|--|
| Time | Conditions | Temp. (F) | "Hg/Dir. | RH (%) | Wind Spd/Dir. | | | |
| 1045 | Clear | 46 | 29.86 / /\ | 44 | 14 / N | | | |

| The Water | Site Inspection Fin | dings | |
|-----------------|--|-------------------------------|-----------------|
| <u>Landfill</u> | Guidance | Site Locations | Required |
| Components | Typical Problems | and Types of | Maintenance and |
| | | <u>Problems</u> | Repairs |
| Stormwater | Obstructed or interrupted stormwater | All drainage | N/A |
| Drainage | flow commonly caused by sediment in drainage pipes and structures, debris on | system | |
| Pipe | drainage grates, uneven settlement or | components | |
| Structures, | separation of drainage pipes and/or | appear to be | |
| Manholes, & | structures. Long-term problems often | clear of | |
| Catch | include pipe or structure cracks, loose mortar and brick work, broken or missing | excessive sand, | |
| Basins | structure steps and deteriorated drainage | gravel, dirt or other debris. | |
| | frames, grates, and manhole covers. | | |
| Gabions & | Obstructed or interrupted stormwater | No significant | N/A |
| Rip Rap | flow is commonly caused by debris or vegetative growth in the gabion cages and | loss of stone | |
| Channels | rip rap channels. Broken gabion cages can | from gabions. | |
| | result in gabion stone loss creating | No significant | |
| | erosion and washout problems | erosion noted. | |
| | | | |
| | | | |

| Landfill | Guidance | Site Locations | Required | | |
|---|---|------------------------------|------------------|--|--|
| Components | <u>Omponents</u> <u>Typical Problems</u> | | Maintenance and | | |
| | | <u>Problems</u> | Repairs | | |
| Recharge | Overflowing of the recharge basins or a | No indication of | N/A | | |
| Basins | decrease of the drainage capacity is often due to excessive vegetative growth and | overflowing | | | |
| | sediment on the basin surface. Scouring at | basins or | | | |
| | drainage outlets can be caused by | inlet/outlet | | | |
| | excessive stormwater flow. | scouring. | | | |
| | | Vegetation growth in both | | | |
| | | | | | |
| | | basins, but each drains in a | | | |
| | | | | | |
| Vacatativa | Bare, bald, or dead grass areas often | timely manner. Some small | Schedule seeding | | |
| Vegetative Cover, | result from dry climate periods or | bald spots at top | or hydroseeding | | |
| Topsoil, & | droughts. Damage to the vegetative cover, | at north side | w/ M. Gross. | | |
| Final Cover | topsoil, or final cover material may result | and along | W/ 1V1. G1055. | | |
| Materials | from the following: soil erosion, washouts, stormwater run-on or run-off, | access road. No | | | |
| 111111111111111111111111111111111111111 | rodent holes, or unwanted vegetative | ponding noted. | | | |
| | growth such as trees, shrubs, and vines. | Woody | | | |
| | Ponding areas and wet spots are often | vegetation cut | | | |
| | caused by uneven soil settlement or poor soil drainage. | down Jan. '07. | | | |
| | 352 | | | | |
| | | 37 | 27/4 | | |
| Landfill | Severe erosion of the cover material could cause landfill liner and geosynthetic | No significant | N/A | | |
| Liner & | material deterioration from unwanted | erosion of or | | | |
| Geosyntheti | atmospheric exposure. Liner rips or tears | damage to cover materials | | | |
| c Materials | could occur as a result of uneven soil | noted. | | | |
| | settlement below the liner. Excessive loads placed on the landfill area could | noted. | | | |
| | result in liner punctures. | | | | |
| | _ | | | | |
| Cos Plawer | Structural damage to the blower | Blower | Schedule | | |
| Gas Blower Station | stationhouse, lighting, and/or electrical | units/motors | housekeeping for | | |
| Station | power systems is often caused by storms, | operating | blower shed w/ | | |
| | long-term weather exposure, and/or vandalism. Note: The inspection, | effectively. | M. Gross. | | |
| | maintenance, and repairs of the gas | Housekeeping | | | |
| | monitoring wells, collection wells, and | needed in | | | |
| | condensate traps are recorded as part of | blower shed. | | | |
| | the Gas Monitoring activities. | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

| T 1011 | 0 :1 | | 1 |
|--------------|---|------------------|-----------------|
| Landfill | Guidance | Site Locations | Required |
| Components | Typical Problems | and Types of | Maintenance and |
| | | <u>Problems</u> | Repairs |
| Crushed | Stone loss can occur due to vehicular use, | No excessive | N/A |
| Stone Roads | erosion, and settlement. Excessive | stone loss | |
| | vegetative growth within roadway boundaries will result in obstructed or | noted. Minimal | |
| | reduced roadway capacity. | vegetation | |
| | reduced readway capacity. | growth in or | |
| | | next to | |
| | | roadways. | |
| | | | _ |
| Bituminous | Corrosive chemical spills or the seasonal | Minor cracks | N/A |
| Pavements | effects of freeze/thaw cycles often cause pavement cracks and deterioration. | noted in paved | |
| | Pavement settling can result in ponding | area and paved | |
| | areas. | road leading to | |
| | | garage – no | |
| | | action required. | |
| Fences, | Vandalism and on-site tampering can be | No vandalism | N/A |
| Gates, | detected by checking for cut-open fences, | or damage | |
| Guide Rails, | broken gates and locks, missing locks, | noted wrt | |
| Locks, & | and missing or graffiti-damaged signs. Damaged guide rail sections often occur | fencing, gates | |
| Warning | from vehicular contact. In general, metal | and signage. | |
| Signs | corrosion, rusting, cracking, pitting, or | 8 8 | |
| | fatigue conditions should be checked for. | | |
| | | | |
| | | | |
| T abadaa | Trans placed in the yrong location my | No domestic | N/A |
| Lobster | Traps placed in the wrong location my cause loss of vegetation and the | No damage or | N/A |
| Traps & | subsequent erosion of surface soils. Traps | interference | |
| Fishing | leaning against fence line my damage | noted due to | |
| Gear | fencing. Traps may not interfere with | storage of | |
| | landfill access, maintenance, or repair | marine | |
| | activities. | equipment. | |
| | | | |
| | | | |
| | | | |

| Additional Comments: N/A | | | | | | | |
|--------------------------|--|--|--|--|--|--|--|
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |