



Boat Showroom 197 Main Avenue Wynantskill, NY Page 1 of 4



Photo #1: Extraction point and damper valve located at northwest wall.



Photo #2: Extraction point and damper valve located at northwest wall.



Photo #3: Extraction point and damper valve located at southeast wall.



Photo #4: Extraction point and damper valve located at southeast wall.



Boat Showroom 197 Main Avenue Wynantskill, NY Page 2 of 4



Photo #5: Extraction point and damper valve located in the addition.




Photo #6: Blower for extraction points along southeast wall.