NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

Division of Environmental Remediation, Remedial Bureau E 625 Broadway, 12th Floor, Albany, NY 12233-7017 P: (518) 402-9813 I F: (518) 402-9819 www.dec.ny.gov

April 6, 2015

Mr. Stephen Fleming, P.E. Senior Remediation Manager Safety-Kleen Systems, Inc. 11923 Tramway Drive Cincinnati, OH 45241

RE: Safety-Kleen Amityville, Site No. 152154

Dear Mr. Fleming:

The New York State Department of Environmental Conservation has reviewed Safety-Kleen's "Post-Injection and Q4 2014 Groundwater Monitoring Program Report" dated February 3, 2015. The report provides the results of two (2) rounds of groundwater sampling which occurred after the completion of the remedial injection program.

Upon review, the Department has the following comments:

As part of the Injection Program 26,550 pounds of BOS 200® was injected into 111 points. The target depth for injection was 16' to 30' below ground surface.

The Department is encouraged by the decrease of mineral spirits concentrations in site groundwater wells, however, insufficient information has been submitted to evaluate the injection program. Additional groundwater sampling rounds will need to be collected prior to an assessment of the long-term effectiveness of the BOS 200 Injection Program and whether additional injections are advisable or necessary.

Attachment 1 (Site Map) needs to be updated to reflect the installation of Wells GT-6 & GT-7.



If you have any questions on this matter, please contact me at (518) 402-9813.

Sincerely,

Kent D. Johnson

Hat D John

Senior Engineering Geologist

Remedial Section B, Remedial Bureau E

Division of Environmental Remediation

ec: A. Everett, USEPA, Region 2

M. Leary, NYAG

M. Roma, NYAG

K. Murphy, Region 1

D. Radtke