

Hurricane Project Status Report

Project Information

Site Name: **Nyack MGP**

Address: **Gedney St. Nyack, NY**

DEC PM Name: **Elizabeth Lukowski**

Site Primary Contact Name and No.: **Maribeth McCormick 845-783-5534**

Site Alternate Contact Name and No.: _____

Damage and Release Assessment

Does the project have stockpiles? (Yes/No) **No**

Are the stockpiles damaged? (Yes/No) **N/A**

If yes, please provide photographs. Has the damage been repaired? (Yes/No) _____

Did soil from the project site move offsite? (Yes/No) **No. Debris from river was washed onshore**

If yes, please describe the approximate volume, nature of impact and area of impact (mud in roads, etc.). Also provide photograph. **Photos attached showing shoreline and debris line on lower terrace.** _____

Was there any erosion damage? **Rip rap along shoreline appears intact. Shoreline vegetation was damaged by storm surge.** _____

Are there any onsite contaminant exposures caused by the storm? **No** _____

Status of stockpiles: N/A

Was the excavation damaged? N/A

Were there any onsite spill or other releases not described above? Propane tank was observed on site immediately following storm. Fire Dept. was notified and O&R was advised that they were allowing tank to vent. At time on inspection on 11/23/12, tank was no longer on site.

Spill reported to DEC yet? N/A

Have all active remedial systems (GW pump and treatment, SVE/AS, SSDS) been checked and verified to be operating properly? MW- 42 was found to be damaged (Photo attached)

Was any remedial equipment (pumps, blowers, etc) flooded/damaged by the storm? _____

What corrective actions have been implemented N/A

What corrective actions are planned? O&R will coordinate with GEI to either repair or decommission MW-42

What is the schedule for corrective actions? TBD

Have any environmental response been made (i.e. spills)? Any other pertinent information to report?

Property owner (Presidential Insurance Company) has a 30 Yd dumpster on site and is cleaning up debris that washed ashore. In addition, two boats washed ashore during storm. One boat has

been removed from site. The second boat was on site on 11/23 but had an insurance inspection sticker on it so O&R expects that boat will be removed from site shortly. IDW on site was on the upper terrace. Drums are secure and undamaged. Photos attached.

Please complete this report and email it back with **PHOTOGRAPHS** of impacted areas to your assigned DEC Project Manager.





















