

APPENDIX E
PHOTOGRAPHS

Photographs – NYSEG Bridge Street Well Abandonment



Photo 1: Angle Well packer removal.



Photo 2: Packer removed from Angle Well.

Photographs – NYSEG Bridge Street Well Abandonment



Photo 3: Angle Well packer.



Photo 4: Angle Well packer.

Photographs – NYSEG Bridge Street Well Abandonment



Photo 5: Angle Well packer.



Photo 6: View of inside of 2" PVC (above packer) from Angle Well.

Photographs – NYSEG Bridge Street Well Abandonment



Photo 7: Disposing of PVC from Angle Well packer.



Photo 8: Disposing of PVC from Angle Well packer.

**Photographs – NYSEG Bridge Street
Well Abandonment**



Photo 9: Purge out standing water in Angle Well.



Photo 10: Purge out standing water in Angle Well.

**Photographs – NYSEG Bridge Street
Well Abandonment**



Photo 11: Purge water drum from Angle Well.



Photo 12: View of pump immediately after purging water from Angle Well.

Photographs – NYSEG Bridge Street Well Abandonment



Photo 13: Grouting up Angle Well.



Photo 14: Angle Well after grouting.

Photographs – NYSEG Bridge Street Well Abandonment



Photo 15: View of site and Gore sorber points.



Photo 16: View of site.

Photographs – NYSEG Bridge Street Well Abandonment



Photo 17: View of site.



Photo 18: View of shed at site.