



**2024 Annual Vegetation and Wetland  
Monitoring Report  
Saranac Lake Gas Company, Inc.  
NYSDEC Site 516008  
Saranac Lake, Essex County, New York**

**Work Assignment No. D009806-34**

*Prepared for*

New York State Department of Environmental Conservation  
Division of Environmental Remediation  
625 Broadway  
Albany, New York 12233-7017



*Prepared by*

EA Engineering, P.C. and Its Affiliate  
EA Science and Technology  
Washington Station  
333 West Washington Street, Suite 30  
Syracuse, New York 13202  
315-431-4610

**September 2024**

Revision: FINAL  
EA Project No. 1602534

*This page intentionally left blank*

## TABLE OF CONTENTS

	<u>Page</u>
LIST OF TABLES .....	ii
LIST OF FIGURES .....	ii
LIST OF APPENDICES .....	ii
LIST OF ACRONYMS AND ABBREVIATIONS .....	iii
1. INTRODUCTION .....	1
1.1 GOALS AND OBJECTIVES .....	1
2. METHODS .....	3
2.1 LAKE FLOWER .....	3
2.2 BRANDY BROOK.....	4
2.3 WETLAND AREAS.....	4
3. RESULTS .....	7
3.1 LAKE FLOWER .....	7
3.2 BRANDY BROOK.....	8
3.3 WETLAND AREAS.....	9
4. CONCLUSIONS / RECOMMENDATIONS.....	11

## **LIST OF TABLES**

Table 1.	Current Monitoring Status of Each OU
Table 2.	Lake Flower Monitoring Results
Table 3.	Brandy Brook Monitoring Results
Table 4.	Wetland Areas Monitoring Results
Table 5.	Proposed Riparian Plantings

## **LIST OF FIGURES (provided in Appendix B)**

Figure 1.	Site Vicinity Map
Figure 2.	Monitoring Areas and Data Collection Points – Pontiac Bay/Lake Flower
Figure 3.	Monitoring Areas and Data Collection Points – Brandy Brook West
Figure 4.	Monitoring Areas and Data Collection Points – Brandy Brook East
Figure 5.	Photograph Location Map 1
Figure 6.	Photograph Location Map 2

## **LIST OF APPENDICES**

Appendix A.	Design Drawings
Appendix B.	Figures
Appendix C.	Wetland Data Sheets
Appendix D.	On-Site Photographs



**LIST OF ACRONYMS AND ABBREVIATIONS**

%	Percent
EA	EA Engineering, P.C. and its Affiliate EA Science and Technology
FAC	Facultative
No.	Number
NWP	Nationwide Permit
NYSDEC	New York State Department of Environmental Conservation
OU	Operable unit
USACE	U.S. Army Corps of Engineers

*This page intentionally left blank*

## 1. INTRODUCTION

EA Engineering, P.C. and its affiliate EA Science and Technology (EA) was retained by the New York State Department of Environmental Conservation (NYSDEC) to perform annual vegetation and wetland monitoring associated with the remediation work conducted at the Saranac Lake Gas Company (Co.), Inc. Site (NYSDEC Site Number [No.] 516008) in the Village of Saranac Lake, Essex County, New York (Figure 1). Site design, regulatory authorization, and the first 2 years of annual reporting were completed by others and EA was retained by NYSDEC to monitor the site annually starting in April 2023. The following description of the project is based upon information presented in previous monitoring reports.

The NYSDEC has completed remediation at the site associated with Permit Application No. NAN-2017-0040-UDE, which included the condition to restore 1,360 linear feet of existing stream channel, 0.58 acres of riparian emergent and scrub shrub wetland, 0.09 acres of upland riparian area and stream bank, 71,650 square feet of Pontiac Bay, and 175 feet of shoreline.

The purpose of this report is to fulfill the requirements of the U.S. Army Corps of Engineers (USACE) authorization to complete remediation and restoration activities within jurisdictional areas under the USACE Nationwide Permit (NWP) 38 in which an annual monitoring report is required to describe the conditions of the restored wetlands and riparian areas for a period of 5 years to ensure that permit conditions and restoration objectives are being met at the conclusion of the 5-year monitoring period.

EA has been tasked with conducting the annual vegetation and wetland monitoring of the restored areas as detailed in the approved design plans (Appendix A). This report presents a summary of the 2024 annual monitoring activity conducted to ensure the long-term success of the restored wetland, stream and riparian areas conducted as part of the remedial action. Since the project site operable units (OUs) were restored during different years, the 5-year monitoring period for each OU is slightly different as described in Table 1.

**Table 1. Current Monitoring Status of Each OU**

OU	Common Name	Monitoring Subset Area	Date of Restoration	Monitoring Year (1-5)
OU1	Wetland Areas	WP-1	June 2022	2
		WP-2		
OU2	Brandy Brook Area	BB-1	June 2019	4
		BB-2		
OU3	Lake Flower Area	LF-1	June 2019	4
		LF-2		
		LF-3		
		Cedar Area		

### 1.1 GOALS AND OBJECTIVES

Annual monitoring of the restored wetland areas, stream channel, and riparian areas is required to be conducted to meet the conditions of the authorization received from USACE to perform the remediation under NWP 38. The annual monitoring must be conducted to ensure the permittee

successfully restored 1,360 linear feet of Brandy Brook, 0.58 acres of riparian emergent and scrub shrub wetland, 0.09 acres of upland riparian area and stream bank, 71,650 square feet of Pontiac Bay, and 175 feet of shoreline.

Per the Special Conditions of NWP 38, the following criteria shall be met for successful restoration of the site:

- Ensure that all proposed wetland, upland, and stream restoration plantings have an 85 percent (%) survival rate.
- Ensure that the newly established planting areas do not consist of more than a total of 5% areal coverage of invasive species.
- Ensure that no mowing of the restoration areas has occurred.
- Complete wetland data sheets within restored wetland areas to document wetland characteristics including wetland hydrology exists with the wetland areas.

In order to determine if these goals and objectives are being met within the restored areas, the annual monitoring for this year's effort as well as future efforts will be conducted annually following the methods provided in this report for a period of 5 years. At the end of the 5<sup>th</sup> monitoring year, EA will include a discussion in the annual monitoring report to identify if additional monitoring should be conducted after the 5<sup>th</sup> year and make recommendations for monitoring to be terminated if the conditions are acceptable to the regulatory agencies.

## 2. METHODS

To satisfy both USACE and NYSDEC monitoring requirements, the restoration monitoring efforts include the collection of specific data for reporting, including the requirements below, which are described in more detail in the sections that follow:

- Wetland, Riparian, and Upland Vegetation Monitoring
- Documentation of Erosion and Signs of Instability Along Brandy Brook and the Banks of Lake Flower
- Hydrology Monitoring within Restored Wetland Areas
- Development of Anaerobic Soil Conditions with Wetland Areas

For the annual monitoring, the project site was separated into three sections, consisting of the banks of Lake Flower, Brandy Brook, and the two restored wetland areas. These sections were separated based on the monitoring methods utilized to document the site conditions and are depicted on Figures 2 through 4 (Appendix B).

During an on-site discussion with NYSDEC staff during the previous 2023 monitoring event, it was requested to break the monitoring area into distinct areas based on existing on-site conditions to provide recommendations relevant to specific areas, rather than broad general recommendations. Therefore, a total of 8 distinct monitoring areas were established on-site in 2023, as depicted on Figures 2 through 4, and described in greater detail in the following sections. These 8 distinct monitoring areas were established during the 2023 monitoring effort and assessed again during the 2024 monitoring event. Wetland monitoring areas and key observations were located with a global positioning system in the field for repeat monitoring and are depicted on the figures in Appendix B. Location and directions of on-site photographs are depicted on Figures 5 and 6 (Appendix B) and on-site photographs are provided in Appendix D.

### 2.1 LAKE FLOWER

The banks of Lake Flower were monitored to determine the successful restoration of the vegetation along the banks and note areas of erosion and instability. The Lake Flower Restoration Section was separated into four distinct monitoring areas (Figure 2). These four monitoring locations consisted of three sections of shoreline on the northern banks of Lake Flower (LF-1, LF-2, and LF-3) and one are of Cedar plantings on the southern bank of Lake Flower. Within the Lake Flower Monitoring Areas, EA conducted a visual survey of the planted material and conducted an estimate of survivability based on counting live and dead woody stems along the shoreline, as well as estimating percent cover of native vegetation and percent cover of invasive species. General observations on restoration success and areas of concern, such as erosion and instability, were also documented within each monitoring area.

## **2.2 BRANDY BROOK**

The stream channel identified as Brandy Brook was monitored to determine the successful restoration of the stream which included the successful establishment of riparian vegetation along the banks and identification of any areas of erosion and instability within the channel. Brandy Brook Restoration Section was separated into two distinct monitoring areas (Figures 3 and 4). These two monitoring areas included the northern portion of Brandy Brook (BB-1) located between Slater Avenue and Pine Street and the southern portion of Brandy Brook (BB-2) located between Brandy Brook Avenue and Wetland Area 2. Within the Brandy Brook Monitoring Areas, EA conducted a visual survey of the restored stream banks to document the percent vegetation cover along the banks and identify areas of bare earth lacking vegetation, as well as estimating percent cover of invasive species. General observations on restoration success and areas of concern, such as erosion and instability, were also documented within Brandy Brook.

## **2.3 WETLAND AREAS**

Two wetland areas were restored as part of the remediation effort and are both located along the southern portion of the project site at the upstream end of Brandy Brook (Figure 4). These two wetlands were monitored to determine the successful restoration of the vegetation within the wetlands as well as ensuring wetland characteristics, such as wetland hydrology and hydric soils, are developing. The northern wetland monitoring area (Wet-1) consists of an emergent wetland which was seeded with an emergent wetland mix, and the southern wetland monitoring area (Wet-2) consists of a newly planted forested wetland. Within the two wetland areas, EA completed formal wetland data sheets (Appendix C) to ensure all three wetland criteria are present and the two areas meet the requirements of a wetland. In addition to the formal wetland data plot, EA also conducted a meander search throughout the two wetlands to estimate coverage of invasive species and estimate total plant cover throughout the wetlands. Within the newly planted Wet-2 area, EA also conducted an estimate of survivability based on counting live and dead woody stems. General observations on restoration success and areas of concern, such as erosion and instability, were also documented within each wetland area.

A formal wetland delineation data form for the Northcentral and Northeast Region was completed within each wetland area to document the vegetation species, wetland hydrology indicators, and hydric soil conditions within each wetland monitoring area. Field personnel collected soil to a depth of approximately 18 inches or until refusal was encountered to observe soil conditions and classify the soil as either hydric or non-hydric.

Wetland hydrology supplies the moisture required to support wetland vegetation and creates the conditions necessary for the formation of hydric soils. Primary indicators of wetland hydrology include, but are not limited to, observed inundation or saturation, watermarks, drift deposits, sediment deposits, aquatic fauna, oxidized rhizospheres on living roots, and water-stained leaves. Secondary indicators of wetland hydrology include, but are not limited to, drainage patterns, dry season water table, crayfish burrows, and the Facultative (FAC)-Neutral Test. The FAC-Neutral Test involves comparing the number of obligate and facultative wetland plant species to the number of facultative upland and upland plant species, with FAC species being neutral. If 50% or more of the plant species are obligate or facultative wetland, the FAC-Neutral Test is met. Meeting

the FAC-Neutral Test is considered a secondary indicator of wetland hydrology. An area must contain at least one primary indicator or two secondary indicators of wetland hydrology for the parameter of wetland hydrology to be met.

Hydric soils are soils that are saturated, ponded, or flooded long enough during the growing season to develop anaerobic conditions in the upper portion of the soil column (typically within the upper 18 inches). The prolonged presence of water results in the chemical reduction of elements, particularly iron and manganese. Reduced soils often exhibit a gray (or “gleyed”) color that reflects either the leaching of elements or the presence of reduced elements (again, generally iron and manganese).

Hydric soils are often characterized by bright mottles, sometimes called redoxymorphic features. Mottles are an indication of incomplete saturation. They typically represent isolated pockets where elements (mainly iron) have remained oxidized. Another feature of hydric soils is a low matrix chroma in the diagnostic zone, which is typically identified as the upper 18 inches of the soil layer but may vary. For mineral hydric soils, the diagnostic zone typically must have a matrix chroma of two or less for soils with mottles, or a matrix chroma of one or less for soils without mottles. To make this determination, soil cores are collected in the field in suspected wetland areas, and the soil colors are compared to a Munsell Soil Color Chart. Other examples of field indicators for hydric soils include, but are not limited to, high organic content, histic epipedons, and concretions.

Since hydric soils indicators in newly created or recently disturbed wetlands can be difficult to observe, the hydric soils assessment was supplemented with the use of alpha, alpha-dipyridyl test strips to determine the presence of ferrous iron in the soil. These test strips are placed on the face of a soil sample and soaked with water. If ferrous iron is present in the soil sample, the test strips turn reddish pink. Within each wetland plot, a soil sample was collected, and test strips were placed on the soil sample in 4-inch increments from a depth of 0 inches down to 16 inches.

*This page intentionally left blank*



### 3. RESULTS

Annual monitoring was performed on 24 June 2024, which included general observations of wetland hydrology and soils as well as vegetation assessments within the restored wetlands, stream banks, and riparian areas.

#### 3.1 LAKE FLOWER

The Lake Flower section of the project site included the riparian banks of the lake and monitoring included documenting the survivability of planted woody stems along the banks, as well as percent native vegetation cover and percent invasive coverage. A total of four monitoring areas were established during the 2023 annual monitoring event, as depicted on Figure 2, and were evaluated again during the current monitoring event. Based on the data collected during the 2024 monitoring event, monitoring area LF-2, LF-3, and the Cedar Area had a survivability of 95% and above of the woody stems counted in 2023. During the 2023 and 2024 monitoring efforts, no woody stems were observed within area LF-1. Furthermore, the woody stem counts in both LF-2 and LF-3 have increased from 2023, due to the natural establishment of woody vegetation, including the establishment of American elm (*Ulmus americana*), black willow (*Salix nigra*), and gray alder (*Alnus incana*). A total of 43 new woody stems were identified during the 2024 monitoring effort. All four monitoring areas within the Lake Flower area had a percent native cover of 90% or above and an invasive cover of 5% or less. Additionally, wildlife browsing was also observed on numerous woody stems within LF-2 and LF-3 including beaver activity on larger mature trees along the top of the banks.

One hundred (100) % of the cedar trees planted during the initial restoration effort have survived in the Cedar area and appear to be healthy with no obvious sign of disease or decay.

**Table 2. 2024 Lake Flower Monitoring Results**

Area No.	2023 No. of Live Woody Stems	2024 No. of Live Woody Stems	Survivability 2023 → 2024	No. of Woody Stems Naturally Established	% Native Cover	% Invasive Cover
LF-1	0	0	--	0	100%	0%
LF-2	10	10	100%	8*	90%	0%
LF-3	59	59	100%	50*	95%	5%
Cedar Area	34	34	100%	0	90%	0%
<b>Total</b>	<b>103</b>	<b>103</b>	<b>100.0%</b>	<b>58*</b>	<b>93.75%</b>	<b>1.25%</b>

Notes:

\* Natural establishment of native woody stems from non-planted material does not include dense patches of bayberry which form dense clusters of 50-100 stems, observed throughout LF-2 and LF-3.

No signs of bank erosion or instability were observed within the Lake Flower section of the project site.

### 3.2 BRANDY BROOK

The Brandy Brook section of the project site included the restored stream channel riparian banks of the lake and monitoring included documenting any signs of erosion or instability along the banks or within the stream channel and at constructed restoration structures, as well as estimating percent native vegetation cover, and percent invasive coverage throughout the riparian areas adjacent to the stream channel. The Brandy Brook section of the project site is separated into two monitoring areas which were established during the 2023 annual monitoring event as depicted on Figures 3 and 4 and were evaluated during this monitoring event. Based on the data collected during this monitoring, the riparian areas adjacent to the stream channel in both BB-1 and BB-2 are currently exceeding the success criteria for vegetation cover (85% coverage) and have an invasive species cover below 5% (Table 3). Sections of riprap placed upstream and downstream of multiple culverts within both BB-1 and BB-2 contribute to the vegetation cover being below 100%. The core fabric logs placed along the bottom of the stream banks have become fairly vegetated throughout the length of BB-1 and BB-2 and the logs are mostly not identifiable due to the large amount of vegetation growing along the stream edge.

**Table 3. Brandy Brook Monitoring Results**

Area No.	% Native Cover	% Invasive Cover	Observations / Areas of Concern
BB-1	90%	1%	The area directly east of Slater Avenue has limited vegetation cover along the bottom of the bank along the core fiber log. Live stakes may be suitable in this area.
BB-2	95%	1%	Rip-rap slope at corner of Pine Street and Brandy Brook Avenue appears to receive significant street runoff and should be monitored closely.  The concrete headwall and box culvert between BB1 and BB-2 has signs of scour and should be closely monitored in future events.  Areas of previously identified invasive species (Japanese knotweed) have been treated successfully.
<b>Total</b>	<b>92.5%</b>	<b>1%</b>	

During the monitoring effort, EA personnel did not observe areas of stream bank erosion or signs of stream instability along the channel. In 2023 an area of concern at the historic concrete box culvert was identified, showing signs of scour under the concrete headwall. The existing fabric log was re-staked in this location in 2023 and the log has begun to become well vegetated, with no additional signs of erosion were observed in 2024. Additionally, in 2023 NYSDEC noted concern over the potential of future erosion along the rip-rap slope at the corner of Pine Street and Brandy Brook Avenue, since this location appears to receive significant runoff from the roads. However, during the 2024 monitoring effort this area was reviewed with NYDEC staff and no signs of erosion or rip-rap instability were noted during the 2024 monitoring event. The top of the slope has become more vegetated and no evidence of rip-rap movement down the bank was identified. The stream channel appears to be well connected to the wetlands and floodplain, and photographic documentation of the current channel conditions is provided in Appendix C. Established stream photograph locations are provided on Figures 5 and 6 (Appendix B). All in-stream structures and

habitat features that are on the design drawings were visually observed during the monitoring event and are in place and appear to be properly functioning per the design plans.

In 2023 two areas of Japanese knotweed were identified and have been treated since the initial planting efforts. The area of previously identified knotweed at the corner of Pine Street and Brandy Brook Avenue has been fully removed and the area along the bike trail has been treated effectively with only two small stems of knotweed re-propagating. Although the previously identified Japanese knotweed areas have been treated and are below the 5% cover threshold, the areas of previously identified Japanese knotweed should continue to be monitored and treated as identified.

One new area was identified for the presence of Japanese knotweed within BB-1 at one of the driveway crossings along Brandy Brook Road (Figure 3). This area should be treated for Japanese knotweed to ensure no further spread of this species along the banks of the stream channel.

### 3.3 WETLAND AREAS

The restored wetland areas of the project site included one emergent wetland and one forested/shrub wetland. The monitoring for these two wetlands included documenting the survivability of planted woody stems within Wet-2 only, as well as percent native vegetation cover, percent invasive coverage in both wetlands, documenting the presence of hydric soils, wetland hydrology, and noting any additional issues or concerns with the successful restoration of these areas back to wetlands. A total of two monitoring areas were established during the 2023 annual monitoring event (Figure 4) and were evaluated during this monitoring event. Based on the data collected during this monitoring event, both wetlands are achieving the success criteria for survivability, vegetation cover, and invasive cover; as well as the presence of hydric soils and wetland hydrology (Table 4).

**Table 4. Wetland Areas Monitoring Results**

Area No.	2023 No. of Live Trees	2023 Survivability	2024 No. of Live Trees	2024 Survivability	% Native Cover	% Invasive Cover	Hydric Soils	Wetland Hydrology
Wet-1	NA	NA	NA	NA	100%	0%	Yes	Yes
Wet-2	76*	95%	74*	92.5%	95%	0%	Yes	Yes
<b>Total</b>	<b>76</b>	<b>95%</b>	<b>74</b>	<b>92.5%</b>	<b>97.5%</b>	<b>0%</b>	<b>-</b>	<b>-</b>

Notes:

\*2 trees have died between the 2023 and 2024 monitoring efforts

NA = Not applicable/available

The original planting count as indicated in the Annual Monitoring Report - Year 2 (2022); Wet-2 included 95 woody stems (24 white pine, 23 red maple, 23 birch, and 25 dogwood). However, in April 2023, it was noted that 10 of the white pine were not successful and were replaced with more tolerant wetland species (*Acer rubrum* - red maple). During the 2023 monitoring event a total of 80 planted woody stems were observed within the wetland area (Wet-2) with 76 live stems and 4 dead stems, for a survivability of 95%. However, it appears some of these 95 trees were planted along the opposite bank of the stream channel along the riparian edge and therefore were not included in the wetland survivability calculations. It should be noted that 14 live large trees and

one dead white pine was observed on the opposite bank of the stream channel during the wetland monitoring effort for a survivability of 93% for the trees along the riparian edge. The native vegetation cover in Wet-2 has increased by 10% and the emergent wetland vegetation has shown vigorous growth of the last year. During the 2023 monitoring effort, recent disturbance and re-seeding was identified in this area which has been repaired and the re-seeding has been very effective.

Wetland hydrology indicators as well as hydric soils were identified throughout both wetlands. A formal USACE wetland data sheet was collected within each wetland area. At each data collection location, EA obtained a soil sample (14-18 inches deep) using a stainless-steel auger. The hydric soils indicator of a depleted matrix was observed within each wetland. Additionally, wetland hydrology including surface water, saturated soils, drainage patterns, passing of the FAC-Neutral Test, and presence of reduced iron were observed in both wetlands.

#### 4. CONCLUSIONS / RECOMMENDATIONS

In general, the restored wetlands, stream channel, and riparian areas appear to be functioning as designed and invasive species are below the required 5%. The two wetland areas are meeting or exceeding the success criteria and the stream channel is stable and functioning as designed. All the areas along Lake Flower are meeting the native cover and invasive cover requirements for the project and woody stem survivability and natural establishment is high in all areas except LF-1.

Monitoring areas LF-1 currently does not have any woody stems along the bank and in 2023, many of the live stakes appear to have been planted along the lower portion of the banks below the water line. NYSDEC expressed concern over the lack of bank shading within these two monitoring areas, which should be planted with shrubs along the top of bank, along the riprap edge or additional small trees should be planted to provide shade along the shoreline. This recommendation was approved in the final 2023 monitoring report and should be planted before the end of the 2024 growing season. Table 5 provides a general planting recommendation for areas LF-1 and LF-2, which includes planting shrubs along the top of the rip-rap edge within LF-1 and along the banks of LF-2. The presence of large rock and rip-rap in these two areas along the banks would likely inhibit the placement of additional live stakes along the bank.

**Table 5. Proposed Riparian Plantings**

Scientific Name	Common Name	Size	Quantity
<b>LF-1</b>			
<i>Cephalanthus occidentalis</i>	Buttonbush	1 gallon	8
<i>Betula nigra</i>	River birch	5-7 gallon	4
<i>Acer rubra</i>	Red Maple	5-7 gallon	4
<b>LF-2</b>			
<i>Cephalanthus occidentalis</i>	Buttonbush	1 gallon	3
<i>Betula nigra</i>	River birch	5-7 gallon	3
<i>Spiraea alba</i>	White meadowsweet	1 gallon	3

All plants shall be sourced from stock grown within a 150-mile radius of the project site, acclimated to the climate of Upstate New York, and grown from naturally occurring ecotypes in the region. Substitutions to plant species, type, size, and origin may be made at the approval of NYSDEC based on species availability. Due to the observed deer browsing on vegetation along the Lake Flower shoreline, new plantings should include the addition of deer browsing tubes.

The rip-rap slope and box culvert located between BB-1 and BB-2 was initially an area of concern in 2023 and was recommended to be closely monitored during future monitoring events to ensure erosion or scour does not continue in this area. During the 2024 monitoring effort, no additional erosion or scour was identified in this area and the top of slope and bottom of the slope at the edge of the rip rap has become more densely vegetated and appears to be stable. Similarly, the 2023 re-planted area within Wet-2 has become very well established and no bare spots or tire rutting was observed in 2024.

Invasive species throughout the project site are sparse and under restoration goals. However, the two identified areas of Japanese knotweed should continue to be monitored, and continued

treatment is recommended for throughout 2024 to spot treat the areas of Japanese knotweed. If not continuously treated, this population can re-establish and exceed the 5% threshold rapidly, as Japanese knotweed is an aggressive, fast growing invasive species.

# **Appendix A**

## **Design Drawings**


*This page intentionally left blank*











MACTEC

MACTEC Engineering and Geology, P.C.  
P.O. Box 7050, 511 Congress Street  
Portland, ME 04106  
(207) 775-5401

NEW YORK

Department of  
Environmental  
Conservation

CIVIL

BOTTOM OF EXCAVATION  
OU02

REMEDIAL ACTION

SARANAC LAKE GAS CO., INC.  
SARANAC LAKE, NEW YORK  
NYSDEC SITE NUMBER - 516008

VERIFY SCALE

BAR IS ONE INCH ON  
ORIGINAL DRAWING.

DATE

JAN 2020

PROJ

3611-16-1193

DWG

C-201

SHEET

3 OF 11

STATE OF NEW YORK

ENGINEER

060317

MACTEC

03/31/20

MACTEC

RECORD DRAWING

REVISION

CHK

DR

MAP

DGN

NO.

DATE

1

3/31/20

BY

APVD


MAP

APVD

MJS

03/31/20

UNAUTHORIZED ALTERATION OR ADDITION TO THIS DOCUMENT IS A VIOLATION OF SECTION 7209 OF THE NEW YORK STATE EDUCATION LAW.




CONFIRMATION SAMPLE LOCATIONS:

Line	stationcode	latitude	longitude	surfacelev	Line	stationcode	latitude	longitude	surfacelev	Line	stationcode	latitude	longitude	surfacelev	Line	stationcode	latitude	longitude	surfacelev
1	OL-2-sOIL-131	44.323056	-74.121266	1327.957	56	OL-2-sLD-17-BOT	44.322233	-74.11535	1332.325	111	OL-2-sLD-63-sIDE	44.321531	-74.115356	1332.152	166	OL-2-sOIL-132	44.321649	-74.115322	1332.351
2	OL-2-sOIL-132	44.323119	-74.121264	1328.376	57	OL-2-sLD-15-BOT	44.321905	-74.115636	1332.293	112	OL-2-sLD-66-sIDE	44.321543	-74.115433	1333.34	167	OL-2-sOIL-133	44.321705	-74.115367	1332.953
3	OL-2-sOIL-133	44.323102	-74.121263	1327.042	58	OL-2-sLD-19-BOT	44.322332	-74.115324	1332.159	113	OL-2-sLD-67-sIDE	44.321532	-74.11543	1333.337	168	OL-2-sOIL-134	44.322251	-74.115676	1334.139
4	OL-2-sOIL-134	44.323054	-74.121484	1325.74	59	OL-2-sLD-20-BOT	44.321725	-74.115606	1334.375	114	OL-2-sLD-65-sIDE	44.32162	-74.115465	1334.553	169	OL-2-sOIL-135A	44.322859	-74.120113	1331.007
5	OL-2-sOIL-135	44.323092	-74.121513	1326.673	60	OL-2-sLD-20-BOT	44.322965	-74.115679	1333.674	115	OL-2-sLD-69-sIDE	44.322005	-74.115469	1333.351	170	OL-2-sOIL-135A-sIDE	44.323376	-74.120136	1327.53
6	OL-2-sLD-126	44.323194	-74.120653	1325.633	61	OL-2-sLD-21-BOT	44.321603	-74.115605	1331.435	116	OL-2-sLD-7	44.321617	-74.115753	1333.13	171	OL-2-sOIL-136	44.322945	-74.12033	1325.67
7	OL-2-sLD-127	44.323153	-74.12067	1325.996	62	OL-2-sLD-22-BOT	44.322943	-74.1157	1332.420	117	OL-2-sLD-70-sIDE	44.321991	-74.115314	1334.296	172	OL-2-sOIL-137	44.323322	-74.120333	1325.721
8	OL-2-sLD-128	44.323142	-74.121044	1326.419	63	OL-2-sLD-23-BOT	44.321956	-74.115791	1331.535	118	OL-2-sLD-71-sIDE	44.322057	-74.115406	1333.142	173	OL-2-sOIL-138	44.322812	-74.120555	1325.564
9	OL-2-sLD-129	44.323173	-74.121043	1327.396	64	OL-2-sLD-24-BOT	44.322571	-74.115344	1331.945	119	OL-2-sLD-72-sIDE	44.322659	-74.115339	1332.919	174	OL-2-sOIL-139	44.323294	-74.120442	1326.036
10	OL-2-sLD-130	44.323164	-74.121139	1325.432	65	OL-2-sLD-25-BOT	44.321938	-74.115337	1332.965	120	OL-2-sLD-73-sIDE	44.322179	-74.115367	1334.93	175	OL-2-sOIL-140	44.322915	-74.120535	1325.996
11	OL-2-sLD-144	44.323141	-74.121033	1325.904	66	OL-2-sLD-26-BOT	44.322102	-74.115902	1332.005	121	OL-2-sLD-74-sIDE	44.322157	-74.115901	1333.94	176	OL-2-sOIL-141	44.323217	-74.120505	1325.91
12	OL-2-sLD-145	44.323125	-74.121155	1325.65	67	OL-2-sLD-27-sIDE	44.322177	-74.115903	1331.369	122	OL-2-sLD-75-sIDE	44.322276	-74.115421	1333.034					
13	OL-2-sLD-45	44.323152	-74.120679	1325.279	68	OL-2-sLD-25-BOT	44.322525	-74.119116	1331.667	123	OL-2-sLD-76-sIDE	44.322347	-74.115457	1333.293					
14	OL-2-sLD-47	44.323157	-74.121037	1326.271	69	OL-2-sLD-29-BOT	44.32259	-74.119191	1330.909	124	OL-2-sLD-77-sIDE	44.322559	-74.115704	1333.534					
15	OL-2-sLD-45	44.323117	-74.121157	1326.724	70	OL-2-sLD-30-BOT	44.321324	-74.115656	1334.384	125	OL-2-sLD-75-sIDE	44.322421	-74.115369	1332.607					
16	OL-2-sOIL-162	44.323123	-74.121053	1327.107	71	OL-2-sLD-30-BOT	44.322945	-74.119271	1331.165	126	OL-2-sLD-79-sIDE	44.322944	-74.11573	1334.202					
17	OL-2-sOIL-163	44.323156	-74.121109	1327.294	72	OL-2-sLD-31-BOT	44.323003	-74.11935	1331.025	127	OL-2-sLD-58-BOT	44.321893	-74.115334	1332.296					
18	OL-2-sLD-0164-BOT	44.321679	-74.115325	1333.897	73	OL-2-sLD-32-BOT	44.323065	-74.119425	1331.324	128	OL-2-sLD-59-sIDE	44.32264	-74.11555	1333.369					
19	OL-2-sLD-180-BOT	44.321217	-74.111709	1334.572	74	OL-2-sLD-34-BOT	44.323153	-74.119569	1329.902	129	OL-2-sLD-51-sIDE	44.322296	-74.115762	1334.642					
20	OL-2-sLD-16-BOT	44.321547	-74.115341	1331.311	75	OL-2-sLD-35-BOT	44.323244	-74.11967	1331.479	130	OL-2-sLD-52-sIDE	44.322367	-74.115712	1333.536					
21	OL-2-sLD-100-sIDE	44.322679	-74.119609	1332.242	76	OL-2-sLD-36-BOT	44.323003	-74.119749	1330.659	131	OL-2-sLD-53-sIDE	44.322472	-74.115514	1333.67					
22	OL-2-sLD-101-sIDE	44.323035	-74.119444	1332.327	77	OL-2-sLD-37-BOT	44.323359	-74.11953	1326.655	132	OL-2-sLD-54-sIDE	44.322594	-74.115773	1333.263					
23	OL-2-sLD-102-sIDE	44.323136	-74.119635	1332.07	78	OL-2-sLD-35-BOT	44.323093	-74.119607	1335.433	133	OL-2-sLD-55-sIDE	44.32245	-74.115553	1333.435					
24	OL-2-sLD-103-sIDE	44.323116	-74.119521	1331.75	79	OL-2-sLD-37-BOT	44.32304	-74.119655	1325.769	134	OL-2-sLD-56-sIDE	44.322635	-74.115594	1332.944					
25	OL-2-sLD-104-sIDE	44.323195	-74.119505	1332.312	80	OL-2-sLD-3A-BOT	44.321324	-74.115655	1333.659	135	OL-2-sLD-57-sIDE	44.322629	-74.115901	1333.057					
26	OL-2-sLD-105-sIDE	44.323173	-74.11961	1332.905	81	OL-2-sLD-48-BOT	44.321391	-74.115132	1333.545	136	OL-2-sLD-55-sIDE	44.322722	-74.115906	1332.574					
27	OL-2-sLD-106-sIDE	44.323231	-74.119659	1332.803	82	OL-2-sLD-40-BOT	44.323274	-74.120115	1329.194	137	OL-2-sLD-59-sIDE	44.322655	-74.1159011	1333.313					
28	OL-2-sLD-105-sIDE	44.323259	-74.119771	1332.301	83	OL-2-sLD-40A	44.323365	-74.120131	1327.434	138	OL-2-sLD-98-BOT	44.321771	-74.115367	1329.714					
29	OL-2-sLD-109-sIDE	44.32337	-74.119817	1326.733	84	OL-2-sLD-41-BOT TOW Mts	44.323333	-74.120217	1325.749	139	OL-2-sLD-60-sIDE	44.322739	-74.119903	1332.264					
30	OL-2-sLD-111-BOT	44.323193	-74.115447	1333.995	85	OL-2-sLD-42	44.323332	-74.120402	1326.907	140	OL-2-sLD-91-sIDE	44.322735	-74.119977	1332.139					
31	OL-2-sLD-110-sIDE	44.323345	-74.119544	1327.611	86	OL-2-sLD-43	44.323303	-74.120493	1326.269	141	OL-2-sLD-92-sIDE	44.322534	-74.11995	1331.935					
32	OL-2-sLD-111-sIDE	44.323407	-74.119577	1326.533	87	OL-2-sLD-44	44.323375	-74.120522	1329.695	142	OL-2-sLD-93-sIDE	44.322512	-74.119934	1332.45					
33	OL-2-sLD-112-sIDE	44.323353	-74.119929	1326.796	88	OL-2-sLD-45	44.323345	-74.120547	1325.393	143	OL-2-sLD-94-sIDE	44.322594	-74.119955	1331.093					
34	OL-2-sLD-113-sIDE	44.323443	-74.119993	1325.552	89	OL-2-sLD-46	44.323102	-74.121256	1327.407	144	OL-2-sLD-95-sIDE	44.322575	-74.119925	1331.957					
35	OL-2-sLD-114-sIDE	44.323427	-74.119956	1325.336	90	OL-2-sLD-14A-BOT	44.321391	-74.115132	1331.933	145	OL-2-sLD-96-sIDE	44.322962	-74.119925	1332.326					
36	OL-2-sLD-115-sIDE	44.323336	-74.120102	1329.031	91	OL-2-sLD-5	44.321465	-74.115207	1333.453	146	OL-2-sLD-97-sIDE	44.322944	-74.119925	1332.645					
37	OL-2-sLD-116-sIDE	44.323343	-74.120217	1325.345	92	OL-2-sLD-30	44.323074	-74.121403	1326.347	147	OL-2-sLD-95-sIDE	44.323015	-74.119332	1331.902					
38	OL-2-sLD-117-sIDE	44.323366	-74.120219	1329.417	93	OL-2-sLD-31	44.323065	-74.12152	1326.363	148	OL-2-sLD-99-sIDE	44.322965	-74.119365	1332.324					
39	OL-2-sLD-115	44.323302	-74.120493	1327.495	94	OL-2-sLD-32	44.323033	-74.121626	1326.315	149	OL-2-sOIL-122	44.323323	-74.120633	1329.411					
40	OL-2-sLD-119	44.323335	-74.120495	1325.292	95	OL-2-sLD-33	44.321158	-74.117942	1336.947	150	OL-2-sOIL-123	44.32336	-74.120665	1329.696					
41	OL-2-sLD-12-BOT	44.323202	-74.115455	1332.932	96	OL-2-sLD-33A-sIDE	44.321153	-74.117943	1335.677	151	OL-2-sOIL-124	44.323229	-74.120731	1329.991					
42	OL-2-sLD-120	44.323291	-74.120476	1326.711	97	OL-2-sLD-34	44.321232	-74.117953	1335.612	152	OL-2-sOIL-125	44.323302	-74.120755	1329.995					
43	OL-2-sLD-121	44.323222	-74.120496	1327.032	98	OL-2-sLD-35	44.321296	-74.119653	1336.996	153	OL-2-sOIL-126	44.323054	-74.121494	1326.74					
44	OL-2-sLD-13-BOT	44.322652	-74.115499	1332.343	99	OL-2-sLD-36	44.321255	-74.11591	1335.347	154	OL-2-sOIL-128	44.322892	-74.121515	1326.673					
45	OL-2-sLD-14-BOT	44.32171	-74.115444	1329.205	100	OL-2-sLD-37	44.321313	-74.115105	1335.005	155	OL-2-sOIL-129	44.323044	-74.121612	1326.579					
46	OL-2-sLD-140B-BOT	44.321725	-74.115343	1325.543	101	OL-2-sLD-38	44.321336	-74.115699	1334.705	156	OL-2-sOIL-137	44.32305	-74.12162	1326.417					
47	OL-2-sLD-143	44.323212	-74.120559	1325.475	102	OL-2-sLD-39	44.321405	-74.115119	1335.175	157	OL-2-sOIL-138	44.323146	-74.115714	1327.074					
48	OL-2-sLD-15-BOT	44.322162	-74.115331	1323.342	103	OL-2-sLD-40	44.321542	-74.115249	1333.045	158	OL-2-sOIL-139	44.321361	-74.115257	1335.364					
49	OL-2-sLD-15A-sIDE	44.323359	-74.120113	1331.007	104	OL-2-sLD-41	44.321473	-74.115175	1330.31	159	OL-2-sOIL-141	44.323334	-74.120335	1325.096					
50	OL-2-sLD-16-BOT	44.322255	-74.115453	13223															


















MACTEC

MACTEC Engineering and Geology, P.C.  
P.O. Box 7050, 511 Congress Street  
Portland, ME 04106-7050  
(207) 775-5401

NEW YORK

Department of Environmental Conservation

REMEDIAL ACTION

SARANAC LAKE GAS CO., INC.  
SARANAC LAKE, NEW YORK  
NYSDEC SITE NUMBER - 516008

CIVIL

BOTTOM OF  
ISS AREA

VERIFY SCALE

BAR IS ONE INCH ON  
ORIGINAL DRAWING. 1"

DATE

JAN 2020

PROJ

3611-16-1193

DWG

C-207

SHEET

9 OF 11

MACTEC

03/31/20

RECORD DRAWING

REVISION

CHK

DR

MAP

APVD

BY

MAP

MJS


APVD

BY

MAP

MJS

UNAUTHORIZED ALTERATION OR ADDITION TO THIS DOCUMENT IS A VIOLATION OF SECTION 7209 OF THE NEW YORK STATE EDUCATION LAW.



FILE NAME: Z:\Projects\insysect1\Saranac Lake\REC-C-208-TOP OF MONOLTH- ISS AREA.dwg PLOT DATE: Fri, 13 Mar 2020 PLOT TIME: 3:04 PM

STATE OF NEW YORK  
JAMES H. BLACK  
ENGINEER  
06031  
LICENSED PROFESSIONAL ENGINEER

03/31/20

MAP

MJS

BY

APVD

RECORD DRAWING

REVISION

CHK

APVD

MAP

NO.

1

DATE

3/31/20

DSGN

DR

MAP

BRT

CHK

APVD

BY

MJS

NEW YORK  
Department of  
Environmental  
Conservation

REMEDIAL ACTION  
SARANAC LAKE GAS CO., INC.  
SARANAC LAKE, NEW YORK  
NYSDEC SITE NUMBER - 516008

MACTEC  
Engineering and Geology, P.C.  
P.O. Box 7050, 511 Congress Street  
Portland, ME 04106  
(207) 775-5401

CIVIL  
TOP OF MONOLITH/SAND WEDGE SURVEY  
ISS AREA


VERIFY SCALE  
BAR IS ONE INCH ON  
ORIGINAL DRAWING.  
0 1"

DATE JAN 2020  
PROJ 3611-16-1193  
DWG C-208  
SHEET 10 OF 11

0 2.5 5 10  
SCALE IN FEET

THIS DRAWING IS THE PROPERTY OF MACTEC, INCLUDING ALL PATENTED AND PATENTABLE FEATURES AND/OR CONFIDENTIAL INFORMATION AND ITS USE IS CONDITIONED UPON THE USER'S AGREEMENT NOT TO REPRODUCE THE DRAWING, IN WHOLE OR PART, NOR THE MATERIAL DESCRIBED THEREON, NOR THE USE OF THE DRAWING FOR ANY PURPOSE OTHER THAN SPECIFICALLY PERMITTED IN WRITING BY MACTEC.

UNAUTHORIZED ALTERATION OR ADDITION TO THIS DOCUMENT IS A VIOLATION OF SECTION 7209 OF THE NEW YORK STATE EDUCATION LAW.



**ATTACHMENT 2**



LOCATION MAP  
NOT TO SCALE

LEGEND

- Boundary Line  
Adjoiner Line  
Gravel Road  
Overhead wires  
Chainlink Fenceline  
Adjoiner Line  
Easement Area  
ISS Limits  
Final Cap  
Found iron pipe/rebar  
Set 5/8" capped rebar  
Calculated corner

TREE KEY

- Birch  
Cherry  
Hemlock  
Maple  
Pine  
Spruce

MAP REFERENCES

1. See Map entitled "Map Showing Survey of Property for Adirondack Bottled Gas Corp." prepared by Magurk & Odono, PC, dated June 23, 1980.

NOTES

1. This survey was prepared without the benefit of an updated Abstract of Title and is subject to whatever facts an updated Abstract of Title may show.

ONLY COPIES FROM THE ORIGINAL OF THIS SURVEY MARKED WITH AN ORIGINAL OF THE LAND SURVEYOR'S EMBOSSED SEAL SHALL BE CONSIDERED TO BE VALID TRUE COPIES.

Unauthorized alteration or addition to a survey map bearing a licensed land surveyor's seal is a violation of section 7209, sub-division 2, of the New York State Education Law.

Certifications, if any, indicated hereon signify that this survey was prepared in accordance with the existing Code of Practice for Land Surveys adopted by the New York State Association of Professional Land Surveyors. Said certifications shall run only to the person for whom the survey is prepared, and on his behalf to the title company, governmental agency and lending institution listed hereon, and to the assignees of the lending institution. Certifications are not transferable to any additional institutions or subsequent owners.

GREGORY L. PEACOCK  
Reputed Owner  
L. 1386 pg. 73  
Tax parcel 32.215-6-2

GREGORY L. PEACOCK  
Reputed Owner  
L. 1028 pg. 187  
Tax parcel 32.215-6-3

GEORGE C. HUTTIG  
Reputed Owner  
L. 1384 pg. 275  
Tax parcel 32.232-1-1

DEBORAH FOX  
AUBREY FOX  
Reputed Owner  
L. 1920 pg. 186  
Tax parcel 32.232-1-2

RANDOLPH SMITH, Jr.  
LYNN LOUISE SMITH  
Reputed Owner  
L. 721 pg. 87  
Tax parcel 32.232-1-5

ESSEX COUNTY  
Reputed Owner  
L. 1415 pg. 194  
Tax parcel 32.232-1-15

JANICE M. GAUTHIER  
Reputed Owner  
L. 844 pg. 112  
Tax parcel 32.232-1-6

ROBERT OHMANN  
MARY L. OHMANN  
Reputed Owner  
L. 056 pg. 120  
Tax parcel 32.232-1-7

STEVEN P. SCHMIDT  
MONICA D. SCHMIDT  
Reputed Owner  
L. 1972 pg. 210  
Tax parcel 32.232-1-8

GEORGE E. PAYE III  
Reputed Owner  
L. 1794 pg. 120  
Tax parcel 32.232-1-9


GEORGE E. PAYE III  
Reputed Owner  
L. 1794 pg. 120  
Tax parcel 32.232-1-10

GEORGE E. PAYE III  
Reputed Owner  
L. 1794 pg. 120  
Tax parcel 32.232-1-16

COUNTY OF ESSEX  
COUNTY OF FRANKLIN  
Reputed Owner  
L. 1143 pg. 217  
Tax parcel 32.232-1-13

SARANAC LAKE GAS CO INC.  
Reputed Owner  
L. 141 pg. 392  
Tax parcel 32.231-1-11

STATE OF NEW YORK  
Reputed Owner  
L. 1951 pg. 17  
Tax parcel 32.247-4-1.2



Contour Interval: 1 Foot  
Horizontal Datum: NAD 83  
Vertical Datum: NAVD 88



GEOMATICS  
land surveying, pc

STACEY L. ALLOTT, L.S.  
P.O. BOX 1277 SARANAC LAKE, NY  
518-891-6218 Phone  
geomatisticspc@gmail.com www.geomatistics.pro

MAP OF SURVEY showing Final Conditions  
Saranac Lake Gas Company Remediation  
PREPARED FOR  
D.A. COLLINS ENVIRONMENTAL SERVICES, LLC

SITUATE IN LOT 12, TOWNSHIP 11, OLD MILITARY TRACT, VILLAGE OF SARANAC LAKE, TOWN OF NORTH ELBA, COUNTY OF ESSEX AND STATE OF NEW YORK.

REVISIONS / DATE / BY

COPYRIGHT 2021

CHECKED BY SLA

DRAWN BY REL

DATE SURVEY 06/08/22  
MAP 11/03/22

SCALE IN./FT. 1"=40'  
RATIO 1:480

TAX MAP NO. 32.231-1-11

MAP NO. 21007  
Sheet 1 of 6

CADD File: 21007 SH1016 final conditions.dwg





LOCATION MAP  
NOT TO SCALE

LEGEND

- Boundary Line
- Adjoiner Line
- Gravel Road
- Overhead wires
- Chainlink Fenceline
- Adjoiner Line
- Easement Area
- ISS Limits
- Final Cap
- Found iron pipe/rebar
- Set 5/8" capped rebar
- Calculated corner

ONLY COPIES FROM THE ORIGINAL OF THIS SURVEY MARKED WITH AN ORIGINAL OF THE LAND SURVEYOR'S EMBOSSED SEAL SHALL BE CONSIDERED TO BE VALID TRUE COPIES.

Unauthorized alteration or addition to a survey map bearing a licensed land surveyor's seal is a violation of section 7209, sub-division 2, of the New York State Education Law.

Certifications, if any, indicated hereon signify that this survey was prepared in accordance with the existing Code of Practice for Land Surveys adopted by the New York State Association of Professional Land Surveyors. Said certifications shall run only to the person for whom the survey is prepared, and on his behalf to the title company, governmental agency and lending institution listed hereon, and to the assignees of the lending institution. Certifications are not transferable to any additional institutions or subsequent owners.

GREGORY L. PEACOCK  
Reputed Owner  
L. 1366 pg. 73  
Tax parcel 32.215-6-2

GREGORY L. PEACOCK  
Reputed Owner  
L. 1028 pg. 187  
Tax parcel 32.215-6-3

GEORGE C. HUTTIG  
Reputed Owner  
L. 1384 pg. 275  
Tax parcel 32.232-1-1

DEBORAH FOX  
AUBREY FOX  
Reputed Owner  
L. 1920 pg. 186  
Tax parcel 32.232-1-2

RANDOLPH SMITH, Jr.  
LYNN LOUISE SMITH  
Reputed Owner  
L. 721 pg. 87  
Tax parcel 32.232-1-5

ESSEX COUNTY  
Reputed Owner  
L. 1419 pg. 194  
Tax parcel 32.232-1-15

JANICE M. GAUTHIER  
Reputed Owner  
L. 844 pg. 112  
Tax parcel 32.232-1-6

ROBERT OHMANN  
MARY L. OHMANN  
Reputed Owner  
L. 656 pg. 120  
Tax parcel 32.232-1-7

STEVEN P. SCHMIDT  
MONICA D. SCHMIDT  
Reputed Owner  
L. 1972 pg. 210  
Tax parcel 32.232-1-8


GEORGE E. PAYE III  
Reputed Owner  
L. 1794 pg. 120  
Tax parcel 32.232-1-9

GEORGE E. PAYE III  
Reputed Owner  
L. 1794 pg. 120  
Tax parcel 32.232-1-10

SARANAC LAKE GAS CO INC.  
Reputed Owner  
L. 141 pg. 392  
Tax parcel 32.231-1-11

GEORGE E. PAYE III  
Reputed Owner  
L. 1794 pg. 120  
Tax parcel 32.232-1-16

COUNTY OF ESSEX  
COUNTY OF FRANKLIN  
Reputed Owner  
L. 1143 pg. 217  
Tax parcel 32.232-1-13



Horizontal Datum: NAD 83  
Vertical Datum: NAVD 88



GEOMATICS  
land surveying, pc

STACEY L. ALLOTT, L.S.  
P.O. BOX 1277 SARANAC LAKE, NY  
518-891-6218 Phone  
geomatistics@gmail.com www.geomatistics.pro

MAP OF SURVEY showing Final Cap Limits Location  
Saranac Lake Gas Company Remediation

PREPARED FOR  
D.A. COLLINS ENVIRONMENTAL SERVICES, LLC

SITUATE IN LOT 12, TOWNSHIP 11, OLD MILITARY TRACT, VILLAGE OF  
SARANAC LAKE, TOWN OF NORTH ELBA, COUNTY OF ESSEX AND STATE OF NEW YORK.

REVISIONS / DATE / BY

COPYRIGHT 2021

CHECKED BY SLA

DRAWN BY REL

DATE SURVEY 06/08/22  
MAP 11/03/22

SCALE IN./FT. 1"=40'  
RATIO 1:480

TAX MAP NO. 32.231-1-11

MAP NO. 21007  
SHEET 2 of 6

CADD File: 21007 SH2of6 final cap.dwg



LOCATION MAP  
NOT TO SCALE

LEGEND

- Boundary Line
- Adjoiner Line
- Gravel Road
- Overhead wires
- Chainlink Fenceline
- Adjoiner Line
- Easement Area
- ISS Limits
- Final Cap
- Found iron pipe/rebar
- Set 5/8" capped rebar
- Calculated corner

ONLY COPIES FROM THE ORIGINAL OF THIS SURVEY MARKED WITH AN ORIGINAL OF THE LAND SURVEYOR'S EMBOSSED SEAL SHALL BE CONSIDERED TO BE VALID TRUE COPIES.

Unauthorized alteration or addition to a survey map bearing a licensed land surveyor's seal is a violation of section 7209, sub-division 2, of the New York State Education Law.

Certifications, if any, indicated hereon signify that this survey was prepared in accordance with the existing Code of Practice for Land Surveys adopted by the New York State Association of Professional Land Surveyors. Said certifications shall run only to the person for whom the survey is prepared, and on his behalf to the title company, governmental agency and lending institution listed hereon, and to the assignees of the lending institution. Certifications are not transferable to any additional institutions or subsequent owners.

GREGORY L. PEACOCK  
Reputed Owner  
L. 1386 pg. 73  
Tax parcel 32.215-6-2

GREGORY L. PEACOCK  
Reputed Owner  
L. 1028 pg. 187  
Tax parcel 32.215-6-3

GEORGE C. HUTTIG  
Reputed Owner  
L. 1384 pg. 275  
Tax parcel 32.232-1-1

DEBORAH FOX  
AUBREY FOX  
Reputed Owner  
L. 1920 pg. 186  
Tax parcel 32.232-1-2

RANDOLPH SMITH, Jr.  
LYNN LOUISE SMITH  
Reputed Owner  
L. 721 pg. 87  
Tax parcel 32.232-1-5

ESSEX COUNTY  
Reputed Owner  
L. 1419 pg. 194  
Tax parcel 32.232-1-15

JANICE M. GAUTHIER  
Reputed Owner  
L. 844 pg. 112  
Tax parcel 32.232-1-6

ROBERT OHMANN  
MARY L. OHMANN  
Reputed Owner  
L. 656 pg. 120  
Tax parcel 32.232-1-7

STEVEN P. SCHMIDT  
MONICA D. SCHMIDT  
Reputed Owner  
L. 1972 pg. 210  
Tax parcel 32.232-1-8

GEORGE E. PAYE III  
Reputed Owner  
L. 1794 pg. 120  
Tax parcel 32.232-1-9


GEORGE E. PAYE III  
Reputed Owner  
L. 1794 pg. 120  
Tax parcel 32.232-1-10

GEORGE E. PAYE III  
Reputed Owner  
L. 1794 pg. 120  
Tax parcel 32.232-1-16

COUNTY OF ESSEX  
COUNTY OF FRANKLIN  
Reputed Owner  
L. 1143 pg. 217  
Tax parcel 32.232-1-13

SARANAC LAKE GAS CO INC.  
Reputed Owner  
L. 141 pg. 392  
Tax parcel 32.231-1-11

STATE OF NEW YORK  
Reputed Owner  
L. 1951 pg. 17  
Tax parcel 32.247-4-1.2



Contour Interval: 1 Foot  
Horizontal Datum: NAD 83  
Vertical Datum: NAVD 88



GEOMATICS  
land surveying, pc

STACEY L. ALLOTT, L.S.  
P.O. BOX 1277 SARANAC LAKE, NY  
518-891-6218 Phone  
geomatisticspc@gmail.com www.geomatistics.pro

MAP OF SURVEY showing Final ISS Limits Location  
Saranac Lake Gas Company Remediation

PREPARED FOR  
D.A. COLLINS ENVIRONMENTAL SERVICES, LLC

SITUATE IN LOT 12, TOWNSHIP 11, OLD MILITARY TRACT, VILLAGE OF  
SARANAC LAKE, TOWN OF NORTH ELBA, COUNTY OF ESSEX AND STATE OF NEW YORK.

REVISIONS / DATE / BY

COPYRIGHT 2021

CHECKED BY SLA

DRAWN BY REL

DATE SURVEY 06/08/22  
MAP 11/03/22

SCALE IN./FT. 1"=40'  
RATIO 1:480

TAX MAP NO. 32.231-1-11

MAP NO. 21007  
Sheet 3 of 6

CADD File: 21007 SH3of6 ISS.dwg



LOCATION MAP  
NOT TO SCALE

LEGEND

- Boundary Line  
Adjoiner Line  
Gravel Road  
Overhead wires  
Chainlink Fenceline  
Adjoiner Line  
Easement Area  
ISS Limits  
Final Cap  
Found iron pipe/rebar  
Set 5/8" capped rebar  
Calculated corner

ONLY COPIES FROM THE ORIGINAL OF THIS SURVEY MARKED WITH AN ORIGINAL OF THE LAND SURVEYOR'S EMBOSSED SEAL SHALL BE CONSIDERED TO BE VALID TRUE COPIES.

Unauthorized alteration or addition to a survey map bearing a licensed land surveyor's seal is a violation of section 7209, sub-division 2, of the New York State Education Law.

Certifications, if any, indicated hereon signify that this survey was prepared in accordance with the existing Code of Practice for Land Surveys adopted by the New York State Association of Professional Land Surveyors. Said certifications shall run only to the person for whom the survey is prepared, and on his behalf to the title company, governmental agency and lending institution listed hereon, and to the assignees of the lending institution. Certifications are not transferable to any additional institutions or subsequent owners.

GREGORY L. PEACOCK  
Reputed Owner  
L. 1366 pg. 73  
Tax parcel 32.215-6-2

GREGORY L. PEACOCK  
Reputed Owner  
L. 1028 pg. 187  
Tax parcel 32.215-6-3

GEORGE C. HUTTIG  
Reputed Owner  
L. 1364 pg. 275  
Tax parcel 32.232-1-1

DEBORAH FOX  
AUBREY FOX  
Reputed Owner  
L. 1920 pg. 186  
Tax parcel 32.232-1-2

RANDOLPH SMITH, Jr.  
LYNN LOUISE SMITH  
Reputed Owner  
L. 721 pg. 87  
Tax parcel 32.232-1-5

ESSEX COUNTY  
Reputed Owner  
L. 1419 pg. 194  
Tax parcel 32.232-1-15

JANICE M. GAUTHIER  
Reputed Owner  
L. 844 pg. 112  
Tax parcel 32.232-1-6

ROBERT OHMANN  
MARY L. OHMANN  
Reputed Owner  
L. 056 pg. 120  
Tax parcel 32.232-1-7


STEVEN P. SCHMIDT  
MONICA D. SCHMIDT  
Reputed Owner  
L. 1972 pg. 210  
Tax parcel 32.232-1-8

GEORGE E. PAYE III  
Reputed Owner  
L. 1794 pg. 120  
Tax parcel 32.232-1-9

GEORGE E. PAYE III  
Reputed Owner  
L. 1794 pg. 120  
Tax parcel 32.232-1-10

SARANAC LAKE GAS CO INC.  
Reputed Owner  
L. 141 pg. 392  
Tax parcel 32.231-1-11

COUNTY OF ESSEX  
COUNTY OF FRANKLIN  
Reputed Owner  
L. 1143 pg. 217  
Tax parcel 32.232-1-13



Horizontal Datum: NAD 83  
Vertical Datum: NAVD 88



GEOMATICS  
land surveying, pc

STACEY L. ALLOTT, L.S.  
P.O. BOX 1277 SARANAC LAKE, NY  
518-891-6218 Phone  
geomatisticspc@gmail.com www.geomatistics.pro

MAP OF SURVEY showing Excavation Limits Location  
Saranac Lake Gas Company Remediation

PREPARED FOR  
D.A. COLLINS ENVIRONMENTAL SERVICES, LLC

SITUATE IN LOT 12, TOWNSHIP 11, OLD MILITARY TRACT, VILLAGE OF  
SARANAC LAKE, TOWN OF NORTH ELBA, COUNTY OF ESSEX AND STATE OF NEW YORK.

REVISIONS / DATE / BY

COPYRIGHT 2021

CHECKED BY SLA

DRAWN BY REL

DATE SURVEY 06/08/22  
MAP 11/03/22

SCALE IN./FT. 1"=40'  
RATIO 1:480

TAX MAP NO. 32.231-1-11

MAP NO. 21007  
Sheet 4 of 6





LOCATION MAP  
NOT TO SCALE

LEGEND

- Boundary Line
- Adjoiner Line
- Gravel Road
- Overhead wires
- Chainlink Fenceline
- Adjoiner Line
- Easement Area
- ISS Limits
- Final Cap
- Found iron pipe/rebar
- Set 5/8" capped rebar
- Calculated corner

ONLY COPIES FROM THE ORIGINAL OF THIS SURVEY MARKED WITH AN ORIGINAL OF THE LAND SURVEYOR'S EMBOSSED SEAL SHALL BE CONSIDERED TO BE VALID TRUE COPIES.

Unauthorized alteration or addition to a survey map bearing a licensed land surveyor's seal is a violation of section 7209, sub-division 2, of the New York State Education Law.

Certifications, if any, indicated hereon signify that this survey was prepared in accordance with the existing Code of Practice for Land Surveys adopted by the New York State Association of Professional Land Surveyors. Said certifications shall run only to the person for whom the survey is prepared, and on his behalf to the title company, governmental agency and lending institution listed hereon, and to the assignees of the lending institution. Certifications are not transferable to any additional institutions or subsequent owners.

GREGORY L. PEACOCK  
Reputed Owner  
L. 1366 pg. 73  
Tax parcel 32.215-6-2

GREGORY L. PEACOCK  
Reputed Owner  
L. 1028 pg. 187  
Tax parcel 32.215-6-3

GEORGE C. HUTTIG  
Reputed Owner  
L. 1364 pg. 275  
Tax parcel 32.232-1-1

DEBORAH FOX  
AUBREY FOX  
Reputed Owner  
L. 1920 pg. 126  
Tax parcel 32.232-1-2

RANDOLPH SMITH, Jr.  
LYNN LOUISE SMITH  
Reputed Owner  
L. 721 pg. 87  
Tax parcel 32.232-1-5

ESSEX COUNTY  
Reputed Owner  
L. 1419 pg. 194  
Tax parcel 32.232-1-15

JANICE M. GAUTHIER  
Reputed Owner  
L. 844 pg. 112  
Tax parcel 32.232-1-6

ROBERT OHMANN  
MARY L. OHMANN  
Reputed Owner  
L. 656 pg. 120  
Tax parcel 32.232-1-7

STEVEN P. SCHMIDT  
MONICA D. SCHMIDT  
Reputed Owner  
L. 1972 pg. 210  
Tax parcel 32.232-1-8

GEORGE E. PAYE III  
Reputed Owner  
L. 1794 pg. 120  
Tax parcel 32.232-1-9


GEORGE E. PAYE III  
Reputed Owner  
L. 1794 pg. 120  
Tax parcel 32.232-1-10

SARANAC LAKE GAS CO INC.  
Reputed Owner  
L. 141 pg. 392  
Tax parcel 32.231-1-11

GEORGE E. PAYE III  
Reputed Owner  
L. 1794 pg. 120  
Tax parcel 32.232-1-16

COUNTY OF ESSEX  
COUNTY OF FRANKLIN  
Reputed Owner  
L. 1143 pg. 217  
Tax parcel 32.232-1-13

STATE OF NEW YORK  
Reputed Owner  
L. 1951 pg. 17  
Tax parcel 32.247-4-1.2



Horizontal Datum: NAD 83  
Vertical Datum: NAVD 88




GEOMATICS  
land surveying, pc

STACEY L. ALLOTT, L.S.  
P.O. BOX 1277 SARANAC LAKE, NY  
518-891-6218 Phone  
geomatisticspc@gmail.com www.geomatistics.pro

MAP OF SURVEY showing Fenceline Location  
Saranac Lake Gas Company Remediation  
PREPARED FOR  
D.A. COLLINS ENVIRONMENTAL SERVICES, LLC  
SITUATE IN LOT 12, TOWNSHIP 11, OLD MILITARY TRACT, VILLAGE OF  
SARANAC LAKE, TOWN OF NORTH ELBA, COUNTY OF ESSEX AND STATE OF NEW YORK.

REVISIONS / DATE / BY		
COPYRIGHT	2021	
CHECKED BY	SLA	
DRAWN BY	REL	
DATE	SURVEY MAP	06/08/22 11/03/22
SCALE	IN./FT. RATIO	1"=40' 1:480
TAX MAP NO.	32.231-1-11	
MAP NO.	21007 Sheet 5 of 6	

CADD File: 21007 SHSof6 fenceline.dwg



LOCATION MAP  
NOT TO SCALE


LEGEND

- Boundary Line
- Adjoiner Line
- Gravel Road
- Overhead wires
- Chainlink Fenceline
- Adjoiner Line
- Easement Area
- ISS Limits
- Final Cap
- Found iron pipe/rebar
- Set 5/8" capped rebar
- Calculated corner

ONLY COPIES FROM THE ORIGINAL OF THIS SURVEY MARKED WITH AN ORIGINAL OF THE LAND SURVEYOR'S EMBOSSED SEAL SHALL BE CONSIDERED TO BE VALID TRUE COPIES.

Unauthorized alteration or addition to a survey map bearing a licensed land surveyor's seal is a violation of section 7209, sub-division 2, of the New York State Education Law.

Certifications, if any, indicated hereon signify that this survey was prepared in accordance with the existing Code of Practice for Land Surveys adopted by the New York State Association of Professional Land Surveyors. Said certifications shall run only to the person for whom the survey is prepared, and on his behalf to the title company, governmental agency and lending institution listed hereon, and to the assignees of the lending institution. Certifications are not transferable to any additional institutions or subsequent owners.



GEOMATICS  
land surveying, pc

STACEY L. ALLOTT, L.S.  
P.O. BOX 1277 SARANAC LAKE, NY  
518-891-6218 Phone  
geomatisticspc@gmail.com www.geomatistics.pro

MAP OF SURVEY showing Monitoring Wells Locations  
Saranac Lake Gas Company Remediation

PREPARED FOR  
D.A. COLLINS ENVIRONMENTAL SERVICES, LLC

SITUATE IN LOT 12, TOWNSHIP 11, OLD MILITARY TRACT, VILLAGE OF  
SARANAC LAKE, TOWN OF NORTH ELBA, COUNTY OF ESSEX AND STATE OF NEW YORK.

REVISIONS / DATE / BY

COPYRIGHT 2021

CHECKED BY SLA

DRAWN BY REL

DATE SURVEY 06/08/22  
MAP 11/03/22

SCALE IN./FT. 1"=40'  
RATIO 1:480

TAX MAP NO. 32.231-1-11

MAP NO. 21007  
Sheet 6 of 6

CADD File: 21007 SH606 mon\_wells.dwg

## **Appendix B**

### **Figures**

*This page intentionally left blank*












\\syracusefp\Syracuse\GIS\data\Standard\local\Saranac Lake\PROJECTS\ArcPro (aprx)\Saranac Lake Wetlands\Saranac Lake Wetlands.aprx



- Legend**
- Brandy Brook Monitoring Areas**
- BB-1
  - BB-2
  - Gravelly/coarse sand material
  - Approximate Upland Edge
  - Restored Stream Channel
  - Japanese Knotweed
  - Site Location



Map Date: 7/19/2024  
Projection: NAD 1983 State Plane New York East  
Source: WSP; ESRI


Figure 3  
Monitoring Areas and Data Collection Points - Brandy Brook West  
Saranac Lake Gas Co., Inc  
(NYSDEC Site No. 516008)  
Saranac Lake, New York








\\syracusefp\Syracuse\GISData\StateandLocal\Saranac Lake\PROJECTS\ArcPro (aprx)\Saranac Lake\SaranacLake.aprx





\\syracusefp\Syracuse\GIS\data\State\dl\ocal\Saranac Lake\PROJECTS\Ar\Pro (aprx)\Saranac Lake Wetlands\SaranacLake Wetlands.aprx



- Legend**
- ★ Site Location
  - 10 Photo Location/Direction



Note:  
The photographs referenced on this figure are presented in the Saranac Lake 2023 Annual Wetlands Monitoring Report, Appendix D (Onsite Photos).

Map Date: 7/19/2024  
Projection: NAD 1983 State Plane New York East  
Source: WSP; ESRI



**Figure 5**  
**Photograph Location Map #1**  
Saranac Lake Gas Co., Inc.  
(NYSDEC Site No. 516008)  
Saranac Lake, New York



\\syracusefp\Syracuse\GIS\data\Stateand\local\Saranac Lake\PROJECTS\ArcPro (aprx)\Saranac Lake Wetlands\Saranac Lake Wetlands.aprx



VICINITY MAP



### Legend

- ★ Site Location
- 25 Photo Location/Direction



0 75 150  
Feet

Note:  
The photographs referenced on this figure are  
presented in the Saranac Lake 2023 Annual Wetlands  
Monitoring Report, Appendix D (Onsite Photos).

Map Date: 7/19/2024  
Projection: NAD 1983 State Plane New York East  
Source: WSP; ESRI



Department of  
Environmental  
Conservation



**Figure 6**  
**Photograph Location Map #2**  
Saranac Lake Gas Co., Inc.  
(NYSDEC Site No. 516008)  
Saranac Lake, New York



*This page intentionally left blank*

**Appendix C**

**Wetland Data Sheets**

*This page intentionally left blank*

## WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Saranac lake City/County: Saranac lake / essex county Sampling Date: 2024-06-24  
Applicant/Owner: NYSDEC State: New York Sampling Point: Dpw1  
Investigator(s): TMK Section, Township, Range: \_\_\_\_\_  
Landform (hillslope, terrace, etc.): Floodplain Local relief (concave, convex, none): Concave Slope (%): 0  
Subregion (LRR or MLRA): \_\_\_\_\_ Lat: 44.32211081 Long: -74.11838117 Datum: WGS 84  
Soil Map Unit Name: \_\_\_\_\_ NWI classification: PEM

Are climatic / hydrologic conditions on the site typical for this time of year? Yes ☒ No \_\_\_\_\_ (If no, explain in Remarks.)  
Are Vegetation \_\_\_\_\_, Soil \_\_\_\_\_, or Hydrology \_\_\_\_\_ significantly disturbed? Are "Normal Circumstances" present? Yes ☒ No \_\_\_\_\_  
Are Vegetation \_\_\_\_\_, Soil \_\_\_\_\_, or Hydrology \_\_\_\_\_ naturally problematic? (If needed, explain any answers in Remarks.)

### SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present? Yes <input checked="" type="checkbox"/> No _____	Is the Sampled Area within a Wetland? Yes <input checked="" type="checkbox"/> No _____ If yes, optional Wetland Site ID: _____
Hydric Soil Present? Yes <input checked="" type="checkbox"/> No _____	
Wetland Hydrology Present? Yes <input checked="" type="checkbox"/> No _____	
Remarks: (Explain alternative procedures here or in a separate report.)	

### HYDROLOGY

Wetland Hydrology Indicators:		Secondary Indicators (minimum of two required)
Primary Indicators (minimum of one is required; check all that apply)		_____ Surface Soil Cracks (B6)
_____ Surface Water (A1)	_____ Water-Stained Leaves (B9)	<input checked="" type="checkbox"/> Drainage Patterns (B10)
<input checked="" type="checkbox"/> High Water Table (A2)	_____ Aquatic Fauna (B13)	_____ Moss Trim Lines (B16)
<input checked="" type="checkbox"/> Saturation (A3)	_____ Marl Deposits (B15)	_____ Dry-Season Water Table (C2)
_____ Water Marks (B1)	_____ Hydrogen Sulfide Odor (C1)	_____ Crayfish Burrows (C8)
_____ Sediment Deposits (B2)	_____ Oxidized Rhizospheres on Living Roots (C3)	_____ Saturation Visible on Aerial Imagery (C9)
_____ Drift Deposits (B3)	<input checked="" type="checkbox"/> Presence of Reduced Iron (C4)	_____ Stunted or Stressed Plants (D1)
_____ Algal Mat or Crust (B4)	_____ Recent Iron Reduction in Tilled Soils (C6)	_____ Geomorphic Position (D2)
_____ Iron Deposits (B5)	_____ Thin Muck Surface (C7)	_____ Shallow Aquitard (D3)
_____ Inundation Visible on Aerial Imagery (B7)	_____ Other (Explain in Remarks)	_____ Microtopographic Relief (D4)
_____ Sparsely Vegetated Concave Surface (B8)		<input checked="" type="checkbox"/> FAC-Neutral Test (D5)
<b>Field Observations:</b>		Wetland Hydrology Present? Yes <input checked="" type="checkbox"/> No _____
Surface Water Present? Yes _____ No <input checked="" type="checkbox"/> Depth (inches): _____		
Water Table Present? Yes <input checked="" type="checkbox"/> No _____ Depth (inches): <u>2</u>		
Saturation Present? Yes <input checked="" type="checkbox"/> No _____ Depth (inches): <u>0</u> (includes capillary fringe)		
Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:		
Remarks:		

**VEGETATION – Use scientific names of plants.**

 Sampling Point: Dpw1

Tree Stratum (Plot size: <u>30</u> )	Absolute % Cover	Dominant Species?	Indicator Status															
1. _____	_____	_____	_____	<b>Dominance Test worksheet:</b> Number of Dominant Species That Are OBL, FACW, or FAC: <u>8</u> (A)  Total Number of Dominant Species Across All Strata: <u>9</u> (B)  Percent of Dominant Species That Are OBL, FACW, or FAC: <u>88.88</u> (A/B)														
2. _____	_____	_____	_____															
3. _____	_____	_____	_____															
4. _____	_____	_____	_____															
5. _____	_____	_____	_____															
6. _____	_____	_____	_____															
7. _____	_____	_____	_____															
		_____ = Total Cover		<b>Prevalence Index worksheet:</b> <table style="width: 100%;"> <tr> <td style="width: 50%;">Total % Cover of:</td> <td style="width: 50%;">Multiply by:</td> </tr> <tr> <td>OBL species <u>50</u></td> <td>x 1 = <u>50</u></td> </tr> <tr> <td>FACW species <u>45</u></td> <td>x 2 = <u>90</u></td> </tr> <tr> <td>FAC species <u>0</u></td> <td>x 3 = <u>0</u></td> </tr> <tr> <td>FACU species <u>10</u></td> <td>x 4 = <u>40</u></td> </tr> <tr> <td>UPL species <u>0</u></td> <td>x 5 = <u>0</u></td> </tr> <tr> <td>Column Totals: <u>105</u> (A)</td> <td><u>180</u> (B)</td> </tr> </table> Prevalence Index = B/A = <u>1.71</u>	Total % Cover of:	Multiply by:	OBL species <u>50</u>	x 1 = <u>50</u>	FACW species <u>45</u>	x 2 = <u>90</u>	FAC species <u>0</u>	x 3 = <u>0</u>	FACU species <u>10</u>	x 4 = <u>40</u>	UPL species <u>0</u>	x 5 = <u>0</u>	Column Totals: <u>105</u> (A)	<u>180</u> (B)
Total % Cover of:	Multiply by:																	
OBL species <u>50</u>	x 1 = <u>50</u>																	
FACW species <u>45</u>	x 2 = <u>90</u>																	
FAC species <u>0</u>	x 3 = <u>0</u>																	
FACU species <u>10</u>	x 4 = <u>40</u>																	
UPL species <u>0</u>	x 5 = <u>0</u>																	
Column Totals: <u>105</u> (A)	<u>180</u> (B)																	
Sapling/Shrub Stratum (Plot size: <u>15</u> )																		
1. <u>Alnus incana</u>	<u>5</u>	<input checked="" type="checkbox"/>	<u>FACW</u>															
2. _____	_____	_____	_____															
3. _____	_____	_____	_____															
4. _____	_____	_____	_____															
5. _____	_____	_____	_____															
6. _____	_____	_____	_____															
7. _____	_____	_____	_____															
		<u>5</u> = Total Cover																
Herb Stratum (Plot size: <u>5</u> )																		
1. <u>Juncus effusus</u>	<u>15</u>	<input checked="" type="checkbox"/>	<u>OBL</u>	<b>Hydrophytic Vegetation Indicators:</b> <input type="checkbox"/> 1 - Rapid Test for Hydrophytic Vegetation <input checked="" type="checkbox"/> 2 - Dominance Test is >50% <input checked="" type="checkbox"/> 3 - Prevalence Index is ≤3.0 <sup>1</sup> <input type="checkbox"/> 4 - Morphological Adaptations <sup>1</sup> (Provide supporting data in Remarks or on a separate sheet) <input type="checkbox"/> Problematic Hydrophytic Vegetation <sup>1</sup> (Explain)  <sup>1</sup> Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.														
2. <u>Typha latifolia</u>	<u>15</u>	<input checked="" type="checkbox"/>	<u>OBL</u>															
3. <u>Verbena hastata</u>	<u>15</u>	<input checked="" type="checkbox"/>	<u>FACW</u>															
4. <u>Eupatorium perfoliatum</u>	<u>10</u>	<input checked="" type="checkbox"/>	<u>FACW</u>															
5. <u>Carex lurida</u>	<u>10</u>	<input checked="" type="checkbox"/>	<u>OBL</u>															
6. <u>Carex vulpinoidea</u>	<u>10</u>	<input checked="" type="checkbox"/>	<u>OBL</u>															
7. <u>Impatiens capensis</u>	<u>10</u>	<input checked="" type="checkbox"/>	<u>FACW</u>															
8. <u>Solidago canadensis</u>	<u>10</u>	<input checked="" type="checkbox"/>	<u>FACU</u>															
9. <u>Lysimachia nummularia</u>	<u>5</u>		<u>FACW</u>															
10. _____	_____	_____	_____															
11. _____	_____	_____	_____															
12. _____	_____	_____	_____															
		<u>100</u> = Total Cover																
Woody Vine Stratum (Plot size: <u>30</u> )																		
1. _____	_____	_____	_____															
2. _____	_____	_____	_____															
3. _____	_____	_____	_____															
4. _____	_____	_____	_____															
		_____ = Total Cover																
Remarks: (Include photo numbers here or on a separate sheet.)																		



**SOIL**

Sampling Point: Dpw1

**Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)**

Depth (inches)	Matrix		Redox Features				Texture	Remarks
	Color (moist)	%	Color (moist)	%	Type <sup>1</sup>	Loc <sup>2</sup>		
0 - 4	10YR 2/2	100					Sandy Loam	
4 - 12	10YR 4/2	85	10YR 5/1	15	D	M	Sandy Loam	
12 - 16	10YR 5/2	90	10YR 5/1	10	D	M	Sandy Loam	
-								
-								
-								
-								
-								
-								
-								
-								
-								
-								
-								

<sup>1</sup>Type: C=Concentration, D=Depletion, RM=Reduced Matrix, MS=Masked Sand Grains.

<sup>2</sup>Location: PL=Pore Lining, M=Matrix.

**Hydric Soil Indicators:**

- |   |  |
|---|--|
| <input type="checkbox"/> Histosol (A1)                        | <input type="checkbox"/> Polyvalue Below Surface (S8) (LRR R, MLRA 149B) |
| <input type="checkbox"/> Histic Epipedon (A2)                 | <input type="checkbox"/> Thin Dark Surface (S9) (LRR R, MLRA 149B)       |
| <input type="checkbox"/> Black Histic (A3)                    | <input type="checkbox"/> Loamy Mucky Mineral (F1) (LRR K, L)             |
| <input type="checkbox"/> Hydrogen Sulfide (A4)                | <input type="checkbox"/> Loamy Gleyed Matrix (F2)                        |
| <input type="checkbox"/> Stratified Layers (A5)               | <input checked="" type="checkbox"/> Depleted Matrix (F3)                 |
| <input type="checkbox"/> Depleted Below Dark Surface (A11)    | <input type="checkbox"/> Redox Dark Surface (F6)                         |
| <input type="checkbox"/> Thick Dark Surface (A12)             | <input type="checkbox"/> Depleted Dark Surface (F7)                      |
| <input type="checkbox"/> Sandy Mucky Mineral (S1)             | <input type="checkbox"/> Redox Depressions (F8)                          |
| <input type="checkbox"/> Sandy Gleyed Matrix (S4)             |  |
| <input type="checkbox"/> Sandy Redox (S5)                     |  |
| <input type="checkbox"/> Stripped Matrix (S6)                 |  |
| <input type="checkbox"/> Dark Surface (S7) (LRR R, MLRA 149B) |  |

**Indicators for Problematic Hydric Soils<sup>3</sup>:**

- ☐ 2 cm Muck (A10) (LRR K, L, MLRA 149B)
- ☐ Coast Prairie Redox (A16) (LRR K, L, R)
- ☐ 5 cm Mucky Peat or Peat (S3) (LRR K, L, R)
- ☐ Dark Surface (S7) (LRR K, L)
- ☐ Polyvalue Below Surface (S8) (LRR K, L)
- ☐ Thin Dark Surface (S9) (LRR K, L)
- ☐ Iron-Manganese Masses (F12) (LRR K, L, R)
- ☐ Piedmont Floodplain Soils (F19) (MLRA 149B)
- ☐ Mesic Spodic (TA6) (MLRA 144A, 145, 149B)
- ☐ Red Parent Material (F21)
- ☐ Very Shallow Dark Surface (TF12)
- ☐ Other (Explain in Remarks)

<sup>3</sup>Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

**Restrictive Layer (if observed):**

Type: \_\_\_\_\_

Depth (inches): \_\_\_\_\_

Hydric Soil Present? Yes ☒ No ☐

Remarks:

## WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Saranac lake City/County: Saranac lake / essex county Sampling Date: 2024-06-24  
Applicant/Owner: NYSDEC State: New York Sampling Point: Dpw2  
Investigator(s): TMK Section, Township, Range: \_\_\_\_\_  
Landform (hillslope, terrace, etc.): Floodplain Local relief (concave, convex, none): Concave Slope (%): 0  
Subregion (LRR or MLRA): \_\_\_\_\_ Lat: 44.32122824 Long: -74.1178153 Datum: WGS 84  
Soil Map Unit Name: \_\_\_\_\_ NWI classification: Pfo/pss

Are climatic / hydrologic conditions on the site typical for this time of year? Yes ☒ No \_\_\_\_\_ (If no, explain in Remarks.)  
Are Vegetation \_\_\_\_\_, Soil \_\_\_\_\_, or Hydrology \_\_\_\_\_ significantly disturbed? Are "Normal Circumstances" present? Yes ☒ No \_\_\_\_\_  
Are Vegetation \_\_\_\_\_, Soil \_\_\_\_\_, or Hydrology \_\_\_\_\_ naturally problematic? (If needed, explain any answers in Remarks.)

### SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present? Yes <input checked="" type="checkbox"/> No _____	Is the Sampled Area within a Wetland? Yes <input checked="" type="checkbox"/> No _____ If yes, optional Wetland Site ID: _____
Hydric Soil Present? Yes <input checked="" type="checkbox"/> No _____	
Wetland Hydrology Present? Yes <input checked="" type="checkbox"/> No _____	
Remarks: (Explain alternative procedures here or in a separate report.)	

### HYDROLOGY

Wetland Hydrology Indicators:		Secondary Indicators (minimum of two required)
Primary Indicators (minimum of one is required; check all that apply)		<input checked="" type="checkbox"/> Surface Soil Cracks (B6)
<input checked="" type="checkbox"/> Surface Water (A1)	<input type="checkbox"/> Water-Stained Leaves (B9)	<input checked="" type="checkbox"/> Drainage Patterns (B10)
<input checked="" type="checkbox"/> High Water Table (A2)	<input type="checkbox"/> Aquatic Fauna (B13)	<input type="checkbox"/> Moss Trim Lines (B16)
<input checked="" type="checkbox"/> Saturation (A3)	<input type="checkbox"/> Marl Deposits (B15)	<input type="checkbox"/> Dry-Season Water Table (C2)
<input type="checkbox"/> Water Marks (B1)	<input type="checkbox"/> Hydrogen Sulfide Odor (C1)	<input type="checkbox"/> Crayfish Burrows (C8)
<input checked="" type="checkbox"/> Sediment Deposits (B2)	<input type="checkbox"/> Oxidized Rhizospheres on Living Roots (C3)	<input type="checkbox"/> Saturation Visible on Aerial Imagery (C9)
<input checked="" type="checkbox"/> Drift Deposits (B3)	<input checked="" type="checkbox"/> Presence of Reduced Iron (C4)	<input type="checkbox"/> Stunted or Stressed Plants (D1)
<input type="checkbox"/> Algal Mat or Crust (B4)	<input type="checkbox"/> Recent Iron Reduction in Tilled Soils (C6)	<input type="checkbox"/> Geomorphic Position (D2)
<input type="checkbox"/> Iron Deposits (B5)	<input type="checkbox"/> Thin Muck Surface (C7)	<input type="checkbox"/> Shallow Aquitard (D3)
<input type="checkbox"/> Inundation Visible on Aerial Imagery (B7)	<input type="checkbox"/> Other (Explain in Remarks)	<input type="checkbox"/> Microtopographic Relief (D4)
<input type="checkbox"/> Sparsely Vegetated Concave Surface (B8)		<input checked="" type="checkbox"/> FAC-Neutral Test (D5)
<b>Field Observations:</b>		Wetland Hydrology Present? Yes <input checked="" type="checkbox"/> No _____
Surface Water Present? Yes <input checked="" type="checkbox"/> No _____ Depth (inches): <u>2</u>		
Water Table Present? Yes <input checked="" type="checkbox"/> No _____ Depth (inches): <u>0</u>		
Saturation Present? Yes <input checked="" type="checkbox"/> No _____ Depth (inches): <u>0</u> (includes capillary fringe)		
Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:		
Remarks:		

**VEGETATION – Use scientific names of plants.**

 Sampling Point: Dpw2

Tree Stratum (Plot size: <u>30</u> )	Absolute % Cover	Dominant Species?	Indicator Status															
1. <u>Acer rubrum</u>	<u>15</u>	<input checked="" type="checkbox"/>	<u>FAC</u>	<b>Dominance Test worksheet:</b> Number of Dominant Species That Are OBL, FACW, or FAC: <u>8</u> (A)  Total Number of Dominant Species Across All Strata: <u>8</u> (B)  Percent of Dominant Species That Are OBL, FACW, or FAC: <u>100.00</u> (A/B)														
2. <u>Acer saccharinum</u>	<u>15</u>	<input checked="" type="checkbox"/>	<u>FACW</u>															
3. <u>Betula populifolia</u>	<u>10</u>	<input checked="" type="checkbox"/>	<u>FAC</u>															
4. _____	_____	_____	_____															
5. _____	_____	_____	_____															
6. _____	_____	_____	_____															
7. _____	_____	_____	_____															
			<u>40</u> = Total Cover	<b>Prevalence Index worksheet:</b> <table style="width: 100%;"> <tr> <td style="width: 50%;">Total % Cover of:</td> <td style="width: 50%;">Multiply by:</td> </tr> <tr> <td>OBL species <u>65</u></td> <td>x 1 = <u>65</u></td> </tr> <tr> <td>FACW species <u>55</u></td> <td>x 2 = <u>110</u></td> </tr> <tr> <td>FAC species <u>25</u></td> <td>x 3 = <u>75</u></td> </tr> <tr> <td>FACU species <u>5</u></td> <td>x 4 = <u>20</u></td> </tr> <tr> <td>UPL species <u>0</u></td> <td>x 5 = <u>0</u></td> </tr> <tr> <td>Column Totals: <u>150</u> (A)</td> <td><u>270</u> (B)</td> </tr> </table> Prevalence Index = B/A = <u>1.80</u>	Total % Cover of:	Multiply by:	OBL species <u>65</u>	x 1 = <u>65</u>	FACW species <u>55</u>	x 2 = <u>110</u>	FAC species <u>25</u>	x 3 = <u>75</u>	FACU species <u>5</u>	x 4 = <u>20</u>	UPL species <u>0</u>	x 5 = <u>0</u>	Column Totals: <u>150</u> (A)	<u>270</u> (B)
Total % Cover of:	Multiply by:																	
OBL species <u>65</u>	x 1 = <u>65</u>																	
FACW species <u>55</u>	x 2 = <u>110</u>																	
FAC species <u>25</u>	x 3 = <u>75</u>																	
FACU species <u>5</u>	x 4 = <u>20</u>																	
UPL species <u>0</u>	x 5 = <u>0</u>																	
Column Totals: <u>150</u> (A)	<u>270</u> (B)																	
<b>Sapling/Shrub Stratum (Plot size: <u>15</u> )</b>																		
1. <u>Alnus incana</u>	<u>10</u>	<input checked="" type="checkbox"/>	<u>FACW</u>															
2. _____	_____	_____	_____															
3. _____	_____	_____	_____															
4. _____	_____	_____	_____															
5. _____	_____	_____	_____															
6. _____	_____	_____	_____															
7. _____	_____	_____	_____															
			<u>10</u> = Total Cover															
<b>Herb Stratum (Plot size: <u>5</u> )</b>																		
1. <u>Carex scoparia</u>	<u>20</u>	<input checked="" type="checkbox"/>	<u>FACW</u>	<b>Hydrophytic Vegetation Indicators:</b> <input type="checkbox"/> 1 - Rapid Test for Hydrophytic Vegetation <input checked="" type="checkbox"/> 2 - Dominance Test is >50% <input checked="" type="checkbox"/> 3 - Prevalence Index is ≤3.0 <sup>1</sup> <input type="checkbox"/> 4 - Morphological Adaptations <sup>1</sup> (Provide supporting data in Remarks or on a separate sheet) <input type="checkbox"/> Problematic Hydrophytic Vegetation <sup>1</sup> (Explain)  <sup>1</sup> Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.														
2. <u>Carex lurida</u>	<u>20</u>	<input checked="" type="checkbox"/>	<u>OBL</u>															
3. <u>Carex lupulina</u>	<u>15</u>	<input checked="" type="checkbox"/>	<u>OBL</u>															
4. <u>Carex vulpinoidea</u>	<u>15</u>	<input checked="" type="checkbox"/>	<u>OBL</u>															
5. <u>Juncus effusus</u>	<u>10</u>	_____	<u>OBL</u>															
6. <u>Verbena hastata</u>	<u>10</u>	_____	<u>FACW</u>															
7. <u>Solidago canadensis</u>	<u>5</u>	_____	<u>FACU</u>															
8. <u>Scirpus atrovirens</u>	<u>5</u>	_____	<u>OBL</u>															
9. _____	_____	_____	_____															
10. _____	_____	_____	_____															
11. _____	_____	_____	_____															
12. _____	_____	_____	_____															
			<u>100</u> = Total Cover															
<b>Woody Vine Stratum (Plot size: <u>30</u> )</b>																		
1. _____	_____	_____	_____	<b>Definitions of Vegetation Strata:</b>  <b>Tree</b> – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.  <b>Sapling/shrub</b> – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.  <b>Herb</b> – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.  <b>Woody vines</b> – All woody vines greater than 3.28 ft in height.														
2. _____	_____	_____	_____															
3. _____	_____	_____	_____															
4. _____	_____	_____	_____															
			_____ = Total Cover															
Remarks: (Include photo numbers here or on a separate sheet.)																		

## SOIL

Sampling Point: Dpw2**Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)**

Depth (inches)	Matrix		Redox Features				Texture	Remarks
	Color (moist)	%	Color (moist)	%	Type <sup>1</sup>	Loc <sup>2</sup>		
0 - 2	10YR 3/1	100					Loamy Sand	
2 - 16	10YR 4/2	90	10YR 5/2	10	D	M	Loamy Sand	
-								
-								
-								
-								
-								
-								
-								
-								
-								
-								
-								
-								
-								
-								

<sup>1</sup>Type: C=Concentration, D=Depletion, RM=Reduced Matrix, MS=Masked Sand Grains.<sup>2</sup>Location: PL=Pore Lining, M=Matrix.**Hydric Soil Indicators:**

- |   |  |
|---|--|
| <input type="checkbox"/> Histosol (A1)                        | <input type="checkbox"/> Polyvalue Below Surface (S8) (LRR R, MLRA 149B) |
| <input type="checkbox"/> Histic Epipedon (A2)                 | <input type="checkbox"/> Thin Dark Surface (S9) (LRR R, MLRA 149B)       |
| <input type="checkbox"/> Black Histic (A3)                    | <input type="checkbox"/> Loamy Mucky Mineral (F1) (LRR K, L)             |
| <input type="checkbox"/> Hydrogen Sulfide (A4)                | <input type="checkbox"/> Loamy Gleyed Matrix (F2)                        |
| <input type="checkbox"/> Stratified Layers (A5)               | <input checked="" type="checkbox"/> Depleted Matrix (F3)                 |
| <input type="checkbox"/> Depleted Below Dark Surface (A11)    | <input type="checkbox"/> Redox Dark Surface (F6)                         |
| <input type="checkbox"/> Thick Dark Surface (A12)             | <input type="checkbox"/> Depleted Dark Surface (F7)                      |
| <input type="checkbox"/> Sandy Mucky Mineral (S1)             | <input type="checkbox"/> Redox Depressions (F8)                          |
| <input type="checkbox"/> Sandy Gleyed Matrix (S4)             |  |
| <input type="checkbox"/> Sandy Redox (S5)                     |  |
| <input type="checkbox"/> Stripped Matrix (S6)                 |  |
| <input type="checkbox"/> Dark Surface (S7) (LRR R, MLRA 149B) |  |

**Indicators for Problematic Hydric Soils<sup>3</sup>:**

- |  |
|--|
| <input type="checkbox"/> 2 cm Muck (A10) (LRR K, L, MLRA 149B)       |
| <input type="checkbox"/> Coast Prairie Redox (A16) (LRR K, L, R)     |
| <input type="checkbox"/> 5 cm Mucky Peat or Peat (S3) (LRR K, L, R)  |
| <input type="checkbox"/> Dark Surface (S7) (LRR K, L)                |
| <input type="checkbox"/> Polyvalue Below Surface (S8) (LRR K, L)     |
| <input type="checkbox"/> Thin Dark Surface (S9) (LRR K, L)           |
| <input type="checkbox"/> Iron-Manganese Masses (F12) (LRR K, L, R)   |
| <input type="checkbox"/> Piedmont Floodplain Soils (F19) (MLRA 149B) |
| <input type="checkbox"/> Mesic Spodic (TA6) (MLRA 144A, 145, 149B)   |
| <input type="checkbox"/> Red Parent Material (F21)                   |
| <input type="checkbox"/> Very Shallow Dark Surface (TF12)            |
| <input type="checkbox"/> Other (Explain in Remarks)                  |

<sup>3</sup>Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.**Restrictive Layer (if observed):**

Type: \_\_\_\_\_

Depth (inches): \_\_\_\_\_

Hydric Soil Present? Yes ☒ No ☐

Remarks:

**Appendix D**

**On-Site Photographs**

*This page intentionally left blank*



**Photograph 1:** Lack of woody vegetation along the bank in Monitoring Area LF-1.



**Photograph 2:** Overview of Monitoring Areas LF-1 and LF-2.



**Photograph 3:** Surviving live stakes observed at the transition from Monitoring Area LF-2 and LF-3.



**Photograph 4:** Dead live stakes observed within Monitoring Area LF-2.





**Photograph 5:** Signs of wildlife browsing on live stakes planted within Monitoring Area LF-3.



**Photograph 6:** Beaver activity observed on trees along the banks within Monitoring Area LF-3.



**Photograph 7:** Successful live stakes along the banks within Monitoring Area LF-3.



**Photograph 8:** Mature trees along the banks within Monitoring Area LF-3.





**Photograph 9:** Live stakes successfully growing under mature trees within Monitoring Area LF-3.



**Photograph 10:** Vegetated and stable banks within Monitoring Area LF-3.



**Photograph 11:** Existing woody shrubs along the banks within Monitoring Area LF-3.



**Photograph 12:** Cedar Planting Area on the South bank of Lake Flower.





**Photograph 13:** Rip rap bank and partially vegetated areas at the northwestern portion of Brandy Brook.



**Photograph 14:** View of well vegetated stream banks, facing upstream along Brandy Brook.



**Photograph 15:** View facing upstream of Brandy Brook along Brandy Brook Avenue.



**Photograph 16:** View facing upstream of the eastern portion of Monitoring Area BB-1.





**Photograph 17:** Easternmost portion of Monitoring Area BB-1.



**Photograph 18:** Area of street runoff along the top of banks of Brandy Brook at the northern portion of BB-2.



**Photograph 19:** Rip-rap slope of Brandy Brook at the northern end of BB-2 along Brandy Brook Avenue.



**Photograph 20:** Area of concern at historic culvert on the northern end of Monitoring Area BB-2.






**Photograph 21:** View facing upstream of Brandy Brook, withing Monitoring area BB-2.



**Photograph 22:** View facing upstream of Brandy Brook, withing Monitoring area BB-2.



**Photograph 23:** Area of previously identified and treaded invasive species (Japanese knotweed).




**Photograph 24:** Partially submerged stable drop log structure observed along Brandy Brook within





**Photograph 25:** View of stable stream channel bank with core log structure along Area BB-2.



**Photograph 26:** Submerged stable rock vane structure within Brandy Brook within Monitoring Area BB-2.



**Photograph 27:** Well vegetated and stable stream banks of Brank Brook within Area BB-2.



**Photograph 28:** Restored emergent wetland area identified at Monitoring Area Wet-1.





**Photograph 29:** View facing south from Monitoring Area Wet-1.



**Photograph 30:** saturated soils identified within the soil sample at Monitoring Area Wet-1.



**Photograph 31:** Groundwater identified within soil sample pit at Monitoring Area Wet-1.



**Photograph 32:** Large alder shrubs located within Monitoring Area Wet-1.





**Photograph 33:** Southern portion of Brandy Brook between wetland areas Wet-1 and Wet-2.



**Photograph 34:** Restored stream channel within Monitoring Area Wet-2.



**Photograph 35:** Submerged drop log structure within the restored stream channel within Monitoring Area Wet-2.



**Photograph 36:** 2023 planted trees within Monitoring Area Wet-2.





**Photograph 37:** Overview of Monitoring Area Wet-2.



**Photograph 38:** Restored stream channel within Monitoring Area Wet-2.



**Photograph 39:** 2023 tire rut areas now revegetated within the area of Wet-2.



**Photograph 40:** Sandy soils with redox features observed within Monitoring Area Wet-2.





**Photograph 41:** Saturated wetland soils within Wet-2.



**Photograph 42:** 2023 planted tree within Wet-2 with tree staking.



**Photograph 43:** Submerged aquatic vegetation observed in the open water area of LF-1.



**Photograph 44:** Green frog observed in the area of Wet-2.

*This page intentionally left blank*