

Project: <u>Prinoschield</u>	Date: <u>12-1-20</u>
Location: <u>St. Vincent St., Utica</u>	Project No.: <u>633027</u>
Personnel: <u>AS</u>	Field Conditions: <u>Cloudy, Showers</u>

4" Well = .66 gal/ft
6" Well = 1.47 gal/ft

Report No. (Site Name) - NYSDEC Site No. 633027 Date: 12-1-20


 Department of
Environmental
Conservation

Report No. _____ (Site Name) - NYSDEC Site No. 633027 Date: 12-1-20

Report No. _____ (Site Name) - NYSDEC Site No. 633027 Date: 12-1-20

[illegible][illegible]

*On-Site scale for off-site shipment, delivery ticket for material received

Equipment/Material Tracking Comments:

Report No. _____ (Site Name) - NYSDEC Site No. 633027 Date: 12-1-20

Prismshield






DAILY INSPECTION REPORT

Page 4 of 9

Report No. _____ (Site Name) - NYSDEC Site No. 633027 Date: 12-1-20

Princeton Id


Include (insert) figures with markups showing location of work and job progress



DAILY INSPECTION REPORT

Report No. _____ (Site Name) - NYSDEC Site No. 633027 Date: 12-1-20
Prinoshield

Page 5 of 9



DAILY INSPECTION REPORT

Page 6 of 9

Report No. (Site Name) - NYSDEC Site No. 633027 Date: 12-1-20

Princeton

Site Photographs (Descriptions Below)	

Report No.

(Site Name) - NYSDEC Site No. 633027

Date: 12-1-20

Page 7 of 9

Primoshield

Comments	
Site Inspector(s):	Date: