



NOV 2 3 2020

	STRU	JCTURE	INSPECTION	V
--	------	--------	------------	---

ENVIRONMENTAL REMEDIATION REGION 7 - SYRACUSE

	Routine or Non-Rou	tine (circ	le one)		STRACUSE
Address:	4556 Water House Rt C	JAY, I	UY	Structure ID	#: Eagle COM
Performed by:	Mark lucker			Dat	e:_11-13-20
Have the follow	ring items changed since the last visit?				
Building Foot Pr				<u>Yes</u>	No
Basement/Slab					
Heating / Ventila	iting Systems				1/
Basement Finish	1				
Crawlspaces					
Drains, Sumps, I	Floor Cracks				
Wall Penetration	s, Cracks				
Appliances (in ba	asement)				<u> </u>
Siding					
Are there any ne in previously exis	w buildings on the property or conversion o sting building? If Yes, describe in comments section belo				
Ownership	•				
	If Yes, write new owner name contact information Date of Ownership Change Owner Name Telephone No.	rmation be	elow		
If any of these is maintenance su	tems have changed, a redesign may be r ipervisor for field review.	equired.	Contact the		
Documentation Were digital photon	tographs taken of the entire system?	Yes	No		
	vner provided "Operational Fact Sheet"?	Yes	□No	No - has already	been provided
Was the drawing	updated to show any changes?	Yes	□ No.	√N/A	
Was a Service C not be addressed	all filed for items that could during this visit?	Yes	No	□ N/A	
Comments					
×					
			-		



### FAN AND ELECTRICAL

		Routine or	Non-Routi	ine (circle	one)						
Address: 4366 Wat	erhou	J50	Rd		Str	ucture ID #	# Ecc	ale C	Comt	CONTIC	:5 .
Performed by: Mark Tu	cken					Date	:_11-	13-2	<u>Comt</u>		
Equipment Documentation		8									
Manometer Reading at Fan Inlet (" w.c. )	/acuum)										
Fan #	HP 720	,	HP220				T	7			
Fan Model	1		2	1	1	ļ	<b>-</b>	_			
Manometer Reading (Prior Commissioned)	*		X				<del></del>	-			
Manometer Reading (As Found)	*		×		<b>-</b>	<del>                                     </del>	+	-			
Manometer Reading (As Left)	*		*	<del> </del>		<b>-</b>	+-	$\dashv$			
		L1	7	<u> </u>		<u> </u>					
Manometer Reading at Sub-Slab SSPs (" Note: For SSPs located in accessible cran	w.c. vacu wispaces w	um) ith EPDM me	embrane, u	use the cra	wlspace field	form to re	cord the S	SSP manon	neter reading	j.	
SSP#	İ	2	3	14	15	La	T	T			
Manometer Reading (Prior Commissioned)	23/4	27/8	23/4	2 3/4	27/8	23/4	†	-			
Manometer Reading (As Found)	23/4	23/4	23/4	27/8		27/5	,	$\dashv$			
Meet Criteria?**	٠,	Ú	TO T	TU O	100	10/8	1	-			
Manometer Reading (As Left)	23/4	23/4	23/4	27/9	2 7/8	27/2	1	-			
Fan System Inspection		LA 171	Sun of the			1/2 1/6		┙			
Is fan cover still present?			_	As Foun	_			As Le	<u>ft</u>		
Each fan mounted securely?		100	Yes	□ No	☐ NA		Yes	☐ No	<b>□</b> UC		
Coupling connections secure?			Yes Yes	∐ No □ No			Yes	☐ No	<b>∑</b> Uc		
Is excessive noise heard when fan is running	g?		-	No.			Yes	☐ No	Uc		
Switch is locked in the ON position?				DINO			☐ Yes☐ Yes	No	∑ uc		
Is set point indicated on speed controller?		i	Yes	□No	NA		Yes	No	UC		
Has fan been in continuous operation since	previous vis	it?	Yes	No	The state of the s		☐Yes	∐ No □ No	UC		
Is the pipe penetration sealed on the structu	re's exterior	1	Yes	□No	- NA		Yes	□ No	UC		
Is the downspout/PVC junction sufficiently se	ealed?	1	Yes	□ No	D NA		Yes	□ No	UC		
ls conduit penetration sealed on the structur	e's exterior'	? . [	Yes	□ No	NA		Yes	□ No	AZZ UC		
Each fan runs when switch is ON position?		1	Yes	☐ No			Yes	□No	TUC		
Each fan stops when switch is in OFF position	on?	ী	Yes	No			Yes	□ No	Duc		
Does the condensate line appear to be funct	tioning corre	ectly? [	Yes	□ No 🤺	NA		Yes	No	Duc		
s each fan below its maximum vacuum?		E	Yes	☐ No	* N/4		Yes	No	Duc		
(HP220 = 2.5" w.c., GP501 = 4.25" w.c., FR f fan vacuum is at maximum, measure velou	-250 = 2.6"	w.c., HS-50	00 = 53" w	.c.)	1				Ass		
SSP #	city at each	SSP (record	below).		T			_			
								_			
/elocity at SSP (As Found)								_			
/elocity at SSP (As Left) Does the SSP velocity meet criteria ( > 1 ft/n	nin\2				لــــا		-				
	inity f	Ł	Yes	No	NA		Yes	☐ No	Duc		
Electrical System Inspection											
Are all electrical connections secure?		7	Yes	□No			Yes	Ο.,	<b>N</b> ET		
Each junction box closed?		-		No			Yes	☐ No	Duc		
Conduit/Wire properly supported?				☐ No			Yes	□ No	Duc		
Are audible alarm(s) present and working pro	perly?			☐ No	NA NA		Yes	□ No	Duc		
Are appliances affected by fan operation?			Yes	Duo.			Yes	No	Duc		
abeling Inspection								1			
Correct labels applied in proper location? ***		<u> </u>	Yes	□No			Yes	☐ No	Duc		
Are labels still legible?		-		☐ No			Yes	□ No	Duc		
s SSDS breaker identified in the electrical pa		7	- 9.	□ No			Yes	□No	Duc		
Commissioned value written on SSP sticker?		Ď	Yes	☐ No			Yes	No	Duc		
Comments/Corrective Action			1						1		

As Found conditions = before corrective action. [NA = Not Applicable]
 As Left conditions = after corrective action. [UC = Unchanged from As Found conditions]

As Left conditions = after corrective action, [UC = Unchanged from As Found conditions]

\*\*Oriteria is met if deviation is less than or equal to 0.25\*wc (for all fans with the exception of the HS-5000). For an HS-5000 fan, criteria is met if deviation is less than or equal to 10% of the prior commissioned value or less than or equal to 0.25\*wc, whichever is greater.

If deviation exceeds criteria (0.25\*wc or 10% of prior commissioned value, as applicable), conduct communication testing and document on Re-Commissioning Field Form.

\*\*\*Correct labels are at least one green label per floor and one white sticker at every suction point.



## PIPING, SLAB AND WALL

Routine or Non-Routine (circle one)								
Address: 4566 Water Ho	use Rd	_		Structur	e ID #:	لهمع	e Co	M
Performed by: Mark Turk	ker	_			Date:	11-1	3-20	_
Piping Check System suction point seals are accessible?		<b>X</b>	As Found	ı L		î <del>sc</del> i	As Left	
System suction points are sealed to the slab?		Yes	□ No □ No			Yes	∐ No	UC
Each component is installed?		Yes	□ No		-	Yes	□ No □ No	UC
Piping system is properly supported (6'-horizont	al/8'-vertical)	Yes	□ No			Yes	□ No	Duc
Excessive noise is heard in piping joints?		Yes	No			Yes	No	Duc
Smoke 10% of all pipe joints and/or piping modifi	cations?	Yes	No			Yes	No	Duc
Did smoke enter joints? **		Yes	No			Yes	No	Quo
Floor Check								
Are areas of the slab not visible (e.g. floor coveri	ng)?	Yes	No			Yes	No	Duc
Are areas of the slab not accessible (e.g. stored	items)?	Yes	☐ No			Yes	☐ No	Duc
Were drawing-identified slab crack repairs/modif Did smoke enter? **	ications smoke tested?	Yes	No	NA		Yes	☐ No	Duc
Are other cracks present that did not draw smoke		Yes	☐ No	NA		Yes	☐ No	Duc
Are other cracks present that did draw smoke?**		☐ Yes ☐ Yes	DNo DNo	∐ NA □ NA		Yes	No	Buc
Were newly identified slab cracks indicated on di		Yes	□ No	D NA		☐ Yes ☐ Yes	No No	
Check and clean Dranjer(s)?	ŭ	Yes	□No	DINA		Yes	□ No	
Smoke Dranjer(s)?		Yes	No	ANA		Yes	□ No	4 Duc
Wall Check								
Are areas of the walls not visible (e.g. finished wa	alls)?	Yes	□No			Yes	No	Duc
Are areas of the walls not accessible (e.g. stored	items)?	Yes	□No			Yes	□ No	
Were drawing-identified wall crack repairs/modifications smoke tested?			☐ No	NA NA		Yes	□ No	Duc
Did smoke enter wall crack(s)? **  Are other wall cracks/penetrations present that did not draw smoke?			☐ No	NA		Yes	☐ No	"Duc
Are other wall cracks/penetrations present that did draw smoke?  Are other wall cracks/penetrations present that did draw smoke?**			No	☐ NA		Yes	No	Duc
Were newly identified wall cracks indicated on drawing?			No.	□ NA		∐ Yes	No	UC
Is top course of block wall open?			□ No □ No	DINA DINA		☐ Yes☐ Yes	∐ No □ No	UC
Smoke top course of block wall (open-top block only)?			□No	DAMA		Yes	□ No	Duc
Did smoke enter top course? **			No	NA		Yes	□ No	Duc
Are utility penetrations sealed so they don't draw	smoke?	Yes	No			Yes	No	Quo
Sump Check								
Have any non-approved modifications been mad	e to sump cover?	Yes	No	NA		Yes	No	Duc
Is sump cover structurally sound?		Yes	☐ No	NA		Yes	☐ No	Duc
Verify integrity of sump cover seal?  Does sealed sump cover draw smoke? **		Yes	☐ No	NA		Yes	☐ No	Dyc
boos scaled sump cover draw smoke?		∐ Yes	No	NA		Yes	☐ No	Duc
Exhaust Stack Check		-						
Distance above eave	Commissioned distance		1	_		Criteria:	≥ 1 ft	
Distance from nearest opening	Commissioned distance	:>	10-	_		Criteria:	≥ 10 ft	
Distance above nearest opening	Commissioned distance		2			Criteria:	≥ 2 ft	-
Are vertical exhaust stack supports installed ever	ry 8' maximum?	Yes	□ No	☐ NA		Yes	No	Dinc
Distances from stack exhaust to openings appea *** If the existing exhaust stack is modified and/o the "Stack Modification Field Form" and attach	r to be unchanged? r removed and replaced :	Yes as part of n	□ No on-routine s	system ma	intenar	Yes nce, comp	□ No lete	Duc
Comments								
					······································			_

Notes:

\* As Found conditions = before corrective action. [NA = Not Applicable]

\* As Left conditions = after corrective action. [UC = Unchanged from As Found conditions]

\*\* If answered YES to this question, perform corrective action and re-test.



#### **CRAWLSPACE**

•	Routin	or Non-Routine (c	circle one)		
Address:	4566 W	ter House I	Rd Stru	cture ID #: &ag	e Cor
Performed by:	Mark Tuc	KeR	_	Date: ] \ -	3-20
Inaccessible Crawlspace (V	entilation)	NA			
As Found*	Crawispace 1	Crawlspace 2	Crawlspace 3	Crawlspace 4	7
SSP#	1				1
Target Velcocity (fpm)					1
Measured Velocity (fpm)	- 1 N. man 1 1 1 1				
Meets Criteria? **	. M	and person -		OF THE PARTY OF THE PARTY OF	San Sandara
As Left*	Crawlspace 1	Crawlspace 2	Crawlspace 3	Crawlspace 4	]
SSP#	Gramspace 1	Oramspace 2	Orawispace 3	Orawispace 4	1
Target Velcocity (fpm)				).	1
Measured Velocity (fpm)					]
Meets Criteria? **					
Is sampling port to Inaccessib plug?	le crawl space thread	led with a Yes	No	Yes No	
Accessible Crawlspace (Sul	o-Membrane Depres	surization)	⊠NA		
As Found*	Crawlspace 1	Crawlspace 2	Crawlspace 3	Crawlspace 4	7
SSP#			J. G.	Significant in	1
Prior Commissioned					1
Manometer reading ( " w.c.) As found Manometer reading				-	-
( " w.c.)					_
As Left*	Crawlspace 1	Crawlspace 2	Crawlspace 3	Crawlspace 4	1
SSP#					1
Manometer reading ( " w.c.)					1
					_
Accessible Crawlspace Perl	The state of the s		ound	As Left	
Was each membrane joint sm Did smoke enter? ***	loke tested?	∐ Yes □ Yes	∐ No □ No	Yes No	∐uc
Was the membrane perimeter	r amaka taata da	Yes	□ No	∐Yes ☐ No ☐Yes ☐ No	∐uc ∏uc
Did smoke enter? ***	smoke tested?	Yes	□No	Yes No	□uc
Is the suction point manometer	er(s) reading ≤ -1/10"		□No	Yes No	□uc
Comments			•		
					_
					_
					_
* As Found conditions = before c * As Left conditions = after correct			conditions)		
		g Juliu			

<sup>\*\*\*</sup> Inaccessible Crawlspace Criteria: Measured velocity ≥ 90% of Target Velocity (adjust if >110% of target velocity)

\*\*\* If answered YES to this question, perform corrective action and re-test.

\*\*\*\* If answered NO to this question, adjust valve accordingly and re-check all SSP and fan readings.