



Northern Circuits


Figure 1
Site Location
Northern Circuits, Inc.
6 Adler Drive
East Syracuse, New York
WA # D006130-23
Site # 734124
HRP # NEW9623.P2

INQUIRY #: 3061871.5

YEAR: 1995

| = 750'





LEGEND

- -HISTORICAL BORING INSTALLED BY LCS, INC. IN2009
- AREA OF 6 MIL VAPOR BARRIER BENEATH BUILDING BASED ON ENGINEERING DRAWING OBTAINED DURING THE MAY 5, 2011 INITIAL SITE VISIT
- ⊗ -SEWER LOCATION




FIGURE 2
SITE PLAN
NORTHERN CIRCUITS, INC.
6 ADLER DRIVE
EAST SYRACUSE, NY
WA# D006130-23
Site ID # 734124
HRP# NEW9623.P2
NOT TO SCALE

HRP
Associates, Inc.

Environmental/Civil Engineering & Hydrogeology

Creating the Bicht Solutions Together

Offices in CT SC NY EI MA and TX
 Circulating the original conditions logline!


Ollices III Cl, SC, NI, FL, WA, and LA

1 Fairchild Square, Suite 110

Clifton Park, NY 12065

Ph:(518)877-7101 Fax:(518)877-8561

www.hrassociates.com



LEGEND


- PROPOSED OVERBURDEN MONITORING WELL
- PROPOSED BORING
- PROPOSED SOIL VAPOR POINT
- HISTORICAL BORING – INSTALLED BY LCS, INC. IN 2009
- SEWER SAMPLE LOCATION
- INDOOR AIR SAMPLE LOCATION
- AREA OF 6 MIL VAPOR BARRIER BENEATH BUILDING

NOTES:

- INSIDE SAMPLING LOCATIONS TO CORRESPOND TO SUMPS AND AREAS OF CONCERN, FINAL LOCATIONS WERE SELECTED IN THE FIELD.
- BORING LOCATIONS INVOLVE COLLECTING SOIL SAMPLES AND GROUNDWATER GRAB SAMPLES.
- OVERBURDEN MONITORING WELL LOCATIONS INVOLVE SOIL AND GROUNDWATER SAMPLES.
- HRP-SV-1 THROUGH HRP-SV-7 NOT SAMPLED DUE TO HIGH GROUNDWATER TABLE.

BASED ON ENGINEERING DRAWINGS OBTAINED DURING THE MAY 5, 2011 INITIAL SITE VISIT

FIGURE 3
SAMPLE LOCATIONS
NORTHERN CIRCUITS, INC.
6 ADLER DRIVE
EAST SYRACUSE, NY
WA# D006130-23
HRP # NEW9623.P2
NOT TO SCALE
SITE ID # 734124





ADLER DRIVE




FIGURE 5B
MONITORING WELLS
ANALYZED FOR METALS
NORTHERN CIRCUITS, INC.
6 ADLER DRIVE
EAST SYRACUSE, NY
WA# D006130-23
HRP# NEW9623.P2
NOT TO SCALE

HRP Associates, Inc.
Environmental/Civil Engineering & Hydrogeology
Creating the Right Solutions Together
Offices in CT, SC, NY, FL, MA, and TX
1 Fairchild Square, Suite 110
Clifton Park, NY 12065
Ph:(518)877-7101 Fax:(518)877-8561
www.hrpassociates.com




FIGURE 5 A
SOIL BORINGS ANALYZED
FOR METALS
NORTHERN CIRCUITS, INC.
6 ADLER DRIVE
EAST SYRACUSE, NY
WA# D006130-23
SITE ID# 734124
NOT TO SCALE

HRP Associates, Inc.
Environmental/Civil Engineering & Hydrogeology
Creating the Right Solutions Together
Offices in CT, SC, NY, FL, MA, and TX
1 Fairchild Square, Suite 110
Clifton Park, NY 12065
Ph:(518)877-7101 Fax:(518)877-8561
www.hrpassociates.com

ADLER DRIVE





FIGURE 6
SOIL SAMPLES
ANALYZED FOR VOCs
NORTHERN CIRCUITS, INC.
6 ADLER DRIVE
EAST SYRACUSE, NY
WA# D006130-23
HRP# NEW9623.P2
NOT TO SCALE

ADLER DRIVE





FIGURE 7
GROUNDWATER SAMPLES
ANALYZED FOR VOCs
NORTHERN CIRCUITS, INC.
6 ADLER DRIVE
EAST SYRACUSE, NY
WA# D006130-23
SITE ID # 734124
HRP# NEW9623.P2
NOT TO SCALE

LEGEND

- INSTALLED OVERBURDEN MONITORING WELL
- INSTALLED BORING
- INSTALLED SOIL VAPOR POINT
- HISTORICAL BORING — INSTALLED BY LCS, INC IN 2009
- SEWER SAMPLE LOCATION
- INDOOR AIR SAMPLE LOCATION
- AREA OF 6 MIL VAPOR BARRIER BENEATH BUILDING
BASED ON ENGINEERING DRAWINGS OBTAINED DURING
MAY 5, 2011 INITIAL SITE VISIT




NOTE: ALL UNITS ARE IN ug/l (MICROGRAMS PER LITER).

— Sample Exceeds NYSDEC Class GA Criteria

HRP Associates, Inc.
Environmental/Civil Engineering & Hydrogeology
Creating the Right Solutions Together
Offices in CT, SC, NY, FL, MA, and TX
1 Fairchild Square, Suite 110
Clifton Park, NY 12065
Ph:(518)877-7101 Fax:(518)877-8561
www.hrpassociates.com



ADLER DRIVE



LEGEND

—INSTALLED OVERBURDEN MONITORING WELL

—INSTALLED BORING

—INSTALLED SOIL VAPOR POINT

—HISTORICAL BORING, INSTALLED BY LCS, INC. IN 2009

—AREA OF 6 MIL VAPOR BARRIER BENEATH BUILDING, BASED ON ENGINEERING DRAWINGS OBTAINED ON INITIAL SITE VISIT

—Groundwater Sample Exceeds NYSDEC Class GA Criteria

NOTE:
ALL UNITS ARE IN ug/kg
(MICROGRAMS PER KILOGRAM).

HRP-SV-1 THROUGH HRP-SV-7 NOT SAMPLED DUE TO HIGH GROUNDWATER

FIGURE 8
GROUNDWATER
ANALYZED FOR METALS
NORTHERN CIRCUITS, INC.
6 ADLER DRIVE
EAST SYRACUSE, NY
WA# D006130-23
SITE ID # 734124
HRP# NEW9623.P2
NOT TO SCALE

HRP Associates, Inc.
Environmental/Civil Engineering & Hydrogeology
Creating the Right Solutions Together
Offices in CT, SC, NY, FL, MA, and TX
1 Fairchild Square, Suite 110
Clifton Park, NY 12065
Ph:(518)877-7101 Fax:(518)877-8561
www.hrpassociates.com





FIGURE 9
AIR SAMPLES ANALYZED
FOR TO-15
NORTHERN CIRCUITS, INC.
6 ADLER DRIVE
EAST SYRACUSE, NY
WA# D006130-23
SITE ID # 734124
HRP# NEW9623.P2
NOT TO SCALE

HRP Associates, Inc.
Environmental/Civil Engineering & Hydrogeology
Creating the Right Solutions Together
Offices in CT, SC, NY, FL, MA, and TX
1 Fairchild Square, Suite 110
Clifton Park, NY 12065
Ph:(518)877-7101 Fax:(518)877-8561
www.hrpassociates.com