

2024 Annual Report Oswego Castings Site (738033) Oswego, New York

Work Assignment No. D009806-34

Prepared for

New York State Department of Environmental Conservation
Division of Environmental Remediation
625 Broadway
Albany, New York 12233-7017



Prepared by

EA Engineering and Geology, P.C., and Its Affiliate
EA Science and Technology
Washington Station
333 West Washington Street, Suite 300
Syracuse, New York 13202
315-431-4610

March 2025 Version: DRAFT

EA Project No. 16025-34-00-CP




TABLE OF CONTENTS

		$\underline{\mathbf{p}}_{\mathbf{i}}$	age
LIST LIST	OF FIG OF API	BLES	ii . iii
1.	BACI	KGROUND	1
	1.1 1.2	SITE DESCRIPTION PROJECT BACKGROUND	
2.	SITE	INSPECTION	5
	2.1 2.2 2.3 2.4 2.5 2.6 2.7 2.8 2.9 2.10	JANUARY 2024 FEBRUARY 2024 MARCH 2024 APRIL 2024 MAY 2024 JUNE 2024 JULY 2024 AUGUST 2024 OCTOBER 2024 DECEMBER 2024	5 6 6 6 6
3. ₄		CLUSIONS AND RECOMMENDATIONS	

LIST OF TABLES

Table 1. Monitoring Well Construction Details

LIST OF FIGURES

Figure 1. Site Location

Figure 2. Site Layout

Figure 3. Depth to Water at MW-1

Version: DRAFT Page iii March 2025

LIST OF APPENDICES

Appendix A. Daily Inspection Reports

Appendix B. Field Notes

Appendix C. Comprehensive Photographic Log

Version: DRAFT Page iv March 2025

LIST OF ACRONYMS AND ABBREVIATIONS

Arcadis CE, Inc.

BTOC Below top of casing

DER Division of Environmental Restoration
DNAPL Dense non-aqueous phase liquid
DPW Department of Public Works

EA Engineering and Geology, P.C. and its affiliate EA Science and Technology

No. Number

NOV Notice of Violation

NYCRR New York Codes, Rules and Regulations

NYSDEC New York State Department of Environmental Conservation

OU Operable unit

PCB Polychlorinated biphenyl

ROD Record of Decision

Site Oswego Castings Site SMP Site Management Plan

Version: DRAFT Page 1 March 2025

1. BACKGROUND

This Annual Report is a required element for the Oswego Castings Site located in Oswego, New York, hereinafter referred to as the Site (**Figure 1**). The Site is currently in the New York State Inactive Hazardous Waste Disposal Site Remedial Program (Site Number [No.] 738033), which is administered by the New York State Department of Environmental Conservation (NYSDEC). The reporting period for this Annual Report is 1 January 2024 to 31 December 2024. In January 2023, EA Engineering and Geology, P.C. and its affiliate EA Science and Technology (EA) was issued Work Assignment No. D009806-34 to perform site management activities at the Site.

1.1 SITE DESCRIPTION

The 22-acre Site is in a sparsely populated industrial area. There are residential properties located to the south, across Mitchell Street. NYSDEC regulated wetlands are located north and west of the Site. The nearest surface water body is Lake Ontario which is located approximately one-half mile north of the Site. The site geology consists of native overburden soils that are primarily unconsolidated glacial sediments or till. The water table varies from ground surface to 3 to 4 feet below ground surface. The overall groundwater flow direction is from the south to north, subject to the regional flow pattern toward Lake Ontario.

The Site is currently used by the City of Oswego Department of Public Works (DPW) as a staging area for equipment and materials used in the day-to-day and seasonal operations of the DPW. The Site and buildings are generally not secured. The boundary fence partially surrounds the Site and is damaged near monitoring well MW-6. Stockpiles of various materials (i.e., rocks, mulch, vegetation debris) have been observed within the site boundary.

1.2 PROJECT BACKGROUND

The Site was formerly owned by B and K Metals Inc. (previously Oberdorfer Foundries, Inc.). Oswego Castings Inc., a subsidiary of Oberdorfer Foundries, Inc. operated an aluminum die casting facility on the Site from 1956 to 1986. Polychlorinated biphenyls (PCBs) were detected on the Site in core sands, foundry waste, and wastewater discharged to a process line/septic tank discharge line after the facility closed, during an investigation performed by a prospective buyer. Starting in June 1988, preliminary investigations of the facility were performed by Oberdorfer Foundries, which identified PCBs above the New York State hazardous classification of 50 parts per million. The expected sources of the PCBs include leaks in hydraulic equipment and binders or coatings applied to core sand surfaces. In July 1993, B and K Metals Inc. entered into an Order on Consent with the NYSDEC for a remedial investigation/feasibility study. The remedial investigation/feasibility study was conducted between July 1993 and February 1997. A Record of Decision (ROD) was issued for Operable Unit (OU)-1 in 1997 (NYSDEC 1997) and called for excavation of approximately 4,100 cubic yards of soil, sediment, and foundry sand. In addition, the ROD called for removal of the septic tank and placement of crushed stone over the existing on-site landfill. The remedial action for OU-1 immediately followed and included excavation of surface soils, subsurface soils, and foundry wastes, and wetland sediments for off-site disposal; removal of a septic tank and tank contents for off-site disposal; and installation of a soil/crushed stone cover over the landfill area (NYSDEC 1999). A ROD for OU-2 was issued in 2000 (NYSDEC 2000), calling for construction of a concrete pad over the yard area and floor of the sawmill in addition to applying geotextile cover/stone to the former cooling water pond, construction of a new pond, and extending the roof drain from the former cooling water pond to the newly constructed pond. The remedial action for OU-2 was conducted in 2001 and included excavation and consolidation of sediments and soils into the former cooling water pond, installation of a concrete cap over the yard area, excavation of a new pond, and installation of four monitoring wells. As part of the Interim Remedial Measure for the Site, the foundry roof was cleaned to control a PCB source, and PCB impacted soil at the former loading dock was removed (NYSDEC 2002). Site features are shown on **Figure 2**.

In May 2010, the stone buffer for the landfill was regraded and landscape fabric and new stone were applied to the landfill cap. In April 2010, groundwater monitoring well MW-2 was replaced, and three new monitoring wells were installed (MW-5, MW-6, and MW-7). Well locations are presented on **Figure 2**.

An Environmental Notice was placed on the Site in May 2012 as an institutional control for remedy. The purpose of the Environmental Notice was to limit the use of the Site to industrial and/or commercial use, prevent owners from disturbing the remedial controls, prevent use of on-site groundwater, and grant access to the NYSDEC and its agents for purposes of maintaining the remedy.

In October 2012, Arcadis CE, Inc. (Arcadis) was issued work assignment D007618-11 to perform operation and maintenance and monitoring at the Site.

According to the Oswego County Real Property database, the property was acquired by the City of Oswego from Great Lakes Veneer Corp. in November 2012.

Based on routine site inspections performed by Arcadis and/or NYSDEC since 2012, the vacant buildings at the site are deteriorating, are not secured, and have been vandalized. In addition, copper (wires and/or pipe) have been removed from the buildings and a pad-mounted transformer.

On 23 April 2015, oil spills were identified in two on-site buildings that resulted from deteriorated and/or tipped storage containers. Upon identification of the spills, the incident was reported by Arcadis to the NYSDEC Project Manager and NYSDEC Spills Hotline. The associated NYSDEC Spill No. is 1500821. The Spills Division removed the containers and cleaned the spill areas. According to the NYSDEC Spills Database, the incident was closed on 22 October 2015.

A NYSDEC-approved Site Management Plan (SMP) was prepared by Arcadis in February 2016. The Site Management Plan provides procedures for operation and maintenance and monitoring to manage the remaining contamination at the site.

On 18 July 2019, NYSDEC performed a routine inspection at the Site and identified improper storage of drums and barrels; a new storage tank on the concrete cover area; placement of road millings surrounding groundwater monitoring wells and over the landfill area; removal of required site fencing and signage; and lack of notification of a change in use of the property (Arcadis of

March 2025

New York, Inc. 2021). The NYSDEC issued a Notice of Violation (NOV) to the City of Oswego on 2 October 2019 indicating it was not in compliance with the requirements of the SMP, New York Code of Rules and Regulations (NYCRR) Section 6 Part 375, and NYSDEC Division of Environmental Restoration (DER) Part 10 (NYSDEC 2010). The NOV stipulated the following corrective measures:

- Immediately sealing, labeling, and securing drums on an impervious surface, followed by removal and disposal of all drums within 90 days.
- Cleanup of spillage identified on the concrete cover area.
- An engineer's evaluation of tank loading on the concrete cover; placement of the tank on an impervious surface; and properly securing, labeling, and managing the storage tank and its contents.
- Removal of road millings surrounding monitoring wells and landfill area and grading the landfill area to improve drainage and prevent ponding of water.
- Replacement of site fencing and signage required by the ROD.
- Provide proper change of use notifications to the NYSDEC indicating the new site use.

A subsequent inspection by NYSDEC on 29 July 2020 identified continued deficiencies related to the NOV (Arcadis of New York, Inc. 2021). The NYSDEC issued a letter to the City on 28 September 2020 summarizing the remaining work to bring the Site into compliance by 20 October 2020 or the NYSDEC would move forward with an Order on Consent for the continued violations.

The remaining work includes:

- Installation of permanent fencing around the tank on the concrete cover.
- Correctly labeling the tank volume.
- Providing records for tank contents.
- Further removal of road millings from the monitoring wells based on groundwater sample results.
- Providing an engineering study for the proposed parking area indicating it will not interfere with the monitoring well network and the water table.
- Grading the landfill area due to continued ponding of water and providing survey to document final grade.

- Removal road millings from landfill area and provide documentation of disposal or perform testing to indicate millings do not contain hazardous constituents.
- Removal of vegetation debris from the landfill area and place signage to delineate the limits of the landfill that indicate no staging of materials can occur in the area.
- Submit change of use notifications to the NYSDEC for proper filing.

EA began conducting site monitoring activities in March 2023. Observations from the 30 March 2023 inspection included a large vegetation and debris mound on the soft cap, which lead to a subsequent NOV that was issued 23 October 2023. Corrective action included removing all stored tree debris, mulch, and other waste from the capped area. The large debris mound was removed before the following inspection on 10 November 2023. EA continued monitoring the Site in 2024.

Version: DRAFT Page 5 March 2025

2. SITE INSPECTION

Field activities included as-needed site inspections as well as the SMP-required groundwater sampling event. Site inspections were conducted monthly and included monitoring the condition of the soil cover and dense non-aqueous phase liquid (DNAPL) in MW-1. The monitoring well network is listed in **Table 1**. Daily Inspection Reports are provided in **Appendix A**. The field notes for the Site can be found in **Appendix B**, and a comprehensive photographic log in **Appendix C**.

2.1 **JANUARY 2024**

On 11 January 2024, EA performed a site inspection to assess the site conditions and monitor the DNAPL in MW-1. EA gauged the monitoring well for DNAPL. The depth to water was 2.39 feet below top of casing (BTOC), and the depth to the bottom of the well was 17.76 feet BTOC. Trace product was observed on the water level indicator. EA removed the existing absorbent sock and installed a clean absorbent sock at the bottom of the well with small weights.

2.2 FEBRUARY 2024

EA performed a site inspection to assess the site conditions and monitor the DNAPL in MW-1 on 15 February 2024. EA gauged the monitoring well for DNAPL. The depth to water was 3.54 feet BTOC, and the depth to the bottom of the well was 17.50 feet BTOC. Trace product was observed on the water level indicator. EA removed the existing absorbent sock and installed a clean absorbent sock at the bottom of the well with small weights. Observations from the site inspection included recently disturbed soil south of MW-1 and MW-2R and ponding on the soil cover system.

2.3 MARCH 2024

On 18 March 2025, EA performed a site inspection to assess the site conditions and monitor the DNAPL in MW-1. EA gauged the monitoring well for DNAPL. The depth to water was 3.00 feet BTOC, and the depth to the bottom of the well was 17.53 feet BTOC. Trace product was observed on the water level indicator. EA removed the existing absorbent sock and installed a clean absorbent sock at the bottom of the well with small weights. Observations from the site inspection included ponding on the soil cover system.

2.4 APRIL 2024

EA performed a site inspection to assess the site conditions and monitor the DNAPL in MW-1 on 19 April 2024. EA gauged the monitoring well for DNAPL. The depth to water was 2.19 feet BTOC, and the depth to bottom of the well was 17.61 feet BTOC. Trace product was observed on the water level indicator. EA removed the existing absorbent sock and installed a clean absorbent sock at the bottom of the well with small weights. Observations from the site inspection included ponding on the soil cover system. EA also conducted a site walk to locate the monitoring wells for an upcoming groundwater sampling event.

Version: DRAFT Page 6 March 2025

2.5 MAY 2024

On 6 May 2024, EA performed monitoring well sampling and a site inspection to assess the site conditions and monitor the DNAPL in MW-1. Measurements for depth to water and depth to bottom were recorded for all wells, as shown in **Table 1**. EA removed the existing adsorbent sock from MW-1 and observed trace produce on the adsorbent sock. A clean adsorbent sock was installed at the bottom of MW-1. Observations from the site inspection included settlement and ponded water on the landfill soil cap and various sized holes and cracks in the concrete cover. All observations from the 6 May 2024 field event are summarized in the 2024 Annual Groundwater Report (EA 2025).

2.6 JUNE 2024

On 17 June 2024, EA performed a site inspection to assess the site conditions and monitor the DNAPL in MW-1. EA gauged the monitoring well for DNAPL. The depth to water was 5.97 feet BTOC, and the depth to bottom of the well was 17.43 feet BTOC. Trace product was observed on the water level indicator. EA removed the existing absorbent sock and installed a clean absorbent sock at the bottom of the well with small weights. Observations from the site inspection included a drainage ditch running from the southern boundary to the western boundary of the soil cover and three small piles (two soil and one vegetation debris) located partially inside the northern boundary of the soil cover.

2.7 JULY 2024

EA performed a site inspection to assess the site conditions and monitor the DNAPL in MW-1 on 15 July 2024. EA gauged the monitoring well for DNAPL. The depth to water was 4.95 feet BTOC, and the depth to bottom of the well was 17.45 feet BTOC. Trace product was observed on the water level indicator. EA removed the existing absorbent sock and installed a clean absorbent sock at the bottom of the well with small weights. Observations from the site inspection included a drainage ditch running from the southern boundary to the western boundary of the soil cover and three small piles (two soil and one vegetation debris) located partially inside the northern boundary of the soil cover.

2.8 AUGUST 2024

On 26 August 224, EA performed a site inspection to assess the site conditions and monitor the DNAPL in MW-1. EA gauged the monitoring well for DNAPL. The depth to water was 4.35 feet BTOC, and the depth to bottom of the well was 17.46 feet BTOC. Trace product was observed on the water level indicator. EA removed the existing absorbent sock and installed a clean absorbent sock at the bottom of the well with small weights. Observations from the site inspection included a ponding and running water on the soil cover.

2.9 OCTOBER 2024

Based on the previous monthly inspection, NYSDEC instructed EA to perform the site inspections once every 2 months. EA performed a site inspection to assess the site conditions and monitor the

DNAPL in MW-1 on 22 October 2024. EA gauged the monitoring well for DNAPL. The depth to water was 4.35 feet BTOC, and depth to bottom of the well was 17.46 feet BTOC. EA removed the existing absorbent sock and installed a clean absorbent sock at the bottom of the well with small weights. Observations from the site inspection included a ponding on the soil cover.

2.10 DECEMBER 2024

On 16 December 2024, EA performed a site inspection to assess the site conditions and monitor the DNAPL in MW-1. EA gauged the monitoring well for DNAPL. The depth to water was 3.05 feet BTOC, and depth to bottom of the well was 17.52 feet BTOC. EA removed the existing absorbent sock and installed a clean absorbent sock at the bottom of the well with small weights. Observations from the site inspection included a ponding on the soil cover.

Version: DRAFT
EA Engineering and Geology, P.C. and Its Affiliate
EA Science and Technology

March 2025

This page intentionally left blank

Version: DRAFT Page 9 March 2025

3. CONCLUSIONS AND RECOMMENDATIONS

EA conducted field activities from January to December 2024. EA continued monthly site inspections from January to August, when the frequency was reduced to every 2 months. The monthly inspection included monitoring the condition of the soft cap and DNAPL in MW-1. Over the course of the site monitoring program, EA observed a ponding and/or a depression in the soft cap during all site inspection. The photographic log (**Appendix C**) documents the condition of the soft cap.

During the site inspection, no measurable DNAPL was observed in monitoring well MW-1. Trace amount of DNAPL was observed on the water level indicator, shown in the Daily Inspection Reports of **Appendix A**. The depth to groundwater is summarized on **Figure 3**.

EA recommends reducing the frequency of site inspections to quarterly or bi-annually. The site inspections and absorbent sock replacements of MW-1 shall continue until no product is observed or measured for three consecutive site inspections. Then, subsequent site inspections will be conducted as needed. The next sampling event of the monitoring well network is scheduled for the third quarter of 2025.

Version: DRAFT
EA Engineering and Geology, P.C. and Its Affiliate
EA Science and Technology

Narch 2025

This page intentionally left blank


4. REFERENCES

- Arcadis of New York, Inc. 2021. Periodic Review Report Oswego Castings Site, Site Number 7-38-033. March.
- EA Engineering, P.C. and its affiliate EA Science and Technology (EA). 2025. 2024 Annual Groundwater Monitoring Report, Oswego Castings Site (738033), Oswego, New York. February.
- New York State Department of Environmental Conservation (NYSDEC). 1997. Record of Decision, Oswego Castings Site, Oswego (C), Oswego County. Site Number 7-38-033. March.
- ——. 1999. Construction Certification Report, Oswego Castings Site, Site 7-38-033. 11 January.
- ——. 2000. Record of Decision, Oswego Castings Site Operable Unit No. 2 Yard/Buildings, Oswego, Oswego County. Site Number 7-38-033. March.
- ——. 2002. Remediation Summary Report, Oswego Castings Site, City of Oswego, Oswego County, Contract No. D004283, Site No. 7-38-033. January.
- ———. 2010. Division of Environmental Remediation (DER)-10 Technical Guidance for Site Investigation and Remediation. May.

Version: DRAFT
EA Engineering and Geology, P.C. and Its Affiliate
EA Science and Technology

Version: DRAFT
Page 12
Arch 2025

This page intentionally left blank






Table 1. Monitoring Well Construction Details


Manitanina		XX/all	Depth to	Elevation (feet above mean sea leve				
Monitoring Well ID, Well Location	Coordinates (longitude/ latitude)	Well Diameter (inches)	Bottom (feet BTOC)	Casing	Surface	Screen Top	Screen Bottom	
MW-1*, on-site	43.4734° N, -	4	17.48**	313.3	311.3	307.3	295.3	
MW-2R, on-site	76.4755° W 43.4735° N, - 76.4752° W	2	15.73**	313.1	311.1	307.1	295.1	
MW-3, downgradient	43.4747° N, - 76.4739° W	4	17.35**	311.7	309.7	305.7	293.7	
MW-4, on-site	43.4741° N, - 76.4759° W	4	16.43**	312.5	310.5	306.5	294.5	
MW-5, downgradient	43.4748° N, - 76.4773° W	2	16.91**	312.7	308.00	Not provided	Not provided	
MW-6, upgradient	43.4739° N, - 76.4731° W	2	36.85**	331.8	325.00	Not provided	Not provided	
MW-7, downgradient	43.4754° N, - 76.4758° W	2	16.12**	314.1	309.00	Not provided	Not provided	


Notes:


BTOC = Below top of casing


^{*} MW-1 has historically had oily sheen/free product of light non-aqueous phase liquid present. There is currently an absorbent sock installed at the bottom of the well.


^{**} Depth to bottom collected on 6 May 2024.















Figure 3. Depth to Water at MW-1


Notes:

BTOC: Below top of casing

ft: Foot/feet



Appendix A Daily Inspection Reports



(Oswego Castings), Site No. 738033

NEW YORK Contract No. D009806 Department of **NYSDEC** Environmental Division of Environmental Remediation DEC PM - J. Stefansky Conservation Engineer PM - J. Oliver Site Location: Mitchell St., Oswego 13126 Engineer Insp. - H. Bedell **Weather Conditions General Description** PMCloudy AM **Temperature** 34F ΑM PMAM Wind 8 mph E PM**Health & Safety** If any box below is checked "Yes", provide explanation under "Health & Safety Comments". Were there any changes to the Health & Safety Plan? No X NA *Yes NA X Were there any exceedances of the perimeter air monitoring reported on this date? No Were there any nuisance issues reported/observed on this date? *Yes Nο NA X **Health & Safety Comments** Discussed cold stress, and slips, trips, and falls for site inspection tailgate safety meeting. 1000 **Summary of Work Performed** Arrived at site: 0915 Departed Site: (0915) H. Bedell and C. Zook (EA) on-site for absorbent sock exchange and gauge DNAPL in MW-1. (0920) Calibrated PID. (0930) EA removed the absorbent sock out of the well. No product was observed in the absorbent sock. (0940) DTW in MW-1 was 2.39 ft BTOC, and DTB was 17.76 ft BTOC. No measurable product, trace product observed on water level indicator. (0950) EA replaced the absorbent sock at the bottom of the well. (1000) H. Bedell & C. Zook (EA) offsite. **Equipment/Material Tracking** If any box below is checked "Yes", provide explanation under "Material Tracking Comments". Were there any vehicles which did not display proper D.O.T numbers and placards? *Yes No NA X Were there any vehicles which were not tarped? * Yes NA X No Were there any vehicles which were not decontaminated prior to exiting the work * Yes NA X No **Personnel and Equipment** Individual Company Trade **Total Hours** Hannah Bedell EΑ 0.75 Engineer Clara Zook EΑ Intern 0.75 Contractor/Vendor Quantity **Equipment Description** Used Various Hand tools EΑ NA Yes 2020 Ford Explorer EΑ 1 Yes Oil water interface probe PINE Yes PINE Honeywell 3000+ miniRAE Yes Imported/ Daily **Waste Profile Exported** Source or Disposal Daily **Material Description** Delivered Weight off Site Facility (If Applicable) Loads (If Applicable) to Site (tons)* *On-Site scale for off-site shipment, delivery ticket for material received

Page 1 of 5

Date: 01/11/2024

Equipment/Material Tracking Comments:


(Oswego Castings), Site No. 738033

Name	Representing	Entered	Entered Exclusion/CRZ Zon		
		Yes	No NA		
		Yes	No NA		
Site Representatives	•	<u>.</u>	·		
Name	Representin	ng			
Hannah Bedell	EA				
Project Schedule Comments					
ssues Pendina					
ssues Pending					
	ed to take place before the next sa	ampling event.			
	ed to take place before the next sa	ampling event.			
	ed to take place before the next sa	ampling event.			
Vegetation clearing will ne		ampling event.			
Vegetation clearing will ne		ampling event.			
Vegetation clearing will ne		ampling event.			
 Vegetation clearing will ne Interaction with Public, Property 		ampling event.			

Page **2** of **5**

Date: 01/11/2024

Page **3** of **5 Date: 01/11/2024**



Videos of discreet operations have been provided to the DEC Project Manager to facilitate understanding of the ongoing work? Yes \square No \square N/A X



(Oswego Castings), Site No. 738033

REMEDIAL ACTIVITIES AT PROPERTIES

Page **4** of **5**

Date: 01/11/2024

1.	Does anyone at this location have any symptoms of a respiratory infection (e.g., cough, sore throat, fever, or shortness of breath)?	Yes □	No ⊠		
2.	Have anyone at this location been tested and confirmed to have COVID-19?	Yes □	No ⊠		
3.	Were personal protective gloves, masks, and eye protection being used?	Yes □	No ⊠		
4.	Does the Department and its contractors have your permission to enter the property at this time?	Yes ⊠	No □		
5.	If Yes to 1 or 2, follow the latest NYSDOH COVID-19 guidance: https://coronavirus.health.ny.gov/home	Yes ⊠	No □		
Comments:					
N/A					

ON-SITE WASTE STORAGE

Drums, roll offs and piles are staged in secure areas?	Yes ⊠	No □	N/A□
Liners and berms have been installed if necessary to prevent cross contamination of clean areas?	Yes □	No □	N/A⊠
Containers are in good condition or properly overpacked?	Yes □	No □	N/A⊠
Waste materials are scheduled to be properly characterized and disposed of prior to demobilization?	Yes □	No □	N/A⊠
Complying with RCRA 90 day storage limitation for hazardous waste?	Yes □	No □	N/A⊠
Piles are securely covered when not in use?	Yes □	No □	N/A⊠
Containers are closed when not in use?	Yes □	No □	N/A⊠
Staging areas should be inspected periodically and any issues addressed immediately?	Yes □	No □	N/A⊠
Signage and labeling comply with RCRA requirements for all staging areas and containers?	Yes □	No □	N/A⊠
If any issues noted, has Contractor been notified?	Yes □	No □	N/A⊠
Comments:			

NUISANCE CHECKLIST

Were there any community complaints related to work on this date?	Yes □	No ⊠	N/A□
Were there any odors detected on this date?	Yes □	No ⊠	N/A□
Was noise outside specification and/or above background on this date?	Yes □	No ⊠	N/A□
Were vibration readings outside specification and/or above background on this date?	Yes □	No □	N/A⊠
Any visible dust observed beyond the work perimeter on this date?	Yes □	No □	N/A⊠
Any visible contrast (turbidity) beyond engineering controls observed on this date?	Yes □	No □	N/A⊠
Was turbidity checked at the outfall(s)?	AM □	РМ□	N/A⊠
Were any property owners NOT provided advance notice for work performed on this property on this date?	Yes □	No □	N/A⊠



(Oswego Castings), Site No. 738033

Was the temporary fabric structure closed at the end of the day?	Yes □	No □	N/A⊠
Has Contractor failed to protect all foundations and structures adjacent to and adjoining the site which are affected by the excavations or other operations connected with performance of the Work?	Yes □	No □	N/A⊠
If yes, has Contractor been notified?	Yes □	No □	N/A⊠
Comments: N/A			

Page **5** of **5**

Date: 01/11/2024

RESILIENCE/GREEN REMEDIATION CHECKLIST

Is site power procured from renewable energy sources (e.g., solar, wind, geothermal, biomass and biogas)?	Yes □	No □	N/A⊠
Is the Contractor employing 2007 or newer or retrofitted (BART*) diesel on-road trucks and non-road equipment?	Yes □	No □	N/A⊠
Is vehicle idling adequately reduced per 6NYCRR Part 217-3?	Yes □	No □	N/A⊠
Have equipment operators been trained in the idling requirements of 6NYCRR Part 217-3?	Yes □	No □	N/A⊠
Is BART-equipped equipment properly maintained and working?	Yes □	No □	N/A⊠
Is work being sequenced to avoid double handling?	Yes □	No □	N/A⊠
Is there an onsite recycling program for CONTRACTOR-generated wastes and is it complied with?	Yes □	No □	N/A⊠
Are office trailer heating and cooling systems maintained at efficient set points, have programable thermostats been installed?	Yes □	No □	N/A⊠
Are products and materials used in performance of the work appropriately certified (e.g., LEED, Energy Star, Sustainable Forestry Initiative®, etc.)?	Yes □	No □	N/A⊠
Are resiliency features included in the design, or completed remedy properly installed and/or maintained (flood control, storm water controls, erosion measures, etc.)?	Yes □	No □	N/A⊠
Are green remediation elements included in the design, or completed remedy properly installed and/or maintained (e.g., porous pavement, geothermal, variable speed drives, native plantings, natural stream bank restoration, etc.)?	Yes □	No □	N/A⊠
Has Contractor been notified of any deficiencies?	Yes □	No □	N/A⊠
Are remote/call in job meetings being held in lieu of meeting in person where possible?	Yes □	No □	N/A⊠
Comments: N/A			

^{*} BART – Best Available Retrofit Technology

(Oswego Castings), Site No. 738033

Equipment/Material Tracking Comments:

Contract No. D009806 Department of **NYSDEC** YORK **Environmental** Division of Environmental Remediation DEC PM - J. Stefansky Conservation Engineer PM - J. Oliver Site Location: Mitchell St., Oswego 13126 Engineer Insp. - H. Bedell **Weather Conditions General Description** PMCloudy AM **Temperature** 34F ΑM PM AM Wind 8 mph E PM **Health & Safety** If any box below is checked "Yes", provide explanation under "Health & Safety Comments". Were there any changes to the Health & Safety Plan? No X NA *Yes NA X Were there any exceedances of the perimeter air monitoring reported on this date? No Were there any nuisance issues reported/observed on this date? *Yes Nο NA X **Health & Safety Comments** Discussed cold stress, and slips, trips, and falls for site inspection tailgate safety meeting. 1030 **Summary of Work Performed** Arrived at site: 1000 Departed Site: (1000) H. Bedell and M. Gilkey (EA) on-site for absorbent sock exchange and gauge DNAPL in MW-1. (1005) Calibrated PID. (1015) EA removed the absorbent sock out of the well. No product was observed in the absorbent sock. DTW in MW-1 was 3.54 ft BTOC, and DTB was 17.50 ft BTOC. No measurable product, trace product observed on water level indicator. (1020) EA replaced the absorbent sock at the bottom of the well. (1025) EA conducted visual inspection of soft cap. (1030) H. Bedell & M. Gilkey (EA) offsite. **Equipment/Material Tracking** If any box below is checked "Yes", provide explanation under "Material Tracking Comments". Were there any vehicles which did not display proper D.O.T numbers and placards? *Yes NA X * Yes Were there any vehicles which were not tarped? No NA X Were there any vehicles which were not decontaminated prior to exiting the work * Yes No NA X site? **Personnel and Equipment** Individual Company **Trade Total Hours** EΑ 0.5 Hannah Bedell Engineer Moriah Gilkey EΑ Engineer 0.5 Contractor/Vendor Quantity Used **Equipment Description** Various Hand tools NA EΑ Yes 2020 Ford Explorer EΑ Yes Oil water interface probe PINE Yes Honeywell 3000+ miniRAE PINE Yes Imported/ Daily **Waste Profile Exported** Source or Disposal Daily **Material Description Delivered** Weight off Site (If Applicable) Facility (If Applicable) Loads to Site (tons)* *On-Site scale for off-site shipment, delivery ticket for material received

Page 1 of 7

Date: 02/15/2024

(Oswego Castings), Site No. 738033

Issues Pending • Vegetation clearing will need to take place before the next samplin	Name	Representing	Entered Exclusion/CRZ		CRZ Zo
Name Hannah Bedell EA Project Schedule Comments Issues Pending • Vegetation clearing will need to take place before the next sampling			Yes	No	NA
Name Hannah Bedell EA Project Schedule Comments Issues Pending • Vegetation clearing will need to take place before the next sampling			Yes	No	NA
Name Hannah Bedell EA Project Schedule Comments Issues Pending • Vegetation clearing will need to take place before the next sampling	Site Representatives				
Project Schedule Comments Issues Pending • Vegetation clearing will need to take place before the next sampling		Representing			
Vegetation clearing will need to take place before the next sampling	Hannah Bedell	EA			
 Issues Pending Vegetation clearing will need to take place before the next sampling 					
Issues Pending	Project Schedule Comments	•			
Vegetation clearing will need to take place before the next sampling					
Vegetation clearing will need to take place before the next sampling					
Vegetation clearing will need to take place before the next sampling					
Vegetation clearing will need to take place before the next sampling					
Vegetation clearing will need to take place before the next sampling					
Vegetation clearing will need to take place before the next sampling					
Vegetation clearing will need to take place before the next sampling					
Vegetation clearing will need to take place before the next sampling					
Vegetation clearing will need to take place before the next sampling					
Vegetation clearing will need to take place before the next sampling	Januar Danding				
	issues Pending				
Interaction with Public, Property Owners, Media, etc.		and to take place before the next samp	ling event		
Interaction with Public, Property Owners, Media, etc.		eed to take place before the next samp	ling event.		
micraelien man, respect, emisse, meana, etc.		eed to take place before the next samp	ling event.		
	 Vegetation clearing will ne 		ling event.		
	 Vegetation clearing will ne 		ling event.		
	 Vegetation clearing will ne 		ling event.		
	 Vegetation clearing will ne 		ling event.		
	 Vegetation clearing will ne 		ling event.		
	Vegetation clearing will ne		ling event.		

Page 2 of 7
Date: 02/15/2024

Page 3 of 7 Date: 02/15/2024

Site Photographs (Descriptions Below)




Absorbent sock removed from MW-1 with no visible DNAPL



M. Gilkey gauging MW-1



Drum located near MW-1 for absorbent sock disposal



Trace amount of DNAPL present on oil/water probe



Disturbed cover near MW-2R, approximately 3 feet deep



Excavation present near MW-2R



East side of excavated area near MW-2R



Ponding present on soil cap looking northeast




Ponding on soil cap looking west



Ponding present in northeast corner of soil cap

DAILY INSPECTION REPORT (Oswego Castings), Site No. 738033



Page **5** of **7**

Videos of discreet operations have been provided to the DEC Project Manager to facilitate understanding of the ongoing work? Yes \square No \square N/A X

(Oswego Castings), Site No. 738033

REMEDIAL ACTIVITIES AT PROPERTIES

Page **6** of **7**

Date: 02/15/2024

1.	Does anyone at this location have any symptoms of a respiratory infection (e.g., cough, sore throat, fever, or shortness of breath)?	Yes □	No ⊠
2.	Have anyone at this location been tested and confirmed to have COVID-19?	Yes □	No ⊠
3.	Were personal protective gloves, masks, and eye protection being used?	Yes □	No ⊠
4.	Does the Department and its contractors have your permission to enter the property at this time?	Yes ⊠	No □
5.	If Yes to 1 or 2, follow the latest NYSDOH COVID-19 guidance: https://coronavirus.health.ny.gov/home	Yes ⊠	No □
Comm N/A	ents:		

ON-SITE WASTE STORAGE

Drums, roll offs and piles are staged in secure areas?	Yes ⊠	No □	N/A□
Liners and berms have been installed if necessary to prevent cross contamination of clean areas?	Yes □	No □	N/A⊠
Containers are in good condition or properly overpacked?	Yes □	No □	N/A⊠
Waste materials are scheduled to be properly characterized and disposed of prior to demobilization?	Yes □	No □	N/A⊠
Complying with RCRA 90 day storage limitation for hazardous waste?	Yes □	No □	N/A⊠
Piles are securely covered when not in use?	Yes □	No □	N/A⊠
Containers are closed when not in use?	Yes □	No □	N/A⊠
Staging areas should be inspected periodically and any issues addressed immediately?	Yes □	No □	N/A⊠
Signage and labeling comply with RCRA requirements for all staging areas and containers?	Yes □	No □	N/A⊠
If any issues noted, has Contractor been notified?	Yes □	No □	N/A⊠
Comments:			

NUISANCE CHECKLIST

Were there any community complaints related to work on this date?	Yes □	No ⊠	N/A□
Were there any odors detected on this date?	Yes □	No ⊠	N/A□
Was noise outside specification and/or above background on this date?	Yes □	No ⊠	N/A□
Were vibration readings outside specification and/or above background on this date?	Yes □	No □	N/A⊠
Any visible dust observed beyond the work perimeter on this date?	Yes □	No □	N/A⊠
Any visible contrast (turbidity) beyond engineering controls observed on this date?	Yes □	No □	N/A⊠
Was turbidity checked at the outfall(s)?	AM □	РМ□	N/A⊠
Were any property owners NOT provided advance notice for work performed on this property on this date?	Yes □	No □	N/A⊠



(Oswego Castings), Site No. 738033

Was the temporary fabric structure closed at the end of the day?	Yes □	No □	N/A⊠
Has Contractor failed to protect all foundations and structures adjacent to and adjoining the site which are affected by the excavations or other operations connected with performance of the Work?	Yes □	No □	N/A⊠
If yes, has Contractor been notified?	Yes □	No □	N/A⊠
Comments: N/A			

Page **7** of **7 Date: 02/15/2024**

RESILIENCE/GREEN REMEDIATION CHECKLIST

Is site power procured from renewable energy sources (e.g., solar, wind, geothermal, biomass and biogas)?	Yes □	No □	N/A⊠
Is the Contractor employing 2007 or newer or retrofitted (BART*) diesel on-road trucks and non-road equipment?	Yes □	No □	N/A⊠
Is vehicle idling adequately reduced per 6NYCRR Part 217-3?	Yes □	No □	N/A⊠
Have equipment operators been trained in the idling requirements of 6NYCRR Part 217-3?	Yes □	No □	N/A⊠
Is BART-equipped equipment properly maintained and working?	Yes □	No □	N/A⊠
Is work being sequenced to avoid double handling?	Yes □	No □	N/A⊠
Is there an onsite recycling program for CONTRACTOR-generated wastes and is it complied with?	Yes □	No □	N/A⊠
Are office trailer heating and cooling systems maintained at efficient set points, have programable thermostats been installed?	Yes □	No □	N/A⊠
Are products and materials used in performance of the work appropriately certified (e.g., LEED, Energy Star, Sustainable Forestry Initiative®, etc.)?	Yes □	No □	N/A⊠
Are resiliency features included in the design, or completed remedy properly installed and/or maintained (flood control, storm water controls, erosion measures, etc.)?	Yes □	No □	N/A⊠
Are green remediation elements included in the design, or completed remedy properly installed and/or maintained (e.g., porous pavement, geothermal, variable speed drives, native plantings, natural stream bank restoration, etc.)?	Yes □	No □	N/A⊠
Has Contractor been notified of any deficiencies?	Yes □	No □	N/A⊠
Are remote/call in job meetings being held in lieu of meeting in person where possible?	Yes □	No □	N/A⊠
Comments: N/A			

^{*} BART – Best Available Retrofit Technology

(Oswego Castings), Site No. 738033

Contract No. D009806 Department of **NYSDEC** YORK **Environmental** STATE Division of Environmental Remediation DEC PM - J. Stefansky Conservation Engineer PM - J. Oliver Site Location: Mitchell St., Oswego 13126 Engineer Insp. - H. Bedell **Weather Conditions General Description** PMCloudy AM **Temperature** 32F ΑM PMAM Wind 18 mph W PM**Health & Safety** If any box below is checked "Yes", provide explanation under "Health & Safety Comments". Were there any changes to the Health & Safety Plan? No X NA Were there any exceedances of the perimeter air monitoring reported on this date? *Yes NA X No Were there any nuisance issues reported/observed on this date? *Yes Nο NA X **Health & Safety Comments** Discussed cold stress, and slips, trips, and falls for site inspection tailgate safety meeting. 1000 **Summary of Work Performed** Arrived at site: 0930 Departed Site: (0930) H. Bedell and K. Katzer (EA) on-site for absorbent sock exchange and gauge DNAPL in MW-1. (0935) Calibrated PID. (0940) EA removed the absorbent sock out of the well. Product was observed in the absorbent sock. DTW in MW-1 was 3.00 ft BTOC, and DTB was 17.53 ft BTOC. No measurable product, trace product observed on water level indicator. (0950) EA replaced the absorbent sock at the bottom of the well. (0955) EA conducted visual inspection of soft cap. (1000) H. Bedell & K. Katzer (EA) offsite. **Equipment/Material Tracking** If any box below is checked "Yes", provide explanation under "Material Tracking Comments". Were there any vehicles which did not display proper D.O.T numbers and placards? *Yes NA X * Yes Were there any vehicles which were not tarped? No NA X Were there any vehicles which were not decontaminated prior to exiting the work * Yes No NA X site? Personnel and Equipment Individual Company **Trade Total Hours** EΑ 0.5 Hannah Bedell Engineer Kathryn Katzer EΑ Engineer 0.5 Contractor/Vendor Used **Equipment Description** Quantity NA Various Hand tools Yes EΑ 2020 Ford Explorer EΑ Yes Oil water interface probe PINE Yes Honeywell 3000+ miniRAE PINE Yes Imported/ Daily **Waste Profile** Exported Source or Disposal Daily **Material Description** Delivered Weight off Site (If Applicable) Facility (If Applicable) Loads to Site (tons)* *On-Site scale for off-site shipment, delivery ticket for material received **Equipment/Material Tracking Comments:**

Page 1 of 6

Date: 03/18/2024

(Oswego Castings), Site No. 738033

Name	Rep	resenting	Entered Exclusion/CRZ Zo		
Police officer	New York State D Environmental Co		Yes	No NA	
			Yes	No NA	
Site Representatives			·	·	
Name		Representing			
Hannah Bedell		EA			
Kathryn Katzer		EA			

Page 2 of 6

Date: 03/18/2024

Issues Pending

Vegetation clearing will need to take place before the next sampling event.

Interaction with Public, Property Owners, Media, etc.

Two members of the public inquired about our employer, as they were waiting to meet with NYSDEC officials. One officer of the NYSDEC Police asked for the property owner's contact information and suggested that the Site may be redeveloped for a Bryne Dairy. EA provided the contact information for Craig Rebeor, Department of Public Works Commissioner for the City of Oswego.

Site Photographs (Descriptions Below)



Collection of PID measurement from MW-1



Some product observed on the absorbent sock from MW-1



Trace product observed on the oil/water interface probe



View of south-end of soft cap and north-end of concrete cap

(Oswego Castings), Site No. 738033



Page 4 of 6

Date: 03/18/2024

Videos of discreet operations have been provided to the DEC Project Manager to facilitate understanding of the ongoing work? Yes \square No \square N/A X

(Oswego Castings), Site No. 738033

REMEDIAL ACTIVITIES AT PROPERTIES

Page **5** of **6**

Date: 03/18/2024

1.	Does anyone at this location have any symptoms of a respiratory infection (e.g., cough, sore throat, fever, or shortness of breath)?	Yes □	No ⊠
2.	Have anyone at this location been tested and confirmed to have COVID-19?	Yes □	No ⊠
3.	Were personal protective gloves, masks, and eye protection being used?	Yes □	No ⊠
4.	Does the Department and its contractors have your permission to enter the property at this time?	Yes ⊠	No □
5.	If Yes to 1 or 2, follow the latest NYSDOH COVID-19 guidance: https://coronavirus.health.ny.gov/home	Yes ⊠	No □
Comm	ents:		
N/A			

ON-SITE WASTE STORAGE

Drums, roll offs and piles are staged in secure areas?	Yes ⊠	No □	N/A□
Liners and berms have been installed if necessary to prevent cross contamination of clean areas?	Yes □	No □	N/A⊠
Containers are in good condition or properly overpacked?	Yes □	No □	N/A⊠
Waste materials are scheduled to be properly characterized and disposed of prior to demobilization?	Yes □	No □	N/A⊠
Complying with RCRA 90 day storage limitation for hazardous waste?	Yes □	No □	N/A⊠
Piles are securely covered when not in use?	Yes □	No □	N/A⊠
Containers are closed when not in use?	Yes □	No □	N/A⊠
Staging areas should be inspected periodically and any issues addressed immediately?	Yes □	No □	N/A⊠
Signage and labeling comply with RCRA requirements for all staging areas and containers?	Yes □	No □	N/A⊠
If any issues noted, has Contractor been notified?	Yes □	No □	N/A⊠
<u>Comments:</u>			

NUISANCE CHECKLIST

Were there any community complaints related to work on this date?	Yes □	No ⊠	N/A□
Were there any odors detected on this date?	Yes □	No ⊠	N/A□
Was noise outside specification and/or above background on this date?	Yes □	No ⊠	N/A□
Were vibration readings outside specification and/or above background on this date?	Yes □	No □	N/A⊠
Any visible dust observed beyond the work perimeter on this date?	Yes □	No □	N/A⊠
Any visible contrast (turbidity) beyond engineering controls observed on this date?	Yes □	No □	N/A⊠
Was turbidity checked at the outfall(s)?	AM □	РМ□	N/A⊠
Were any property owners NOT provided advance notice for work performed on this property on this date?	Yes □	No □	N/A⊠



(Oswego Castings), Site No. 738033

Was the temporary fabric structure closed at the end of the day?	Yes □	No □	N/A⊠
Has Contractor failed to protect all foundations and structures adjacent to and adjoining the site which are affected by the excavations or other operations connected with performance of the Work?	Yes □	No □	N/A⊠
If yes, has Contractor been notified?	Yes □	No □	N/A⊠
Comments: N/A			

Page 6 of 6

Date: 03/18/2024

RESILIENCE/GREEN REMEDIATION CHECKLIST

Is site power procured from renewable energy sources (e.g., solar, wind, geothermal, biomass and biogas)?	Yes □	No □	N/A⊠
Is the Contractor employing 2007 or newer or retrofitted (BART*) diesel on-road trucks and non-road equipment?	Yes □	No □	N/A⊠
Is vehicle idling adequately reduced per 6NYCRR Part 217-3?	Yes □	No □	N/A⊠
Have equipment operators been trained in the idling requirements of 6NYCRR Part 217-3?	Yes □	No □	N/A⊠
Is BART-equipped equipment properly maintained and working?	Yes □	No □	N/A⊠
Is work being sequenced to avoid double handling?	Yes □	No □	N/A⊠
Is there an onsite recycling program for CONTRACTOR-generated wastes and is it complied with?	Yes □	No □	N/A⊠
Are office trailer heating and cooling systems maintained at efficient set points, have programable thermostats been installed?	Yes □	No □	N/A⊠
Are products and materials used in performance of the work appropriately certified (e.g., LEED, Energy Star, Sustainable Forestry Initiative®, etc.)?	Yes □	No □	N/A⊠
Are resiliency features included in the design, or completed remedy properly installed and/or maintained (flood control, storm water controls, erosion measures, etc.)?	Yes □	No □	N/A⊠
Are green remediation elements included in the design, or completed remedy properly installed and/or maintained (e.g., porous pavement, geothermal, variable speed drives, native plantings, natural stream bank restoration, etc.)?	Yes □	No □	N/A⊠
Has Contractor been notified of any deficiencies?	Yes □	No □	N/A⊠
Are remote/call in job meetings being held in lieu of meeting in person where possible?	Yes □	No □	N/A⊠
Comments: N/A			

^{*} BART – Best Available Retrofit Technology

(Oswego Castings), Site No. 738033

ŃEW YORK Contract No. D009806 Department of **NYSDEC Environmental** STATE Division of Environmental Remediation DEC PM - J. Stefansky Conservation Engineer PM - J. Oliver Site Location: Mitchell St., Oswego 13126 Engineer Insp. - H. Bedell **Weather Conditions General Description** PMCloudy AM **Temperature** 55F ΑM PMAM РМ Wind 18 mph W **Health & Safety** If any box below is checked "Yes", provide explanation under "Health & Safety Comments". Were there any changes to the Health & Safety Plan? No X NA Were there any exceedances of the perimeter air monitoring reported on this date? *Yes NA X No Were there any nuisance issues reported/observed on this date? *Yes Nο NA X **Health & Safety Comments** Discussed cold stress, and slips, trips, and falls for site inspection tailgate safety meeting. **Summary of Work Performed** Arrived at site: 0915 Departed Site: 1045 (0915) H. Bedell, C. Derrick and A. Faux (EA) on-site for absorbent sock exchange and gauge DNAPL in MW-1. (0920) Calibrated PID. (0925) EA removed the absorbent sock out of the well and took water level. Product was observed in the absorbent sock. DTW in MW-1 was 2.91 ft BTOC, and DTB was 17.61 ft BTOC. No measurable product, trace product observed on water level indicator. (0940) EA replaced the absorbent sock at the bottom of the well. (0945) EA began locating wells onsite and clearing brush to make access. (1045) H. Bedell, C. Derrick and A. Faux (EA) offsite. **Equipment/Material Tracking** If any box below is checked "Yes", provide explanation under "Material Tracking Comments". Were there any vehicles which did not display proper D.O.T numbers and placards? *Yes NA X No Were there any vehicles which were not tarped? * Yes No NA X Were there any vehicles which were not decontaminated prior to exiting the work * Yes Nο NA X Personnel and Equipment Individual Company **Total Hours** Trade Hannah Bedell Engineer EΑ EΑ 1.5 Cassie Derrick Engineer Alex Faux EΑ Geologist 1.5 **Equipment Description** Contractor/Vendor Quantity Used Various Hand tools EΑ Yes NA 2019 Ford F-150 Yes EΑ PINE Oil water interface probe 1 Yes Honeywell 3000+ miniRAE PINE Imported/ Daily **Waste Profile Exported** Source or Disposal Daily **Material Description Delivered** Weight off Site Facility (If Applicable) (If Applicable) Loads to Site (tons)* *On-Site scale for off-site shipment, delivery ticket for material received **Equipment/Material Tracking Comments:**

Page 1 of 7

Date: 04/19/2024

(Oswego Castings), Site No. 738033

Name		Representing	Entered I	CRZ Zon		
			Yes	Yes No NA		
			Yes	No	NA	
Site Representatives			103	110	NA .	
Name		Representing				
Hannah Bedell		EA				
Cassie Derrick		EA				
Alex Faux		EA				
Drainet Schodule Common	4	•				
		6 May 2024.				
		6 May 2024.				
Groundwater sampling planr		6 May 2024.				
Groundwater sampling planr		6 May 2024.				
Groundwater sampling planr		6 May 2024.				
Groundwater sampling planr Issues Pending	ed for the week of (
Groundwater sampling planr Issues Pending	ed for the week of (
Groundwater sampling plans Issues Pending Interaction with Public, Pro	ed for the week of (

Page **2** of **7**

Date: 04/19/2024

Page 3 of 7
Date: 04/19/2024

Site Photographs (Descriptions Below)



Ponding present around MW-1




Some product observed on the absorbent sock from MW-1



Trace product observed on the oil/water interface probe



Current state the area south of MW-1





Ponding present on soil cap looking north

View of south-end of soft cap and north-end of concrete cap





Location of MW-5 in northwest area of site

Location of MW-6 by fence in southeast corner of site

(Oswego Castings), Site No. 738033



Page **5** of **7**

Date: 04/19/2024

Videos of discreet operations have been provided to the DEC Project Manager to facilitate understanding of the ongoing work? Yes \square No \square N/A X

(Oswego Castings), Site No. 738033

REMEDIAL ACTIVITIES AT PROPERTIES

Page **6** of **7**

Date: 04/19/2024

1.	Does anyone at this location have any symptoms of a respiratory infection (e.g., cough, sore throat, fever, or shortness of breath)?	Yes □	No ⊠
2.	Have anyone at this location been tested and confirmed to have COVID-19?	Yes □	No ⊠
3.	Were personal protective gloves, masks, and eye protection being used?	Yes □	No ⊠
4.	Does the Department and its contractors have your permission to enter the property at this time?	Yes ⊠	No □
5.	If Yes to 1 or 2, follow the latest NYSDOH COVID-19 guidance: https://coronavirus.health.ny.gov/home	Yes ⊠	No □
Comm	ents:		
N/A			

ON-SITE WASTE STORAGE

Drums, roll offs and piles are staged in secure areas?	Yes ⊠	No □	N/A□
Liners and berms have been installed if necessary to prevent cross contamination of clean areas?	Yes □	No □	N/A⊠
Containers are in good condition or properly overpacked?	Yes □	No □	N/A⊠
Waste materials are scheduled to be properly characterized and disposed of prior to demobilization?	Yes □	No □	N/A⊠
Complying with RCRA 90 day storage limitation for hazardous waste?	Yes □	No □	N/A⊠
Piles are securely covered when not in use?	Yes □	No □	N/A⊠
Containers are closed when not in use?	Yes □	No □	N/A⊠
Staging areas should be inspected periodically and any issues addressed immediately?	Yes □	No □	N/A⊠
Signage and labeling comply with RCRA requirements for all staging areas and containers?	Yes □	No □	N/A⊠
If any issues noted, has Contractor been notified?	Yes □	No □	N/A⊠
Comments:			

NUISANCE CHECKLIST

Were there any community complaints related to work on this date?	Yes □	No ⊠	N/A□
Were there any odors detected on this date?	Yes □	No ⊠	N/A□
Was noise outside specification and/or above background on this date?	Yes □	No ⊠	N/A□
Were vibration readings outside specification and/or above background on this date?	Yes □	No □	N/A⊠
Any visible dust observed beyond the work perimeter on this date?	Yes □	No □	N/A⊠
Any visible contrast (turbidity) beyond engineering controls observed on this date?	Yes □	No □	N/A⊠
Was turbidity checked at the outfall(s)?	AM □	РМ□	N/A⊠
Were any property owners NOT provided advance notice for work performed on this property on this date?	Yes □	No □	N/A⊠



(Oswego Castings), Site No. 738033

Was the temporary fabric structure closed at the end of the day?	Yes □	No □	N/A⊠
Has Contractor failed to protect all foundations and structures adjacent to and adjoining the site which are affected by the excavations or other operations connected with performance of the Work?	Yes □	No □	N/A⊠
If yes, has Contractor been notified?	Yes □	No □	N/A⊠
Comments: N/A			

Page **7** of **7**

Date: 04/19/2024

RESILIENCE/GREEN REMEDIATION CHECKLIST

Is site power procured from renewable energy sources (e.g., solar, wind, geothermal, biomass and biogas)?	Yes □	No □	N/A⊠
Is the Contractor employing 2007 or newer or retrofitted (BART*) diesel on-road trucks and non-road equipment?	Yes □	No □	N/A⊠
Is vehicle idling adequately reduced per 6NYCRR Part 217-3?	Yes □	No □	N/A⊠
Have equipment operators been trained in the idling requirements of 6NYCRR Part 217-3?	Yes □	No □	N/A⊠
Is BART-equipped equipment properly maintained and working?	Yes □	No □	N/A⊠
Is work being sequenced to avoid double handling?	Yes □	No □	N/A⊠
Is there an onsite recycling program for CONTRACTOR-generated wastes and is it complied with?	Yes □	No □	N/A⊠
Are office trailer heating and cooling systems maintained at efficient set points, have programable thermostats been installed?	Yes □	No □	N/A⊠
Are products and materials used in performance of the work appropriately certified (e.g., LEED, Energy Star, Sustainable Forestry Initiative®, etc.)?	Yes □	No □	N/A⊠
Are resiliency features included in the design, or completed remedy properly installed and/or maintained (flood control, storm water controls, erosion measures, etc.)?	Yes □	No □	N/A⊠
Are green remediation elements included in the design, or completed remedy properly installed and/or maintained (e.g., porous pavement, geothermal, variable speed drives, native plantings, natural stream bank restoration, etc.)?	Yes □	No □	N/A⊠
Has Contractor been notified of any deficiencies?	Yes □	No □	N/A⊠
Are remote/call in job meetings being held in lieu of meeting in person where possible?	Yes □	No □	N/A⊠
Comments: N/A			

^{*} BART – Best Available Retrofit Technology

(Oswego Castings), Site No. 738033

NYSDEC Division of Environmental Remediation

Site Location: Mitchell St., Oswego 13126

ŃEW YORK Department of **Environmental** Conservation

Contract No. D009806

Page 1 of 8

Date: 05/06/2024

DEC PM - J. Stefansky Engineer PM - J. Oliver

Engineer Insp. - M. Gilkey

Weather Conditions General Description PMSunny AM Sunny **Temperature** 60F AM 62F PMAM N/A Wind N/A PM

Health & Safety

If any box below is checked "Yes", provide explanation under "Health & Safety Comments".

Were there any changes to the Health & Safety Plan?	*Yes	No X	NA
Were there any exceedances of the perimeter air monitoring reported on this date?	*Yes	No	NA X
Were there any nuisance issues reported/observed on this date?	*Yes	No	NA X

Health & Safety Comments

Ticks and poison ivy were discussed during the tailgate safety meeting.

Summary of Work Performed	Arrived at site:	0800	Departed Site:	1215
---------------------------	------------------	------	----------------	------

(0800) C. Derrick, M. Gilkey, H. Bedell, and A. Faux (EA) onsite.

(0805) Calibrate PIDs. Hold safety tailgate meeting.

(0815) Start gauging wells.

(0910) Calibrate Horibas.

(0931) Start purge MW-7.

(0936) Start purge MW-1.

(0944) Start purge MW-4.

(0951) Sample 738033-MW-7-20240506.

(1004) Sample 738033-MW-1-20240506.

(1011) Sample 738033-MW-4-20240506 with MS/MSD.

(1018) Start purge MW-3.

(1020) Replace absorbent sock in MW-1. Absorbent sock pulled from MW-1 had trace amount of product on sock. No product detected with Oil/Water interface probe.

(1028) Start purge MW-2R.

(1039) Sample 738033-MW-3-20240506.

(1056) Sample 738033-MW-2R-20240506 with field duplicate.

(1101) Start purge MW-5.

(1121) Start purge MW-6.

(1122) Sample 738033-MW-5-20240506.

(1147) Sample 738033-MW-6-20240506.

(1200) Inspect concrete and soil caps and take field blank sample.

(1215) EA offsite.

Well ID	Sample	Purge Start	Sample	QA/QC
	Date	Time	Time	
MW-1	5/6/24	0936	1104	
MW-2R	5/6/24	1028	1056	FD
MW-3	5/6/24	1018	1039	
MW-4	5/6/24	0944	1011	MS/MSD
MW-5	5/6/24	1101	1122	
MW-6	5/6/24	1121	1147	
MW-7	5/6/24	0931	1004	

Equipment/Material Tracking

If any box below is checked "Yes", provide explanation under "Material Tracking Comments".

Were there any vehicles which did not display proper D.O.T numbers and placards?	*Yes	No	NA X
Were there any vehicles which were not tarped?	* Yes	No	NA X
Were there any vehicles which were not decontaminated prior to exiting the work site?	* Yes	No	NA X



(Oswego Castings), Site No. 738033

	ent								
Individual		Co	mpany		Tra	ıde		Total I	lours
Cassandra Derrick			EA		Geol	ogist		4.25	
Moriah Gilkey			EA		Engineer			4.25	·
Hannah Bedell			EA		Engineer			4.25	
Alex Faux			EA		Geol	ogist		4.25	
Equipment Description	on		Cont	ractor/Vendor			Quantity	Use	ed
Horiba			Pine	Environmental			3	Υ	
RXI GX-6000				Environmental			2	Y	
Peristaltic Pumps			Pine	Environmental			3	Υ	
Solonist Water Level Me				Environmental			3	Υ	
Oil-Water Interface Pro					1	Υ			
55-Gallon Steel Drun	m	=			1	Y			
Hand Tools		EA NA			Y				
Ford F-150 Truck				EA			1	Y	
Dodge Ram Truck				Enterprise			TI TI	Y	
Material Description	Imported/ Delivered to Site	Exported off Site		aste Profile Applicable)			· Disposal Applicable)	Daily Loads	Daily Weigh (tons)
^{N/A} Equipment/Material Tra	acking Com	ımente:	<u>I</u>						<u>I</u>
Visitors to Site									
Name			Rep	resenting		En	tered Exc	lusion/CF	RZ Zon
None			•			Yes		No	
						Ye	s	No	
Site Representatives									
Name				Representin	ıg				
Cassandra Derrick				EA					
Moriah Gilkey				EA					
Hannah Bedell				EA					
Alex Faux				EA					
Project Schedule Comi	ments			!					
Sample cooler was pack	ed, sealed,	and deliver	ed to S	GS Galson.					
Issues Pending									
None.	Dugueste	Duma 11	alie - t						
	, Property (Owners, Me	edia, et	Cc.					

Page 2 of 8 Date: 05/06/2024



(Oswego Castings), Site No. 738033

Site Photographs (Descriptions Below)



View of concrete cap.



Page 3 of 8

Date: 05/06/2024

Surface water pooling between concrete cap and soil cap with observed product and sheen.



Pooling and hole in concrete cap.



Drum for purged groundwater with label.



Surface water pooling between concrete cap and soil cap with observed product and sheen.

Cracks and pooling in concrete cap.





Low-flow groundwater purge setup on MW-1.

Low-flow groundwater purge setup on MW-6.



Page 5 of 8 Date: 05/06/2024 (Oswego Castings), Site No. 738033





View of soil cap and pooling from NW.

View of soil cap and pooling from SW.





View of soil cap and pooling from NE.

View of soil cap, concrete cap, and pooling from North.





View of soil cap and pooling from North.

View of soil cap, concrete cap, and pooling from North.

(Oswego Castings), Site No. 738033




Absorbent sock pulled from MW-1. Trace amount of product present on sock. No product detected with Oil/Water interface probe.



Page 6 of 8

Date: 05/06/2024

Absorbent sock pulled from MW-1. Trace amount of product present on sock. No product detected with Oil/Water interface probe.



Oil/Water interface probe after use in MW-1.

Site Inspector(s): Cassandra Derrick, Moriah Gilkey, Hannah Bedell, and Alex Faux

Date: 05/06/2024

Videos of discreet operations have been provided to the DEC Project Manager to facilitate understanding of the ongoing work? Yes \square No \square N/A X



(Oswego Castings), Site No. 738033

REMEDIAL ACTIVITIES AT PROPERTIES

Page **7** of **8**

Date: 05/06/2024

1.	Does anyone at this location have any symptoms of a respiratory infection (e.g., cough, sore throat, fever, or shortness of breath)?	Yes □	No ⊠		
2.	2. Have anyone at this location been tested and confirmed to have COVID-19?				
3.	Were personal protective gloves, masks, and eye protection being used?	Yes □	No ⊠		
4.	Does the Department and its contractors have your permission to enter the property at this time?	Yes ⊠	No □		
5.	If Yes to 1 or 2, follow the latest NYSDOH COVID-19 guidance: https://coronavirus.health.ny.gov/home	Yes □	No □		
Comm N/A	ents:				

ON-SITE WASTE STORAGE

Drums, roll offs and piles are staged in secure areas?	Yes ⊠	No □	N/A□
Liners and berms have been installed if necessary to prevent cross contamination of clean areas?	Yes □	No □	N/A⊠
Containers are in good condition or properly overpacked?	Yes □	No □	N/A⊠
Waste materials are scheduled to be properly characterized and disposed of prior to demobilization?	Yes □	No □	N/A⊠
Complying with RCRA 90 day storage limitation for hazardous waste?	Yes □	No □	N/A⊠
Piles are securely covered when not in use?	Yes □	No □	N/A⊠
Containers are closed when not in use?	Yes □	No □	N/A⊠
Staging areas should be inspected periodically and any issues addressed immediately?	Yes □	No □	N/A⊠
Signage and labeling comply with RCRA requirements for all staging areas and containers?	Yes □	No □	N/A⊠
If any issues noted, has Contractor been notified?	Yes □	No □	N/A⊠
Comments: NA			

NUISANCE CHECKLIST

Were there any community complaints related to work on this date?	Yes □	No ⊠	N/A□
Were there any odors detected on this date?	Yes □	No ⊠	N/A□
Was noise outside specification and/or above background on this date?	Yes □	No ⊠	N/A□
Were vibration readings outside specification and/or above background on this date?	Yes □	No □	N/A⊠
Any visible dust observed beyond the work perimeter on this date?	Yes □	No □	N/A⊠
Any visible contrast (turbidity) beyond engineering controls observed on this date?	Yes □	No □	N/A⊠
Was turbidity checked at the outfall(s)?	AM □	РМ□	N/A⊠
Were any property owners NOT provided advance notice for work performed on this property on this date?	Yes □	No □	N/A⊠



(Oswego Castings), Site No. 738033

Was the temporary fabric structure closed at the end of the day?	Yes □	No □	N/A⊠
Has Contractor failed to protect all foundations and structures adjacent to and adjoining the site which are affected by the excavations or other operations connected with performance of the Work?	Yes □	No □	N/A⊠
If yes, has Contractor been notified?	Yes □	No □	N/A⊠
Comments: N/A			

Page 8 of 8

Date: 05/06/2024

RESILIENCE/GREEN REMEDIATION CHECKLIST

Is site power procured from renewable energy sources (e.g., solar, wind, geothermal, biomass and biogas)?	Yes □	No □	N/A⊠
Is the Contractor employing 2007 or newer or retrofitted (BART*) diesel on-road trucks and non-road equipment?	Yes □	No □	N/A⊠
Is vehicle idling adequately reduced per 6NYCRR Part 217-3?	Yes □	No □	N/A⊠
Have equipment operators been trained in the idling requirements of 6NYCRR Part 217-3?	Yes □	No □	N/A⊠
Is BART-equipped equipment properly maintained and working?	Yes □	No □	N/A⊠
Is work being sequenced to avoid double handling?	Yes □	No □	N/A⊠
Is there an onsite recycling program for CONTRACTOR-generated wastes and is it complied with?	Yes □	No □	N/A⊠
Are office trailer heating and cooling systems maintained at efficient set points, have programable thermostats been installed?	Yes □	No □	N/A⊠
Are products and materials used in performance of the work appropriately certified (e.g., LEED, Energy Star, Sustainable Forestry Initiative®, etc.)?	Yes □	No □	N/A⊠
Are resiliency features included in the design, or completed remedy properly installed and/or maintained (flood control, storm water controls, erosion measures, etc.)?	Yes □	No □	N/A⊠
Are green remediation elements included in the design, or completed remedy properly installed and/or maintained (e.g., porous pavement, geothermal, variable speed drives, native plantings, natural stream bank restoration, etc.)?	Yes □	No □	N/A⊠
Has Contractor been notified of any deficiencies?	Yes □	No □	N/A⊠
Are remote/call in job meetings being held in lieu of meeting in person where possible?	Yes □	No □	N/A⊠
Comments: N/A			

^{*} BART – Best Available Retrofit Technology

(Oswego Castings), Site No. 738033

Contract No. D009806 Department of **NYSDEC** YORK **Environmental** Division of Environmental Remediation DEC PM - J. Stefansky Conservation Engineer PM - J. Oliver Site Location: Mitchell St., Oswego 13126 Engineer Insp. - H. Bedell **Weather Conditions General Description** PMSunny AM **Temperature** 74F ΑM PM AM Wind 8 mph S PM **Health & Safety** If any box below is checked "Yes", provide explanation under "Health & Safety Comments". Were there any changes to the Health & Safety Plan? No X NA Were there any exceedances of the perimeter air monitoring reported on this date? *Yes NA X No NA X Were there any nuisance issues reported/observed on this date? *Yes Nο **Health & Safety Comments** Discussed slips, trips, and falls and heat stress for site inspection tailgate safety meeting. 0930 1030 **Summary of Work Performed** Arrived at site: Departed Site: (0930) H. Bedell and C. Zook (EA) on-site for absorbent sock exchange and gauge DNAPL in MW-1. (0935) Calibrated PID. (0940) EA removed the absorbent sock out of the well and took water level. Product was observed in the absorbent sock. DTW in MW-1 was 5.97 ft BTOC, and DTB was 17.43 ft BTOC. No measurable product trace product observed on water level indicator. (0955) EA replaced the absorbent sock at the bottom of the well. (1005) EA conducted a visual inspection of the soft cap. There is a small drainage ditch present running from the western boundary to the southern boundary of the cap. No saturation was observed. There were 3 small piles (2 dirt and 1 debris) located partially inside the northern boundary of the cap near the north east corner. (1030) H. Bedell and C. Zook (EA) offsite. **Equipment/Material Tracking** If any box below is checked "Yes", provide explanation under "Material Tracking Comments". Were there any vehicles which did not display proper D.O.T numbers and placards? *Yes No NA X Were there any vehicles which were not tarped? * Yes No NA X Were there any vehicles which were not decontaminated prior to exiting the work No * Yes NA X Personnel and Equipment Individual Company **Trade Total Hours** Hannah Bedell Engineer EΑ Clara Zook FΑ Intern 1.0 **Equipment Description** Contractor/Vendor Quantity Used Various Hand tools NΑ Yes FA 2023 Ford Expedition EΑ Yes PINE Yes Oil water interface probe 1 Honeywell 3000+ miniRAE PINE Imported/ Daily **Waste Profile** Daily **Exported** Source or Disposal **Material Description** Delivered Weight off Site Facility (If Applicable) Loads (If Applicable) to Site (tons)*

Page 1 of 7

Date: 06/17/2024

*On-Site scale for off-site shipment, delivery ticket for material received

Equipment/Material Tracking Comments:

(Oswego Castings), Site No. 738033

Name	R	Representing		Entered Exclusion/CR	
			Yes	No	NA
			Yes	No	NA
Site Representatives					
Name		Representing			
Hannah Bedell		EA			
Clara Zook		EA			
Project Schedule Comments					
Issues Pending					
Project Schedule Comments Issues Pending Interaction with Public, Prope	rty Owners, Media,	etc.			
Issues Pending	rty Owners, Media,	etc.			

Page 2 of 7
Date: 06/17/2024

Page 3 of 7
Date: 06/17/2024

Site Photographs (Descriptions Below)






Vegetaion present around MW-1

Some product observed on the absorbent sock from MW-1







Current state the area south of MW-1, large ruts present but ground was not soft



Some product observed on the absorbent sock from MW-1



Page **4** of **7 Date: 06/17/2024**

City of Oswego had moved drum with used absorbent socks to this location in front of building adjacent to MW-1, EA moved back next to MW-1




Two small piles present along northern boundary of soft cap



View of soft cap looking north

(Oswego Castings), Site No. 738033



Page **5** of **7**

Date: 06/17/2024

Videos of discreet operations have been provided to the DEC Project Manager to facilitate understanding of the ongoing work? Yes \square No \square N/A X

(Oswego Castings), Site No. 738033

REMEDIAL ACTIVITIES AT PROPERTIES

Page **6** of **7**

Date: 06/17/2024

1.	Does anyone at this location have any symptoms of a respiratory infection (e.g., cough, sore throat, fever, or shortness of breath)?	Yes □	No ⊠
2.	Have anyone at this location been tested and confirmed to have COVID-19?	Yes □	No ⊠
3.	Were personal protective gloves, masks, and eye protection being used?	Yes □	No ⊠
4.	Does the Department and its contractors have your permission to enter the property at this time?	Yes ⊠	No □
5.	If Yes to 1 or 2, follow the latest NYSDOH COVID-19 guidance: https://coronavirus.health.ny.gov/home	Yes ⊠	No □
Comm N/A	ents:		

ON-SITE WASTE STORAGE

Drums, roll offs and piles are staged in secure areas?	Yes ⊠	No □	N/A□
Liners and berms have been installed if necessary to prevent cross contamination of clean areas?	Yes □	No □	N/A⊠
Containers are in good condition or properly overpacked?	Yes □	No □	N/A⊠
Waste materials are scheduled to be properly characterized and disposed of prior to demobilization?	Yes □	No □	N/A⊠
Complying with RCRA 90 day storage limitation for hazardous waste?	Yes □	No □	N/A⊠
Piles are securely covered when not in use?	Yes □	No □	N/A⊠
Containers are closed when not in use?	Yes □	No □	N/A⊠
Staging areas should be inspected periodically and any issues addressed immediately?	Yes □	No □	N/A⊠
Signage and labeling comply with RCRA requirements for all staging areas and containers?	Yes □	No □	N/A⊠
If any issues noted, has Contractor been notified?	Yes □	No □	N/A⊠
Comments:			

NUISANCE CHECKLIST

Were there any community complaints related to work on this date?	Yes □	No ⊠	N/A□
Were there any odors detected on this date?	Yes □	No ⊠	N/A□
Was noise outside specification and/or above background on this date?	Yes □	No ⊠	N/A□
Were vibration readings outside specification and/or above background on this date?	Yes □	No □	N/A⊠
Any visible dust observed beyond the work perimeter on this date?	Yes □	No □	N/A⊠
Any visible contrast (turbidity) beyond engineering controls observed on this date?	Yes □	No □	N/A⊠
Was turbidity checked at the outfall(s)?	AM □	РМ□	N/A⊠
Were any property owners NOT provided advance notice for work performed on this property on this date?	Yes □	No □	N/A⊠



(Oswego Castings), Site No. 738033

Was the temporary fabric structure closed at the end of the day?	Yes □	No □	N/A⊠
Has Contractor failed to protect all foundations and structures adjacent to and adjoining the site which are affected by the excavations or other operations connected with performance of the Work?	Yes □	No □	N/A⊠
If yes, has Contractor been notified?	Yes □	No □	N/A⊠
Comments: N/A			

Page **7** of **7 Date: 06/17/2024**

RESILIENCE/GREEN REMEDIATION CHECKLIST

Is site power procured from renewable energy sources (e.g., solar, wind, geothermal, biomass and biogas)?	Yes □	No □	N/A⊠
Is the Contractor employing 2007 or newer or retrofitted (BART*) diesel on-road trucks and non-road equipment?	Yes □	No □	N/A⊠
Is vehicle idling adequately reduced per 6NYCRR Part 217-3?	Yes □	No □	N/A⊠
Have equipment operators been trained in the idling requirements of 6NYCRR Part 217-3?	Yes □	No □	N/A⊠
Is BART-equipped equipment properly maintained and working?	Yes □	No □	N/A⊠
Is work being sequenced to avoid double handling?	Yes □	No □	N/A⊠
Is there an onsite recycling program for CONTRACTOR-generated wastes and is it complied with?	Yes □	No □	N/A⊠
Are office trailer heating and cooling systems maintained at efficient set points, have programable thermostats been installed?	Yes □	No □	N/A⊠
Are products and materials used in performance of the work appropriately certified (e.g., LEED, Energy Star, Sustainable Forestry Initiative®, etc.)?	Yes □	No □	N/A⊠
Are resiliency features included in the design, or completed remedy properly installed and/or maintained (flood control, storm water controls, erosion measures, etc.)?	Yes □	No □	N/A⊠
Are green remediation elements included in the design, or completed remedy properly installed and/or maintained (e.g., porous pavement, geothermal, variable speed drives, native plantings, natural stream bank restoration, etc.)?	Yes □	No □	N/A⊠
Has Contractor been notified of any deficiencies?	Yes □	No □	N/A⊠
Are remote/call in job meetings being held in lieu of meeting in person where possible?	Yes □	No □	N/A⊠
Comments: N/A			

^{*} BART – Best Available Retrofit Technology

(Oswego Castings), Site No. 738033

Contract No. D009806 Department of **NYSDEC** YORK **Environmental** STATE Division of Environmental Remediation DEC PM - J. Stefansky Conservation Engineer PM - J. Oliver Site Location: Mitchell St., Oswego 13126 Engineer Insp. - M. Gilkey **Weather Conditions General Description** PMSunny AM **Temperature** 78 ΑM PMAM Wind 8 mph S PM**Health & Safety** If any box below is checked "Yes", provide explanation under "Health & Safety Comments". Were there any changes to the Health & Safety Plan? No X NA Were there any exceedances of the perimeter air monitoring reported on this date? *Yes NA X No Were there any nuisance issues reported/observed on this date? *Yes Nο NA X **Health & Safety Comments** Discussed slips, trips, and falls and heat stress for site inspection tailgate safety meeting. **Summary of Work Performed** Arrived at site: 0900 Departed Site: 0945 (0900) M. Gilkey and C. Zook (EA) on-site for absorbent sock exchange and gauge DNAPL in MW-1. (0910) Calibrated PID. (0915) EA removed the absorbent sock out of the well and took water level. Product was observed in the absorbent sock. DTW in MW-1 was 4.95 ft BTOC, and DTB was 17.45 ft BTOC. No measurable product, trace product observed on water level indicator. (0920) EA replaced the absorbent sock at the bottom of the well. (0930) EA conducted a visual inspection of the soft cap. There is a small drainage ditch present running from the western boundary to the southern boundary of the cap. Drainage ditch was damp, but no running water was observed. There were two areas of small to moderate ponding on the soft cap area. There were 3 small piles (2 dirt and 1 debris) located partially inside the northern boundary of the cap near the northeast corner. (0945) M. Gilkey and C. Zook (EA) offsite. **Equipment/Material Tracking** If any box below is checked "Yes", provide explanation under "Material Tracking Comments". Were there any vehicles which did not display proper D.O.T numbers and placards? NA X *Yes No Were there any vehicles which were not tarped? NA X * Yes No Were there any vehicles which were not decontaminated prior to exiting the work * Yes No NA X site? Personnel and Equipment Individual **Total Hours** Company Trade Moriah Gilkey EΑ Engineer 1.0 Clara Zook EΑ 1.0 Intern Contractor/Vendor **Equipment Description** Quantity Used Various Hand tools EΑ NA Yes 2023 Ford Explorer EΑ Yes 1 Oil water interface probe PINE Yes PINE Honeywell 3000+ miniRAE Yes Imported/ Daily **Waste Profile Exported** Source or Disposal Daily **Material Description Delivered** Weight off Site Facility (If Applicable) I nads (If Applicable) to Site (tons)* *On-Site scale for off-site shipment, delivery ticket for material received **Equipment/Material Tracking Comments:**

Page 1 of 7

Date: 07/15/2024

(Oswego Castings), Site No. 738033

Site Representatives Name Moriah Gilkey	Representing EA EA	Yes	No No	NA NA
Moriah Gilkey Clara Zook Project Schedule Comments Issues Pending	EA	•	No	NA
Moriah Gilkey Clara Zook Project Schedule Comments Issues Pending	EA	•	NO	NA
Moriah Gilkey Clara Zook Project Schedule Comments Issues Pending	EA			
Moriah Gilkey Clara Zook Project Schedule Comments Issues Pending	EA			
Project Schedule Comments Issues Pending				
Project Schedule Comments Issues Pending				
Issues Pending				
Issues Pending				
Interaction with Public Property Owners Media etc				
Interaction with Public Property Owners Media etc				
Interaction with Public Property Owners Media etc				
interaction with rubinc, rroperty owners, wedia, etc	C.			

Page 2 of 7 Date: 07/15/2024

Site Photographs (Descriptions Below)





Page 3 of 7

Date: 07/15/2024

Vegetation around MW-1 and drum near southern wall of the main building onsite.

Main Building onsite and pole barn on the southern end of the site. Photo taken looking east.





Main Building onsite and pole barn on the southern end of the site. Photo taken looking east. MW-2R is located within the phragmites in the picture.

Vegetation around MW-1 and drum near southern wall of the main building onsite. Photo taken looking northwest.



View of soft cap looking northeast standing on the southwest corner of the soft cap.



Page **4** of **7**

Date: 07/15/2024

View of soft cap looking southeast standing on the southwest corner of the soft cap.



View from northwest corner of soft cap looking east



Piles of gravel not on soft cap on the northwest side of the site



View from northwest corner of soft cap looking southest



View from northwest quadrante of soft cap looking southeast. Small – medium puddles were observed on the soft cap.

(Oswego Castings), Site No. 738033



Page **5** of **7**



Trace oil observed on the absorbant sock



Small amount of oil on the end of the oil water interface probe



View from northeast corner of soft cap looking southwest. Moderately sized ponding occurring.



View from northeast corner of soft cap looking west

Site Inspector(s): Moriah Gilkey Date: 07/15/2024

Videos of discreet operations have been provided to the DEC Project Manager to facilitate understanding of the ongoing work? Yes \square No \square N/A X

(Oswego Castings), Site No. 738033

REMEDIAL ACTIVITIES AT PROPERTIES

Page **6** of **7**

Date: 07/15/2024

1.	Does anyone at this location have any symptoms of a respiratory infection (e.g., cough, sore throat, fever, or shortness of breath)?	Yes □	No ⊠
2.	Have anyone at this location been tested and confirmed to have COVID-19?	Yes □	No ⊠
3.	Were personal protective gloves, masks, and eye protection being used?	Yes □	No ⊠
4.	Does the Department and its contractors have your permission to enter the property at this time?	Yes ⊠	No □
5.	If Yes to 1 or 2, follow the latest NYSDOH COVID-19 guidance: https://coronavirus.health.ny.gov/home	Yes ⊠	No 🗆
Comm	ents:		
N/A			

ON-SITE WASTE STORAGE

Drums, roll offs and piles are staged in secure areas?	Yes ⊠	No □	N/A□
Liners and berms have been installed if necessary to prevent cross contamination of clean areas?	Yes □	No □	N/A⊠
Containers are in good condition or properly overpacked?	Yes □	No □	N/A⊠
Waste materials are scheduled to be properly characterized and disposed of prior to demobilization?	Yes □	No □	N/A⊠
Complying with RCRA 90 day storage limitation for hazardous waste?	Yes □	No □	N/A⊠
Piles are securely covered when not in use?	Yes □	No □	N/A⊠
Containers are closed when not in use?	Yes □	No □	N/A⊠
Staging areas should be inspected periodically and any issues addressed immediately?	Yes □	No □	N/A⊠
Signage and labeling comply with RCRA requirements for all staging areas and containers?	Yes □	No □	N/A⊠
If any issues noted, has Contractor been notified?	Yes □	No □	N/A⊠
Comments:			

NUISANCE CHECKLIST

Were there any community complaints related to work on this date?	Yes □	No ⊠	N/A□
Were there any odors detected on this date?	Yes □	No ⊠	N/A□
Was noise outside specification and/or above background on this date?	Yes □	No ⊠	N/A□
Were vibration readings outside specification and/or above background on this date?	Yes □	No □	N/A⊠
Any visible dust observed beyond the work perimeter on this date?	Yes □	No □	N/A⊠
Any visible contrast (turbidity) beyond engineering controls observed on this date?	Yes □	No □	N/A⊠
Was turbidity checked at the outfall(s)?	AM □	РМ□	N/A⊠
Were any property owners NOT provided advance notice for work performed on this property on this date?	Yes □	No □	N/A⊠



(Oswego Castings), Site No. 738033

Was the temporary fabric structure closed at the end of the day?	Yes □	No □	N/A⊠
Has Contractor failed to protect all foundations and structures adjacent to and adjoining the site which are affected by the excavations or other operations connected with performance of the Work?	Yes □	No □	N/A⊠
If yes, has Contractor been notified?	Yes □	No □	N/A⊠
Comments: N/A			

Page **7** of **7**

Date: 07/15/2024

RESILIENCE/GREEN REMEDIATION CHECKLIST

Is site power procured from renewable energy sources (e.g., solar, wind, geothermal, biomass and biogas)?	Yes □	No □	N/A⊠
Is the Contractor employing 2007 or newer or retrofitted (BART*) diesel on-road trucks and non-road equipment?	Yes □	No □	N/A⊠
Is vehicle idling adequately reduced per 6NYCRR Part 217-3?	Yes □	No □	N/A⊠
Have equipment operators been trained in the idling requirements of 6NYCRR Part 217-3?	Yes □	No □	N/A⊠
Is BART-equipped equipment properly maintained and working?	Yes □	No □	N/A⊠
Is work being sequenced to avoid double handling?	Yes □	No □	N/A⊠
Is there an onsite recycling program for CONTRACTOR-generated wastes and is it complied with?	Yes □	No □	N/A⊠
Are office trailer heating and cooling systems maintained at efficient set points, have programable thermostats been installed?	Yes □	No □	N/A⊠
Are products and materials used in performance of the work appropriately certified (e.g., LEED, Energy Star, Sustainable Forestry Initiative®, etc.)?	Yes □	No □	N/A⊠
Are resiliency features included in the design, or completed remedy properly installed and/or maintained (flood control, storm water controls, erosion measures, etc.)?	Yes □	No □	N/A⊠
Are green remediation elements included in the design, or completed remedy properly installed and/or maintained (e.g., porous pavement, geothermal, variable speed drives, native plantings, natural stream bank restoration, etc.)?	Yes □	No □	N/A⊠
Has Contractor been notified of any deficiencies?	Yes □	No □	N/A⊠
Are remote/call in job meetings being held in lieu of meeting in person where possible?	Yes □	No □	N/A⊠
Comments: N/A			

^{*} BART – Best Available Retrofit Technology

(Oswego Castings), Site No. 738033

Contract No. D009806 Department of **NYSDEC** YORK **Environmental** Division of Environmental Remediation DEC PM - J. Stefansky Conservation Engineer PM - J. Oliver Site Location: Mitchell St., Oswego 13126 Engineer Insp. - H. Bedell **Weather Conditions General Description** PMSunny AM **Temperature** 70 ΑM PM3 mph S AM РМ Wind **Health & Safety** If any box below is checked "Yes", provide explanation under "Health & Safety Comments". Were there any changes to the Health & Safety Plan? No X NA Were there any exceedances of the perimeter air monitoring reported on this date? *Yes NA X No Were there any nuisance issues reported/observed on this date? *Yes Nο NA X **Health & Safety Comments** Discussed slips, trips, and falls and heat stress for site inspection tailgate safety meeting. 0910 **Summary of Work Performed** Arrived at site: Departed Site: 0940 (0910) H. Bedell and A. Townsend (EA) on-site for absorbent sock exchange and gauge DNAPL in MW-1. (0915) Calibrated PID. (0920) EA removed the absorbent sock out of the well and took water level. Product was not observed in the absorbent sock, DTW in MW-1 was 4.35 ft BTOC, and DTB was 17.46 ft BTOC. No measurable product, trace product observed on water level indicator. (0930) EA replaced the absorbent sock at the bottom of the well. (0935) EA conducted a visual inspection of the soil cover. There is a small drainage ditch present running from the western boundary to the southern boundary of the soil cover. Running water was observed in the drainage ditch. There was ponding on the soil cover area. (0940) H. Bedell and A. Townsend (EA) offsite. **Equipment/Material Tracking** If any box below is checked "Yes", provide explanation under "Material Tracking Comments". Were there any vehicles which did not display proper D.O.T numbers and placards? *Yes NA X No Were there any vehicles which were not tarped? Yes No NA X Were there any vehicles which were not decontaminated prior to exiting the work * Yes Nο NA X Personnel and Equipment Individual Company Trade **Total Hours** Hannah Bedell Engineer EΑ 0.5 Amanda Townsend FΑ Engineer **Equipment Description** Contractor/Vendor Quantity Used Various Hand tools NA Yes FA 2023 Ford Expedition EΑ 1 Yes PINE Yes Oil water interface probe 1 Honeywell 3000+ miniRAE PINE Imported/ Daily **Waste Profile Exported** Source or Disposal Daily **Material Description** Delivered Weight off Site Facility (If Applicable) Loads (If Applicable) to Site (tons)*

Page 1 of 6

Date: 08/26/2024

Equipment/Material Tracking Comments:

*On-Site scale for off-site shipment, delivery ticket for material received

(Oswego Castings), Site No. 738033

Visitors to Site Name	Pon	roconting	Entored F	Exclusion/	CP7 7000
Name	Kep	Representing		ZXCIUSIOII/	CKZ ZUITE
			Yes	No	NA
			Yes	No	NA
Site Representatives					
Name		Representing			
Hannah Bedell		EA			
Amanda Townsend		EA			
Project Schedule Comments					
Issues Pending					
Interaction with Public, Property	y Owners, Media, et	c.			

Page 2 of 6 Date: 08/26/2024

Page 3 of 6 (Oswego Castings), Site No. 738033 Date: 08/26/2024 Site Photographs (Descriptions Below) Absorbant sock that was removed from MW-1.

Vegetation around MW-1



No oil observed on the absorbant sock.



Trace amount of oil on the end of the oil water interface probe.

(Oswego Castings), Site No. 738033



View of soil cover looking north standing on the south side of the soil cover.



Page 4 of 6

Date: 08/26/2024

View of soil cover looking northeast standing on the southwest corner of the soil cover.



View of soil cover looking southwest. Running water observed.



View from south side of soil cover looking north.

Ponding occurring.



View from east side of soil cover looking west



View from south side of soil cover looking north.

Tracks in soil cover.

Site Inspector(s): Hannah Bedell

Date: 08/26/2024

Videos of discreet operations have been provided to the DEC Project Manager to facilitate understanding of the ongoing work? Yes \square No \square N/A X



(Oswego Castings), Site No. 738033

REMEDIAL ACTIVITIES AT PROPERTIES

Page **5** of **6**

Date: 08/26/2024

1.	Does anyone at this location have any symptoms of a respiratory infection (e.g., cough, sore throat, fever, or shortness of breath)?	Yes □	No ⊠
2.	Have anyone at this location been tested and confirmed to have COVID-19?	Yes □	No ⊠
3.	Were personal protective gloves, masks, and eye protection being used?	Yes □	No ⊠
4.	Does the Department and its contractors have your permission to enter the property at this time?	Yes ⊠	No □
5.	If Yes to 1 or 2, follow the latest NYSDOH COVID-19 guidance: https://coronavirus.health.ny.gov/home	Yes ⊠	No □
Comm N/A	<u>ents:</u>		

ON-SITE WASTE STORAGE

Drums, roll offs and piles are staged in secure areas?	Yes ⊠	No □	N/A□
Liners and berms have been installed if necessary to prevent cross contamination of clean areas?	Yes □	No □	N/A⊠
Containers are in good condition or properly overpacked?	Yes □	No □	N/A⊠
Waste materials are scheduled to be properly characterized and disposed of prior to demobilization?	Yes □	No □	N/A⊠
Complying with RCRA 90 day storage limitation for hazardous waste?	Yes □	No □	N/A⊠
Piles are securely covered when not in use?	Yes □	No □	N/A⊠
Containers are closed when not in use?	Yes □	No □	N/A⊠
Staging areas should be inspected periodically and any issues addressed immediately?	Yes □	No □	N/A⊠
Signage and labeling comply with RCRA requirements for all staging areas and containers?	Yes □	No □	N/A⊠
If any issues noted, has Contractor been notified?	Yes □	No □	N/A⊠
Comments:			

NUISANCE CHECKLIST

Were there any community complaints related to work on this date?	Yes □	No ⊠	N/A□
Were there any odors detected on this date?	Yes □	No ⊠	N/A□
Was noise outside specification and/or above background on this date?	Yes □	No ⊠	N/A□
Were vibration readings outside specification and/or above background on this date?	Yes □	No □	N/A⊠
Any visible dust observed beyond the work perimeter on this date?	Yes □	No □	N/A⊠
Any visible contrast (turbidity) beyond engineering controls observed on this date?	Yes □	No □	N/A⊠
Was turbidity checked at the outfall(s)?	AM □	РМ□	N/A⊠
Were any property owners NOT provided advance notice for work performed on this property on this date?	Yes □	No □	N/A⊠



(Oswego Castings), Site No. 738033

Was the temporary fabric structure closed at the end of the day?	Yes □	No □	N/A⊠
Has Contractor failed to protect all foundations and structures adjacent to and adjoining the site which are affected by the excavations or other operations connected with performance of the Work?	Yes □	No □	N/A⊠
If yes, has Contractor been notified?	Yes □	No □	N/A⊠
Comments: N/A			

Page 6 of 6 Date: 08/26/2024

RESILIENCE/GREEN REMEDIATION CHECKLIST

Is site power procured from renewable energy sources (e.g., solar, wind, geothermal, biomass and biogas)?	Yes □	No □	N/A⊠
Is the Contractor employing 2007 or newer or retrofitted (BART*) diesel on-road trucks and non-road equipment?	Yes □	No □	N/A⊠
Is vehicle idling adequately reduced per 6NYCRR Part 217-3?	Yes □	No □	N/A⊠
Have equipment operators been trained in the idling requirements of 6NYCRR Part 217-3?	Yes □	No □	N/A⊠
Is BART-equipped equipment properly maintained and working?	Yes □	No □	N/A⊠
Is work being sequenced to avoid double handling?	Yes □	No □	N/A⊠
Is there an onsite recycling program for CONTRACTOR-generated wastes and is it complied with?	Yes □	No □	N/A⊠
Are office trailer heating and cooling systems maintained at efficient set points, have programable thermostats been installed?	Yes □	No □	N/A⊠
Are products and materials used in performance of the work appropriately certified (e.g., LEED, Energy Star, Sustainable Forestry Initiative®, etc.)?	Yes □	No □	N/A⊠
Are resiliency features included in the design, or completed remedy properly installed and/or maintained (flood control, storm water controls, erosion measures, etc.)?	Yes □	No □	N/A⊠
Are green remediation elements included in the design, or completed remedy properly installed and/or maintained (e.g., porous pavement, geothermal, variable speed drives, native plantings, natural stream bank restoration, etc.)?	Yes □	No □	N/A⊠
Has Contractor been notified of any deficiencies?	Yes □	No □	N/A⊠
Are remote/call in job meetings being held in lieu of meeting in person where possible?	Yes □	No □	N/A⊠
Comments: N/A			

^{*} BART – Best Available Retrofit Technology

(Oswego Castings), Site No. 738033

Date: 10/22/2024 Contract No. D009806 Department of **NYSDEC** YORK **Environmental** Division of Environmental Remediation DEC PM - J. Stefansky Conservation Engineer PM - J. Oliver Site Location: Mitchell St., Oswego 13126 Engineer Insp. - H. Bedell **Weather Conditions General Description** PMSunny AM **Temperature** 57 ΑM PMAM Wind 6 mph SE PM**Health & Safety** If any box below is checked "Yes", provide explanation under "Health & Safety Comments". Were there any changes to the Health & Safety Plan? No X NA Were there any exceedances of the perimeter air monitoring reported on this date? *Yes NA X No Were there any nuisance issues reported/observed on this date? *Yes Nο NA X **Health & Safety Comments** Discussed situational awareness of heavy machinery and large trucks entering and exiting the site for site inspection tailgate safety meeting. Arrived at site: 0910 Departed Site: 0940 **Summary of Work Performed** (0920) H. Bedell and M. Gilkey (EA) on-site for absorbent sock exchange and gauge DNAPL in MW-1. (0930) Calibrated PID. (0932) EA removed the absorbent sock out of the well. Trace amounts of product was observed in the absorbent sock. (0935) Gauged MW-1 DTW in MW-1 was 4.35 ft BTOC, and DTB was 17.46 ft BTOC. No measurable product, trace product observed on water level indicator. (0945) EA replaced the absorbent sock at the bottom of the well. (0950) EA conducted a visual inspection of the soil cover. There is a small drainage ditch present running from the western boundary to the southern boundary of the soil cover. Running water was observed in the drainage ditch. There was ponding on the soil cover area. (1020) H. Bedell and M. Gilkey (EA) offsite. **Equipment/Material Tracking** If any box below is checked "Yes", provide explanation under "Material Tracking Comments". Were there any vehicles which did not display proper D.O.T numbers and placards? *Yes NA X Were there any vehicles which were not tarped? * Yes No NA X Were there any vehicles which were not decontaminated prior to exiting the work * Yes No NA X site? Personnel and Equipment Individual Company **Trade Total Hours** Hannah Bedell EΑ Engineer 1.0 Moriah Gilkey Engineer 10 Contractor/Vendor Used **Equipment Description** Quantity Various Hand tools EΑ NA Yes 2023 Ford Expedition EΑ Yes 1 PINE Oil water interface probe 1 Yes Honeywell 3000+ miniRAE **PINE** Yes Imported/ Daily **Waste Profile Exported** Source or Disposal Daily **Material Description** Delivered Weight off Site (If Applicable) Facility (If Applicable) Loads to Site (tons)*

Page 1 of 6

*On-Site scale for off-site shipment, delivery ticket for material received

Equipment/Material Tracking Comments:




(Oswego Castings), Site No. 738033

Visitors to Site Name Representing **Entered Exclusion/CRZ Zone** Yes No NA NA Yes No **Site Representatives** Representing Name Hannah Bedell EΑ EΑ Moriah Gilkey **Project Schedule Comments** Next inspection is planned for December 2024. **Issues Pending** Interaction with Public, Property Owners, Media, etc.

Page 2 of 6

Date: 10/22/2024

Page 3 of 6 Date: 10/22/2024





Vegetation around MW-1



Absorbant sock that was removed from MW-1.



Vegetation cleared around MW-4



Trace amount of oil on the end of the oil water interface probe.



IDW drums onsite near MW-1



View of soil cover looking south standing on the northwest corner of the soil cover. Drainage ditch visible



View of soil cover looking southeast.



View from middle of soil cover looking east. Ponding occurring.



View from east side of soil cover looking south. With running water and ponding present

Site Inspector(s): Hannah Bedell



Tracks and ponding in soil cover along easter border looking north

Date: 10/22/2024

Videos of discreet operations have been provided to the DEC Project Manager to facilitate understanding of the ongoing work?

Yes \square No \square N/A X



(Oswego Castings), Site No. 738033

REMEDIAL ACTIVITIES AT PROPERTIES

Page **5** of **6**

Date: 10/22/2024

1.	Does anyone at this location have any symptoms of a respiratory infection (e.g., cough, sore throat, fever, or shortness of breath)?	Yes □	No ⊠
2.	Have anyone at this location been tested and confirmed to have COVID-19?	Yes □	No ⊠
3.	Were personal protective gloves, masks, and eye protection being used?	Yes □	No ⊠
4.	Does the Department and its contractors have your permission to enter the property at this time?	Yes ⊠	No □
5.	If Yes to 1 or 2, follow the latest NYSDOH COVID-19 guidance: https://coronavirus.health.ny.gov/home	Yes ⊠	No □
Comm	ents:		
N/A			

ON-SITE WASTE STORAGE

Drums, roll offs and piles are staged in secure areas?	Yes ⊠	No □	N/A□
Liners and berms have been installed if necessary to prevent cross contamination of clean areas?	Yes □	No □	N/A⊠
Containers are in good condition or properly overpacked?	Yes □	No □	N/A⊠
Waste materials are scheduled to be properly characterized and disposed of prior to demobilization?	Yes □	No □	N/A⊠
Complying with RCRA 90 day storage limitation for hazardous waste?	Yes □	No □	N/A⊠
Piles are securely covered when not in use?	Yes □	No □	N/A⊠
Containers are closed when not in use?	Yes □	No □	N/A⊠
Staging areas should be inspected periodically and any issues addressed immediately?	Yes □	No □	N/A⊠
Signage and labeling comply with RCRA requirements for all staging areas and containers?	Yes □	No □	N/A⊠
If any issues noted, has Contractor been notified?	Yes □	No □	N/A⊠
Comments:			

NUISANCE CHECKLIST

Were there any community complaints related to work on this date?	Yes □	No ⊠	N/A□
Were there any odors detected on this date?	Yes □	No ⊠	N/A□
Was noise outside specification and/or above background on this date?	Yes □	No ⊠	N/A□
Were vibration readings outside specification and/or above background on this date?	Yes □	No □	N/A⊠
Any visible dust observed beyond the work perimeter on this date?	Yes □	No □	N/A⊠
Any visible contrast (turbidity) beyond engineering controls observed on this date?	Yes □	No □	N/A⊠
Was turbidity checked at the outfall(s)?	AM □	РМ□	N/A⊠
Were any property owners NOT provided advance notice for work performed on this property on this date?	Yes □	No □	N/A⊠



(Oswego Castings), Site No. 738033

Was the temporary fabric structure closed at the end of the day?	Yes □	No □	N/A⊠
Has Contractor failed to protect all foundations and structures adjacent to and adjoining the site which are affected by the excavations or other operations connected with performance of the Work?	Yes □	No □	N/A⊠
If yes, has Contractor been notified?	Yes □	No □	N/A⊠
Comments: N/A			


Page 6 of 6

Date: 10/22/2024

RESILIENCE/GREEN REMEDIATION CHECKLIST

Is site power procured from renewable energy sources (e.g., solar, wind, geothermal, biomass and biogas)?	Yes □	No □	N/A⊠
Is the Contractor employing 2007 or newer or retrofitted (BART*) diesel on-road trucks and non-road equipment?	Yes □	No □	N/A⊠
Is vehicle idling adequately reduced per 6NYCRR Part 217-3?	Yes □	No □	N/A⊠
Have equipment operators been trained in the idling requirements of 6NYCRR Part 217-3?	Yes □	No □	N/A⊠
Is BART-equipped equipment properly maintained and working?	Yes □	No □	N/A⊠
Is work being sequenced to avoid double handling?	Yes □	No □	N/A⊠
Is there an onsite recycling program for CONTRACTOR-generated wastes and is it complied with?	Yes □	No □	N/A⊠
Are office trailer heating and cooling systems maintained at efficient set points, have programable thermostats been installed?	Yes □	No □	N/A⊠
Are products and materials used in performance of the work appropriately certified (e.g., LEED, Energy Star, Sustainable Forestry Initiative®, etc.)?	Yes □	No □	N/A⊠
Are resiliency features included in the design, or completed remedy properly installed and/or maintained (flood control, storm water controls, erosion measures, etc.)?	Yes □	No □	N/A⊠
Are green remediation elements included in the design, or completed remedy properly installed and/or maintained (e.g., porous pavement, geothermal, variable speed drives, native plantings, natural stream bank restoration, etc.)?	Yes □	No □	N/A⊠
Has Contractor been notified of any deficiencies?	Yes □	No □	N/A⊠
Are remote/call in job meetings being held in lieu of meeting in person where possible?	Yes □	No □	N/A⊠
Comments: N/A			

^{*} BART – Best Available Retrofit Technology



(Oswego Castings), Site No. 738033

ŃEW YORK Contract No. D009806 Department of **NYSDEC Environmental** Division of Environmental Remediation DEC PM - J. Stefansky Conservation Engineer PM - A. Etringer Site Location: Mitchell St., Oswego 13126 Engineer Insp. - H. Bedell **Weather Conditions General Description** NA PMCloudy AM **Temperature** 36 AM NA PMWind 12 mph SE AM NA PM

Page 1 of 6

Date: 12/16/2024

Health & Safety						
If any box below is checked "Yes", provide explanation under "Health & Safety Comments".						
Were there any changes to the Health & Safety Plan?	*Yes	No X	NA			
Were there any exceedances of the perimeter air monitoring reported on this date?	*Yes	No	NA X			
Were there any nuisance issues reported/observed on this date?	*Yes	No	NA X			

Health & Safety Comments

Discussed situational awareness of heavy machinery and large trucks entering and exiting the site for site inspection, as well as being aware of cold temperatures during the tailgate safety meeting.

Summary of Work PerformedArrived at site:0750Departed Site:0820

(0750) H. Bedell and C. Zook (EA) on-site for absorbent sock exchange and gauge DNAPL in MW-1.

(0755) Calibrated PID.

(0800) EA removed the absorbent sock out of the well. Trace amounts of product was observed in the absorbent sock.

(0803) Gauged MW-1

DTW in MW-1 was 3.05 ft BTOC, and DTB was 17.52 ft BTOC. No measurable product, trace product observed on water level indicator.

(0810) EA replaced the absorbent sock at the bottom of the well.

(0815) EA conducted a visual inspection of the soil cover. There is a small drainage ditch present running from the western boundary to the southern boundary of the soil cover. There was ponding on the soil cover area.

(0820) H. Bedell and C. Zook (EA) offsite.

Equipment/Material Tracking If any box below is checked "Yes", provide explanation under "Material Tracking Comments".

Were there any vehicles which did not display proper D.O.T numbers and placards?	*Yes	No	NA X
Were there any vehicles which were not tarped?	* Yes	No	NA X
Were there any vehicles which were not decontaminated prior to exiting the work site?	* Yes	No	NA X

Personnel and Equipment

Individual	Co	mpany	Trade		Total F	lours		
Hannah Bedell		EA	Engineer		Engineer		0.5	5
Clara Zook		EA	Intern		0,	5		
Equipment Description		Contractor/Vendor		Quantity	Use	ed		
Various Hand tools		EA		NA	Yes			
2020 Ford Explorer		EA		1	Yes			
Oil water interface probe		PINE 1		Yes				
Honeywell 3000+ miniRAE	PINE 1		Yes					
Tioney well 0000: Illilli tit					Daily			

Material Description	Imported/ Delivered to Site	Exported off Site	Waste Profile (If Applicable)	Source or Disposal Facility (If Applicable)	Daily Loads	Daily Weight (tons)*

*On-Site scale for off-site shipment, delivery ticket for material received

Equipment/Material Tracking Comments:

Visitors to Site



(Oswego Castings), Site No. 738033

Representing **Entered Exclusion/CRZ Zone** Name Yes No NA Yes No NA **Site Representatives** Representing Name EΑ Hannah Bedell **Project Schedule Comments** Next inspection is planned for February 2025. **Issues Pending** Interaction with Public, Property Owners, Media, etc.

Page **2** of **6**

Date: 12/16/2024

Page 3 of 6 Date: 12/16/2024

Site Photographs (Descriptions Below)



MW-1



Absorbant sock that was removed from MW-1.



Q2 2024 groundwater sampling purge water drum



Absorbent sock drum

(Oswego Castings), Site No. 738033



View of soil cover looking northeast



Page 4 of 6

Date: 12/16/2024

View of soil cover looking east standing on the southwest corner of the soil cover. Drainage ditch visible



View of western side of soil cover looking north



View of concrete cover, ponding visible



Ponding in soil cover along eastern border looking northeast

Site Inspector(s): Hannah Bedell

Date: 12/16/2024

Videos of discreet operations have been provided to the DEC Project Manager to facilitate understanding of the ongoing work? Yes \square No \square N/A X



(Oswego Castings), Site No. 738033

REMEDIAL ACTIVITIES AT PROPERTIES

Page **5** of **6**

Date: 12/16/2024

1.	Does anyone at this location have any symptoms of a respiratory infection (e.g., cough, sore throat, fever, or shortness of breath)?	Yes □	No ⊠
2.	Have anyone at this location been tested and confirmed to have COVID-19?	Yes □	No ⊠
3.	Were personal protective gloves, masks, and eye protection being used?	Yes □	No ⊠
4.	Does the Department and its contractors have your permission to enter the property at this time?	Yes ⊠	No □
5.	If Yes to 1 or 2, follow the latest NYSDOH COVID-19 guidance: https://coronavirus.health.ny.gov/home	Yes ⊠	No □
Comm	ents:		
N/A			

ON-SITE WASTE STORAGE

Drums, roll offs and piles are staged in secure areas?	Yes ⊠	No □	N/A□
Liners and berms have been installed if necessary to prevent cross contamination of clean areas?	Yes □	No □	N/A⊠
Containers are in good condition or properly overpacked?	Yes □	No □	N/A⊠
Waste materials are scheduled to be properly characterized and disposed of prior to demobilization?	Yes □	No □	N/A⊠
Complying with RCRA 90 day storage limitation for hazardous waste?	Yes □	No □	N/A⊠
Piles are securely covered when not in use?	Yes □	No □	N/A⊠
Containers are closed when not in use?	Yes □	No □	N/A⊠
Staging areas should be inspected periodically and any issues addressed immediately?	Yes □	No □	N/A⊠
Signage and labeling comply with RCRA requirements for all staging areas and containers?	Yes □	No □	N/A⊠
If any issues noted, has Contractor been notified?	Yes □	No □	N/A⊠
Comments:			

NUISANCE CHECKLIST

Were there any community complaints related to work on this date?	Yes □	No ⊠	N/A□
Were there any odors detected on this date?	Yes □	No ⊠	N/A□
Was noise outside specification and/or above background on this date?	Yes □	No ⊠	N/A□
Were vibration readings outside specification and/or above background on this date?	Yes □	No □	N/A⊠
Any visible dust observed beyond the work perimeter on this date?	Yes □	No □	N/A⊠
Any visible contrast (turbidity) beyond engineering controls observed on this date?	Yes □	No □	N/A⊠
Was turbidity checked at the outfall(s)?	AM □	РМ□	N/A⊠
Were any property owners NOT provided advance notice for work performed on this property on this date?	Yes □	No □	N/A⊠



(Oswego Castings), Site No. 738033

Was the temporary fabric structure closed at the end of the day?	Yes □	No □	N/A⊠
Has Contractor failed to protect all foundations and structures adjacent to and adjoining the site which are affected by the excavations or other operations connected with performance of the Work?	Yes □	No □	N/A⊠
If yes, has Contractor been notified?	Yes □	No □	N/A⊠
Comments: N/A			

Page 6 of 6

Date: 12/16/2024


RESILIENCE/GREEN REMEDIATION CHECKLIST

Is site power procured from renewable energy sources (e.g., solar, wind, geothermal, biomass and biogas)?	Yes □	No □	N/A⊠
Is the Contractor employing 2007 or newer or retrofitted (BART*) diesel on-road trucks and non-road equipment?	Yes □	No □	N/A⊠
Is vehicle idling adequately reduced per 6NYCRR Part 217-3?	Yes □	No □	N/A⊠
Have equipment operators been trained in the idling requirements of 6NYCRR Part 217-3?	Yes □	No □	N/A⊠
Is BART-equipped equipment properly maintained and working?	Yes □	No □	N/A⊠
Is work being sequenced to avoid double handling?	Yes □	No □	N/A⊠
Is there an onsite recycling program for CONTRACTOR-generated wastes and is it complied with?	Yes □	No □	N/A⊠
Are office trailer heating and cooling systems maintained at efficient set points, have programable thermostats been installed?	Yes □	No □	N/A⊠
Are products and materials used in performance of the work appropriately certified (e.g., LEED, Energy Star, Sustainable Forestry Initiative®, etc.)?	Yes □	No □	N/A⊠
Are resiliency features included in the design, or completed remedy properly installed and/or maintained (flood control, storm water controls, erosion measures, etc.)?	Yes □	No □	N/A⊠
Are green remediation elements included in the design, or completed remedy properly installed and/or maintained (e.g., porous pavement, geothermal, variable speed drives, native plantings, natural stream bank restoration, etc.)?	Yes □	No □	N/A⊠
Has Contractor been notified of any deficiencies?	Yes □	No □	N/A⊠
Are remote/call in job meetings being held in lieu of meeting in person where possible?	Yes □	No □	N/A⊠
Comments: N/A			

^{*} BART – Best Available Retrofit Technology

Appendix B

Field Notes



10 00	0.1	(22842	_		1/11/2024						11
USWea	o Costing	5 (13803) F Claudu	87 In F		ety (AM)						77.1
0915	H. Bedell	t C. Zoo	K (EA) o.	nsite	1				,		
	Calibrat										1
0930	Remo	e sock					<u> </u>				per many control of the control of t
0940	Gauge DTW	2.39									
	DT DN	IAPL: K	o DN AP	- present	+						
	BTB	:17.76				·					1
0950	Replace H Bedell &	Sock in	well				<u></u>				:
10 00	H Bedell &	C.Zook	(EA) of	site_					 		2011
					·		,				
									-		
						· ·			-		
******			_								
		Tour	Redly	Ø .							11 E C C C C C C C C C C C C C C C C C C
. <u> </u>		01 - 11 - 2	1								
		/				į					1
				1							1 100
-				1		<u></u>					
:			1			<u> </u>					
		*** *						1			
								-		_	
· ·					 					Rite	in the Rain

ego Costings (738033) 1/11/2024	Oswego Costi	ngs (73803)	6		2/15/2024 ¹¹
Wx: 34°F, Cloudy, 8 mph E 82% humidly (AM)	1200	WX: 28°F P	orthy claudy 7,	uph 3, 69	x husidely (Ar
H. Bedell & C. Zook (EA) onsite			1.6.1key (FA) a	pusite	
Calibrate PID	1005	Calibrate P			
Remove sock from well	1015 R	emore Sock	e from well a	nd gave	ge well
Gauge PNAPL and water in well	-				
DTW. 2.39		4	?L' No Duape	Present	
DT DNAPL: NO DNAPL present	1020	DTB: 1		·	
DTB:17.76	1020 Re	eplaced soc	k in well		01
Replace Sock in well			sual inspect		
H. Bedell & C. Zook (EA) offsite	1030 H	nRedell & M	1.6.1 key (EA)	dts,te	
				/	
Top Redel			-0	D	
The state of the s		12	15 2021		
01 · 11 · 2024		02.	15.2024		
					1
					Jan.
				Reti	in the Rain
		-		1	

FIELD CALIBRATION FORM

Site Name: Oswego Castings (738033)


INSTRUMENT: RKI	INSTRUMENT ID No:
OPERATOR: H. Bedell	WEATHER: 32°F, cloudy
SPAN GAS TYPE: Isolatylene	DATE: 3/18/24
CALIBRATION NOTES:	
Zero Cal: O.O pom	
Span Cal: 100 ppm	
COMMENTS:	
	And a service of the
SIGNATURE: Lu Bedll I	DATE: 3/8/24


12 Oswer Castings (732033)	3/18/24		13
WX: 32°F, cloudy, 18 mph W			
2930 H. Bedell & K. Katzer (EA) onsite			
935 Calibrate PID			
5 940 Remove sock from well, take	e water		
benel reading			
PID: 0.8 cpm			
DTW: 3.0 ft			
DTB: 17.53A			
DTNAPL: 17.53 ft (Trace an	wonts)		
1950 Replace Sock in well.			
1955 Conduct visual inspection of so	oft cap		
000 H. Bedell & K. Katzer (EA) offsite			
2			
	,		
Tarkella			
3.18.24			
	4		
			-
			Rite in the Rain.

] ,			
vego Castings (732033) 3/18/24	Oswea	o Castings (73803	3)	\$	19/24 13
WX: 32°F, cloudy, 18 mph W		Wx: 52%, Cloud			
7 H. Bedell & K. Katzer (EA) on site	0915	H. Bedell, C. Deraic	L, A. Faus	(EA) on	ite
i Calibrate PID	0920				
Remove sock from well, take water	0925		n well	take wa	fer level
level reading		reading			
PID: 0.8 pm		DTW3 2.91 ft	PI	D: 0.0	pn
DTW: 3.0 At		DTB: 17.61 ft			
DTB: 17.53 A		DTNAPL: 17.6	A (Trace	amounts	
DTNAPL: 17.53 ft (Trace amounts)	<u>०१५७</u>	Acplace sock in	rell		
Replace Sock in well	oqus	Began locating u	ells onst		
Conduct visual inspection of soft cap	1045	EA offsite.	-		
H. Bedell & K. Katzer (EA) affsite	<u></u>				
	1		× 144.4		
		•			
		· · · · · · · · · · · · · · · · · · ·			
Jan Belle					
	· · · · · ·				
3.18.24					
	<u> </u>			and such that I such I for the successful of the	
			LA LUCA VIDE		
	<u>}</u>			Rite	In the Rain.
	•	· I	1	1	

	14 OSWIE (1	o Casti	no 17	32033)		
		atheres				er 11
ĺ			_	ey 4.6	edem A.	Faux
9	4	A) onsite	1.0		, ,	- Para-to-
-				asery t	ail sate	meeting.
	-	of gai	1	1 _		
		alibra	1			
	Ab.	tart P	*			
		tact p				
		tort p				
_	•			-MW-I	-202403	o6.
		í		WW-7-	i -	
•	•					DUWMME
		place so	•	1		
i		art pur	1			
			"	W-2R.		
				-mw-3		Section 1990.
					i	obwith FD
:	11015	fart pur	ge MN	-5.		
		art pur				
	1122 50	more 7	38033.	MW-5-	0024050	6.
	1147 50	imple -	138033	MW-6.	202405	Ob
	1200 in	speet ca	es and	take fie	ablank	4
:	1215 E	A offsi	te.			
i		The state of the s	19-	7	A STATE OF THE PARTY OF THE PAR	d and the second second
			Cer			
			5.6.	2027		The state of the s
As.	خث			The second second		

18 Osus	ego Castings (7380	023/		Co W1201			·	
	WX 7HOF Sun	1 72 % L	unid 14	8march S	-		-	
0930	HiBedell & C. Zoo	K (EA)	onsite	7				
0935	Calibrate PID							
	Span cal: 1	00.1	\					
	Zer (al: 0.0							
0940	Gauge MW-1	 		- V-14 1000-000-000-000-000-000-000-000-000-00			<u>-</u> .	
	RD=0.2p	ern						
	DTW=5.97							
	DT DNAPL= /7	1.43 (tre	ce amou	rts)				* -
	DTB=17.43						No. 2	
<u> </u>	Replace Sock in a	rell						
1005	Conduct Visua	linspeed	gonof	saft	<u> </u>			
	EA Offsite				1			
1030	14045/PC		Ja Strans	and the same of th				
			And the second second					
				1.2477777				
	Mod	1///						
	ARCIO	74						
	6.17.20	7						
			- The state of the	*************************************	-			
		- MANIAR TEXT	***************************************		, ,			
				The state of the s	:			
		· ·		- 1	WINDS AND STATE OF THE STATE OF	#		
				1		-		
			· 	·	1			






rego Castings (738033) 10/22/24	4	***************************************	23
Wx: Sunny, 57°F, Carph SE			
H. Bedull & M. wilkey (EA) onsite			A LINE OF THE STATE OF THE STAT
Calibrate PED			
Zero Cal: O.O ppm			
Span Cal: 100.0 ppm			:
Remove absorbert sock from well (MW-1)			
Gange MW-1			
BID: O.O pan			
οτω: 4.53			
DTB: 17.45			
Trace amounts of DNAPL on	 		
cil water probe	·		4954 · · · ·
Replace well absorbent sock in well			
) Inspect soft cap			
EA desite			
	क		1
	5		
1/0/1-1/			
A. Bedell			
10 22.24			
	1		
			Rite in the Rain.
	 •	1	in the second of


•

·····		: :	<u> </u>		,		<u> </u>	,			
300	in Casti	ys (738	033)		10/22/24	Oswego	Costines	(13803))	12	16/2423
		nny, 5					Wx: 36	PF Clou	edy, 12 n	oph SE	
)	H. Bede	II È M. C	silken (1	A) ons	le min	0750	H. Budel	1 e C.Z	ook (EA) onsite	J
		PID	7			0795	Calibrat	•	1		·
		ero Cal:	0.0 00						OPPM		
		oon Cal:			,	6 *			100.1		
					ell (Mw-1)	0800			ent sock		W-1
		MW-1				0803	Gauge				
	1 13	10: 0.C	-				PI	5:0.0p	om		
		rw: 4.5							5 ft loa	5	
	1	TB: 17.	1				į.		2 Pt ba		
		Face an		CD NAP	1-01		Ta	10 amount	s of RV	APL on	0.1
		oil wate				•		oter Proh		doca	
					well	0810			nt sock	inue	1(
\ ~		et sof		2000		0815	Inspeal	- Soft o	a 0		
ر ا	EA OCE		Cap			0820	EA off	site	T		
	LP OR	5,70				:					
							. 4				
								,	. 1		
		1/0	1 - 11				7	1DOG	W.C.		
	1	1. Bee	Sell		-	i		1000			
	, ,	0.22.	24	**		: 	lZ	16.2	9		
	<u> </u>	V.C.					/	•			
		7				#					
	 / - - 										
										Riz	to in the Rain.
	<u></u>					•	1		1		1 :-



Appendix C

Comprehensive Photographic Log





Description:	Trace produce observed on adsorbent sock.	Photograph 1
Direction:	Looking North	Date: 11 January 2024



Description:	Site conditions are MW-1 included ponding water	Photograph 2
	at surface.	
Direction:	Looking east	Date: 11 January 2024



Description:	Ponded water/ice on landfill soil cap	Photograph 3	
Direction:	Looking northeast	Date: 15 February 2024	



Description:	Trace produce observed on adsorbent sock.	Photograph 4
Direction:	Looking north	Date: 15 February 2024



Description:	Collection of PID measurement at MW-1.	Photograph 5
Direction:	Looking north	Date: 18 March 2024



Description: Trace product on oil water interface probe after inspection of MW-1		Photograph 6
Direction:	Looking east	Date: 18 March 2024



Description:	Monitoring well MW-5 is in need of repair as the inner casing extends up and over outer casing.	Photograph 7
Direction:	Looking north	Date: 19 April 2024



Description:	Ponded water on landfill soil cap	Photograph 8
Direction:	Looking north	Date: 19 April 2024



Description:	View of south extent of landfill soil cap and	Photograph 9
	concrete cap	
Direction:	Looking south	Date: 6 May 2024



Description:	Low-flow groundwater purge setup on MW-6.	Photograph 10	
Direction:	Looking east	Date: 6 May 2024	



Description:	Phragmites growth at MW-1.	Photograph 11
Direction:	Looking north	Date: 17 June 2024



Description:	Trace product observed on absorbent sock that was	Photograph 12
	removed from MW1.	
Direction:	Looking north	Date: 17 June 2024



Description:	Trace product on oil water interface probe	Photograph 13
Direction:	Looking north	Date: 15 July 2024



Description:	View of ponding water on the landfill soil cap	Photograph 14
Direction:	Looking southwest	Date: 15 July 2024



Description:	Trace product on absorbent sock removed from MW-1.	Photograph 15
Direction:	Looking west	Date: 26 August 2024



Description:	View of ponding water on the landfill soil cap	Photograph 16
Direction:	Looking southwest	Date: 26 August 2024



Description:	Trace product on absorbent sock removed from MW-1.	Photograph 17
Direction:	Looking north	Date: 22 October 2024



Description:	Trace product observed on the oil water interface	Photograph 18
	probe	
Direction:	Looking southeast	Date: 22 October 2024



Description:	Trace product on absorbent sock removed from MW-1.	Photograph 19
Direction:	Looking southeast	Date: 16 December 2024



Description:	View of landfill soil cap covered in snow. Compression and ponding water visible in center.	Photograph 20
Direction:	Looking northeast	Date: 16 December 2024