


# New York State Department of Environmental Conservation

Division of Environmental Remediation - Central Office

Remedial Bureau C

Section D



Erin Crotty  
Commissioner

## DAILY INSPECTION REPORT

<b>Site Code #:</b> 7-55-08	<b>Date:</b> November 7, 2003	<b>Report #:</b> NYSEG110703
-----------------------------	-------------------------------	------------------------------

**Site Name:** NYSEG Ithaca Court St.

**Location:** Ithaca, Chemung County

**NYSEG Proj. Mgr.:** Bert Finch

**DEC Proj. Mgr.:** Bill Ottaway

**Consultant Proj. Mgr.:**

**Proj. Contr.:** Severson Environmental

**Site Phone & Fax:**

	AM	PM
<b>Weather</b>	P. Sunny	P. Sunny
<b>Temperature</b>	35 degrees	47 degrees
<b>Wind Direction</b>	NW	NW

### Description of work performed by contr. this report period:

- Begin removal of clay tile pipe at 42 feet east of storm sewer grate (credit union entrance).
- Staining begins at 1.5 feet bgs.; pipe found at 2.5 feet bgs. Water line found at 4.5 feet bgs, directly below clay pipe. Clay pipe is 8 inches in diameter, has a 1/4 inch braided wire running along inside. No material within pipe; has staining, sheen on it.
- Soil around water line is heavily impacted, sheen, coal tar odor, NAPL present.
- Uncovered sanitary sewer main at 5 feet bgs, about 2 feet south of clay pipe. Slight impacts noted around pipe.
- Excavated to clean material on north side of water line; total depth of 8 feet bgs. Small area of impact (2 inch diameter) at this depth. Removal to 8 feet occurred at last 17 feet of excavation (dug west to east).
- Removed a total of 25 feet of clay tile pipe.
- NYSEG took samples SW-5 (on top of sewer line, 5 feet bgs), bottom sample BM-4 (8 feet bgs), and from material around water line (4.5 feet bgs).

### Description of inspections performed by engr. this report period:

-

**Discussions/comments regarding visitors, contractor and/or engineer:**

- 

**Change Orders:**

- 

**Sampling and Analyses:**

- 

Major Issues	Description & Reason

**Health & Safety:**

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Visitors	Representing	Entered Exclusion Zone

**Contractor's Information:**

Prime contractor worked from 7:00A to 4:30P.

Subcontractor	Activity	Hours Worked

Equipment	P	1	2	3	Personnel	P	1	2	3
Daewoo 135 Backhoe	1				Site Supervisor	1			
Air Handling Equipment	1				Operator	2			
					Laborer	3			

**Site Representative:** R. Scott Deyette

**Date:** November 7, 2003

**Representative's signature:**

**Reviewed By:**

**Date:**