### **New York State Department of Environmental Conservation**

Division of Environmental Remediation - Central Office Remedial Bureau C Section D



#### DAILY INSPECTION REPORT

<b>Site Code #:</b> 7-55-08	<b>Date:</b> July 8, 2004	Report #: NYSEG070804

Site Name: NYSEG Ithaca Court St. Location: Ithaca, Chemung County NYSEG Proj. Mgr.: Bert Finch DEC Proj. Mgr.: Bill Ottaway

Consultant Proj. Mgr.:

**Proj. Contr.:** Sevenson Environmental

Site Phone & Fax:

	AM	PM
Weather	Overcast	P. Sunny
Temperature	65 degrees	78 degrees
Wind Direction		

### Description of work performed by contr. this report period:

- Continued excavation of Duct #1 from midpoint of Park Place to east corner of Park and Court St. Impacts start at about 3.5 feet bgs. Under clay storm sewer heavier tar impacts begin. Top of duct at 3.5 feet bgs. Found water main for Park St. At 4.5 feet bgs, at middle of road. Heavy tar, impacted soil noted around pipe. NYSEG dug to Removed 55 feet of clay tile pipe. Removed a total of 8 feet of duct.
- Sent 5 trucks to ESMI

#### Description of inspections performed by engr. this report period:

• Dave Budosh (URS) onsite.

# <u>Discussions/comments regarding visitors, contractor and/or engineer:</u>

•

#### **Sampling and Analyses:**

.

Major Issues	Description & Reason
Excavating wet soil	Due to heavy rains on 7/7, a lot of groundwater present. Sevenson has trouble controlling water in excavation, and dealing with collapsing walls of excavation. Excavation could have gone deeper if conditions were better controlled.

# **Health & Safety:**

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Visitors	Representing	Entered Exclusion Zone

# **Contractor's Information:**

Prime contractor worked from 7:00A to 3:30P.

Site Representative: R. Scott Deyette Date: July 8, 2004

Representative's signature:

REVISED 5/99 @BLANK.wpd