

October 19, 2021

Mr. Justin Starr Project Manager New York State Department of Environmental Conservation 625 Broadway Albany, New York 12233-7014

Subject: 2021 Annual Site Inspection Report

RG&E Pavilion Former MGP Site

6903 Ellicott Street Road

Town of Pavilion, Genesee County, New York 14525

NYSDEC Site No. 819024

Dear Mr. Starr:

On behalf of the Rochester Gas & Electric Corporation (RG&E), NEU-VELLE LLC (NEU-VELLE) has completed the second post-remediation annual Site Inspection of the RG&E Pavilion Former Manufactured Gas Plant (MGP) site [New York State Department of Environmental Conservation (NYSDEC) Site No. 819024], located at 6903 Ellicott Street Road in the Town of Pavilion, Genesee County, New York (referred to herein as the "Site"). A Site Management Plan (SMP) for the Site has been completed and approved by NYSDEC and is currently pending final signatures of remedial parties.

NEU-VELLE performed a visual inspection of the Site, including an evaluation of the surface cover system for evidence of disturbance, erosion or removal of cover materials, settlement, or other conditions that could potentially result in exposure to subsurface MGP residuals. Photographs were collected during this September 20, 2021 Site Inspection. The existing cover materials at the Site were observed to be in good condition, and there were no noticeable signs of significant deterioration of the surface cover. Additionally, the existing groundwater monitoring well network, consisting five (5) wells finished with "stick-up" protective steel casings, was found to be in good condition. Documentation of NEU-VELLE's inspection is provided as **Attachment A** of this letter report. Please feel free to contact me at (585) 478-3167 with any questions or concerns.

Sincerely,

NEU-VELLE, LLC

Attachment A – Site Inspection Form and Photographs

cc: Mr. Jeremy Wolf, RG&E

Attachment A





SITE-WIDE INSPECTION FORM

RG&E Pavilion Former MGP Site

Date: 9/20/21		Time:	13:00 Al	M	<u> </u>
Weather Conditions:	Partly Sunn	y			
Temperature:	78 F	Precipitation:		None	
Personnel and Company	Kyle R. Mil	<u>ler, Neu-Velle, LLC</u>	C		
		RAM			
Signatures:					
Has ownership of the property changed since the last inspection?					Yes No
Are Institutional Controls/Engineering Controls (IC/ECs) in place and effective?					Yes/No
If not, explain why.					
Are there any changes to the Site use that would affect the SMP or IC/ECs?					Yes No
Is the Site used for vegetable gardens or agricultural purposes?					Yes /No



Is native soil, the geotextile fabric demarcation layer, or other signs of MGP impact (sheens, st visible?	aining, tar-like material)
	Yes /No
Is the site cover intact (i.e., no visible sign of excavations, erosion, damage)?	Yes / No
Is groundwater used as a potable water source?	Yes /(No)
is groundwater used as a potable water source:	Tes/(NO)
Are there any site changes (either surface or subsurface) since the last inspection event?	Yes No
Photographs taken?	(Yes / No
See Photolog	100
Are there any fencing changes since the last inspection event?	Yes /No



Training Building and the Northeastern Portion of the Site - Viewing Northeast



Gas Regulator Building and the Central Portion of the Site - Viewing South



Northwestern Portion of the Site - Viewing Northwest



Western End of Office Building and Southwestern Portion of the Site - Viewing South



Locker Room Building, Eastern End of Office Building, and Plastic Drums Containing Purged Groundwater - Viewing Southeast



Northeastern Side of the Site - Viewing Northeast



Typical "Stick Up" Groundwater Monitoring Well at the Site



Northwestern Portion of the Site - Viewing North



Northern Portion of the Site - Viewing North



Southeastern Portion of the Site – Viewing Northeast