

22 May 2023

TECHNICAL MEMORANDUM

TO: Jasmine Stefansky, Assistant Geologist

Remedial Bureau E, Division of Environmental Remediation

Remedial Section D

FROM: Joshua Oliver, EA Project Manager

SUBJECT: Annual Site Inspection

Former Rochester Metal-#828100, Rochester, New York

Contract/Work Assignment No. D009806-34

EA Project No. 16025.34

EA Engineering, P.C. and its affiliate EA Science and Technology (EA) were tasked by the New York State Department of Environmental Conservation (NYSDEC) under Work Assignment (WA) Number (No.) D009608-34 to complete site management tasks at remedial sites across New York State. This technical memorandum summarizes the annual site inspection completed at the Former Rochester Metal Site located at 100 Lake Avenue in Rochester, Monroe County, New York.

The annual site inspection was completed as part of the initial site reconnaissance visit on 31 March 2023. EA was accompanied by NYSDEC. The site visit consisted of a walk-through observation of property boundaries and adjoining properties. Not all portions of the site were accessible because of fencing and a locked gate, which also made the interior of the building inaccessible. Not all site monitoring wells were able to be located, but those that were accessible appeared in good condition. The on-site asphalt cap was in good condition and appeared to be recently sealed with no cracks. Weather conditions at the time of this site visit were approximately 40 degrees Fahrenheit and overcast.


Additional information regarding the site visit on 31 March 2023 can be found in the Daily Field Report, attached in Attachment A. The completed annual inspection report form is attached in Attachment B. A photographic log from the site inspection is attached in Attachment C. At this time, there are no upcoming sampling events. Next steps include revising the Site Management Plan to incorporate a 5-year Periodic Review Report reporting schedule.

Attachments

A Daily Field Report


B Inspection Report Form

C Photograph Log



Attachment A

Daily Field Report



(Former Rochester Metal), Site No. 828100

ŃEW YORK Contract No. D009806 Department of **NYSDEC Environmental** Division of Environmental Remediation DEC PM - J.Stefansky Conservation Engineer PM - J.Oliver Site Location: 100 Lake Avenue, Rochester 14608 Engineer Insp. - N.Peck **Weather Conditions General Description** PM Rain, Overcast AM **Temperature** 40F AM PMAM Wind N/A PM**Health & Safety** If any box below is checked "Yes", provide explanation under "Health & Safety Comments". Were there any changes to the Health & Safety Plan? *Yes No X NA *Yes NA X Were there any exceedances of the perimeter air monitoring reported on this date? No Were there any nuisance issues reported/observed on this date? *Yes No X NA **Health & Safety Comments** Onsite property covered in pavement (hard cap). 11AM Departed Site: 1130AM **Summary of Work Performed** Arrived at site: Joshua Oliver, Nicole Peck, and Noah Robinson, (EA), onsite at (11AM) met up with Jasmine Stefansky, Charles Gregory, and Payson Long (NYSDEC) onsite at Site 828100. Onsite property covered in pavement. EA and NYSDEC did not find all applicable monitoring wells for the Site but there are no upcoming sampling events. Discussed possibly performing well abandonment if warranted by NYSDEC and emerging contaminant results. Onsite pavement (hard cap) upon inspection was in good condition, newly sealed with no cracks. NYSDEC and EA left Site around 1130AM **Equipment/Material Tracking** If any box below is checked "Yes", provide explanation under "Material Tracking Comments". Were there any vehicles which did not display proper D.O.T numbers and placards? *Yes No NA X Were there any vehicles which were not tarped? * Yes No NA X Were there any vehicles which were not decontaminated prior to exiting the work site? Yes Nο NA X Personnel and Equipment Individual **Total Hours** Company Trade Joshua Oliver 0.5 EΑ Project Manager Noah Robinson EΑ Scientist 0.5 Nicole Peck EΑ Engineer 0.5 Jasmine Stefansky **NYSDEC** Project Manager 0.5 Payson Long NYSDEC Project Manager 0.5 Charles Gregory NYSDEC Project Manager 0.5 **Equipment Description** Contractor/Vendor Quantity Used Imported/ Daily **Waste Profile** Source or Disposal Exported Daily **Material Description** Delivered Weight off Site Facility (If Applicable) Loads (If Applicable) to Site (tons)* *On-Site scale for off-site shipment, delivery ticket for material received **Equipment/Material Tracking Comments: Visitors to Site** Name **Entered Exclusion/CRZ Zone** Representing None Yes No

Page 1 of 7

Date: 03/31/2023



Yes

No

(Former Rochester Metal), Site No. 828100

Site Representatives	
Name	Representing
No property owners onsite	
Project Schedule Comments	
None.	
Issues Pending	
None.	
Interaction with Public, Property Owners, Media, e	tc.
None.	

Page 2 of 7 Date: 03/31/2023

Include (insert) figures with markups showing location of work and job progress

Site Photographs (Descriptions Below)



Photo 1: MW-02 located off-site to the northwest in the adjacent parking lot



Page 3 of 7

Date: 03/31/2023

Photo 2: Adjacent parking lot to the northwest of the site



Photo 3: Adjacent parking lot to the northwest of the site



Photo 4: Adjacent parking lot to the northwest of the site



Photo 5: Inaccessible portion of the site containing MW-04, which could not be found



Photo 6: MW-01 located off-site to the northwest in the adjacent parking lot

(Former Rochester Metal), Site No. 828100




Photo 7: MW-03 located on site



Page **4** of **7**

Date: 03/31/2023

Photo 8: Site asphalt cover looks to be in good condition and surrounded by black metal fence



Photo 9: Inaccessible small grassy area located to the southeast of the east of the site

WELL MONITORING TABLE: N/A

	T	I	
Well ID	DTW	DTB	Notes

Site Inspector(s): Josh Oliver, Nicole Peck, and Noah Robinson Date: 3/31/23

DAILY INSPECTION REPORT (Former Rochester Metal), Site No. 828100

Videos of discreet operations have been provided to the DEC Project Manager to facilitate understanding of the ongoing work? Yes \square No \square N/A X

Page **5** of **7**

Date: 03/31/2023

(Former Rochester Metal), Site No. 828100

REMEDIAL ACTIVITIES AT PROPERTIES

Page **6** of **7**

Date: 03/31/2023

1.	. Does anyone at this location have any symptoms of a respiratory infection (e.g., cough, sore throat, fever, or shortness of breath)?		No ⊠
2.	Have anyone at this location been tested and confirmed to have COVID-19?	Yes □	No ⊠
3.	Were personal protective gloves, masks, and eye protection being used?	Yes □	No ⊠
4.	Does the Department and its contractors have your permission to enter the property at this time?	Yes □	No □
5.	If Yes to 1 or 2, follow the latest NYSDOH COVID-19 guidance: https://coronavirus.health.ny.gov/home	Yes □	No 🗆
Comm N/A	ents:		

ON-SITE WASTE STORAGE

Drums, roll offs and piles are staged in secure areas?	Yes □	No □	N/A⊠
Liners and berms have been installed if necessary to prevent cross contamination of clean areas?		No □	N/A⊠
Containers are in good condition or properly overpacked?	Yes □	No □	N/A⊠
Waste materials are scheduled to be properly characterized and disposed of prior to demobilization?	Yes □	No □	N/A⊠
Complying with RCRA 90 day storage limitation for hazardous waste?	Yes □	No □	N/A⊠
Piles are securely covered when not in use?	Yes □	No □	N/A⊠
Containers are closed when not in use?	Yes □	No □	N/A⊠
Staging areas should be inspected periodically and any issues addressed immediately?	Yes □	No □	N/A⊠
Signage and labeling comply with RCRA requirements for all staging areas and containers?	Yes □	No □	N/A⊠
If any issues noted, has Contractor been notified?	Yes □	No □	N/A⊠
Comments: NA			

NUISANCE CHECKLIST

Were there any community complaints related to work on this date?	Yes □	No ⊠	N/A□
Were there any odors detected on this date?	Yes □	No ⊠	N/A□
Was noise outside specification and/or above background on this date?	Yes □	No ⊠	N/A□
Were vibration readings outside specification and/or above background on this date?	Yes □	No □	N/A⊠
Any visible dust observed beyond the work perimeter on this date?	Yes □	No □	N/A⊠
Any visible contrast (turbidity) beyond engineering controls observed on this date?	Yes □	No □	N/A⊠
Was turbidity checked at the outfall(s)?	AM □	РМ□	N/A⊠
Were any property owners NOT provided advance notice for work performed on this property on this date?	Yes □	No □	N/A⊠



(Former Rochester Metal), Site No. 828100


Was the temporary fabric structure closed at the end of the day?	Yes □	No □	N/A⊠
Has Contractor failed to protect all foundations and structures adjacent to and adjoining the site which are affected by the excavations or other operations connected with performance of the Work?	Yes □	No □	N/A⊠
If yes, has Contractor been notified?	Yes □	No □	N/A⊠
Comments: N/A			

Page **7** of **7 Date: 03/31/2023**


RESILIENCE/GREEN REMEDIATION CHECKLIST

Is site power procured from renewable energy sources (e.g., solar, wind, geothermal, biomass and biogas)?	Yes □	No □	N/A⊠
Is the Contractor employing 2007 or newer or retrofitted (BART*) diesel on-road trucks and non-road equipment?	Yes □	No □	N/A⊠
Is vehicle idling adequately reduced per 6NYCRR Part 217-3?	Yes □	No □	N/A⊠
Have equipment operators been trained in the idling requirements of 6NYCRR Part 217-3?	Yes □	No □	N/A⊠
Is BART-equipped equipment properly maintained and working?	Yes □	No □	N/A⊠
Is work being sequenced to avoid double handling?	Yes □	No □	N/A⊠
Is there an onsite recycling program for CONTRACTOR-generated wastes and is it complied with?	Yes □	No □	N/A⊠
Are office trailer heating and cooling systems maintained at efficient set points, have programable thermostats been installed?	Yes □	No □	N/A⊠
Are products and materials used in performance of the work appropriately certified (e.g., LEED, Energy Star, Sustainable Forestry Initiative®, etc.)?	Yes □	No □	N/A⊠
Are resiliency features included in the design, or completed remedy properly installed and/or maintained (flood control, storm water controls, erosion measures, etc.)?	Yes □	No □	N/A⊠
Are green remediation elements included in the design, or completed remedy properly installed and/or maintained (e.g., porous pavement, geothermal, variable speed drives, native plantings, natural stream bank restoration, etc.)?	Yes □	No □	N/A⊠
Has Contractor been notified of any deficiencies?	Yes □	No □	N/A⊠
Are remote/call in job meetings being held in lieu of meeting in person where possible?	Yes □	No □	N/A⊠
Comments: N/A			

^{*} BART – Best Available Retrofit Technology



Attachment B Inspection Report Form




Inspection Report Form Former Rochester Metal 100 Lake Ave, Rochester, New York

Reason for Inspection: Annual Inspection

Date/Time of Inspection: March 31, 2023 11:00 AM


Inspector Name/Company: N. Peck, N. Robinson, J. Oliver (EA Engineering)

	Coi	ndition	Action Required						
INSPECTION OF:	Adequate/ Stable	Damaged/ Deteriorating	Yes	No	Comments/Location				
1. Facility Access Control									
1. Facility security	X			X					
2. Final Cover System									
A. Vegetative Cover Prohibited (present?)	X			X					
B. Pavement Cover/Side Walk	X			X					
1. Cracks/Holes	X			X					
C. Settlement	X			X					
D. Erosion	X			X					
E. Drainage Controls	X			X					
F. Presence of Excavation or Surface									
Penetration (interior & exterior)	X			X	Did not access interior				
1. Interior					Did not access interior				
3. SVE/SSD System					Did not access SVE/SSD System				
A. Fans									
1. Running?					Did not access SVE/SSD System				
Fan 1 Vacuum Reading "wc									
Fan 2 Vacuum Reading "wc									
2. Secured?					Did not access SVE/SSD System				
B. Piping									
1.Integrity					Did not access SVE/SSD System				
2. Building Penetration					Did not access SVE/SSD System				
3. GES & NYSDEC signage					Did not access SVE/SSD System				
C. Presence of new air intake near									
SVE/SSDS discharge points					Did not access SVE/SSD System				



Attachment C

Photograph Log



Site Photographs (Descriptions Below)



Photo 1: MW-02 located off-site to the northwest in the adjacent parking lot




Photo 2: Adjacent parking lot to the northwest of the site



Photo 3: Adjacent parking lot to the northwest of the site



Photo 4: Adjacent parking lot to the northwest of the site



Photo 5: Inaccessible portion of the site containing MW-04, which could not be found



Photo 6: MW-01 located off-site to the northwest in the adjacent parking lot



Photo 7: MW-03 located on site



Photo 8: Site asphalt cover looks to be in good condition and surrounded by black metal fence



Photo 9: Inaccessible small grassy area located to the southeast of the east of the site