

# NEW YORK DEPARTMENT OF ENVIRONMENTAL CONSERVATION DIVISION MATERIALS MANAGEMENT

## 6 NYCRR Part 360

## SOLID WASTE MANAGEMENT FACILITY INSPECTION REPORT

**Continuation Sheet** 

FACILITY NAME:		LOCATION:		FACILITY ID#:	DATE:	IME:	
Air Force Plant #51 Site			e Greece (T), N	Monroe (C)	N/A	10-30-18	09:00
INSPECTOR'S NAME:			CODE:	PERSONS I	NTERVIEWED & TITLES		
Mark Amann			S	N/A	UM TUMGAG ASAD	SHORINGS GEOGRAPHICAL	/ Kokata
REGION WEATHER CONDITIONS:			IS:	DEC PERMIT NUMBER			
8	8 Sunny, 37 °F, WSW wind up to 7 mph			d up to 7 mph	N/A	STIS NULLARIMITATO	
SHEET			CONTINUATION	SHEET	PART(S) 360-		
1	OF	6	⊠ YES □ NO	le Banotona Set	Attached –	Violations of Part (160 are Supple	

Violations of Part 360 are Subject to Applicable Civil, Administrative, and Criminal Sanctions Set Forth in ECL Article 71 and as Appropriate, the Clean Water and Air Acts.

Additional Violations May be noted on Sheet one of this inspection report.

Provide site sketches, clarification, supplemental information, locations of photographs or samples and/or locations of violations (uncorrected violations must be described in detail and located on a sketch.)

I conducted an inspection of the above-mentioned site with Scott Williams from the Division of Environmental Remediation. Pile dimensions (length x width x average height) were obtained with a steel tape measure.

Cathode ray tube (CRT) devices from old TV sets were observed at various locations around the site. Generally, the CRTs were on the ground facing screen-side down and the deflection yokes had been removed. I counted 16 CRTs total. Due to overgrown vegetation and the waste piles, it is possible that more CRTs were present but hidden from view. Most of the CRTs were at the north end of the site. 8 CRTs were located north of Building 2, 1 CRT north of Building 9, 5 CRTs between Buildings 9 and 11, 1 CRT along the fence southeast of former Building 1 South, and 1 CRT along the west perimeter road.

<u>Waste tires</u> were located within Building 9. I counted 89 tires total. The tire pile within the north side of the building had dimensions of approx. 12 ft x 9 ft x 2.5 ft. The tire pile within the south side of the building was intermixed with orange plastic (similar to snow fencing) and measured approx. 13 ft x 11 ft x 2.5 ft. There were 5 tires dumped on the south end of the site just south of former Building 1 South and 1 tire along the west perimeter road.

Piles of construction and demolition (C&D) debris were observed primarily on the south end of the site in the area just south of former Building 1 South. The C&D debris consisted of, but was not limited to dimensional lumber, plywood, fencing and posts, roofing debris, windows, paint cans, landscape timbers, and vinyl fencing and lattice. Other solid waste included tree debris, wooden pallets, furniture, carpet, a mattress, a VCR, and piles of broken up asphalt pavement and concrete. Due to the large number of piles and time constraints, I did not attempt to quantify all of the waste present. However, I measured the dimensions of three C&D debris piles that were easily accessible. Pile 1: 15 ft x 9 ft x 2 ft, Pile 2: 19 ft x 15 ft x 2 ft, and Pile 3: 11 ft x 10 ft x 1 ft. Two small piles of asphalt shingles approx. 2 cubic yards in size each were observed along the west perimeter road. On the north end of the site, a pile of asphalt shingles was located in Building 9. Pile dimensions were approx. 13 ft x 9 ft x 2.5 ft. One pile of C&D debris (windows) was observed north of Building 2 and measured approx. 15 ft x 5 ft x 1.5 ft.

The site entrance gate appeared to be in disrepair. Judging from the overgrown vegetation that had woven itself into the wire mesh, the gate hadn't been used in some time.

Based upon my observations, the site was being used for the unauthorized disposal of solid waste. Violation of Environmental Conservation Law (ECL) §27-0707 and Title 6 NYCRR Part 360.9.

I Hereby acknowledge receipt of the Facility Copy of this report

Individual in responsible charge

Signature/Date par requested mos



# NEW YORK DEPARTMENT OF ENVIRONMENTAL CONSERVATION DIVISION MATERIALS MANAGEMENT

#### 6 NYCRR Part 360

## SOLID WASTE MANAGEMENT FACILITY INSPECTION REPORT Continuation Sheet

FACILITY NAME:		LOCATION:			FACILITY ID#:	DATE:	TIME:
Air Force Plan	t #51 Site	Greece (T), Monroe (C)			N/A	10-30-18	09:00
INSPECTOR'S	S NAME:	CODE:	PERSONS	INTERVIE	EWED & TITLES		
Mark Amann		S N/A					
REGION	WEATH	ER CONDITION	<b>1</b> S:	DEC	PERMIT NUMBER		memA str
8	See pag	See page 1 N/A SEST OSCI					
SHEET	(	ONTINUATION	SHEET	PAR	Γ(S) 360-	uniny 37°F, WSW wind up	8
2 OF	6 5	AYES II NO		Δ	ttached -		

Violations of Part 360 are Subject to Applicable Civil, Administrative, and Criminal Sanctions Set Forth in ECL Article 71 and as Appropriate, the Clean Water and Air Acts.

Additional Violations May be noted on Sheet one of this inspection report.

Additional Violations May be noted on Sheet one of this inspection report.

Provide site sketches, clarification, supplemental information, locations of photographs or samples and/or locations of violations (uncorrected violations must be described in detail and located on a sketch.)



CRT located in overgrown vegetation north of Building 2

 CRT partially covered with asphalt pavement between Buildings 9 and 11

I Hereby acknowledge receipt of the Facility Copy of this report

Individual in responsible charge

Signature/Date

ignature not requested min



## NEW YORK DEPARTMENT OF ENVIRONMENTAL CONSERVATION DIVISION MATERIALS MANAGEMENT

#### 6 NYCRR Part 360

### SOLID WASTE MANAGEMENT FACILITY INSPECTION REPORT

**Continuation Sheet** 

FACILITY NA	ME:	LOCATION:	MOLY	FACILI	TY ID#:	DATE:			IME:		
Air Force Plan	t #51 Site	Greece (T), Mo	nroe (C)	N/A	(3) eq	moM .com	1 24 200	09:00			
INSPECTOR'	S NAME:	CODE:	PERSONS INT	ERVIEWED &	TITLES						
Mark Amann		S	N/A		AWA				nomAJhak		
REGION	WEATH	IER CONDITIONS:		DEC PERMIT	NUMBER						
8	See pag	ge 1		AWA			Lanag	38e			
SHEET		CONTINUATION S	HEET	PART(S) 360-	THE				TREUN		
3 OF	6	☑ YES ☐ NO		Attached -	_				0 #		

Violations of Part 360 are Subject to Applicable Civil, Administrative, and Criminal Sanctions Set Forth in ECL Article 71 and as Appropriate, the Clean Water and Air Acts.

Additional Violations May be noted on Sheet one of this inspection report.

Provide site sketches, clarification, supplemental information, locations of photographs or samples and/or locations of violations (uncorrected violations must be described in detail and located on a sketch.)



 Waste tires on north interior side of Building 9

Waste tires and orange plastic on south interior side of Building 9

Masa Amaun Inspector's Signature

I Hereby acknowledge receipt of the Facility Copy of this report

Individual in responsible charge

Signature/Date

jgnahne not requested mas



# NEW YORK DEPARTMENT OF ENVIRONMENTAL CONSERVATION DIVISION MATERIALS MANAGEMENT 6 NYCRR Part 360

## SOLID WASTE MANAGEMENT FACILITY INSPECTION REPORT Continuation Sheet

FACILITY N	AME:	LOCATION:			FACILITY ID#:		DATE:		IME:	
Air Force Pla	ant #51 Sit	e Greece (T), M	Monroe (C)	AV	N/A	(T) Monroe (C)	10-30-18	09:	00	
INSPECTOR	R'S NAME	CODE:	PERSONS	SINTERVIE	WED & TITLES					
Mark Amanr	1	S	N/A							
REGION	WEAT	HER CONDITION	IS: 938	DEC	PERMIT NUMBE	ER BUOIT				
8	See pa	ige 1		N/A			cage 1	80	8 -	
SHEET		CONTINUATION	SHEET	PART	(S) 360-					
4 0	6	⊠ YES □ NO		At	tached –					

Violations of Part 360 are Subject to Applicable Civil, Administrative, and Criminal Sanctions Set Forth in ECL Article 71 and as Appropriate, the Clean Water and Air Acts.

Additional Violations May be noted on Sheet one of this inspection report.

Additional Violations May be noted on Sheet one of this inspection report.

Provide site sketches, clarification, supplemental information, locations of photographs or samples and/or locations of violations (uncorrected violations must be described in detail and located on a sketch.)



Piles of C&D debris at south end of site



Piles of C&D debris at south end of site

Mark Janann mspector's Signature I Hereby acknowledge receipt of the Facility Copy of this report

Individual in responsible charge

Signature/Date

ignahme mt rymskil aug



# NEW YORK DEPARTMENT OF ENVIRONMENTAL CONSERVATION DIVISION MATERIALS MANAGEMENT 6 NYCRR Part 360

### SOLID WASTE MANAGEMENT FACILITY INSPECTION REPORT


Con	tinu	atio	n Sh	neet

FACILITY NAI	ME:	LOCATION:			FACILITY ID#:		DATE:	TIME://YTLIDA
Air Force Plan	t #51 Site	e Greece (T), Mor	roe (C)	AV	N/A	Disputation (The	10-30-18	09:00
INSPECTOR'S	S NAME:	CODE:	PERSONS IN	TERVIE	WED & TITLES			
Mark Amann		S	N/A			A84		Erds Amano
REGION	WEATH	HER CONDITIONS:		DEC	PERMIT NUMBER			
8	See pa	ge 1		N/A	AM		Lepro	302 L
SHEET		CONTINUATION SI	HEET	PART	(S) 360-			
5 OF	6	⊠ YES □ NO		At	tached –			B

Violations of Part 360 are Subject to Applicable Civil, Administrative, and Criminal Sanctions Set Forth in ECL Article 71 and as Appropriate, the Clean Water and Air Acts.

Additional Violations May be noted on Sheet one of this inspection report.

Provide site sketches, clarification, supplemental information, locations of photographs or samples and/or locations of violations (uncorrected violations must be described in detail and located on a sketch.)



Piles of C&D debris at south end of site

Pile of asphalt shingles in Building 9

Mark Junum Inspector's Signature I Hereby acknowledge receipt of the Facility Copy of this report

Individual in responsible charge

Signature/Date

nature not rejusted and



#### NEW YORK DEPARTMENT OF ENVIRONMENTAL CONSERVATION **DIVISION MATERIALS MANAGEMENT** 6 NYCRR Part 360

#### SOLID WASTE MANAGEMENT FACILITY INSPECTION REPORT **Continuation Sheet**

FACILITY NAME: LOCATION:			KOLUTY 10#	FACILITY ID:	#:	MOI	DATE:	TIM	E:M YTLJIDA		
Air Ford	e Plan	t #51 S	te Greece (T), N	Ionroe (C)	A	N/A	(a) same	$A_{r}(T)$	10-30-18	134	09:00
INSPECTOR'S NAME:		: CODE:	PERSO	PERSONS INTERVIEWED & TITLES							
Mark Amann			S	N/A							
REGIO	N	WEAT	HER CONDITION	S:	DEC	PERMIT NUM	BER	MOIT	ATHER COND	BW	. Иотов
8	8 See page 1				N/A						
SHEET			CONTINUATION	SHEET	PART	T(S) 360-	SHEET	иот,	CONTINUA		THER
6	OF	6	☐ YES ☒ NO		A	ttached –					TO 8

Violations of Part 360 are Subject to Applicable Civil, Administrative, and Criminal Sanctions Set Forth in ECL Article 71 and as Appropriate, the Clean Water and Air Acts.

Additional Violations May be noted on Sheet one of this inspection report.

Provide site sketches, clarification, supplemental information, locations of photographs or samples and/or locations of violations (uncorrected violations must be described in detail and located on a sketch.)

8 CRTs, 1 pile of C&D debris (windows)

Building 2

1 small pile of debris

West perimeter road

asphalt shingles, carpet, mattress

1 pile of asphalt shingles, 1 tire

1 CRT near fence 1 CRT

Building 9 Waste tire piles, asphalt shingles inside

5 CRTs at various locations between Buildings 9 and 11

**Building 11** 

Gate

Building 1 South

C&D debris piles 1, 2, and 3

More piles of C&D debris, 5 tires, and other wastes

I Hereby acknowledge receipt of the Facility Copy of this report

Individual in responsible charge

grahme not required Test Signature/Date

1 CRT, 1 pile of

ector's Signature