

July 25, 2025

Ms. Kathryn Lovell New York State Department of Environmental Conservation Division of Environmental Remediation, Region 8 6272 East Avon-Lima Road Avon, New York 14414

Re: Monthly Monitoring Report – June 2025 1000 Turk Hill Road, Fairport, New York NYSDEC Site ID No. 828161

Dear Ms. Lovell:

On behalf of New Coleman Holdings, Inc., Roux Environmental Engineering and Geology, D.P.C. (Roux) has prepared this Monthly Monitoring Report (MMR) to summarize the ongoing monitoring and remediation activities, including operation and maintenance of the sub-slab depressurization systems (SSDSs), at 1000 Turk Hill Road, Fairport, New York. Roux has engaged a local subcontractor (Trec Environmental Inc. [Trec]) to perform the monthly monitoring of the SSDSs.

The MMR for May 2025 was submitted to the New York State Department of Environmental Conservation (NYSDEC) and the New York State Department of Health (NYSDOH) on June 16, 2025.

### **SSDS Monitoring**

The monthly SSDS monitoring event was performed by Trec on June 24, 2025. Nine of the 12 SSDS vacuum monitoring points were inspected, measured, and confirmed to be operating within the pre-established parameters. During the visit, the monitoring points associated with Systems B1, B2, C1 and C2 in Building 1 (located in the vacant spaces formerly occupied by Wonder Repair and Nat's Nuts) could not be accessed. The vacuum measurements from all accessible monitoring points were consistent with previous monitoring events and within the required performance ranges for those systems.

The exterior components of each of the five SSDSs on Building 1 and Building 3 were also inspected. As previously noted, the mounting brackets for System A in Building 3 are broken, but the vent pipe remains fastened and will continue to be inspected monthly to ensure operation is not impacted. It was also noted that vegetation growth on the north side of Building 1 is causing rubbing on some of the discharge piping.

The vacuum measurements and other pertinent information documented during the inspection are provided on the attached Monthly SSDS Monitoring and Inspection Checklist – June 2025 (Table 1). The locations and designations of the various SSDS systems and monitoring points are shown on the attached SSDS As-Built Drawings prepared by Envirosafe Inspections & Consulting (Attachment 1).

The next SSDS monitoring event is planned to occur during the week of July 28, 2025, and will be documented in a future Monthly Monitoring Report.

# **Remedial Injection Program**

Work related to the remedial injection program is ongoing. The second groundwater performance monitoring event to evaluate the injection program performance was completed between April 21 and 23, 2025 with the results detailed in the June 16, 2025 Groundwater Monitoring Report. The 2<sup>nd</sup> Phase of the remedial injection program was performed July 1 through July 14, 2025, and the next groundwater performance monitoring event is tentatively scheduled to be performed the week of August 4<sup>th</sup>.

If you have any questions or require additional information, please do not hesitate to contact me at (917) 825-1108 or via email at <a href="mailto:masmith@rouxinc.com">masmith@rouxinc.com</a>.

Sincerely,

ROUX ENVIRONMENTAL ENGINEERING AND GEOLOGY, D.P.C.

Matthew Smith Senior Scientist I

**ROUX ASSOCIATES, INC.** 

Christopher Battista Principal Scientist

## Attachments

cc: Anthony Perretta, NYSDOH
Charlotte Theobald, NYSDEC
Charles J. Sgro, New Coleman Holdings, Inc.
Allie LeBlanc, New Coleman Holdings, Inc.
Steve Russo, Esq., Greenberg Traurig, LLP
Omar Ramotar, P.E., Roux Associates, Inc.

#### Table 1. Monthly SSDS Monitoring and Inspection Checklist - June 2025

Turk Hill Park, 1000 Turk Hill Road, Fairport, New York - NYSDEC Site No. 828161

### Building 1

Building 1	Tenant / Location	Date	Time	Baseline Manometer Reading (In. W.C.) 1/29/18	Current Manometer Reading (In. W.C.)	Evidence of Water/ Condensation Accumulation	Is The Fan Operating as Expected?	Is Any of The Piping Damaged or Disconnected?	Comments
System A	Canal Metalsmith	6/24/2025	12:55 PM	2.4	2.2	N	Υ	N	
System B1	Wonder Repair & Floor Coverings	6/24/2025	12:40 PM	1.0	N/A & 1.0	N	Υ	N	Fairport Computer is now Floor Coverings.
System B2	Vacant (Formerly Wonder Repair)	6/24/2025	12:35 PM	1.0	N/A	N	Υ	N	No access to the vacant tenant space.
System C1	Vacant (Formerly Nat's Nuts)	6/24/2025	12:30 PM	0.9	N/A	N	Υ	N	No access to the vacant tenant space.
System C2	Vacant (Formerly Nat's Nuts)	6/24/2025	12:30 PM	1.0	N/A	N	Υ	N	No access to the vacant tenant space.
System D	Amazing Grains Bread Company	6/24/2025	12:20 PM	2.8	2.4	N	Υ	N	
System E	Amazing Grains Bread Company	6/24/2025	12:15 PM	1.9	1.8	N	Υ	N	

### Building 3

Building 3	Tenant / Location	Date	Time	Baseline Manometer Reading (In. W.C.) 1/29/18	Current Manometer Reading (In. W.C.)	Evidence of Water / Condensation Accumulation	Is The Fan Operating as Expected?	Is Any of The Piping Damaged or Disconnected?	Comments
System A	Men's Bathroom	6/24/2025	12:00 PM	2.5	2.5	N	Υ	N	
System B	Loading Dock	6/24/2025	11:45 AM	1.9	2.0	N	Υ	N	
System C	Former Spartacus (tenant space)	6/24/2025	11:20 AM	2.2	2.2	N	Υ		Tenant does not maintain consistent hours. No access during O&M visit. Image of manometer provided by teneant.
System D	Millwork Shop	6/24/2025	11:35 AM	2.8	2.6	N	Υ	N	
System E	CrossFit Fairport	6/24/2025	11:00 AM	2.8	2.5	N	Υ	N	No access.


Notes:

N/A - Not Available

NM - Not Measured

In W.C. - inches of water column








PO Box 671 Honeoye, NY 14471 585-704-4385

www.envirosafeinspections.com

Figure 1





PO Box 671 Honeoye, NY 14471 585-704-4385

www.envirosafeinspections.com

Figure 2