

Penn Yan Former MGP Site  
150 Water Street, Penn Yan, NY

## Erosion and Sediment Control

Name of Inspector: George Fischer

Weather: Clear, 81 °

7/19/2018

Are all the erosions controls functioning properly?	YES - Comment	NO – Comment
	YES - some silt fence on west side pulled from stakes but is on uphill side of site.	
Is any silt fence in need of repair or replacement?		NO
Are any storm drain inlet protections in need of repair or replacement?		N/A
Is there any potentially contaminated water migrating off-site?		No
Are any hay bales in need of repair or replacement?		N/A

### Additional Checks

	Comments:
Condition of runoff at all points of discharge from the site (pipe, culverts and ditches)	N/A
Condition of all natural water bodies which receive runoff	Clear
Corrective action to repair E&S	N/A

Construction activity not in line with SWPPP	N/A
--	-----

**Notes:**

Inspection completed during temporary shut-down.

