

# DAILY OBSERVATION REPORT

Pg. 1 of 12

Report No.: 174

D&B Project File: 3150-31

Date: 9/11/2018

<b>D&amp;B Engineers and Architects, P.C.</b>	<b>Contractor PM: Matt Thorpe</b>
	<b>NYSDEC PM: Gerry Pratt</b>
<b>Site Location: 150 Water Street, Penn Yan, NY 14527</b>	<b>NYSDEC Chief Inspector: Scott Deyette</b>
	<b>Construction Manager: Tony Certo</b>
	<b>Project Engineer: AECOM</b>
	<b>Remedial Contractor: Severson</b>
	<b>Air Monitoring: AECOM</b>
	<b>Health &amp; Safety: Ben Faery</b>

## Weather Conditions

<b>General Description</b>	<b>a.m. Mostly cloudy</b>	<b>p.m. Mostly cloudy</b>
<b>Temperature</b>	<b>a.m. 69°F</b>	<b>p.m. 68°F</b>
<b>Wind Direction</b>	<b>a.m. 0 mph</b>	<b>p.m. 0 mph</b>

## HEALTH & SAFETY:

List the deviation under the "Items for Concern" section of this report for ANY box(s) below checked "YES"

Were there any changes to the Health & Safety Plan?	*Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	NA <input type="checkbox"/>
Were there any exceedances at the perimeter action level reported on this date?	Air: *Yes <input type="checkbox"/>	No <input type="checkbox"/>	NA <input checked="" type="checkbox"/>
Were there any Noise /Vibration exceedances reported on this date?	Noise: *Yes <input type="checkbox"/>	No <input type="checkbox"/>	NA <input checked="" type="checkbox"/>
	Vibration: *Yes <input type="checkbox"/>	No <input type="checkbox"/>	NA <input checked="" type="checkbox"/>
Were there any breaches to the tent structure or silt fence reported/observed on this date?	*Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	NA <input type="checkbox"/>
Were there any dust/odor issues reported or observed on this date?	*Yes <input type="checkbox"/>	No <input type="checkbox"/>	NA <input checked="" type="checkbox"/>

## WASTE HAULING:

List the deviation under the "Items for Concern" section of this report for ANY box(s) below checked "YES"

Were there any vehicles which did not display proper D.O.T. or NYCRR Part 364 numbers and placards?	*Yes <input type="checkbox"/>	No <input type="checkbox"/>	NA <input checked="" type="checkbox"/>
Were there any vehicles which were not lined or tarped?	*Yes <input type="checkbox"/>	No <input type="checkbox"/>	NA <input checked="" type="checkbox"/>
Were there any vehicles which were not decontaminated prior to exiting the work site?	*Yes <input type="checkbox"/>	No <input type="checkbox"/>	NA <input checked="" type="checkbox"/>

## MATERIALS REMOVED FROM SITE:

Waste Material	Disposal Facility	Daily Loads	Loads to Date	Total Daily Weight (tn)*	Total Weight to Date (tn)**
NA					

\* Daily weight estimated based on truck capacity

\*\*Adjusted periodically based on weight tickets from disposal facilities.

# DAILY OBSERVATION REPORT

Pg. 2 of 12

Report No.: 174

D&B Project File: 3150-31

Date: 9/11/2018

## MATERIALS IMPORTED TO SITE:

Source of Material	Material Type	No. of Loads	Quantity/Comments
NA			

## SUMMARY OF EVENTS

Today AECOM started the process of relocation/installation of their liquid level settlement system to the second floor of the former MGP building.

AECOM reported visible sheen on the water at the outlet control structure, southeast of the MGP site. This was confirmed by D&B Engineers. There was no other sheen visible along the outlet. This sheen is consistent with previous observations at the site.

## VISITORS TO SITE:

Name	Company	Purpose of Visit	Enter Exclusion Zone
John Ruspantini	NYSEG	Weekly site meeting	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
			Yes <input type="checkbox"/> No <input type="checkbox"/>
			Yes <input type="checkbox"/> No <input type="checkbox"/>
			Yes <input type="checkbox"/> No <input type="checkbox"/>

## PROJECT SCHEDULE:

AECOM will continue installation of the new liquid level settlement system. AECOM will install pads and masts for the total stations, one located on the site and one located south of the outlet (off-site).

SES will continue to mobilize.

## ISSUES PENDING:

NA

## ITEMS OF CONCERN:

NA

## SITE REPRESENTATIVE/ CONSTRUCTION INSPECTOR:

Skylar Haas

, Site Representative

SIGNATURE:



DATE: 9-11-18

# DAILY OBSERVATION REPORT

Pg. 3 of 12

Report No.: 174

D&B Project File: 3150-31

Date: 9/11/2018

# DAILY OBSERVATION REPORT

Pg. 4 of 12

Report No.: 174

D&B Project File: 3150-31

Date: 9/11/2018



**Photo 1:** Sheen visible at the outlet control structure facing west.

# DAILY OBSERVATION REPORT

Pg. 5 of 12

Report No.: 174

D&B Project File: 3150-31

Date: 9/11/2018



**Photo 2:** Sheen visible at the outlet control structure facing west.



# DAILY OBSERVATION REPORT

Pg. 6 of 12

Report No.: 174

D&B Project File: 3150-31

Date: 9/11/2018



**Photo 3:** Sheen visible at the outlet control structure facing west.



# DAILY OBSERVATION REPORT

Pg. 7 of 12

Report No.: 174

D&B Project File: 3150-31

Date: 9/11/2018



**Photo 4:** Sheen visible at the outlet control structure facing northwest.



# DAILY OBSERVATION REPORT

Pg. 8 of 12

Report No.: 174

D&B Project File: 3150-31

Date: 9/11/2018



**Photo 5:** East side of the outlet control structure, no visible sheen. Facing east.



# DAILY OBSERVATION REPORT

Pg. 9 of 12

Report No.: 174

D&B Project File: 3150-31

Date: 9/11/2018



**Photo 6:** View from Liberty St bridge southwest of the MGP site, no visible sheen. Facing northeast.

# DAILY OBSERVATION REPORT

Pg. 10 of 12

Report No.: 174

D&B Project File: 3150-31

Date: 9/11/2018



**Photo 7:** View of the outlet near the outfall piping southeast of the MGP site, no visible sheen. Facing south.



# DAILY OBSERVATION REPORT

Pg. 11 of 12

Report No.: 174

D&B Project File: 3150-31

Date: 9/11/2018



**Photo 8:** View of the level markings on the second floor of the MGP for AECOM's liquid level settlement system.



# DAILY OBSERVATION REPORT

Pg. 12 of 12

Report No.: 174

D&B Project File: 3150-31

Date: 9/11/2018



**Photo 9:** View of the southside of the MGP building, facing east.