



NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
Division of Environmental Remediation

Inactive Hazardous Waste Site Operations and Maintenance Review Report

Form Date 06.10.01

Site Name: Essex - Hope		Class: 4	Number: 907015
O&M Funding Source: <input type="checkbox"/> State Superfund <input type="checkbox"/> Federal Superfund <input type="checkbox"/> Municipal <input checked="" type="checkbox"/> Responsible Party			
O&M Information: O&M Start: December 1998 End: Annual Cost:			
Interim Remedial Measures/Operable Units in O&M Phase:			
<input type="checkbox"/> Drum Removal	<input checked="" type="checkbox"/> Soil Removal	<input type="checkbox"/> Tank Removal	
<input checked="" type="checkbox"/> Cap/Cover	<input type="checkbox"/> Containment Structure	<input type="checkbox"/> Fence/Security	
<input checked="" type="checkbox"/> Groundwater Recovery/Treatment	<input type="checkbox"/> Leachate Collection/Treatment	<input checked="" type="checkbox"/> Vapor Extraction/Treatment	
<input checked="" type="checkbox"/> Air Sparging/Stripper System	<input checked="" type="checkbox"/> Treatment/Filtration Plant/System	<input type="checkbox"/> Potable Water Supply/System	
<input type="checkbox"/> Other:			
Institutional Controls: <input type="checkbox"/> Deed Restriction <input checked="" type="checkbox"/> Discharge Permit <input type="checkbox"/> Department of Health Sampling			
<input checked="" type="checkbox"/> Other: Air Permit			
O&M Review Information:			
Reports: On File Region 9 DER:			
Inspection: June 29, 1999			
Sampling: PRP Reports on file. Last - 1st. Qtr. 1999			
Other:			
Conclusions:			
Remedy Effective? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No:			
ROD Compliance? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No:			
Consent Order Compliance? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No:			
Other:			
Recommendations: <u>Old contaminated water storage tank should be removed from pad area. grass needs cutting for vector control in the UST area. Lock out all accessible, outdoor electrical panels and switches. Replace the positive pressure intake stack to prevent vapor intake from vacuum blower at the treatment facility. Surface water stands over MW - 1. All monitoring well covers should be checked and all missing bolts be replaced. Cracks in asphalt should be cleaned and sealed. Water meters on old buildings should be monitored to determine if there is leakage in the potable system. Air sparging PVC piping in VEW shed are discolored from heat. This should be replaced with a more suitable material. Determine the status of repair of the vacuum blower in the former UST area. Review system for changes and modifications and update manuals and prints where necessary.</u>			
ROD/Consent Order Modifications? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes (per above) Reclassify the Site? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes → Class:			
Comments: <u>System continues to be operated in a satisfactory manner and provides continued remediation of the area. Efforts to optimize the operation and enhance system removal productivity should continue.</u>			
Project Manager:		Reviewer:	
			
Date: 7/6/99		Date: 7/6/99	
Maurice F. Moore, Region 9 DER, 716-851-7220		Martin L. Doster, P.E. Region 9 DER 716-851-7220	
Name Region or Bureau Telephone		Name Region or Bureau Telephone	

Copy To: W.H. Welling - C.O.