



SITE INSPECTION REPORT

Site Name: Houdaille Industries, Strippit Division

Site Number: 915053

Location: 12975 Clarence Center Road, Akron, New York, 14001

Inspection Date: 8/7/2026

NYSDEC Project Manager: Bradley Demo

Weather Conditions: Light Rain, 72°F

Personnel Onsite: Ray Kampff **(Day Engineering and Geology)** Bruce, Dan, Brendan
(Sun Environmental)

Description of Work Performed: Drum removal

- NYSDEC observed removal of possible drum remains discovered just outside of capped area during the last landfill inspection completed by Day. Material was hardened, rock-like with rust color on the outside, possibly indicating the shell of a drum that was missed during consolidating/capping operations over 30 years ago.
- Material was sampled for waste characterization and placed in a 55-gal drum along with the 4-6 inches of soil beneath it. NYSDEC noted no odors, discoloration, or residual material left behind. No stressed vegetation was observed in the area. As the material was located outside of the landfill footprint no cover material was used to backfill the approximately 1ft x 2.5 ft x 6-inch depression. Drum was placed on Strippit property to be removed later pending waste characterization results.
- No other environmental conditions of note were observed while walking the landfill area.

Inspector: Bradley Demo

Signature: 

Site Inspection Report

Houdaille Industries Strippit Division (Site No. 915053)

August 7, 2026

Page 2

Photolog:



Material to be removed.

Site Inspection Report

Houdaille Industries Strippit Division (Site No. 915053)

August 7, 2026

Page 3



Same as above, closeup view.

Site Inspection Report

Houdaille Industries Strippit Division (Site No. 915053)

August 7, 2026

Page 4



Landfill conditions.