Number of Samples

N/A

Report No.: 7-29-13---0001* EEEPC Project File: EN-003229-0001-06TT0 Date: Monday, 07/29/13 **Client: NYSDEC** Contract No. D007631 Temperature: (F) 59 (am) 63 (pm) Wind Direction: **Division of Environmental Remediation** __(am)__(pm) **Construction Management Oversight** Weather: (am) Light Rain NYSDEC Site # 9-15-157 (pm) Cloudy Re: Air-stripper Teardown and Cleaning Site: Mr. C's Dry Cleaners Site Address: 586 Main Street, East Aurora, Erie County, Arrive at site: 10:45 (am) **New York 14052** Leave site: 5:00 (pm) **HEALTH & SAFETY:** Are there any changes to the Health & Safety Plan? Yes () No (X) (If yes, list the deviation under items for concern) Yes () n/a(X) Yes () n/a(X) * No () Are monitoring results at acceptable levels? -- Soils: Notes: * No () -- Waters: Yes () n/a(X)* No () -- Air (CAMP): *If No, provide comments **OTHER ITEMS:** Site Drawing(s) Attached: Yes () No (X) Photos Taken: Attached: Yes (X) No()

Samples Taken For Analysis Today:

Pg. 2 of 14

Report No.: 7-29-13---0001* EEEPC Project File: EN-003229-0001-06TT0 Date: Monday, 07/29/13

DESCRIPTION OF DAILY WORK PERFORMED:

- 1045 hrs Arrived at the site with Iyer Environmental and Acome Construction staff present. Staff
 member was cleaning air stripper trays with a pressure washer. Staff members were working inside
 the Mr. C's treatment building.
- 1330 hrs Staff used a pressure washer, grinder, and drills to clean and restore air stripper trays. Staff continued to clean inside the Mr. C's treatment building.
- 1500 hrs Staff restacked clean air stripper trays in the Mr. C's treatment building using the forklift.
- 1700 hrs Staff members cleaned the site and left.

CONTRACTOR/SUBCONTRACTOR PERSONNEL ON SITE:

Name Company Representing		Reason Onsite	Hours on-site
R. Allen	lyer Environmental	Helper	7
Subcontractor Personnel	Acone Construction	Helper	7
Subcontractor Personnel	Acone Construction	Helper	7
Subcontractor Personnel	Acone Construction	Helper	7

Report No.:	7-29-130001*	EEEPC Project File:	EN-003229-0001-06TT0	Date:	Monday, 07/29/13
	(* Date of Work and Daily Observation Report No.)	•			

EQUIPMENT ON SITE:

Equipment	Hrs	Equipment	Hrs	Equipment	Hrs	Equipment	Hrs
Forklift	7						
Pressure Washer	7						

^{1 –} Active Equipment 2 – Inactive Equipment

VISITORS TO SITE:

• D. Iyer, Iyer Environmental

PROJECT SCHEDULE ITEMS / ISSUES:

• None

PROJECT BUDGET ISSUES:

• None

OFF-SITE WASTE TRANSPORTATION/DISPOSAL PRODUCTION:

Waste Stream	Method of Transport	Estimated	Disposal Facilities		
		Volume			
N/A					
N/A					

ITEMS OF CONCERN:

• None

Report No.:	7-29-130001* Date of Work and Daily Observation Report No.)	EEEPC Project File:	EN-003229-0001-06TT0	Date: _	Monday, 07/29/13
COMMENT					
• None	•				
	ENT(S) TO THIS REPO		oosed change orders, p	hoto log, (drawings)
		Jared Best, EE	EPC , <u>Site Representat</u>	<u>ive</u>	
	PRESENTATIVE / TION INSPECTOR:	\bigcirc .			
Name: (si	gnature)	(forly	/bh\	_ Date: 7/2	29/13
N	V. Welling – NYSDEC M. Steffan – E & E Buffalo T Heins – E & E Buffalo	<i>V</i>			

Pg. 5 of 14

7-29-13---0001*
(* Date of Work and Daily Observation Report No.) Report No.: EEEPC Project File: EN-003229-0001-06TT0 Date: Monday, 07/29/13

DAILY PHOTOLOG

Date	Photo ID	Description
7/29/13	IMG_20130729_110049.JPG	Setup outside the Mr. C's treatment building - looking Northeast
7/29/13	IMG_20130729_110215.JPG	Staff using a pressure washer to clean an air stripper tray - looking Northeast
7/29/13	IMG_20130729_113628.JPG	Setup outside the Mr. C's treatment building - looking East
7/29/13	IMG_20130729_115805.JPG	Setup outside the Mr. C's treatment building - looking East
7/29/13	IMG_20130729_115856.JPG	Setup outside the Mr. C's treatment building - looking Northeast
7/29/13	IMG_20130729_115949.JPG	Inside Mr. C's treatment building
7/29/13	IMG_20130729_133127.JPG	Inside Mr. C's treatment building
7/29/13	IMG_20130729_160851.JPG	Staff cleaning and restoring air stripper trays
7/29/13	IMG_20130729_165359.JPG	Staff restacking air stripper trays in the Mr. C's treatment building

Pg. 6 of 14



IMG_20130729_110049.JPG



IMG_20130729_110215.JPG

Pg. 8 of 14



IMG_20130729_113628.JPG

Pg. 9 of 14



IMG_20130729_115805.JPG

Report No.: 7-29-13---0001* EEEPC Project File: EN-003229-0001-06TT0 Date: Monday, 07/29/13

(* Date of Work and Daily Observation Report No.)



IMG_20130729_115856.JPG

Pg. 11 of 14



IMG_20130729_115949.JPG

Pg. 12 of 14

Report No.: 7-29-13---0001* EEEPC Project File: EN-003229-0001-06TT0 Date: Monday, 07/29/13

EOS PRINTED DE LA PORTE DE LA

IMG_20130729_133127.JPG

Pg. 13 of 14



IMG_20130729_160851.JPG

Pg. 14 of 14

Report No.: 7-29-13---0001* EEEPC Project File: EN-003229-0001-06TT0 Date: Monday, 07/29/13

(* Date of Work and Daily Observation Report No.)



IMG_20130729_165359.JPG