

Hyde Park Landfill 2009 Gorge Inspection Walk

DER Site Management, 7/21/09

Photos with Notes

Photo

Description



Seep 2 on access road. Typical flow. I was catching up to the group who had gathered at the foot of the hill. Due to a mis-understanding, I met the rest of the participants at the bottom of the hill at the entrance to the gorge path.



Seep 2



Walking on the Niagara River
path



Walking upstream



Walking upstream



Minor flow beneath the rocks and vegetation not very visible here.



Minor flow beneath the rocks and vegetation not very visible here.



Bloody Run.



Stone pavement.



River edge



Laid up stone from the
short-lived railroad alignment



Jane Pietraszek-Polovich
Conestoga-Rovers and
Associates
2055 Niagara Falls Blvd.
Suite 3
Niagara Falls, New York 14304
Phone: 716-297-6150 x 314
Fax: 716-297-2265 Jane is at
the Garfield Avenue sewer outfall.



Outcrop above the outfall



The Garfield Avenue sewer outfall
at the river edge



Cave at Garfield Avenue outfall



Snake in the grass at Garfield outfall



Opposite side, canada




Telephoto shot of the Niagara River.



No telephoto, same view of the Niagara River. She was really flowing fast.



Up the stairs, Devil's Hole State Park



Rock face



Matt Forcucci, NYSDOH



Matt Forcucci, NYSDOH



Rock face.



Overlook from the Robert Moses, unused lanes



Overlook from the Robert Moses, unused lanes



Overlook from the Robert Moses, unused lanes



Overlook from the Robert Moses, unused lanes



Crossing the Robert Moses Parkway at the end of the inspection walk