



SITE INSPECTION REPORT

Site Name: Frontier Chemical Pendleton

Site Number: 932043

Location: Townline Road, Pendleton, New York, 14120

Inspection Date: 4/1/2026

NYSDEC Project Manager: Bradley Demo

Weather Conditions: Cloudy, 59°F

Personnel Onsite: Jesse Grossman (**Glynn Group**), Max Liffiton, Greg Ernst (**Sevenson Environmental**)

Description of Work Performed: Site Inspection

- NYSDEC onsite 10:00 AM to 11:00 AM for semiannual inspection.
- Glynn surveyed water level of Quarry Lake with Topcon AT-FG and inspected weir. Glynn Group unaware of remedial significance of surveying water level of Quarry Lake, it was an item on original inspection checklist after remedial action was completed, per Jesse. Overflow weir was observed to be flooded and water flowing into lake. Per Glynn Group, weir was simply geotechnical fabric and stone laid down in that area during remedial action completion.
- Sevenson pumping collection system for influent and effluent sampling. NYSDEC informed them of ongoing requirement to include disposal records of treatment system carbon tanks. If carbon is treated as non-hazardous solid waste, applicable testing records must be provided in annual Periodic Review Reports.
- Ruts in driveway along western to northwestern site perimeter. Several animal borrow holes were observed in eastern/northeastern landfill capped area and will need to be backfilled.

Inspector: Bradley Demo

Signature:

Site Inspection Report

Frontier Chemical Pendleton (Site No. 932043)

April 1, 2026

Page 2

Photolog:



Wetlands west/northwest of Quarry Lake.

Site Inspection Report

Frontier Chemical Pendleton (Site No. 932043)

April 1, 2026

Page 3



Weir conditions, view facing south.

Site Inspection Report

Frontier Chemical Pendleton (Site No. 932043)

April 1, 2026

Page 4



Animal Burrows in landfill cap.

Site Inspection Report

Frontier Chemical Pendleton (Site No. 932043)

April 1, 2026

Page 5



Landfill cap conditions, view facing southwest.

Site Inspection Report

Frontier Chemical Pendleton (Site No. 932043)

April 1, 2026

Page 6



Groundwater collection system sump vault.

Site Inspection Report

Frontier Chemical Pendleton (Site No. 932043)

April 1, 2026

Page 7



Glynn survey setup.

Site Inspection Report

Frontier Chemical Pendleton (Site No. 932043)

April 1, 2026

Page 8



Vehicle ruts, view facing south.

Site Inspection Report

Frontier Chemical Pendleton (Site No. 932043)

April 1, 2026

Page 9



Landfill cap conditions, view facing south/southeast.