

NYSDEC

Region 9

Division of Environmental Remediation

Site: Olin Industrial Welding Site

Phase: Management

Site No.: 932050

Contractor PM:

NYSDEC PM: Bradley Demo

Construction Manager:

Project Engineers:

Remedial Contractor: WSP/Tim Dillon

Air Monitoring:

Health & Safety:

Weather Conditions

| | | | |
|---------------------|--------------|----|----|
| General Description | Cloudy | am | pm |
| Temperature | 33°F | am | pm |
| Wind Direction | E, 10-15 MPH | am | pm |

HEALTH & SAFETY:

(*If any box(s) below are checked "Yes", list the deviation under the "Items for Concern" section of this report).

| | | | |
|---|---------------------|--------|--------|
| Were there any changes to the Health & Safety Plan? | *Yes () | No () | NA (x) |
| Were there any exceedances at the perimeter action level reported on this date? | Air: *Yes () | No () | NA (x) |
| Were there any Noise /Vibration exceedances reported on this date? | Noise: *Yes () | No () | NA (x) |
| | Vibration: *Yes () | No () | NA (x) |
| Were there any breaches to the tent structure or silt fence reported/observed on this date? | *Yes () | No () | NA (x) |
| Were there any dust/odor issues reported or observed on this date? | *Yes () | No (x) | NA () |

WASTE HAULING :

(*If any box(s) below are checked "Yes", list the deviation under the "Items of Concern" section of this report).

| | | | |
|---|-----------|--------|--------|
| Were there any vehicles which did not display proper D.O.T numbers and placards? | *Yes () | No () | NA (x) |
| Were there any vehicles which were not lined or tarped? | *Yes () | No () | NA (x) |
| Were there any vehicles which were not decontaminated prior to exiting the work site? | * Yes () | No () | NA (x) |

Materials Removed From Site: N/A**Disposal Facility:**

Total Loads: (on this date)

Total Loads: (to date)

Total Daily Weight: (est.)

Total Weight: (*approx.)

Actual (total weight) adjusted periodically based on weight tickets submitted by the disposal facilities.*Summary of Events:**

- NYSDEC onsite 8:15 am to 10:00 am. Olin technicians conducting semi-annual sampling surface discharge (SD-1) as well as MW-1 and MW-2. Leachate collection sampling will occur in fall. Severson onsite conducting semi-annual gauging and sitewide inspection
- Fencing, leachate control recovery system (LCRS) flow meters, piping, sump, and vegetative cover in good shape, no deficiencies noted. Some standing water in perimeter drainage ditch but no evidence of erosion or settlement. All catch basins, monitoring wells and LCRS cleanout found to be in acceptable conditions. Piezometer P-1R hinge would not shut, should be noted on inspection form. NYSDEC requested annual mowing occur after Aug 15, Severson noted.
- Asphalt cover in good shape, 1 instance of vegetation growth through cover was noted. No further action needed at this time. All manholes, culverts, drop inlets in acceptable conditions. Only 1 of 3 outfalls/headwall was visible from opposite side of Gill Creek and appeared to be in good condition.
- PRMW-1, PRMW-2 additional standpipe need to be identified on site figure. One unidentified monitoring well was observed in poor condition in NE portion of site between Gill Creek and Veterans Drive.

VISITORS TO SITE:

| NAME | Representing | Entered Exclusion/CRZ Zone | |
|--------------|--------------|----------------------------|-------|
| Steve, Corey | Olin | Yes (x) | No () |
| Max, Danny | Severson | Yes (x) | No () |
| | | Yes () | No () |
| | | Yes () | No () |

PROJECT SCHEDULE:

- Next inspection/sampling will occur in the fall.

ISSUES PENDING:

-

ITEMS OF CONCERN:

-

Inspector: Bradley Demo

Signature: *Bradley W. Demo*

Date: 3/25/2025



OU-2 vegetative cover/drainage ditch with a small amount of standing water. View looking NW.



Asphalt/Vegetative cover. View looking W.



Asphalt/Vegetative cover. View looking E.



Vegetative cover/OU-2 view looking N.



Wooded area outside of cover system. View facing W.



Culvert/Riprap.



Drainage ditch/vegetative cover OU-2 view facing N.



Olin sampling SD-1.



Asphalt cover with minor vegetation growth through cracks.



Electric panel/control box for LCRS.



LCRS cleanout pipe.



LCRS cleanout pipe/northern vegetative cover facing W.



LCRS cleanout pipe/northern vegetative cover facing E.



Catch Basin in NE corner.



Gill Creek/OU-1.



Outfall/headwall at Gill Creek/OU-1. Only 1 of 3 outfalls was observed on this date.



LCRS sumps/piping/flow meter.



LCRS containment box.



PRMW-1/unidentified standpipe.



Drop inlet, typical.



Asphalt cover facing N.



Asphalt cover facing W.



Unidentified well between Veterans Dr. and Gill Creek.