



- 201' - 198' - 185' - 174' - 158' - 139' - 136.5'	- 1121, - 119, - 103, - 100, - 89,	DRAINAGE S PIPE I I	- 40.4'	TRANSIT .5666666666.
SEEP 22 SEEP 21 SEEP 21 SEEP 13 SEEP 13 SEEP 13 SEEP 13 SEEP 13 SEEP 15 SEEP 1	SEEP 16 SEEP 10 SEEP 10 SEEP 9 SEEP 8 NEW SEEP 7	SEEP 6 58'	SEEP 5	SEEP 4 SEEP 3 SEEP 1

NORTHEAST

BASELINE IN FEET FROM MEASURING POINT PK-01

NYSEG TRANSIT STREET FORMER MGP SITE NAPL SEEP STUDY - NEW YORK STATE BARGE CANAL BASELINE SEEP LOCATIONS



FIGURE 1

**SOUTHWEST** 



Seep 1: Image taken 3/17/08. Note slight black staining on rock face.



Seep 1: After cleanup of rock face (3/17/08).



Seep 1: No noticable seep activity (4/10/08).





Seep 2: Image taken 3/17/08. Note black staining on rock face.



Seep 2: Image taken after cleanup of rock face on 3/17/08.



Seep 2: Slight white film developing upon inspection (4/10/08).





Seep 3: Image taken 3/17/08. Note black staining and NAPL globules.



Seep 3: Image taken after cleanup of rock face on 3/17/08.



Seep 3: Slight white film, tar globules, and sheen noted during inspection on 4/10/08.





Seep 4: Image taken 3/17/08. Note slight black staining on rock surface.



Seep 4: Image taken after cleanup of rock face on 3/17/08.



Seep 4: Slight white film developing on Seep 4, noted by the yellow arrow on the left. Image taken on 4/10/08.





Seep 5: Image taken 3/17/08. Note slight black staining and white film.



Seep 5: Image taken after cleanup of rock face on 3/17/08.



Seep 5: Slight white film developing and rust discoloration noted during inspection on 4/10/08.





Seep 12: Image taken 3/17/08. Note black staining on rock face.



Seep 12: Image taken after cleanup of rock face on 3/17/08.



Seep 12: White film developing. Note black staining and tar globules. Image taken on 4/10/08.





Seep 16: Image taken 3/17/08. Note black staining and slight sheen on rock face.



Seep 16: Image taken after cleanup of rock face on 3/17/08.




Seep 16: Slight white film developing. Note black staining and tar globules. Slight odor observed during inspection on 4/10/08.





Seep 18: Image taken 3/17/08. Note black staining and white film on rock face.




Seep 18: Image taken after cleanup of rock face on 3/17/08.



Seep 18: Slight white film developing, slight sheen observed. Note black staining. Image taken during inspection on 4/10/08.





Seep 19: Image taken 3/17/08. Note black staining and white film on rock face. (Note: Rock face was not cleaned at this seep).




Seep 19: White film and black staining noted during inspection on 4/10/08.





Seep 20: Image taken 3/17/08. Note black staining and white film on rock face. (Note: Rock face was not cleaned at this seep)



Seep 20: Closeup image taken on 3/17/08. Note black tar stains.



Seep 20: Black staining, tar globules, and odor during inspection on 4/10/08.





Seep 22: Image taken 3/17/08. Black staining and white film noted on rock face. (Note: Rock face was not cleaned at this seep).



Seep 22: White film and black tar globules noted on rock face during inspection on 4/10/08.

