

Fax: 516-333-8660

## 702 Grand Blvd WestBury, NY 11590 690 Muncy Avenue, Lindenhurst, NY 11757

## Fax Cover Sheet

Company: Ellis Koch	From: Gale Valenti
Attn: Ellis	<b>Date</b> : June 26, 2012
Fax: 516-740-0071	Pages: 2
<b>Phone:</b> 516-983-7333	
Notes: The following page is the inspection	on sheet for June.
Respectfully,	
Gale	
Gale Valenti Construx   Administrative Assistant 702 Grand Boulevard   Westbury NY 115	.an

Direct: 516.333.3133 | gvalenti@con-strux.com | http://www.con-strux.com/

SITE WALK-THROUGH CHECKLIST	
TASK:	CHECK BOX IF TASK IS COMPLETED (If not completed, please state reason)
1. Clearing of Perimeter Debris (Outer Fence)	Clear
2. Grass & Tree Inspection (Outer Fence)	Clear Cut wat
3. Review "Wash Out" of Bulk Head	Some Repair needed but Stable
4. Review Boom Position, Tie Off & Barnacles	Boom Ok -
Inspect Oil "Sheens" in Water (Please Specify)     a. location of water pools showing a sheen     b. number of pads put into the water body	none Observed
6. Inspect any JDP/BWE Machinery (broken glass or vandalism)	Secure
7. Tarps & any Temporary Work	Secure
Inspect Water System     (including freezing and flush-out)	Some - noever Activated
9. Is Tank Empty?	LVES
10. Is Irrigation System Flushed?	yes
11. Review Electrical and Job Trailer	Locked & Secure
12. Silt Fence	In Place a Secure
13. Check Oil Collection Boom for Holes and Replace when Absorbent Material is at Capacity	OK
Date/Time of Inspection: 10:00m 6/26/	Site: Harbor Isle - Island Park, NY
Inspection Done By:	Weather Conditions: Clear 65

Notes: Piles of feedstock soil and treated soil need to be covered with poly sheeting and weighted down. The better they are weighted down, the less the site will need to be visited to replace the covers. Until confidence in the integrity of the covers is obtained, they should be checked at least once a week and more frequently, if conditions are unusually windy.

A log of site visits and activities needs to be maintained for review by the DEC.

If sheens are detected, absorbent pads need to be placed in the sheens to remove the floating oils