
	Daily Activity Report		
OAK RF	820 East 182nd Street Bronx, NY		
			BCP Site No. C203149
		General Site Information	
Date:	Monday, March 6, 2023		
Weather:	Partly Cloudy, 40° F		
Wind Direction/Speed:	E @ 5 mph		
AKRF Personnel on Site:	J. Kelleher-Ferguson		
AKRF Equipment on Site:	Mini RAE 3000 Photoionization Detectors [(PID) x3] and DustTrak Aerosol Monitors (x3)		
/isitors:	None		
	Contractor Information		
Subcontractor		Service	
Island Pump & Tank Corp. (IPT)		Tank removal contractor	
East Northport, NY			
	Description and Location of Work Activities	Performed	


IPT continued to clean three of the 4,000 gallon gasoline USTs. The emptied and cleaned tanks were transported off-site as scrap metal. Tank contents and cleaning fluids were containerized in 55-gallon drums for future off-site disposal.

CAMP Air Monitoring Results		
CAMP Station	UPWIND	DOWNWIND
Odors:	None	None
VOC Action Level Exceedance(s):	2	None
Particulate Action Level Exceedance(s):	None	None
Maximum VOC Level (ppm) 15-min avg:	15.19	1.181
Maximum Particulate Level (mg/m³) 15-min avg:	0.0425	0.0515

CAMP Response Actions: VOC exceedances were detected at the upwind CAMP station. AKRF collected supplementary readings at the upwind location using the roving equipment, and the VOC levels were below the action level. Furthermore, AKRF did not observe any activities being conducted near the upwind station that would be expected to cause elevated PID readings and the downwind levels and work zone readings were below the action level. AKRF continued to troubleshoot the PID and after replacing it with a new unit, the concentrations decreased to within normal background levels for the remainder of the day and were consistent with the roving unit.

Additional Information		
	Removal/cleaning of gasoline and waste oil USTs, associated piping, and any grossly contaminated fill/soil (if encountered). Collection of post-excavation endpoint samples.	
Comments:	None	





Photograph 1 - IPT, cleaning the interior of a gasoline tank, view facing northeast.

Photograph 2 -IPT removing a clean tank as scrap steel, view facing west.



Photograph 3 - IPT cutting into a UST prior to cleaning, view facing southeast.

