

Daily Activity Report

Seton Brilla Charter School 1956 Jerome Avenue, Bronx, NY

BCP No. C203152

| General | Site Int | formation |
|---------|----------|-----------|
| | | |

| Date: | Monday, January 23, 2023 | | |
|-------------------------|--|--|--|
| Weather: | Rain, 30°F | | |
| Wind Direction/Speed: | N @ 13 mph | | |
| AKRF Personnel on Site: | J. Kelleher-Ferguson | | |
| AKRF Equipment on Site: | Mini RAE 3000 Photoionization Detector [(PID) x1], 2 Fixed Air Monitoring Stations [DustTrak | | |
| Visitors: | None. | | |

Contractor Information

Contracting Company Main Personnel Equipment

- 1)JEL installed lagging along the property boundary.
- 2) One truckload of soil/fill from the Site was sent for off-site disposal at the CE Carteret facility.

Site Soil Disposal Tracking Information

| Destination Facility | Daily Trucks | Total Trucks | Daily Approx. Cubic Yds | Total Approx. Cubic Yds | Total Site Loads | Total Approximate Cubic Yards |
|---------------------------------------|--------------|--------------|----------------------------|----------------------------|------------------|-------------------------------------|
| Clean Earth Carteret | 1 | 46 | 20 | 920 | 77 | 1,540 |
| Clean Earth Southeastern Pennsylvania | 0 | 10 | 0 | 200 | | |
| Concrete Disposal | 0 | 21 | 0 | 420 | | |
| N/A | 0 | 0 | 0 | 0 | | |
| N/A | 0 | 0 | 0 | 0 | | |

CAMP Air Monitoring Results

| CAMP Station | UPWIND | | | DOWNWIND | | | |
|---|--------|--|--|----------|-------|--|--|
| Odors: | None. | | | | None. | | |
| VOC Action Level Exceedance(s): | None. | | | | None. | | |
| Particulate Action Level Exceedance(s): | None. | | | | None. | | |
| Maximum VOC Level (15 min ppm): | NA | | | | NA | | |
| Maximum Particulate Level (15 min mg/m³): | NA | | | | NA | | |

Notes: CAMP monitoring was not performed due to heavy rain throughout the day.

Additional Information


Planned Work Activity for Following Day/Week:

1) Excavation of and removal of soil/fill.

2) Brookside is expected to return to the Site to clean and remove the USTs from site.

Comments:

None.



Site Photographs QAKRF Photograph 1 - JEL receiving a supply dropoff, view facing southeast Photograph 2 -JEL performing mainanence on their drill rig, view facing east. AKRE Photograph 3 - JEL loading a truck for off-site disposal, view facing east.