



1099 Webster Ave
Supplemental Investigation Results Report
1099 Webster Ave, Bronx, NY



Clutter within the Machine Shop area.



Soil sampling within the Mechanic Shop.

1099 Webster Ave
Supplemental Investigation Results Report
1099 Webster Ave, Bronx, NY



Top of building at the Interior Parking Area, showing UST vent piping.



Center drain within the Large Auto Mechanic area.

**1099 Webster Ave
Supplemental Investigation Results Report
1099 Webster Ave, Bronx, NY**



Large Test Pit within the Interior Parking Area, showing corroded below grade piping.




Large Test Pit within the Interior Parking Area, showing leaking UST.

1099 Webster Ave
Supplemental Investigation Results Report
1099 Webster Ave, Bronx, NY




Soil boring SB-10 located within the Large Auto Mechanic area.



Groundwater sample being collected within the Interior Parking Area.

1099 Webster Ave
Supplemental Investigation Results Report
1099 Webster Ave, Bronx, NY



Soil Vapor Sample being collected in the Machine Shop.