



PROJECT No.: 170361306	CLIENT: Gowanus President Owner LLC	DATE: Wed., February 22 nd , 2023
PROJECT: 514 Union Street		WEATHER: Overcast/Rain, 39 – 44 °F Wind: NW @ 3 – 10 mph
LOCATION: Brooklyn, New York		TIME: 6:45 am – 3:45 pm
BCP SITE ID: C224318		MONITOR: Audrey Seery
EQUIPMENT: Geoprobe 6620DT MiniRAE 3000 Photoionization Detector (PID) Air monitoring station (DustTrak II, MiniRAE 3000 PID) Solinst Water Level Meter YSI 600XL Water Quality Meter JCB 507 Forklift	PRESENT AT SITE: Langan: Audrey Seery Regenesis: Julian Serrano, Neal Wang Coastal Environmental Solutions, Inc.: John Slavin	
OBSERVATIONS, DISCUSSIONS, TEST RESULTS, ETC.: Langan was on-site to document implementation of the New York State Department of Environmental Conservation (NYSDEC)-approved February 2 nd , 2023 Interim Remedial Measures Work Plan (IRMWP) No. 2.		
Site Activities <ul style="list-style-type: none">Regenesis completed four low-dose PlumeStop® injections points (IP22, IP27, IP28, and IP29) across the target treatment interval (TTZ) of 10 to 30 feet below grade surface (bgs). Remedial products applied included PlumeStop®, S-MicroZVI®, and BDI PLUS®.		
Sampling <ul style="list-style-type: none">No samples were collected.		
Cc: J. Hayes, M. Burke, P. McMahon, V. De Paula, B. Koontz	By: Audrey Seery	Langan, D.P.C.

CAMP

- Langan performed continuous air monitoring at downwind perimeter of the work zone for volatile organic compounds (VOCs) and particulate matter smaller than 10 microns in diameter (PM10) during ground-intrusive activity. VOC and PM10 action levels were not exceeded during the monitoring period. Recorded air monitoring data is summarized in the following graphs:



Cc:	J. Hayes, M. Burke, P. McMahon, V. De Paula, B. Koontz	By:	Audrey Seery Langan, D.P.C.
-----	--	-----	---------------------------------------

Anticipated Activities

- Regeneration will continue application of remedial products via injection points.

Cc:	J. Hayes, M. Burke, P. McMahon, V. De Paula, B. Koontz	By:	Audrey Seery Langan, D.P.C.
-----	--	-----	---------------------------------------

Site Photographs



Photo 1: Regensis applying remedial products at injection point IP27 (facing east).




Photo 2: Regensis applying remedial products at injection points IP22(facing west).






Cc: J. Hayes, M. Burke, P. McMahon, V. De Paula, B. Koontz

By: Audrey Seery
Langan, D.P.C.

Site Map



Legend

-  Approximate Site Boundary
-  Approximate Drum Location
-  Approximate Air Monitoring Station Location(s)
-  Completed Injection Point
-  Injection Point in Progress

Notes

1. Base Map adapted from Figure 8 of the 2 February 2023 IRMWPs No. 2.

Drum Inventory

1. Five 55-gallon drums containing soil cuttings
2. Three 55-gallon drum containing purged groundwater
3. One 55-gallon drum containing drilling fluid

Cc:	J. Hayes, M. Burke, P. McMahon, V. De Paula, B. Koontz	By:	Audrey Seery Langan, D.P.C.
-----	--	-----	--------------------------------