

## **WEEKLY INSPECTION REPORT**

Prepared By:	WEATHER	Snow	Rain		Overcast	Partly Cloudy	Bright Sun	х	Wind
Thomas Jensen	TEMP.	< 32	32-50	X	50-70	70-85	>85		

IEC Project No:	14729	NYSDEC BCP Site No:	C224329	Date:	12/13/23
Project:	585 Union Street, Brooklyn, NY				

Consultant:	Personnel On Site:
Impact Environmental Engineering and	IEEG (Environmental) – Thomas Jensen
Geology, PLLC (IEEG)	Broadway Construction Group, Shannon Dowling
Time On: 13:00	
Time Out: 13:30	
Consideration of the state of t	

#### Scope of Work:

• Weekly Site inspection.

### **Site Activities:**

- Continued interior framing up to the 9<sup>th</sup> floor;
- Continued exterior framing up to the 9<sup>th</sup> floor;
- Sheeting has been placed on parts of the exterior of the building;
- Sheetrock has begun to be put up on the second and third floors of the building; and
- General super structure work (plumbing, carpentry, electrical, etc.).

## **Community Air Monitoring Program (CAMP):**

• CAMP was not deployed as the purpose of the Site visit was for a weekly inspection.

### **Notable Site Conditions:**

None.

## Planned for the Next Day/Week:

• Continued superstructure work.

# **PHOTO LOG**

585 Union Street, Brooklyn, NY



Photo 1 –
Representative
photo of
sheetrock on
the second
floor.




Photo 2 – Representative view of the first floor.




Photo 3 –
Representative photo of the exterior of the building.

