

DAILY STATUS REPORT

Prepared By: Ela Kusmierz

WEATHER	Snow	Rain	Overcast	X	Partly Cloudy	X	Bright Sun	
TEMP.	< 32	32-50	50-70		70-85	Х	>85	Х

Langan Project No:	100688803	Project:	12074 Flatlands Avenue p/o Lot 1	Date:	08/07/2024
NYSDEC BCP Site No:	C224353			Time:	06:30 – 18:00

Consultant:

Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C.

PERSONNEL ON SITE:

Langan: Daniel Horvath (Environmental), Ela

Kusmierz (Environmental) **Monadnock:** Michael Sullivan

United Concrete: Claudio Cappiello, Miguel Flores

and laborers

American Dewatering Grouting (ADG): Patty and

crew

EQUIPMENT ON SITE: Bobcat T76 Skid Steer, Komatsu PC 490 LC Excavator, Comacchio MC8D Drill Rig

Site Activities

- 3 truckloads of non-hazardous material were removed for off-Site disposal to Clean Earth Philadelphia in Philadelphia, PA.
 - United excavated an approximately 10-foot long by 15-foot-wide area between 6 feet below ground surface (bgs) and 12 feet bgs in disposal grids WC20, WC21, WC26, and WC27. No staining, odors, or elevated PID readings were observed during excavation. All excavated material was loaded for off-Site disposal to Clean Earth Philadelphia in Philadelphia, PA.
- United placed filter fabric above the exposed soil on the Support of Excavation (SOE) slope for the adjacent Site to the east (BCP Site No. C224290) along the eastern boundary of the Site. The slope has been fully re-covered.
- ADG installed a dewatering monitoring well in the northeastern portion of the logistics zone for monitoring of the dewatering system at the adjacent Site to the east (BCP Site No. C224290).

Samples Collected

None

Community Air Monitoring Program (CAMP)

- Langan implemented the CAMP during import during soil disturbance. CAMP equipment consisted of a
 DustTrack II and photoionization detector (PID) at dedicated locations on the downwind and upwind
 perimeter of the Site, as well as a personal DataRam (pDR) and photoionization detector (PID) at a work
 zone monitoring station.
 - Dust and VOC concentrations were not detected in exceedance of the daily short-term exposure limit (STEL).



Problems Encountered

None

Activities Scheduled for Next Day

- Trucks will traverse through the logistical zone of the Site to the adjacent Site to the east (BCP Site No. C224290) for the installation of SOE and the installation of the deep foundation piles and dewatering wells.
- ADG will continue installing dewatering monitoring wells in the logistics zone for monitoring of the dewatering at the adjacent Site to the east (BCP Site No. C224290).

Two Week Outlook

 Trucks will continue to traverse through the logistical zone of the Site to the adjacent Site to the east (BCP Site No. C224290) for the loading and export of material, the installation of SOE, and the installation of the deep foundation piles and dewatering wells.



Truck Count Log of Imported Material										
Facility/Material:	Tilcon New York Inc., Mount Hope Quarry (1.5-inch Clean Stone)		Tilcon New York Inc., Mount Hope Quarry (0.75-inch Clean Stone)		Braen Stone of Sparta Lafayette, New Jersey (1.5-inch Clean Stone)		Braen Stone of Sparta Lafayette, New Jersey (0.75-inch Clean Stone)			
Volume:	Trucks	Cu. Yds.	Trucks	Cu. Yds.	Trucks	Cu. Yards	Trucks	Cu. Yards	Trucks	Cu. Yards
Today:	0	0	0	0	0	0	0	0		
Total:	0	0	0	0	25	500	0	0		
Approved Quantity:		500		500		500		500		_
Facility/Material:										
Volume:	Trucks	Cu. Yds.	Trucks	Cu. Yds.	Trucks	Cu. Yards	Trucks	Cu. Yards	Trucks	Cu. Yards
Today:										
Total:										
Approved Quantity:										

Note: 20 cubic yards assumed per truckload



Truck Count Log of Exported Material											
Facility/Material:	Philadelphia Approval i	h Philadelphia a, Pennsylvania # 243100026 00 tons)	Carteret, Approval	rth Carteret New Jersey #243070587 00 tons)				_			
Volume:	Trucks	Cu. Yds.	Trucks	Cu. Yds.	Trucks	Cu. Yds.	Trucks	Cu. Yds.	Trucks	Cu. Yds.	
Today:	3	60	0	0							
Total:	70	1,400	20	400							

Note: 20 cubic yards assumed per truckload

LANGAN

Photo Log

Photo 1 – United loading non-hazardous material for off-Site disposal to Clean Earth Philadelphia, facing south.



Photo 2 – United placing filter fabric above exposed soil in the eastern portion of the Site, facing north.



LANGAN

Photo 3 – View of filter fabric above exposed soil in the northeastern portion of the Site, facing south.



Photo 4 – United excavating material for off-site disposal to Clean Earth Philadelphia in the eastern portion of the site, facing north.



