

Project	Bedford Beverly Brownfield Site	Report No.	123
BCP Site	BCP Site No. C224384	Date	03/29/2024
Location	2359 and 2360 Bedford Avenue,	File No.	0205432
	Brooklyn, NY		
Client	Bedford Beverly Acquisitions LLC	Temperature	41-55°F
Contractor	Haley & Aldrich, Maman	Wind	NW to SE, 13 mph
	Contracting (Maman),	Direction	
	International Concrete		
Weather	Cloudy	Personnel on	E. Nunez
		Site	
l l	F00/	Time on Cite	C.45 are to 1.00 per
Humidity	58%	Time on Site	6:45 am to 1:00 pm

Haley & Aldrich of New York Engineering and Geology, LLP (Haley & Aldrich) was present to document implementation of the January 2024 NYSDEC-approved Remedial Action Work Plan (RAWP) prepared by Haley & Aldrich for the Bedford Beverly BCP Site (C224384), located at 2359 and 2360 Bedford Avenue, Brooklyn, NY. Site observations are summarized below.

Daily Observations:

- Contractor (International Concrete) continued support of excavation (SOE) and foundation installation within Lot 14 and Lot 53.
- Contractor (International Concrete) continued breaking up concrete in the northwestern region of Lot 53 and stockpiling for disposal.
- Contractor (International Concrete) continued footing and subgrade preparation in Lots 14 and
 53.

Waste Disposal/Backfill Import Tracking:

Material Export:

Soil/Fill disposal is summarized below:

	Management, K	nyshore Soil Teasbey, NJ (Non- Soil)	,	NJ LLC, Prospect on-Haz Soil)	Facility: Keystone Trade Center, Fairless Hills, PA (Non-Haz Soil)			
Today:	0 Loads	0 CY	0 Loads	0 CY	0 Loads	0 CY		
Total:	447 Loads	8,940 CY	2,083 Loads	41,660 CY	866 Loads	17,320 CY		
	Facility: Posil	lico Materials	Facility: Republi	c Environmental	Facility: Conestoga Republic			
	Permitted Wo	ash Plant, LLC,	Systems, LLC, Hatfield PA (Haz Soil)		Environmental Systems, LLC, Prospect Park, NJ (Non-Haz Soil)			
	Farmingdale, N	Y (Non-Haz Soil)						
Today:	0 Loads	0 CY	0 Loads	0 CY	0 Loads	0 CY		
Total:	687 Loads	13,740CY	<u>5 Loads</u>	100 CY	44 Loads	880 CY		
Sitewide Total			*Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present					
Today:	0 Loads	0 CY	in the Final Engineering Report (FER)					
Total:	4.200 Loads	84.000 CY						



Asphalt disposal is summarized below:

	Facility: Flush Recycling, F (Asph	lushing NY	Materials, F	: Mount Fairless Hills, Sphalt)		
					Tota	ls:
Today:	0 Loads	0 CY	0 Loads 0 CY		0 Loads	0 CY
<u>Total:</u>	<u>117 Loads</u>	2,340 CY	43 Loads 860 CY		<u>160 Loads</u>	3,200 CY

^{*}Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present in the Final Engineering Report (FER)

C&D disposal is summarized below:

	Facility:	Mount		
	Mate	rials,		
	Fairless I	Hills, PA		
	(Non-Haz	Concrete)	Total	ls:
Today:	0 Loads 0 CY		0 Loads	0 CY
<u>Total:</u>	224 Loads	<u>4,480 CY</u>	<u>224 Loads</u>	<u>4,480 CY</u>

^{*}Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present in the Final Engineering Report (FER)

Material Import:

o Material import is summarized below:

	Facility: Mount Hope		Facility:	Mount Hope		
	Quarry,		Q	uarry,		
	Who	arton, NJ	Wharton, NJ		harton, NJ	
	(AS	TM #57)	(ASTM #3)		Т	otals:
Today:	8 Loads	201.51 Tons	2 Loads 48.63 Tons		10 Loads	250.14 Tons
Total:	39 Loads	960.63 Tons	33 loads	804.97 Tons	72 Loads	<u>1,765.6 Tons</u>

Injection Tracking:

- ZVI injections were completed on February 1, 2024, in Lot 14.
- ISCO injections were completed on February 12, 2024, in Lot 53.

Samples Collected:

No samples collected.

CAMP Activities:

 Air monitoring during ground-intrusive activities was performed at four locations during ground intrusive between 7:15 am to 12:00 pm. No 15-minute average concentration of volatiles organic compounds (VOCs) or particulate 15-minute average concentration of matter smaller than 10 microns in diameter (PM10) exceeded the action levels. No visible dust was observed leaving the site perimeter.



Activitie	es Planned for Coming Week:
	Contractor (International Concrete) will continue stockpiling soil at Lots 14 and 53 for disposal.
	Contractor (International Concrete) will continue transportation and disposal of soil/fill to
	approved facilities.
	Contractor (International Concrete) will continue footing and subgrade preparation in Lots 14 and 53.
	!
	· ·
	· ·
	· ·



Site Photographs:




Photo 1: View of site conditions in Lot 53, facing east.



Photo 2: View of site conditions in Lot 14, facing northwest.





2360 Bedford Avenue, Brooklyn NY

Air Monitoring Log

Date: 2024-03-29

Personnel: E. Nunez

Weather: Cloudy
Humidity: 58%

Wind Direction: NW to SE, 13 mph

Particulate Background (ug/m3): 4.882

PID Background (ppm) : 0.0

Action Levels : <u>Downwind perimeter of work area above background levels</u>

PID (ppm): > 5 ppm for the 15-min average Dust (ug/m3): > 150 for the 15-min average

Minute of Time	Avg. PM10 (Station1)	Avg. PM10 (Station2)	Avg. PM10 (Station3)	Avg. PM10 (Station4)	Avg. VOC(Station1)	Avg. VOC(Station2)	Avg. VOC(Station3)	Avg. VOC(Station4)	Odors	Notes Activities/ Additional Monitoring
07:15	6.583	4.091	9.800	4.882	0.0	0.0	0.0	0.0		
07:30	6.921	4.520	9.490	4.997	0.0	0.0	0.0	0.0		
07:45	7.125	5.154	6.218	5.337	0.0	0.0	0.0	0.0		
08:00	7.538	7.572	7.129	6.112	0.0	0.0	0.0	0.0		
08:15	8.433	14.446	7.592	6.890	0.0	0.0	0.0	0.0		
08:30	8.779	9.138	7.868	7.441	0.0	0.0	0.0	0.0		
08:45	8.927	6.867	7.553	6.668	0.0	0.0	0.0	0.0		
09:00	8.909	6.383	7.474	5.908	0.0	0.0	0.0	0.0		
09:15	8.997	5.900	7.115	6.024	0.0	0.0	0.0	0.0		
09:30	8.415	6.482	5.946	5.707	0.0	0.0	0.0	0.0		
09:45	8.159	5.876	8.185	5.172	0.0	0.0	0.0	0.0		
10:00	7.322	5.034	6.644	5.070	0.0	0.0	0.0	0.0		
10:15	10.155	5.147	7.560	4.851	0.0	0.0	0.0	0.0		
10:30	9.455	4.517	6.080	4.853	0.0	0.0	0.0	0.0		
10:45	9.708	4.212	7.881	4.416	0.0	0.0	0.0	0.0		

2360 Bedford Avenue, Brooklyn NY

Air Monitoring Log

Minute of Time	Avg. PM10 (Station1)	Avg. PM10 (Station2)	Avg. PM10 (Station3)	Avg. PM10 (Station4)	Avg. VOC(Station1)	Avg. VOC(Station2)	Avg. VOC(Station3)	Avg. VOC(Station4)	Odors	Notes Activities/ Additional Monitoring
11:00	8.856	4.897	7.265	4.3	0.0	0.0	0.0	0.0		
11:15	7.751	5.076	8.221	5.1	0.0	0.0	0.0	0.0		
11:30	8.986	3.895	6.651	4.6	0.0	0.0	0.0	0.0		
11:45	8.487	3.741	6.070	4.9	0.0	0.0	0.0	0.0		
12:00		3.849				0.0				