

Project	Bedford Beverly Brownfield Site	Report No.	197
BCP Site	BCP Site No. C224384	Date	07/30/2024
Location	2359 and 2360 Bedford Avenue, Brooklyn, NY	File No.	0205432
Client	Bedford Beverly Acquisitions LLC	Temperature	77-87 °F
Contractor	Haley & Aldrich, Maman Contracting (Maman), International Concrete	Wind Direction	S to N, 9 mph
Weather	Sunny	Personnel on Site	C. Jackson
Humidity	80%	Time on Site	8:25am to 5:45pm

Haley & Aldrich of New York Engineering and Geology, LLP (Haley & Aldrich) was present to document implementation of the January 2024 NYSDEC-approved Remedial Action Work Plan (RAWP) prepared by Haley & Aldrich for the Bedford Beverly BCP Site (C224384), located at 2359 and 2360 Bedford Avenue, Brooklyn, NY. Site observations are summarized below.

## Daily Observations:

- Contractor (International Concrete) continued installation of foundation elements within Lots 14 and Lot 53.
- Contractor (International Concrete) imported #57 stone from Tilcon of Mount Hope Quarry in Wharton, NJ.

### Waste Disposal/Backfill Import Tracking:

### **Material Export:**

Soil/Fill disposal is summarized below:

	Management, K	nyshore Soil Teasbey, NJ (Non- Soil)	,	NJ LLC, Prospect on-Haz Soil)	Facility: Keystone Trade Center, Fairless Hills, PA (Non-Haz Soil)			
Today:	0 Loads	0 CY	0 Loads	0 CY	0 Loads	0 CY		
<u>Total:</u>	479 Loads	9,580 CY	2,093 Loads 41,860 CY		995 Loads	19,900 CY		
	Facility: Posil	lico Materials	Facility: Republi	c Environmental	Facility: Conestoga Republic			
	Permitted Wo	ash Plant, LLC,	Systems, LLC, Hatfield PA (Haz		Environmental Systems, LLC,			
	Farmingdale, N	Y (Non-Haz Soil)	Soil)		Prospect Park, NJ (Non-Haz Soil)			
Today:	0 Loads	0 CY	0 Loads	0 CY	0 Loads	0 CY		
<u>Total:</u>	687 Loads	13,740 CY	5 Loads	5 Loads 100 CY 44		880 CY		
	Sitewide To	tal	*Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present					
Today:	0 Loads	0 CY	in the Final Engineering Report (FER)					
Total:	4.371 Loads	87.420 CY	1					



o Asphalt disposal is summarized below:

	Facility: Flush	ning Asphalt	Facility:	Mount		
	Recycling, F (Aspl	_	-	airless Hills, sphalt)		
					Tota	ls:
Today:	0 Loads	0 CY	0 Loads 0 CY		0 Loads	0 CY
<u>Total:</u>	<u>117 Loads</u>	<u>2,340 CY</u>	43 Loads	<u>860 CY</u>	<u>160 Loads</u>	3,200 CY

<sup>\*</sup>Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present in the Final Engineering Report (FER)

C&D disposal is summarized below:

	Facility:	Mount		
	Mate	rials,		
	Fairless I	Hills, PA		
	(Non-Haz	Concrete)	Total	ls:
Today:	0 Loads	0 CY	0 Loads	0 CY
<u>Total:</u>	<u>232 Loads</u>	<u>4,640 CY</u>	232 Loads	<u>4,640 CY</u>

<sup>\*</sup>Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present in the Final Engineering Report (FER)

### **Material Import:**

- Four (4) loads of #57 stone were imported to the Site from Tilcon of Mount Hope Wuarry in Wharton , NJ
- Stone import is summarized below:

	Facility:	Mount Hope	Facility:	Mount Hope			
	(	Quarry,	Q	luarry,			
	Wharton, NJ		Wharton, NJ				
	(ASTM #57)		(AS	STM #3)	Totals:		
Today:	4 Loads 98.09 Tons		0 Loads 0 Tons		4 Loads	98.09 Tons	
<u>Total:</u>	118 Loads 2,925.93 Tons		36 loads	<u>931.33 Tons</u>	<u>154 Loads</u>	3,857.26 Tons	

o RCA import is summarized below:

	Facility: Recycling Ltd N	I., Brooklyn, Y	Totals:			
	(RC			<u> </u>		
Today:	0 Loads	0 CY	0 Loads	0 CY		
<u>Total:</u>	<u>125 Loads</u>	2,500 CY	<u>125 Loads</u>	2,500 CY		

<sup>\*</sup>Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present in the Final Engineering Report (FER)

### Injection Tracking:

- ZVI injections were completed on February 1, 2024, in Lot 14.
- ISCO injections were completed on February 12, 2024, in Lot 53.

### Samples Collected:

• None.



## **CAMP Activities:**

- Air monitoring during ground-intrusive activities was performed at four locations between 8:30 am to 5:30 pm.
- No 15-minute average concentration of volatiles organic compounds (VOCs) or particulate 15-minute average concentration of matter smaller than 10 microns in diameter (PM10) exceeded the action levels. No visible dust was observed leaving the site perimeter.

0	Contractor (International Concrete) will continue footing and subgrade preparation in
	Lots 14 and 53.





Photo 1: View of footing preparation in Lot 53, facing east.



Photo 2: View of site conditions in Lot 14, facing southwest.







#### 2360 Bedford Avenue, Brooklyn NY

### Air Monitoring Log

Date: 2024-07-30

Personnel: C. Jackson

Weather: Sunny
Humidity: 80%

Wind Direction : S to N, 9 mph

Particulate Background (ug/m3): 18.753

PID Background (ppm) : 0.0

Action Levels : <u>Downwind perimeter of work area above background levels</u>

PID (ppm): > 5 ppm for the 15-min average

Dust (ug/m3): > 150 for the 15-min average

Minute of Time	Avg. PM10 (Station1)	Avg. PM10 (Station2)	Avg. PM10 (Station3)	Avg. PM10 (Station4)	Avg. VOC(Station1)	Avg. VOC(Station2)	Avg. VOC(Station3)	Avg. VOC(Station4)	Odors	Notes Activities/ Additional Monitoring
08:30	17.620	17.585		18.753	0.0	0.0		0.0		
08:45	14.323	17.086	16.864	21.128	0.0	0.0	0.0	0.1		
09:00	13.051	14.897	14.150	20.695	0.0	0.0	0.0	0.0		
09:15	12.601	12.475	13.104	18.846	0.0	0.0	0.0	0.0		
09:30	13.468	14.907	12.761	16.537	0.0	0.0	0.0	0.0		
09:45	12.524	12.394	13.333	18.656	0.0	0.0	0.0	0.0		
10:00	13.153	12.084	12.512	20.743	0.0	0.0	0.0	0.0		
10:15	12.103	12.585	12.233	20.580	0.0	0.0	0.0	0.0		
10:30	12.904	12.614	12.979	16.670	0.0	0.0	0.0	0.0		
10:45	14.085	12.151	13.224	16.812	0.0	0.0	0.0	0.0		

## 2360 Bedford Avenue, Brooklyn NY

## Air Monitoring Log

Minute of Time	Avg. PM10 (Station1)	Avg. PM10 (Station2)	Avg. PM10 (Station3)	Avg. PM10 (Station4)	Avg. VOC(Station1)	Avg. VOC(Station2)	Avg. VOC(Station3)	Avg. VOC(Station4)	Odors	Notes Activities/ Additional Monitoring
11:00	14.523	12.597	14.562	16.9	0.0	0.0	0.0	0.0		
11:15	15.628	11.421	13.316	18.9	0.0	0.0	0.0	0.0		
11:30	14.341	12.213	13.933	33.2	0.0	0.0	0.0	0.2		
11:45	12.080	12.319	13.034	25.6	0.0	0.0	0.0	0.1		
12:00	13.147	11.920	11.448	15.1	0.0	0.0	0.0	0.0		
12:15	23.158	12.225	11.727	15.1	0.0	0.0	0.0	0.0		
12:30	13.432	11.395	13.616	13.5	0.0	0.0	0.0	0.0		
12:45	13.592	13.690	16.556	18.3	0.0	0.0	0.0	0.0		
13:00	13.811	11.885	16.715	28.4	0.0	0.0	0.0	0.0		
13:15	14.029	19.724	22.778	15.0	0.0	0.0	0.0	0.0		
13:30	15.297	19.290	17.110	15.1	0.0	0.0	0.0	0.0		
13:45	16.749	25.875	15.532	26.7	0.0	0.0	0.0	0.0		
14:00	14.236	21.075	16.090	14.1	0.0	0.0	0.0	0.0		
14:15	14.894	20.260	21.492	16.6	0.0	0.0	0.0	0.0		
14:30	13.399	24.139	26.738	14.5	0.0	0.0	0.0	0.0		
14:45	12.765	20.809	21.563	14.5	0.0	0.0	0.0	0.0		
15:00	13.149	22.359	19.715	13.4	0.0	0.0	0.0	0.0		
15:15	12.075	18.195	16.199	12.3	0.0	0.0	0.0	0.0		
15:30	11.457	16.914	12.068	12.7	0.0	0.0	0.0	0.0		
15:45	12.618	16.111	11.475	12.5	0.0	0.0	0.0	0.0		
16:00	14.523	16.391	13.768	13.1	0.0	0.0	0.0	0.0		
16:15	11.193	14.122	16.677	11.3	0.0	0.0	0.0	0.0		
16:30	13.975	13.203	15.314	10.7	0.0	0.0	0.0	0.0		
16:45	26.839	14.576	16.620	11.0	0.0	0.0	0.0	0.0		
17:00	19.147	13.920	17.843	11.1	0.0	0.0	0.0	0.0		
17:15	16.687	13.191	15.434	11.2	0.0	0.0	0.0	0.0		