

Project	Bedford Beverly Brownfield Site	Report No.	201
BCP Site	BCP Site No. C224384	Date	08/05/2024
Location	2359 and 2360 Bedford Avenue,	File No.	0205432
	Brooklyn, NY		
Client	Bedford Beverly Acquisitions LLC	Temperature	73-88°F
Contractor	Haley & Aldrich, Maman	Wind	S to N, 7 mph
	Contracting (Maman),	Direction	
	International Concrete		
Weather	Sunny	Personnel on	E. Nunez
		Site	
Humidity.	54%	Time on Site	7:20 am to 2:20nm
Humidity	34%	Time on Site	7:30 am to 2:30pm

Haley & Aldrich of New York Engineering and Geology, LLP (Haley & Aldrich) was present to document implementation of the January 2024 NYSDEC-approved Remedial Action Work Plan (RAWP) prepared by Haley & Aldrich for the Bedford Beverly BCP Site (C224384), located at 2359 and 2360 Bedford Avenue, Brooklyn, NY. Site observations are summarized below.

#### Daily Observations:

• Contractor (International Concrete) continued installation of foundation elements within Lots 14 and Lot 53.

#### Waste Disposal/Backfill Import Tracking:

## **Material Export:**

- o None.
- Soil/Fill disposal is summarized below:

	Facility: Bayshore Soil Management, Keasbey, NJ (Non- Haz Soil)		Facility: P Park I Park, NJ (No	NJ LLC, Prospect on-Haz Soil)	Facility: Keystone Trade Center, Fairless Hills, PA (Non-Haz Soil)		
Today:	0 Loads	0 CY	0 Loads	0 CY	0 Loads	0 CY	
<u>Total:</u>	449 Loads	9,580 CY	2,093 Loads	41,860 CY	955 Loads	19,900 CY	
	Facility: Posil	lico Materials	Facility: Republi	c Environmental	Facility: Conestoga Republic		
	Permitted Wo	ash Plant, LLC,	Systems, LLC, Hatfield PA (Haz		Environmental Systems, LLC,		
	Farmingdale, N	Y (Non-Haz Soil)	Soil)		Prospect Park, NJ (Non-Haz Soil)		
Today:	0 Loads	0 CY	0 Loads	0 CY	0 Loads	0 CY	
Total:	687 Loads	13,740CY	5 Loads	100 CY	44 Loads	880 CY	
	Sitewide To	tal	*Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present				
Today:	0 Loads	0 CY	in the Final Engineering Report (FER)				
Total:	4.371 Loads	87.420 CY					



Asphalt disposal is summarized below:

	Facility: Flush Recycling, F (Asph	lushing NY	Materials, F	: Mount Fairless Hills, Sphalt)	Totals:		
Today:	0 Loads	0 CY	0 Loads 0 CY		0 Loads	0 CY	
<u>Total:</u>	<u>117 Loads</u>	2,340 CY	43 Loads	860 CY	<u>160 Loads</u>	3,200 CY	

<sup>\*</sup>Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present in the Final Engineering Report (FER)

o C&D disposal is summarized below:

	Facility:	Mount		
	Mate	rials,		
	Fairless I	Hills, PA		
	(Non-Haz	Concrete)	Total	ls:
Today:	0 Loads	0 CY	0 Loads	0 CY
<u>Total:</u>	<u>232 Loads</u>	<u>4,640 CY</u>	232 Loads	4,640 CY

<sup>\*</sup>Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present in the Final Engineering Report (FER)

#### **Material Import:**

- o None.
- Stone import is summarized below:

	Facility: Mount Hope Quarry, Wharton, NJ		Facility:	Mount Hope		
			Quarry,			
			Who	arton, NJ		
	(AS	TM #57)	(ASTM #3)		Totals:	
Today:	0 Loads	0 Tons	0 Loads	0 Tons	0 Loads	0 Tons
<u>Total:</u>	<u>118 Loads</u>	2,925.93 Tons	36 loads	931.33 Tons	<u>154 Loads</u>	3,857.26 Tons

o RCA import is summarized below:

	Facility:	Allocco		
	Recycling Ltd	l., Brooklyn,		
	N'	Υ		
	(RC	A)	Total	ls:
Today:	0 Loads 0 CY		0 Loads	0 CY
<u>Total:</u>	125 Loads	2,500 CY	<u>125 Loads</u>	<u>2,500 CY</u>

<sup>\*</sup>Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present in the Final Engineering Report (FER)

#### Injection Tracking:

- ZVI injections were completed on February 1, 2024, in Lot 14.
- ISCO injections were completed on February 12, 2024, in Lot 53.

#### Samples Collected:

No samples were collected.



#### **CAMP Activities:**

- Air monitoring during ground-intrusive activities was performed at two locations during ground intrusive between 8:30 am to 2:00 pm.
- No 15-minute average concentration of volatiles organic compounds (VOCs) or particulate 15-

	minute average concentration of matter smaller than 10 microns in diameter (PM10) exceeded the action levels. No visible dust was observed leaving the site perimeter.							
Activit	ies Plar O	nned for Coming Week:  Contractor (International Concrete) will continue footing and subgrade preparation in Lots 14 and 53.						



# Site Photographs:



Photo 1: View of site conditions in Lot 14, facing west.





Photo 2: View of site conditions in Lot 14, facing west.





#### 2360 Bedford Avenue, Brooklyn NY

#### Air Monitoring Log

Date: 2024-08-05

Personnel: E. Nunez

Weather: Sunny

Humidity: 54%

Wind Direction: S to N, 7 mph

Particulate Background (ug/m3): 16.473

PID Background (ppm): 0.0

Action Levels : <u>Downwind perimeter of work area above background levels</u>

PID (ppm): >5 ppm for the 15-min average Dust (ug/m3): >150 for the 15-min average

Minute of Time	Avg. PM10 (Station1)	Avg. PM10 (Station2)	Avg. PM10 (Station3)	Avg. PM10 (Station4)	Avg. VOC(Station1)	Avg. VOC(Station2)	Avg. VOC(Station3)	Avg. VOC(Station4)	Odors	Notes Activities/ Additional Monitoring
08:30		19.399								
08:45		14.720		16.473		0.1		0.0		
09:00		15.630		13.226		0.1		0.0		
09:15		13.882		14.061		0.1		0.0		
09:30		16.934		12.052		0.1		0.0		
09:45		15.321		10.313		0.1		0.0		
10:00		13.802		8.292		0.1		0.0		
10:15		13.501		9.130		0.1		0.0		
10:30		21.193		8.049		0.0		0.0		
10:45		14.475		8.297		0.1		0.0		

## 2360 Bedford Avenue, Brooklyn NY

## Air Monitoring Log

Minute of Time	Avg. PM10 (Station1)	Avg. PM10 (Station2)	Avg. PM10 (Station3)	Avg. PM10 (Station4)	Avg. VOC(Station1)	Avg. VOC(Station2)	Avg. VOC(Station3)	Avg. VOC(Station4)	Odors	Notes Activities/ Additional Monitoring
11:00		9.602		7.8		0.1		0.0		
11:15		15.460		10.5		0.1		0.3		
11:30		10.540		9.9		0.0		0.0		
11:45		10.005		9.0		0.1		0.0		
12:00		14.014		8.2		0.3		0.0		
12:15		10.363	12.237	7.9		0.2	0.0	0.0		
12:30		15.488	10.710	7.7		0.2	0.0	0.0		
12:45		15.952		7.8		0.1		0.0		
13:00		13.960		8.3		0.2		0.0		
13:15		14.261		8.6		0.2		0.0		
13:30		21.486		8.2		0.1		0.0		
13:45		10.805		8.0		0.1		0.0		
14:00		9.010		7.9		0.2		0.0		

