

Project	Bedford Beverly Brownfield Site	Report No.	203
BCP Site	BCP Site No. C224384	Date	08/07/2024
Location	2359 and 2360 Bedford Avenue,	File No.	0205432
	Brooklyn, NY		
Client	Bedford Beverly Acquisitions LLC	Temperature	69-74°F
Contractor	Haley & Aldrich, Maman	Wind	NE to SW, 10 mph
	Contracting (Maman),	Direction	
	International Concrete		
Weather	Rainy	Personnel on	E. Nunez
		Site	
l la consi elita e	0.00/	Time on Cite	7:00 am to 3:45 am
Humidity	86%	Time on Site	7:00 am to 2:45pm

Haley & Aldrich of New York Engineering and Geology, LLP (Haley & Aldrich) was present to document implementation of the January 2024 NYSDEC-approved Remedial Action Work Plan (RAWP) prepared by Haley & Aldrich for the Bedford Beverly BCP Site (C224384), located at 2359 and 2360 Bedford Avenue, Brooklyn, NY. Site observations are summarized below.

#### Daily Observations:

• Contractor (International Concrete) continued installation of foundation elements within Lots 14 and Lot 53.

#### Waste Disposal/Backfill Import Tracking:

## **Material Export:**

- o None.
- Soil/Fill disposal is summarized below:

	Management, K	yshore Soil easbey, NJ (Non- Soil)	Facility: P Park I Park, NJ (No	NJ LLC, Prospect on-Haz Soil)	Facility: Keystone Trade Center, Fairless Hills, PA (Non-Haz Soil)		
Today:	0 Loads	0 CY	0 Loads	0 CY	0 Loads	0 CY	
<u>Total:</u>	449 Loads	9,580 CY	2,093 Loads	41,860 CY	955 Loads	19,900 CY	
	Facility: Posillico Materials		Facility: Republi	c Environmental	Facility: Conestoga Republic		
	Permitted Wo	ash Plant, LLC,	Systems, LLC, H	atfield PA (Haz	Environmental Systems, LLC,		
	Farmingdale, N	Y (Non-Haz Soil)	Soil)		Prospect Park, NJ (Non-Haz Soil)		
Today:	0 Loads	0 CY	0 Loads	0 CY	0 Loads	0 CY	
Total:	687 Loads	13,740CY	5 Loads	100 CY	44 Loads	880 CY	
	Sitewide To	tal	*Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present				
Today:	0 Loads	0 CY	in the Final Engineering Report (FER)				
Total:	4.371 Loads	87.420 CY					



Asphalt disposal is summarized below:

	Facility: Flush Recycling, F (Asph	lushing NY	Materials, F	: Mount Fairless Hills, Sphalt)	Totals:		
Today:	0 Loads	0 CY	0 Loads	0 Loads 0 CY		0 CY	
<u>Total:</u>	<u>117 Loads</u>	2,340 CY	43 Loads	860 CY	<u>160 Loads</u>	3,200 CY	

<sup>\*</sup>Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present in the Final Engineering Report (FER)

o C&D disposal is summarized below:

	Facility:	Mount		
	Mate	rials,		
	Fairless I	Hills, PA		
	(Non-Haz	Concrete)	Total	ls:
Today:	0 Loads	0 CY	0 Loads	0 CY
<u>Total:</u>	<u>232 Loads</u>	<u>4,640 CY</u>	232 Loads	4,640 CY

<sup>\*</sup>Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present in the Final Engineering Report (FER)

#### **Material Import:**

- o None.
- Stone import is summarized below:

	Facility: Mount Hope		Facility:	Mount Hope		
	(	Quarry,	Q	luarry,		
	Wharton, NJ		Who	arton, NJ		
	(AS	TM #57)	(AS	(ASTM #3)		otals:
Today:	0 Loads 0 Tons		0 Loads	0 Tons	0 Loads	0 Tons
<u>Total:</u>	<u>118 Loads</u>	2,925.93 Tons	36 loads	931.33 Tons	<u>154 Loads</u>	3,857.26 Tons

o RCA import is summarized below:

	Facility:	Allocco			
	Recycling Ltd	l., Brooklyn,			
	N'	Υ			
	(RC	A)	Totals:		
Today:	0 Loads 0 CY		0 Loads	0 CY	
<u>Total:</u>	125 Loads	2,500 CY	<u>125 Loads</u>	<u>2,500 CY</u>	

<sup>\*</sup>Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present in the Final Engineering Report (FER)

#### Injection Tracking:

- ZVI injections were completed on February 1, 2024, in Lot 14.
- ISCO injections were completed on February 12, 2024, in Lot 53.

#### Samples Collected:

No samples were collected.



#### **CAMP Activities:**

- Due to rain, visual and olfactory monitoring was conducted from 7:00 am to 10:00 am. No visible dust was observed leaving the site perimeter.
- Air monitoring during ground-intrusive activities was performed at four locations during ground

intrusive work from 10:00 am to 2:00 pm. No 15-minute average concentration of volatile organic compounds (VOCs) or particulate 15-minute average concentration of matter smalle than 10 microns in diameter (PM10) exceeded the action levels. No visible dust was observed leaving the site perimeter.
ctivities Planned for Coming Week: <ul> <li>Contractor (International Concrete) will continue footing and subgrade preparation in Lots 14 and 53.</li> </ul>



# Site Photographs:



Photo 1: View of site conditions in Lot 14, facing northwest.





Photo 2: View of site conditions in Lot 14, facing north.





#### 2360 Bedford Avenue, Brooklyn NY

#### Air Monitoring Log

Date: 2024-08-07

 Personnel :
 E. Nunez

 Weather :
 Rainy

 Humidity :
 86%

 Wind Direction :
 NE to SW, 10 mph

Particulate Background (ug/m3) : 6.807

PID Background (ppm) : 0.0

Action Levels : <u>Downwind perimeter of work area above background levels</u>

PID (ppm): > 5 ppm for the 15-min average Dust (ug/m3): > 150 for the 15-min average

Minute of Time	Avg. PM10 (Station1)	Avg. PM10 (Station2)	Avg. PM10 (Station3)	Avg. PM10 (Station4)	Avg. VOC(Station1)	Avg. VOC(Station2)	Avg. VOC(Station3)	Avg. VOC(Station4)	Odors	Notes Activities/ Additional Monitoring
10:00		6.807		6.333		0.1		0.0		
10:15		6.361		4.776		0.1		0.0		
10:30		4.992		5.513		0.1		0.0		
10:45		7.662		13.823		0.1		0.0		

## 2360 Bedford Avenue, Brooklyn NY

## Air Monitoring Log

Minute of Time	Avg. PM10 (Station1)	Avg. PM10 (Station2)	Avg. PM10 (Station3)	Avg. PM10 (Station4)	Avg. VOC(Station1)	Avg. VOC(Station2)	Avg. VOC(Station3)	Avg. VOC(Station4)	Odors	Notes Activities/ Additional Monitoring
11:00		4.876		6.1		0.0		0.0		
11:15		6.798		7.0		0.1		0.0		
11:30		5.776		5.8		0.1		0.0		
11:45		6.553		6.0		0.1		0.0		
12:00		2.768		3.0		0.1		0.0		
12:15		2.875		2.9		0.1		0.0		
12:30		2.833		3.0		0.1		0.0		
12:45		3.783		5.8		0.0		0.0		
13:00		5.235		5.2		0.0		0.0		
13:15		5.407		8.8		0.0		0.0		
13:30		4.468		6.0		0.0		0.0		
13:45		4.112		5.4		0.0		0.0		
14:00		6.837		7.3		0.0		0.0		

